



Aviation Investigation Factual Report

Location:	Fulshear, Texas	Accident Number:	CEN17LA011
Date & Time:	October 3, 2016, 18:00 Local	Registration:	N83WR
Aircraft:	Fokker DR-1	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (partial)	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Flight test		

Factual Information

On October 3, 2016, about 1800 central daylight time, a Fokker DR-1 airplane, N83WR, experienced a loss of engine power and the pilot made a forced landing near Fulshear, Texas. The airline transport rated pilot was not injured and the airplane sustained substantial damage. The airplane was registered to and operated by a private individual under the provisions of 14 Code of Federal Regulations Part 91 as a test flight. Visual meteorological conditions prevailed and no flight plan was filed. The local flight had just departed the Covey Trails Airport, Fulshear, Texas.

The responding Federal Aviation Administration (FAA) inspector reported that the airplane's construction had just been completed by the owner and the accident flight was the airplane's first test flight. The owner asked the accident pilot to conduct the test flight. Prior to the accident flight the owner secured the airplane to a fixed object and completed a full power engine run with no anomalies noted. The airplane was then subjected to eight high-speed taxi runs conducted. A few small oil leaks were observed from the rocker box covers; the gaskets were replaced and the oil leaks were resolved. Later, the pilot departed from X09 and experienced a partial loss of engine power during the initial climb and the airplane was not able to maintain altitude. The pilot made a forced landing into a tree nursery about one mile from X09. The spars on all three right wings were damaged.

The owner reported that the Rotax R3600 engine was received new with 0 hours on March 31, 2016. The engine was installed on the airplane and had accumulated about 4 hours of tests runs prior to the accident flight.

The FAA inspector conducted a postaccident examination of the engine and fuel system. The examination revealed that the fuel filter and gascolator were clear of contaminants and the engine was unremarkable. The fuel pressure regulator and throttle body injector were disassembled and no anomalies were noted. The mechanical fuel pump was disassembled and housing screws were slightly loose and the fuel screen was not seated properly.

The engine manufacturer stated that their products are experimental and there is no standard installation for the engine, only guidelines. This leaves the owner free to experiment with the engine and fuel system installation.

Pilot Information

Certificate:	Airline transport; Commercial; Flight engineer	Age:	65, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	February 1, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	23000 hours (Total, all aircraft), 0 hours (Total, this make and model), 18850 hours (Pilot In Command, all aircraft), 80 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Fokker	Registration:	N83WR
Model/Series:	DR-1	Aircraft Category:	Airplane
Year of Manufacture:	2015	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	103
Landing Gear Type:		Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Rotec
ELT:	Not installed	Engine Model/Series:	R3600
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KTME,168 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	17:55 Local	Direction from Accident Site:	341°
Lowest Cloud Condition:	Few / 6000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	4 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.86 inches Hg	Temperature/Dew Point:	29°C / 15°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Fulshear, TX (X09)	Type of Flight Plan Filed:	None
Destination:	Fulshear, TX (X09)	Type of Clearance:	None
Departure Time:	18:00 Local	Type of Airspace:	Class E

Airport Information

Airport:	COVEY TRAILS X09	Runway Surface Type:	Grass/turf
Airport Elevation:	130 ft msl	Runway Surface Condition:	Dry;Vegetation
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	3352 ft / 100 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	29.652221,-95.842498(est)

Administrative Information

Investigator In Charge (IIC):	Lindberg, Joshua
Additional Participating Persons:	Rick Bolton; Federal Aviation Administration; Houston, TX
Report Date:	January 18, 2017
Last Revision Date:	
Investigation Class:	Class
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=94159

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).