	DEPAR	TMENT OF HO	OMELAND			OMB No. 1625-0001 Explos: 01/31/2016		
	REPO	ORT OF MAI						
1. Name of Vessel or Facility		ECTION I. GENE		MATION Nationality	4. Call Sign	5. USCG Certificate of Inspection Issued et:		
1. Name of Vessel of Facility M/T CARLA MAERSK		9171503		Danish	OZGB2	Houston, TX		
6. Typa (Toxing, Freight, Fish, Drill, elc.) 7. Length		8, Gross Toris				, diesel, gas, (urolno)		
Tanker 182,75		29289 1998			Diesel			
}	Dieli (FL-In) FWD AFT,	DNV, BV, elo.)			14. Date (of occurrence 9 March 20			
Steel 39.5		Det Nors	Det Norske Veritas					
18. Location (See Instruction No. 10A) 17. Estimated Loss of Damage TO: Houston Ship Channel - Buoys 89/90 - S.E. of Morgan's Point 17. Estimated Loss of Damage TO:								
18 Name, Address & Telephone No. of Oper HandyTankers K/S, 4t. Copenhagen, K, Denma		eds Gade	28, 1402,	CARGO T	BD BD nknown			
19. Name of Master or Person In Charge	USCG	Ucense	20. Nəmə	of Pilol	USCG License Size License			
Adam Napierski, Mast		s Xino	Cap	ot. Larry Ev	ang 🛛 YES			
19a. Home or Work Street Address (City, St			o, 20a. Home	or Work Street Address	(City, Stele, Zip Code) 20b.1	Home or Work Telephone No		
		<u></u>			2			
21. Casually Elements (Chock as many as NO. OF PERSONS ON BOARD -2		x <i>k 44.)</i> Flooding; Swamp	ING WITHOUT	r sinking		IERGENCY EQUIPMENT		
					(Describe in Block 44.)			
		FOUNDERING OR SI		ľ	INADEQUATE (Descrit	UFESAVING EQUIPMENT FAILED OR INADEQUATE (Describe in Block 44.)		
	HEAVY WEATHER D	DAMAGE	L.	BLOW OUT (Petroleur	BLOW OUT (Petroleum exporation/production)			
(Identify Substance and emount in Block 44.)								
OIL SPILL - ESTIMATE AMOUNT:	CE DAMAGE	(Dəscribə in Block 44.)						
	DAMAGE TO AIDS T	OTHER (Specify)						
CARGO CONTAINER LOST/DAMAC	STEERING FAILURE							
 COLLISION (IdenSily other vessel or object in Block 	MACHINERY OR EQU ELECTRICAL FAILUR		UKE.					
	STRUCTURAL FAILU			·				
22. Conditions	<u>, , , , , , , , , , , , , , , , , , , </u>							
B, WEATH			O, VISIBILI	Isibilibi	<u>5 mi</u>			
A. Sea or River Conditions				R TEMPERATURE	5°C-(60°+)			
(wavo holghi, river slogo, CRAIN elc.)		TYMLIGHT Night	[] FAIR	/F		1		
X FOG		G. WIND			ND SPEED & 7.0 RECTION	емрегатике <u>15°с</u> - (60°+) регеова <u>70 и/ссс</u> ЕЛСТ		
	ER (Specily)			H. C	URRENT SPEED 0.5	160 "		
23. Navigation Information	<u></u>	9.0	24.	<u>&</u>	DIRECTION	24a. Time and		
[] MOORED, DOCKED OR FIXED	AL	$\frac{107}{100}$		Port HOUSEON Where Bound	to Venezuela	Date of Departure 0925 9 Mar 15		
25. 25a.		25b.	250.	· · · · · ·	25d (Describe in Block	44.)		
NUMBER ENV	ply Loaded Total	TOTAL	махімим	Length Width	D PUSHING AHEAD			
FOR OF		H P. OF	SIZE OF TOW	/				
ONLY VESSELS		TOWING	WITH TOW-			IDE TOW-BOAT ON TOW		
TOWED	SECTION IL B	UNITS ARGE INFORMAT	BOAT(S) TION		·····	USCG Certificate of		
26. Neme	26a. Official Numb		286, Туре	26c, Length	26d. Gross Tona Inst	pection issued at:		
261, Year Bulli 269. SINGLE S	KIN 26h, Drag FWD	AFT	26i. Operating C	Sompany	L.,			
26], Damega Amount	·	26k. Describe Dame	ge to Barga					
BARGE								
CARGO								
OTHER	<u> </u>					Page 1 of 5		

CG-2692 (03/13)

Page 1 of 6

<u> </u>	SECTION	I PERSONNEL	ACCIDENT INFOR	MATION				
27. Person Involved 27a, Name (Last, First, Midde Name)			Automatic an on		27c. Status			
🗌 MALE 📋 OR FEMALE					Crew			
					Pessenger			
					Other			
28, Birth Date 29, Te	lephone No.	30. Job Posit	ion		31. (Check here If all duly)			
32. Employer - (il different from Bloc	k 10., fill in Nemo, Address, Telep	xhona Na.)		· · · · · · · · · · · · · · · · · · ·				
33. Person's Time		- 		34, Industry of Empl	ayer (Toxing, Fishing, Shipping, g. elc.)			
A. IN THIS INDUSTRY -		YEAR(s) Month(s	S) Crew Supply, Drillin,	g, e(c.)			
B. WITH THIS COMPANY -				35. Was the Injured Person Incapacitized 72 Hours or				
C. IN PRESENT JOB OR POSITION -				More?				
D. ON PRESENT VESSE			38. Date of Death	36 Date of Desth				
	IEN ACCIDENT OCCURRE	n.						
37. Activity of Person at Time of Accl	dent	<u> </u>			<u></u>			
30. Specific Location of Accident on V	'essel/Facility		<u></u>		<u></u>			
39. Type of Accident (Fell, Ceughi bo	threen, elc.)		40. Resulting Injury	(Cut, Bruise, Fracture, Burn, C	He.J			
41. Peri of Body Injured	1. Peri of Body Jajured 42. Equipment Involved in Accident							
43. Specific Object, Part of It # Equips	nent in block 42., of Substance (C	nenuca, sorveni, ek	c.) Instancecuy produces	ក្រុង ក្មេបារ្វុ				
	SECTIO	ON IV, DESCRIP	TION OF CASUALT	Y				
44. Describe how accident occured, da	supproversion ou spectra	involvement and rec	ommendations for corre	clive selety measures, (Sea	Instructions and attach additional			
sheets if necessary).								
See attached from	Adam Napierski,	Master / M	T. CARLA MA	ERSK.				
45. Winess to Casually (Name, Addres	ss Telephono No.1		<u></u>					
Capt, Adam Napiers		atson, 808	Travis, Ste	, 1300, Houston	, TX 713-225-0905			
6. Witness to Casualiy (Name, Addre:								
2/0 Francis Estreb	or, c/o Eastham,	Watson, 800	3 Travis, Ste					
	SECTION V. PERSON MAK			47c. Tit				
IT. Namo (PRINT) (Last, First, Middle)	47b./	Address (City, Stelo	, Zip Code)		aster			
Napierski, Adam			Watson, Dale	e & Forney 71	ephone No. 13 - 225 - 0905			
47a. Signaturi	ß	08 Travis,	#1300, Houst	on 77002				
ΓĤ	P COAST GUARD LISE ON	V	le	PORTING OFFICE:	· <u>////////////////////////////////////</u>			
FOR COAST GUARD USE ONLY REPORTING OFFICE: MISLE Incident Investigation Activity Data Entry: MISLE Incident Investigation Activity Number (if applicable)								
	DATA COLLECTION		RMAL 🗐FO	RMAL				
· · · · · · · · · · · · · · · · · · ·	INVESTIGATOR (Name)		DATE	APPROVED BY (Name)	DATE			
arious Marine Incident 🗌 Yas 📋 ajor Marina Casually 🔲 Yas 🔲	NO							
G-2692 (03/13)	<u></u>		L		Page 2 of 5			
~ /AAI 1A1								

Morgan's Point Collision with MV Conti Peridot

Pilot boarded Carla Maersk shore side at Texas Petrochemical terminal 0900lt. I was present at the bridge and one tug was standing buy aiready. When Pliot attended the bridge informed him about one tug and he confirmed the second one should be arriving shortly. It was rainy although no fog was predicted according to information from the pllot. A car carrier have to pass ahead of us before we could departure, meanwhile completed the Master/Pllot exchange info and after both tugs were made fast we let go all head lines and all stern lines 0925lt. Once the car carrier did pass we departed at 0950lt. During channel transit there was several meetings with mostly barges, eventually the rain ceased and visibility was good. The speed orders were varying at slow and half ahead. After several meeting with other vessels we approached the Fred Hartman bridge before Barbour's Cut basin. Pilot started to raise concern about the visibility condition at Galveston and eventually advised that visibility is zero. He Informed that we may even anchor in the channel. He also suggested that vessel could turn into Barbour's Cut basin and anchor until next day. This decision had to be taken soon as we passed the bridge and was closing in to the entrance for B'Cut, however he also advised there is no tugs available and during further discussion I did not considered it would be safe enough to turn into B'Cut without tug assistance, keeping in mind that in worst case we could always anchor in the channel, pilot advise that now is anyway to late and we'll just continue. After the Fred Hartman bridge visibility worsened however still was abt 1.5nm. One more lookout with radio was ordered to proceed forward and started the fog signal. As per pilot there was one more inbound vessel we had to meet. Range on radars was set to 1.5nm and 0.75nm. When passed the B'Cut entrance turning to south we passed a barge on our port side. Lookout forward reported a vessel ahead, shape of this vessel could also be seen from bridge. The distance to target was confirmed by 2/Off with radar range to be 0.5nm. Target moved from dead ahead onto our port side and the same time pilot initiated turn to starboard by giving 10 degrees on the stbd rudder in order to pass port to port. When the meeting vessel (Conti Peridot) was on port at abt 10 degrees and at a distance of abt 0.3nm she begun to turn har bow to port. By that time I believed she is only stabilizing her heading. However her swing to port continued until her starboard broadside became visible; by that time it was obvious that she is loosing the steering. Pilot ordered hard to starboard and full ahead. Intention was to clear her bow if somehow she managed to regain her steering and veer to starboard. However Conti Peridot continued to swing to port and at abt 90 degrees from our heading she made hard contact on our port side by WBT 2P and WBT3P and Carla Maersk lost speed and was aground in mud on starboard side of the channel. Contl Peridot moved astern and separated from our hull. Pilot gave order for dead astern and stopped engine when vessel was about in middle of the channel. Carla Maersk begun very fast to list to port more than 10 degrees. Starboard anchor was lowered by gear to one shackle in water. PA announcement was made by 2/Off to all crew for proceeding to muster station and C/Off was contacted by UHF radio. Plan was to keep vessel upright and also move the cargo away from 3P and 4P. This could be done by transferring cargo into the empty cargo tanks 1P/5 or 2P/S or 10 P/S. When transferred cargo from 3P to 2S vessel begun to come upright, this was giving confidence that the list could be handled. When vessel was upright the transferring of cargo continued until ullage in 3P and 4P was at sea level, idea was that if cargo tanks 3P or 4P was actually breached the sea water will go into the tank rather than cargo escaping out from the tank.

Adam Naplerski

Master / Garla Maersk



