

1 **National Transportation Safety Board**

2  
3 Office of Marine Safety

4 Washington, D.C. 20594

5  
6  
7  
8  
9 Group Chairman's Factual Report

10  
11  
12  
13 **Engineering/IIC Group**  
14

15  
16  
17 *Stretch Duck 7*

18 DCA18MM028

19 March 30, 2020

20

1 **Contents**

2

3

4 1. Accident Information ..... 3

5 2. IIC / Engineering Group ..... 3

6 3. Accident summary ..... 4

7 4. Investigation ..... 4

8 5. Company Information..... 5

9 6. Vessel Information.....5

10 7. Postaccident Tests .....13

11

12

13

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23

**1. Accident Information**

**Vessel:** *Stretch Duck 7*  
**Accident Number:** DCA18MM028  
**Date:** July 19, 2018  
**Time:** 1908 Central Daylight Savings Time (GMT-5)  
**Location:** Table Rock Lake, Stone County, Missouri  
36°35.236' N 093°19.113' W  
**Accident type:** Sinking with loss of life  
**Complement:** 31 total (2 crew, 29 passengers)

**2. IIC / Engineering Group**

**Chairman:** Brian Young, Office of Marine Safety  
National Transportation Safety Board (NTSB)  
**Members: Party Coordinators**  
CAPT Wayne Arguin, U.S. Coast Guard  
LT George Knowles, Missouri State Highway Patrol (MSHP)  
Frank English, Ripley Entertainment Inc.  
Lora Wilson, National Weather Service / NOAA

1 **3. Accident summary**

2 About 1908 local time on July 19, 2018, the 33-foot-long amphibious passenger vessel  
3 *Stretch Duck 7*, part of a fleet of vessels operated by Ride The Ducks Branson, sank during a storm,  
4 with heavy winds that developed rapidly on Table Rock Lake near Branson, Missouri. Of the 31  
5 persons aboard, 17 fatalities resulted. Prior to the accident, the National Weather Service had  
6 issued a severe thunderstorm warning for the area advising of wind gusts of 60 mph. The manager-  
7 on-duty advised the captain and driver before departing the shoreside boarding facility to complete  
8 the lake portion of the tour before the land tour (which normally occurred first) due to the  
9 approaching weather. About 5 minutes after the vessel entered the water, the leading edge of a  
10 “derecho” passed through the area generating reported 3- to 5-foot waves and strong winds, with  
11 the highest wind gust recorded at 73 mph. The captain changed course, shortening the usual tour  
12 around an island, and attempted to exit the lake. However, during the effort to reach land, the  
13 vessel took on water and foundered approximately 250 feet away from the exit ramp near the stern  
14 of the *Showboat Branson Belle*, a moored paddle wheeler. Personnel from several fire, emergency  
15 medical services, and law enforcement agencies, along with the paddle wheeler crew and  
16 passengers, rescued and triaged 14 passengers, seven of whom were transported to local hospitals.  
17 Loss of the vessel was estimated at \$184,000.

18 **4. Investigation**

19 The NTSB was the lead federal agency in this safety investigation. The NTSB launched a  
20 full team of investigators to Branson, Missouri on July 20, 2018. The US Coast Guard, Missouri  
21 State Highway Patrol, National Weather Service, and Ride The Ducks Branson were named as  
22 parties to the investigation. While on scene, investigators interviewed passengers from the *Stretch*  
23 *Duck 7*, crew members from other duck boats, crewmembers from the *Showboat Branson Belle*,  
24 and first responders from the Branson area. In addition, investigators documented the vessel’s  
25 characteristics and damage, and they retrieved and reviewed recorded data from the vessel’s DVR  
26 (digital video recorder). Investigators returned to Branson August 21-23 to participate in the post  
27 casualty examination and surveys of lifesaving equipment, bilge pumping systems, and alarm  
28 systems. The Coast Guard established a separate Marine Board of Investigation to determine  
29 causal factors and develop recommended safety measures, but as of the date of this report, has not  
30 been scheduled.

1 **5. Company Information**

2 Ride The Ducks was founded in Branson, Missouri in 1977 and owned by Bob McDowell.  
3 Ride The Ducks agreed to provide vehicles to Boston Duck Tours in 1994 and Ride The Ducks of  
4 Seattle in 1997. In 1996, Ride The Ducks subsidiary, Amphibious Vehicle Manufacturing (AVM)  
5 received USCG approval for the patented “stretch duck.” Ride The Ducks was acquired by  
6 Herschend Family Entertainment Corporation in 2005.

7 In 2005, Amphibious Vehicle Manufacturing received USCG approval for the patented  
8 “truck duck.” Herschend sold a majority interest in the company to an independent investor in  
9 2012, and Ride The Ducks became an independent company. Chance Rides in Wichita took over  
10 this business from AVM in 2008 and built Truck Ducks until 2014. In 2014, Ride The Ducks  
11 opened in Guam, and in Mobile Alabama in 2016. The Branson operation was sold to Ripley  
12 Entertainment in December 2017. As of the date of this report, Ride The Ducks’ fleet, operated by  
13 various companies around the United States, consisted of 95 vehicles, which carried over  
14 1,500,000 passengers each year in 6 locations. The Branson operation, which was acquired by  
15 Ripley Entertainment, Inc. in December 2017, consisted of approximately 22 amphibious vessels  
16 that operated solely in the Branson, Missouri area.

17 **6. Vessel Information**

18 *Stretch Duck 7*, an amphibious vehicle, was originally built in 1944 by General Motors  
19 Corporation for the U.S. Government and based on a 2 ½ ton, six-wheel drive truck chassis, drive  
20 train, and engine. Over 21,500 of these vehicles were manufactured for military use, commonly  
21 referred to by their designation, DUKW, pronounced “Duck.”<sup>1</sup>

22 *Stretch Duck 7* was 33 feet long and 8 feet wide. During water operations with a full  
23 passenger load, the vessel’s draft was about 5 feet with a freeboard of about 2 feet. The on-road  
24 drive arrangement had been modified from the original DUKW six-wheel drive (6 x 6)  
25 arrangement to a four-wheel drive (6 x 4) system. The hull and mechanical systems of *Stretch*  
26 *Duck 7* comprised of both new and rebuilt components installed on the chassis of a 1944-vintage  
27 DUKW. The hull comprised of 14-gauge side shell, 12-gauge bottom plating, and 10-gauge bow  
28 steel and was reinforced by interior framing and exterior reinforcement ribs.

---

<sup>1</sup>The acronym DUKW signifies: “D” indicated the first year of manufacture (1942), the “U” indicated a utility amphibious vehicle, the “K” indicated all-wheel drive, and the “W” indicated two powered rear axles.

1           The conversion and operation of these former military amphibious vessels for use in the  
2 tourism industry began in 1971, in Branson Missouri. *Stretch Duck 7* was acquired by Ozark  
3 Scenic Tours Inc. in 1982 and was modified in 1996 by increasing the overall length by 15 inches,  
4 moving the captain’s station 18 inches forward for better visibility, and the hull was deepened in  
5 the stern area adding buoyancy. The vessel was inspected by the Coast Guard and issued a  
6 certificate of inspection as a small passenger vessel and land-based operation of the duck boats  
7 was regulated by the Federal Motor Carrier Safety Administration.

8           As part of RTDI’s conversion, the majority of the vessel’s hull and its systems were  
9 replaced including drive train, suspension, tires, wheels, axles, and wiring. According to RTDI’s  
10 Fleet Operations Manager, these modifications improved maneuverability and visibility for the  
11 driver, increased reserve buoyancy, and reduced trim. Vessels modified in this manner were known  
12 as “stretch ducks” and the original design before stretching were referred to as “fleet ducks” or  
13 “original ducks.” Later models of stretch ducks, known locally as “master jigs”, were updated with  
14 completely new hulls, increased beam, and higher gunwales.<sup>2</sup> A total of 56 fleet ducks were  
15 updated and converted to stretch ducks or master jig ducks, in the time period from 1996 to 2005,  
16 by . In approximately 2005, AVM commenced building a newer version of the amphibious vessel  
17 known as “truck ducks”. These vessels, built on an M35, 2 ½ ton truck chassis, were built with no  
18 original DUKW parts.<sup>3</sup> Chance Rides in Wichita took over this business from AVM in 2008 and  
19 built truck ducks until 2014.

---

<sup>2</sup> *Stretch Duck 54* was a Master Jig Duck.

<sup>3</sup> The M35 is 6x6 2.5-ton medium duty truck. It replaced the WWII CCKW “Deuce and a half” for the U.S. military which the DUKW is also based on.

1 **Stretch Duck 7 vessel particulars**

Vessel Name	<i>Stretch Duck 7</i>
Owner/Operator	Ripley Entertainment Inc. dba Ride The Ducks
Flag	United States
Type	Small passenger vessel
Built	1944
Official number	248292
State registration	MO 4463BK
Construction	Welded steel
AVM Hull number	35311427
Operator DOT number	609062
Draft	5 feet 2.375 inches
Length	33 feet
Engine	Chevrolet 427 gasoline
Horsepower	235
Beam	8 feet
Gross tonnage	4
Displacement	8 long tons

2  
3 **Propulsion System**

4 *Stretch Duck 7* was propelled on both land and water by a Chevrolet, 8-cylinder, 235-hp  
5 gasoline engine that was fitted in an engine compartment located forward of the captain’s station.  
6 For land operation, the engine output shaft was connected to an automatic transmission. The  
7 transmission was connected to a single-speed transfer case that was connected to differentials at  
8 the forward and mid axles, which were then connected to the forward and middle driving wheels.  
9 For water operation, a separate output from the transfer case was connected to the propeller through  
10 a reduction gear and a propeller shaft. The operator had to engage and disengage the propeller  
11 manually before and after each waterborne operation. The three-bladed propeller had a diameter  
12 of 24 inches.

13 A conventional (automotive style) power-assisted hydraulic steering system was used to  
14 steer the *Stretch Duck 7* on the road. On the water, steering was accomplished by a mechanical  
15 linkage (a push-pull cable) from the steering column to the rudder tiller at the stern. In the event

1 of an on-water steering failure, the vehicle was equipped with a redundant steering cable that could  
2 be connected manually to the tiller and operated with a hand crank.

3 The engine was cooled by a conventional (automotive style) closed and pressurized cooling  
4 system using a mixture of water and ethylene glycol (antifreeze). The mixture was cooled by  
5 passing it through both a traditional air-cooled radiator and a water-cooled heat exchanger called  
6 a keel cooler mounted on the exterior of the vessel, below the waterline.

### 7 **Engine Ventilation System**

8 The radiator was mounted at the front of the engine. Air flow across the radiator was  
9 generated by an engine-driven axial-flow fan and could be supplemented by air entering through  
10 the partially open engine compartment cover (hood). The engine compartment cover (hood) was  
11 hinged on the aft side and could be remotely closed by pulling a handle below the steering wheel  
12 in the captain's station.



13

14 **Top: Engine compartment cover (hood) in closed position. Bottom: Forward ventilation**  
15 **grating of *Stretch Duck 7* with spring loaded damper in closed position.**



1 Another ventilation opening forward of the hood allowed air to enter forward of the  
2 radiator. This hatch consisted of an approximately 3-square foot opening with an expanded-metal  
3 grating and a spring-loaded hinged plate which was held upwards with spring tension when closed.  
4 After passing across the radiator, the air was directed to port and starboard plenums on either side  
5 of the engine bay before exiting to the atmosphere through 28-inch wide by 7.5-inch high screened  
6 openings on both port and starboard sides, outboard of the captain's station just forward of the  
7 passenger cabin. The dampers on both sides of the vessel, the engine compartment hood, and the  
8 damper on the bow were approved by the U.S. Coast Guard and satisfied applicable regulatory  
9 requirements and were designed to be manually closed in the event of an engine fire from  
10 individual levers in the captain's station, as a means to assist in fire suppression. Closing the side  
11 dampers and engine compartment hood could also limit water ingress. When asked if the engine  
12 would continue to run after dampers were closed, the fleet operations manager stated that it wasn't  
13 a "great idea to continue under normal operation like that." And that "it would run for a while, but  
14 eventually you're going to start to experience some overheat, probably."



15

16

**Starboard side engine cooling air exhaust grating on *Stretch Duck 7*.**

1 **Forward Air Intake Hatch: Original Design and Installation**

2 According to the fleet operations manager who began working at Ride the Ducks  
3 International, LLC (RTDI) in the early 1990s, the smaller forward hatch on all fleet DUKWs and  
4 stretch ducks was designed with a wire mesh grate over the hatch, without any damper to enable  
5 closure, thus allowing air to freely flow into the engine space at all times. In approximately 1998  
6 to 1999, the Coast Guard determined that the ventilation system did not meet the requirements for  
7 fire suppression, because there was no means of closure (i.e. damper) in the event of an engine  
8 fire. In response, the current forward hatch ventilation closure design, approved by the Coast  
9 Guard, was subsequently installed on the *Stretch Duck 7* and other fleet/stretch ducks. The damper  
10 on *Stretch Duck 7* was 27 ¾ inches wide by 15 ¼ inches long and had a 3/8-inch raised lip around  
11 three sides. The damper was held closed (upward) by three spring loaded hinges which were  
12 attached to the underside of the grating's frame. The damper was held in the open position  
13 (downward) with a latch which was connected to a cable that was directly linked to the engine  
14 compartment hood closing device. When an operator pulled the handle to close the engine  
15 compartment hood, (as the captain of *Stretch Duck 7* did on the evening of the accident), the  
16 damper in the forward hatch would also close at the same time. This arrangement on the stretch  
17 ducks allowed for the damper to be kept in the open position during normal operation (allowing  
18 for additional engine ventilation/cooling) and closed for fire suppression in the event of an engine  
19 fire.

20 **Hatch Design Differences between *Stretch Duck 7* and *Stretch Duck 54***

21 Unlike the *Stretch Duck 7* which was a stretch duck version, the *Stretch Duck 54* was a  
22 master jig version. The master jig duck was designed with a wider beam and a higher bow deck  
23 than that of the fleet/original DUKWs or stretch ducks, which allowed for a greater volume of air  
24 to be drawn through the engine space. Through testing of the first master jig duck in approximately  
25 2002, RTDI found that the additional cooling provided by the keel coolers and the additional  
26 volume of air provided by the newer hull design allowed for enhanced cooling/ventilation and  
27 eliminated the need for the forward hatch opening. Based on this testing, RTDI determined that  
28 this would support keeping the forward hatch closed at all times on the master jig design except  
29 when needed to access the space for maintenance, without the need for a spring-loaded damper.

1 Thus, the *Stretch Duck 7* had a forward hatch with a releasable, spring loaded damper, and *Stretch*  
2 *Duck 54* did not.

### 3 **Damper Position on *Stretch Duck 7***

4 According to Ripley's Fleet Operations Manager, the stretch ducks generally had operated  
5 with the damper in the forward hatch in the open position to allow for additional ventilation.  
6 However, with the installation of the keel coolers on the *Stretch Duck 7*, Ripley's had been  
7 operating and testing the *Stretch Duck 7* throughout the 2018 season with the forward hatch damper  
8 in the closed position. Ripley's view was that the installation of the keel coolers likely provided  
9 sufficient cooling to the point where the damper in the forward hatch could remain closed at all  
10 times, and was exploring the feasibility of doing so longer term, similar to the design/operation of  
11 the master jig vessels using a solid cover over the forward hatch. On July 18, 2018, the forward  
12 hatch/damper of *Stretch Duck 7* was already in the closed position and would have remained so  
13 throughout the voyage.

### 14 **Approximate Damper Opening Weight**

15 Investigators sought to estimate the approximate weight required to overcome the  
16 spring tension and open the forward hatch downward from the closed position. A 3-lb. weight was  
17 placed in the center of the damper, and the damper remained closed. A 4-lb. weight was placed in  
18 the center of the damper, and the damper opened about ½-inch, and then the weight shifted down  
19 towards the opened side. Weights were then placed on the aft side of the damper, furthest from the  
20 hinges. With 2 lbs. of weight on the aft side, the damper remained closed. With 2.5 lbs. applied,  
21 the damper opened about 4.5 inches. With 3 lbs. applied to the aft side, the damper opened about  
22 8.5 inches, and with 4 lbs. the damper opened wide.

### 23 **Bilge System**

24 Although *Stretch Duck 7* was classified as an open boat with no subdivision, the bilge wells  
25 around the axles and shaft tunnel created separate spaces where bilge water could accumulate.  
26 These areas were the engine compartment forward of the front axle, the midship section, and each  
27 side of the shaft tunnel aft of the rear axle. The vessel was equipped with a total of six bilge alarms  
28 located near the bottom of the various bilge compartments. The following four spaces contained  
29 one bilge alarm: the engine compartment forward of the axle; the sea chest; and the two aft

1 compartments on either of the shaft tunnel. In the midship section there were two alarms located  
2 near the bottom of those compartments, one on each side of the vessel. The structural configuration  
3 of the midship section of the vessel allowed for water to freely communicate between the port and  
4 starboard side of the vessel, while the sea chest remained watertight. The bilge alarms were float  
5 switches that were activated when the water level exceeded a pre-determined height.

6 The *Stretch Duck 7* was equipped with three, Coast Guard-approved Rule 2000 standard  
7 model bilge pumps. Two pumps were located on the hull bottom in each of the aft bilge wells, on  
8 either side of the propeller shaft tunnel, and one pump was located on the port side between the  
9 forward and aft wheel wells. The submersible-style, 12-volt electric pumps were manufactured by  
10 Xylem Inc. Installed adjacent to each bilge pump was a “Rule-a-Matic Plus” automatic float  
11 switch, which would activate the bilge pump when the water level in the bilge reached  
12 approximately ½ inch. The Rule 2000 pumps were also equipped with 1 1/8-inch diameter plastic  
13 discharge hoses which discharged at the gunwale, two on the port side of the passenger area, and  
14 one on the starboard side. Each pump also had a separate yellow indicating light on the dashboard  
15 at the captain’s station that illuminated if the pump was in operation.

16 A bilge alarm system control box was located on the starboard side of the captain’s station  
17 under the dashboard. It was labelled as “Highwater Box” and provided audible and visual  
18 indicators of the bilge alarm status. A red light was labelled for forward, mid-section, sea chest,  
19 and aft. There was an alarm buzzer, a test button, and a mute button. When any of the bilge floats  
20 were activated, the corresponding red light on the control console illuminated and the associated  
21 audible alarm sounded.



22

23

**“Highwater Box” on the starboard side of the captain’s station of the *Stretch Duck 7***

1           The original DUKW design included a high capacity bilge pump, driven by a chain off the  
2 tail shaft, known as a “Higgins Pump.” With a capacity of about 250 gallons per minute (gpm)  
3 when the engine and propeller shaft were engaged at full throttle, the pumps were designed to  
4 ensure the DUKW’s survivability in three-foot seas or surf and 15 mph winds according to NVIC  
5 1-01.<sup>4</sup> The Higgins Pump only functioned if the engine was running and the propeller shaft  
6 was rotating; its pumping rate increased or decreased with propeller shaft rotation speed. Parts for  
7 Higgins Pumps eventually became increasingly difficult to obtain. To alleviate this problem, RTDI  
8 sought and obtained approval from the Coast Guard to remove the Higgins Pumps after enclosing  
9 all the through-hull penetrations in a single water tight sea chest.<sup>5</sup> Should a transmission shaft boot  
10 fail as it did in the *Miss Majestic* accident, only the sea chest would flood. The sea chest on *Stretch*  
11 *Duck 7* was measured after the vessel was recovered. The approximate measurements from fore to  
12 aft was 48 inches. The athwartships measurement was 33 inches and the depth was 27 inches. The  
13 sea chest was not exactly rectangular, and for volumetric calculation, it was noted that several  
14 components such as the transmission gear were installed within the sea chest. A bilge alarm was  
15 installed inside the sea chest of the *Stretch Duck 7*.

## 16 **7. Post-Accident Tests**

17           On Wednesday, July 25, 2018, the recovered *Stretch Duck 7* was inspected at a hanger by  
18 investigators and party members. The following systems were tested:

- 19           • Bilge pump operation
- 20           • Bilge pump auto activation and indication
- 21           • Bilge alarm system
- 22           • Engine compartment air shutoff system
- 23           • Steering system
- 24           • Propeller running indication

25

26

---

<sup>4</sup> See Section 8.4 of this report for discussion of NVIC 1-01.

<sup>5</sup> Sea chests on ships are larger penetrations in a ship’s hull providing suction for systems such as cooling, fire, and ballast water instead of many smaller hull penetrations. The sea chest on a *Stretch Duck* is dry, enclosing hull penetrations for the two drive shafts, propeller shaft, and keel cooler.

1 **Bilge system operation**

2 Each bilge pump was operationally tested using an external 12-volt battery, supplied by  
3 Ride The Ducks, connected to the electrical wires locally at each pump. The pumps were tested in  
4 the field using existing bilge water that had accumulated during the sinking. Each of the pumps  
5 operated as expected, near capacity of their ratings. An owner-supplied battery was provided due  
6 to the assumption that the engine would not operate after being submerged.

7 **Bilge pump automatic activation and indication**

8 The battery was then connected to the automatic bilge-float activation function for each of  
9 the bilge pumps on the vessel. When the water level was raised to activate the bilge pump  
10 activation float switch, the pump automatically started in each case. When the level dropped below  
11 the activation level, the pumps automatically stopped in each of the cases. The external battery  
12 was then relocated to the engine compartment and connected to each bilge circuit to test the  
13 operation of the indicating lights on the dashboard console. In each of the three pump locations  
14 the yellow (amber) indicating lights were illuminated when the pumps were operational.

15 **Bilge alarm system**

16 The external battery power was connected to the bilge alarm system. Each bilge float was  
17 tested, and successfully registered on the panel with audio and red visible alarms. The four areas  
18 were: sea chest, mid-section, forward, and aft. The only issue was that the audible alarm was unable  
19 to be silenced.

20 **Engine compartment air shutoff system**

21 The closing system for the port and starboard air intake dampers was tested by pulling each  
22 lever at the driver's console to inboard. In both cases, the dampers shut closed. The vessel was  
23 found at the bottom of the lake with the side dampers in the open position, and the hood cover in  
24 the closed position. The forward hatch was also found with the damper in the closed position.

25 **Steering system**

26 The front end of the *Stretch Duck 7* was jacked up to raise the front wheels off the deck.  
27 The steering system was activated by hand operation and verified proper operation of the rudder.

28

1 **Propeller running indication**

2           The external battery was connected to the “prop running” indicating light properly  
3 illuminated each time the propeller shaft was engaged.

4