TUNISIA SHIP REPAIRS

Your Mediterranean Partner



9-Annex

- A. Oil certificate
- B. DMI certificate
- C. Bilge alarm
- **D.** Themys report
- E. Tuniclean report
- F. temperature sensor

Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N* 879570/L B.P. N* 10 7050- MENZEL BOURGUIBA –TUNISIE Tél : ______ / Fax : +______ / E-mail :



TUNISIA SHIP REPAIRS Your Mediterranean Partner



9-Annex

A. Oil certificate

Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N* 879570/L B.P. N* 10 7050- MENZEL BOURGUIBA –TUNISIE Tél : +216 72 418 590 / Fax : +216 72 418 354 / E-mail : cmrtun@cmrtunisie.com



Material Safety Data Sheet

SECTION 1 PRODUCT AND COMPANY IDENTIFICATION

Taro® DP

Product Use: Engine Oil Product Number(s): 40709, 41674, 41675, 43023, 43036 Synonyms: Taro® 20 DP 30, Taro® 20 DP 40, Taro® 20 DP 50, Taro® 30 DP 30, Taro® 30 DP 40 Company Identification Chevron Marine Products LLC 44 South Broadway White Plains, NY 10601 United States of America

Transportation Emergency Response

CHEMTREC: CHEMTREC (800) 424-9300 or (703) 527-3887 Health Emergency ChevronTexaco Emergency Information Center: Emergency Information Centers are located in the USA. International collect calls accepted. (800) 231-0623 or (510) 231-0623 Product Information Product Information: 914-285-7300 MSDS Requests: 914-285-7300

SECTION 2 COMPOSITION/ INFORMATION ON INGREDIENTS

SECTION 3 HAZARDS IDENTIFICATION

IMMEDIATE HEALTH EFFECTS

Eye: Not expected to cause prolonged or significant eye irritation.

Skin: Contact with the skin is not expected to cause prolonged or significant irritation. Not expected to be harmful to internal organs if absorbed through the skin.

Ingestion: Not expected to be harmful if swallowed.

Inhalation: Not expected to be harmful if inhaled. Contains a petroleum-based mineral oil. May cause respiratory irritation or other pulmonary effects following prolonged or repeated inhalation of oil mist at airborne levels above the recommended mineral oil mist exposure limit. Symptoms of respiratory irritation may include coughing and difficulty breathing.

SECTION 4 FIRST AID MEASURES

Eye: No specific first aid measures are required. As a precaution, remove contact lenses, if worn, and flush eyes with water.

1 of 6

Taro® DP MSDS: 7841 **Global Marine Products**

City Family of Brands

Chevron

Skin: No specific first aid measures are required. As a precaution, remove clothing and shoes if contaminated. To remove the material from skin, use soap and water. Discard contaminated clothing and shoes or thoroughly clean before reuse.

Ingestion: No specific first aid measures are required. Do not induce vomiting. As a precaution, get medical advice.

Inhalation: No specific first aid measures are required. If exposed to excessive levels of material in the air, move the exposed person to fresh air. Get medical attention if coughing or respiratory discomfort occurs.

SECTION 5 FIRE FIGHTING MEASURES

FIRE CLASSIFICATION:

OSHA Classification (29 CFR 1910.1200): Not classified by OSHA as flammable or combustible.

NFPA RATINGS: Health: 0 Flammability: 1 Reactivity: 0

FLAMMABLE PROPERTIES:

Flashpoint: (Cleveland Open Cup) 220 °C (428 °F) (Min) Autoignition: No Data Available Flammability (Explosive) Limits (% by volume in air): Lower: Not Applicable Upper: Not Applicable

EXTINGUISHING MEDIA: Use water fog, foam, dry chemical or carbon dioxide (CO2) to extinguish flames.

PROTECTION OF FIRE FIGHTERS:

Fire Fighting Instructions: This material will burn although it is not easily ignited. For fires involving this material, do not enter any enclosed or confined fire space without proper protective equipment, including self-contained breathing apparatus.

Combustion Products: Highly dependent on combustion conditions. A complex mixture of airborne solids, liquids, and gases including carbon monoxide, carbon dioxide, and unidentified organic compounds will be evolved when this material undergoes combustion.

SECTION 6 ACCIDENTAL RELEASE MEASURES

Protective Measures: Eliminate all sources of ignition in vicinity of spilled material.

Spill Management: Stop the source of the release if you can do it without risk. Contain release to prevent further contamination of soil, surface water or groundwater. Clean up spill as soon as possible, observing precautions in Exposure Controls/Personal Protection. Use appropriate techniques such as applying non-combustible absorbent materials or pumping. Where feasible and appropriate, remove contaminated soil. Place contaminated materials in disposable containers and dispose of in a manner consistent with applicable regulations.

Reporting: Report spills to local authorities and/or the U.S. Coast Guard's National Response Center at (800) 424-8802 as appropriate or required.

SECTION 7 HANDLING AND STORAGE

General Handling Information: Avoid contaminating soil or releasing this material into sewage and drainage systems and bodies of water.

Static Hazard: Electrostatic charge may accumulate and create a hazardous condition when handling this material. To minimize this hazard, bonding and grounding may be necessary but may not, by themselves, be sufficient. Review all operations which have the potential of generating and accumulating

an electrostatic charge and/or a flammable atmosphere (including tank and container filling, splash filling, tank cleaning, sampling, gauging, switch loading, filtering, mixing, agitation, and vacuum truck operations) and use appropriate mitigating procedures. For more information, refer to OSHA Standard 29 CFR 1910.106, 'Flammable and Combustible Liquids', National Fire Protection Association (NFPA 77, 'Recommended Practice on Static Electricity', and/or the American Petroleum Institute (API) Recommended Practice 2003, 'Protection Against Ignitions Arising Out of Static, Lightning, and Stray Currents'.

Container Warnings: Container is not designed to contain pressure. Do not use pressure to empty container or it may rupture with explosive force. Empty containers retain product residue (solid, liquid, and/or vapor) and can be dangerous. Do not pressurize, cut, weld, braze, solder, drill, grind, or expose such containers to heat, flame, sparks, static electricity, or other sources of ignition. They may explode and cause injury or death. Empty containers should be completely drained, properly closed, and promptly returned to a drum reconditioner or disposed of properly.

SECTION 8 EXPOSURE CONTROLS/PERSONAL PROTECTION

GENERAL CONSIDERATIONS:

Consider the potential hazards of this material (see Section 3), applicable exposure limits, job activities, and other substances in the work place when designing engineering controls and selecting personal protective equipment. If engineering controls or work practices are not adequate to prevent exposure to harmful levels of this material, the personal protective equipment listed below is recommended. The user should read and understand all instructions and limitations supplied with the equipment since protection is usually provided for a limited time or under certain circumstances.

ENGINEERING CONTROLS:

Use in a well-ventilated area.

PERSONAL PROTECTIVE EQUIPMENT

Eye/Face Protection: No special eye protection is normally required. Where splashing is possible, wear safety glasses with side shields as a good safety practice.

Skin Protection: No special protective clothing is normally required. Where splashing is possible, select protective clothing depending on operations conducted, physical requirements and other substances in the workplace. Suggested materials for protective gloves include: 4H (PE/EVAL), Nitrile Rubber, Silver Shield, Viton.

Respiratory Protection: No respiratory protection is normally required.

If user operations generate an oil mist, determine if airborne concentrations are below the occupational exposure limit for mineral oil mist. If not, wear an approved respirator that provides adequate protection from the measured concentrations of this material. For air-purifying respirators use a particulate cartridge.

Use a positive pressure air-supplying respirator in circumstances where air-purifying respirators may not provide adequate protection.

Occupational Exposure Limits:

Component	Agency	TWA	STEL	Ceiling	Notation
Highly refined mineral oil (C15 - C50)	ACGIH	5 mg/m3	10 mg/m3	-	
Highly refined mineral oil (C15 - C50)	OSHA Z-1	5 mg/m3			

SECTION 9 PHYSICAL AND CHEMICAL PROPERTIES

Attention: the data below are typical values and do not constitute a specification.

Color: Brown Physical State: Liquid Odor: Petroleum odor pH: Not Applicable Vapor Pressure: <0.01 mmHg @ 37.8 °C (100 °F) Vapor Density (Air = 1): >1 Boiling Point: >315°C (599°F) Solubility: Soluble in hydrocarbons; insoluble in water Freezing Point: Not Applicable Specific Gravity: 0.89 @ 15.6°C (60.1°F) / 15.6°C (60.1°F) Volatile Organic Compounds (VOC): 1.1 %weight (Approximate) Viscosity: 10.6 cSt @ 100°C (212°F) (Min)

SECTION 10 STABILITY AND REACTIVITY

Chemical Stability: This material is considered stable under normal ambient and anticipated storage and handling conditions of temperature and pressure.

Incompatibility With Other Materials: May react with strong acids or strong oxidizing agents, such as chlorates, nitrates, peroxides, etc.

Hazardous Decomposition Products: None known (None expected) Hazardous Polymerization: Hazardous polymerization will not occur.

SECTION 11 TOXICOLOGICAL INFORMATION

IMMEDIATE HEALTH EFFECTS

Eye Irritation: The eye irritation hazard is based on evaluation of data for similar materials or product components.

Skin Irritation: The skin irritation hazard is based on evaluation of data for similar materials or product components.

Skin Sensitization: No product toxicology data available.

Acute Dermal Toxicity: The acute dermal toxicity hazard is based on evaluation of data for similar materials or product components.

Acute Oral Toxicity: The acute oral toxicity hazard is based on evaluation of data for similar materials or product components.

Acute Inhalation Toxicity: The acute inhalation toxicity hazard is based on evaluation of data for similar materials or product components.

ADDITIONAL TOXICOLOGY INFORMATION:

This product contains petroleum base oils which may be refined by various processes including severe solvent extraction, severe hydrocracking, or severe hydrotreating. None of the oils requires a cancer warning under the OSHA Hazard Communication Standard (29 CFR 1910.1200). These oils have not been listed in the National Toxicology Program (NTP) Annual Report nor have they been classified by the International Agency for Research on Cancer (IARC) as; carcinogenic to humans (Group 1), probably carcinogenic to humans (Group 2A), or possibly carcinogenic to humans (Group 2B). These oils have not been classified by the American Conference of Governmental Industrial Hygienists (ACGIH) as: confirmed human carcinogen (A1), suspected human carcinogen (A2), or confirmed animal carcinogen with unknown relevance to humans (A3).

During use in engines, contamination of oil with low levels of cancer-causing combustion products occurs. Used motor oils have been shown to cause skin cancer in mice following repeated application and continuous exposure. Brief or intermittent skin contact with used motor oil is not expected to have serious effects in humans if the oil is thoroughly removed by washing with soap and water.

SECTION 12 ECOLOGICAL INFORMATION

ECOTOXICITY

The toxicity of this material to aquatic organisms has not been evaluated. Consequently, this material should be kept out of sewage and drainage systems and all bodies of water.

ENVIRONMENTAL FATE

This material is not expected to be readily biodegradable.

SECTION 13 DISPOSAL CONSIDERATIONS

Use material for its intended purpose or recycle if possible. Oil collection services are available for used oil recycling or disposal. Place contaminated materials in containers and dispose of in a manner consistent with applicable regulations. Contact your sales representative or local environmental or health authorities for approved disposal or recycling methods.

SECTION 14 TRANSPORT INFORMATION

The description shown may not apply to all shipping situations. Consult 49CFR, or appropriate Dangerous Goods Regulations, for additional description requirements (e.g., technical name) and mode-specific or quantity-specific shipping requirements.

DOT Shipping Description: PETROLEUM LUBRICATING OIL

IMO/IMDG Shipping Description: PETROLEUM LUBRICATING OIL

ICAO/IATA Shipping Description: PETROLEUM LUBRICATING OIL

SECTION 15 REGULATORY INFORMATION

EPCRA 311/312 CATEGORIES:

- 1. Immediate (Acute) Health Effects:
- 2. Delayed (Chronic) Health Effects:
- Fire Hazard:
- Sudden Release of Pressure Hazard: NO
- 5. Reactivity Hazard:

REGULATORY LISTS SEARCHED:

01-1=IARC Group 1	03=EPCRA 313
01-2A=IARC Group 2A	04=CA Proposition 65
01-2B=IARC Group 2B	05=MA RTK
02=NTP Carcinogen	06=NJ RTK
-	07=PA RTK

No components of this material were found on the regulatory lists above.

CHEMICAL INVENTORIES:

All components comply with the following chemical inventory requirements: AICS (Australia), DSL (Canada), EINECS (European Union), ENCS (Japan), KECI (Korea), PICCS (Philippines), TSCA (United States).

NO

NO

NO

NO

NEW JERSEY RTK CLASSIFICATION:

Under the New Jersey Right-to-Know Act L. 1983 Chapter 315 N.J.S.A. 34:5A-1 et. seq., the product is to be identified as follows: PETROLEUM OIL (Motor oil)

WHMIS CLASSIFICATION:

This product is not considered a controlled product according to the criteria of the Canadian Controlled Products Regulations.

SECTION 16 OTHER INFORMATION

NFPA RATINGS: Health: 0 Flammability: 1 Reactivity: 0

HMIS RATINGS: Health: 1 Flammability: 1 Reactivity: 0

(0-Least, 1-Slight, 2-Moderate, 3-High, 4-Extreme, PPE:- Personal Protection Equipment Index recommendation, *- Chronic Effect Indicator). These values are obtained using the guidelines or published evaluations prepared by the National Fire Protection Association (NFPA) or the National Paint and Coating Association (for HMIS ratings).

LABEL RECOMMENDATION:

Label Category : ENGINE OIL 1

REVISION STATEMENT: This revision updates the following sections of this Material Safety Data Sheet: 1-16

Revision Date: 11/11/2004

ABBREVIATIONS THAT MAY HAVE BEEN USED IN THIS DOCUMENT:

TWA - Time Weighted Average
PEL - Permissible Exposure Limit
CAS - Chemical Abstract Service Number
IMO/IMDG - International Maritime Dangerous Goods
MSDS - Material Safety Data Sheet
NFPA - National Fire Protection Association (USA)
NTP - National Toxicology Program (LISA)
OSHA - Occupational Safety and Health Administration

Prepared according to the OSHA Hazard Communication Standard (29 CFR 1910.1200) and the ANSI MSDS Standard (Z400.1) by the ChevronTexaco Energy Research & Technology Company, 100 Chevron Way, Richmond, California 94802.

The above information is based on the data of which we are aware and is believed to be correct as of the date hereof. Since this information may be applied under conditions beyond our control and with which we may be unfamiliar and since data made available subsequent to the date hereof may suggest modifications of the information, we do not assume any responsibility for the results of its use. This information is furnished upon condition that the person receiving it shall make his own determination of the suitability of the material for his particular purpose.



Safety Data Sheet

SECTION 1 PRODUCT AND COMPANY IDENTIFICATION

Taro® DP

 Product Use:
 Engine Oil

 Product Number(s):
 02504, 02505, 02506, 02507, 41674, 41675, 43023, 43036

 Synonyms:
 Taro® 20 DP 30, Taro® 20 DP 30X, Taro® 20 DP 40, Taro® 20 DP 40X, Taro® 30 DP 30X, Taro® 30 DP 40, Taro® 30 DP 40X

Company Identification

Chevron Products UK Limited 1 Westferry Circus Canary Wharf London E14 4HA United Kingdom +44(0)20 77 19 3000

Transportation Emergency Response

Europe: 0044/(0)18 65 407333 Health Emergency Chevron Emergency Information Center: Emergency Information Centers are located in the USA. International collect calls accepted. (800) 231-0623 or (510) 231-0623 Product Information Product Information: +44(0)20 77 19 3000 FAX number: +44(0)20 77 19 5171

SECTION 2 HAZARDS IDENTIFICATION

CLASSIFICATION: Not classified as dangerous according to EU regulatory guidelines. IMMEDIATE HEALTH EFFECTS

Eye: Not expected to cause prolonged or significant eye irritation.

Skin: Contact with the skin is not expected to be harmful.

Ingestion: Not expected to be harmful if swallowed.

Inhalation: Not expected to be harmful if inhaled. Contains a petroleum-based mineral oil. May cause respiratory irritation or other pulmonary effects following prolonged or repeated inhalation of oil mist at airborne levels above the recommended mineral oil mist exposure limit. Symptoms of respiratory irritation may include coughing and difficulty breathing.

DELAYED OR OTHER HEALTH EFFECTS: Not classified.

ENVIRONMENTAL EFFECTS: Not classified.

SECTION 3 COMPOSITION/ INFORMATION ON INGREDIENTS

COMPONENTS	EC NUMBER	SYMBOL / RISK PHRASES	AMOUNT
------------	-----------	--------------------------	--------

Revision Number: 0 Revision Date: OCTOBER 12, 2009

1 of 6

Taro® DP MSDS: 27229

Highly refined mineral oil (C15 - C50)	*	None	60 - 100
Salts of alkyl hydroxybenzoic acids	Confidential	Xi/R38, Xi/R43, R53	%weight
Benzoic acid, hydroxy-,		Xi/R38, Xi/R43, R53	
mono-C20-28-branched alkyl derivs., calcium salts (2:1)			

*Contains one or more of the following EINECS numbers: 265-090-8, 265-091-3, 265-096-0, 265-097-6, 265-098-1, 265-101-6, 265-155-0, 265-156-6, 265-157-1, 265-158-7, 265-159-2, 265-160-8, 265-161-3, 265-166-0, 265-169-7, 265-176-5, 276-735-8, 276-736-3, 276-737-9, 276-738-4, 278-012-2. The full text of all R-phrases is shown in Section 16.

SECTION 4 FIRST AID MEASURES

Eye: No specific first aid measures are required. As a precaution, remove contact lenses, if worn, and flush eyes with water.

Skin: No specific first aid measures are required. As a precaution, remove clothing and shoes if contaminated. To remove the material from skin, use soap and water. Discard contaminated clothing and shoes or thoroughly clean before reuse.

Ingestion: No specific first aid measures are required. Do not induce vomiting. As a precaution, get medical advice.

Inhalation: No specific first aid measures are required. If exposed to excessive levels of material in the air, move the exposed person to fresh air. Get medical attention if coughing or respiratory discomfort occurs.

SECTION 5 FIRE FIGHTING MEASURES

FLAMMABLE PROPERTIES: Flashpoint: (Cleveland Open Cup) 220 °C (428 °F) Minimum Autoignition: No Data Available Flammability (Explosive) Limits (% by volume in air): Lower: Not Applicable Upper: Not Applicable

EXTINGUISHING MEDIA: Use water fog, foam, dry chemical or carbon dioxide (CO2) to extinguish flames.

PROTECTION OF FIRE FIGHTERS:

Fire Fighting Instructions: This material will burn although it is not easily ignited. For fires involving this material, do not enter any enclosed or confined fire space without proper protective equipment, including self-contained breathing apparatus.

Combustion Products: Highly dependent on combustion conditions. A complex mixture of airborne solids, liquids, and gases including carbon monoxide, carbon dioxide, and unidentified organic compounds will be evolved when this material undergoes combustion.

SECTION 6 ACCIDENTAL RELEASE MEASURES

Protective Measures: Eliminate all sources of ignition in vicinity of spilled material. **Spill Management:** Stop the source of the release if you can do it without risk. Contain release to prevent further contamination of soil, surface water or groundwater. Clean up spill as soon as possible, observing precautions in Exposure Controls/Personal Protection. Use appropriate techniques such as applying non-combustible absorbent materials or pumping. Where feasible and appropriate, remove contaminated soil. Place contaminated materials in disposable containers and dispose of in a manner consistent with applicable regulations. Reporting: Report spills to local authorities as appropriate or required.

SECTION 7 HANDLING AND STORAGE

Specific Use: Engine Oil

General Handling Information: Avoid contaminating soil or releasing this material into sewage and drainage systems and bodies of water.

Static Hazard: Electrostatic charge may accumulate and create a hazardous condition when handling this material. To minimize this hazard, bonding and grounding may be necessary but may not, by themselves, be sufficient. Review all operations which have the potential of generating and accumulating an electrostatic charge and/or a flammable atmosphere (including tank and container filling, splash filling, tank cleaning, sampling, gauging, switch loading, filtering, mixing, agitation, and vacuum truck operations) and use appropriate mitigating procedures.

Container Warnings: Container is not designed to contain pressure. Do not use pressure to empty container or it may rupture with explosive force. Empty containers retain product residue (solid, liquid, and/or vapor) and can be dangerous. Do not pressurize, cut, weld, braze, solder, drill, grind, or expose such containers to heat, flame, sparks, static electricity, or other sources of ignition. They may explode and cause injury or death. Empty containers should be completely drained, properly closed, and promptly returned to a drum reconditioner or disposed of properly.

SECTION 8 EXPOSURE CONTROLS/PERSONAL PROTECTION

GENERAL CONSIDERATIONS:

Consider the potential hazards of this material (see Section 3), applicable exposure limits, job activities, and other substances in the work place when designing engineering controls and selecting personal protective equipment. If engineering controls or work practices are not adequate to prevent exposure to harmful levels of this material, the personal protective equipment listed below is recommended. The user should read and understand all instructions and limitations supplied with the equipment since protection is usually provided for a limited time or under certain circumstances. Refer to appropriate CEN standards.

ENGINEERING CONTROLS:

Use in a well-ventilated area.

PERSONAL PROTECTIVE EQUIPMENT

Eye/Face Protection: No special eye protection is normally required. Where splashing is possible, wear safety glasses with side shields as a good safety practice.

Skin Protection: No special protective clothing is normally required. Where splashing is possible, select protective clothing depending on operations conducted, physical requirements and other substances in the workplace. Suggested materials for protective gloves include: 4H (PE/EVAL), Nitrile Rubber, Silver Shield, Viton.

Respiratory Protection: No respiratory protection is normally required. If user operations generate an oil mist, determine if airborne concentrations are below the occupational exposure limit for mineral oil mist. If not, wear an approved respirator that provides adequate protection from the measured concentrations of this material. For air-purifying respirators use a particulate cartridge.

Occupational Exposure Limits:

Component	Country/ Agency	TWA	STEL	Ceiling	Notation
Highly refined mineral oil (C15 - C50)	United Kingdom	5 mg/m3	10 mg/m3		

SECTION 9 PHYSICAL AND CHEMICAL PROPERTIES

Attention: the data below are typical values and do not constitute a specification.

Color: Brown Physical State: Liquid Odor: Petroleum odor pH: Not Applicable Vapor Pressure: <0.01 mmHg @ 37.8 °C (100 °F) Vapor Density (Air = 1): >1 **Boiling Point:** >315°C (599°F) Soluble in hydrocarbons; insoluble in water Solubility: Not Applicable Freezing Point: Density: 0.9 kg/l @ 15°C (59°F) (Typical) Viscosity: 10.6 - 14.5 mm2/s @ 100°C (212°F) Viscosity: 89 - 140 mm2/s @ 40°C (104°F) Evaporation Rate: No Data Available

SECTION 10 STABILITY AND REACTIVITY

Chemical Stability: This material is considered stable under normal ambient and anticipated storage and handling conditions of temperature and pressure.

Incompatibility With Other Materials: May react with strong acids or strong oxidizing agents, such as chlorates, nitrates, peroxides, etc.

Hazardous Decomposition Products: None known (None expected) Hazardous Polymerization: Hazardous polymerization will not occur.

SECTION 11 TOXICOLOGICAL INFORMATION

IMMEDIATE HEALTH EFFECTS

Eye Irritation: The eye irritation hazard is based on evaluation of data for similar materials or product components.

Skin Irritation: The skin irritation hazard is based on evaluation of data for similar materials or product components.

Skin Sensitization: The skin sensitization hazard is based on evaluation of data for similar materials or product components.

Acute Dermal Toxicity: The acute dermal toxicity hazard is based on evaluation of data for similar materials or product components.

Acute Oral Toxicity: The acute oral toxicity hazard is based on evaluation of data for similar materials or product components.

Acute Inhalation Toxicity: The acute inhalation toxicity hazard is based on evaluation of data for similar materials or product components.

ADDITIONAL TOXICOLOGY INFORMATION:

In accordance with the Directive 94/69/EC (21st ATP to DSD), Nota L, reference IP 346/92: "DMSO Extraction Method", we have determined that the base oils used in this preparation are not carcinogenic. During use in engines, contamination of oil with low levels of cancer-causing combustion products occurs. Used motor oils have been shown to cause skin cancer in mice following repeated application and continuous exposure. Brief or intermittent skin contact with used motor oil is not expected to have

serious effects in humans if the oil is thoroughly removed by washing with soap and water.

SECTION 12 ECOLOGICAL INFORMATION

ECOTOXICITY

This material is not expected to be harmful to aquatic organisms. The product has not been tested. The statement has been derived from the properties of the individual components.

MOBILITY

No data available.

PERSISTENCE AND DEGRADABILITY

This material is not expected to be readily biodegradable. The product has not been tested. The statement has been derived from the properties of the individual components.

POTENTIAL TO BIOACCUMULATE

Bioconcentration Factor: No data available. Octanol/Water Partition Coefficient: No Data Available

SECTION 13 DISPOSAL CONSIDERATIONS

Use material for its intended purpose or recycle if possible. Oil collection services are available for used oil recycling or disposal. Place contaminated materials in containers and dispose of in a manner consistent with applicable regulations. Contact your sales representative or local environmental or health authorities for approved disposal or recycling methods.

In accordance with European Waste Catalogue (E.W.C.) the codification is the following: 13 02 05

SECTION 14 TRANSPORT INFORMATION

The description shown may not apply to all shipping situations. Consult appropriate Dangerous Goods Regulations for additional description requirements (e.g., technical name) and mode-specific or quantity-specific shipping requirements.

ADR/RID Shipping Description: NOT REGULATED AS DANGEROUS GOODS FOR TRANSPORTATION UNDER ADR/RID

ICAO/IATA Shipping Description: PETROLEUM LUBRICATING OIL; NOT REGULATED AS DANGEROUS GOODS FOR TRANSPORT UNDER ICAO TI OR IATA DGR

IMO/IMDG Shipping Description: PETROLEUM LUBRICATING OIL; NOT REGULATED AS DANGEROUS GOODS FOR TRANSPORT UNDER THE IMDG CODE (AMENDMENT 34-08)

SECTION 15 REGULATORY INFORMATION

REGULATORY LISTS SEARCHED:

01=EU. Directive 76/769/EEC: Restrictions on the marketing and use of certain dangerous substances. 02=EU Directive 90/394/EEC: Carcinogens at work. 03=EU Directive 92/85/EEC: Pregnant or breastfeeding workers. 04=EU Directive 96/82/EC (Seveso II): Article 9. 05=EU Directive 96/82/EC (Seveso II): Articles 6 and 7. 06=EU Directive 98/24/EC: Chemical agents at work.

No components of this material were found on the regulatory lists above.

CHEMICAL INVENTORIES:

All components comply with the following chemical inventory requirements: DSL (Canada), ENCS (Japan), IECSC (China), KECI (Korea), PICCS (Philippines), TSCA (United States).

One or more components is listed on ELINCS (European Union). Secondary notification by the importer may be required. All other components are listed or exempted from listing on EINECS.

One or more components does not comply with the following chemical inventory requirements: AICS (Australia)

CLASSIFICATION - LABELING:

Under the criteria of the directive EEC/67/548 (dangerous substances) and EEC/1999/45 (dangerous preparations): Not classified

contains: Benzoic acid, hydroxy-, mono-C20-28-branched alkyl derivs., calcium salts (2:1).
 May produce an allergic reaction.
 Salts of alkyl hydroxybenzoic acids. May produce an allergic reaction.

SECTION 16 OTHER INFORMATION

REVISION STATEMENT: This is a new Material Safety Data Sheet. **Revision Date:** OCTOBER 12, 2009

Full text of R-phrases:

R38; Irritating to skin. R43; May cause sensitization by skin contact. R53; May cause long-term adverse effects in the aquatic environment.

ABBREVIATIONS THAT MAY HAVE BEEN USED IN THIS DOCUMENT:

TLV - Threshold Limit Value	TWA	-	Time Weighted Average
STEL - Short-term Exposure Limit	PEL	-	Permissible Exposure Limit
CVX - Chevron	CAS	-	Chemical Abstract Service Number

Prepared according to the criteria of EU Regulation 1907/2006 by the Chevron Energy Technology Company, 100 Chevron Way, Richmond, California 94802.

The above information is based on the data of which we are aware and is believed to be correct as of the date hereof. Since this information may be applied under conditions beyond our control and with which we may be unfamiliar and since data made available subsequent to the date hereof may suggest modifications of the information, we do not assume any responsibility for the results of its use. This information is furnished upon condition that the person receiving it shall make his own determination of the suitability of the material for his particular purpose.



HIGH PERFORMANCE, READILY BIODEGRADABLE HYDRAULIC FLUID

Description:

EnviroLogic[®] 3046 hydraulic fluid is a high performance, readily biodegradable, synthetic ISO 46 grade hydraulic fluid. It is intended for severe service, extreme high temperature (150°F), low temperature (-20°F) and high pressure (5000+psi) applications. It exhibits enhanced wear protection, cleanliness and longer life than conventional petroleum hydraulic oils. EnviroLogic® 3046 can directly replace petroleum oil based hydraulic fluids of the same viscosity, yet has reduced environmental impact in the event of a leak or spill, as it is readily biodegradable and non-sheening.

EnviroLogic® 3046 series is self certified as an Environmentally Acceptable Lubricant (EAL) compliant with 2013 US EPA Vessel General Permit (VGP).

Meets the ISO classification Hydraulic Environmental Polyalphaolefin and related hydrocarbon products (HEPR) per ISO 6743-4.

It meets or exceeds the following performance levels:

- Hatlapa .
- Rexroth 0
- Blohm + Voss
- NOV
- Sauer-Danfoss
- Cargotec/MacGregor
- IHC Merwede
- Komatsu

- 8 Gates
- Parker Hannifin/Denison
- Linde
- Thrustmaster
- Eaton/Vickers
- **Rolls Royce**
- LinkBelt

Property	Method	Requirements	Result
Kinematic Viscosity			
At 40°C, cSt	D445	41.4-50.6	48
At 100°C, cSt	D445	7.8 min	10
Viscosity Index	D2270	90 min	185
Density(60°F), kg/m ³	D4052	report	860
Pour Point, °C	D97	-15 max	-51
Flash Point (COC), °C	D92	185 min	221
Acid Number, mgKOH/g	D664	Report	0.30
Steel Pin Corrosion (4 hours, 100°C)	D665	Pass	
Deionized Water			Pass
Synthetic Salt Water			Pass



3046

Property	Method	Requirements	Result
Foam Properties (after 10 minutes)	D892		
Sequence I, mL	Tendency/Stability	50-0 max	10-0
Sequence II, mL	Tendency/Stability	50-0 max	50-0
Sequence III, mL	Tendency/Stability	50-0 max	10-0
Demulse Properties (54°C)	D1401		
Oil / Water / Emulsion		40/37/3	40/40/0
Minutes		30	10
Copper Corrosion	D130		
3hrs @ 100 °C		2 max	1a
Oxidation	D2272		
Mins to 25 psi loss			400-500
FZG		10 min	12 Pass
Hydrolytic Stability	D2619		
Copper Weight Loss, mg/cm ³			0.00
Change in Acid Number,			0.00
mgKOH/g			
Appearance of Copper Panel			1b
Vickers 35VQ25 Vane Pump*	35VQ25		Pass
Vickers V104C Vane Pump*			
Total loss of ring and vane, mg			Pass
Biodegradability, % in 28 Days	D7373	60% min	>60
Ecotoxicity			
Fathead minnow, 96h LC50, ppm	OECD 203	>100	>1,000
Daphnia magna, 48h EC50, ppm	OECD 202	>100	>120
Algae, 72h EC50, ppm	OECD 201	>100	>110
Elastomer Compatibility			
SRE-NBR-1 (100°C 168 hours)	D471		Pass
HNBR (100°C 168 hours)	D471	10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Pass
PU (100°C 168 hours)	DIN 1817		Pass
FKM (100°C 168 hours)	DIN 1817	A MARKAN AND A MARKAN	Pass
Compatibility with Select Hydraulic	the Cardonne in Sec.		
Fluids	the second second second	La ser se restante	United and the
Biodegradable Competitor stored	Tan.	Pass	Pass
Biodegradable Competitor stored	No.	Pass	Pass
Petroleum Hydraulic Fluid stored @	The second	Pass	Pass
Petroleum Hydraulic Fluid stored @ -5°F		Pass	Pass

NOTICE: While this information is presented in good faith and believed to be accurate, RSC Bio Solutions does not guarantee satisfactory results from reliance thereon. The data is offered solely for your information and RSC Bio Solutions disclaims all liability for any loss or damage from its use. Thoroughly test any application according to the product directions and independently conclude satisfactory performance. Nothing contained herein is to be construed as a recommendation to use the product in violation of any patent.

Updated: 6/2/16



obos vadukson oneer Mentor, Ohio 44060 800-861:3558 rschin.com Envitologice' is a ragisteted (lådemärk ef Terrepove Technaiopet, L Farteside Technologies, Urt Däk Böb Bio Solutiona. Farteside Technologies, Urt Däk Böb Bio Solutiona.



210 READILY BIODEGRADABLE, INDUSTRIAL ISO 100 GEAR OIL

Description:

EnviroLogic[®] 210 is a readily biodegradable, synthetic gear oil for use in industrial applications. EnviroLogic[®] 210 is an ISO 100 viscosity grade, AGMA 3EP oil, having high AW/EP properties, excellent corrosion and rust protection, and outstanding system cleanliness characteristics. In addition, it can directly replace petroleum oil based products of the same viscosity. The excellent performance characteristics of EnviroLogic[®] 210 make it suitable in a wide variety of industrial gear applications where incidental exposure of the oil to the environment is of concern. Examples are off-shore oil and gas, marine transportation & construction, steel milling, mining, and power utility operations. In the event of an oil spill or leak, the fluid biodegrades by more than 60% within 28 days, thereby minimizing any environmental impact.

EnviroLogic[®] 210 is self certified as an Environmentally Acceptable Lubricant (EAL) compliant with 2013 US EPA Vessel General Permit (VGP).

It meets or exceeds the following performance levels:

- Aegir
- AGMA 9005 (3 EP)
- AGMA 250.04/251.02 (3 EP)
- Berg
- Blohm + Voss
- Chesterton
- Cincinnati Milacron P-76
- David Brown \$1.53.101
- DIN 51517, Part 3

IHC Merwede
James Walker
Kamewa
Kemel
Ortlinghaus

- Schottel
- U.S. Steel 224
- Wartsila

Property	Method	Spec.	Result
Kinematic Viscosity	D445		Result
At 40°C, cSt		90.0 -	100
		110.0	
At 100°C, cSt			18
Viscosity Index	D2270	And an and a state of the second s	>175
Density(60°F), g/cm ³	D4052		0.84
Pour Point, °C	D97	-12 min.	-39
Flash Point (COC), °C	D92		185
Copper Corrosion	D130		
3 Hrs. @ 100°C		1b min.	1b



ASTM 5864 and ASTM D7373 compliant

210

Property	Method	Spec.	Result
Steel Pin Corrosion (4 hours, 100°C)	D665		T COMPLE
Deionized Water		Pass	Pass
Synthetic Salt Water		Pass	Pass
Foam Properties	D892		1 405
Sequence I, mL	Tendency/Stability	50/0	50/0
Sequence II, mL	Tendency/Stability	50/0	50/0
Sequence III, mL	Tendency/Stability	50/0	50/0
Demulse Properties (54°C)	D1401		50/0
Oil / Water / Emulsion			40/40/0
Minutes		30 max.	10
TOST Oxidation	D943		10
Hours to TAN of 2.0 mg			> 1500
KOH/g			
Air Release	D3427		D1674273.2
@ 90°C	9 max.		8.0
Four Ball EP	D2783		0.0
Weld Load	250 min.		> 250
LWI, kg	45 min.		> 48
Four Ball Wear	D4172 Mod.		2 10
54°C/1800 rpm/20 kg/1 Hr.	Scar, mm		0.34
Timken Wear	D2782		0.51
OK Load, Ibs.	60 min.		> 60
Fail Load, Ibs.			> 65
Gear Oil Oxidation	D2893B		
△ 100°C K.V. @ 312 Hrs.	6% max.		4.2%
Elastomer Compatibility			1.2 /0
Buna N (100°C 168 Hours)	D471		Pass
Viton (150°C 168 Hours)	D471		Pass
Biodegradability	D7373	60% min.	> 60
Ecotoxicity		0070 mm.	~ 00
athead minnow	OECD 203	>100mg/L	> 1000 mg/L
Daphnia	OECD 202	>100mg/L	> 130 mg/L
Algae	OECD 201	>100mg/L	> 120 mg/L

NOTICE: While this information is presented in good faith and believed to be accurate, RSC Bio Solutions does not guarantee satisfactory results from reliance thereon. The data is offered solely for your information and RSC Bio Solutions disclaims all liability for any loss or damage from its use. Thoroughly test any application according to the product directions and independently conclude satisfactory performance. Nothing contained herein is to be construed as a recommendation to use the product in violation of any patent.



9609 Jackson Street Mentor, Ohio 44060 800-661-3558

EnviroLopic# is a registered tradsmark of Terresolve Technologies, Ltd: Terresolve Technologies, Ltd. BBA RSC Bio Solutions. Suppright = 2014. RSC Bio Solutions. All hights Reserved. TUNISIA SHIP REPAIRS Your Mediterranean Partner



9-<u>Annex</u>

B.DMI certificate

Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N* 879570/L B.P. N* 10 7050- MENZEL BOURGUIBA –TUNISIE Tél : +216 72 418 590 / Fax : +216 72 418 354 / E-mail : <u>cmrtun@cmrtunisie.com</u>





INSPECTION CERTIFICATE EN 10204 - 3.1

Copy of the Works Certificate in our possession

Customer DMI SARL

Batch marking	1
Our ref nr	BVQ
Quality of steel	Q345B T10
Commodity	LP-81-B plate

Chemical analysis

Specification

	% C	% Mn	% Si	% P	% S
Required	≤0.20	1.00-1.60	≤0.55	≤0.040	≤0.040
Obtained	0.14	1.42	0.32	0.027	0.008

Mechanical test

	Heat treatment		σ	σ5	Ak(J) Temp: -20°C ISO-V			
			N/mm ²	9/0	1	2	3	Total/3
Standard	Quenching and tempering	470-630	Min 325	Min 12	Min. 27			Min. 27
Obtained	Quenching and tempering	540	400	26	48	51	53	51

Hardness	
7	

Diffusion Matériel Industriel

Site Internet : www.dmifrance.com E-mail : 160, Ch. de la Madrague Ville - 13015 Marseille - Tél. - Fax 5.A.R.L au capital de 100 000 € - R.C.S Marseille B 315 067 983 00033 - N° intracommunautaire FR 71 315 067 983 - Code APE 518 C

Antwerp, 12/05/16



INSPECTION CERTIFICATE EN 10204 - 3.1

Copy of the Works Certificate in our possession

Customer DMI SARL

Batch marking

Our ref nr BVQ

Quality of steel Q345B T16

Commodity LP-81-B plate Specification

Chemical analysis

	% C	% Mn	% Si	% P	% S
Required	≤0.20	1.00-1.60	<u>≤</u> 0.55	<u><0.040</u>	<u><</u> 0.040
Obtained	0.16	1.44	0.36	0.026	0.013

Mechanical test

	Heat treatment	Heat treatment $\sigma_b = \sigma_s$	σs	σ5	Ak(J) Temp: -20°C			ISO-V
		N/mm ²	N/mm ²	9/e	1	2	3	Total/3
Standard	Quenching and tempering	470-630	Min 325	Min 12	Min. 27		Min. 27	
Obtained	Quenching and tempering	525	375	26.5	48	52	55	52

Hardness	
1	

Diffusion Matériel Industriel

Site Internet : www.dmifrance.com 160, Ch. de la Madrague Ville - 13015 Marseille - Tél.

E-mail :

160, Ch. de la Madrague Ville - 13015 Marseille - Tél. S.A.R.L au capital de 100 000 € - R.C.S Marseille B 315 067 983 00033 - N° intracommunautaire FR 71 315 067 983 - Code APE 518 C

Antwerp, 12/05/16



INSPECTION CERTIFICATE EN 10204 - 3.1

Copy of the Works Certificate in our possession

Antwerp, 12/05/16

Customer	DMI SARL
Batch marking	1
Our ref nr	BVQ
Quality of steel	Q345B GB/T 1591-1994
Commodity Specification	LP-61-G

Chemical analysis

Heat-No	% C	% Mu	% Si	% Cr	% P	% S	% Mo
Standard	<u>≤</u> 0.20	1.00-1.60	≤0.55	-	≤0.040	≤0.040	-
01501-0481	0.17	1.43	0.29	-	0.025	0.014	

Mechanical test

Heat-No	Heat treatment	ot ob	σ	σ5	Ak(J)	Temp	o: -20°C	ISO-V	
		N/mm ²	N/mm ²	9/0	1	2	3	Total/3	
Standard	Quenching and tempering	470-630	Min 345	21			4	Min. 27	
01501-0481	Quenching and tempering	600	378	31	37	48	55	47	

iess (HB)
/

Diffusion Matériel Industriel

E-mail :

Site Internet : www.dmifrance.com

160, Ch. de la Madrague Ville - 13015 Marseille - Tél.

Fax S.A.R.L au capital de 100 000 € - R.C.S Marseille B 315 067 983 00033 - N° intracommunautaire FR 71 315 067 983 - Code APE 518 C



INSPECTION CERTIFICATE EN 10204 - 3.1

Copy of the Works Certificate in our possession

Antwerp, 12/05/16

Customer DMI SARL

Batch marking /

Our ref nr BVQ

Quality of steel Q345B GB/T 1591-1994

Commodity LP-61-G Specification

Chemical analysis

Heat-No	% C	% Mn	% Si	% Cr	% P	% S	% Mo
Standard	≤0.20	1.00-1.60	≤0.55	-	≤0.040	≤0.040	-
0082005837	0.15	1.47	0.28	-	0.015	0.005	-

Mechanical test

Heat-No	Heat treatment	σ_{b}	σs	σ5	Ak(J)	Tem	o: −20°C	ISO-V
	active in continent	N/mm^2	N/mm ²	0/0	1	2	3	Total/3
Standard	Quenching and tempering	470-630	Min 345	21			-	Min, 27
0082005837	Quenching and tempering	540	390	29	85	102	113	100

Hardn	ess (HB)
/	1


Diffusion Matériel Industriel

Site Internet : www.dmifrance.com 160, Ch. de la Madrague Ville - 13015 Marseille - Tél.


e.com E-mail :

160, Ch. de la Madrague Ville - 13015 Marseille - Tél. Fax S.A.R.L au capital de 100 000 € - R.C.S Marseille B 315 067 983 00033 - N° intracommunautaire FR 71 315 067 983 - Code APE 518 C VIEW A-A





LOADS		TENSION [kN]
BREAKING LOAD	BL	200
PROOF LOAD	PL	110
SAFE WORKING LOAD	SWL	100






Site Internet : www.dmifrance.com E-mail : 160, Ch. de la Madrague Ville - 13015 Marseille - Tél. S.A.R.L au capital de 100 000 € - R.C.S Marseille B 315 067 983 00033 - N° intracommunautaire FR 71 315 067 983 - Code APE 518 C

Diffusion Matériel Industriel



175



LOADS		TENSION[kN]
BREAKING LOAD	BL	200
PROOF LOAD	PL	125
SAFE WORKING LOAD	SWL	100

Welding a=3

TOTAL WEIGHT: 4,9	ko	(5	i																																					((((\$																																												1					ł	ļ	1			Ś								1												1					ĺ	l	I	1
ł				ķ	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ķ	k	ķ	k	ķ	ķ	k	k	k	k	k	k	k	k	k	k	ķ	ķ	ķ	k	k	ķ	ķ	ķ	ķ																																																		ł	ł	ł	1	1	1	1	11	11	11	91	91	91	91	.91	.91	.91	1.91	1.91	4.91	4.91	4.91	4.91	4.91	4.91	4.91	4,91	4.91	4.91	4.91	4.91	: 4.91	: 4.91	: 4.91	: 4.91	: 4,91	: 4,91	1:4.91
l				\$	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	\$	k	\$	k	\$	\$	k	k	k	k	k	k	k	k	k	k	\$	\$	\$	k	k	\$	\$	\$	\$																																																			l	ļ	1	1	1	1	1	11) (91	91	91	91	.91	.91	.91	1.91	1.91	4.91	4.91	4.91	4.91	4.91	4.91	4,91	4,91	4.91	4.91	4.91	4.91	: 4.91	: 4.91	: 4,91	: 4,91	: 4,91	: 4,91	1:4.91
	ł			k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k																																																		1	1	1		1	1)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	1:4.9
		ŀ	ŀ	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ŀ	ŀ	ł	ł	ł	ł	1	1	1	1	1	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	1							1	1	ł	ł)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4.9	: 4.9	: 4,9	: 4,9	: 4.9	1:4.9
		ŀ	ŀ	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ŀ	ŀ	ł	ł	ł	ł	1	1	1	1	1	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	1							l	ł	ł	ł)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	1:4.9
		ŀ	ŀ	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ŀ	ŀ	ł	ł	1	1	1	1	1	1	1	1	1	1	1	1	1	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	1	1	1	1	1	1	1	1							l	ł	ł	ł)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	1:4.9
		ł	ł	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ł	ł	ł	ł	1	1	1	1	1	1	1	1	1	1	1	1	1	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	1	1	1	1	1	1	1	1							1	ł	ł	ł)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4,9	1:4.9
		ł	ł	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ł	ł	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1							1	1	Ì	ł)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4,9	: 4,9	: 4.9	: 4,9	: 4,9	1:4.9
		ł	ł	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	k	ł	ł	ł	ł	1	1	1	1	1	1	1	1	1	1	1	1	1	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	ł	1	1	1	1	1	1	1	1								ł	ł	ł)	9	9	9	9	.9	.9	.9	1.9	1.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	4.9	: 4.9	: 4.9	: 4.9	: 4.9	: 4,9	: 4.9	F: 4,9



Site Internet : www.dmifrance.com E-mail: 160, Ch. de la Madrague Ville - 13015 Marseille - Tél. - Fax S.A.R.L au capital de 100 000 € - R.C.S Marseille B 315 067 983 00033 - N° intracommunautaire FR 71 315 067 983 - Code APE 518 C

Diffusion Matériel Industriel

TUNISIA SHIP REPAIRS Your Mediterranean Partner



9-<u>Annex</u>

C.Bilge alarm

Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N* 879570/L B.P. N* 10 7050- MENZEL BOURGUIBA –TUNISIE Tél : +216 72 418 590 / Fax : +216 72 418 354 / E-mail : <u>cmrtun@cmrtunisie.com</u>





DECKMA HAMBURG GmbH

<u>Address:</u>

Kieler Strasse 316 22525 Hamburg Germany

Tel.:	+4
Fax:	+4
eMail:	
Internet:	www.deckma.com

Calibration Certificate No. 5001123

This is to certify, that the below described instrument has been tested and calibrated in accordance with the requirements of MEPC.107(49).

Equipment:	15 ppm Bilge Alarm
Туре:	OMD-2005, Measuring Cell
Serial No. Measuring Cell:	5001123
Value Master Instrument:	22 ppm
Value OMD-2005 Measuring Cell:	22 ppm
Date of Calibration:	06.05.2016

Calibration is only necessary at one point >20 ppm as unit is linear between 0 ppm and 30 ppm.

DECKMA HAMBURG GmbH Kieler Str. 316 D-22525 Hamburg Germany

Electronic file. No signatures are required



Authorized Service Station

AMM	
151 Avenue des Aygalades Bat C	
13015 MARSEILLE (FRANCE)	
Tel : +++++++++++++++++++++++++++++++++++	
Fax:+	
Mail :	
Site : amm-marseille.com	

DECKM/	A HAMBURG GmbH	
Kieler Stra	asse 316	
22525 Ha	mburg	
Germany		
Tel.:	+	
Fax:	+4- (-)	
eMail:		
Internet:	www.deckma.com	

Function Check Certificate for 15 ppm Bilge Alarm

CARRIBEAN FANTASY
15 ppm Bilge Alarm Monitor
0MD-2005
5001123
16-06-109853
The Instrument has been tested according to the instructions of the manufacturer and complies with the requirements specified in IMO Resolutions MEPC.107(49).

Calibration Check

Testpoint	Calculated	Result	Tested by
Test with clean water	0 _{ppm}	0 ppm	gilles BRIAND
First Check with Test Fluid	20 ppm	21 ppm	gilles BRIANS
Second Check with Test Fluid	20 ppm	21 ppm	gilles BRIANT

Company confirms

Ray Agy AUTOMATISME MESURE MAINTENANCE

151, av. des Aygalades - 13015 MARSEILLE

Tel.:

Date 21/06/2016

RAPPORT D'INTERVENTION - lulu N° FE.27.D 14657 Dossier N° : DEMANDEUR: America Cruise Ferries NAVIRE: CARRIGIAN FANTASY SITE: BIZERTE (TURISE) **TRAVAUX EFFECTUÉS** Demande du client : Vaification annuelle du OMD 2005/15ppm Beckm 1) Verification de l'appareil avec selection Test MERC-107 Validité Juin 2017 * à l'éau - » à Oppm - » + Sppm 3- » NON confame. * Avec Solution - » 10ppm - » + 35ppm 5- » NON confame. * Après un rettoyage intense de la cellule aussi que plusious esais, la mesure reste mauvaise d'ou l'Adigation de remplace la cellule adrielle, r-S: 5007736 par une nouvelle, u.S: 50011. 2%) <u>Remfacement et nise en service</u> de la nouvelle cellale ains que son dessicant. Verfication avec Solution MEPC-107 (Juin 2017) Pau Oppm -> Oppm Pour 20ppm -> 21ppm 3) Conclusion: L'appareil est conforme ains que les commans des électronnes du cincuit au seuf 1 FOURNITURES QTE DÉSIGNATION QTE DÉSIGNATION 1 Solution d'éla Connage QTE Ellule de merure DECKart Demcant" MAIN D'ŒUVRE U.S. STAT HEURES DATE NOMS NORMALES SUPPLEMENT. ATTENTE 016/15 BRIAND TRAJET Selon Devis 16116 BRLANT MM CLIENT ures atelier : OUI NON Commentaires : avaux terminés : IUO I D NON Le: 21/6/16 SIZERVE m : Signat Nom/fonction : Signa CALON 1 TECH, MENTAGE

TUNISIA SHIP REPAIRS Your Mediterranean Partner





D. Themys report

Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N* 879570/L B.P. N* 10 7050- MENZEL BOURGUIBA – TUNISIE Tél : 4 / E-mail :



TUNISIA SHIP REPAIRS Your Mediterranean Partner





D.themys report





THEMYS AIS REVAA 230711.doc AUTOMATIC IDENTIFICATION SYSTEM (AIS) TEST REPORT

Name of ship/call sign:	CARIBBEAN FANTASY / 3EFP4
MMSI number:	372067000
Port of registry:	PANAMA
IMO Number:	8814263
Gross tonnage:	28112
Date keel laid:	25-10-1988

<u> 1 </u>	nstallation details	Yes No NA
	Item	
1.1	AIS transponder type: FURUNO FA-150	
1.2	Type approval certificate	X
1.3	Initial installation configuration report on board?	X
1.4	Drawings provided? (Antenna-, AIS-arrangement and block diagram)	X
1.5	Main source of electrical power, :	X
1.6	Emergency source of electrical power, :	X
1.7	Capacity to be verified if the AIS is connected to a battery	X
1.8	Pilot plug near pilots operating position?	X
1.9	120 V AC provided near pilot plug? (Panama and St. Lawrence requirement)	X

2 - 1	AIS programming . Static information	
2.1	MMSI number	372067000
2.2	IMO number	8814263
2.3	Radio call sign	3FEP4
2.4	Name of ship	CARIBBEAN FANTASY
2.5	Type of ship	6
2.6	Ship length and beam	176,27
2.7	Location of GPS antenna	41,146,24,4

<u>3 – A</u>	AIS programming . Dynamic information		
3.1	Ships position with accuracy and integrity status (Source: GNSS)	X	
3.2	Time in UTC (Source: GNSS)	X	
3.3	Course over ground (COG) (will fluctuate at dockside) (Source GNSS)	X	
3.4	Speed over ground (SOG) (zero at dockside) (Source: GNSS)	X	
3.5	Heading (Source: Gyro)	X	
3.6	Navigational status	X	
3.7	Rate of turn, where available (ROT)		X
3.8	Angle of heel, pitch and roll, where available		X

4 – 1	AIS programming . voyage related information	
4.1	Ships draught	
4.2	Type of cargo	X
4.3	Destination and ETA (at masters discretion)	
4.4	Route plan (optional)	
4.5	Short safety-related messages	X

3Refer to Recommendation on performance standards for a universal ship borne automatic identification system (AIS) (resolution MSC.74(69), annex 4). Page : 3





5 – Performance test using measuring instrument		Yes No	
5.1	Frequency measurements AIS ch. 1 and 2, GMDSS ch. 70	X	
5.2	Transmitting output, AIS ch. 1 and 2, GMDSS ch. 70	X	
5.3	Polling information ch. 70	X	
5.4	Read data from AIS	X	
5.5	Send data to AIS	X	
5.6	Check AIS response to	X	

6. On air performance test			
6.1	Check reception performance	X	
6.2	Confirm reception of own signal from other ship/VTS	X	
6.3	Polling by VTS/shore installation	X	

Electromagnetic interference from AIS observed to other installations?: NIL

Remarks:		
	NIL	
ĺ.		
	On following TEST REPORT the status are : Y = YES / OK N = NO / in Fault NA = Not Applicable NP = Not possible	

Name of Radio Inspector	Name of Radio Inspector	Date and place
Company		31-05-2016
THEMYS-SA	ELIE D'ELIA	MEMZEL BOURGUIBA
THEMYS	tole	
13360 ROQUEVARE		
F Sam (12 300 190 00/01)		

4Refer to Recommendation on performance standards for a universal ship borne automatic identification system (AIS) (resolution MSC.74(69), annex 4). Page : 4 hemys>

ANNUAL TESTING OF 406MHz SATELLITE EPIRBS

Issued in accordance with IMO MSC/Circ. 1040 & Guidelines as required by SOLAS reg. IV/15.9

Ship's Information

EPIRB's Information

Ship's name : CARIBBEAN FANTASY MMSI : 372067000

IMO : 8814263 Call Sign : 3FEP4

Manufacturer & type : JOTRON TRON 40S EPIRB Serial number : 14871

On board EPIRB n° :2Hydrostatic release expiration date :NABattery expiration date :09-2018Next Shore base maintenance due :09-2018Next Annual Testing due :06-2017

Cospas Sarsat Id: AE88D55C34D35D1

MSC/Circ.1040 Paragraph 3.x	Requirement	Result
3.1	Checking position and mounting for float-free operation	N/A
3.2	Verifying the presence of a firmly attached lanyard in good condition, the lanyard should be neatly stowed, and must not be tied to the vessel or mounting bracket.	OK
3.3	Carrying out visual inspection for defects.	OK
3.4	Carrying out the self-test routine.	OK
3.5	Checking that the EPIRB identification (15 Hex ID and other required information) is clearly marked on the equipment.	ОК
3.6	Decoding the EPIRB 15 Hex ID and other information from the transmitted signal, checking that the decoding information (15 Hex ID or MMSI/callsign data, as required by administration) is identical to the identification.	ОК
3.7	Checking registration through documentation or through the point of contact associated with that country code.	ОК
3.8	Checking the battery expiry date.	OK
3.9	Checking the hydrostatic release and its expiry date, as appropriate.	N/A
3.10	Checking the emission in the 406 MHz band using the self-test mode or an appropriate device to avoid activating the satellite system.	ОК
3.11	If possible, checking emission on the 121,5 MHz frequency using the self-test mode or an appropriate device to avoid activating the satellite system.	ОК
3.12	Checking that EPIRB has been maintained by an approved shore-based maintenance provider at internals required.	ОК
3.13	After the test, remounting the EPIRB in its bracket, checking that no transmission has been started.	N/A
3.14	Verifying the presence of beacon operating instructions.	OK

Test analysis gives by certified & calibrated equipment: DANPHONE FUTRONIC MK IIS/N: 01463

Measurement made by Futronic Test Box serial number: 01463 Calibration due: 10-09-2016 Control measurement on MMSI 372067000 Time/date: 15:16:03 / 31-05-2016 EPIRB 406.037 MHz # 2 Time/date: 15:17:03 / 31-05-2016 Country Code: 372 ON-AIR TEST MODE Standard Location Maritime MMSI: 067000 Beacon no: 1 Latitude Default Longitude Default Internal Navigation Device, 121.5MHz Homing B112 = 1/Yes Received Message (Bit 25-144): 8EB213C8C07FDFFB536B378BDF2086 Programmed Identifier (Bit 26-85): AE88D55C34D35D1 Freq:406,036.8 kHz Level: 239

Tuesday, May 31, 2016

Memzel Bourguiba

Elie d'Elia

Place :

Date :

Service Engineer :

Signature & Stamp :



THEMYS SAS THEMYS S.A.S : Quartier la Chaume – CD 45 - Pont de l'Étoile- 13360 Roquevaire – France Tél: + Website : www.themys-sa.com - E-mail : S.A.S au capital de 1 192 913,56 euros – RCS Marseille B 413 395 690 – NAF 511R – TVA FR 81 413 395 690 REV : 02 UPDATE : 06-01-2014 Themys ANNUAL TESTING OF 406MHz SATELLITE EPIRBS

Issued in accordance with IMO MSC/Circ. 1040 & Guidelines as required by SOLAS reg. IV/15.9

Ship's Information

Ship's name : CARIBBEAN FANTASY MMSI: 372067000

IMO : 8814263 Call Sign : 3FEP4

Manufacturer & type : JOTRON TRON 40S EPIRB Serial number : 14872

EPIRB's Information	
On board EPIRB nº :	The second
Hydrostatic release expiration date :	09-2017
Battery expiration date :	09-2018
Next Shore base maintenance due :	09-2018
Next Annual Testing due :	06-2017

Cospas Sarsat 1d: AE88D55C34D34D1

Examination of the installed 406 MHz satellite EPIRB

MSC/Circ.1040 Paragraph 3.x	Requirement	Result
3.1	Checking position and mounting for float-free operation	OK
3.2	Verifying the presence of a firmly attached lanyard in good condition, the lanyard should be neatly stowed, and must not be tied to the vessel or mounting bracket.	OK
3.3	Carrying out visual inspection for defects.	ОК
3.4	Carrying out the self-test routine.	OK
3.5	Checking that the EPIRB identification (15 Hex 1D and other required information) is clearly marked on the equipment.	OK
3.6	Decoding the EPIRB 15 Hex ID and other information from the transmitted signal, checking that the decoding information (15 Hex ID or MMSI/callsign data, as required by administration) is identical to the identification.	ОК
3.7	Checking registration through documentation or through the point of contact associated with that country code.	ОК
3.8	Checking the battery expiry date.	OK
3.9	Checking the hydrostatic release and its expiry date, as appropriate.	OK
3.10	Checking the emission in the 406 MHz band using the self-test mode or an appropriate device to avoid activating the satellite system.	ОК
3.11	If possible, checking emission on the 121,5 MHz frequency using the self-test mode or an appropriate device to avoid activating the satellite system.	OK
3.12	Checking that EPIRB has been maintained by an approved shore-based maintenance provider at internals required.	OK
3.13	After the test, remounting the EPIRB in its bracket, checking that no transmission has been started.	OK
3.14	Verifying the presence of beacon operating instructions.	OK

Test analysis gives by certified & calibrated equipment: DANPHONE FUTRONIC MK 11 S/N: 01463

Measurement made by Futronic Test Box serial number: 01463 Calibration due: 10-09-2016 Control measurement on MMSI 372067000 Time/date: 15:16:03 / 31-05-2016 EPIRB 406,037 MHz # 1 Time/date: 15:16:03 / 31-05-2016 Country Code: 372 ON-AIR TEST MODE Standard Location Maritime MMSI: 067000 Beacon no: 0 Latitude Default Longitude Default Internal Navigation Device, 121.5MHz Homing B112 = 1/Yes Received Message (Bit 25-144): 8EB213C8C07FDFFB536B378BDF2086 Programmed Identifier (Bit 26-85): AE88D55C34D34D1 Freq:406,036.9 kHz Level: 238

Place	:	

Date :

Service Engineer :

Signature & Stamp :

THEMYS

Tuesday, May 31, 2016

Memzel Bourguiba

Elie d'Elia

THEMYS S.A.S : Quartier la Chaume - CD 45 - Pont de l'Etoile- 13360 Roquevaire - France Tel: +1 - Fax; + - Website : www.themys-sa.com - E-mail : S.A.S au capital de 1 192 913,56 euros - RCS Marseille B 413 395 690 - NAF 511R - TVA FR 81 413 395 690 REV: 02 UPDATE: 06-01-2014

CLASE DE BUQUE TYPE OF VESSEL	LICENCIA Nº LICENSE Nº	SMSSM /mmsi	
PA	5126-C	372067000	

LICENCIA REGLAMENTARIA DE ESTACION DE RADIO / RADIO STATION STATUTORY LICENSE

 X
 SERVICIO INTERNACIONAL INTERNATIONAL SERVICE
 SERVICIO INTERIOR LOCAL SERVICE
 PERMISO DE NAVEGACIÓN NAVIGATION PERMIT

 De conformidad con la leyes de la República de Panamá y con el Reglamento de Radiocomunicación anexo al Convenio Internacional de Telecomunicaciones Vigente se autoriza por la presente a instalar y utilizar el equipo radioeléctrico a bordo de la nave
 PERMISO DE NAVEGACIÓN NAVIGATION PERMIT

It is hereby authorized the installation of radioelectronic equipment aboard this vessel, according with the laws of the Republic of Panama and the radiocommunications rules, annexed to the international Telecomunications Convention, currently in force

2 NOMBRE DEL BUQUE NAME OF VESSEL		3 DISTINTIVO DE LLAMADA CALL SIGN	4 LLAMADA SELECTIVA SELECTIVE CALL	5 PATENTE Nº: PATENT Nº:	6 TONELAJE BRUTO GROSS TONNAGE
CARIBBEAN FANTASY		3FEP4	372067000	43124-11	28112.00
7 PROPIETARIO Y DOMICILIO OWNER AND ADDRESS		8 AUTORIDAD ENCARGADA DE LA CONTABILIDAD Y DOMICILIO ACCOUNTING AUTHORITY AND ADDRESS		9 CATEGORIA DE SERVIO TYPE OF SERVICE	CP GMDSS
					RIO Y DOMICILIO
BAJA FERRIES S.A. DE C.V IGN ESQ. MARCELO RUBIO, COL. CE PAZ B.C.S.	ACIO ALLENDE 1025 NTRO C.P. 23000 LA	DRIVE SUITE 500, WEST BETH	WORKS INC 6903 ROCKLEDGE HESDA MD20817 P.O. BOX 5754, ARE USA	COMISION FEDERAL DE	TELECOMUNICACIONES SER PISO COL HIPODROMO 6100; MEXICO D.F.
TRANSMISORES		MARCA Y TIPO POTENCIA			SANDA DE FRECUENCIA
TRANSMITTER 2 VHF	SAILOR - RT2048	MAKE AND TYPE POWER 12048 1725W		TRANSMISSION F3E/G3E	FREQUENCY 155 to 163 MHz
2 VHF DSC (encoder)	SALOR - RM2042		********	372067000	******
2 VHF DSC (watch receiver)	SAILOR - RM2042	2	*********	372067000	*******
3 Portable two-way transceivers	ACR ELECTRONI	C - GMDSS SURVIVAL RADIO 2727	1-5W	F3E/G3E	158.3 - 156.85 MHz
1 MF/HF Radio Telephony (RTF)	FURUNO ELECTR	RIC - FS 2571C	50-500W	R3E/H3E/J3E/F1B	1.6 - 27.5 MHz
2 Telex (NBDP)	JRC/FURUNO EU	ECT JUE-87 FELCOM 15	******	372067000	*****
1 MF/HF	FURUNO ELECTRIC - FS2571C		********	372007000	********
1 MF/HF/ DSC	FURUNO ELECTRIC - FS2571C		********	372067000	**********
1 Navtex	FURUNO ELECTRIC - NX-700		********	F1B	518kHz
1 AIS	FURUNO ELECTRIC - FA-1502		2/12.5W	G2B/G1D	156.025 - 162.025 MHz
2 GPS	FURUNO ELECTR	RIC - GP-150 GP-37	****	****	1575.42 MHz
2 EGC	JRC/FURUNO EL	ECT JUE-87 FELCOM 15	14DBW	BPSK	1.5-1.6GHZ
1 SSAS	SAILOR T&T - TT-	3000SSA	14DBW	Q1/F1B	1626.5-1646.5MHZ
2 Inmarsat C	JRC/FURUNO ELI	ECT JUE-87 FELCOM 15	14DBW	BPSK	1.5 - 1.6GHz
1 Otros (others)	JOTRON - TRON	AIR VHF-AM	****		****
		N - TRON 405 MK2-372067000		G1B/A3X	NORTH E ER L.
		1 · 11011 •00 mile2012001000		GIBROA	406/121.5 MHz
EMBARCACIONES DE SALVAMENTO					
LIFE SAVING VESSELS					
	1 Radar - FURUNO	DELECTRIC - FAR 2817	25KW	PON	S-BAND
RADIO NAVEGACION	1 Radar - FURUNO	DELECTRIC - FAR 2837 S	30KW	PON	X-BAND
RADIO NAVEGACION	1 SART - JOTRON	- TRON SART 9 GHZ	400MW/0.4W	QON	9200 - 9500 MHz/9GHz
OBSERVACIONES					
****************************	************	*******	******	******	***
,					

Expedida 23 DE JUNIO DE 2016 issued

Válida hasta 22 DE JUNIO DE 2021

Derechos Fees 2016 <u>RECIBO OFICIAL No. 10092683A del 23 de junio de</u> 2016



RECORD OF PASSENGER / CARGO SHIP SAFETY RADIO EQUIPMENT (GMDSS SHIPS)

Under the provision of the International Convention for the Safety of Life at Sea (SOLAS) 1974, as amended by the November 1988 Amendments concerning Radiocommunications for the Global Maritime Distress and Safety System (GMDSS)

This form must be kept on board and be available for inspection by a nominated Surveyor or recognised organisation at all times.

File No.		Port of survey	MEMZEL BOURGUII	ЗA	Date of survey	31-05-2016
Name of Ship	CARIBBEAN FANTA	CARIBBEAN FANTASY			NA number	76747
Port of registry	PANAMA	PANAMA			Flag	PANAMA
IMO Number	8814263	Gross Tonnage	28112	I	Date keel laid	25-10-1988

CALL SIGN:	3FEP4	ID for DSC (VHF):	372067000
MMSI:	372067000	ID for DSC (MF):	372067000
SEL CALL N. for NBDP :	NA	ID for DSC (MF/HF):	NA
ID for SATELLITE EPIRB: 1° st ID for INMARSAT A/B: 2° nd ID for INMARSAT A/B:	372067000 NA NA	ID for 1°st INMARSAT C: ID for 2°nd INMARSAT C:	437206710 437206713

1	AREAS FOR WHICH THE SHIP IS EQ	UIPPED ^{[1] [2]}	2	METHODS TO ENSURE THE AVAILABILITY RADIO FACILITIES		
1.1	Al	N	2.1	DUPLICATION OF EQUIPMENT	X	
1.2	A1 + A2	N	2.2	SHORE BASED MAINTENANCE	X	
1.3	A1 + A2 + A3	X	2.3	AT SEA MAINTENANCE CAPABILITY	N	
1.4	A1 + A2 + A3 + A4	N	1			
3	COMPOSITION OF RADIO INSTALLATION					
3.1	PRIMARY SYSTEM	1	3.2	DUPLICATED SYSTEM	1	
3.1.1	VHF	X	3.2.1	VHF	x	
3.1.2	MF	X	3.2.2	MF / HF (NBDP)	N	
3.1.3	MF / HF (NBDP)	N	3.2.3	INMARSAT SES	X	
3.1.4	INMARSAT SES	X				

4	SECONDARY MEANS OF ALERTING:	
4.1	VHF (DSC)	N
4.2	MF (DSC)	N
4.3	HF (DSC)	N
4.4	406 MHZ EPIRB	X
4.5	INMARSAT EPIRB	N
4.6	VHF EPIRB	N
4.7	INMARSAT A/B	N
4.8	INMARSAT C	N

[1] The squares are to be marked with: X, to mean that the item examined was found satisfactory, with N, to mean that the item was not examined, with R, to mean that remarks concerning the item examined are to be given and with -, to mean that the item is not applicable to the ship surveyed

5	EXEMPTIONS / EQUIVALENTS (Reg. I/4; I/5; IV/3. to 3.3)	
5.1	Exemptions have been granted by the competent Authority in accordance with Regulations I/4 and IV/3 of the Convention See Authority letter Ref. No. dated:	N
5.2	Equivalents have been accepted by the competent Authority in accordance with Regulations I/5 of Convention See Authority letter Ref. No. dated: IMO documents:	N

6	RADIO INSTALLATION (Reg. IV/6).	
6.1	The required equipment is fitted and suitably located (Reg. IV/6.1 and 6.2.1 to 6.2.3) Location of the equipment: GMDSS CONSOL	37
6.2	The equipment in 6.1 is provided with the required lighting (Reg. IV/6.2.4).	<u> </u>
6,3	The equipment in 6.1 is provided with the required signal markings (Reg. IV/6.2.5).	X
6.4	The required navigational VHF equipment is available, and where necessary facilities should be available to permit radiocommunications from the wings of the navigation bridge (Reg. IV/6.3).	x
6.5	Is the radio installation (s) so located that no harmful interference affects its use and so located to ensure the greatest possibility of operational availability (Reg. IV/6.2.1).	x
6.6	Is the antenna fitted as high as possible, sufficiently separated from other antennae, and fitted in such a position that no obstacles significantly degrade its performance ?(Reg. IV/6).	x
6.7	Adequate tools and spares shall be provided to enable the equipment to be maintained (Reg. IV/15.4).	X

7		RADIO EQUIPMENT - GENERAL (Reg. IV/7)	
7.1	VHF Receiver / Transmi Type of equipment: Power supply:	tter, including Digital Selective Calling (DSC) (Reg. IV/7.1.1) SAILOR RT2048 24V	x
	State where distress alert	is initiated: GOOD	
7.2	VHF DSC Watch Receiv	rer (Reg. IV/7.1.2)	
	Type of equipment:	SAILOR RM2042	Х
<u> </u>	Power supply:	24V	
7.3		paratus (Reg. IV/7.1.III / 6.2.1)	
	(AT LEAST THREE APPA	RATUS IS TO PROVIDED ON EVERY PASSENGER SHIP AND EVERY CARGO SHIP OF 500 TONS	Х
acconsistent participation	GROSS TONNAGE AND TONNAGE)	UPWARDS AND AT LEAST TWO ABOARD CARGO SHIPS OF 300 TO 500 TONS GROSS	
	Make /Type:	ACR 2727	
	Where Located:	GMDSS CONSOL	
dus vice in the second	Approved by:	FCC ID: B668L2ACR-SR-103	
	Validity of battery:	08-2020,08-2020,12-2020	
7.4		Transponder (SART) is provided (Reg. IV/7.1.3 - III/6.2.2)	
		TUS IS TO PROVIDED ON EACH SIDE OF EVERY PASSENGER SHIP AND OF EVERY CARGO	x
Westerlands		S TONNAGE AND UPWARDS AND AT LEAST ONE ABOARD CARGO SHIPS OF 300 TO 500 TONS	A
	GROSS TO TONNAGE)		
	Type of equipment:	SART	
	Make:	JOTRON TRON SART	
	Approved by:	DNV MED-D-215	
	Validity of battery:	05-2019,05-2019	
ļ	Where stowed the SAR:	EACH WAY OUT OF BRIDGE	
7.5	NAVTEX Receiver (Reg	g. IV/7.1.4)	
	Type of equipment:	FURUNO NX-700	x
	Frequencies:	518.0 AND 480.0 KHz	
7.6		T EGC Receiver (Reg. IV/7.1.5) - WITH INMARSAT SES	
	Type of equipment:	FURUNO FELCOM 15	х
	Dedicated (yes/no):	Yes	
7.7		AFETY INFORMATION RECEIVER (Reg. IV/7.1.5)	
	Type of equipment:		N
	Dedicated (yes/no):	No	

File	/	1	1
------	---	---	---

.8 Satellite EPIRB (Reg. VHF EPIRB	INMARSAT (1.6 GHZ)		
SERIAL NUMBER:	14872	COSPAS - SARSAT (406 MHZ)	X
MMSI	372067000		
Type of equipment:	JOTRON TRON 40S MK II		
Where located:	UPPER BRIDGE		
Remote activation (yes	s/no): No		
Expiry date of battery:	09-2018		
Expiry date of hydrosta	tic release: 09-2017		

8	RADIO EQUIPMENT - SEA AREA A1 only (Reg. IV/8)	
8.1	Secondary means of alert (Reg. IV/8.1) Equipment provided: Type of the equipment:	N
8.2	VHF General Communication (Reg. IV/8.2)	N
8.3	VHF EPIRB for DSC Channel 70 (in lieu of the satellite EPIRB), is provided (Reg. IV/8.3). Type of the equipment: Where located:	N

9	RADIO EQUIPMENT - SEA AREAS A1 + A2 only(Reg. IV/9)	
9.1	MF Receiver / Transmitter (including DSC) (Reg. IV/9.1.1) Type of the equipment: Power supply: Remote control (yes/no): If yes, where located:	N
9.2	MF DSC Watch Receiver, (Reg. IV/9.1.2) Type of the equipment:	N
9.3	Secondary means of alert (Reg. IV/9.1.3) Equipment provided: Type of the equipment: Power supply: Remote control: (yes/no): If yes, where located:	N
9.4	Distress alert transmission (Reg. IV/9.2) Where from: How:	N
9.5	General communications (Reg. IV/9.3) Equipment provided: Type of the equipment: Power supply: Part of equipment mentioned in 13.1 (yes/no):	N

RADIO EQUIPMENT - SEA AREAS A1 + A2 + A3 (Reg. IV/10) INMARSAT OPTION only				
INMARSAT (Reg. IV/10.1)				
INMARSAT ship earth station (Reg. IV/10.1.1)		X		
Standard: C		x		
Type: FURUNO FELCOM 15				
Power supply: 24V				
Antenna placed: TOP OF RADAR MAST				
External equipment: FURUNO DISTRESS C	ALL UNIT			
Remote control: (yes/no): Yes				
MF Receiver / Transmitter (including DSC) (Reg. IV	/10.1.2)			
Type of the equipment: FURUNO FS-2571		х		
Power supply: 24V		~		
Remote control: (yes/no): No				
If yes, where located:				
	INMARSAT (Reg. IV/10.1)INMARSAT ship earth station (Reg. IV/10.1.1)Standard:CType:FURUNO FELCOM 15Power supply:24VAntenna placed:TOP OF RADAR MASTExternal equipment:FURUNO DISTRESS C.Remote control: (yes/no):YesMF Receiver / Transmitter (including DSC) (Reg. IVType of the equipment:FURUNO FS-2571Power supply:24VRemote control: (yes/no):No	INMARSAT (Reg. IV/10.1) INMARSAT ship earth station (Reg. IV/10.1.1) Standard: C Type: FURUNO FELCOM 15 Power supply: 24V Antenna placed: TOP OF RADAR MAST External equipment: FURUNO DISTRESS CALL UNIT Remote control: (yes/no): Yes MF Receiver / Transmitter (including DSC) (Reg. IV/10.1.2) Type of the equipment: FURUNO FS-2571 Power supply: 24V Remote control: (yes/no): No		

10.4	MF DSC Watch Receiver, (Reg. IV Type of the equipment: FURUNC	/10.1.3) D FS-2571	x
10.5			
10.5	Secondary means of alert (Reg. IV/10.1.4)		
	Equipment provided: SATELLI	TE EPIRB 406 MHZ	v
	Type of the equipment: JOTRON	I TRON 40S MK II	
	Power supply: 12V		
	Remote control: (yes/no): No		
	If yes, where located:		

11	RADIO EQUIPMENT - SEA AREAS A1 + A2 + A3 (Reg. IV/10) MF / HF OPTION only	
11.1	MF/HF (Reg. IV/10.2)	N
11.2	MF/HF Receiver / Transmitter (Reg. IV/10.2.1) including DSC and NBDP (DIRECT PRINTING TELEGRAPHY) Type of the equipment: Power supply: Remote control: (yes/no): If yes, where located:	
11.3	MF/HF DSC Watch Receiver, (Reg. IV/10.2.2) Type of the equipment:	
11.4	Secondary means of alert (Reg. IV/10.2.3) Equipment provided: Type of the equipment: Power supply: Remote control: (yes/no) If yes, where located:	
11.5	General communications (Reg. IV/10.2.4) Equipment provided: Type of the equipment: Power supply: Part of equipment mentioned in 11.2 (yes/no):	
11.6	Distress alert transmission (Reg. IV/10.3) Where from: How:	

12	RADIO EQUIPMENT - SEA AREAS A1 + A2 + A3 + A4 (Reg. IV/11)		
12.1	MF/HF (Reg. IV/11.1)	N	
12.2	MF/HF Receiver / Transmitter (Reg. IV/10.2.1) including DSC and NBDP (DIRECT PRINTING TELEGRAPHY) Type of the equipment: Power supply: Remote control: (yes/no): If yes, where located:	N	
12.3	MF/HF DSC Watch Receiver, (Reg. IV/10.2.2) Type of the equipment:	N	
12.4	Secondary means of alert (Reg. IV/10.2.3) (IV/10.2.3.1 IS MANDATORY) Equipment provided: Type of the equipment: Power supply: Remote control: (yes/no): If yes, where located:	N	
12.5	General communications (Reg. IV/10.2.4) Equipment provided: Type of the equipment: Power supply: Part of equipment mentioned in 12.2 (yes/no):	N	
12.6	Distress alert transmission (Reg. IV/10.3) Where from: How:	N	

13	SOURCES OF ENERGY (Reg. IV/13)	
13.1	Main source (Reg. IV/13.1)	X
13.2	The emergency source of energy provided fully complies with the requirements of regulations II -1/42 or II Convention (Reg. IV/13.2.)	I -1/43 of the X
13.3	Reserve source of energy (Reg. IV/13.2) Type of source: LEAD ACID XTREM Capacity: 180AH Enough for: 1 hours (1 or 6)	ж х
13.4	Independent reserve source (Reg. IV/13.3)	X
13.5	Basic equipment supplied by the reserve source: (Reg. IV/13.4)	
	Equipment: VHFDrain: 2.6 AEquipment: DSC/VHFDrain: 0.5 AEquipment: MFDrain: 9.0 AEquipment: DSC MFDrain: 2.5 AEquipment: NAVTEXDrain: 0.75 AEquipment: SES CDrain: 5.6 AEquipment: EGC SES CDrain: 1.0 AEquipment: NADrain: AEquipment: NADrain: AEquipment: NADrain: A	X
13.6	Duplicate equipment supplied by the reserve source: (Reg. IV/13.4) Equipment: VHF Drain: 2.6 A	X
	Equipment: DSC VHFDrain: 0.5 AEquipment: SES CDrain: 5.6 AEquipment: EGC SES CDrain: 1.0 AEquipment: NADrain: A	
13.7	Additional equipment supplied by the reserve source:(Reg. IV/13.4)Equipment: AISDrain: 5 AEquipment: NADrain: AEquipment: NADrain: AEquipment: NADrain: AEquipment: NADrain: AEquipment: NADrain: A	x
13.8	Electrical lighting is also supplied by the reserve source (yes/no): Yes (Reg. IV/13.5) If yes, specify relevant drain: 1.0 A	X
13.9	Charging equipment for the reserve source (Reg. IV/13.6). Type: SAILOR N1404 Capacity: 30 A Where located: GMDSS CONSOL	x
	Installation of the reserve source (Reg. IV/13.7). Siting of the reserve source: BATTERIES ROOM BRIDGE DECK	X
13.11	External equipment is connected to the radio installations (yes/no): No (Reg. IV/13.8). If yes, item 17.7 has been completed accordingly (yes/no): No	N

14	PERFORMANCE STANDARDS (Reg. IV/14)	
	All radio equipment is of an approved type (Reg. IV/14.1)	Х

15	MAINTENANCE REQUIREMENTS (Reg. IV/15)			
15.1	The equipment is readily accessible for inspection and maintenance (Reg. IV/15.2)			
15.2	Adequate information is provided to enable the equipment to be properly operated and maintained (Reg. IV/15.3)	Х		
15.3	Adequate tools and spares are provided (Reg. IV/15.4)	Х		
15.4	Availability of the equipment is ensured by at least one of the methods mentioned below: (for Sea areas A1 and A2) (Reg.			
	15.6)	Ν		
	Duplication of the equipment (yes/no):			
	Shore - based maintenance (yes/no):			
	At sea electronic maintenance capability (yes/no):			

15.5 Availability of the equipment is ensured by at least two of the methods mentioned below: (for Sea areas A3 and A4) (Reg. 15.7)
 Duplication of the equipment (yes/no): Yes
 Shore - based maintenance (yes/no): Yes
 At sea electronic maintenance (in the intervence of the intervence of

At sea electronic maintenance capability (yes/no): No

16		DUPLICATION OF	THE EQUIPMENT (Reg. IV/15.5)	
16.1	VHF Receiver / Transmitter including DSC			
	Type of the equipment:	SAILOR RT2048		х
	Power supply:	24V		Л
16.2	INMARSAT Ship Earth	Station		
	Standard:	С		х
	Type of the equipment:	JRC JUE-87		А
	Power supply:	24V		
	Antenna placed:	TOP OF RADAR MAST		
	External equipment:	NO		
	Remote control (yes/no):	No		
	If yes, where located:			
16.3	MF/HF Receiver / Transm	nitter including DSC and NBDP		
	Type of the equipment:	3		Ν
	Power supply:			IN
	Remote control (yes/no):			
	If yes, where located:			
16.4	Shore-based maintenand	te		
	Issued at:	REPUBLICA DOMINICANA	Date of issue: 19-01-2016	x
	Covering:	GMDSS EQUIPMENT	Exp. date: 19-01-2017	л
16.5	At sea electronic mainte	nance capability		
	Name of maintainer:			N
	Document from Flag Adn	inistration:		IN
	Issued at:		Date of issue:	
	Competence level:			

17		RADIO RECORDS (Reg. IV/17)				
17.1	Form:	GMDSS LOG BOOK				
	Correctly kept (yes/no):	Yes				

and a subsection	18	ITU PUBLICATIONS (ITU RR App. S16)	
Distriction of the local distriction of the local distribution of the	18.1	Latest edition of ITU PUBLICATIONS required by RADIO REGULATIONS	X

19	ADDITIONALS REQUIREMENTS FOR PASSENGER SHIPS					
19.1	Is one qualified person assigned to perform only radiocommunication duties during distress incidents (Reg. IV/16.2)					
19.2	Distress panel (Reg. IV/6.4, 6.6)					
	Were located:	IN FRONT OF CONNING PLACE	х			
19.3	equipment (Reg. IV/6.5)					
19.4	Two-way on-scene radiocommunications facility operating on 121.5 MHZ and 123.1 MHZ (Reg. IV/7.5)					
	Type:	JOTRON TRON AIR	Х			
	Where located:	RADIO ROOM				
19.5	Additional EPIRB (Reg	IV/6.4)				
	Type:	JOTRON	х			
	Where located:	GMDSS CONSOL				
	Expiry date of battery	09-2018				
	MMSI:	372067000				
	(If the satellite EPIRB is	used as a secondary means of distress alerting and is not remotely activated)				


20	EQUIPMENT RENEWED, ADDITIONS, REPAIRS AND / OR CHANGES HAVE BEEN MADE SINCE THE RECORD WAS PREPARED				
Item No.	Description	Surveyor / Port / Date			
	NIL				

Completed at: MEMZEL BOURGUIBA

on: 31-05-2016

Competent Radio Expert's name, signature and stamp

Elie D'ELIA



RINA Surveyor name and signature



REPORT OF SAFRAD INITIAL / PERIODICAL / RENEWAL This report is based on the IMO Resolution A.1053(27) adopted on 30 November 2011 "Survey guidelines under the harmonized system of survey and certification (HSSC), 2011" and meets the provisions of SOLAS 74/83 as amended by the relevant IMO Resolutions up to and including MSC.282(86)

File No. 2016/

Ship's Name CARIBBEAN FANTASY

Flag PAN	AMA				IMO No. 881420	53	RINA No. 7	74747	
Job No.					and the second second second second				
Place of S	lace of Survey MEMZEL BOURGUIBA				First Date of survey: 31-05-20 Last Date of survey: 31-05-20				
Initial Surv	vey	Periodical Survey		-	Renewal Survey				
				-	Renewal Survey				
Survey con	npletely carried out 🛛	Partial Survey:	commenced	1	continued 🔲	com	pleted 🗖		
A									
Additional	information recorded in a sep	arate narrative form:		Yes		No			
			Legend	-					
Х	Inspected and found in order (or	Yes if the item requires a Ve	s/No answor\					_	
N	Not inspected (partial survey: pe	nding items will be listed in th	Shin Sumou Statual			_			
D	Damaged and/or deficient (or No	if the item requires a Ves/No	a chip durvey datus)	Te. 11					
R	Repaired (to be detailed in the n	arrative form)	answer/, to be detailed	in the	narrative form				
NA	Not Applicable (not required by t		coccary by the Supreme		-11			_	
OOS	Out of Service	the set set as a se	cessary by the Surveyor	when	allowed by rules)				

where required, dates are to be written in the dd/mm/yyyy format.

Narrative section: to be used for additional information pertaining the filling in of the present form; repairs made or prescribed, damages or deficiencies are to be detailed in a separate narrative form.

INFORMATION ON THE SURVEY ITEMS

The numbers of the survey items coincide with those of the IMO Resolution A 1053(27) except that the first two digits have been omitted; the letters before the digits concern the certificate to which the survey relates (i.e. E = Safety equipment, P = Safety Passengers, etc.) and the type of survey (i.e. I = initial, P = periodical, etc.). Underlined survey items are relevant to amendments adopted after the date of adoption of the Resolution and therefore not included in the same. Whilst the Convention or Code references are included, when possible, it should be noted that, in general, it has not been possible to indicate where there are differing requirements dependent upon ship's keel laying date. Consequently, care should be taken in applying specific requirements, particularly where there have been amendments that are only applicable to ships built after a certain date.

INITIAL SURVEY - RI

RI.1 - EXAMINATION OF PLANS AND DESIGNS

RI.1.1 - Establishment of the sea areas declared for operation, the equipment installed to fulfil the functional requirements for the sea areas of operation, the methods adopted to ensure the availability of the functional requirements and the arrangements for supply of an emergency source of energy (if any) (SOLAS 74/88 regs.II-1/42-43 and IV/1 to 15)	X
RI.1.2 - Establishment of which radio equipment is to be surveyed and, if duplication of equipment is used as a means of ensuring the availability of the functional requirements, establishment of which is the "basic equipment" and which the "duplicated equipment" (SOLAS 74/88 reg.IV/15) (Additional radio communications equipment provided other than for SOLAS compliance should be noted)	x
RI.1.3 - Confirmation that all SOLAS equipment complies with appropriate performance standards not inferior to those adopted by IMO (SOLAS 74/88 reg.IV/14)	x
RI.1.4 - Examination of the plans for the provision and positioning of the radio installation, including sources of energy and antennas (SOLAS 74/88 regs.II-1/42-43, IV/6 and 14 and V/19)	X
RI.1.5 - Examination of the plans for the provision and positioning of the radio lifesaving appliances (SOLAS 74/88 reg.III/6)	X
RI.2 - SURVEY DURING CONSTRUCTION AND AFTER INSTALLATION	
RI.2.1 - Examination of the position, physical and electromagnetic protection and illumination of each radio installation (SOLAS 74/88 reg. IV/6)	X
RI.2.2 - Confirmation of the provision of equipment for the radio installation with due regard to the declared sea areas in which the ship will trade and the declared means of maintaining availability of functional requirements (SOLAS 74/88 regs. III/6 and IV/7 to 11, 14 and 15)	x
RI.2.3 - Confirmation of the ability to initiate the transmission of ship-to-shore distress alerts by at least two separate and independent means, from the position from which the ship is normally navigated (SOLAS 74/88/06 regs. IV/4 and 7 to 11)	X
RI.2.4 - Examination of all antennas, including:	x
RI.2.4.1 - Visual check of all antennas, including INMARSAT antennas, and feeders for satisfactory siting and absence of defects (SOL.AS 74/88 reg. IV/14)	x
RI.2.4.2 - Check of the insulation and safety of all antennas	X
RI.2.5 - Examination of the reserve source of energy, including	X

RI.2.5.1 - Check that there is sufficient capacity to operate the basic or duplicated equipment for 1 hour or 6 hours, as appropriate (SOLAS 74/88 reg. IV/13)

х

File No. / / /	Ship's Name CARIBBEAN FA	NTASY
Flag PANAMA	IMO No. 8814263 RINA No	. 76747
Job No.	First Date of survey: 31-	05-2016
Place of Survey MEMZEL BOURGUIBA	Last Date of survey: 31-	05-2016
RI.2.5.2 - If the reserve source of energy is a battery:		
RI.2.5.2.1 - Check of its siting and installation (SOLAS 74/88 reg. IV/13		X
RI.2.5.2.2 - Where appropriate, check of its condition by specific gravity measurement or voltage	measurement	
RI.2.5.2.3 - With the battery off charge, and the maximum required radio installation load connec of the battery voltage and discharge current		X
RI.2.5.2.4 - Check that the charger(s) are capable of recharging the reserve battery within 10 hour	rs (SOLAS 74/88 reg. IV/13)	x
RI.2.5.2.5 - Check that information on ship's position is provided continuously and automatically to (SOLAS 74/88 reg. IV/18)	o all two-way communication equipment	
RI.2.6 - Examination of the VHF transceiver(s), including		x
RI.2.6.1 - Check for operation on channels 6, 13 and 16 (SOLAS 74/88 regs. IV/7 and 14)		x
RI.2.6.2 - Check of the frequency tolerance, transmission line quality and radio-frequency power o	utput (SOLAS 74/88 reg. IV/14)	x
RI.2.6.3 - Check for correct operation of all controls, including priority of control units (SOLAS 74/8		x
RI.2.6.4 - Check that the equipment operates from the main, emergency (if provided) and reserve	sources of energy (SOLAS 74/88 reg. IV/13)	
RI.2.6.5 - Check the operation of the VHF control unit(s) or portable VHF equipment provided for n	avigational safety (SOLAS 74/88 reg. lV/6)	X
RI.2.6.6 - Check for correct operation by on-air contact with a coast station or other ship		X
RI.2.7 - Examination of the VHF DSC controller and channel 70 DSC watch receiver, including		X
RI.2.7.1 - Performance of an off-air check confirming the correct Maritime Mobile Service Identity 74/88 reg. IV/14)	is programmed in the equipment (SOLAS	x
RI.2.7.2 - Check for correct transmission by means of a routine or test call to a coast station, other special test equipment	r ship, on-board duplicate equipment or	x
RI.2.7.3 - Checking for correct reception by means of a routine or test call from a coast station, ot special test equipment	her ship, on-board duplicate equipment or	X
RI.2.7.4 - Check of the audibility of the VHF DSC alarm		X
RI.2.7.5 - Check that the equipment operates from the main, emergency (if provided) and reserve :	sources of energy (SOLAS 74/88 reg. IV/13)	X
RI.2.8 - Examination of the MF/HF radiotelephone equipment, including		X
RI.2.8.1 - Check that the equipment operates from the main, emergency (if provided) and reserve	sources of energy (SOLAS 74/88 reg. IV/13)	X
RI.2.8.2 - Check of the antenna tuning in all appropriate bands		x
RI.2.8.3 - Check that the equipment is within frequency tolerance on all appropriate bands (SOLAS	74/88 reg. IV/14)	X
RI.2.8.4 - Check for correct operation by contact with a coast station and/or measuring transmissio	n line quality and radio-frequency output	X
RI.2.8.5 - Check of the receiver performance by monitoring known stations on all appropriate bands	s	X
RI.2.8.6 - If control units are provided outside the navigating bridge, check that the control unit on purpose of initiating distress alerts (SOLAS 74/88 regs. IV/9, 10, 11 and 14)	the bridge has first priority for the	NA
RI.2.9 - Examination of the HF radio telex equipment, including:		NA
RI.2.9.1 - Check that the equipment operates from the main, emergency (if provided) and reserve s	sources of energy (SOLAS 74/88 reg. IV/13)	NA
RI.2.9.2 - Confirmation that the correct selective calling number is programmed in the equipment		NA
RI.2.9.3 - Check of the correct operation by inspection of recent hard copy or by a test with a coast and 11);	t radio station (SOLAS 74/88 regs. IV/10	NA
RI.2.10 - Examination of the MF/HF DSC controller(s), including:		X
RI.2.10.1 - Check that the equipment operates from the main, emergency (if provided) and reserve V/13)	sources of energy (SOLAS 74/88 reg.	
RI.2.10.2 - Confirmation that the correct Maritime Mobile Service Identity is programmed in the equ	lipment	
RI.2.10.3 - Check of the off-air self-test programme		X
		L

File No. / / /	Ship's Name	CARIBBEA	N FANTASY
Flag PANAMA	IMO No. 881426	53 RI	NA No. 76747
Job No.	First D	Date of survey	: 31-05-2016
Place of Survey MEMZEL BOURGUIBA	Last D	Date of survey	: 31-05-2016
RI.2.10.4 - Check of the operation by means of a test call on MF and/or HF to a coast radio station MF/HF transmissions (SOLAS 74/88 regs. IV/9 to 11)	if the rules of the be	rth permit the	use of X
RI.2.10.5 - Check of the audibility of the MF/HF DSC alarm			X
RI.2.11 - Examination of the MF/HF DSC watch receiver(s), including:			X
RI.2.11.1 - Confirmation that only distress and safety DSC frequencies are being monitored (SOLAS	74/88 regs. IV/9 to 12	2	X
RI.2.11.2 - Check that a continuous watch is being maintained whilst keying MF/HF radio transmitt	ers (SOLAS 74/88 reg.	. IV/12)	X
RI.2.11.3 - Check for correct operation by means of a test call from a coast station or other ship			X
RI.2.12 - Examination of the INMARSAT ship earth station(s), including:			X
RI.2.12.1 - Check that the equipment operates from the main, emergency (if provided) and reserve uninterrupted supply of information from the ship's navigational or other equipment is required en in the event of failure of the ship's main or emergency source of electrical power (SOLAS 74/88 reg	suring such information	nd that where a on remains ava	an ilable X
RI.2.12.2 - Check of the distress function by means of an approved test procedure where possible ((SOLAS 74/88 regs. IV/	/10, 12 and 14)	X
RI.2.12.3 - Check for correct operation by inspection of recent hard copy or by test call			X
RI.2.13 - Examination, if appropriate, of the NAVTEX equipment (SOLAS 74/88 regs. IV/7, 12 and 14	4), including:		X
RI.2.13.1 - Check for correct operation by monitoring incoming messages or inspecting recent hard	сору		X
RI.2.13.2 - Running the self-test programme if provided			X
RI.2.14 - Examination of the enhanced group call equipment (SOLAS 74/88 regs. IV/7 and 14), inclu	ıding:		X
RI.2.14.1 - Check for correct operation and area by monitoring incoming messages or by inspecting	recent hard copy		X
RI.2.14.2 - Running the self-test programme if provided			X
RI.2.15 - Examination, if appropriate, of the radio equipment for receipt of maritime safety inform 12 and 14), including:	nation by HF NBDP (SO	LAS 74/88 regs	. IV/7, NA
RI.2.15.1 - Check for correct operation by monitoring incoming messages or inspecting recent hard	сору		NA
RI.2.15.2 - Running the self-test programme if provided			NA
RI.2.16 - Examination of the 406 MHz satellite EPIRB (SOLAS 74/88 regs. IV/7 and 14), including:			X
RI.2.16.1 - Check of the position and mounting for float-free operation			x
RI.2.16.2 - Visual inspection for defects			x
RI.2.16.3 - Performance of the self-test routine			X
RI.2.16.4 - Check that unique beacon identification code is clearly marked on the outside of the eq unique beacon identification code and confirming it is correct	uipment and, where I	possible, decod	ing the X
RI.2.16.4bis - Check that the checking that the unique beacon identification code programmed in t beacon identification code assigned by or on behalf of the Administration	he EPIRB corresponds	with the uniqu	e X
RI.2.16.4ter - Check that the MMSI number if encoded in the beacon corresponds with the MMSI nur	mber assigned to the s	ship	X
RI.2.16.5 - Check and indication of the battery expiry date 09-2018			X
RI.2.16.6 - Check of the hydrostatic release, if provided, and indication of its expiry date 09-2017			X
RI.2.16.7 - Check of the emission on opertaional frequencies, coding and registration on the 406 M call to a satellite	Hz signal without tran	smission of a di	stress X
RI.2.16.8 - Check that the EPIRB has been subject to maintenance at intervals not exceeding five y maintenance facility (SOLAS 74/00 reg. IV/15.9	ears at an approved s	hore-based	X
RI.2.16.9 - Check, if possible, of the emission on operational frequencies, coding and registration o transmission of a distress call to the satellite system	on the 121,5 MHz hom	ing signal withc	x
RI.2.17 - Examination of the two-way VHF radiotelephone apparatus (SOLAS 74/88 reg. III/6), inclusion	ding:		X
RI.2.17.1 - Check for correct operation on channel 16 and one other by testing with another fixed o	or portable VHF install	lation	X
RI.2.17.2 - Check of the battery charging arrangements where rechargeable batteries are used			X

Flag PANAMA	Ship's Name CARIBBEAN FA	
Job No.		0. 7674
Place of Survey MEMZEL BOURGUIBA	First Date of survey: 31 Last Date of survey: 31	
		-03-201
RI.2.17.3 - Check and indication of the expiry date of primary batteries where used 08-2020	,08-2020,12-2020	x
I.2.17.4 - Check, where appropriate, of any fixed installation provided in a survival craft:		NA
1.2.18 - Examination of the search and rescue locating device(s) (SOLAS 74/88/08 regs. III/6	and IV/7 and 14), including:	x
I.2.18.1 - Check of the position and mounting		X
I.2.18.2 - Monitoring of the response on ship's 9 GHz radar		X
I.2.18.3 - Check and indication of the battery expiry date 05-2019,05-2019		x
1.2.19 - Examination of the test equipment and spares carried to ensure carriage is adequate hip trades and the declared options for maintaining availability of the functional requirement	e in accordance with the sea areas in which the nts (SOLAS 74/88 reg. IV/15)	x
1.2.20 - Check of the distress panel installed at the conning position; or, where applicable, a osition (SOLAS 74/88 reg.IV/6)	-	X
I.2.21 - Check that positional information is provided continuously and automatically to all o istress alert (SOLAS 74/88 reg.IV/6)		ι 🛛 Χ
1.2.22 - Check of the distress alarm panel installed at the conning position and its visual and OLAS 74/88 reg.IV/6)		X
1.2.23 - Check of the provision and operation of the means for two-way on-scene communica peration on 121.5 MHz and 123.1 MHz from the position from which the ship is normally navi	ation for search and rescue purposes and its igated (SOLAS 74/88 reg.IV/7)	X
I.3 - REQUIRED DOCUMENTATION TO BE PLACED ON BOARD		·····
.3.1 - Check and indication of expiry date for a valid radio licence issued by the Flag Admin		X
.3.2 - Check of the radio operator's certificates of competence (SOLAS 74/88 reg.IV/16 and	I ITU RR Art.55)	X
.3.3 - Check of the radio log (SOLAS 74/88 reg. IV/17 and ITU RR App.11)		X
.3.4 - Check the carriage of up-to-date ITU publications (ITU RR App.11)		X
1.3.5 - Check the carriage of operating manuals for all equipment (SOLAS 74/88 reg.IV/15)		Х
.3.6 - Check the carriage of service manuals for all equipment when at-sea maintenance is	the declared option (SOLAS 74/88 reg.IV/15)	NA
1.4 - COMPLETION OF THE INITIAL SURVEY		
1.4.0 - Verification of the Flag Administration's additional requirements, if any, as per releva	ant Instruction to Surveyors	NA
.4.1 - After a satisfactory survey, the Cargo Ship Safety Radio Certificate and its associated	Record of Equipment (Form R) have been issued	NA
ERIODICAL SURVEY - RP		
P.1 - EXAMINATION OF CURRENT CERTIFICATES AND OTHER RECORDS		
P.1.1 - Check of the validity, as appropriate, of the Cargo Ship Safety Equipment Certificate the Cargo Ship Safety Construction Certificate or The Cargo Ship Safety Certificate	e, the Cargo Ship Safety Radio Certificate and	Х
2.1.2 - Check of the validity of the Safety Management Certificate (SMC) and that a copy of	the Document of Compliance (DOC) is on board	
2.1.3 - Check of the validity of the International Ship Security Certificate		
2.1.4 - Check of the validity of the International Load Line Certificate or International Load	Line Exemption Certificate	
2.1.5 - Check of the validity of the International Oil Pollution Prevention Certificate		
2.1.6 - Check of the Certificate of class		
.1.7 - Check, when appropriate, of the validity of the international Certificate of Fitness fo the Certificate of Fitness for the Carriage of Dangerous Chemicals in Bulk	or the Carriage of Dangerous Chemicals in Bulk	NA
.1.8 - Check, when appropriate, of the validity of the International Certificate of Fitness fo	or the Carriage of Liquefied Gases in Bulk	NA
2.1.9 - Check, when appropriate, of the validity of the International Pollution Prevention Centry of the Stances in Bulk	rtificate for the Carriage of Noxious Liquid	NA
2.1.10 - Check, when appropriate, of the validity of the International Sewage Pollution Preve	ention Certificate	
1.11 - Check, when appropriate, of the validity of the International Air Pollution Preventio	on Certificate	
2.1.11bis - Check, when appropriate, of the validity of the International Energy Efficiency Ce	ertificate (MARPOL Appey VI roos 6 4 and 6 54	<u> </u>

File No. / / /	Ship's	Name CAI	RIBBEAN	FANTASY
Flag PANAMA	IMO No.	8814263	RINA	No. 76747
Job No.		First Date o	of survey:	31-05-2016
Place of Survey MEMZEL BOURGUIBA		Last Date o	of survey:	31-05-2016
RP.1.12 - Check that the ship's complement complies with the Minimum Safe Manning Document (SC reg.V/13(b))	LAS 74/00	reg.V/14.2) (S	OLAS 74/88	х
RP.1.13 - Check that adequate information is on board to enable the equipment to be properly open	ated and m	aintained		X
RP.1.14 - Check that the Master, officers and ratings are certificated as required by the STCW Conve	ention			X
RP.1.15 - Confirmation that any new equipment has been properly approved before installation and would affect the validity of the certificate	that no cha	anges have bee	n made such	as NA
RP.1.16 - Confirmation that a record has been kept in the period since the last survey to the satisfac required by the Radio Regulations (SOLAS 74/88 reg.IV/17)	tion of the	Administration	n and as	x
RP.1.17 - Check from documentary evidence that the actual capacity of the battery has been proved 74/88 reg.IV/13)	l in port wi	thin the last 12	months (SO	LASX
RP.1.18 - Confirmation that the provisions of RI.3 have been met				X
RP.1.19 - Check that the annual test has been carried out for the Satellite EPIRB and, if applicable, s carried out at intervals not exceeding five years (SOLAS 74/04 reg. IV/15)	shore-based	d maintenance	has been	x
RP.1.20 - Confirmation of the availability of the International Anti-Fouling System Certificate (AFS 2	001 Annex	4 Reg 2), wher	ı applicable	NA
RP.2 - SURVEY OF RADIO INSTALLATION				
RP.2.1 - The provisions of RI.2				x
RP.3 - COMPLETION OF THE PERIODICAL SURVEY				
RP.3.0 - Verification of the Flag Administration's additional requirements, if any, as per relevant Inst	truction to	Surveyors		NA
RP.3.1 - After a satisfactory survey, the Cargo Ship Safety Radio Certificate has been endorsed				X
RP.3.2 - The survey has shown that the condition of the ship is unsatisfactory. See Narrative Report f	or details			NA
RENEWAL SURVEY - RR				
RR.1 - EXAMINATION OF CURRENT CERTIFICATES AND OTHER RECORDS				
RR.1.1 - The provisions of RP.1 except for the validity of the Cargo Ship Safety Radio Certificate				
RR.2 - SURVEY OF RADIO INSTALLATION				
RR.2.1 - The provisions of RI.2				X
RR.3 - COMPLETION OF THE RENEWAL SURVEY				
RR.3.0 - Verification of the Flag Administration's additional requirements, if any, as per relevant Inst	ruction to	Surveyors		NA
RR.3.1 - After a satisfactory survey, the Cargo Ship Safety Radio Certificate has been issued as per th	e provision	s of RI.4		NA
Competent Radio Expert's name, signature, stamp: Elie D'ELIA	lu. La Ci 133 Fax	THEMYS haums Pont ba ('Etoi 860 ROOUEVAIRE M 413 395 663 00022	10	

Date: 31-05-2016

Signature:

RINA Services S.p.A.

Ship's Name CARIBBEAN FANTASY

IMO No. 8814263 RINA No. 76747

First Date of survey: 31-05-2016

Last Date of survey: 31-05-2016

NARRATIVE SECTION

<u>I</u>	

File No. 1 1 1

Flag PANAMA

Job No.

ITEM

Place of Survey MEMZEL BOURGUIBA

NOTES



113,555 (90,0002)

CHECKSHEET ON SOLAS SURVEYS-SSAS

Associated REPORT NO. URVEY_SR_1407_2016 DATE 31-05-2016 RADIO TECHNICIANS SURVEY- SSAS 1 NAT TONNAGE 28112 DATE KEEL LAID 25-10-1988 PORT OF REGISTRY PANAMA CALL SIGN 3FEP4 OFFICIAL NUMBER 43124-11 INO NUMBER 8814263 INMARSAT ID NUMBERS 437206710 Ship Security Alert System (SSAS) YES NO - a. Checked for compliance with IMO performance standards ² . - - b. Checked for compliance with IMO performance standards ² . - - b. Checked for compliance with IMO performance standards ² . - - b. Checked that a minimum of two activation points, one of which is on the navigation birdge, are provided, that are protected against inadverteri operation. (It should got be necessary for the user to remove seals or to break any I/d or cover in order to operate any control.) - - - - c. Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating any atmor or indication to be related on the ship identify and current position associated with a date and time. (The transmission includes the ship identify and current position associated and/or reset. - - d. Checked that the SSAS,	/ESS	EL	CARIBBEAN FANTASY	CL	ASS NO.	RINA 7747
NAT TONNAGE 28112 DATE KEEL LAID 25-10-1988 PORT OF REGISTRY PANAMA CALL SIGN 3FEP4 OFFICIAL NUMBER 43124-11 MO NUMBER 8814263 INMARSAT ID NUMBERS 437206710 Ship Security Alert System (SSAS) YES NO • a. Checked for compliance with IMO performance standards ² . • • b. Checked that a minimum of two activation points, one of which is on the navigation bridge, are provided, that are protected against inadvertent operation. (It should got be necessary for the user to remove seals or to break any lid or cover in order to operate any control.) ³ • • c. Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. uning of channels, setting of modes or menu options. (Operation of the activation point should not cause any alarm or indication to be raised on the ship nor should it impair the functionality of the GMDSS installation.) • d. Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating that the alert has not been generated in accordance with GMDSS distress procedures. • e. Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addresseed to a shore station and should not to ship stations.) • f. Checked that the SSAS capable of being tested. • • <td>Asso</td> <td>ciated REPORT NO</td> <td>SURVEY_SR_14-07_2016</td> <td>DATE</td> <td>31-05-2016</td> <td></td>	Asso	ciated REPORT NO	SURVEY_SR_14-07_2016	DATE	31-05-2016	
CALL SIGN 3FEP4 OFFICIAL NUMBER 43124-11 MO NUMBER 8814263 INMARSAT ID NUMBERS 437206710 Ship Security Alert System (SSAS) YES NO a. Checked for compliance with IMO performance standards ² . Image: Compliance with IMO performance standards ² . Image: Compliance with IMO performance standards ² . b. Checked that a minimum of two activation points, one of which is on the navigation bridge, are provided, that are protected against inadvertent operation. (It should got be necessary for the user to remove seals or to break any IId or cover in order to operate any control.) Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission indicated by SSAS activation points include a unique code/ identifier indicating in that the alert has not been generated in accordance with GMDSS distress procedures. Image: Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addressed to a shore station and should not to ship stations.) Image: Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset. Image: Checked that the SSAS capable of being tested. Image: Checked that, where the ship security alert system is powered from the ship's main source of electrical power is it also possible to operate the system from an alternative source of power. Redio Technician's R			RADIO TECHNICI	ANS SURVEY- SSAS	S ¹	
PORT OF REGISTRY PANAMA CALL SIGN 3FEP4 OFFICIAL NUMBER 43124-11 MO NUMBER 8814263 INMARSAT ID NUMBERS 437206710 ship Security Alert System (SSAS) YES NO a. Checked for compliance with IMO performance standards ² . Image: Compliance with Image: Compliance with out on the navigation bridge, are provided, that are protected against inadvertent operation. (It should not be necessary for the user to remove seals or to break any IId or cover in order to operate any control.) ³ Image: Compliance with Ima	VAT T	ONNAGE	28112	DATE KEEL LAID	25-10-198	8
MONUMBER 8814263 INMARSAT ID NUMBERS 437206710 hip Security Alert System (SSAS) YES NO a. Checked for compliance with IMO performance standards ² . Image: Checked that a minimum of two activation points, one of which is on the navigation bridge, are provided, that are protected against inadvertent operation. (It should not be necessary for the user to remove seals or to break any lid or cover in order to operate any control.) ³ Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating that the alert has not been generated in accordance with GMDSS distress procedures. Image: Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addressed to a shore station and should not to ship stations.) Image: Checked that the SSAS capable of being tested. Image: Checked that the SSAS capable of being tested. Image: Checked that the SSAS capable of being tested. Image: Checked that the sign and alternative source of power. Redio Technician's Remarks: Remarks: Redio Technician's Remarks: Image: Checked that the space from an alternative source of power.	ORT	OF REGISTRY				
Interaction YES NO a. Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with operation of the source of the user for endow seals or to break any life or over in order to operate any control.) ³ Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for compliance with IMO performance standards ² . Image: Checked for complicin adoc or decemplic with a date and time.	ALL	SIGN	3FEP4	OFFICIAL NUMBER	43124-1	11
 a. Checked for compliance with IMO performance standards². b. Checked that a minimum of two activation points, one of which is on the navigation bridge, are provided, that are protected against inadvertent operation. (It should not be necessary for the user to remove seals or to break any lid or cover in order to operate any control.) c. Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. uning of channels, setting of modes or menu options. (Operation of the activation point should not cause any alarm or indication to be raised on the ship nor should it impair the functionality of the GMDSS installation.) d. Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating that the alert has not been generated in accordance with GMDSS distress procedures. e. Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addressed to a shore station and should not to ship stations.) f. Checked that the SSAS capable of being tested. g. Checked that the SSAS capable of being tested. g. Checked that, where the ship security alert system is powered from the ship's main source of electrical power is it also possible to operate the system from an alternative source of power. 	N ON	UMBER	8814263	INMARSAT ID NUMBE	ERS43720	06710
b. Checked that a minimum of two activation points, one of which is on the navigation bridge, are provided, that are protected against inadvertent operation. (It should not be necessary for the user to remove seals or to break any lid or cover in order to operate any control.) Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission of the security alert possible without any adjustment of the GMDSS installation.) c. Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating that the alert has not been generated in accordance with GMDSS distress procedures. Image: Checked that the transmission includes the ship identity and current position associated with a date and time, (The transmission should be addressed to a shore station and should not to ship stations.) Image: Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset. Image: Checked that the SSAS capable of being tested. g. Checked that the SSAS capable of being tested. Image: Checked that the spice security alert system is powered from the ship's main source of electrical power Image: Checked that the spice security alert system is powered from the ship's main source of electrical power h. Checked that, where the ship security alert and iternative source of power. Image: Checked that the spice security alert system is powered from the ship's main source of electrical power Image: Checked that the spice security alert system is powered from the ship's main source of ele	hip Se	curity Alert System (SSAS)			YES	NO
b. Checked that a minimum of two activation points, one of which is on the navigation bridge, are provided, that are protected against inadvertent operation. (It should not be necessary for the user to remove seals or to break any lid or cover in order to operate any control.) Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission of the security alert possible without any adjustment of the radio system, i.e. Image: Checked that the transmission of the security alert possible without any adjustment of the GMDSS installation.) c. Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating that the alert has not been generated in accordance with GMDSS distress procedures. Image: Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addressed to a shore station and should not to ship stations.) Image: Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset. Image: Checked that the SSAS capable of being tested. g. Checked that the SSAS capable of being tested. Image: Checked that the spip security alert system is powered from the ship's main source of electrical power Image: Checked that, where the ship security alert system is powered from the ship's main source of electrical power Image: Checked that, where the ship security alert and ternative source of power.	a.	Checked for compliance with IM	MO performance standards ² .		V	
tuning of channels, setting of modes or menu options. (Operation of the activation point should not cause any alarm or indication to be raised on the ship nor should it impair the functionality of the GMDSS installation.) d. Checked that the transmission initiated by SSAS activation points include a unique code/ identifier indicating that the alert has not been generated in accordance with GMDSS distress procedures. Image: Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addressed to a shore station and should not to ship stations.) Image: Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset. Image: Checked that the SSAS capable of being tested. g. Checked that the SSAS capable of being tested. Image: Checked that, where the ship security alert system is powered from the ship's main source of electrical power Image: Checked that, where the ship security alert and the source of power. adio Technician's Remarks: Image: Checked the security alert system from an alternative source of power. Image: Checked the security alert system from an alternative source of power.		Checked that a minimum of two that are protected against inad-	o activation points, one of which is on vertent operation. (It should not be n	the navigation bridge, are provi ecessary for the user to remove	ded, 🛛 🗹 seals	
that the aleft has not been generated in accordance with GMDSS distress procedures. e. Checked that the transmission includes the ship identity and current position associated with a date and time. (The transmission should be addressed to a shore station and should not to ship stations.) Image: Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset. Image: Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset. Image: Checked that the SSAS capable of being tested. g. Checked that the SSAS capable of being tested. Image: Checked that, where the ship security alert system is powered from the ship's main source of electrical power Image: Checked that the system from an alternative source of power. adio Technician's Remarks: Image: Checked that the system is powered from the ship's main source of electrical power Image: Checked that the system from an alternative source of power.	C,	tuning of channels, setting of m	odes or menu options. (Operation of	f the activation point should not	cause	
(The transmission should be addressed to a shore station and should not to ship stations.) f. Checked that the SSAS, when activated, continues the ship security alert until deactivated and/or reset, Image: Checked that the SSAS capable of being tested. g. Checked that the SSAS capable of being tested. Image: Checked that, where the ship security alert system is powered from the ship's main source of electrical power h. Checked that, where the ship security alert system from an alternative source of power. adio Technician's Remarks:	d.	Checked that the transmission that the alert has not been gen	initiated by SSAS activation points in erated in accordance with GMDSS di	clude a unique code/ identifier ir istress procedures.	ndicating 🛛	
g. Checked that the SSAS capable of being tested. Image: Checked that the SSAS capable of being tested. h. Checked that, where the ship security alert system is powered from the ship's main source of electrical power Image: Checked that is it also possible to operate the system from an alternative source of power. adio Technician's Remarks:	ē,	Checked that the transmission (The transmission should be a	includes the ship identity and current ddressed to a shore station and shou	t position associated with a date Id not to ship stations.)	and time, 🔽	
h. Checked that, where the ship security alert system is powered from the ship's main source of electrical power is it also possible to operate the system from an alternative source of power.	ť,	Checked that the SSAS, when	activated, continues the ship security	/ alert until deactivated and/or re	set, 🗹	
is it also possible to operate the system from an alternative source of power. adio Technician's Remarks:	g.	Checked that the SSAS capat	le of being tested.			
	h.	Checked that, where the ship s is it also possible to operate the	ecurity alert system is powered from a system from an alternative source of	the ship's main source of electri of power.	cal power 🗹	
NII	adio	Technician's Remarks:				
NIL			NIL			
		THEMYS		Elie D	'ELIA	
Ju La Chaume Port de l'Escale Elie D'ELIA		13360 HOQUEVAIRE		Radio Tech	nician's Signature	

THEMYS-SA

Company


31-05-2016

Date

The following part of the survey should always be performed by a fully qualified Radio Technician who has adequate knowledge of the ISPS Code Regulations pertaining to the SSAS, the SOLAS Convention, as amended, and the IMO performance standards for SSAS. 2

If installed on or after 1 July 2004, conforms to performance standards not inferior to those specified in the Annex resolution MSC.147(77).

If installed before 1 July 2004, conforms to performance standards not inferior to those specified in the Annex to resolution MSC.136(76). Personnel involved in the survey of the SSAS installation and testing are to have the necessary security clearance to know where the "secure" activation point(s) are located on board. If they do not have security clearance, then the appropriate ship's crew/operating person is to be requested to activate the SSAS "IN TEST MODE" from the bridge and from the other "secure" location.



Objet:	RE: Inmarsat-C Ship Security Alert Message [IMN:437206711 REF:841791]			
Date:	mardi 31 mai 2016 18:23:45 heure normale d'Europe centrale			
De:	threat			
À:	'Gustavo Abaroa Galvez'			
Cc:	'CF Master', 'Area Tecnica'			
Pièces join	ointes: image003.jpg			

Good day Dear Ing. Gustavo Abaroa PDT y OCPM - DPA & CSO DIRECCION GENERAL BAJA FERRIES S.A. DE C.V.

Message have been received in good order. Thanks for your prompt response.

Best regards,



Leonel Medina MSc. Nautical Engineer Maritime Ships Security Department Directorate of Merchant Marine Panama Maritime Authority Telephone: +

www.segumar.com

<u>Merchant Marine Circular No. 313</u> Validity of color copies of original documents

On board of the Panamanian Flagged Vessels, the color copies of the following documents shall be valid for a period no longer than thirty (30) calendars day, counting from the issuing date of the respective documents, until the original documents are received onboard; as evidence that the application is being processed:

- 1. International Ship Security Certificate (ISSC)
- 2. Continuous Synopsis Record (CSR)

De: Gustavo Abaroa Galvez [mailto: Enviado el: martes, 31 de mayo de 2016 11:34 a.m.

Para:

CC: CF Master; Area Tecnica

Asunto: RV: Inmarsat-C Ship Security Alert Message [IMN:437206711 REF:841791]

Dear Sirs We confirm below Alert message is a Test and not a real alarm I already spoke to Master and confirmed with agreed password Please disregard this Alert message Kind regards

Ing. Gustavo Abaroa :: PDT y OCPM - DPA & CSO DIRECCION GENERAL :: BAJA FERRIES S.A. DE C.V. Ave. Emilio Barragán y Prolongación Carnaval s/n, Fracc. Playa Sur, Mazatlan, Sinaloa tel.

: http://www.bajaferries.com.mx

Por favor considera el ambiente antes de imprimir este e-mail. Recicla Reduce Reusa

-----Mensaje original-----

De: 437206711 inmc@SkyFile-C.com Enviado el: martes, 31 de mayo de 2016 10:10 a.m. Para: Area Tecnica Asunto: Inmarsat-C Ship Security Alert Message [IMN:437206711 REF:841791]

Caribbean Fantasy: IMO 8814263: Call Sign 3FEP4: MMSI 372067000

++++

__ Información de ESET Endpoint Security, versión de la base de datos de firmas de virus 13574 (20160531)

El mensaje fue verificado por ESET Endpoint Security.

part000.txt - esta correcto

http://www.eset-la.com

Información de ESET Endpoint Security, versión de la base de datos de firmas de virus

El mensaje fue verificado por ESET Endpoint Security.

Mensaje de correo electronico - esta correcto

http://www.eset-la.com

Información de ESET Endpoint Security, versión de la base de datos de firmas de virus 13574 (20160531)

El mensaje fue verificado por ESET Endpoint Security.

Mensaje de correo electronico - esta correcto image003.jpg - esta correcto

http://www.eset-la.com

TUNISIA SHIP REPAIRS Your Mediterranean Partner





E.tuniclean report

Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N° 879570/L B.P. N° 10 7050- MENZEL BOURGUIBA –TUNISIE Tél : 4 / Fax : 4 / E-mail :






GALLEY EXHAUST SAMPLE REPORT Pre and Post photography For the cleaning of the Kitchen Exhaust Ductwork


Place : Menzel Bourguiba CARIBBEAN FANTASY Date : May 2016


IMO: 8814263 MMSI: 372067000


PHOTOGRAPHIC REPORT

America Cruise Ferries













RECOVERY DUCT CLEANING SAMPLE REPORT Pre and Post photography




PHOTOGRAPHIC REPORT




















































1	
1	
1	
	1 1
	1
1	
1	
1	
1	
1	
I contract of the second se	
L.	

TUNISIA SHIP REPAIRS Your Mediterranean Partner



9-<u>Annex</u>

F.temperature sensor


Direction Technique / Technical Department / service: Quality and studies COMPAGNIE MEDITERRANEENNE DE REPARATION Tunisie S.A. au capital de 4 000 000 DT RC Tunis B2426522004-Matricule fiscal N* 879570/L B.P. N* 10 7050- MENZEL BOURGUIBA – TUNISIE Tél : // Fax : // E-mail :





Bible 1001225


Bible moteur DAIHATSU 6DL28 en version genset / BAJA Ferries (Navire Carribean Fantasy / Affaire 531097) Avis N° 21926 du 10/05/16

Numéro d'article	Entrepôt	Nom du produit	Commentaire	N° de plan
1016204	6,00	MD1.2 K 100 3/4 3 F1A	CYLINDER EXHAUST TEMPERATURE SENSOR	3D101C091-
1016204	2,00	MD1.2 K 100 3/4 3 F1A	BEFORE TURBOCHARGER TEMPERATURE SENSOR	3D101C091-
9280122	8,00	DGF 100 5/8BSPP 32 3/4BSPP 304L	CYLINDER & TURBO BORED POCKET	3D928C828A
9264637	8,00	JT CUIVRE 23 X30 - 1.5	COPPER GASKET FOR BORED POCKET	DIN 7603-CU
1494968	1,00	CP F K 6+1+1 E1 06DL28 RFT	EXHAUST + TURBO WIRING PIPE	3D749D549-
2498774	4,00	FIX.50 CP/ PASS. PC2.6V 1ST	WIRING PIPE BRACKET SET	3D249A290-
1394703	1,00	CL12P KC F1A FR 50	EXHAUST+TC T° INTERFACE TO ENGINE ROOM	3D139C006F












Bible 1001224


Bible moteur MITSUI-MAN 8L58/64 en version propulsion / BAJA Ferries (Navire Carribean Fantasy / Affaire 531097) Avis N° 21925 du 10/05/16


Numéro d'article	Quantité	Nom du produit	Commentaire	N° de plan
1344708	10,00	MP12 S 360 5/8 3/4 4,5 F1A	THRUST & BEARING TEMPERATURE SENSOR	3D134N342-
1016202	8,00	MD1.2 K 150 3/4 4,5 F1A	CYLINDER EXHAUST TEMPERATURE SENSOR	3D101C091-
9289712	8,00	DGF 150 3/4BSPP 32 3/4BSPP 304L	CYLINDER BORED POCKET	3D928C828A
1016203	2,00	MD1.2 K 250 3/4 4,5 F1A	BEFORE & AFTER TURBOCHARGER	3D101C091-
9280120	2,00	DGF 250 3/4BSPP 32 3/4BSPP 304L	TURBOCHARGER BORED POCKET	3D928C828A
9260396	10,00	JT CUIVRE 26.2X30.9 -1.5	COPPER GASKET FOR BORED POCKET	PARKER
1494967	1,00	CPT 08L58/64 KS RFT	MULTIPURPOSE WIRING PIPE	3D749N548-
2498194	8,00	FIX.60 CPT/ET+CP+EC+PL1ST	WIRING PIPE BRACKET SET	3D249P089A
1394705	1,00	CL36 CU35F1A FR 40	PORT BEARING T° INTERFACE TO ENGINE ROOM	3D139N116M
1394706	1,00	CL36 CU35F1A FR 60	OR STARBOARD BEARING T° INTERFACE TO ENGINE ROOM	3D139N116M
1395138	1,00	CL12P KC F1A FR 40	PORT EXHAUST+TC T° INTERFACE TO ENGINE ROOM	3D139C006P
1394704	1,00	CL12P KC F1A FR 60	OR STARBOARD EXHAUST+TC T° INTERFACE TO ENGINE ROOM	3D139C006P
1618210	8,00	MPT108 S3F 1/2BSPP 100 DIN.B	CON-RODS SPLASH OIL TEMPERATURE	3D161C061C











13					
12	35F1A	FR	60	MP TD	1394706
11	35F1A	FR	40	MP BD	1394705
10	35F1A	FR	30	MP1	1399928
9	35F1A	FR	25	MP4	1399927
8	35F1A	FR	20	MP2	1399926
7	35F1A	35F1C	32	MP1 / MP4	1399713
6	35F1A	35F1C	27	MP2 / MP3	1399712
5	35F1A	FR	5		1399642
4	35F1A	35F1A	5		1398401
3	35F1A	FR	15	X11.48906-0051 / MP3	1398325
2	35F1A	FR	12	X11.48906-0050	1398324
1	35F1A	FR	11	X11.48906-0049	1398323
Туре	A	В	L (m)	MAN Sachsnummer (*)	Code CMR

Ce document appartient à CMR France — Reproduction et communication interdites (loi du 11 Mars 1902) This drawing belongs to CMR France and shant be reproduced nor communicated without our agreement (law dated March 11th 1902)

<u>CMR</u>		Look at / Va	 bir folio	1		Instrument cable	 N° Plan MAN : MAN Zeichnung :
FRANCE	nd.	Modifications		Date/Des. Visa Da			 D11.48906-0048
N° du piga lad o	φ 2/2 Folio 1	Emission CONTROLE MESURE REGULATION TECHNOPOLE DE CHATEAU-GOMBERT RUE JOHN MAYNARD KEVNES / BP 85 13381 MAREBUE CEDEX 15 - TEL(33) 91.11.37.00	AP ACC	20/05/94 PS 20 Z4036 139N116M2	No scale	Cable de prolongation	

