

1 National Transportation Safety Board

2
3 Office of Marine Safety
4 Washington, D.C. 20594
5

6
7
8 Group Chairman's Factual Report
9

10
11
12
13 **Engineering Group**
14

15
16 *SS El Faro*
17 DCA16MM001
18
19

1 **1. Accident Information**

Vessel:	SS <i>El Faro</i>
Accident Number:	DCA16MM001
Date:	October 1, 2015
Time:	0739 eastern daylight time (EDT)
Location:	North Atlantic Ocean, 40 nautical miles northeast of Acklins and Crooked Islands, Bahamas 23.3925° N, 73.9029° W
Accident type:	Sinking
Complement:	27 crew, 6 supernumeraries

2 **2. Engineering Group**

Chairman	Brian Young Office of Marine Safety National Transportation Safety Board Washington, DC 20594
Party member—US Coast Guard	██████████ Marine Inspector, Office of Traveling Inspectors
Party member—TOTE Services, Inc.	Jim Fisker-Andersen Director of Ship Management - Commercial
Party member—American Bureau of Shipping	Louis O'Donnell Assistant Chief Surveyor

3 **3. Accident Summary**

4 On Thursday, October 1, 2015, about 0715 EDT, the US Coast Guard received distress alerts from
5 the 790-foot roll-on/roll-off container (Ro/Con) ship *El Faro*. The US-flagged ship, owned by TOTE
6 Maritime Puerto Rico (formerly Sea Star Line, LLC¹) and operated by TOTE Services, Inc. (TOTE), was

¹ On September 17, 2015, the parent company, TOTE, Inc., announced that Sea Star Line had been renamed TOTE Maritime Puerto Rico.

1 40 nautical miles northeast of Acklins and Crooked Islands, Bahamas, and close to the eye of Hurricane
2 Joaquin. The ship was en route from Jacksonville, Florida, to San Juan, Puerto Rico, with a cargo of
3 containers and vehicles. Just minutes before the distress alerts were received, the *El Faro* master had
4 called TOTE's designated person ashore and reported that a scuttle had popped open on deck two and that
5 there was free communication of water into the No. 3 hold. He said the crew had controlled the ingress of
6 water but that the ship was listing 15° and had lost propulsion. The Coast Guard and TOTE were unable
7 to reestablish communication with the ship. Twenty-eight US crewmembers, including an off-duty
8 engineering officer sailing as a supernumerary, and five Polish workers were on board. The vessel sank
9 in 15,400 feet of water.

10 The Coast Guard, US Navy, and US Air Force dispatched multiple assets to the ship's last known
11 position, but the search was hampered by hurricane-force conditions on scene. On Sunday, October 4, a
12 damaged lifeboat and two damaged liferafts were located. The same day, the Coast Guard found a
13 deceased crewmember wearing an immersion suit. A Coast Guard rescue swimmer tagged the body in the
14 immersion suit and left to investigate reported signs of life elsewhere but then could not relocate the tagged
15 suit. No signs of life were found, and on Monday, October 5, a debris field and oil slick were discovered.
16 The Coast Guard determined that *El Faro* was lost and declared the event a major marine casualty. The
17 Coast Guard suspended the unsuccessful search for survivors at sundown on Wednesday, October 7.

18 **4. Investigation**

19 The National Transportation Safety Board (NTSB) learned of the accident from the Coast Guard
20 on the afternoon of October 1, 2015. A team of five investigators, a board member, and support staff
21 launched from NTSB headquarters on October 6 and arrived on scene in Jacksonville later the same day.

1 The investigation was led by the NTSB. Parties to the investigation were the Coast Guard, TOTE, the
2 American Bureau of Shipping (ABS), and the National Weather Service. Company officials, off-duty
3 crewmembers, Coast Guard inspectors, ABS surveyors, and witnesses were interviewed. The on-scene
4 part of the investigation was completed on October 15.

5 After the initial launch, the fact-gathering phase of the engineering investigation included
6 interviews in Maine (Rockland, Castine, and Portland) during November and December 2015 of family
7 members and of cadets from the Maine Maritime Academy. Coast Guard officers were interviewed in
8 Washington, DC, in the spring of 2016. The Coast Guard convened Marine Board of Investigation (MBI)
9 hearings in Jacksonville in February and May 2016. The NTSB participated in the hearings. Vessel
10 documents and maintenance records were collected from TOTE. Project books and vessel pictures were
11 provided by Maine Maritime Academy cadets who had sailed aboard *El Faro* in the summer of 2015.
12 Investigators visited *El Yunque*, a sister ship to *El Faro*, on several occasions.

13 **5. Vessel**

14 **5.1. Description and History**

15 *El Faro*, hull No. 670, was built in 1975 as the SS *Puerto Rico* at Sun Shipbuilding in Chester,
16 Pennsylvania. It was one of Sun's *Ponce*-class vessels designed specifically for the Puerto Rican trade.
17 Operated by the Navieras de Puerto Rico Steamship Company, the *Puerto Rico* hauled cargo to and from
18 the US East Coast for 15 years. In 1993, the ship was purchased by Totem Ocean Trailer Express and
19 renamed *Northern Lights*. The vessel sailed frequently between Tacoma, Washington, and Anchorage,
20 Alaska. In 1993, the vessel was lengthened by 90 feet at Alabama Shipyard, Inc., during a major

1 conversion.² After servicing the Alaska trade, the vessel was chartered by the US government from 2000
2 to 2003 to carry military cargo for Operation Iraqi Freedom.³

3 In 2006, the ship was converted from a Ro/Ro cargo ship to a Ro/Con vessel and renamed *El Faro*.
4 A Ro/Ro vessel is an oceangoing cargo ship that uses a dockside ramp to roll on or roll off wheeled cargo
5 such as containers, trailers, trucks, cars, and heavy construction equipment. A Ro/Con vessel is a hybrid
6 that has ramps serving vehicle decks as well as cargo decks accessible to cranes.

7 At the time of the accident, *El Faro* was owned by TOTE Maritime and operated by TOTE
8 Services. From 2006 to 2008, the vessel had been variously under charter, running from the US East Coast
9 to the Middle East. Between 2008 and 2011, *El Faro* was laid up except for brief activations, including a
10 run between Philadelphia, Jacksonville, and San Juan. Beginning in 2011, the vessel was laid up in
11 Baltimore and out of service for about 2 years (until December 6, 2013).⁴ In May 2014, *El Faro* was
12 placed into the Jones Act liner service in the Caribbean trade between Jacksonville and San Juan, replacing
13 *El Morro* when that vessel was scrapped.⁵ TOTE had plans to convert *El Faro* back to Ro/Ro service for
14 the Alaska trade in early 2016.⁶ The vessel's history can be summarized as follows:

- 15 • Initial construction: 1975, Sun Shipbuilding, Chester, Pennsylvania.
- 16 • Lengthening: 1993, Mobile, Alabama—major conversion.

² According to Title 46 *United States Code* (USC) 2101 (14a), a “major conversion” means a vessel conversion that (a) substantially changes the dimensions or carrying capacity of the vessel; (b) changes the type of the vessel; (c) substantially prolongs the life of the vessel; or (d) otherwise so changes the vessel that it is essentially a new vessel.

³ MBI: TOTE vice president marine operations.

⁴ Interview: port engineer, tech review comments TOTE director of operations.

⁵ Tech review comments: TOTE director of operations.

⁶ MBI: TOTE vice president marine operations.

- 1 • Modification from Ro/Ro to Ro/Con configuration: 2006, Mobile—not considered a major
- 2 conversion by Coast Guard.
- 3 • Layup period: Baltimore, Maryland, 2013, approximately 2 years.
- 4 • Post-layup shipyard/drydocking: Bahamas, December 2013.

5 Vessel particulars were as follows:

Vessel Name	SS <i>El Faro</i>
Owner/Operator	TOTE Maritime Puerto Rico/TOTE Services
Port of Registry	San Juan, Puerto Rico
Flag	United States
Type	Cargo—Ro/Con
Built	1975
Official number	561732
Classification society	American Bureau of Shipping
Construction	Steel, reduced scantlings
Draft	30 feet (9.1 meters)
Length	790 feet (240.8 meters)
Beam	105 feet (32.0 meters)
Gross/net tonnage	31,515/21,473
Engine power and type	Steam turbine, 30,000 shaft horsepower, single screw
Service speed	20 knots
Cargo	Containers and rolling cargo
Fuel capacity	11,552 barrels
Fresh water capacity	410 long tons ⁷
Ballast water capacity	4,623 long tons
Persons on board	33
Fatalities	33
Damage cost	Estimated \$36 million ⁸

⁷ One long ton = 2,240 pounds.

⁸ Email from TOTE director of operations.

1 **5.2. Machinery**

2 The engine room of *El Faro* contained two boilers, a high-pressure turbine, a low-pressure turbine,
3 a reduction gear set, a main condenser, two turbogenerators, three feed pumps, two forced-draft fans, and
4 other associated equipment to produce power and propulsion for the ship. Also located in the engine room
5 were fuel and lube oil service and transfer pumps as well as bilge, cargo, ballast, and fire pumps. Auxiliary
6 equipment such as evaporators, air compressors, a sewage treatment plant, HVAC equipment, and heaters
7 and coolers were located in the space as well.

8 The machinery installed in the engine room was located on several decks. The propeller shaft,
9 reduction gear, main condenser, boiler foundations, and most pumps were located in the lower engine
10 room on the tanktop deck, called the “lower level.” The operating platform, main turbines,
11 turbogenerators, boiler controls, and switchboards were on the third deck. Several fans, storage tanks, and
12 heaters were located above these decks in the “engine casing.” Outside the engine room was an emergency
13 fire pump in the No. 3 cargo hold on the starboard side of the tanktop level, a steering gear system at the
14 stern, and an emergency generator on the cabin deck. The cargo spaces contained ventilation fans,
15 winches, and hydraulically operated watertight cargo doors.

16 **5.3. Main Engine**

17 *El Faro* was propelled by a 30,000-horsepower (hp), General Electric cross-compound, geared
18 steam turbine set connected to a single, fixed-pitched, five-bladed propeller by a set of General Electric
19 reduction gears. The propulsion turbines were installed side by side and connected by a steam crossunder
20 pipe. The turbine rotors were connected to the pinions of the double-reduction gear, thereby reducing the

1 speed of the turbines to propeller speed.⁹ According to the 1973 ABS rules for building and classing steel
2 vessels, the lubricating oil system of the main engine was to be “so arranged that it would function
3 satisfactorily when the vessel is permanently inclined to an angle of 15° athwartship and 5° fore and aft.”
4 The vessel was subject to 1973 ABS rules because the construction contract was signed in 1973.¹⁰



5

6

Figure 1. Propeller, rudder, and shaft of *El Faro* while in drydock (TOTE photo).

⁹ Main engine manual.

¹⁰ ABS rules for building and classing steel vessels 1973, section 36.65.1, p. 468.

1 The high-pressure (HP) turbine casing had two halves, upper and lower. The journal bearings and
2 thrust bearings could be accessed without removing the upper case. The steam chest, which contained the
3 ahead steam control valves, was integral with the upper half of the casing.¹¹

4 The low-pressure (LP) turbine had an ahead steam inlet located in the aft end of the lower half of
5 the casing. The inlet was connected to the exhaust of the HP turbine by a crossunder pipe. The astern
6 steam inlet allowed steam to flow to the steam ring of the reversing element.¹²

7 The turbines were equipped with speed-limiting devices that held the turbine speed at a governing
8 point if an overspeed condition occurred. An overspeed governor pump was located in the forward bearing
9 bracket of each turbine. During an overspeed condition, the output of the governor pump would increase
10 and operate an overspeed relay. The action of the relay would cause the steam control valves to move in
11 the closing direction and limit the speed of the turbine.¹³

¹¹ Main engine manual.

¹² Main engine manual.

¹³ Main engine manual.



1

2

Figure 2. Main propulsion turbines seen from aft end of engine room (photo from *El Yunque*).

3

4

5

6

The rated steam inlet pressure to the HP turbine was 845 psig (pounds per square inch gauge), and the maximum speed of the turbine at rated horsepower was 6,700 revolutions per minute (rpm). The maximum speed of the LP turbine was rated at 3,418 rpm. The maximum allowable propeller speed was 132 rpm.¹⁴

7

8

9

Connecting the turbine set to the propeller were General Electric double-reduction, double-helical, articulated-type reduction gears, type MD-92-1. The major rotating elements of the gear set consisted of two first-reduction pinions, two first-reduction gears, two second-reduction pinions, and one main gear,

¹⁴ Main engine manual.

1 connected to the main propeller shaft. The speed of these elements at maximum horsepower was as
2 follows:¹⁵


First-reduction pinion HP....	6,700 rpm
First-reduction pinion LP.....	3,418 rpm
Intermediate HP.....	887 rpm
Intermediate LP.....	887 rpm
Propeller.....	128 rpm

3 *El Faro* was equipped with a torque tube between the main engine and the propeller. It was
4 essentially an intermediate shaft, constructed of rolled steel, that connected the stern tube shaft to the
5 propeller shaft. According to *El Faro*'s off-duty chief engineer and the company's director of marine
6 operations, there was a casting at each end about 3 feet in diameter. Another *Ponce*-class vessel, the
7 *Matsonia*, had experienced a failure of the torque tube.¹⁶ It appeared to be an isolated incident and brought
8 to light that the speed-limiting governor needed cleaning to ensure proper response.¹⁷

¹⁵ Main engine manual.

¹⁶ Interviews: off-duty chief engineer, TOTE director of marine services.

¹⁷ Interview: off-duty first assistant engineer. TOTE director of marine services.



1

2

Figure 3. Gear arrangement diagram showing reduction gear set (General Electric manual).

1 **5.4. Boilers**




Figure 4-1.—Cutaway view of a D-type boiler.

2
3 **Figure 4.** Cutaway view of main propulsion boiler (Babcock and Wilcox manual).

4 The two Babcock and Wilcox boilers installed aboard *El Faro* had a design steam pressure of
5 1,070 psi, but they were being operated at about 860 psi at 900° F before the accident.¹⁸ The boilers, rated
6 for 110,000 pounds of steam per hour, had a heating surface of 7,900 square feet. The boilers were
7 designed so that “all components to be supplied for shipyard use . . . permit satisfactory operation under
8 the following conditions unless stated in customer’s specifications: momentary roll–30°; permanent list–
9 15°; permanent trim–5°.”¹⁹

¹⁸ Interview: off-duty second assistant engineer, engine logbooks.

¹⁹ Email from Babcock and Wilcox district service manager, July 6, 2016.

1 Each boiler was a two-drum, front-fired unit that included a 60-inch steam drum with
2 hemispherical heads and a 27-inch water drum with elliptical heads. The drums were connected by a
3 generating tube bank of 21 rows of 1-1/4-inch (outside diameter [OD]) in-line tubes staggered at their
4 entrance to the steam drum and bent at the ends so they entered the drums around the circumference of
5 the drum, allowing them to expand or bell.

6 The generating tube bank was arranged so the furnace gases made a single pass over it before
7 entering the economizer. Two rows of 2-inch OD tubes between the furnace and the superheater screened
8 the superheater from the direct radiation of the furnace gases. One row of 2-inch OD tubes between the
9 superheater and the 1-1/4-inch OD bank tubes supported the superheater guides. One of the screen rows
10 was also used to support the superheater guides.²⁰

11 **Superheater.** The vertical superheater was made up of 177 U-bent tubes (1-1/4-inch OD) arranged
12 in three loops and connected to two horizontal headers supported at the front and rear of the boiler. Panels
13 in the casing at the bottom of the boiler allowed access to the superheater headers and also to the steam
14 side of the tubes through handholes in the headers. The superheater was arranged so that all produced
15 steam made four passes through it. The U-tubes extended 8 feet 9 inches, measured centerline to centerline
16 on the tubes. Spacer castings were attached to each guide tube. Superheater tubes and guide castings could
17 be replaced without removing the superheater guide screen or other boiler tubes. The superheater tubes in
18 all passes were welded to headers.²¹

²⁰ Boiler manual.

²¹ Boiler manual.

1 The furnace was composed of three walls, a roof, and a floor. The front, side, and rear walls were
2 water-cooled with boiler tubes. The sidewall tubes were bent up toward the steam drum and formed the
3 furnace roof. The floor tubes were covered by about 5 inches of refractory (heat-resistant material). Three
4 Saratoga-type oil burners were installed in the burner double front. They consisted of radial door air
5 registers and 12-inch impellers and were equipped with Babcock and Wilcox steam atomizers having
6 automatic shutoff valves.²²

7 The superheater cavity for each boiler contained two horizontal IK 525-A soot blowers. The soot
8 blowers entered through the front of the boiler and extended approximately the full length of the
9 superheater.²³

10 **Economizer.** Economizers perform a key function in providing high overall thermal efficiency by
11 recovering low-temperature energy from the flue gas before it is exhausted to the atmosphere, and by
12 transferring the energy to the incoming feedwater.²⁴ The economizers on *El Faro* were of the extended-
13 surface, continuous-loop, flared type arranged in the uptake after the last row of boiler generating tubes.
14 Each economizer was 16 rows wide and consisted of 1-1/2-inch OD studded tubes. The inlet and outlet
15 headers were seamless forged steel fitted with one handhole in the end of the header for inspection. The
16 tubes were seal-welded externally to the headers.²⁵

²² Boiler manual.

²³ Boiler manual.

²⁴ Babcock and Wilcox website.

²⁵ Boiler manual.

1 **Steam Drum Internals.** The steam drum had three safety valves on the top centerline of the steam
2 drum. Two of the valves were 2-inch spring-loaded units; the third had a 1-1/2-inch spring-loaded pilot
3 valve. The manufacturer recommended setting the 1-1/2-inch pilot safety valve at 1,030 psig and the 2-
4 inch valves at 1,050 and 1,070 psig.²⁶

5 **Internal Feed Line.** A 5-inch internal feedline in the steam drum extended about 90 percent of the
6 drum length. Its horizontal centerline was 12 inches below the normal water level and was connected to
7 the feed supply nozzle. The feed pipe had one row of 1/2-inch-diameter holes along the top to introduce
8 feedwater into the drum evenly throughout the length. The normal water level was at the horizontal
9 centerline of the steam drum.²⁷

10 **Dry Pipe.** A 6-inch dry pipe was suspended along the top centerline inside the steam drum. It was
11 perforated along its upper surface with seven rows of 3/8-inch-diameter holes. Drain holes were drilled in
12 the bottom of the pipe at each end.²⁸ Steam entered the dry pipe through the upper perforated area and
13 exited the pipe through the connection from the top of the drum to the superheater. The dry pipe had the
14 dual function of reducing moisture carryover and allowing an even withdrawal of steam from the water
15 surface.²⁹

16 **Surface Blow Pipe.** A surface blow pipe was used to remove grease, scum, and light solids from
17 the boiler water through the surface blow line connection. The horizontal centerline of the surface blow

²⁶ Boiler manual.

²⁷ Boiler manual.

²⁸ Boiler manual.

²⁹ Boiler manual.

1 line was 2 inches below the normal water level. The 3/4-inch-diameter pipe was perforated along the top
2 centerline by four 3/8-inch holes.³⁰

3 **Chemical Feed Pipe.** A 3/4-inch chemical feed pipe was used to inject boiler chemicals into the
4 steam drum while the boiler was operating. It also served as a sampling pipe for testing the boiler water.
5 It extended almost the entire length of the drum. Its horizontal centerline was 6 inches below the normal
6 water level and had a row of 33 1/8-inch-diameter holes drilled along it. The pipe was connected to the
7 chemical feed piping nozzle at the end of the drum.³¹

8 **Swash Plates.** Vertical swash plates were located in the lower half of the steam drum at the
9 approximate center point. The purpose of the plates was to reduce excessive surging of water in the drum
10 from one end of the steam drum to the other when the ship was pitching.³²

11 **Control System.** Burner management, steam pressure, and boiler water level in the boilers were
12 monitored and controlled by a system designed and installed by a company called Nortech. Off-duty
13 engineering officers told investigators that boiler automation was tested annually by the ship's crew, in
14 accordance with the periodic safety test procedure retained aboard the vessel. Investigators requested the
15 vessel-specific document from the operating company, but it could not be provided because it had been
16 kept aboard *El Faro*.

³⁰ Boiler manual.

³¹ Boiler manual.

³² Boiler manual.



1
2 **Figure 5.** *El Faro* boiler control console (photo by Maine Maritime Academy cadet).

3 Investigators received the periodic safety test procedure from *El Faro*'s sister ship *El Yunque*,
4 which used the Technical Marine Service boiler automation system, a similar test procedure to *El Faro*'s.

5 The procedure listed 16 test items:

- 6
- 7 • Lamp test
 - 8 • Manual boiler trip
 - 9 • Drum level high/low alarms
 - 10 • Low-low drum level alarm and trip
 - 11 • Forced draft fan fail alarm and trip
 - 12 • Low air flow alarm
 - 13 • Last-flame-out alarm and trip
 - 14 • Boiler control power
 - 15 • Burner safety trip control
 - 16 • Trial for ignition
 - Purge cycle

- 1 • Boiler in bypass indication
- 2 • Power failure alarms
- 3 • Atomizing steam low-pressure alarm
- 4 • Fuel oil low-pressure alarm
- 5 • Process controller operation³³

6 According to interviews with off-duty *El Faro* engineers, the periodic safety test procedure was
7 completed during the off-duty second assistant engineer's last trip, which ended about 9 weeks before the
8 accident. He signed off the vessel on August 10, 2015.³⁴

9 **5.5. Electrical Generation and Distribution System**

10 *El Faro* had two steam turbogenerators manufactured by Terry Steam Turbine Company. Two
11 General Electric marine alternating-current generators that operated at 1,800 rpm, powered by 900 psi of
12 superheated steam, were coupled to steam turbines by a set of reduction gears. Each generator had a
13 capacity of 2,000 kilowatts of three-phase power at 450 volts and 60 hertz. The main 450-volt switchboard
14 was energized by the two turbogenerators. The emergency bus, in the emergency generator room, was fed
15 from the main bus through an electrical bus tie.

16 The vessel was constructed according to the 1973 ABS rules for building and classing steel
17 vessels, which required the generators to "be located with their shafts in a fore-and-aft direction on the
18 vessel and must lubricate and operate satisfactorily when permanently inclined to an angle of 15°
19 athwartship and 5° fore and aft; the bearings are to be arranged that they will not spill oil under a

³³ Interview: off-duty chief engineer.

³⁴ Interview: off-duty second assistant engineer.

1 momentary roll of 22.5°.”³⁵ Each turbogenerator was outfitted with a lubricating system consisting of an
2 oil pump, main sump, cooler, and strainer. The sump, an integral part of the subbase structure, contained
3 baffles to allow for the vessel’s pitching and rolling at sea. The turbogenerators were initially designed
4 with positive-displacement, gear-type lube oil pumps that were submerged into the sump to ensure
5 flooding of oil. The pump was driven from the free end of the low-speed shaft through a right-angle gear
6 and vertical extension shaft. According to TOTE, the original right-angle, gear-driven pump was replaced
7 with a pump mounted on the end of the gear case and directly driven by the low-speed gear shaft. A 40-
8 gallon-per-minute (gpm), 50-psi auxiliary motor-driven pump was also piped into the system, as well as
9 an oscillating hand pump for priming or starting the generator without electrical power.³⁶

10 The turbogenerators were equipped with protective devices incorporated into the lubrication
11 system: a low-oil-pressure shutdown in the governor, a low-oil-pressure alarm switch, a low-oil-pressure
12 trip mechanism, and an overspeed trip dump valve.

³⁵ ABS rules for building and classing steel vessels 1973, section 35.29, p. 380.

³⁶ Tech review comments: TOTE:



1

2 **Figure 6.** *El Faro's* main 450-volt electrical switchboard (photo by Maine Maritime Academy cadet).

3 The emergency diesel generator (EDG) consisted of a Detroit model 7163-7005-16V71 diesel
4 engine driving an electrical generator. The two-stroke, 16-cylinder engine had a bore of 4-1/2 inches and
5 a stroke of 5 inches.³⁷ The 450-volt, three-phase, 350-kilowatt alternating-current generator could
6 automatically start using battery power and provide electrical power if power to the main bus was lost.³⁸

³⁷ Detroit diesel manual.

³⁸ Interview: off-duty chief engineer.

1 According to the 1973 ABS rules for building and classing steel vessels, the emergency generator was
2 required to function when the ship was inclined at 22.5° and when the trim of the ship was 10°. ³⁹

3 The EDG fuel supply tank was located outside the emergency generator room on the port side of
4 the cabin deck, just aft of the EDG room. It had a capacity of 5,000 gallons. The tank had last been filled
5 on July 8, 2015, with 1,800 gallons of diesel fuel. According to logbook entries, the tank contained 4,800
6 gallons on September 1, 2015. ⁴⁰

7 To power the main switchboard from the emergency generator switchboard, the main switchboard
8 had to be stripped of all nonessential loads so the smaller emergency generator could power up vital
9 circuits. This process was called “backfeeding” the main bus from the emergency bus. It was necessary
10 when “lighting off the plant” (firing up the boilers) from a “dead ship condition” (main propulsion plant,
11 boilers, and auxiliaries not operating due to absence of power). ⁴¹ On August 25, 2015, the engine
12 department used the backfeed function of the emergency generator to power the main bus while
13 performing maintenance during a scheduled plant shutdown. ⁴² According to entries made in the preventive
14 maintenance system, the emergency generator was operated monthly with an electrical load for a two-
15 hour period, testing the auto-start function. ⁴³

³⁹ ABS rules for building and classing steel vessels 1973, section 35.19.3, p. 377.

⁴⁰ Engine logbooks for July 2015 and September 2015.

⁴¹ Interview: off-duty chief engineer.

⁴² AMOS maintenance history.

⁴³ AMOS maintenance history.

1 **5.6. Fuel Oil System**

2 *El Faro* had a capacity of 11,552 barrels (bbl) of fuel.⁴⁴ Fuel consumption was approximately 2.0
3 bbl per nautical mile.⁴⁵ The double-bottom (DB) storage tanks on the *El Faro* were located as follows:

- 4 • No. 2A DB inboard port and starboard (approximately 2,202 bbl each)
- 5 • No. 3 DB inboard port and starboard (approximately 2,673 bbl each)⁴⁶

6 At the time of the accident, the vessel burned heavy fuel oil RMK500. Samples of fuel from each
7 bunkering operation were kept on board as well as with the supplier for testing, if necessary. The
8 specifications of the fuel oil received in May 2015 were as follows:⁴⁷

- 9 • Viscosity at 50°centigrade (C): 460
- 10 • API⁴⁸ gravity at 60° F: 10.2
- 11 • Density at 13° C: 998
- 12 • Temperature (° F): 136
- 13 • Flash point (° F): 198
- 14 • Pour point (° F): 27
- 15 • Water (% volume): 0.05
- 16 • Sulphur (% m/m⁴⁹): 3.38

⁴⁴ *El Faro* Vessel Information Booklet Rev-1.

⁴⁵ MBI *El Yunque* captain testimony.

⁴⁶ *El Faro* Vessel Information Booklet Rev-1.

⁴⁷ Specifications from records retained by Maine Maritime Academy cadet.

⁴⁸ API = American Petroleum Institute.

⁴⁹ Percent by mass (measure of concentration).

1 The fuel was usually burned at sea from the No. 3 DB storage tanks, three port and three starboard.
2 Twice a day, the second engineer on the 4-to-8 watch transferred the fuel from the No. 3 DB tanks to a
3 single fuel oil settler, whose capacity was 1,800 bbl (273 tons). The fuel was heated by steam coils inside
4 the settler to about 130° F and pumped through two sets of strainers before being heated again by another
5 set of heaters to 230° F, atomized by 150-psi steam, and burned in the boilers.⁵⁰ While it was in liner
6 service between Jacksonville and Puerto Rico, the vessel bunkered weekly. It burned about 800 to 900 bbl
7 a day at full sea speed.⁵¹

8 The fuel oil settler had a high suction and low suction piping arrangement. The low suction was
9 usually used unless the system contained debris. The engineering crew normally changed both sets of fuel
10 oil strainers before every departure.⁵² In interviews, off-duty engineers could not recall any issues with the
11 quality of fuel aboard *El Faro*.⁵³

12 **5.7. Lube Oil System**

13 The lubricating oil system for the main engine consisted of two IMO Series TKC422BS-337
14 positive-displacement vertical rotary screw-type pumps, rated at 450 gpm, manufactured by DeLaval
15 Turbine, Inc. The pumps were driven by 40-hp electric motors.⁵⁴ According to the electrical power
16 distribution diagram (1252-938-1), lube oil service pump No. 1 was powered by the main 450-volt
17 switchboard and protected by a 100-amp breaker. Lube oil service pump No. 2 was powered by the

⁵⁰ Engine logbook.

⁵¹ Interviews: off-duty chief engineer and off-duty second assistant engineer.

⁵² Interviews: off-duty chief engineer and off-duty second assistant engineer.

⁵³ Interviews: off-duty chief engineer and off-duty second assistant engineer.

⁵⁴ DeLaval lube oil service pump instruction manual.

1 emergency 450-volt switchboard and also protected by a 100-amp breaker.⁵⁵ The manufacturer
2 recommended that a priming connection be piped to the suction side of the pump, and that a vent
3 connection be made to the discharge side of the pump. The lube oil pump manual states that “running the
4 pump without oil will cause rapid wear of housings, rotors, and other internal parts.”⁵⁶ The pumps were
5 equipped with mechanical seals. The purpose of a mechanical seal is to contain the pressurized fluid inside
6 the pump housing where the rotating shaft passes through a stationary housing. A mechanical seal is a
7 device that consists of a stationary component and a rotating assembly, held against each other with spring
8 pressure, and typically lubricated by a fluid film created by the fluid being pumped. The lube oil system
9 normally operated with one service pump running, with the second service pump in standby mode. This
10 configuration would allow the standby pump to automatically start if a pressure switch sensed a 10-psi
11 pressure drop in the lube oil supply line to the bearings.⁵⁷ Discharge oil pressure could be low for several
12 reasons, including loss of pump prime, leaks in suction piping, obstructions (such as debris) in suction
13 piping, leaking seals, low oil level, air in system, or clogged strainers.⁵⁸ According to “Control and comm,
14 upper machinery space” drawing 1252-930-1, *El Faro* had communication points to advise watchstanders
15 about lube oil issues such as: lube oil gravity tank, low lube oil pressure to main unit, lube oil cooler
16 temperature, seven main unit lube oil temperature sensors, main unit lube oil sump. While aboard *El*
17 *Yunque*, investigators noted the following alarms for the lube oil system on the main control panel: lube
18 oil gravity tank level low, lube oil pump power failure, standby lube oil pump running, lube oil sump level

⁵⁵ Electrical power distribution diagram, 1252-938-1,

⁵⁶ DeLaval lube oil service pump instruction manual.

⁵⁷ Interviews: off-duty chief engineer, off-duty first assistant engineer. TOTE’s arrangement of machinery material list.

⁵⁸ DeLaval lube oil service pump instruction manual.

- 1 high, lube oil sump level low, lube oil service pump discharge pressure low, lube oil cooler temperature
- 2 low, lube oil cooler temperature high.⁵⁹



3
4 **Figure 7.** Lube oil pumps and associated piping (photo from *El Yunque*).

5 The pumps discharged lube oil to the main engine bearings through an orifice in the supply line,
6 as well as to a 3,200-gallon gravity tank in the upper engine room. The orifice was sized and adjusted
7 during original construction to provide a pressure of 12 psig at the lube oil inlet header to the unit, with

⁵⁹ Control and comm, upper machinery space” drawing 1252-930-1,

1 oil at 115° and a Saybolt viscosity of 279.⁶⁰ The gravity tank was designed to overflow when at the proper
2 level, and to supply lube oil to the bearings of the main turbines and reduction gears through a 5-inch pipe
3 if pump pressure was lost. The gravity tank, which was 9 feet high, was located on the main deck level,
4 about 35 feet above the operating platform. During normal operation, the level in the gravity tank would
5 be maintained above an internal overflow line located 8 feet 2 inches above the bottom of the tank. The
6 overflowing oil could be observed and monitored on the operating level of the engine room through an
7 illuminated port (“bull’s-eye”) in the oil supply line as the oil returned to the bottom of the main sump. In
8 the event of pressure loss, about 8 minutes of reserve oil for the main engine bearings was available in the
9 gravity tank. The reserve oil would flow down through the supply pipe, through the orifice, and into the
10 bearings as protection while the engine was coming to a stop.⁶¹

⁶⁰ Diagrammatic arrangement of the lubricating system, drawing 663-904-100.

⁶¹ Interviews: off-duty chief engineer, off-duty first and second assistant engineers. Main engine manual.



1
2 **Figure 8.** “Bulls-eye” for monitoring lube oil flow to main engine (photo from *El Yunque*).

3 The lube oil service pumps took suction from the reduction gear sump through an 8-inch pipe, a
4 check valve, and a set of duplex magnetic suction strainers. According to the chief engineer’s turnover
5 notes from August 2015, both lube oil service pumps would have required maintenance during the
6 upcoming shipyard repair period. The forward pump required replacement of the mechanical seal, and the
7 after pump required the pump to be rebuilt or replaced because it was “running 3 psi lower than the forward
8 pump.” These items were identified in a worklist for the shipyard.⁶²

⁶² Chief engineer’s turnover notes and shipyard worklist August 2015.




1
2 **Figure 9.** Lube oil service suction strainers (photo from *El Yunque*).

3 The lube oil sump was located at the bottom of the reduction gear and extended below the tanktop
4 level. According to the diagrammatic arrangement of the lubricating system, the suction pipe was 10
5 inches above the bottom of the sump, about 22 inches to starboard of centerline, and about 24 inches from
6 the after bulkhead of the sump. The sump was accessed by two manholes in the forward end of the sump.⁶³
7 A measurement taken aboard *El Yunque* in October 2016 indicated that the pump suction was located 73
8 inches above the tanktop. Using the diagrammatic arrangement of the lubricating system, investigators

⁶³ Diagrammatic arrangement of the lubricating system, drawing 663-904-100.

1 estimated a height of 90 inches between the bell mouth to the tanktop inside the lube oil sump. Further
2 measurements were to be made aboard *El Yunque* at the next opportunity.⁶⁴



3
4 **Figure 10.** *Left:* Lube oil check valve above sump suction below main shaft. *Right:* Lube oil suction pipe
5 at tanktop. (Photos from *El Yunque*)

6 According to logbook entries from September 2015, when the main engine was operating at about
7 120 rpm, the normal operating lube oil suction pressure was about 8 psig, and discharge pressure was
8 about 58 psig. The lube oil typically entered the coolers at about 134° F. The temperature of the lube oil
9 was about 20° lower after being cooled by the single-pass seawater coolers, which were rated for 450
10 gpm.⁶⁵

11 The pressure relief valve on the discharge side of the lube oil pumps was set at 85 psig. The pump
12 manufacturer stated that the relief valve discharge should not be piped to the pump inlet line; but if it was

⁶⁴ Connections on lube oil sump, drawing 663-904-04.

⁶⁵ Diagrammatic arrangement of the lubricating system, drawing 663-904-100, main engine logbooks.

1 necessary to be piped in this manner, it should be made as remote from the pump as possible. A set of 5-
2 inch magnetic duplex strainers was located on the discharge side of the pumps, as well as an orifice that
3 was installed to maintain 55 psi of pressure to the turbine governor system.⁶⁶ Also part of the lube oil
4 system were two coolers—heat exchangers that used seawater to remove heat generated by the main
5 engine from the oil. Two Alfa-Laval purifiers were piped into the system to remove water and
6 contaminants from the lubricating oil for the propulsion turbine/reduction gear and the ship's service
7 turbogenerators.⁶⁷

8 The main engine lube oil sump had a design capacity of 2,870 gallons. The high-level capacity
9 was 2,020 gallons, the operating capacity was 1,426 gallons, and the low level was 724 gallons. According
10 to logbook entries, the lube oil level was maintained at about 26 inches.⁶⁸ According to the alteration
11 section of the diagrammatic arrangement of the lubricating system for hulls 662, 663, and 664, changes
12 were made to the original design specifications for the operating levels of the lube oil sump in 1972 before
13 the keel of *El Faro* was laid. The operating capacity was increased from 900 gallons to 1,426 gallons, the
14 low-level capacity was decreased from 750 to 724, and the sump design capacity was decreased from
15 4,250 gallons to 2,870 gallons.⁶⁹

16 The sounding table for the quantity of main engine sump lube oil obtained from *El Yunque*
17 indicated that a sounding of 26 inches corresponded to a quantity of 1,345.67 gallons in the sump.⁷⁰ The

⁶⁶ Diagrammatic arrangement of the lubricating system, drawing 663-904-100.

⁶⁷ AMOS component list.

⁶⁸ Main engine logbooks.

⁶⁹ Diagrammatic arrangement of lubricating system, drawing 663-904-100.

⁷⁰ Diagrammatic arrangement of lubricating system, drawing 663-904-100.

1 sump was equipped with a manual sounding tube, as well as a remote level transmitter that displayed the
2 sump level at the operating console.⁷¹


3 *El Faro* had two tanks for the storage of additional lube oil. A 4,465-gallon, rectangular storage
4 tank was located on the starboard side of the operating level at frames 195-199, and a 4,608-gallon,
5 rectangular settling tank was located on the port side of the operating level at frames 195-199.⁷² Lube oil
6 could be added to the main engine sump via the lube oil purifier through a 2-inch pipe.

7 A low-bearing-oil-pressure switch was installed in the oil feed line to the main engine bearings.
8 The switch was electrically connected to a normally deenergized solenoid dump valve. The pressure
9 switch was designed so that if it sensed a pressure drop at the most remote bearing to a point where the
10 bearings could be damaged, it would energize and release lube oil pressure from the ahead operating
11 cylinder, thereby closing the ahead steam control valves by action of the springs on the valve levers. The
12 valve was set to close at 4 psig and open at 8 psig of oil pressure.⁷³ If the lubricating system pressure fell
13 below 4 psig at the pressure switch, the throttles would close and stop the flow of steam to the turbines.

⁷¹ Diagrammatic arrangement of lubricating system, drawing 663-904-100.

⁷² Diagrammatic arrangement of lubricating system, drawing 663-904-100.

⁷³ Diagrammatic arrangement of lubricating system, drawing 663-904-100.



1

2


Figure 11. Low-lube-oil pressure switch, circled (photo from *El Yunque*).

3

4

5

The ahead steam valves were located in the steam chest of the HP turbine. They were arranged in a “split beam” configuration that allowed the valves to lift off their seats in a specific sequence when, in response to the movement of the ahead operating cylinder piston, the beam was raised by the lift rods.



1

2 **Figure 12.** Main engine throttle arrangement, emergency levers circled (photo from *El Yunque*).

3 The ahead operating piston responded to the steam control valve on the main console, which would
4 be manually adjusted by a member of the engine department based on orders received from the bridge via
5 the engine-order telegraph.⁷⁴

⁷⁴ Main engine manual.



1

2 **Figure 13.** Engine order telegraph on operating console of engine room (photo from *El Yunque*).

3 In the event of a failure of the control mechanism, including a loss of control oil pressure, the
4 ahead and astern control valves were designed to be operated with a long-handled emergency bar or
5 hydraulic hand pumps attached to cables in the overhead that, in an emergency, would raise the lifting
6 beams and admit steam to the turbines.⁷⁵

⁷⁵ Main engine manual.




Figure 14. Left: Emergency bar for steam control valves (schematic from General Electric manual).
 Right: Emergency operating cables, identified by red arrows (photo from *El Yunque*).

According to the manufacturer’s manual, lube oil could be lost for several reasons: plugged strainer, pump failure, stuck oil header reducing valve, low oil level, improper valve lineup, defective pressure sensor, or excessive oil leakage due to a broken oil line. The action required in such cases was to stop rotation of the shaft and restore oil pressure if possible.⁷⁶

The lube oil system also contained overspeed governor pumps, one in each forward bearing bracket of each turbine. The pump impellers were assembled on the forward end of the turbine rotors. The oil inlets to the pumps came from the bearing headers, and the outlets from the pumps were piped to the


⁷⁶ Main engine manual.

1 overspeed relay. If a condition developed that would cause the turbines to overspeed, the output of the
2 governor pumps would increase and actuate an overspeed relay. The action of the relay would cause the
3 steam control valves to move in the closing direction and decrease the speed of the turbines by limiting
4 the amount of steam admitted.⁷⁷

5 The overspeed system was designed to be self-restoring. When the overspeed condition had been
6 corrected and normal turbine speed was resumed, the lube oil output pressure would drop and the steam
7 control valves would be restored to their previous opened position.⁷⁸

⁷⁷ Main engine manual.

⁷⁸ Main engine manual.



1

2

3

Figure 15. Overspeed relay and speed governing system (schematic from General Electric main engine manual).

4

5

6

The manufacturer recommended that the overspeed relays be tested when operating at greater than 90 percent of ahead speed to ensure that the system was in proper working condition.⁷⁹ The off-duty chief engineer stated that the overspeed limiting device was tested monthly on southbound trips because the

⁷⁹ Main engine manual.

1 vessel would then be running at higher rpms. The overspeed protection device was activated by stepping
2 on a foot-pedal located forward of the HP turbine. An engineer would depress the pedal, observe the
3 throttle closing, then release the pedal and observe the throttle opening up again. The off-duty chief
4 engineer stated that there had not been any issues with these tests.⁸⁰

5 The monthly tests were recorded in a computerized system called AMOS (see section 6.1). A
6 review of the AMOS maintenance records for 2015 indicated that the overspeed test was completed on
7 February 5, July 1, and September 8 of that year. No frequency was assigned to the work order in AMOS.⁸¹

8 The manufacturer recommended an oil with a Saybolt viscosity of 380-560 seconds at 100° F and
9 54-70 seconds at 210° F, and a minimum flash point of 360° F.⁸² *El Faro* used Chevron GST oil (ISO
10 grade 100) as the lubricating oil in the main engine and reduction gear set.⁸³ Typical test data, obtained
11 from Chevron's website, indicate that the Saybolt viscosity of the GST oil was 520 at 100° F and 65.4 at
12 210° F, which met the manufacturer's specifications. The flash point was 504° F, which also met the
13 specifications.⁸⁴

14 The lubricating oil for the main engine system was analyzed quarterly through Chevron's
15 LubeWatch maintenance management system. Oil samples were taken on board and sent to a LubeWatch
16 laboratory for analysis. According to the LubeWatch website, results can be received immediately, by

⁸⁰ Interview: off-duty chief engineer.

⁸¹ AMOS maintenance system.

⁸² Main engine manual.

⁸³ Chevron LubeWatch oil analysis report (see text).

⁸⁴ Chevron website.

1 phone, fax, or email, or can be sent by mail. NTSB investigators examined quarterly LubeWatch oil
2 analyses from 2014 and 2015 for several *El Faro* systems, including turbogenerators, emergency
3 generator, feed pumps, main turbines, air compressors, steering gear, stern tube bearing, and strut
4 bearing.⁸⁵ The analyses consistently reported that “wear rates were normal; abrasive and other contaminant
5 levels are acceptable, viscosity within specified operating range for the main turbine oil system.”⁸⁶

6 The level of lube oil was normally maintained at 26 inches in the sump.⁸⁷ *El Faro* had a storage
7 capacity of 51 long tons of lube oil.⁸⁸

8 On March 14, 2015, the *El Faro* captain submitted a marine casualty report to the Coast Guard
9 after an incident in which the main engine shut down soon after departing San Juan.⁸⁹ No mechanical
10 failures were found. The company conducted an internal investigation and determined that the cause was
11 human error: a crewmember had mistakenly closed a valve in the lube oil system to the main engine. The
12 situation was rectified and corrective actions taken in which the crew received training and the valves
13 were labeled and tied in the proper position.⁹⁰

⁸⁵ LubeWatch oil analysis report.

⁸⁶ LubeWatch oil analysis report.

⁸⁷ Engine logbooks.

⁸⁸ *El Faro* ship particulars, p. 42, Maine Maritime Academy cadet sea project.

⁸⁹ Coast Guard form CG 2692.

⁹⁰ Interview: TOTE director of ship management - commercial.

1 **5.8. Steering**

2 *El Faro's* steering system was built by Kawasaki Heavy Industries, Ltd., of Kobe, Japan. It was
3 an electrohydraulic system, type FR-280. The two Kawasaki-Bruninghaus type BV-732 variable-
4 displacement, axial-piston hydraulic pumps were powered by a pair of 60-hp, three-phase, 60-hertz, 1,150-
5 rpm induction motors having an output of 45 kilowatts. One of the electric motors that powered the system
6 was fed by the main 450-volt bus, and one was fed from the 450-volt emergency bus. The system was
7 designed to have a maximum torque of 140 ton-meters and to turn 65° in 28 seconds. The diameter of the
8 ram was 280 millimeters.⁹¹

9 **5.9. Bilge and Ballast System**

10 The cargo bilge pumping system was powered by the 450-volt main bus. Two vertical centrifugal
11 bilge/ballast pumps, manufactured by Worthington, were located on the lower level of the engine room.
12 Each pump was driven by a 20-hp vertical electric motor. The pumps were rated for 950 gpm at 28.5 psi.⁹²

13 An emergency vertical, centrifugal, submersible bilge pump was powered by the emergency power
14 supply. The pump was located on the lower level of the engine room and could dewater the machinery
15 space. The pump, manufactured by Prosser, was rated at 50 gpm at 30 feet of total dynamic head.⁹³

⁹¹ Steering gear manual.

⁹² Arrangement of machinery material list.

⁹³ Arrangement of machinery material list.

1 According to the AMOS system, bilge alarms in the engine room and cargo spaces were required to be
2 tested monthly.⁹⁴ A bilge alarm panel was located in the engine room.⁹⁵

3 **5.10. Fire Main System**


4 The fire main system aboard *El Faro* consisted of a combination pump, called a “bilge, fire, and
5 general service pump,” located on the starboard side of the lower engine room. The pump was a
6 Worthington vertical, centrifugal model rated at 575 gpm at 125 psig. An emergency fire pump, rated for
7 635 gpm at 125 psig, was located on the starboard side of the No. 3 cargo hold, on the tanktop level. This
8 pump, also a Worthington vertical, centrifugal model,⁹⁶ had its own sea suction directly outboard of the
9 pump. As seen in figure 15, the fire pump was protected by a vertical guard pipe forward of the pump.
10 According to a diagram supplied by TOTE, a platform was located above the pump and a vertical ladder
11 was installed near the pump.⁹⁷

⁹⁴ AMOS maintenance system.

⁹⁵ MBI transcript: chief engineer.

⁹⁶ Arrangement of machinery material list.


⁹⁷ General arrangement AutoCad drawing.



1

2 **Figure 16.** Left photo shows emergency fire pump in No. 3 hold (photo by Maine Maritime Academy
3 cadet). On right, diagram of emergency fire pump location in No. 3 hold, deck four (drawing by Tote).

4 While aboard *El Yunque*, investigators located the emergency fire pump in the No. 3 hold on the
5 tanktop in a similar location to that of *El Faro*'s emergency fire pump. The pump aboard *El Yunque* had
6 vertical pipes welded to the deck and framing as protection. There was no protection around the suction
7 pipe and valve.



1

2

Figure 17. Emergency fire pump and inlet piping in No. 3 hold of *El Yunque*.

3

4 **5.11. Engine Room Ventilation System**

5

6

7

8

9

The engine room ventilation system consisted of two supply fans and two exhaust fans. The axial-flow supply fans were rated for 70,000 cubic feet per minute each and were located in the casing of the engine room. The supply fan intakes were located on the aft and outboard sides of the ventilation trunk on the main deck. Fire damper handles were located on the aft bulkhead of the ventilation trunk on deck No. 2. The fans discharged outside air into ductwork in the engine room to distribute the air throughout the

1 spaces. The engine room exhaust fans were rated for 43,000 cubic feet per minute each and were located
2 in the upper casing of the engine room. The exhaust fans discharged air through ductwork leading to the
3 aft side of the lower navigation bridge deck.⁹⁸

4

5 **6. Maintenance**

6 **6.1. AMOS**

7 The crew of *El Faro* used a computerized preventive maintenance, spare parts, and purchase
8 tracking system called AMOS (Asset Management Operational System). Investigators reviewed
9 maintenance records and purchase orders for the previous 2 years, downloaded from the operating
10 company's file server, and conducted interviews. The off-duty chief and first and second assistant
11 engineers reported no overdue or deferred maintenance at the time of the accident.⁹⁹ The *El Faro* port
12 engineer stated in an interview that he did not check work orders for their completion status and was
13 unaware if there were any outstanding work orders.¹⁰⁰ In an interview, the director of ship management-
14 commercial said that he did not monitor the activity in AMOS on a daily, weekly, or monthly schedule,
15 but did so when an issue was communicated to him. The director further stated that completion of planned
16 maintenance was verified through internal audits. The chief engineer and first assistant engineer were the

⁹⁸ Arrangement of machinery material list.

⁹⁹ Interviews: off-duty chief engineer, off-duty first assistant engineer, off-duty second assistant engineer.

¹⁰⁰ Interview: port engineer.

1 only engine department officers with access to AMOS. They would manually enter maintenance histories
2 and order spare parts.¹⁰¹

3 Each piece of equipment on the vessel was assigned a “component number” in AMOS, and
4 periodic “work orders” were assigned to these components based on weekly or monthly intervals. In 2014,
5 308 records were entered for various maintenance tasks by the deck and engine departments. Routine
6 maintenance, such as inspections, oil changes, lubrication, and manufacturer’s recommended
7 maintenance, were recorded as part of the planned maintenance program. Equipment tests and surveys
8 were also recorded in the database. In 2015, 435 maintenance records were entered into the system up to
9 the time of the accident. A total of 23 entries were made in 2014 and 11 in 2015, under the
10 “Unplanned/Corrective” class of maintenance, in which machinery failures that had been corrected were
11 identified and rectified aboard the ship.¹⁰²

12 **6.2. Boiler Inspection**

13 According to AMOS entries and an email sent by the chief engineer on July 29, 2015, the crew
14 had inspected and cleaned the port boiler on July 11, 2015. The chief engineer advised the port engineers
15 that the brickwork was getting worse and that the front waterwall tubes were bowing out “even further.”
16 The crew had inspected and cleaned the starboard boiler on July 25, 2015, and reported that the front wall
17 brickwork was starting to fail and that the front waterwall tubes were bowing out.¹⁰³ As a result of the
18 inspections, the chief engineer recommended that Walashek complete a boiler survey to determine the

¹⁰¹ Interviews: off-duty chief engineer, off-duty first assistant engineer, off-duty second assistant engineer.

¹⁰² AMOS written history.

¹⁰³ AMOS written history.

1 scope of work to be completed in the shipyard. He recommended that the boilers needed the front wall
2 brickwork repaired or replaced, burner throats renewed, floor brick replaced, and all fire stops repaired.
3 The port engineer responded to the email the following day, stating that he had contacted Walashek to set
4 up inspections and that he wanted to start on the work as soon as logistically possible.¹⁰⁴

5 The fire side of the starboard boiler was inspected by the Walashek boiler repair company
6 (Jacksonville) on September 11, 2015, to identify required maintenance to be addressed during the
7 upcoming shipyard repair period (scheduled for November 2015). The inspection report indicated that the
8 front waterwall tubes were bowed, the refractory damaged, and the burner throats deteriorated.¹⁰⁵ The
9 “highly recommended” repairs included renewing the front wall tubes, brickwork, and burner throats on
10 both boilers. The Walashek representative did not recommend a time frame for the repairs and stated in
11 an interview that in his professional opinion, a couple of months could have elapsed from the inspection
12 date to the repairs.¹⁰⁶ Walashek also recommended restoring the furnace decks, removing the waterwall
13 and superheater handhole plates to inspect headers and seats, opening both steam and water drums for
14 water side inspection, and inspecting a sample of the generator and water tubes with a borescope for pitting
15 and corrosion. Walashek reported that the port boiler economizer had seven temporary tubes (jumpers)
16 installed, signs that the upper bank was starting to fail. Walashek recommended retubing the upper
17 economizer bank.¹⁰⁷

¹⁰⁴ Chief engineer email to port engineer July 29, 2015.

¹⁰⁵ Walashek boiler report, September 11, 2015.

¹⁰⁶ MBI 1 transcript: Walashek representative.

¹⁰⁷ Walashek boiler report, September 11, 2015.

1 The port boiler was not inspected by Walashek, but it was assumed to be in the same condition as
2 the starboard boiler, based on discussions with the *El Faro* off-duty chief and first and second assistant
3 engineers. On September 24, 2015, Walashek prepared a repair estimate for TOTE based on the
4 inspection. The list in the estimate did not include tube repair or replacement.¹⁰⁸ TOTE provided an
5 estimated budget for the 2015 shipyard repairs that included anticipated costs for “economizer
6 replacement/upgrade—port and starboard boilers” under the category “life extension items.”¹⁰⁹ The
7 Walashek representative conducting the boiler inspection had not been trained by the boiler
8 manufacturer.¹¹⁰ According to statements he made at the Coast Guard MBI, the representative did not
9 have any certification that authorized or qualified him to conduct boiler inspections. He had worked for
10 Walashek for 14 years, starting as a boilermaker, and had worked his way up to lead man and
11 superintendent, doing repairs and working on multiple projects.¹¹¹ The boiler inspection was conducted
12 while the ship was under way from San Juan to Jacksonville with the starboard boiler out of operation.
13 The captain had notified the Coast Guard about the single-boiler operation before departure.¹¹²

14 The last water side survey of the *El Faro* propulsion boilers was conducted by ABS in December
15 2013. The survey checklist stated that both boilers had been surveyed, including the internal water side
16 and fire side, boiler mountings, and safety valves, and that the vessel’s maintenance history had been
17 reviewed. The checklist indicated that a hydrostatic test had been completed on December 9, 2013, but

¹⁰⁸ Walashek repair estimate, September 24, 2015.

¹⁰⁹ Tech review comments: TOTE: TOTE00110663 shipyard estimate

¹¹⁰ MBI hearing.

¹¹¹ MBI hearing, February 25, 2016.

¹¹² Coast Guard-supplied emails.

1 the checklist sheets were not used by the surveyor to include comments or numerical data concerning the
2 tests. As a result, pressures were not included in the documentation.¹¹³ Investigators examined AMOS
3 maintenance records during December 2013 for the boilers. An entry for the boiler with component No.
4 BLR.226.02.001 (starboard) indicated that on December 20, 2013, “inspected boiler internals in shipyard
5 looked ok.” A second entry in AMOS for the boiler with component No. BLR.226.02.002 (port) stated,
6 “inspected the boiler in the shipyard December 2013, boiler in good condition.” Both entries were made
7 by the chief engineer.¹¹⁴ No values were recorded in AMOS for test results such as hydrostatic pressure.

8 NTSB investigators requested boiler water chemistry test results for the past 2 years from Drew
9 Marine, the company that supplied test and treatment chemicals. Investigators received evaluative reports
10 of the March 8, 2014, test results for the feedwater system in the following areas: evaporator air ejector
11 drains, condensate system, reserve feed tanks, distilled tank, and atmospheric drain tank. Drew Marine’s
12 analysis found that copper was exceptionally high in the air ejector drains, condensate, reserve tanks, and
13 distilled tank. Iron was exceptionally high in the condensate system, reserve tanks, and distilled tank.
14 Drew recommended cleaning the reserve and distillate water tanks, followed by deaeration and oxygen
15 scavenging.¹¹⁵

16 The test on March 20, 2014, found that the boiler water chemistry contained very high pH and
17 conductivity. Drew Marine recommended that the boiler water sides be inspected for deposits or signs of
18 corrosion. The engineering logbooks between December 2014 and September 2015 showed that the

¹¹³ ABS boiler survey report, December 30, 2013.

¹¹⁴ AMOS written history, 2013

¹¹⁵ Drew Chemical report.

1 shipboard engineers recorded the following boiler chemistry daily: total dissolved solids, pH, chlorides,
2 phosphates, and hydrazine.¹¹⁶ Engine logbooks, AMOS, and interviews with off-duty crewmembers did
3 not discuss any record of Drew’s recommendations from March 2014 being carried out.

4 **6.3. Economizer Repairs**

5 Water leaks developed in the port boiler economizer in August 2015. Jacksonville Machinery and
6 Repair, a shoreside company, repaired the economizer by installing welded jumpers around the leaking
7 tube passes. According to the ABS surveyor, the repairs were tested to 800 psi on September 8, 2015,
8 about a week after the repairs were done.¹¹⁷ The test pressure took into account the discretion afforded
9 by ABS rules for such testing, the fact that the vessel had made a round-trip to San Juan the previous
10 week at operating pressure, and the working pressure on the boiler while the vessel was in port. An off-
11 duty chief engineer was employed aboard the vessel as a supernumerary at the time of the repairs, and
12 recalled that the chief engineer stated that the economizer had been successfully tested at 1,000 psi.¹¹⁸
13 Investigators requested the service report, but TOTE advised that a service report had not been provided,
14 because Jacksonville Machinery and Repair issues “invoice descriptions.” Neither the engine logbook
15 nor AMOS contained any entries regarding the repairs or testing.¹¹⁹

¹¹⁶ Engine logbook.

¹¹⁷ Interview: ABS surveyor.

¹¹⁸ Email from off-duty chief engineer

¹¹⁹ Interviews: off-duty *El Faro* chief engineer and first assistant engineer, Jackson Machinery and Repair representative.

1 **6.4. Lube Oil Analysis**

2 The lubricating oil in critical machinery systems was periodically sampled and sent to a Chevron
3 LubeWatch laboratory for analysis. Investigators examined the last 2 years of results. All critical systems
4 received acceptable results, except for the oil in the stern tube and strut bearing systems. The strut tube
5 bearing oil was tested at the Kemel Company in Hyogo, Japan, on July 3, 2014, and rated as “normal.” It
6 was in the “alert” state in analyses dated January 3, 2015, April 14, 2015, and July 21, 2015, and in the
7 “caution” rating on June 6, 2015.¹²⁰ The stern tube bearing was reported by Chevron LubeWatch in the
8 “caution” range on May 19, 2010, “normal” on October 20, 2010, “severe” on January 14, 2014, and
9 “abnormal” on May 7, 2015.¹²¹

10 **6.5. Stern Tube System and Strut Bearing Analysis**

11 In May 2015, Chevron LubeWatch results indicated that all wear rates were normal in the stern
12 tube system. Water content was acceptable, the total acid number was above the recommended limit, and
13 viscosity was within the specified operating range. Actions required were to sample at a reduced service
14 interval to monitor further. In January 2014, the oil had been reported as “severe,” containing elevated
15 lead, tin, aluminum, and silicon levels.

16 Also in January 2014, analysis of the oil in the strut bearing system indicated a high level of wear
17 metals as well as high levels of silicon, sodium, and potassium. The analysis report stated that the oil

¹²⁰ Kemel test results.

¹²¹ Chevron LubeWatch UINC95A.

1 additives were consistent with the type of oil tested. The recommended action was to check for higher
2 operating temperatures, change oil and filters, check filters for debris, and sample immediately.

3 In April 2015, a strut bearing sample was sent to the Kemel Company for analysis. The results
4 showed that the oil contained high levels of tin, which placed the oil in the alarm state. The results were
5 consistent with the analysis of three previous oil samples taken at 6-month intervals.

6 The strut bearing oil was most recently sampled in July 2015 and analyzed by Kemel. The stern
7 tube oil was once again in the alert status, showing high levels of tin. The equipment's condition was
8 evaluated as poor, and the recommendation was to replace the oil.

9 The shipyard scope of work for 2015 included optional inspection and repair of the strut shaft seal
10 assembly. It also called for an optional flush of the strut bearing oil system, including the piping and head
11 tank. AMOS contained no information about completed strut maintenance. Maintenance by a Kemel
12 representative on the stern tube seal indicated that the forward strut seal had been overhauled with the tail
13 shaft withdrawn while *El Faro* was drydocked from December 15 to December 28, 2013. The
14 representative reported that the forward sealing ring had normal wear, but that the aft sealing ring had
15 4 millimeters of "blistered" condition. Kemel overhauled the aft seal rings with the tailshaft withdrawn
16 and machined 1.0 millimeter off the liner diameter. It was reported that the liners had not been supplied
17 by Kemel.¹²²

¹²² Kemel shipyard report

1 **6.6. Riding Gang**

2 A five-member riding gang, all pipefitters, was aboard the vessel at the time of the accident. The
3 pipefitters, Polish nationals, had signed on as supernumeraries. They were working to refit the ship for a
4 return to the Alaska trade by reinstalling winches, cables, and piping systems. They were under the
5 direction of an off-duty chief engineer who was aboard the ship at the time of the accident.¹²³ Their scope
6 of work consisted of the following:¹²⁴

- 7 • Reinstall Butterworth heater.
- 8 • Reinstall saltwater piping for Butterworth heater.
- 9 • Reconnect sea chest steam-out connections.
- 10 • Install saltwater recirculation system.
- 11 • Reinstall ramp deicing.
- 12 • Verify functionality of freshwater cooling system.
- 13 • Install forward shore ramp (to be done in Tacoma).
- 14 • Install midship shore ramp (Tacoma).
- 15 • Install aft shore ramp (Tacoma).
- 16 • Install forward shore ramp (Anchorage).
- 17 • Install midship shore ramp (Anchorage).
- 18 • Remove covers over deck ramps to allow vehicle access.
- 19 • Install constant-tension winch.

¹²³ Interviews: port engineer, off-duty chief engineer.

¹²⁴ Scope of work for Alaska conversion (TOTE).

1 According to off-duty crewmembers, there was a language barrier between the ship's crew and the
2 riding gang. The most senior member of the riding gang spoke some English and would translate to the
3 rest of his team. The rest of the team did not speak English.¹²⁵

4 According to off-duty crewmembers, the riding gang went through orientation and familiarization
5 regarding lifeboat stations. For abandon-ship drills and procedures, the riding gang was divided between
6 the vessel's two lifeboats.¹²⁶

7 An off-duty engineer from the operating company, who held credentials as a chief engineer,
8 supervised the riding gang. He had sailed on several of the *Ponce*-class ships since 2004 in various
9 engineering capacities. He had also worked as a first assistant engineer aboard *El Faro* since 2014. He
10 was employed as a supernumerary during the accident voyage, having been hired to oversee the Alaska-
11 conversion project. He updated the port engineer regarding progress and part requests.¹²⁷

12 **7. Survey and Inspection**

13 **7.1. US Coast Guard**

14 **7.1.1. Alternate Compliance Program**

15 The Alternate Compliance Program (ACP) is a voluntary process by which US vessels can
16 obtain a Coast Guard Certificate of Inspection (COI) by complying with the standards of an authorized
17 classification society. The program is intended to avoid redundancies in the inspection regimes of the

¹²⁵ MBI testimony by off-duty chief engineer. Interview of chief engineer.

¹²⁶ MBI testimony by off-duty chief engineer.

¹²⁷ Alaska conversion system summary list. Interviews: off-duty chief engineer, port engineer.

1 Coast Guard under the *Code of Federal Regulations* (CFR) and international conventions and by the
2 classification societies under their class rules, while maintaining equivalent levels of safety for US-
3 flagged vessels. In effect, the Coast Guard delegates to the class society the authority to conduct vessel
4 inspections and tonnage measurements and to accept plan reviews and approvals.¹²⁸ The inspection
5 and survey requirements for a vessel enrolled in the ACP would be governed by international
6 conventions, class rules, and an approved US Supplement. The US Supplement was established to
7 reconcile the different standards in the CFR and class rules for surveys, tests, or inspections.¹²⁹ The
8 program began operating in February 1995. It was designed to enhance the competitiveness of the US
9 maritime industry while maintaining a level of safety and environmental protection equivalent to
10 Coast Guard regulations.¹³⁰

11 The program constitutes an alternate method for owners of US-flagged vessels to fulfill the
12 regulatory requirements for vessel design, inspection, and certification. The Coast Guard can issue a COI
13 based on reports issued by authorized and recognized classification societies confirming that a vessel
14 complies with applicable international conventions, classification society rules, and other requirements.
15 ACP is an option for owners of tank vessels, passenger vessels, cargo vessels, miscellaneous vessels, and
16 mobile offshore drilling units that engage in international voyages.¹³¹

17 At the time of the accident, the Coast Guard had entered into formal agreements with five
18 classification societies for ACP participation, under the authority of 46 USC 3316: American Bureau of

¹²⁸ U.S. Supplement and MOU – ABS.

¹²⁹ Tech review comments: ABS.

¹³⁰ Tech review comments: ABS.

¹³¹ USCG.mil.

1 Shipping, Class NK, Det Norske Veritas, Germanischer Lloyd, and Lloyd's Register. The agreements
2 cover the delegation of certain statutory survey and certification functions for US-flagged vessels.
3 Delegated function means a function related to Coast Guard commercial vessel inspection that has been
4 delegated to a recognized classification society.

5 According to Coast Guard inspectors interviewed after the accident, the Coast Guard's oversight
6 of an ACP vessel may include inspections which are less stringent than what would be required of a vessel
7 not enrolled in the ACP program, since the ABS is conducting surveys on their behalf. Coast Guard
8 inspectors are given a special inspection book for conducting ACP examinations of freight vessels (CG-
9 840 ACP FV). Inspectors use inspection book CG-840 MI for full examinations.¹³² According to the Coast
10 Guard, inspection book CG-840 ACP FV has not been revised since January 2001, and inspectors used
11 the CG-840 book with a 1999 revision date during the March inspection of *El Faro*.¹³³ Coast Guard
12 inspectors refer to Navigation and Vessel Inspection Circular 02-95, change 2, with an issue date of May
13 5, 2006.¹³⁴

14 Results of surveys conducted by ABS are recorded in a web-based database (eagle.org). The
15 system is designed so that Coast Guard inspectors can access the database to review previous results before
16 attending vessels for examinations, although there is no written requirement to do so.¹³⁵ Coast Guard

¹³² Interviews: Coast Guard.

¹³³ Tech review comments: USCG

¹³⁴ Tech review comments: USCG

¹³⁵ Interviews: Coast Guard personnel.

1 inspectors and ABS surveyors typically communicate by email regarding vessel inspections and
2 findings.¹³⁶

3 According to the Coast Guard, as of September 2016, the US inspected fleet contained 228 active
4 diesel-powered cargo vessels and 39 active steam-propulsion cargo vessels.¹³⁷

5 **7.1.2. *El Faro* inspections**

6 *El Faro*, which was enrolled in the ACP, had successfully completed an annual survey by an ABS
7 surveyor on February 16, 2015, in Jacksonville. The Coast Guard issued a COI on March 6, 2015, in San
8 Juan, which stated that the vessel was “fit for route and service.”¹³⁸

9 The Coast Guard maintained an “ACP Targeted Vessel” list that was updated annually around
10 October 1. The Coast Guard used an automated risk matrix to determine whether a vessel should be on
11 the targeted list. Point values were assigned to the matrix for issues such as operational controls, port state
12 detentions, overdue deficiencies, major non conformities in SMS audits, marine casualties, vessel service,
13 and vessel age. Ten percent of vessels with the highest aggregate score were added to the list. According to
14 the Coast Guard, at the time of the accident, *El Faro* had not been added to the 2016 ACP Targeted Vessel
15 List, but was slated to be added on October 1, 2015, the day of the accident.¹³⁹

16 *El Faro* had recently reported a medical emergency, which was scored as a “marine casualty”
17 under Coast Guard regulations and added enough points to include the vessel on the targeted list for 2015.

¹³⁶ Interviews: Coast Guard and ABS personnel.

¹³⁷ Email from USCG.

¹³⁸ Interviews: Coast Guard inspector.

¹³⁹ Interviews: Coast Guard inspector.

1 Two additional casualties (one loss of propulsion as a result of crew error and an oil spill) occurred that
2 would have added points to the vessel's total but were not scored by the automated risk matrix because
3 the Coast Guard's data system (MISLE) was in transition at the time, which prevented timely data entry.¹⁴⁰
4 According to the Coast Guard, no operational controls were placed on *El Faro* at the time of the accident.

5 Vessels on the targeted list are subject to additional oversight at the 6-month mark of the
6 examination cycle. The scope of examination can be increased if inspectors find safety issues on board.
7 The Coast Guard had guidance stating that targeted vessels "shall be attended during drydock...
8 activities," but that the Officer in Charge of Marine Inspection (OCMI) had the discretion to determine
9 whether oversight attendance was necessary, considering "operational concerns, unit resources, as well
10 as the extent and reasoning of repairs."¹⁴¹

11 The Coast Guard inspectors who attended the annual COI examination in March 2015 in San Juan
12 had the following qualifications and experience:

- 13 • The lead inspector had over 22 years of experience in the Coast Guard, receiving his first
14 inspection qualification in 1993. He was one of 21 marine inspection training officers in
15 the Coast Guard. He had numerous qualifications at the time of the 2015 COI exam,
16 including machinery, machinery-steam, (which is an extension of the basic machinery
17 qualification), and drydock. He was in the process of developing updated test and training
18 procedures for issuing qualification letters to Coast Guard inspectors. All his qualifications

¹⁴⁰ Tech review comments: USCG.

¹⁴¹ Message R 221722Z from USCG.

1 were current at the time of the 2015 inspection.¹⁴² The lead inspector held the title “Marine
2 Inspection Training Officer.”¹⁴³

- 3 • Three other Coast Guard inspectors participated in the annual COI examination of *El Faro*
4 in March 2015. The machinery inspector had 27 years of experience in the Coast Guard.
5 According the Coast Guard, the inspector had not completed any of the requirements to
6 receive command approval for the qualifications for his machinery steam qualification at
7 the time of the inspection. He participated in the *El Faro* inspection to gain experience with
8 a steam plant but had not received any official signoffs to become qualified.¹⁴⁴

9 The Coast Guard created seven Centers of Expertise in 2009 in an effort to improve marine safety
10 and increase competency in marine inspection and investigation. The centers offered operational support,
11 technical expertise, and focused training to Coast Guard personnel and maritime industry representatives.
12 The activities of the centers included consulting about design, examination, and operational situations and
13 the development of regulations, policies, and doctrines. The centers also helped train Coast Guard
14 inspectors.¹⁴⁵

15 The Vintage Vessel Center of Expertise, created in 2009 and based in Duluth, Minnesota, focused
16 on the steam propulsion systems of commercial cargo vessels or vessels with riveted hulls. According to
17 Coast Guard inspectors, the center closed in 2013. Most of the center’s work dealt with freshwater vessels
18 in the Great Lakes. It also encompassed older vessels operating in any environment—steamers in the US

¹⁴² Interviews: Coast Guard inspector.

¹⁴³ Interviews: Coast Guard inspector.

¹⁴⁴ Tech review comments: USCG

¹⁴⁵ USCG.mil.

1 Maritime Administration's National Defense Reserve Fleet, older warships and sailing vessels, and any
2 vessels built using equipment no longer in standard production. The center's experts were expected to
3 develop and maintain vintage-vessel inspection competencies and curricula, inspect vintage vessels, and
4 establish merchant marine training in steam-powered and legacy-hull fleets.¹⁴⁶

5 **7.2. American Bureau of Shipping**

6 ABS is a not-for-profit classification society founded in 1862. A classification society is a
7 nongovernmental organization that establishes and maintains technical standards for the construction
8 and operation of ships and offshore structures. Classification societies provide classification and
9 statutory services and assist the maritime industry and regulatory bodies with regard to maritime safety
10 and pollution prevention based on accumulated maritime knowledge and technology. The objective of
11 ship classification is to verify the structural strength and integrity of the essential parts of a ship's hull
12 and its appendages, as well as the reliability and function of the propulsion and steering systems, power-
13 generation systems, and other features that maintain essential services on board. Classification societies
14 aim to achieve this objective through the development and application of their own rules and by
15 verifying compliance with international or national statutory regulations on behalf of flag
16 administrations.

17 A classification certificate should not be construed as a warranty of safety, fitness for purpose,
18 or seaworthiness of a ship. It is an attestation only that the vessel is in compliance with the rules that
19 have been developed and published by the society issuing the certificate. Further, classification societies
20 are not guarantors of the safety of life or property as sea or the seaworthiness of a vessel because,

¹⁴⁶ USCG.mil.

1 although the classification of a vessel is based on the understanding that the vessel is loaded, operated,
2 and maintained in a proper manner by competent and qualified personnel, the society has no control
3 over how a vessel is operated and maintained between the periodical surveys it conducts.¹⁴⁷

4 According to the ABS website, “The mission of ABS is to serve the public interest as well as the
5 needs of our members by promoting the security of life and property and preserving the natural
6 environment through the development and verification of standards for the design, construction and
7 operational maintenance of marine-related facilities.¹⁴⁸

8 *El Faro* was classified as “steel” by ABS and the vessel’s status indicated “reduced scantlings”
9 based on corrosion control. *El Faro* was designated by ABS with the notation:

⊠A1, Vehicle Carrier, ⊕, ⊠AMS

10

11 The Maltese cross symbol is assigned to “vessels and off shore units for which the hull construction
12 and/or the manufacture of its machinery and components and any associated required testing, as
13 applicable, is carried out under ABS survey.” The Maltese cross followed by “A1” is a classification
14 symbol that indicates “compliance with the hull requirements of the ABS Rules or their equivalent for
15 unrestricted ocean service and survey by ABS during construction of the vessel.” “Vehicle Carrier” is a
16 notation assigned to a vessel designed and constructed to carry roll-on/roll-off cargoes, including vehicles,
17 cargoes on pallets, etc...and forms part of the classification designation assigned to vessels built in

¹⁴⁷ Website of International Association of Classification Societies <iacs.org.uk>.

¹⁴⁸ ABS website <ww2.eagle.org>.

1 accordance with the ABS Rules for Building and Classing Steel Vessels.” Circle E is a classification
2 symbol that signifies that “the equipment of anchors and chain cables of the vessel is in compliance with
3 the requirements of the ABS Rules, or with the requirements corresponding to the service limitations noted
4 in the vessel’s classification which have been specifically approved for the particular service.” The
5 Maltese cross followed by “AMS” is a classification notation that indicates that a vessel’s machinery,
6 boilers, and systems have been constructed and installed under ABS survey in accordance with the
7 requirements of the ABS Rules.”¹⁴⁹

8 **7.2.1. Qualification of Surveyors**

9 The three ABS surveyors who had attended surveys of *El Faro* in Jacksonville and San Juan since
10 2014 were qualified as follows:

- 11 • The surveyor in Jacksonville held a third assistant engineer’s credential and was a graduate
12 of Massachusetts Maritime Academy. The surveyor had been with ABS for about 7-1/2
13 years after shipping out for a few years and working as a service technician for
14 manufacturers of diesel engines and air compressors. The surveyor transferred to
15 Jacksonville in March 2014 and was in charge of ABS’s project to support new offshore
16 construction (such as drilling platforms). The surveyor attended several ABS academy
17 classes, which included classroom, field, and on-the-job training.¹⁵⁰
- 18 • The San Juan surveyor graduated from the US Merchant Marine Academy in 2004 and
19 sailed as an assistant engineer until 2008, when the surveyor joined ABS. The surveyor

¹⁴⁹ ABS Notations and Symbols February 9, 2016.

¹⁵⁰ Interviews: ABS surveyors.

1 worked at ABS in Ft. Lauderdale, Florida, until November 2013, and then transferred to
2 ABS San Juan. At the time of the *El Faro* inspections, the surveyor held a second
3 engineer's credential for motor (unlimited) and a third engineer's credential for steam
4 (unlimited). The surveyor attended several ABS academy classes, which included
5 classroom, field, and on-the-job training.¹⁵¹

- 6 • The second ABS surveyor from Jacksonville graduated from Massachusetts Maritime
7 Academy in 2007 and went to work for ABS in August of that year in the ship engineering
8 department, as a review engineer for piping systems and equipment. In 2008, the surveyor
9 transferred to the survey department in Tampa, and then transferred to Jacksonville in July.
10 The surveyor attended several ABS academy classes, which included classroom, field, and
11 on-the-job training.¹⁵²

12 **7.2.2. *El Faro* Surveys by ABS: 2014–2015**

- 13 • On January 19, 2015, an ABS surveyor attended *El Faro* to complete the annual survey.
14 The emergency generator was tested online, and bilge alarms, steering gear, and lube oil
15 pumps were all tested. Paperwork for the radio equipment was verified. There were no
16 concerns or findings.¹⁵³
- 17 • On January 23, 2015, an ABS surveyor attended *El Faro* to conduct the annual hull survey.
18 Examined were handrails, welding on decks, ventilation ducts, mooring cleats, cargo doors,

¹⁵¹ Interviews: ABS surveyors.

¹⁵² Interviews: ABS surveyors.

¹⁵³ Interviews: ABS surveyors.

1 gangway, and stability book. A drainage plug in the forward bosun's locker was found to
2 have a small area of wastage. That finding was included in the report.¹⁵⁴

- 3 • On January 27, 2015, an ABS surveyor attended *El Faro* to inspect the coating of ballast
4 tanks No. 1 port and starboard, which had been rated in "poor condition" in the ABS hull
5 survey.¹⁵⁵ The tank coating was still noted as poor after the inspection. During the
6 inspection of the No. 1 port DB ballast tank, frames 50 and 51 were found to be detached
7 at the outboard connection to the tank top. The fillet welds were fractured from the tank
8 top plating between the weld access hole on the frame at the side shell to 2 feet inboard,
9 terminating at another weld access hole (referred to as a "rat hole"). The surveyor
10 recommended that the area be repaired, but TOTE was not required to perform any
11 temporary repairs at that time. The welds were to be repaired at the special periodical
12 survey due on February 26, 2016.
- 13 • On March 10, 2015, an ABS surveyor attended *El Faro* to verify repairs of the steering
14 system to correct a problem, identified during the COI inspection, with a faulty
15 potentiometer that caused an error of 3° to 4° when steering to starboard. The repairs were
16 completed, and the system tested properly.¹⁵⁶
- 17 • On April 14, 2015, an ABS surveyor attended *El Faro* to survey repairs completed on the
18 overhead of the forepeak space in way of the hatch in the bosun's storeroom. The area and
19 related hatch were not watertight spaces in that they were above both the waterline and the

¹⁵⁴ Interviews: ABS surveyors.

¹⁵⁵ Interviews: ABS surveyors.

¹⁵⁶ Interviews: ABS surveyors, Coast Guard inspector.

1 vessel's watertight deck. The area was repaired to the satisfaction of the surveyor, and no
2 pressure tests were needed to test the sufficiency of the repair to this nonwatertight area.¹⁵⁷

- 3 • On June 16, 2015, an ABS surveyor attended *El Faro* to conduct a continuous machinery
4 survey, during which various pumps were operated, including the bilge/ballast pumps.
5 The emergency generator was also started and tested. No deficiencies were found.¹⁵⁸
- 6 • On September 8, 2015, an ABS surveyor attended *El Faro* to survey repairs completed on
7 the port boiler, in which Jacksonville Machinery and Repair installed jumpers on seven
8 leaking economizer tubes. The welding repair to the tubes was inspected and found to be
9 to the satisfaction of the attending ABS surveyor. The repairs had been carried out
10 approximately 2 weeks earlier. The vessel had made a round-trip to San Juan the previous
11 week under normal operating pressure, with no reported problems. A hydrostatic test was
12 performed at 800 psi, which the surveyor considered to be sufficient based on the
13 examination of the repair, the pressure at which the boiler was operating at the time of the
14 survey, and the discretion provided by the ABS rules and the ACP Supplement to determine
15 the testing pressure.¹⁵⁹

16 **8. Engineering Staff**

17 The *El Faro* engineering department consisted of 11 personnel. It had six engineering officers—
18 one chief engineer, one first assistant engineer, one second assistant engineer, and three third assistant

¹⁵⁷ Interviews: ABS surveyors.

¹⁵⁸ Interviews: ABS surveyors.

¹⁵⁹ Interviews: ABS surveyors.

1 engineers. Five crewmembers were also aboard—three oilers and two qualified members of the engine
2 department (QMEDs)/reefer (refrigerator) electricians. The officers were members of the American
3 Maritime Officers (AMO) union, and the crewmembers were members of the Seafarers International
4 Union (SIU).¹⁶⁰

5 The engine department stood manned watches in the engine room at all times. The second and
6 third assistant engineers would stand in 4-hour-on and 8-hour-off rotations. The second assistant engineer
7 stood the 4-to-8 watch, and the third assistant engineers stood the 8-to-12 and 12-to-4 watches. The oilers
8 stood watch in the engine room on a 4-hour-on and 8-hour-off schedule. The chief engineer, first assistant
9 engineer, and QMEDs were dayworkers.¹⁶¹

10 **8.1. Officers**

11 All *El Faro* engineering department officers held credentials issued by the Coast Guard.¹⁶² The
12 third assistant engineering officers who graduated from Maine Maritime Academy had been trained on a
13 diesel-electric ship built in 1990 rather than on the academy's training steamship, TS *State of Maine*,
14 which it replaced in 1997.¹⁶³ The chief engineer onboard at the time of the accident, who graduated from
15 the State University of New York (SUNY) Maritime College, had been trained on a steam training ship,
16 the TS *Empire State VI*, as part of his college seagoing requirement. The first assistant engineer had been
17 trained on Massachusetts Maritime Academy's steamship TS *Enterprise*. According to documents

¹⁶⁰ Crew list.

¹⁶¹ Engine logbooks.

¹⁶² Crew personnel records.

¹⁶³ Maine Maritime Academy website <mainemaritime.edu>.

1 provided by TOTE, none of the engineering officers aboard *El Faro* at the time of the accident had been
2 selected to initially crew TOTE’s new liquid natural gas-fueled container ships, the *Isla Bella* and the
3 *Perla Del Caribe*.¹⁶⁴ TOTE stated that the chief engineer, first assistant engineer, and two third assistant
4 engineers had been sent for training at the engine manufacturer’s facility in preparation to rotate them
5 onto the new ships.¹⁶⁵

6 Investigators reviewed the personnel files for each of the engineering officers aboard *El Faro* at
7 the time of the accident. Chief engineers were “required to complete evaluations on all licensed officers
8 whenever an officer was detached for any reason.”¹⁶⁶ Each officer was evaluated on eleven categories
9 such as cooperation, leadership, attention to assigned duties, watchstanding ability, mechanical ability,
10 knowledge of ship’s equipment, knowledge of company policy and procedures, and personal
11 conduct/appearance. The evaluation sheet used a scale of “poor, fair, good, very good, and excellent” to
12 evaluate the officers. The sheet contained a section for remarks where the chief engineer could describe
13 positive qualities, areas where improvement could be made, and measures taken to further improvement.
14 Boxes could be checked to indicate whether the evaluation had been reviewed with the officer in question
15 and if the individual was recommended for reassignment to the vessel.¹⁶⁷ The company’s safety
16 management system (SMS) had a policy that required the chief engineer to be evaluated periodically. The
17 details of this requirement are discussed in section 9, “Company Safety Management System.”

¹⁶⁴ Crewing lists for *Isla Bella* and *Perla Del Caribe*.

¹⁶⁵ Tech review comments: TOTE.

¹⁶⁶ Ship’s officer evaluation/performance report.

¹⁶⁷ Ship’s officer evaluation/performance report.

1 **Chief Engineers.** The chief engineer on *El Faro* at the time of the accident graduated from SUNY
2 Maritime College in 2003. His most recent credential was issued on November 4, 2014, and expired on
3 November 4, 2019. He was qualified as a chief engineer of steam, motor, and gas turbine vessels of any
4 rating. He joined the ship on August 18, 2015.¹⁶⁸

5 The chief engineer at the time of the accident had undergone several official shipboard evaluations
6 throughout his career with Sea Star/TOTE as a junior officer. On July 22, 2013, while aboard *El Yunque*
7 as first assistant engineer, he received ratings of “very good” or “excellent” in all categories. He was
8 reported to be “intelligent, hard-working, and [having a] good attitude.” He had no areas that required
9 improvement, according to the evaluation. An evaluation as first assistant engineer while aboard *El Morro*
10 on January 5, 2012, stated that he was a “hard working and knowledgeable first (assistant engineer)
11 working his way to becoming a chief” and that he was “able to work through difficult times.”¹⁶⁹

12 Another evaluation was completed on April 14, 2011, while the *El Faro* chief engineer at the time
13 of the accident was aboard *El Morro* as first assistant engineer. Ratings were in the “excellent” and “very
14 good” range. Comments indicated that he had a “can-do attitude, great work ethic and brings a lot of steam
15 experience to *El Morro*.” The evaluation stated that “since he has not spent his whole career at Sea Star,
16 he brings new ideas, methods, management style, and troubleshooting skills to *El Morro*. Great knowledge
17 of steam plant operations.” An evaluation completed in August 2011 as first assistant engineer stated that
18 he was “a pleasure to sail and work with,” and that he was “very self-motivated and works well with the

¹⁶⁸ Crew personnel records.

¹⁶⁹ Crew personnel records.

1 crew and the jobs at hand.”¹⁷⁰ TOTE provided one draft evaluation for the chief engineer, dated October
2 2, 2014, in which the evaluation stated that the chief engineer was “driven to do the best job possible. The
3 ship and crew reflect that.” Ratings for each evaluation criteria were 5 out of 5, meaning “exceptional.”¹⁷¹

4 The off-duty chief engineer who was interviewed by investigators graduated from Maine Maritime
5 Academy in 1996 and started with TOTE in 1999. He began sailing as chief engineer in 2006 aboard the
6 sister ship *El Morro*, and became chief engineer of *El Faro* in 2013.¹⁷²

7 **First Assistant Engineers.** The first assistant engineer on *El Faro* at the time of the accident
8 graduated from Massachusetts Maritime Academy in 2005. His credential was issued on May 8, 2015,
9 and was due to expire on May 8, 2020. He was qualified as chief engineer of steam, motor, and gas turbine
10 vessels of any rating.¹⁷³

11 He joined the ship 2 months before the accident, on August 4, 2015. His first TOTE vessel was *El*
12 *Morro*, which he joined as a third assistant engineer in January 2010. He had several evaluations from
13 chief engineers as second and third assistant engineer in the fair/good/very good range. In January 2015,
14 after his first trip as a first assistant engineer aboard *El Faro*, he was evaluated by the chief engineer. Most
15 of the results were “fair” and “good,” and the chief engineer remarked that he needed “to work on his
16 communication skills,” that he “often acted without thinking in order to complete the job,” and that “his
17 work ethic was lacking in certain areas.” The evaluator also stated: “Greater attention to detail was

¹⁷⁰Crew personnel records.

¹⁷¹ TOTE evaluation of chief engineer, October 2014.

¹⁷² Crew personnel records.

¹⁷³ Crew personnel records.

1 needed.” The first assistant engineer received one “very good” result in the “knowledge of TSI (TOTE
2 Services Inc.) policy and procedures” category. A previous evaluation in January of 2015 as second
3 assistant engineer from the same evaluator showed “excellent” results in each category, and in the remarks
4 section, it was stated that the first assistant engineer “has shown he is ready and capable to sail at a higher
5 position and take on more responsibility.”¹⁷⁴

6 The off-duty first assistant engineer who was interviewed by investigators graduated from Maine
7 Maritime Academy in 1995. He worked aboard several ships before working ashore for 4 years. In 2004,
8 he returned to shipping and worked on *El Faro* when it was named the *Northern Lights*, shipped on *El*
9 *Morro*, and returned to *El Faro* when *El Morro* was scrapped.¹⁷⁵

10 **Second Assistant Engineers.** The credential of the second assistant engineer on *El Faro* at the
11 time of the accident was issued on March 30, 2012, and expired on March 30, 2017. He was qualified as
12 a second engineer of steam, motor, and gas turbine vessels of any horsepower. He received several
13 evaluations. The most recent stated that he was “one of the most dependable” and “hardest working men”
14 the chief engineer had ever worked with. He joined the ship on August 11, 2015.¹⁷⁶

15 The off-duty second assistant engineer who was interviewed by investigators graduated from
16 Massachusetts Maritime Academy in 2012 and came to TOTE after one trip on a tanker. He worked on
17 *El Morro*, and when it was scrapped, joined *El Faro*.¹⁷⁷

¹⁷⁴ Crew personnel records.

¹⁷⁵ Crew personnel records.

¹⁷⁶ Crew personnel records.

¹⁷⁷ Crew personnel records.

1 **Third Assistant Engineers.** One of the third assistant engineers on *El Faro* at the time of the
2 accident graduated from Maine Maritime Academy in 2012. His credential was issued on September 11,
3 2013, and expired on September 11, 2018. He was qualified as a third engineer of steam and motor vessels
4 of any rating. He had a recent evaluation in January 2015. Remarks stated that he was an “excellent
5 engineer and a valuable asset to the vessel.” He had made five 70-day trips aboard *El Faro* before the
6 accident.¹⁷⁸ He joined the ship before the accident voyage on September 22, 2015, in Jacksonville.¹⁷⁹

7 Another third assistant engineer at the time of the accident graduated from Maine Maritime
8 Academy in 2012. His credential was issued on July 9, 2012, and expired on July 9, 2017. He was qualified
9 as a third engineer of steam, motor, or gas turbine vessels of any horsepower. In an evaluation in
10 November 2014, the evaluator remarked that he “shows up on time” and “has done everything I asked
11 him to do.” Also, the evaluator stated that he needed to “pay attention to detail” and “become more familiar
12 with ship’s equipment and automation.” In a previous evaluation dated November 14, 2014, after he had
13 served aboard *El Yunque* as a third assistant engineer, the evaluation indicated that he had done a “very
14 good job as 3rd (assistant engineer)” and he was a “good shipmate and learned the job quickly.” The
15 evaluator stated that he needed to “take on more responsibility and start thinking on his own” and “be
16 more proactive in his job.” He had made two trips aboard *El Yunque* and one trip aboard *El Faro* before
17 the accident. He joined *El Faro* on September 15, 2015, in Jacksonville, 2 weeks before the accident.¹⁸⁰

¹⁷⁸ Crew personnel records.

¹⁷⁹ Crew personnel records.

¹⁸⁰ Crew personnel records.

1 The newest third assistant engineer onboard at the time of the accident graduated from Maine
2 Maritime Academy in 2014. His credential was issued on May 3, 2014, and expired on May 3, 2019. He
3 was qualified as a third engineer of steam and motor vessels of any rating. *El Faro* was his first ship. He
4 signed on in Jacksonville the evening *El Faro* departed on the accident voyage.¹⁸¹

5 **Riding Gang Supervisor.** The off-duty chief engineer who was sailing as a supernumerary and
6 supervising the Polish riding gang graduated from Massachusetts Maritime Academy in 1996. His
7 credential was due to expire on October 28, 2016. He was qualified as chief engineer of steam, motor, and
8 gas turbine vessels of any rating. He joined the ship on August 4, 2015, about 2 months before the accident.
9 He had previously worked aboard *El Yunque* and received positive remarks about his work ethic and safety
10 consciousness.¹⁸²

11 **8.2. Port Engineer**

12 TOTE assigned one port engineer to *El Faro* to assist with maintenance, spare parts, supplies,
13 monitoring inspections and surveys, monitoring vessel certificates, arranging for vendors to facilitate
14 repairs, and shore support. According to TOTE, a backup port engineer was assigned in case the primary
15 port engineer was unavailable.¹⁸³

16 As stated in the company-supplied job description, the port engineer was “responsible for the
17 management and supervision of every aspect of assigned commercial vessels while they are in port, at sea,

¹⁸¹ Crew personnel records.

¹⁸² Crew personnel records.

¹⁸³ MBI: port engineer testimony.

1 and in dry dock, including providing direction to all shipyard and repair vendor personnel engaged in
2 vessel repairs. Oversees installation and repair of marine power plants, propulsion systems, heating and
3 ventilation systems, and other mechanical and electrical equipment in ships and marine facilities.”¹⁸⁴ The
4 port engineer position consisted of several essential duties such as:

- 5 • Prepare budgets and work plans for vessels.
- 6 • Coordinate with captain to ensure proper cargo and other mission-related logistics.
- 7 • Make final judgment regarding mechanical issues in coordination with chief engineer.
- 8 • Review, approve, and process material and spare requisitions submitted by the vessels.
- 9 • Coordinate with captains and chief engineers to manage vessel repairs, maintenance, and
10 requisitioning for spares, goods, and services.
- 11 • Manage repair contractors, regulatory inspection, and crewing activities.
- 12 • Attend vessels to evaluate and observe overall condition and performance.
- 13 • Maintain the maintenance and repair software program.
- 14 • Oversee repairs to equipment such as boilers, turbines, and auxiliary systems.¹⁸⁵

15 The port engineer for the *El Faro* held an unlimited chief engineer’s credential for steam and motor
16 vessels. He graduated from California Maritime Academy in 1976 and had sailed for 28 years on both
17 steam and diesel ships. He started with TOTE as a port engineer in November 2013.¹⁸⁶ He said that he

¹⁸⁴ Port engineer job description.

¹⁸⁵ Port engineer job description.

¹⁸⁶ Interview: port engineer.

1 boarded *El Faro* every week when the ship was in Jacksonville and occasionally visited the ship in San
2 Juan.¹⁸⁷

3 The port engineer reported to TOTE’s director of ship management-commercial, who was
4 responsible for “ensuring all commercial vessels are in compliance with all regulatory requirements.
5 Designs and oversees installation and repair of marine power plants, propulsion systems, heating and
6 ventilation systems, and other mechanical and electrical equipment in ships, dock, and marine facilities.”
7 Other responsibilities included supervising vessel engineering staff, training employees, evaluating
8 performance of employees, developing annual business plans for vessels, coordinating day-to-day
9 activities between office and vessels, distributing pertinent vessel information to involved employees, and
10 overseeing repairs to equipment. The director of ship management-commercial reported to TOTE’s vice
11 president of marine operations–commercial.¹⁸⁸

12 **9. Company Safety Management System**

13 As required by the International Safety Management (ISM) Code and US law, *El Faro* operated
14 under a formal SMS established by the company.¹⁸⁹ TOTE’s SMS procedures were compiled in two
15 manuals, one covering vessel operations (OMV) and another covering emergency preparedness aboard
16 vessels (EPMV). The SMS also included a binder referred to as OPSMEMO that acted as a supplement
17 to the OMV and EPMV manuals acting as interim policy statements for policies that were to be
18 incorporated into the policy manuals or canceled.

¹⁸⁷ Port engineer interview, MBI testimony.

¹⁸⁸ Job description: TOTE director of ship management-commercial.

¹⁸⁹ The ISM Code is incorporated into US law at 46 USC 32. Coast Guard regulations for SMSs are found at 33 CFR 96.

1 The operations manual (OMV section 3.2.1.2) stated: “all newly joining officers and
2 crewmembers, family members, contractors, and owners authorized to sail with the vessel must be
3 indoctrinated into the vessel’s organization and more especially to their duties and responsibilities.” Some
4 crewmembers said that they were given a familiarization tour when joining the vessel. A familiarization
5 booklet was referred to by crewmembers.¹⁹⁰ NTSB investigators requested the booklet and received a
6 generic guide for contractors.

7 The company’s SMS addressed adverse weather in the navigation section of the operations manual
8 (OMV 10.8.1-4). It stated that “the master was responsible for the monitoring and analysis of the weather
9 along the vessel’s intended track.” During adverse weather, the captain was instructed to “ensure that the
10 vessel was properly handled” and to “take proper precautions to safely stow and secure all the vessel’s
11 equipment to prevent any damage to the equipment or vessel.” The captain was to “advise the HQ Office
12 of speed reductions and/or course changes due to adverse weather” and “should consider taking on
13 additional ballast in adverse weather conditions.”¹⁹¹ TOTE reported that there was “no heavy weather
14 guidance provided specifically to engineers in the OMV.”¹⁹² The company’s SMS detailed a policy (OMV
15 3.4.1, “Responsibility for: Contractors, Riding Gangs & Surveyors”) regarding contractors and riding
16 gangs while aboard the ship. The system required oversight by a chief engineer or a chief mate of “hot
17 work,” use of personal protective equipment, and job hazard analysis. The SMS policy specifically stated
18 that all members of a riding gang “shall be given an indoctrination tour of the vessel before or soon after

¹⁹⁰ Interviews: crewmembers.

¹⁹¹ SMS manual, section 10.8.2.

¹⁹² Email from TOTE director of ship management-commercial.

1 sailing as possible” (OMV 3.4.1). NTSB investigators received records of completed indoctrinations up
2 to May 19, 2015, but records for the Polish riding gang could not be obtained because they were kept on
3 the vessel.¹⁹³

4 The SMS manual (OMV 3.2.1.1, “Officer Turnover Notes”) stated that “all licensed officers shall
5 leave a written turnover report for their relief when departing the vessel” and a “signed copy of the
6 turnover notes shall be given to the Master or Chief Engineer for review and retention, prior to payoff.”
7 Off-duty crewmembers stated in interviews that they submitted turnover notes after each rotation. The
8 operating company provided turnover notes from the chief engineer, submitted on August 26, 2014,
9 August 11, 2015, and August 18, 2015.¹⁹⁴

10 According to the SMS manual (OMV 12.6.7.1), evaluations of the captains and chief engineers
11 were to be initiated by the marine crewing department in September of each year. In addition, a completed
12 original evaluation was required to be forwarded to the personnel department for entry into the individual’s
13 personal file.¹⁹⁵ Investigators requested evaluations of the chief engineer that had been completed by the
14 company. One evaluation of the chief engineer was provided, but it was not complete. Several shipboard
15 evaluations were received.¹⁹⁶

¹⁹³ Cadet onboard training indoctrination logs.

¹⁹⁴ Chief engineer turnover notes, chief engineer interview, port engineer interview.

¹⁹⁵ OMV 12.6.7.1

¹⁹⁶ Crew personnel records.

1 An internal audit required by the ISM Code was held on March 6, 2014, after *El Faro*'s layup in
2 Baltimore. No corrective action requests or nonconformities were issued, but the audit included six
3 observations:

- 4 • A master's review needed to be done before the ABS external audit.
- 5 • The semiannual audit of the oily water separator and the annual vessel inspection by the
6 port engineer were due.
- 7 • The chief engineer had inserted all of the updates and changes in the ISM system at the time
8 of the audit.
- 9 • The vessel antenna diagram needed updating.
- 10 • Several of the container walkway gratings on the main deck needed repair.
- 11 • The oil record book and related information binder were missing an update. TOTE was to
12 provide.¹⁹⁷

13 An ISM internal audit was conducted on March 3, 2015, by TOTE's designated person ashore.
14 The audit yielded no corrective action requests or nonconformities, but it included four observations:

- 15 • Recent copy of OPSMEMOS and other communications from the office were not received
16 on *El Faro* due to an incorrect email address.
- 17 • Ship-specific critical equipment list was required to be put in place.
- 18 • Possibility of an online MSDS [material safety data sheet] library and management contract
19 was discussed.

¹⁹⁷ ISM internal audit report, March 6, 2014.

- Previous corrective action reports lacked verification due to *El Faro*'s layup status.¹⁹⁸

10. Postaccident NTSB Actions

10.1. Analysis of Fuel Oil Samples

After the accident, NTSB investigators contacted the supplier and obtained fuel oil samples from *El Faro*'s last three bunkering operations before the accident voyage (on September 8, September 14, and September 21, 2015). The samples were sent for testing to an independent facility, Core Laboratories, in Deer Park, Texas. The fuel was tested for flash point, kinematic viscosity, sediment by extraction, and water. The fuel was found to be within ASTM specifications. The table below shows results and standards, as reported by Core Laboratories:

Sample Date	Flash Point (° F) Min 140	Kinematic Viscosity (cSt @ 100° C) Min 15, Max 50	Sediment by Extraction (Wt%) Max 0.5	Water (LV%) Max 1	Water (Wt%) Max 2
9/8/2015	196	38.45	0.02	0.05	0.07
9/14/2015	196	38.45	0.01	0.05	0.06
9/21/2015	194	36.57	0.01	0.10	0.11

cSt = centistokes. Wt% = weight percent. LV% = liquid volume percent.

10.2. Voyage Data Recorder Search and Recovery

Shortly after the sinking, the NTSB contracted with the Navy to locate the *El Faro* wreckage. The Navy ship *Apache* departed Little Creek, Virginia, on October 19, 2015, fitted with underwater detection

¹⁹⁸ ISM internal audit report, March 3, 2015.

1 equipment. The ship's sonar located the *El Faro* hull on October 31, at a depth of about 15,400 feet. A
2 remotely operated vehicle (ROV) confirmed the finding on November 1.

3 Video from the ROV documented that the navigation bridge and the deck below it had separated
4 from the hull. The top of the engine room casing was open to the sea, all containers had fallen off the
5 cargo areas, and the ship's mast and voyage data recorder (VDR) were missing from the wreckage area.
6 The search was completed on November 15.

7 In April 2016, the National Science Foundation and the Woods Hole Oceanographic Institution
8 jointly sent the research vessel *Atlantis* to the wreckage area to search for *El Faro*'s VDR. *Atlantis* arrived
9 on scene on April 22 and deployed an autonomous underwater vehicle (*Sentry*) to comb the debris field.
10 *Sentry* located the VDR capsule on April 25, but the investigative team determined that it could not be
11 recovered due to its proximity to the mast and other obstructions.

12 *Sentry* surveyed the wreckage of the hull with a high-definition camera. Mooring lines could be
13 seen rising from the hull, including one from the stern that showed signs of having parted.

14 Ten months after the accident, in August 2016, a third mission was launched, aimed at recovering
15 *El Faro*'s VDR. The Navy ship *Apache* departed Little Creek on August 5 and arrived at the accident site
16 on August 8. At 1950 that evening, an ROV retrieved the VDR capsule from a depth of 15,410 feet. The
17 VDR was submerged in a bath of distilled water while the *Apache* traveled to Mayport, Florida. After the
18 ship reached port on August 12, the VDR capsule was transported to NTSB headquarters in Washington,
19 DC, where it was opened by recorder specialists in the presence of the manufacturer's representatives.
20 Over 26 hours of parametric data and audio files were accessed from the VDR's memory module.