

1 National Transportation Safety Board

2
3 Office of Marine Safety
4 Washington, D.C. 20594
5
6
7

8 Group Chairman's Factual Report
9
10
11
12

13 **Engineering Group**
14
15
16
17
18

19 *Andrew J. Barberi*

20 DCA-10-MM-017
21

22 ~~March 1, 2012~~ March 1, 2012
23

24 Brian Curtis

1 **Table of Contents**

2 1. Accident Information..... 3

3 2. Engineering Group..... 3

4 3. Summary..... 3

5 4. Details of Investigation 4

6 4.1. Launch And On-Scene Investigation..... 4

7 4.2. Events Prior to Departure..... 4

8 4.3. Engineering Accident Narrative..... 5

9 4.4. Events Post-Accident 7

10 4.5. Post-accident testing 9

11 4.6. Crew Information 14

12 4.7. Vessels Description..... 16

13 4.8. Damage..... 25

14 4.8.1. *Andrew J. Barberi*..... 25

15 4.8.2. *Terminal*..... 28

16 4.9. Other information 28

17

18

19 Figures

20 Figure 1- St. George Staten Island Ferry slip..... 7

21 Figure 2- Andrew J. Barberi cycloidal propulsion unit controls..... 21

22 Figure 3- Engine Control Room propulsion control station 22

23 Figure 4- Wheelhouse propulsion control station 23

24 Figure 5 – Propulsion system control panel 24

25 Figure 6- Damage to vessel's port side..... 27

26 Figure 7- Damage to vessel's starboard side..... 28

27

28

1 **1. ACCIDENT INFORMATION**

Vessels:	Andrew J. Barberi
Accident Number:	DCA-10-MM-017
Date:	5/8/2010
Time:	09:18:33 Eastern daylight time
Location:	New York City Staten Island Ferry Service
Complement:	18 crew, 244 passengers, 2 NYC police officers, 2 concessionaires- 266 on board

2

3 **2. ENGINEERING GROUP**

Chairman	Brian Curtis Office of Marine Safety Washington, DC 20594
Member- NYC DOT Staten Island Ferry	Bobby Scamell Deputy Director of Maintenance Staten Island, New York
Member – U.S. Coast Guard	Roger Mulford Marine Inspector Sector New York Staten Island, New York
Member - Voith Turbo, Inc.	Lee Erdman Marine Systems Product Manager York, Pennsylvania

4

5 **3. SUMMARY**

6 On Saturday, May 8, 2010, at 0902 local time, the passenger ferry Andrew J. Barberi departed Slip #1
7 at Whitehall Ferry Terminal, New York, with 18 crewmembers, 2 NY Police Officers, 2 concessionaires,
8 and 244 passengers for its regularly scheduled 0900 voyage to St. George's Ferry Terminal, Staten
9 Island, New York, on an established route. At the time, there was an ebb tide and the weather was
10 partly cloudy, with light variable winds and good visibility. At 09:18:33, the vessel allided with the
11 boarding apron and transition bridge on Slip #5 of St. George's Ferry Terminal. 48 people received
12 minor injuries, and both the vessel and the terminal sustained damage.

13

4. DETAILS OF INVESTIGATION

4.1. Launch And On-Scene Investigation.

The Safety Board learned of the accident from the NYC Office of Emergency Management on the afternoon of May 8th. An NTSB Board Member, his assistant, a public affairs officer, and a team of 5 investigators launched from Safety Board headquarters and arrived on scene later that same day. The investigation was led by the Safety Board; the parties to the investigation included the NYC Staten Island Ferry Service, the U.S. Coast Guard, and Voith Turbo, Inc. The on-scene portion of the investigation was completed on May 15th. Follow-on interviews of Ferry Service personnel were held through June 30, 2010.

4.2. Events Prior to Departure

The chief engineer boarded the vessel, which was docked at the Staten Island St. George terminal's slip 3, about 0330 the morning of the accident. He began his normal routine, including starting the ship's service generator, checking the previous day's logbook for any items of concern, and warming the vessel's main engines prior to startup.¹ The engine control room (ECR) contains the Safety Management System (SMS) startup sequence checklists for crewmembers to follow in starting the plant and engines each day.² About 0400 the marine engineer, the only other licensed engineering officer onboard, arrived in the engine room to assist the chief engineer in preparing the plant for startup. Shortly after, the engine room's 3 other crewmembers arrived, made rounds of the plant, and prepared to get underway. A steering and propulsion verification for both of the vessel's end propulsion units was performed one day earlier prior to getting underway³, as was customary for crews to do on the first day of the watch cycle. That verification was done in conjunction with wheelhouse personnel. No propulsion or steering problems were identified.

¹ DeFonce interview, page 11

² Spadarro, page 5

³ 20- AJB Engine Log Book April 1 to May 8.pdf

1 Prior to getting underway that morning, the vessel's crew conducted a fire and boat drill. The
2 engines were started without incident, the engine room was prepared to depart the dock, and
3 propulsion and main engine speed control were transferred to the wheelhouse at about 0605.⁴

4 4.3. Engineering Accident Narrative

5 The Barberi loaded its passengers, and got underway for its first trip of the day from slip 3 about
6 0630. The first 2 ½ trips between the Staten Island St. George terminal and the Whitehall
7 terminal in Manhattan were uneventful, with all engineering systems and operations normal.
8 The oilers and the marine engineer made routine rounds of the plant and its associated
9 equipment, with the chief engineer in the ECR monitoring the plant and propulsion equipment.
10 The oilers would each make a round every 2 hours of the entire plant, including both end
11 propulsion units.⁵ While making rounds, the oilers indicated they would carry handheld radios
12 so that they could communicate with the ECR from outside the space.⁶ The marine engineer
13 and one of the oilers had completed a round of the propulsion end units just prior to the allision,
14 and noted no operational or condition abnormalities in the plant's operation or either propulsion
15 end drive unit.

16 The Barberi departed Manhattan for the 5-mile, 22-minute return leg of its third roundtrip of the
17 day at about 0900. As they made their approach to the Staten Island terminal, the chief
18 engineer, the marine engineer, and 2 of the 3 watch oilers on watch were in the ECR. The
19 ECR received a call from the wheelhouse as the Barberi passed the harbor's "KV buoy" located
20 about 1000 yards from the slip. This call from the wheelhouse was performed as a matter of
21 routine to notify the engine room personnel to, according to the chief engineer, "standby for
22 docking".

⁴ 20- AJB Engine Log Book April 1 to May 8.pdf

⁵ Kloke interview, page 7

⁶ Kloke, page 16

1 The Barberi was equipped with closed circuit television (CCTV), including the ECR. Because of
2 this feature, the engineering staff could view the progress as the vessel made its approach to
3 the dock. Shortly after passing the KV buoy, although no alarms had sounded, the chief
4 engineer detected a noise related to the engine load that “didn’t sound normal”⁷ in comparison
5 to the normal cadence and rhythm of the engines when approaching the St. George terminal.
6 To this point, the chief stated that it had been a “normal approach” in terms of engine speed and
7 pitch.⁸ He walked toward the Human-Machine Interface (HMI) monitor, which monitors and
8 tracks the engines’ governors load and parameters, located near the engine control panel where
9 the engine and propulsion parameters were displayed. The CCTV screen was also located
10 near this same control panel. As he began to survey the engine and propulsion displays, one of
11 the oilers on a settee situated in front of the panel alerted the chief engineer to the CCTV
12 screen. The oiler noticed that the Barberi’s approach speed seemed faster than normal, and
13 that the vessel was quickly nearing the slip.

14 In the brief moment he had to observe the CCTV, the chief engineer could see that the vessel
15 had already entered the slip, and he could see the rack⁹ and bridge¹⁰ (refer to fig. 1) ahead of
16 them, and he knew they were “going to hit ... and hit hard”. The chief engineer looked at the
17 screen and, realizing a hard strike was imminent, told all those in the engine control room to
18 brace themselves. The chief engineer told investigators that the impact consisted of 2 distinct
19 impacts- the first with a lateral movement component, and then a final hard strike, knocking him
20 off of his feet to the control room’s deck.¹¹


⁷ DeFonce, page 42

⁸ DeFonce, page 41

⁹ The wooden structure which assists in guiding the ferry into its slip

¹⁰ The adjustable structure to which the vessel’s embarkation deck mates to allow passengers to offload to the terminal

¹¹ DeFonce, 15



1

2 **Figure 1- St. George Staten Island Ferry slip**3 4.4. Events Post-Accident

4 Immediately following the impact, and having made sure the crew was safe and without
5 injury, the chief engineer noticed the #3 and #4 engines had stopped for unknown reasons.
6 These engines provided rotation power to the Staten Island propulsion drive unit, the end
7 towards the dock. The New York end propulsion unit engines, #1 and #2, were still operating
8 properly. He quickly sent his crew to go out and get those engines restarted to restore
9 propulsion capability to that end unit. After initially being unable to restart the engines, the chief
10 engineer called the wheelhouse to inform them that the engineering crew were not injured, as
11 well as of their inability to get the 2 engines refired, and that he was taking control of the
12 engines back to the ECR. Once taking over control, the engineering crew was able to quickly
13 refire the 2 engines, and the chief once again called the wheelhouse, and returned the engine

1 speed control back to them.¹² The diesel-driven generator supplying electrical power for lights
2 and all onboard equipment never stopped or failed to supply electrical power to all the vessel's
3 operational and lighting circuits throughout the event.

4 Having restarted the 2 stalled engines, the chief engineer next turned his attention to
5 assessing vessel damage from having struck the dock. He tasked one of the 3 oilers to check
6 the engine room bilge levels, another to go about the vessel, sounding all tanks, and report back
7 with those sounds, and the third oiler to go about the vessel and check for any breaches and/or
8 seawater entry. He had his marine engineer, after having restarted the 2 engines, maintain
9 checks on the plant in general. The only damage reported back to the engineers was that in the
10 forward propulsion space, with no hull breaches below the waterline.

11 At that point, a Staten Island Ferry employee that was employed as a chief engineer on this
12 same class vessel, and happened to be riding the ferry, came to the ECR, offering to relieve the
13 chief engineer, allowing him to do his own assessment about the vessel. At about this same
14 time shoreside emergency personnel began arriving in the engine room.¹³

15 The chief engineer first went to both ends to assess any damages, and identified the hull and
16 deck above had been breached in the Staten Island end propulsion unit space. By this time,
17 there were many of SIF's management team, as well as shoreside emergency response
18 personnel on the vessel.

19 The chief continued his walk about the vessel by visiting the wheelhouses. When he arrived in
20 the Staten Island wheelhouse, the wheelhouse which had been controlling the vessel and
21 propulsion systems at the time of the allision, he checked the forward/aft thrust control levers for
22 both end propulsion units. The operator command levers were positioned in neutral, or
23 effectively at zero thrust. The chief engineer then looked at the meters indicating the actual

¹² Defonce interview, pages 16-17

¹³ DeFonce interview, page 18

1 applied thrust at the time for both end units. He noticed that the Staten Island end propulsion
2 unit was at zero ahead pitch, but the New York end propulsion unit meter was still indicating it
3 was thrusting 50% ahead. The #1 and #2 main engines were still running at this time. To verify
4 whether or not the meter was reading correctly, he then walked down to the New York end,
5 looked over the vessel's stern, and could see that the New York end propulsion unit was in fact
6 still thrusting ahead as evidenced by the water it was pushing, even though the wheelhouse
7 command lever was positioned at zero and calling for no thrust. At this time, now nearly noon,
8 the Deputy Director of Maintenance came aboard, met the chief, and was told of the chief's
9 findings. The deputy then went to the engine room, called the wheelhouse, and transferred the
10 ship's propulsion back to ECR control, and successfully brought both end thrust components to
11 zero.

12 The crew, under the supervision of Coast Guard inspectors, moved the *Andrew J. Barberi* to a
13 maintenance slip after the passengers had disembarked and had insured the vessel wasn't
14 taking on any water from hull damage. The propulsion control remained in engine room control,
15 and only the New York end propulsion unit was used to back it from the slip. Once out of the
16 slip, the propulsion was secured, and tugs were used to move and secure the Barberi to the
17 maintenance pier. While being controlled by the engine room station, the NY end propulsion
18 unit performed and responded without any problems being observed.¹⁴

19 At the maintenance pier, the *Andrew J. Barberi* crew and Coast Guard inspectors conducted a
20 dockside operational check of the propulsion units, confirming that the New York-end propulsion
21 unit was not responding properly to pilothouse commands.

22
23 4.5. Post-accident testing

¹⁴ Scamell 5-10-10 interview, page 13

1 4.5.1. Onboard post-Accident testing of propulsion system

2 On May 10, NTSB investigators—with assistance from Voith Turbo, the NYC DOT Ferry
3 Division, the Coast Guard, and a technical service representative familiar with the configuration
4 of the propulsion control system (the engineering group)—tested the two pilothouses' ability to
5 control the pitch of the vessel's propeller blades. These tests were conducted without running the
6 engines and without producing actual thrust. Instead, the engineering group used the propulsion
7 units' electric standby oil pumps to drive the hydraulic controls and change the propeller pitch.
8 From the Staten Island-end pilothouse, the engineering group commanded full forward pitch of
9 both end propulsion units (which, if the engines were running, would create full ahead thrust).
10 Both propulsion units responded properly by positioning the pitch of the propeller blades at 75
11 percent ahead thrust, the maximum attainable percentage while powering the system with the
12 electric standby pumps. The engineering group verified the blade pitch on the propulsion units
13 and then compared it to the pitch response shown on the propeller pitch indicators in the
14 pilothouse; doing so confirmed that the propeller pitch indicators were accurate. The engineering
15 group then commanded both propulsion units to return to zero pitch position (no ahead or astern
16 thrust). The Staten Island-end unit responded properly; however, the New York-end unit
17 remained stuck at 75 percent ahead thrust. The engineering group then transferred control of
18 both propulsion units to the ECR, and when the command for zero pitch was given from there,
19 the propeller blades on both of the propulsion units returned to zero pitch as commanded.

20 The engineering group was thus able to replicate and confirm the New York-end unit's "sticking"
21 problem: After ahead thrust was applied and the control levers brought to zero, the New York-
22 end propulsion unit failed to return to zero pitch. This same anomaly existed when tested from
23 both the Staten Island- and New York-end pilothouses. When ahead/astern thrust was
24 commanded from the ECR, the New York-end propulsion unit responded normally.

1 The 24 volt direct current (dc) electrical signals from each of the wheelhouses was checked for
2 proper continuity and voltage, and found to be in good order between the wheelhouse control
3 levers and the terminations at the propulsion unit control panels.

4 The engineering group then proceeded to focus their efforts on the NY end propulsion control
5 panel. The purpose of the panel is to transform the bridge's electrical signal to a hydraulic oil flow
6 output using electro-hydraulic solenoid valves to control the hydraulic circuit flow. The control
7 panel is pictured in figure 5 in section "4.7.5 Propulsion" of this report with an explanation of the
8 control panel's operation. The panel contains 2 electro-hydraulic solenoid valves, the one
9 situated to the left as you face the panel which controlled the forward/astern thrust component,
10 and one on the right side of the panel to control the port and starboard thrust component. The
11 incoming electrical signal from both wheelhouses to both solenoid valve connections was tested,
12 and found to be proper.

13 Seeing that the wheelhouse signals were being satisfactorily transmitted, and having previously
14 confirmed that the propulsion unit itself was responding properly to command signals from the
15 engine room control station, it was decided to remove the entire NY end propulsion control panel
16 with its oil filters, and return it to the NTSB materials laboratory at headquarters for further
17 examination. At the time of the accident, the right oil filter was online and in service. It was
18 further determined from crew and engineering staff interviews and a review of maintenance
19 records that no evidence existed of the left filter ever having been in service, or the cartridge in
20 the right side filter ever having been changed.

21
22 Once the operational testing of the equipment in service at the time of the accident was
23 completed, both end propulsion control panels were removed and replaced with entire new
24 control panels. On May 13th, once the replacement of the control panels was complete, the

1 engineering group tested both end propulsion units for wheelhouse command response, and
2 both ends performed satisfactorily. The other vessel in the Barberi class, the *Samuel I.*
3 *Newhouse*, had already had its propulsion control panels replaced during its previous shipyard.¹⁵

4 Following the operational testing, the engineering group took oil samples from various points in
5 the NY end propulsion unit for further evaluation as well, in the event that contaminated oil may
6 have been at fault for the improper operation of the unit. Samples taken were:

- 7 - A clean sample of unused Shell Omala 150, the same as used in the control and operation of
- 8 the NY end propulsion unit.
- 9 - A sample from the NY end propulsion drive sump, which supplies oil to the control panel
- 10 through its oil filters
- 11 - A sample from each of the 2 oil filters cartridges on the control panel.

12 The samples were sent out for independent lab testing. The sample results were scored on a 0
13 to 4 scale, 0-1 being normal, and 4 being critical. The results of the samples from the NY end
14 sump and the right side control panel oil filter, the 2 system components that were in-service at
15 the time of the accident, both returned with registered results of a score of 1, or "normal". For
16 further detail of the independent lab reports and testing results, see "Material Lab Factual Report
17 number 11-063".

18 4.5.2. History of Barberi class propulsion control board solenoid valves

19 The maintenance history for the Barberi's propulsion system was downloaded and reviewed for
20 the period between July 30, 2007 and the accident, and there was no record found of
21 maintenance, either preventive or reactive, had been performed on the propulsion control
22 solenoid valves during that period.

23 The engine room logbooks for the period April 1, 2009 through the accident date were also
24 reviewed, and no propulsion-related anomalies or failures were discovered.

¹⁵ Scamell 5-10-10 interview, page 4, line 22

1 In an interview with the senior port engineer for the Staten Island Ferries, he stated that the
2 propulsion control boards and solenoid valves were currently being replaced on the Newhouse
3 and Barberi to upgrade the systems, but not because they had encountered problems with the
4 system. A review of maintenance records and engine logbooks by investigators confirmed that
5 no mention existed of propulsion control problems that would have initiated plans to replace the
6 control boards and solenoids. In the Deputy Director of Maintenance's interview, who had held
7 that position for approximately 6 months at the time of the accident, he stated that he had never
8 seen a propulsion control solenoid valve having been replaced in his 15 years with the company.

9 Investigators spoke with the solenoid valve manufacturer's product management specialist
10 familiar with the solenoid valve, who indicated that this type solenoid is very popular, and used
11 in thousands of applications. He further indicated that the design limit for cycles of this valve is
12 20 million.

13 4.5.3. Materials Lab testing of propulsion control components

14 The NTSB Materials Lab work included: 1) sending the aforementioned oil samples out for
15 independent testing, and; 2) conducting a physical examination of the NY end propulsion unit
16 pitch control panel. For discussion and details of the lab's examination results, refer to "Material
17 Lab Factual Report number 11-063". The following is a bulleted summary of the findings from
18 the lab's examination of the control board's components:

19 -The control board contained 2 electro-hydraulic solenoid control valves to alter the
20 propulsion units propeller blade pitch- 1 solenoid valve to control the ahead/astern
21 propulsion blade pitch component, and 1 to control the port and starboard steering control
22 component.

23 -Both solenoid valves were similar in operational design. The valves shuttled between
24 three positions but normally resided in a neutral state in which no oil flowed through the
25 system. The motion of each valve was controlled by two electrically-actuated solenoids,
26 one on each end of the valve. Each solenoid contained an internal bronze ring.

27 -Both of these solenoid valves were similar in operational design, both containing 2 internal
28 bronze rings, one at each end, to facilitate the solenoid valves' operation

1 -. The bronze rings inside each propulsion valve solenoid were designed with six narrow tabs evenly
2 spaced around the ring. The bronze rings inside each steering valve solenoid were designed with three
3 wide tabs evenly spaced around the ring.

4
5 -The 2 bronze rings in the propulsion solenoid valve were both found broken, with the ring
6 debris located within the valve's body

7 -The 2 bronze rings in the steering valve were found fully intact

8 -The right oil filter (online at the time of the accident) was examined and found to contain
9 no perforations to damage to the inner cartridge through which the oil passes in the
10 hydraulic circuit.

11
12 4.6. Crew Information

13 4.6.1. Engineering crew makeup

14 The engineering crew consisted of 5 people: one licensed chief engineer, one licensed assistant
15 marine engineer, and 3 unlicensed oilers. 2 oilers had worked for the ferry service since 2005,
16 and the third oiler had been with them since 2007. The Barberi's Certificate of Inspection (COI)
17 called for the engineering complement to be at a minimum one chief engineer, one other
18 licensed engineer, and 2 oilers.

19 4.6.2. Chief Engineer

20 The chief engineer was 43 years old, and a 1988 graduate of the United States Merchant Marine
21 Academy in Kings Point, New York. Since his graduation, he had worked both as an
22 engineering officer on vessels for various companies, as well as having worked 10 years from
23 1996 to 2006 in a shoreside fleet management position for Marine Transport Lines out of
24 Weehawken, New Jersey.

25 He held a current United States Coast Guard license as a Chief Engineer of motor vessels
26 (diesel), unlimited horsepower, with a restriction to near coastal waters (out to 200 miles). He
27 also held a United States Coast Guard license as a First Engineer of motor vessels, unlimited
28 horsepower, and as a Third Engineer of steam vessels, unlimited horsepower.

1 He began working for the Staten Island Ferry service in February of 2006, and had worked on
2 most of its vessels as engineer. At the time of the accident, he had been assigned as a
3 permanent chief engineer to the Barberi for about 3 months. His schedule consisted of working
4 Friday through Mondays. Friday's and Sunday's his hours were 0700 until 1500. On Saturday,
5 he would work from 0630 until 1430, and Monday's he would work from 1400 to 0200.

6 He provided the following information when asked about his 72 hour sleep/work cycle:

7 Wed. (May 5)- 1500-0300, working
8 Thur. (May 6)- 0400-0900, sleep
9 0900-2000, home off work
10 2000, sleep
11 Fri. (May 7)- 0315, awake
12 0500-1530, working
13 1700-1930, home off work
14 1930, sleep
15 Sat. (May 8)- 0315, awake, to work
16
17

18 4.6.3. Marine Engineer

19 The marine engineer, the chief's assistant was 61 years old, and held a US Coast Guard third
20 assistant engineer's unlimited horsepower motor license. He had worked in the marine industry
21 nearly his entire life, including working on US Navy destroyers during the Vietnam war.

22 He started working with the Staten Island Ferry service in 1979 as an oiler, and began as an
23 engineer on the vessels in 1985, and had worked on most of the service's vessels.

24 He worked the same schedule as the chief engineer, that being Friday through Monday.

25 He indicated he had a lot of experience working on the Barberi class of vessels, having worked
26 on them since they came out in 1981. When asked if he considered the propulsion system on
27 the Barberi as robust, he replied: "bulletproof".¹⁶

¹⁶ Hild interview, page 31

1 He provided the following information when asked about his 72 hour sleep/work cycle:

2 Wed. (May 5)- 1100-2200, at home
3 2200- to sleep
4 Thur. (May 6)- 0700, awake
5 0700-2230, home off work
6 2230, to sleep
7 Fri. (May 7)- 0300, awake
8 0500-1730, working
9 1730-2000, home off work
10 2030, sleep
11 Sat. (May 8)- 0400, awake, to work
12

13 4.7. Vessels Description

14 4.7.1. General

15 At the time of the accident, the NYCDOT Staten Island Ferry Service fleet was comprised of a
16 total of 9 vessels in 4 different classes of ferryboats: the Kennedy, Molinari, Barberi, and
17 Austen classes. The vessel involved in this accident, the Andrew J. Barberi, is a member of the
18 Barberi class of vessel.¹⁷

19 Equitable Shipyards, Inc., in New Orleans, Louisiana, built the Andrew J. Barberi in 1981. It
20 was the first vessel constructed in its class. Its design capacity is 6,000 passengers. It is a
21 welded steel, double-ended vessel. It has a displacement of 2721 long tons, is 310 feet in
22 length, 70 feet in breadth, and has a design draft of 12' 6".

23

24 4.7.2. Hull

25 The hull is all welded construction, transversely framed on 30-inch centers, and subdivided by
26 watertight bulkheads to provide end ballast tanks, voids, propulsion gear rooms, and machinery
27 spaces. The hull is symmetrical about the midships transverse section; frame numbers are

¹⁷ Scamell 5-10-10 interview, page 21

1 designated such that Frame 0 is located at midships, and extending out to frame 58 in either
2 direction.

3 There are 10 watertight compartments. The engine room, containing the bulk of all main and
4 auxiliary machinery, is located amidships between frame 12 NY end (NYE) and frame 12 of the
5 Staten Island end (SIE). The 4 main engines and auxiliary equipment are located in this space.
6 Also installed in this same space are the engine control room (ECR), auxiliary boilers, and the
7 vessel's electrical generators.

8 Next to these spaces are voids between frames 12 and 20 on both ends. On the NYE, this void
9 contains the crew locker rooms, sewage treatment plant, and CO2 bottle room. On the SIE, this
10 void contains diesel oil storage and service tanks. At both ends between frames 20 and 31 are
11 voids as well. In the NYE this void is a potable water tank. Between frames 31 and 40, there are
12 void spaces as well at both ends.

13 The next compartment on both ends, from frames 39 to 52, form the propulsion gear spaces.
14 These spaces contain the pumps, controls, and reduction gears to drive the cycloidal propellers.

15 The spaces from frames 52 to both ends form ballast tanks; below the ballast tanks at each
16 end there is a fixed, plated steel skeg which protects the cycloidal propeller from impacts with
17 debris as well as improves directional stability and provides structural support for when the
18 vessel is drydocked.

19 Between frames 12 and 40 at each end is a shaft tunnel, containing 2 propulsion line shafts and
20 12 line shaft bearings.

21

22 4.7.3. Superstructure

1 There are 3 decks for passenger use and one open deck restricted to use by the crew.

2 Embarkation is at 2 levels, the main deck and upper embarkation level. Ramps are provided
3 between bridge deck and upper embarkation levels, and stairs are provided between the upper
4 embarkation level and saloon deck, and between the saloon deck and main deck.

5 The enclosed portion of the main deck seats 1630 passengers and has an open boarding area
6 at each end protected by the upper embarkation level above. Seating is arranged with
7 longitudinal seats on centerline and on the outboard sides, with the remaining space being
8 occupied by groupings of transverse seats. Four large hinged doors open the cabin to the
9 boarding space at each end. Enclosed stairwells forward and aft lead up to the saloon deck.

10 The saloon deck is completely enclosed and has seating accommodations for 1258 passengers.
11 Seating is arranged similar to the main deck. Enclosed stairs lead from the saloon deck to the
12 upper embarkation levels; ramps lead from the upper embarkation levels to the bridge deck.

13 The bridge deck is divided by 2 longitudinal bulkheads to provide a convertible promenade area
14 to the port and starboard of the enclosed center. This deck has longitudinal seating on the
15 centerline and on the outboard side of the interior longitudinal bulkheads. The bridge deck
16 seats 784 passengers.

17 The wheelhouses and stack are located on the Hurricane deck. The stacks provide space for
18 the engine casing and passenger space ventilation fans.

19 4.7.4. Vessel particulars

Vessel Name	Andrew J. Barberi
Owner/Operator	NYC DOT Staten Island Ferry Service
Port of Registry	New York City
Flag	US
Type	Ferry vessel
Built	1981
Official number	629314
Classification society	American Bureau of Shipping (ABS)

Construction	Steel
Draft	12' 6"
Length	310'
Beam	70'
Gross tonnage	3335
Engine power and type	4- General Motors EMD 16-645E6 (1750 HP each)
Persons on board	266
Injuries/fatalities	None
Damage cost	Vessel- \$168,625 Terminal- \$13,613

1

2 4.7.5. Propulsion

3 The Andrew J. Barberi is equipped with 2 cycloidal propeller systems, one at each end, rated
4 at 3500 horsepower each. The cycloidal propulsion units installed on the Barberi class are the
5 only 4 units of this size. The propellers provide virtually equal thrust in any direction. For this
6 reason, the cycloidal propellers are used to accomplish both propulsion and steering of the
7 vessel. Cycloidal propulsion is a unique system allowing quick and precise direction and
8 speed control of the vessel. Fig. 2 is a photo of the propeller on the Andrew J. Barberi. The
9 vessel's control system is such that the magnitude and direction of thrust of each propeller is
10 separately and manually controlled. Each of the 2 wheelhouses can control both propellers.
11 An automatic control system maintains the speed of the main engines at approximately 750
12 RPM when the vessel is underway and prevents any of the manual commands to the cycloidal
13 propellers from overloading the engines. The propellers themselves turn at approximately 55-
14 60 RPM when the engines are running at full speed, as the reduction ratio of the gearing
15 between the main engines and the propellers is 13.7:1.

16 Since the vessels came into service in 1981, maintenance and inspection of the Barberi class
17 propulsion units and related control system components has been coordinated by NYCDOT
18 Ferry Division personnel under the supervision of vendors. This includes both shipyard
19 periods and periodic maintenance performed outside of shipyard periods. During all the

1 shipyard periods for the Barberi class vessels, a manufacturer's representative was brought in
2 to conduct inspections and maintenance of the cycloidal propulsion units.

3 During the 2009 shipyard period, NYCDOT Ferry Service contracted for Governor Control
4 Systems to check the propulsion units control systems prior to the vessel going back into
5 service. The report from that service visit indicated that the sea trial was completed with no
6 problems and the system operated as designed.

7 Two main engines are coupled to each end's cycloidal propeller through a hydraulic coupling
8 and a length of line shafting. Two main engines drive the NY end propeller, while the other
9 two main engines drive the Staten Island end propeller. Draining a hydraulic coupling permits
10 declutching its associated engine thereby driving its associated cycloidal propeller using a
11 single engine when required. The propellers each have an right angle reduction gear, as the
12 axis of the propeller rotor is vertical.

1



2

3 **Figure 2- Andrew J. Barberi cycloidal propulsion unit controls**

4 Both forward and aft propulsion systems can be controlled from any of 3 stations- the engine
5 control room, or either of the 2 wheelhouses. To gain wheelhouse control, it must be
6 transferred from the engine control room to either of the 2 wheelhouses. From this point on,
7 control can be transferred back and forth between the 2 end wheelhouses. To accomplish the
8 transfer of control from one station to the other takes 2 individuals, one in the sending station,
9 and one person in the receiving station. The person in the sending station presses a transfer
10 button. They notify the individual in the receiving station that this task has been accomplished,
11 at which time the person receiving control presses an "accept" button in his station to complete
12 the transfer operation. Figures 3 is a photo of the engine control room propulsion control
13 station, and figure 4 is a photo of a wheelhouse control station located on each bridge.

1

2



3

4

Figure 3- Engine Control Room propulsion control station

1



2

3

Figure 4- Wheelhouse propulsion control station


4 Control of the propulsion propeller pitch is accomplished via a 24 volt direct current electrical signal
5 being transmitted from the controlling wheelhouse control station lever and handwheels to the
6 propulsion unit hydraulic control panel (See figure 5) located in the propulsion end unit.

7 The control panel in figure 5 effects propeller blade pitch by the following method. There is one control
8 panel for each end propulsion unit. Pressurized oil is pumped from the propulsion unit's sump first
9 through the control panel's oil filter. Only one of these oil filters is online at any given time, and a
10 selector valve is used to select the online filter to allow for periodic filter cartridge change of the offline
11 filter. After passing through the filter, the oil is then piped to the electro-hydraulic solenoid valves
12 located over the oil filters on the panel. There are 2 of these solenoid valves on the panel, one to
13 control the ahead propeller blade pitch thrust component, and one to control steering, or side to side

1 component of the resultant blade pitch. The output oil pressure from these 2 solenoid valves working in
2 tandem position the hydraulic control rams to properly pitch the propeller blades to result in the
3 commanded direction of thrust.

4 When in engine room control, this signal from the wheelhouse control station is bypassed, so the
5 engine room control station, through mechanical linkages and hardware, directly positions the hydraulic
6 rams at the end propulsion units in their respective spaces, and subsequently positions the blades for
7 the desired resultant pitch.

8



9

10

Figure 5 – Propulsion system control panel

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23

4.7.6. Main Engines

The 4- 16-cylinder main engines are manufactured by General Motors EMD Electromotive Division. They are rated at 1750 horsepower each. Their maximum rated speed is 800 RPM, however their normal operating speed is 725-750 RPM. They are 2 cycle engines, incorporating roots blowers, started with air motors.

4.8. Damage

4.8.1. *Andrew J. Barberi.*

A representative of the American Bureau of Shipping (ABS) conducted a damage survey on May 9, 2010 following the Barberi's allision with the dock to ascertain damages and necessary repairs to the Barberi.¹⁸

Because the *Andrew J. Barberi* is a non-conventional double-ended vessel symmetrical from midships toward each end of the vessel and the damage occurred at the Staten Island end of the vessel, the following text refers to the Staten Island end and its port and starboard sides in reference to that end of the vessel.

Damage to the vessel was generally sustained symmetrically to the port and starboard sides from the point where it impacted the dock's rack pilings on both sides from frames 48 to the vessel's end. Damage to the port and starboard side, respectively, are shown in Figure 6 and 7. Damage to both the vessel's sides involved the hull being breached in that end's space containing the cycloid propulsion unit. All damage was contained to above the vessel's waterline, and in the confines of the frames of the propulsion space.

The damage to both sides included:

¹⁸ ABS Damage Survey- 5-9-2010

- 1) deformation and tearing to the the port and starboard main deck plating above the propulsion space,
- 2) “ “ “ to the port and starboard bulwark¹⁹ between frames 48 and 54,
- 3) main deck mooring chock on the port side was displaced,
- 4) the watertight bulkhead port and starboard was buckled,
- 5) transverse web frames at frames 51 and 53 were deformed,
- 6) port and starboard rub rails were torn and/or deformed.²⁰

8 The hull breaches port and starboard occurred at the rub rail level.

9 Damage was also identified at the bridge deck level port and starboard of the wheelhouse. This
10 damage resulted from the vessel having struck the retracted ramps that would typically be
11 lowered into position once the vessel was docked to allow passenger disembarkation. On the
12 starboard side, the manhole leading into the battery void below sustained damage. On the port
13 side of the wheelhouse over this same battery void, damage was observed to the manhole
14 cover, as well as a vent tube being broken off, and a natural exhaust trunk broken free from its
15 mount. This damage was essentially considered to be cosmetic in nature.

16 The repairs were completed, the ferry service conducted a sea trial with Coast Guard and
17 American Bureau of Shipping inspectors onboard, and the vessel returned to service on June 23,
18 2010. The cost to repair the Barberi was \$168, 625²¹, according to SIF officials.

19 A local dive company performed an underwater hull survey the day following the allision, and
20 found no anomalies or hull damage below the water’s surface²². A video examination was also
21 performed on the propulsion blading that same day by the propulsion systems manufacturer, and
22 found no damage to either end’s underwater propulsion components.

23

¹⁹ Bulwark is a vertical outside bulkhead above the main deck

²⁰ SIFSteel work repairs- 6-8-10

²¹ Email of damage costs for Staten Island Ferry Service dated 7-19-2011

²² Randive Underwater Survey Report- 5-9-10



1

2 **Figure 6- Damage to vessel's port side**



1
2 **Figure 7- Damage to vessel's starboard side**

3
4 **4.8.2. Terminal**

5 The Staten Island Ferry Service shoreside terminal #5 slip where the allision occurred sustained
6 damage to its steel ladders and walkways. The transition bridge, which the ferry connects to upon
7 its arrival at the slip (figure 1), was pushed forward and displaced upon impact, but sustained no
8 damage. The bridge is designed to absorb impact forces and be displaced in the event of a hard
9 landing such as the allision. In the days following the accident, the bridge was rigged back into
10 place, and ladder and walkway steel damage was repaired. The cost to repair the slip was \$13,613.

11 **4.9. Other information**

12 **4.9.1. Safety Management System (SMS)**

13 The International Maritime Organizations (IMO) requires the implementation of a Safety
14 Management System (SMS) on all vessels engaged in international voyages for those countries

1 that are signatory to the IMO's conventions. Although not required by code, because the Staten
2 Island Ferry service does not engage in international voyages, the SMS was created and
3 instituted at the ferry service as a result of an NTSB recommendation resulting from the 2003
4 Andrew J. Barberi dock allision. The SMS received its full certification, its Document of
5 Compliance, in October of 2005²³.

6 4.9.1.1. Critical Equipment

7 Section 10.3 of the International Safety Management (ISM) Code calls for companies to "identify
8 equipment and technical systems the sudden operational failure of which may results in
9 hazardous situations" on their vessels. Each vessel in the ferry services' fleet had its own
10 individual critical equipment list. The ferry service had in fact, in form 31-B of their SMS, listed all
11 those Barberi systems and equipment pieces, to which they referred to as "critical equipment".²⁴
12 The list of critical equipment included all 4 of the Barberi's main engines, its 2 cycloidal
13 propulsion units (1 at each vessel end), and the controls for the propulsion units. The critical
14 equipment also included other engine room equipment such as fire and bilge pumps, emergency
15 generators, and main engine start air compressors.

16 4.9.1.2. Engineering maintenance procedures

17 Section 10.1 of the ISM Code requires a company to ensure it's equipment is maintained in
18 conformity with the relevant rules and regulations. The ferry service had a system whereby the
19 work performed on each piece of the vessel's engineering equipment was tracked by a
20 preventive maintenance (PM) program. The system had established PM maintenance
21 procedures, called work orders, for each piece of equipment, including the procedure to conduct
22 the maintenance, and the frequency at which the maintenance should be conducted (daily,
23 weekly, monthly, etc.). The company employed "planned maintenance coordinators" to maintain
24 and track its vessel equipment maintenance within its program, and to identify any maintenance

²³ 6-10-10 interview, page 21

²⁴ Appendix A- SMS FORM-31B, Barberi Class Critical Equipment List

1 items that were outstanding or overdue. The system tracked both preventive and corrective
2 maintenance for all the equipment, and was capable of tracking Key Performance Indicators
3 (KPI's) used in measuring and benchmarking performance areas related to the completion of
4 preventive and corrective maintenance work on the vessels.

5 During the onscene investigation, questions arose regarding the frequency of oil filter cartridge
6 changes for the propulsion control panel oil filters. These were duplex filters where one filter was
7 online at any given time, and a selector valve was located on the panel to allow the operator to
8 isolate one filter while maintenance could be performed on the offline filter. Engineering crew
9 and staff were interviewed regarding the maintenance of these filters, and maintenance logs
10 were reviewed, but no evidence could be found to indicate that these filters had ever been
11 changed. Upon further investigation, it was found that no preventive maintenance procedure
12 existed in the maintenance system to account for this maintenance item. However, a review of
13 the manufacturer's control/maintenance instruction manual²⁵ acquired from the Deputy Director
14 of Maintenance's office, recommends the propulsion control panel oil filters be changed weekly
15 while the propeller is operating.

16 4.9.1.3. Engineering casualty scenarios

17 The ferry service' SMS also contained emergency preparedness scenario drills as required by
18 section 8.1 and 8.2 of the ISM Code, calling for companies to identify potential emergency
19 shipboard situations, and establishing drills and exercises to respond to them. The ferry service'
20 SMS included 12 different emergency training scenarios, including one accounting for loss of
21 propulsion and steering, and one addressing a vessel response to collisions and allisions.²⁶
22 Following the allision, the chief engineer sent his engineering personnel out to check for hull
23 damage and breaches, sound all tanks, and report back to him, all in accordance with the
24 company SMS requirements contained in the emergency response to a collision or allision.

²⁵ Control/Maintenance manual, VSP-06.02.03e

²⁶ SMS: "Emergency Procedures Manual" section, section 3.4 and 3.5.

1 4.9.2. Actions taken since accident

2 4.9.2.1. Preventive Maintenance Program modifications

3 During the onscene investigation, it was discovered that no preventive maintenance procedure
4 existed for the periodic changeover and filter cartridge replacement of the propulsion system
5 hydraulic control panel oil filters. Investigators reviewed the manufacturer's equipment
6 instruction manual and were able to identify the recommended weekly change of the control
7 panel oil filters. After identifying the maintenance in the manual, the Staten Island Ferry service
8 Director of Maintenance created a recurring PM work order for both end propulsion units, as
9 well as for the sister vessel *Samuel I. Newhouse*, based on the corresponding with the
10 manufacturer's recommended frequency.²⁷ In March of 2011, having changed and inspected
11 the control panel oil filters on a weekly based since the previous June, the PM work order was
12 altered to change the frequency to once every 3 months due to the clean condition of the filter
13 being changed each week, as well as from reviewing the regularly scheduled oil analysis for the
14 unit sumps. The maintenance history records indicated all oil changes conducted as scheduled
15 on the Barberi form June of 2010 through June of 2011.²⁸

16 NYCDOT did quarterly sample and analyze the cycloidal propulsion sump oil. The oil sample
17 report dated 06-May-2010 indicated the oil condition for the NY end sump as "normal".

18 Whereas the propulsion control panel oil filters were a component part of an SMS-identified
19 piece of "critical equipment", investigators wanted to clarify why the oil filter changes had been
20 overlooked and missing as a regularly schedule PM work order. In speaking to the SIF's senior
21 port engineer, he related that to initially indentify all the PM work order procedures related to
22 each vessel's critical equipment, a library was assembled for each vessel in the fleet containing
23 all of its equipment maintenance manuals for each piece of equipment on board, especially its
24 critical equipment. An outside contractor was then hired to review the manuals, and extract the

²⁷ 69- PM Work orders for Prop control panel oil filter change

²⁸ PM control panel oil change status report for 6-12-2010 through 6-17-2-11

1 manufacturers recommended maintenance items for each piece of equipment from its
2 respective manual, and create a PM work order, which was then entered into the system.
3 Once the missing PM work order for the control panel oil filter change was discovered, the
4 maintenance personnel went back and discovered that the manual in the vessel's library did not
5 have the control panel maintenance section included in it, as the copy investigators previously
6 reviewed from the Deputy Director of Maintenance's office. This section was subsequently
7 added to the vessel's library maintenance manual for the propulsion system on the Barberi.

8 Realizing the potential for improper or missing PM work orders for their vessels' critical
9 equipment, SIF's Director of Engineering, in conjunction with the SIF's senior port engineer,
10 conducted a review of the fleet's vessels critical equipment maintenance procedures in the
11 maintenance tracking system during the summer of 2010. This was accomplished by ferry
12 personnel comparing the maintenance manuals against the existing work orders for their
13 equipment. Their goal going forward is to initiate a periodic maintenance effectiveness review of
14 their PM work orders as compared to the manuals for their equipment designated as critical in
15 their SMS. At the time of this report, the task for the effective review program is written, and SIF
16 is in the process of getting funding and approvals to proceed.²⁹

17 4.9.2.2. Propulsion control upgrades

18 Plans are currently underway to modify the 2 Barberi class vessels' propulsion operator stations
19 from the existing handwheels for steering and levers for ahead/astern speed control to a single
20 joystick control station manufactured by Bosch-Rexroth. This joystick control will allow 360
21 degree directional and 0-100% thrust magnitude control of the vessel from a single lever. Each
22 wheelhouse will have 2 joystick controllers, one to control each end propulsion unit. The engine
23 room controls will also be changed out to the joystick controllers. The project is being done
24 under a contract with the propulsion system manufacturer, Voith Turbo, Inc., with Bosch-

²⁹ SIF Director of Engineer email to engineering group chairman dated 7-29-2011

1 Rexroth as a subcontractor doing the installation of the system. The system will incorporate
2 redundant power supplies, to facilitate automatic failover in the event of failure of either of the
3 online power supplies. The system will also utilize electric screwjack actuators to change
4 propeller blade pitch at the propulsion end units, replacing the hydraulic control panels, thereby
5 totally eliminating the control panel oil filters and electro-hydraulic solenoid valves currently
6 being used. The *Andrew J. Barberi* work has been initiated, and is due to be completed during
7 the vessel's out of service period in 2012. The *Samuel I. Newhouse*, the remaining Barberi
8 class vessel, is scheduled to have the system installed during an out of service period to
9 coincide with its drydocking in 2012.

10 4.9.2.3. Installation of propulsion pitch deviation alarm

11 A review of the wheelhouse CCTV image recorder transcript reveals the details of the operator's
12 actions and the times they occurred just prior to the accident. From the transcript, it was
13 apparent that they were not aware of the NY end propulsion system's improper response to his
14 ahead/astern thrust commands during their approach to slip #5 that morning. Beginning at
15 09:16:11, the operator began introducing reduced throttle commands to slow the vessel on its
16 approach. He gave his first SI end command to reduce forward thrust at 09:16:16. At 09:16:52
17 he began reducing the pitch control to both ends. Between then and the allision, the operator
18 repeatedly reduced thrust commands to both end propellers until 09:17:45, at which time the
19 transcripts states that both ahead/astern propulsion levers were an an astern positionAt
20 09:18:04, shortly before impact, both levers were in the full astern position, and the operator
21 was seen pushing downward (in the astern direction) several times before impact. The allision
22 occurred at 09:18:33.

23 Vessels can be fitted, at installation or retroactively, with what is referred to as a pitch deviation
24 alarm. Its design purpose is to visually and audibly alert the wheelhouse operator when their
25 commanded input to the propulsion units is not resulting in the intended response, such as

1 when the operator commands the ahead propulsion to full ahead, but the propulsion unit fails to
2 properly respond, or does not do so in an acceptable timeframe. Although propeller blade pitch
3 commanded settings and actual propeller blade pitch position indicators are required by
4 regulation on vessels with CPP's³⁰, the regulations do not require an unacceptable difference
5 between them to audibly or visually alert the operator. At the time of the accident, the *Andrew J.*
6 *Barberi* did not have a propulsion pitch deviation alarm in its wheelhouse, nor was one required
7 by regulation for vessels with controllable pitch propeller, or cycloidal propulsion systems. The
8 wheelhouse control stations had analog dial gauges that indicated both command signals
9 initiated by the operator, and the response position of the propellers' blade pitch to his
10 commands, which met applicable regulations³¹, but there was no audible or visual alarm
11 capable of making the operator aware of deviations between his command and the propulsion
12 systems response. In the moments leading up to the accident, the wheelhouse operator
13 commanded the NY end propulsion unit to transition from ahead to astern pitch (or thrust) as he
14 approached the St. George terminal slip, but was unaware that the NY end propulsion unit was
15 not responding to his commands.

16 One feature of the impending upgraded propulsion control system will be a pitch deviation
17 alarm. The time lapse between command and response will be programmable at the operating
18 station.³²

19 The Barberi's propulsion system manufacturer was contacted, and indicated that their new
20 cycloidal propulsion control system installations scheduled for 2012 have included in their
21 control systems a pitch deviation alarm alerting the operator to unacceptable time lapses
22 between the operator's commands and the propeller blade pitch response. The manufacturer,
23 recognizing the potential improvement to the safe operation of vessels with its propulsion

³⁰ 46 CFR 62.35-50

³¹ 33 CFR 164.35(m)

³² Discussion summary with SIF Dep. Dir. of Maintenance- 8-5-11

1 systems, is notifying companies with its propulsion systems installed of the available control
2 systems incorporating propeller pitch deviation alarms.

3 In March of 2008, the NTSB Office of Marine Safety investigated a large fish processing vessel,
4 the *Alaska Ranger*, which sunk in the bering sea about 100 miles west of Dutch Harbor, Alaska.
5 In that accident, the vessel experienced an unexpected loss of control of its controllable pitch
6 propeller (CPP). Prior to sinking, the vessel began to thrust in the astern direction while the
7 operator had commanded a forward direction of thrust. The vessel, with a crew of 47 onboard,
8 was taking on water, and began preparing to abandon ship to its liferafts. The captain had
9 commanded the vessel in the ahead direction, and launched the liferafts, anticipating they would
10 come alongside the vessel at the embarkation locations on the deck once the sea painters had
11 become fully extended due to the forward motion of the vessel. Due to a loss of electrical power
12 and the subsequent change to the astern direction, while waiting for the liferafts to come
13 alongside the crew had to jump overboard and swim to the liferafts as opposed to climbing
14 down a ladder directly into them. The captain was not aware that the CPP had not responded to
15 his command for ahead thrust, and was in fact thrusting astern. The accident resulted in 5
16 deaths.

X

Brian Curtis
Engineering Group Chairman

17