



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

October 21, 2014

AIRWORTHINESS

Group Chairman's Factual Report

DCA13FA148

**Attachment 2 – N169GL Maintenance Records
(28 pages)**

MTW AEROSPACE, Inc.

7050 Hwy 80 West
Montgomery, AL 36108

MATERIAL CERTIFICATION

PURCHASE ORDER #:

PART NUMBER: 114-380041-9

DESCRIPTION: ACTUATOR ASSY - MLG

SERIAL NUMBER: 120A

SHIP DATE: 08/15/2011

The undersigned hereby certifies that the material shipped against the above purchase order is in AS REMOVED condition and was originally manufactured by AIRIGHT or one of their designated licensees. That it was not obtained from any U.S. Government source, was not subjected to fire and was obtained from the stock of AIRIGHT Aircraft Serial No. UE-24, P126377

This is to certify that each part covered by this packing list and invoice were produced by a Manufacturer holding an FAA Approved Production Inspection System issued under FAR 21, Sub. Part F. or by Manufacturer holding an FAA Production Certificate issued under FAR 21, sub. Part O. These parts were made by the prime manufacturer or under licensee agreement with the prime manufacturer.

SOURCE: BEECH 1900D

Serial: UE-24

Registration: N124CJ

Former Operator: COLGAN AIR SERVICES

Part: PART 121

Non-Incident Related

Authorized Signature: _____

NICK SHOUBE

Title: SALES

Great Lakes Aviation, Ltd.

PURCHASE ORDER

R54914

Vendor # --> 100702

Ship To

APPH WICHITA INC
1445 SIERRA DRIVE
WICHITA, KS 67209-2933

TEL: [REDACTED]
FAX: [REDACTED]

GREAT LAKES AVIATION
1022 AIRPORT PARKWAY
CHEYENNE, WYOMING 82001

TEL: [REDACTED]
ATTN: PARTS DEPARTMENT

CRO# 2010032
SHOP# 631010
CUST# 4111984
SHIP# 40070

Buyer: A64
Requested By: LINDA

P.O.DATE	NEEDED BY	SHIP VIA	F.O.B.	TERMS
08/15/11	08/15/11	UPS GND		

L#	QTY	UNIT	PART# / DESCRIPTION	PRICE	EX.PRICE
01	1	EA	114-380041-9 MLG ACTUATOR (AIRIGHT) Ser#: 120A J.C.#: UE-24 G.L.#: DGR INSPECT, TEST AND VERIFY FAULT INDICATED UNLESS SPECIFIED OTHERWISE. PROVIDE A DETAILED TEARDOWN REPORT WITH QUOTE. USE TECHNICAL DATA DRAWING OR BLUEPRINT BEECH-APPH 40600 AS REVISED ALL REPAIRS REQUIRE WRITTEN APPROVAL PRIOR TO ANY WORK BEING PERFORMED. COMPLY WITH ALL APPLICABLE AIRWORTHINESS DIRECTIVES, 8130-3 REQUIRED FOR ALL REPAIRS**ALL TECH DATA MUST APPEAR ON QUOTE** FOR QUESTIONS REGARDING THIS ORDER, PLEASE CONTACT LINDA STUEVE AT [REDACTED] FAX INFORMATION TO [REDACTED], OR E-MAIL IT TO [REDACTED] ALL REPAIR QUOTES MUST BE FAXED TO [REDACTED] OR	0.00	0.00
TOTAL					

40600-8

RECEIVED
AUG 19 2011

Authorized Signature

Great Lakes Aviation, Ltd.

PURCHASE ORDER

R54914

Vendor # --> 100702

APPH WICHITA INC
 1445 SIERRA DRIVE
 WICHITA, KS 67209-2933

 TEL: [REDACTED]
 FAX: [REDACTED]

Ship To

GREAT LAKES AVIATION
 1022 AIRPORT PARKWAY
 CHEYENNE, WYOMING 82001

 TEL: [REDACTED]
 ATTN: PARTS DEPARTMENT

Buyer: A64
 Requested By: LINDA

P.O.DATE	NEEDED BY	SHIP VIA	F.O.B.	TERMS
08/15/11	08/15/11	UPS GND		

L#	QTY	UNIT	PART# / DESCRIPTION	PRICE	EX.PRICE
			EMAILED TO THE FOLLOWING ADDRESS ONLY: [REDACTED] BOUGHT AS REMOVED FROM MTW ON PO# S54891 REMOVED FROM UE-24 UNKNOWN TIMES PLEASE EVALUATE FOR OVERHAUL AND FUNCTION TEST SHUTTLE VALVE AS REQUIRED AND ADVISE		
TOTAL					0.00

 Authorized Signature



APPH WICHITA, Inc.

BBA Aviation

Date: 22 Aug 2011

Serial Number: 120A

Part #: 40600-10 40600-12

Description: ACTUATOR ASSY

Received From: GREAT LAKES AVIATION

PO: R54914

Ship To: ATTN: PARTS DEPARTMENT, 1022 AIRPORT PARK

Ship Via:

City, State, Zip: CHEYENNE, WY, 82001, US

Warranty

Overhaul

Repair

Rebuilt

Test

Inspect

Issue 8130

Cycles Since New (CSN):

Cycles Since OH (CSO):

Cycles Since Repair (CSR):

Total Time (TT):

Time Since OH (TSO):

Time Since Repair (TSR):

Date of Approval to Proceed 9/1/11

Date of charges Approved 9/1/11

Customer Purchase Order Instructions / Comments

Unit received as a 40600-8. Upgraded to -12

Work Performed

Work Performed IAW: AIRCRAFT 40600 DRAWING, ISSUED 8.10 REV AC PERFORMED A FUNCTIONAL TEST IAW F.T.B 40600. NO DEFECTS NOTED AT 31 SEP 15 2011

Parts Replaced

1	40600-10	SEAL KIT		
1	40610-2	LOCK NUT		
1	40603-8	END CAP		
1	40605-3	RETAINER		
1	40602-8	HOUSING		
1	53-012-062-0560	ROLL PIN		
1	PLGA 2180010A	PLUG		
1	40601-5	BARREL		
2	MS 21240-0916	BEARING		

Disassembly	
Clean	
Inspected	
Assembly	
Functional Test Performed	SEP 15 2011
Final Inspection Performed	
FAA Form 8130 Issued	

Work Order Number 631010
CRO Number 206032

Repairman's Signature

Inspector's Signature

TEAR DOWN REPORT

CUSTOMER NAME AND ADDRESS: GREAT LAKES
1022 AIRPORT PARKWAY
CHEYENNE, WY 82001

DATE: 8/3011

ATTENTION: SHARI RACE

SUBJECT: ACTUATOR ASSY.

PO#: R54914

PART NUMBER: 40600-10

SERIAL NUMBER: 120A

DATE RECEIVED AT APPH: 8/19/11

SPECIAL INSTRUCTIONS FROM CUSTOMER: OVERHAUL

TEST RESULTS, IF PERFORMED, PRIOR TO DISASSEMBLY OR REPAIR: NONE PERFORMED

OBVIOUS PROBLEMS NOTED DURING TEAR DOWN: DURING TEAR DOWN WE FOUND THE UNIT TO NEED ONE (40603-8) END CAP REPLACED DUE TO DAMAGE AND ONE (PLGA2180010A) LEE PLUG TO BE INSTALLED IN THE NEW END CAP. ONE (40610-2) LOCKNUT, (40605-3) RETAINER, (40602-8) HOUSING, AND ONE (53-012-062-0568) ROLL PIN WILL ALSO BE REPLACED. ALSO BEING REPLACED WILL BE ALL SEALS AND ORINGS.


REASSEMBLY PROCEDURE: WILL BE REASSEMBLED IAW 40600 REV AC DRAWING.

TEST RESULTS FOLLOWING REPAIR OR OVERHAUL: WILL BE FUNTIONAL TESTED IAW 40600 REV AC AND 40600 F.T.B.

WORK ORDER #: 631010

INSPECTOR: JOSH BURDEN

NUMBER: [REDACTED]



APPH Wichita, INC
1445 SIERRA DRIVE
WICHITA, KS 67209

Repair Estimate
Response required

FAX: [REDACTED]
e-mail: [REDACTED]

Date: 08/31/11 Your Purchase Order: R54914
To: GREAT LAKES AVIATION APPH CRD: 200032
Attn: LINDA STUEVE APPH Shop Order: 031010
Fax: WILL EMAIL
P.N. 40600-10(114-380041-17) S.N. 120A

R54888

This unit was received as 40600-8(114-380041-9) and will be overhauled and upgraded to the -10 configuration upon approval.

The above unit has been evaluated and quote approval is required prior to completion.

Standard/Contract Overhaul				\$1,200.00
Parts required over and above standard overhaul:				
Part Number/ARD	Description	Qty	Net Price	Est Price
40610-2	LOCK NUT(CRACKED)	1	\$65.00	\$65.00
40603-8	END CAP(CORROSION)	1	\$775.00	\$775.00
40605-3	RETAINER(DAMAGED)	1	\$60.00	\$60.00
40602-8	HOUSING(CORROSION)	1	\$995.00	\$995.00
53-012-082-0560	ROLL PIN(REQUIRED W/ HOUSING)	1	\$5.00	\$5.00
PLGA2180010A	LEE PLUG(REQUIRED W/ HOUSING)	1	\$10.00	\$10.00
Total Excluded Parts				\$1,900.00
Total Overhaul for approval:				\$3,100.00

Please advise your disposition by noting and signing below and faxing to [REDACTED]

THIS IS ONLY AN ESTIMATE. AN INVOICE WILL BE RENDERED AT COMPLETION FOR ACTUAL TIME AND MATERIAL USED. APPH HAS DONE ITS BEST TO ENSURE THIS QUOTE IS ACCURATE, HOWEVER UNFORESEEN, ADDITIONAL CHARGES MAY APPLY.

APPH Wichita Lead Time Will Be: 30 days from the date of receipt. Subject to delay depending upon customer quote approval.

This order is scheduled to ship via: UPS
This order is scheduled to ship: GROUND Account:

Please advise if you would like to change the scheduled shipping carrier or method.

[REDACTED] [Signature] Quotes Approved

[REDACTED] Please Return As-Is \$150.00 Eval Fee will apply.

Thank you for your business! If you have any questions regarding this quote, please don't hesitate to contact us.

Julie Jones

This estimate is valid for 30 days. If no response is received within 30 days, a charge equal to 15% of the standard overhaul/repair charge will be added, per month, to the final invoice amount. If no response is received after 6 months from the date of this estimate, APPH will assume title of the product and reserves the right to sell this item on the open market as compensation for costs incurred.

Unless otherwise agreed, Standard APPH Wichita Terms and Conditions of Sale apply. A copy can be found at our web site: www.apph.com/wichita or can be sent via fax or e-mail upon request.

Jones, Julie (APPH-WIC)

From: Jones, Julie (APPH-WIC)
Sent: Friday, September 09, 2011 2:58 PM
To: [REDACTED]
Subject: P/O R54914

Hello Linda,

This unit will be upgraded to the 40600-12(114-380041-21) as we do not have the housing required for the -10(-17) and no longer manufacture them. Please update your records to reflect this information. Please feel free to contact me if you have any questions.

*Thank you,
Julie Hibarger
APPH Wichita
Customer Service Specialist*

P: [REDACTED]
F: [REDACTED]
en [REDACTED]

MRO



BBA Aviation

Shop Order 631010/**	Part 40600-10	Description ACTUATOR ASSY	Quantity 1	BOM Rev 1	Rout Rev 2
CRO Number 206032/1	Customer P/N 40600-10	Customer GREAT LAKES AVIATION	Customer PO R54914		
Print Date 22 Aug 2011	Raised By JULIE.JONES	Serial No. 120A	Start Date 30 Aug 2011	Required By 16 Sep 2011	Page 1 of 2

Router Notes

REFERENCE APPH WICHITA DWG. 40600 REVISION AC
 ROUTER REV. 2 - VENDOR NAME & PROCESS, STANDARDIZE ROUTER, REVISE PRINT REV.



354863

OP No.	Due Date	Work Center	Operation	Setup	Unit Time	OP Time
11	30Aug11	AIR	DISASSEMBLE,CLEAN, INSPEC	0.00	0.55	0.55

1 DISASSEMBLE,CLEAN, INSPEC

REFERENCE AIRIGHT 40600 DRAWING CURRENT REVISION
 DISASSEMBLE UNIT
 CLEAN UNIT
 INSPECT PIECE PARTS

Good	Scrap	Oper.	Insp.	Date
1	Ø	■	N/A	AUG 25 2011



354864

OP No.	Due Date	Work Center	Operation	Setup	Unit Time	OP Time
21	16Sep11	RONDI	AIRCAPITOL NDI SERVICE	80.00	0.00	80.00

1 OUTSIDE PROCESS

NON-DESTRUCTIVE INSPECT (MAGNAFLUX PER ASTM 1444-01) PART NUMBERS
 25719-6 SLIDE
 40611-1 ROD END
 25720-2 WASHER
 25720-3*WASHER
 40604-2 PISTON
 40614-1 RETAINER
 NON-DESTRUCTIVE INSPECT (PENETRANT PER ASTM E-1417-99 PART NUMBERS)
 40602-6 HOUSING
 40603-6 END CAP
 25716-1, SPRING
 40601-3 BARREL

REPLACE IF REQUIRED (CHECK YES OR NO)
 YES NO SWITCH - 1EN51-6
 YES NO CONNECTOR - MS3126F12-10P
 YES NO SLIDE - 25719-6
 *NOTE: SLIDE REPLACEMENT IS REQUIRED IF CUSTOMER IS REQUESTING AN UPGRADE TO A -10 ACTUATOR. (Slide Lock is shorter than 1.105")

Good	Scrap	Oper.	Insp.	Date
1	Ø	■	N/A	AUG 26 2011



354865

OP No.	Due Date	Work Center	Operation	Setup	Unit Time	OP Time
22	16Sep11	INSP.	VENDOR COMPLIANCE	0.00	0.10	0.10


1 INSPECT FOR VENDOR

COMPLIANCE 8130


P126968

Good	Scrap	Oper.	Insp.	Date
1	Ø	N/A	■	AUG 30 2011


MRO	Shop Order 631010/**/*	Part 40600-10	Description ACTUATOR ASSY	Quantity 1	BOM Rev 1	Rout Rev 2
------------	---------------------------	------------------	------------------------------	---------------	--------------	---------------

 354866	OP No. 30	Due Date 16Sep11	Work Center OTEST	Operation ASSEMBLE AND TEST	Setup 0.00	Unit Time 1.00	OP Time 1.00
---	--------------	---------------------	----------------------	--------------------------------	---------------	-------------------	-----------------



1 ASSEMBLE, TEST, PAINT REFERENCE AIRIGHT 40600 DRAWING CURRENT REVISION ASSEMBLE FUNCTIONAL TEST ✓ PAINT INSTALL ROD END AND SWITCH ASSY FINAL FUNCTIONAL TEST	Good	Scrap	Oper.	Insp.	Date
	1	0		N/A	9.13.11
	1	0		N/A	SEP 14 2011
	1	0		N/A	9.15.11
	1	0		N/A	SEP 15 2011

 354867	OP No. 40	Due Date 16Sep11	Work Center FASSY	Operation FINAL ASSEMBLY	Setup 0.00	Unit Time 1.25	OP Time 1.25
---	--------------	---------------------	----------------------	-----------------------------	---------------	-------------------	-----------------

1 FINAL ASSEMBLY REFERENCE AIRIGHT 40600 DRAWING CURRENT REVISION INSTALL/INSPECT SAFETY WIRE INSTALL/INSPECT INSPECTION TORQUE SEAL SIGN AND STAMP OFF ISSUE 8130	Good	Scrap	Oper.	Insp.	Date
	1	0		N/A	9.15.11

 354868	OP No. 50	Due Date 16Sep11	Work Center OFINS	Operation FINAL INSPECTION	Setup 0.00	Unit Time 0.10	OP Time 0.10
--	--------------	---------------------	----------------------	-------------------------------	---------------	-------------------	-----------------

1 CUSTOMER PART NUMBER: 40600-10 ALL WORK PERFORMED PER THIS SHOP ROUTER AND IAW AIRIGHT DRAWING NUMBER 40600, CURRENT REVISION REPAIRMAN _____ DATE <u>9.13.11</u> INSPECTOR _____ FAA REPAIR STATION NUMBER OU2R070L / JAA.5895	Good	Scrap	Oper.	Insp.	Date
	1	0		N/A	9.13.11
	1	0	N/A		SEP 19 2011

1. Approving National Aviation Authority / Country: FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: NDI-102950	
4. Organization Name and Address: Air Capital NDI 7ANR504B 424 W. 4th Ave., Belle Plaine, KS 67013					5. Work Order, Contract, or Invoice Number: 631010	
6. Item	7. Description	8. Part Number	9. Eligibility*	10. Quantity	11. Serial/Batch Number	12. Status/Work
1	Assembly	40600-10	N/A	1 ea.	120A	NDI Inspected
13. Remarks Fluorescent Penetrant inspected per MIL-I-6866 (ASTM E 1417-05) and Magnetic Particle inspected per MIL-I-6868 (ASTM E 1444-05) accordingly for the following parts with no defects found: 40604-2 Piston (1), 40614-1 Ball Retainer (1), 40611-1 Rod End (1), 25720-2 Washer (1), 25720-3 Washer (1), 25719-4 Slide (1), 40601-3 Barrel (1), 40602-6 Housing (0), 40603-6 Gland End (0), 25716-1 Spring (1)						
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in block 13				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
15. Authorized Signature NA		16. Approval Authorization No: NA	20. Authorized Signature: 		21. Approval/Certificate No: 7ANR504B	
17. Name (Typed or Printed): NA		18. Date (m/d/y): NA	22. Name (Typed or Printed): Derik Yunker		23. Date (m/d/y): Aug 29, 2011	

FAA Form 8130-3 (05-01)

It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts parts/components/ assemblies from the Airworthiness Authority of the country specified in block 1. Statements in block 14 and 19 do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

The FAA Form 8130-3 and JAA Form One are equivalent. Other countries such as Canada also have equivalent acceptable documents.

*Optional. Installer must cross check eligibility with applicable technical data).



PURCHASE REQUISITION FORM

ATA Aviation

Date

AUG 25 2011

Customer

Great Lakes Aviation

Shop Order

631010

Assembly PN

40600-10

Assembly SN

120A

Cycles

N/A

#	Tech Initial	Part Number	Qty	Description	Lot Number / SN	Issued by	Date	RTS Initial
1	J	40600-10	1	100% Seal Kit				
2		40610-2	1	lock nut - cracked				
3		40603-8	1	End cap - corrosion				
4		40605-3	1	Retainer - damage				
5		40602-X BS	1	Housing - corrosion				
6		53-012-062-0560	1	Roll pin } for new parts				
7		DLGA2180010A	1	Plug				
8		H0601-5	1	BARREL				
9		MS 2240-09-16	2	SEALING				
10		40619.1		WASHER (Slide lock meets specs for -10)				
11								
12								
13								
14								
15								

FUNCTIONAL TEST BULLETIN/40600

MAIN GEAR ACTUATOR: P/N'S: 40600-2,-4,-5,-6,-8,-10,-12 / TEST SPECIFICATIONS FROM
PART# 40600-10 DRAWING 40600 REV. AC
SERIAL # 120A Dated: 8/10
W/O# 631010
DATE: SEP 15 2011

- 1. CYCLE ACTUATOR 25 TIMES AT 3000PSI
NO BINDING/LEAKAGE ALLOWED. PASS
- 2. CHECK/SET STROKE(6.23+/- .03) 6.24
- 3. CHECK FREE PLAY IN LOCK(.020 MAX) PASS
- 4. SHUTTLE VALVE OPERATION(65 TO 105 PSI) 95 PSI
- 5. CHECK SHUTTLE LEAKAGE @ 650PSI 10 DPM MAX(-6,-8,-10,-12)
@2000PSI 20 DPM MAX(-2,-4,-5) PASS
- 6. APPLY 4500PSI PROOF PRESSURE PASS
- 7. CHECK UNLOCK PRESSURE(200 TO 400PSI) 225 PSI
- 8. SET EXTENDED LENGTH(21.98 +/- .25) 21.98
- 9. SET RETRACTED LENGTH(15.75 +/- .25) 15.75
- 10. SET SWITCH(LOCK/UNLOCK) PASS
- 11. DRAIN AND CAP ACTUATOR ✓

INSPECTOR/STAMP



6700
540
6.240

6700
476
6.304

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: R54914	
4. Organization Name and Address: APPH WICHITA INC. 1445 SIERRA DRIVE WICHITA KS 67209 (OU2R070L)					5. Work Order/Contract/Invoice Number: 631010		
6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	ACTUATOR ASSY	40600-12	N/A	1	120A	OVERHAULED	
13. Remarks: Customer Part Number 114-380041-21 Work Order 631010 detailing work performed is attached and on permanent file at APPH Wichita Inc. Overhauled IAW 40600 Rev AC drawing dated August 2010. "CERTIFIES THAT WORK SPECIFIED IN BLOCKS 12/13 WAS CARRIED OUT IN ACCORDANCE WITH EASA.145 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA ACCEPTANCE CERTIFICATE NUMBER EASA 145.5895."							
14. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:		20. Authorized Signature:		21. Approval/Certificate No.:	
						OU2R070L / EASA.145.5895	
17. Name (Typed or Printed):		18. Date:		22. Name (Typed or Printed):		23. Date (MMM/DD/YYYY):	
				JOSHUA BURDEN		Sep. 19, 2011	
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.							
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.							
Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

GREAT LAKES AIRLINES
CERT. G-2A061A



M2-114-380041-15



GREAT LAKES AVIATION, Ltd.

ATA 32-10

SERVICEABLE PARTS TAG

PN 114-380041-21

Name MLG ACTUATOR

SN 120A TSO

Date 26 SEP 11

O/H/Agency APPH WICHITA

WO# 631010/R54914

Shelf Life NA

Insp. [REDACTED]

New O/H Repaired

Bench Removed
Time rem. _____

Remarks:

Installation Data 31823.5

Date 03-15-2002

A/C 11626L TAT 31818.9

Position LH

Log Page 096029

Mech [REDACTED]

OFF S/N 0316A

REQUIRED
REMOVED

GREAT LAKES AVIATION, Ltd.

Aircraft Log

Form MM-10

Log No.: 046024	AIRCRAFT "N" No.: 1696L	DATE: 3-14-12
------------------------	--------------------------------	----------------------

Maintenance Due	Engine Trend Check	Torque	LH:	RH:
TAT:	Flight No.:	Prop. RPM	LH:	RH:
Date:	IOAT:	N 1% (NH/NL)	LH:	RH:
	Press Alt.:	ITT/T6	LH:	RH:
	IAS:	Fuel Flow	LH:	RH:

Capt Emp #	FO Emp #	FA Emp #	Fit Code	Fit No.	From	To	Time Out	Time Off	Time On	Time In	Block Time	Hobbs	Starts		Oil		
													1	2	1	2	APU
[Large handwritten scribbles]																	

THIS AIRCRAFT IS APPROVED FOR RETURN TO SERVICE										Total Block	← Ending	
STATION:	DATE:	TIME:								2730.7	← Beginning	
SIGNATURE:	EMP #:										FLT Code: C-Charter F-Ferry P-Position T-Training CK-Check Ride M-Maintenance R-Revenue	

1	M/P	Emp # 2801	STN: CYS	TIME: 1850	1	STN: CYS	TIME: 2045	Date: 03-14-2012	Rtl: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # SCH MX Discrepancy:					Corrective Action: Performed FCD 1900-61-00-00 ATA: 61				
FCD 61-00-00 Rev 3 Dwg R/H (H. J. 2290)					Rev 3 IAW given instructions. Found one debonded spot on #1 blade trailing edge between b/s 51.53. Spot measured 3/4" long. This mapped on FCD pg 3. No additional discrepancies noted.				
Signature: [Redacted] Emp #:					Signature: [Redacted] Emp #:				
2	M/P	Emp # 11581	STN: CYS	TIME: 00:30	2	STN: CYS	TIME: 03:15	Date: 15 MAR 12	Rtl: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # 98994 Discrepancy: Fb cell BACKLIGHTING ID					Corrective Action: TRANSFERRED TO DML # 98994 ATA: 34				
1 NoP.					AS PER MEL # 33-24 ALL MX PROCEDURES CW AS PER MARK OR CHD CAT D. PLACARDS INSTALLED.				
Signature: [Redacted] Emp #:					Signature: [Redacted] Emp #:				
3	M/P	Emp # 10397	STN: CYS	TIME: 5:30	3	STN: CYS	TIME: 0950	Date: 03-15-12	Rtl: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Control # SA MC Discrepancy:					Corrective Action: R/R LH MLG actuator ATA: 82				
LH MLG Actuator Switch Band					IAW TC 1900-5230.10 Rev 1. P/Noff 119-380091-15 P/No: 119-380091-21 S/No: 0816A S/No on 120A ops checks & R is check good				
Signature: [Redacted] Emp #:					Signature: [Redacted] Emp #:				
4	M/P	Emp # 12928	STN: CYS	TIME: 0530	4	STN: CYS	TIME: 0750	Date: 3/15/12	Rtl: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # SCH MX Discrepancy: IN R/F TO A/C LOG					Corrective Action: CW R/F FOR ATA: 47				
046024/3: R/R REQUIRED FOR					LH MLG ACTUATOR R/R R/F				
LH MLG ACTUATOR R/R R/F					TC 1900-5230.10 Rev 1 ETC 4.3.7				
TC 1900-5230.10 Rev 1					CORRECTED				
Signature: [Redacted] Emp #:					Signature: [Redacted] Emp #:				

COPY



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

MAIN LANDING GEAR ACTUATOR REMOVAL AND INSTALLATION

CARD: 1900-3230.10
REVISION: 1
REVISION DATE: 15 FEB 12

AIRCRAFT #:	1696L	TAT:	31818.9	DATE:	3-15-12	
LOGBOOK/MTX LOG REFERENCE #:	046024/3	POSITION:	LH			
P/N OFF:	114-38004-15	S/N OFF:	0316A			
P/N ON:	114-38004-15-21	S/N ON:	0645A 120A			

INSTRUCTIONS:	Fill in above information completely. The MECH/INSP sign-off blocks below must be signed or marked N/A, with employee's initials and employee number. Shaded blocks require no employee number or initials.
REFERENCE MATERIAL:	1900D MM 32-30-10
TOOLS REQUIRED:	N/A
PARTS REQUIRED:	N/A

NOTE: While performing this Task Card, all discrepancies found must be recorded in either the Aircraft Logbook or on a Maintenance Log Sheet.

TASK	MAIN GEAR ACTUATOR REMOVAL	MECH	INSP
1	Pull the stall warning circuit breaker and the 2-ampere control circuit breaker on the pilot's inboard subpanel. Place the airplane on jacks and remove gear pins. All tires must be clear of the ground. Refer to 1900D MM 7-10-00.		
2	Disconnect the door actuating cams (7) from the doors (1) by removing the cotter pin (2), nut (3), bolt (4) and washer (5) from the upper end of the link assembly (6). Secure doors out of the way to provide better access to the gear assembly, if needed. Refer to Fig. 3.		
3	Disconnect the three hydraulic hoses (14) from the actuator (1), cap and identify each hose.		
4	Remove the nut (5), bolt (3) and washers (4) attaching the actuator rod to the upper drag leg arm (2).		
5	Disconnect the actuator down-position switch wiring at the receptacle plug located in the upper rear of the wheel well.		
6	NOTE: Identify and note the position and thickness of all washers during removal to facilitate correct washer installation and maintain main gear alignment. Remove the nuts (10), bolts (9), bushings (8) and washers (6 and 7) attaching the actuator (1) to the support structure. Remove the actuator (1) from the aircraft.		
7	If a different actuator is being installed, remove the hydraulic fittings (11 and 15) from the actuator. Immediately cap all open lines and fittings to prevent contamination.		



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

CARD: 1900-3230.10
REVISION: 1
REVISION DATE: 15 FEB 12

AIRCRAFT N#: <u>1696L</u>	DATE: <u>03-15-2012</u>
---------------------------	-------------------------

TASK	MAIN GEAR ACTUATOR INSTALLATION	MECH	INSP	
8	Install new o-rings onto hydraulic fittings (11 and 15), install fittings onto actuator and tighten.	[REDACTED]		
9	Position the actuator in the wheel well and install the bushings (8), washers (6 and 7), bolts (9) and nuts (10) to secure the actuator (1) to the support structure. Install the same number of AN960-716L washers on each side of the actuator that were removed in step 6. Torque nut to 100 inch-pounds.			
10	Connect the hydraulic hoses (14) to the actuator (1).			
11	Connect the actuator down-position switch wiring to the plug located in the upper aft corner of the wheel well.			
12	With the actuator (1) fully retracted and the landing gear fully extended, check the alignment with the upper drag leg arm (2). The actuator rod end must slip into the upper drag arm without causing any side loads on the actuator piston rod.			RII [REDACTED]
13	Access landing gear service valve in LH inboard wing and pull up on valve. Connect an 18 PSI air supply to hydraulic pack.			
14	With the other 2 main landing gear pins installed, pull the landing gear control circuit breaker next to the handle, place the landing gear handle in the UP position, then use emergency landing gear hand pump to place the actuator (1) in the extended position.			
15	Manually push the landing gear to the retracted position and again check for any side loads on the actuator piston rod. If any misalignment is found in either position, shift the AN960-716L washers, as required to correct the misalignment. A minimum of one AN960-716L washer is required between the actuator (1) and the support structure.			RII [REDACTED]
16	With landing gear in the extended position, push the service valve in the down position, place landing gear handle in the down position and pump emergency landing gear handle until the actuator (1) is fully retracted.			
17	Check alignment of the actuator rod end with the attaching hole in the upper drag leg arm (2). If the holes do not align: a. Cut the safety wire and loosen the jam nut on the actuator rod end. b. Adjust the actuator rod end to align with the attaching hole. c. Tighten jam nut and install safety wire. With the holes aligned, lubricate bolt (1) with Molykote G-n and install with washers and nut. Torque nut to 290-410 inch-pounds.			RII [REDACTED]
18	Remove all gear pins and operate the landing gear through one cycle.			



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

CARD: 1900-3230.10
REVISION: 1
REVISION DATE: 15 FEB 12

AIRCRAFT N#: <u>169 GL</u>	DATE: <u>03-05-2012</u>
----------------------------	-------------------------

TASK	MAIN GEAR ACTUATOR INSTALLATION (cont'd)	MECH	INSP
19	With the landing gear fully extended, apply moderate pressure to the drag brace assembly as shown in Fig. 2 to bottom out end play in the actuator. Measure the amount of clearance between the upper drag leg and the rig plate. If a clearance of 0.001 and 0.010, at the closest point does not exist, loosen the jam nut and extend the rod end to the next keying position by rotating the actuator piston rod. Tighten the jam nut and install safety wire (MS20995C32) to key washer. Cycle the landing gear through one cycle and verify clearance.	11	RII
20	Retract the landing gear fully and measure the clearance between the landing gear piston and the main spar. If the clearance is not 2.28" +0.25/-0.09", remove the actuator from the aircraft and adjust the stroke as follows. a. Remove the safety wire and loosen the end cap jam nut. b. Rotate the end cap one full turn until proper clearance is achieved, each full turn of the actuator will change the stroke by 0.06 inch. c. After proper clearance is achieved, tighten the jam nut and install safety wire (MS20995C32) and reinstall the actuator. NOTE: To ensure proper alignment of the hydraulic plumbing to the shuttle valve located in the end cap, the end cap must be rotated in 360° rotations only. CAUTION: IF MORE THAN TWO (2) COMPLETE ROTATIONS OF THE END CAP ARE REQUIRED TO OBTAIN PROPER STROKE ADJUSTMENT, STRUCTURAL DAMAGE IS INDICATED AND AIRPLANE STRUCTURE INSPECTION IS REQUIRED.	11	RII
21	With all gear pins removed, supply 18 PSI head pressure and cycle the landing gear with the power pack to check for proper operation of the in-transit and gear-down lights.		RII
22	Perform leak check of landing gear actuator (1).		
	CAUTION: TO PREVENT SERIOUS DAMAGE TO THE PUMP, NEVER OPERATE THE POWER PACK WHEN THE ENGINES ARE NOT RUNNING WITHOUT SUPPLYING 18 PSI OF REGULATED DRY AIR TO THE MANUAL BLEED VALVE TO PRESSURIZE THE RESERVOIR. WHEN CYCLING THE LANDING GEAR WITH THE POWER PACK, DO NOT EXCEED THREE (3) CYCLES IN THE FIRST SIX (6) MINUTES OF OPERATION WITH APPROXIMATELY A TWO-MINUTE COOLING PERIOD BETWEEN CYCLES, THEN WITH A FIVE-MINUTE COOLING INTERVAL BETWEEN EACH CYCLE.		
23	If disconnected in task 2, reconnect the door actuating cams (7) to the doors (1) by installing the bolt (4), washer (5), nut (3) and cotter pin (2) in the upper end of the link assembly (6). Refer to Fig. 3.		
24	Cycle the main landing gear with the power pack and inspect gear doors for proper fit and operation during the retraction cycle.		



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

CARD: 1900-3230.10
REVISION: 1
REVISION DATE: 15 FEB 12

AIRCRAFT N#: 1696L DATE: 03-15-2012

TASK	MAIN GEAR ACTUATOR INSTALLATION (cont'd)	MECH	INSP
	WARNING: BEFORE REMOVING THE AIRPLANE FROM JACKS, MAKE SURE THE LANDING GEAR EMERGENCY EXTEND HAND PUMP HANDLE IS IN THE STOWED POSITION, THE PLUNGER ON THE SERVICE VALVE IS PUSHED DOWN WITH THE HINGED RETAINER IN PLACE, THE LANDING GEAR CONTROL HANDLE IS IN THE DOWN POSITION, THE LANDING GEAR IS DOWN AND LOCKED AND THE ACCUMULATOR IS CHARGED TO 800 +/- 50 PSI.		
25	Service hydraulic fluid reservoir as required.		
26	Remove air source, secure service valve and reinstall panel.		
27	Install gear pins. Remove the aircraft from the jacks and reset the stall warning circuit breaker and the 2-ampere control circuit breaker on the pilot's inboard subpanel.		
28	Remove gear pins or ensure a gear pins installed entry is made in the aircraft logbook.		



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 4

INSTALLATION OF LANDING GEAR ACTUATOR ASSEMBLY

CARD: 4.3.7
REVISION: 4
DATE: 15 OCT 11

Aircraft N#: <u>1696L</u>	TAT: <u>31818.9</u>	Date: <u>3-15-12</u>
Logbook/Mtx Log Reference #: <u>046024/Quos 3</u>	Position: <u>LH</u>	
Instructions:	Fill in above information in applicable blocks. Insp. blocks, both initials and employee number are required. No action is required for shaded blocks.	

NOTE: While performing this Task Card, all discrepancies found must be recorded in either the Aircraft Logbook or on a Maintenance Log Sheet.

TASK	DESCRIPTION	RII
	The Inspector completing this inspection will ensure all maintenance is performed by qualified personnel, that correct part numbers are installed and that appropriate calibrated tooling and maintenance manual procedures and techniques are followed as per GMM, Ch. 16, 16.2.0.D.	
1	Physically verify S/N and part number of any components installed to ensure it matches the serviceable tag and that it is applicable to that aircraft.	
2	Inspect attach points for condition, wear and cracks.	
3	Inspect all removed and reinstalled clamps for security.	
4	Inspect all attach bolts for tightness and safeties.	
5	Inspect hydraulic lines for wear, condition, and proper tightness.	
6	Inspect actuator for proper alignment and rigging.	
7	Inspect gear doors for proper fit and operation during retraction cycle, and for proper tightness and safeties.	
8	Inspect actuator and hydraulic lines for leaks.	
9	Ensure sealant is applied. (EMB-120)	
10	Inspect for proper installation of all access panels.	
11	Perform an inspection of the work area and the surrounding areas for any other defects related or not related to the RII task at hand.	



AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

Landing Gear Hydraulic Line Filter Inspection/Cleaning

Task Card: 1900-1200

Revision: 1

Revision Date: 15 Jul 04

Aircraft N#:	169 GL	TAT:	32636.1	Date:	7-17-12
Man Hours:	2 1/2				

Instructions: Fill in above information completely. In man hours block, fill in actual time to perform task.

In the mech/insp blocks: initials and employee number are required.

Shaded blocks—require no action or initials.

Manual reference: MM 5-20-02, MM 32-30-00

Oil to be used: MIL 5606

Parts required: 3 ea. 20666-6-10 In-line filter

Tools required: Aircraft jacks

Task Number	Task Description	Mech	Insp
1	Place jacks under aircraft jack locations and lift aircraft off of ground until all wheels are clear of the floor.		
2	Remove all electrical power and disconnect battery. Tag cockpit with safety indicating gear work in progress.		
3	Gain access to the nose gear hydraulic line filter. Refer to figure 1, item A. Remove filter. Clean or replace. Tag filter for cleaning if replaced.		
4	Install filter in nose gear hydraulic line.		
5	Gain access to left main landing gear hydraulic line filter. Refer to figure 1, item B. Remove filter. Clean or replace. Tag filter for cleaning if replaced.		
6	Install filter in left main landing gear hydraulic line.		
7	Gain access to right main landing gear hydraulic line filter. Refer to figure 1, item C. Remove filter. Clean or replace. Tag filter for cleaning if replaced.		
8	Install filter in right main landing gear hydraulic line.		
9	Connect battery, remove warning tag from cockpit.		
10	Apply external power to aircraft and perform landing gear retraction and extension check. Perform leak check of nose, left and right landing gear hydraulic line filters during the test.		
11	Ensure all landing gear are down and locked (3 green indicator lights illuminated). Lower aircraft from jacks.		

GREAT LAKES AVIATION, Ltd.

Aircraft Log

Form MM-10

Log No.: 085794				AIRCRAFT "N" No.: 169				DATE: 7/4/13									
Maintenance Due				Engine Trend Check				Torque		LH:		RH:					
TAT:				Flight No.:				Prop. RPM		LH:		RH:					
Date:				IOAT:				N 1% (NH/NL)		LH:		RH:					
				Press Alt.:				ITT/T6		LH:		RH:					
				IAS:				Fuel Flow		LH:		RH:					
Capt Emp #	FO Emp #	FA Emp #	Flt Code	Flt No.	From	To	Time Out	Time Off	Time On	Time In	Block Time	Hobbs	Starts		Oil		
													1	2	1	2	APU
M X O N T																	
THIS AIRCRAFT IS APPROVED FOR RETURN TO SERVICE													Total Block		← Ending		
STATION:				DATE:				TIME:				← Beginning					
SIGNATURE:						EMP #:						FLT Code: C-Charter F-Ferry P-Position T-Training CK-Check Ride M-Maintenance R-Revenue					

1	M/P	Emp #	STN:	TIME:	STN:	TIME:	Date	R/I:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control #		Discrepancy:		Corrective Action:		ATA: 24			
/		/		/		Cont from Block dated Pg 085793 NO 18 @ this time			
Signature: [Redacted]		Emp #: [Redacted]							
2	M/P	Emp # 1310	STN: DEN	TIME: 2036	2	STN: Ocn	TIME: 21:43	Date 7/4/13	R/I: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # 119677		Discrepancy: Upon T/O landing handle was moved to up position, No Intrans Light came on. Gear did not move. Green Deployed Annunciator Remained Illuminated.		Corrective Action: Found micro switch @ service valve sticking cleaned switch & inspected wires Ref AIM 1420 no defects noted Performed landing gear Retraction multiple times OPS/Cont Ref AIM 10-32-01 no defects noted @ this time		ATA: 27 32			
Signature: [Redacted]		Emp #: [Redacted]							
3	M/P	Emp #	STN:	TIME:	3	STN:	TIME:	Date	R/I: Yes <input type="checkbox"/> No <input type="checkbox"/>
Control #		Discrepancy		Corrective Action:		ATA:			
Signature: [Redacted]		Emp #: [Redacted]							
4	M/P	Emp #	STN:	TIME:	4	STN:	TIME:	Date	R/I: Yes <input type="checkbox"/> No <input type="checkbox"/>
Control #		Discrepancy:		Corrective Action:		ATA:			
Signature: [Redacted]		Emp #: [Redacted]							

GREAT LAKES AVIATION, Ltd.

Aircraft Log

Form MM-10

Log No.: 085795				AIRCRAFT "N" No.: 1696L				DATE: 7-5-13									
Maintenance Due				Engine Trend Check				Torque		LH: 2450	RH: 242						
TAT:				Flight No.: 7316		Prop. RPM		LH: 1650	RH: 1550								
Date:				IOAT: 28°C		N 1% (NH/NL)		LH: 95.0	RH: 93.5								
				Press Alt.: 23000		ITT/T6		LH: 700	RH: 680								
				IAS: 178		Fuel Flow		LH: 330	RH: 350								
Capt Emp #	FO Emp #	FA Emp #	Fit Code	Fit No.	From	To	Time Out	Time Off	Time On	Time In	Block Time	Hobbs	Starts		Oil		
													1	2	1	2	APU
13101	12710	-	R	7316	VEN	PER	09 15	09 32	10 56	11 02	104	5760.6	1	1	0	0	-
13103	14057	-	R	7316	PIR	HON	11 17	11 22	11 45	11 50	33	5761.0	1	1			
13103	14054	-	R	7316	HON	MSP	11 53	12 01	13 00	13 09	74	5766.1	1	0			
13441	13934	-	R	7289	MSP	MSP	20 40	20 45	21 04	21 08	28	5762.9	1	1			
THIS AIRCRAFT IS APPROVED FOR RETURN TO SERVICE												Total Block		← Ending			
STATION:				DATE:				TIME:				5762.9		← Beginning			
SIGNATURE:				EMP #:				FLT Code: C-Charter F-Ferry P-Position T-Training CK-Check Ride M-Maintenance R-Revenue									

1	M/P	Emp # 11669	STN: DEX	TIME: 530	1	STN: DEX	TIME: 615	Date 7-5-13	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # 5ch mx Discrepancy:					Corrective Action:				
mx Ron check					cfw daily 1900 mx Remain over night checks, Ref Aim task card 1900-Ron				
Signature: _____					Emp #: _____				
2	M/P	Emp # 13103	STN: MSP	TIME: 1409	2	STN: MSP	TIME: 2002	Date 7-5-13	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # 119697 Discrepancy: upon T/O Landing gear handle was moved to UP position no Intransit light came on. Gear did not move. All 3 green annunciator remained illuminated					Corrective Action: T/S system confirmed Good Power and continuity on SERVICE VALVE MICRO switch, inspected wires from micro switch for chafing. None found, slaved in and checked for power at gear handle				
Signature: continue on item 4					Emp #: _____				
3	M/P	Emp # 10203	STN: MSP	TIME: 1510	3	STN: MSP	TIME: 1830	Date 7/5/13	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # 50A m r Discrepancy: HC exit removed from					Corrective Action: re installed HC exit from SA 20100. lights checked good.				
Signature: _____					Emp #: _____				
4	M/P	Emp #	STN:	TIME:	4	STN: Continued	TIME: From Item 2	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Control # _____ Discrepancy: _____					Corrective Action: Confirmed good Power Gear handle did not fix, checked power to PCB Az16, replaced, also verified power to RH squat switch, jacked and performed PERFORMED GEAR SWING SEVERAL TIMES				
Signature: _____					Emp #: _____				

GREAT LAKES AVIATION, Ltd.

Aircraft Log

Form MM-10

Log No.: 085796				AIRCRAFT "N" No.: 169GL				DATE: 7/5/13									
Maintenance Due				Engine Trend Check				Torque		LH:		RH:					
TAT:				Flight No.:				Prop. RPM		LH:		RH:					
Date:				IOAT:				N 1% (NH/NL)		LH:		RH:					
				Press Alt.:				ITT/T6		LH:		RH:					
				IAS:				Fuel Flow		LH:		RH:					
Capt Emp #	FO Emp #	FA Emp #	Flt Code	Flt No.	From	To	Time Out	Time Off	Time On	Time In	Block Time	Hobbs	Starts		Oil		
													1	2	1	2	APU
THIS AIRCRAFT IS APPROVED FOR RETURN TO SERVICE											Total Block		← Ending				
STATION:				DATE:				TIME:				← Beginning					
SIGNATURE:				EMP #:				FLT Code: C-Charter F-Ferry P-Position T-Training CK-Check Ride M-Maintenance R-Revenue									

1	M/P	Emp # 13842	STN: MSP	TIME: 1958	14	STN: MSP	TIME: 20:00	Date 7-5-13	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # <u>Sch M</u> Discrepancy: <u>REF log PAGE</u>					Corrective Action: <u>1/1W AIM HI</u> ATA: <u>32</u>				
<u>085795 ITEM 2</u>					<u>30-01 OPS CHECK NORMAL EVERY TIME, CLEANED Cannon plug on PRESSURE switch and on micro switch on SERVICE UNLIE,</u>				
Signature: _____					Emp #: _____				
2	M/P	Emp # 13411	STN: MSP	TIME: 2115	2	STN: MSP	TIME: 14:30	Date 7-6-13	RII: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Control # <u>119714</u> Discrepancy: <u>upon Ho landing gear handle was moved to up position + gear did not retract green annunciators remained illuminated.</u>					Corrective Action: <u>T/S system to R/H</u> ATA: <u>82</u>				
<u>Squat safety switch, adjusted and checked rigging 1/1W AIM TC 1900-3260.05 ITEMS 7-17 and 23-26 ops check good RII inspection REQUIRED</u>					Signature: _____ Emp #: _____				
3	M/P	Emp # 13842	STN: MSP	TIME: 1431	3	STN: MSP	TIME: 14:32	Date 7-6-13	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # <u>Sch M</u> Discrepancy: <u>RII inspection required for R/H safety switch rigging</u>					Corrective Action: <u>1/1W RII inspection</u> ATA: <u>32</u>				
<u>1/1W AIM TC 1900-3260.05 ITEMS 7-17 and 23</u>					Signature: _____ Emp #: _____				
4	M/P	Emp # 13842	STN: MSP	TIME: 1436	4	STN: MSP	TIME: 1745	Date 7/6/13	RII: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Control # <u>119739</u> Discrepancy: <u>OPER IE OPS CHECK</u>					Corrective Action: <u>OPS CHECK FLIGHT</u> ATA: <u>32</u>				
<u>FLIGHT REQUIRED DUE TO landing gear maintenance</u>					<u>SATISFACTORY.</u>				
					<u>-ATA CODE 32 JL</u>				
Signature: _____					Emp #: _____				



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

MAIN GEAR SAFETY SWITCH and DOWN POSITION SWITCH R & R

CARD: 1900-3260.05
REVISION: 1
REVISION DATE: 25 APR 11

Aircraft N#: <u>1696L</u>	TAT: <u>34851.2</u>	Date: <u>7-6-13</u>
Logbook/Mtx Log Reference #: <u>085796</u>		Position: <u>R/H</u>

INSTRUCTIONS:	Fill in above information in applicable blocks. For MECH/INSP blocks, both initials and employee number are required. No action is required for shaded blocks.
REFERENCE MATERIAL:	Beech MM 32-60-05, MM 32-60-02, WM 91-15-01, WM 91-14-01, WM 32-61-01, WM 32-61-02
TOOLS REQUIRED:	N/A
PARTS REQUIRED:	N/A

NOTE: While performing this Task Card, all discrepancies found must be recorded in either the Aircraft Logbook or on a Maintenance Log Sheet.

TASK	DESCRIPTION	MECH	INSP
NOTE:	MLG Down Position and Safety Switch will be replaced as an entire harness assembly. The landing gear break out box must be utilized. The unserviceable harness will be returned to the Parts Department.		
Removal of Safety Switch and Down Position Switch (Ref. Figure 1)			
1	Place aircraft on jacks. All tires must be clear of the floor.		
2	Remove the safety switch actuator rod (1) from the attaching bracket on the upper torque knee, and then remove the retaining nut (2).		
3	Remove nut (6) from switch (7).		
4	Use a gear-type puller (obtain locally) to remove the switch arm (3) from the switch shaft to prevent damage to the internal mechanism of the switch.		
5	Remove down position actuator pin from drag brace. Remove safety wire from down position switch jam nuts, then remove lower jam nut and remove switch.		
6	Remove adel clamps securing down position harness, upper strut bracket and oil vent line. Disconnect canon plug.		
Installation and Rigging of Safety Switch (Ref. Figure 1)			
7	Install Switch (7) ensure that positioning prong is in the ailment hole on the back of the main gear assembly. Then install nut (6) and safety.		
8	Jack the landing gear so the shock strut is compressed to .50 inch from the fully extended position.		
NOTE:	Test box lights indicate Red: in air, Green: on ground for safety switch. Red: not locked, Green: locked for down lock switch.		
9	Connect the test box to the wiring plug A107P1 (LH) A108P1 (RH).		
10	Rotate the switch shaft clockwise until test box red lights illuminate.		



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

CARD: 1900-3260.05
REVISION: 1
REVISION DATE: 25 APR 11

Aircraft #: <u>1896L</u>	Date: <u>7-6-13</u>
--------------------------	---------------------

TASK	DESCRIPTION	MECH	INSP
11	Remove the safety wire from the lock screw (4) on the switch arm (3) and back off the lock screw.		
12	Install the switch arm (3) on the switch shaft in a position that is parallel to the upper torque knee and adjust the actuating rod (1) to align with the attaching bracket on the torque knee. Install the actuation rod connecting bolt.		
13	Position the shock strut so that it is 2 inches from the fully extended position, and adjust the switch shaft at the adjusting screw (5) until the test box green lights illuminate and the red lights extinguish.		
14	When satisfactory adjustment is reached, tighten the lock screw (4) and retaining nut (2).		
NOTE:	Before safety wiring the lock screw (4) to the switch arm, recheck the safety switch rigging as follows:		
15	Compress the strut. The green lights of the test box will illuminate and the red lights will extinguish when the shock strut reaches a position 0.38 to 2 inches from the fully extended position. The green test lights will remain illuminated indicating the open circuit as shock strut is fully compressed.		
16	As the shock strut is extended from the fully compressed position, the green test lights will remain illuminated until the shock strut reaches a position 0.38 to 0.62 inch from the fully extended position. At this point, the red test lights will illuminate and the green test lights will extinguish up to and including the fully extended position.		
17	Safety wire the lock screw (4) to the switch arm. Ensure cotter key is installed on actuation rod connection bolt.		
Installation and Rigging of Down Position Switch			
18	Install down position switch into down position plate, ensuring that lock tab engages plate and temporarily install actuating pin.		
19	Adjust switch until green light illuminates on test box adjust the switch an additional 2 turns beyond the actuation point. Remove actuating pin.		
20	Tighten jam nuts then safety wire jam nuts and attach harness to drag brace with adel clamps.		
NOTE:	Avoid excessive bottoming out of the switch		
21	Install and safety down position switch actuating pin.		
22	Disconnect test box from switches' wiring and reinstall switches' wiring and adel clamps securing down position harness to the upper strut bracket and oil vent line.		



GREAT LAKES AVIATION AIRCRAFT INSPECTION MANUAL

VOLUME: IX
CHAPTER: 3A

CARD: 1900-3260.05
REVISION: 1
REVISION DATE: 25 APR 11

Aircraft N#: 1696L Date: 7-6-13

TASK	DESCRIPTION	MECH	INSP
Final Steps			
23	Perform gear extension and retraction. Check for proper operation of the landing gear downlock lights on the pilot's inboard subpanel and the landing gear warning horn.		
24	Remove forward top cowling of either LH or RH engine, verify that low pitch solenoids are in the de-energized position.		
25	Take airplane off of jacks.		
26	Verify that low pitch solenoids are in the energized position, reinstall top forward cowling.		




Figure 1
Page 3 of 3