



## **ATTACHMENT 2**

**AIRWORTHINESS GROUP CHAIRMAN'S FACTUAL REPORT**

**CEN13FA192**

**Sikorsky Aircraft Corporation Tail Gearbox Materials Engineering  
Report No. MER-MI1308142 (8 Pages)**



**Sikorsky**

A United Technologies Company

MER-MI1308142

Page 1

# Materials Engineering Report S-76 Tail Rotor Gearbox Components from Mishap, ERA 369

Requested by: Sikorsky Product Safety

Work performed under charge number: [REDACTED]

Parts Disposition: All parts returned to operator, per direction of  
Sikorsky Product Safety®

[REDACTED]  
Prepared by  
[REDACTED]

[REDACTED]  
Approved by  
[REDACTED]



3/12/14  
Date



# Sikorsky

A United Technologies Company

**Background** – The images at the right and below are from an S-76 IETM, and provide diagrams of the tail rotor gear box, including some of the components that are documented herein. The components shown on the next slide were those examined.



Output Shaft (threaded end visible with Output Flange removed)

CC0971A






**Sikorsky**

A United Technologies Company


**Observations** – Appearance of as-disassembled Tail Gear Box components.



PROPERTY OF SIKORSKY AIRCRAFT. SEE TITLE PAGE




**Observations** – Tail Gear Box Center Housing, looking inboard, with several fractured Output Housing segments still attached. All housing fractures were overload.







**Observations** – Tail Gear Box Output Housing, looking outboard, with much of the flange portion separated by overload fracture.






# Sikorsky

A United Technologies Company

MER-MI1308142

Page 6

**Observations** – Input and Output Bevel Gear teeth had normal-appearing, centered contact patterns. Crest damage appeared to have been sustained during separation of Output Housing from Center Housing.



PROPERTY OF SIKORSKY AIRCRAFT. SEE TITLE PAGE






# Sikorsky

A United Technologies Company

MER-MI1308142

Page 7

**Observations** – Output Bevel Gear to Output Shaft bolted connection had one overload fractured bolt. The shank portion and nut were not received.



PROPERTY OF SIKORSKY AIRCRAFT. SEE TITLE PAGE





**Sikorsky**

A United Technologies Company

MER-MI1308142

Page 8

## **Additional Observations – Bearings**

- All Bearings were reviewed with cognizant Design Engineering Bearing Specialist.
- All Bearings were found to rotate smoothly with no signs of any prior distress.

## **Summary of Findings**

- All fractures were overload, and are considered to have been the result of the mishap. There was no evidence of fatigue cracking.
- Along with the fractures, all other visible damage to the subject components appeared to have been the result of the mishap.
- There were no indications of any pre-existing anomalies with the subject components prior to the mishap.