

# **NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Aviation Engineering Division  
Washington, DC 20594

November 22, 2010

## **AIRWORTHINESS GROUP CHAIRMAN FACTUAL REPORT**

**ACCIDENT:** CEN10FA443

**LOCATIONS:** Oshkosh, Wisconsin

**DATE/TIME:** July 27, 2010

**AIRCRAFT:** Hawker Beechcraft Model 390, N6JR

### **B. GROUP MEMBERS:**

Chairman: Robert L. Swaim  
Washington, DC

Member: Raymond P. Yank II  
Federal Aviation Administration  
Milwaukee, Wisconsin

Member: Robert Ramey  
Hawker Beechcraft  
Wichita, Kansas

### **C. SUMMARY:**

On July 27, 2010, at approximately 1816 Central Daylight Time (CDT), a Hawker Beechcraft Model 390 (N6JR) arriving from Detroit, Michigan, struck the ground and was substantially damaged near runway 18 at Wittman Regional Airport (KOSH), Oshkosh, Wisconsin. The airplane was owned and operated by Roush Fenway Racing LLC under the provisions of 14 Code of Federal Regulations (CFR) Part 91. The pilot had canceled an instrument clearance before entering the general Oshkosh area, and was proceeding to KOSH under visual flight rules. Day visual meteorological conditions prevailed at the time of the accident. The airline transport certificated pilot and passenger sustained serious injuries.

## **D. DETAILS OF THE INVESTIGATION:**

### **AIRPLANE IDENTIFICATION:**

Hawker Beechcraft Model: 390, marketed by the name Premier IA.

Manufacturer Serial Number: RB-161,

Note: Previous names for the airplane manufacturer have been Beech Aircraft Company and Raytheon Aircraft Company.

FAA Registration: N6JR

Engines: Williams International Turbo-Fan Engine Model FJ44-2A, Serial Numbers 105233 and 105232, respectively for the left and right.

### **ACCIDENT PATH:**

The arrival at Oshkosh took place during the 2010 Experimental Aircraft Association Airventure in front of numerous witnesses and cameras.<sup>1</sup> Photos subsequently posted on the internet from multiple sources show the airplane arrive from the northeast, turn to the runway heading (south), fly on a runway heading, then depart controlled flight with the right wing down. Using the surveyed impact position, as well as photographed background buildings as references, the airplane departed controlled flight prior to reaching the mid-point of the 8,000 foot main runway and impacted with the elevator at or near the full airplane nose-up (ANU) position.

A fragment of carbon fiber from the right wing tip was the first fragment of airplane and was found in the first ground contact mark. (See Figure 1) This contact point was located two to three feet from the west edge of a closed runway 18/36 and at the beginning of ground scars leading through the grass toward the resting airplane. The closed parallel runway (18/36) is to the west of the main north/south runway.

---

<sup>1</sup> Photographs copied from various internet sources depicting the flight and impact sequence are attached as Addendum 1.




Figure 1. View toward the airplane from left and right main landing gear tire marks. The first point of ground contact by the wingtip was at the right edge of the photo and is not visible in this view.

A WAAS-enabled GPS and TotalStation® survey equipment used by the Winnebago County Sherriff's Department provided positional data about the debris trail.<sup>2</sup> The location of the first fragment and ground contact was about 4,300 feet from the southern end of the pavement for the main runway that the airplane had been traveling toward. (See Figure 2)

---

<sup>2</sup> Winnebago County reference: S.O.10-2829, Putzer W20



Active Runway 18/36

Closed Runway 18/36

Drainage ditch

Taxiway P

Airplane

Figure 2. Location of airplane with relation to airport features.

The surveyed point of first ground contact was found to be:

43 degrees 58.55 minutes North  
88 degrees 33.45 minutes West

Note: The Group Chairman and Hawker Beechcraft representative assisted the Winnebago County Sherrif's Department conduct the TotalStation survey of the ground markings. Part descriptions entered into the survey were expedited due to impending arrival of severe weather and were later refined, so this report will take precedence in descriptions about parts. When in conflict with this report about survey data, the TotalStation information will take precedence.

The heading of ground scars from the initial impact was 215 degrees. The southwest path of the ground markings and debris from the closed runway led through a low drainage ditch, up a short embankment, and to edge of Taxiway P. Photographs showed that the taxiway had been in use at the time by at least two Cessna 170 airplanes. The accident airplane came to rest in the grass on the east edge of the taxiway, with the nose of the airplane facing the point of first ground contact. (See Figure 3)




Figure 3. Total Station data superimposed upon aerial photo of the airport. The pavement of the active runway is the right edge of the photo and the airplane faces northeast, toward the first marks at the edge of the closed runway 18/36. The tail of the airplane is at Taxiway P. The dashed vertical green lines denote a water-filled drainage ditch. See Appendices for additional detail.

In general, the debris from the left and right sides of the airplane were found on the appropriate left and right sides of the travel path until where the ground was deeply

disturbed on the upslope/downtrack side of the drainage ditch. The nose landing gear doors were found slightly to the left of the centerline of the path near the ditch. Downtrack from the ditch, photos from the accident show the airplane rotate and then move tail first. Corresponding physical debris was the right main landing gear on the left side of the path and the left upper nose baggage door was on the right side of the path.

The order of the following description generally follows the path along the ground.

Perpendicular to the direction of travel and about five to six feet south (to the left) of the first cut was a parallel second cut that also began in the grass. In the second cut was an underwing aerodynamic device that Hawker Beechcraft identified as a vortilon. The vortilons on the accident airplane were only damaged at the outermost installations of the leading edge of the right wing.

The third point of contact with the ground was a comma-shaped tire mark on the edge of the closed runway. The mark led into and displaced gravel that had been at the edge of the closed runway.

Note: The third and fourth points were east of the first point and on the pavement, but still downtrack of the initial impact. These contacts with the closed runway to the east of the first ground contact were due to the width of the debris trail on the angle away from the main runway. See the survey data for more clarity.

Continuing in order along the path, the fourth mark along the ground path was a Z-shaped tire skid, to the left of the centerline of the path toward the resting airplane. This mark on the asphalt had aluminum transfers near the edge of the pavement. To the right of the downtrack end of this mark and in the grass was fairing material from the belly of the airplane, that had been forward of the wing, and marked with part number 390-110198-6025, 7193209. The manufacturer nomenclature for the part number was "Fairing Assembly, Underwing, RH."

Along the path from the runway to the drainage ditch were the right wingtip and light assemblies to the right of center, to the left of center were the left main landing gear door fairing and then the retraction actuator in the grass near the edge of the runway, the belly rotating beacon and surrounding fairing material, to the right were the right wing ice inspection light and landing light, the nose landing gear doors near the centerline of the path, then to the left was the left main landing gear and tire assembly. The wheel and tire assembly from the nose landing gear were found in the drainage ditch.

To the west of the drainage ditch, the upslope dirt had been displaced toward where the airplane was resting on the belly surface. A flap fairing was found, followed by the right main landing gear to the left of the path, and the left nose baggage compartment door on the right side of the path.

## AIRPLANE:

The airplane was found laying on the belly and left wing. Attached to the airframe were the engines, nose radome, tail position light, and left wing tip. No evidence of fire was found. (See figures 4 and 5)



Figure 4. Left side of airplane.



Figure 5. Right side of airplane.

## FUSELAGE:

The majority of the structure was carbon fiber composite material and the following description is generally from forward to aft.

The nose of the airplane had compression damage and tearing near the forward pressure bulkhead, generally oriented between the leading edges of the windshields to the aft end of the nose landing gear box. The right side of the nose had a second compression buckle ahead of this larger damage. The upper portion of the nose landing gear strut remained attached and had been displaced so that the bottom was to the right of the airplane centerline.

The fuselage had been constructed as a large carbon fiber tubular shape and had been mounted above the wing assembly. The tube had bent downward ahead of the wing and near the main cabin door.

The fuselage generally remained intact through the lower portion of the structure. The upper structure had broken apart between the leading edges of the engine pylons, aft of the rear pressure bulkhead.

#### WINGS:

The structural mounting of the fuselage to the wing had been four metal links. The forward two links were visible from the exterior and both were found broken. The fuselage tube was found resting on the wing center section. When the fuselage was lifted with a crane for removal from the grass, the forward edge of the wing hung about a foot lower than normal from the fuselage. (See Figure 6) The bottoms of the wings had scrape marks and black embedded asphalt marks that was similar to the closed runway. (The primary Oshkosh north/south runway is concrete.)



Figure 6. Separated leading edge of left wing root beneath fuselage. (Nose is to the left)

The right wingtip was found on the east side of the drainage ditch and had separated from the wing structure along the rib line that had been immediately inboard of the position light components. The wing had an upward bend at the outboard corner of the outboard flap cutout, to where the second underwing vortilon had been mounted, just inboard of the overwing fuel cap. The vortilon was found in the second of the ground contact scars.



The right wing midflap fairing was not attached to the wing. The part was found on the downtrack/east side of the drainage ditch. The spoilers were found in the stowed positions. The outboard flap and aileron were attached to their respective control and hinge points. The majority of the inboard right flap remained, other than the most inboard portion, which was found on the west side of the drainage ditch.

The left wing, flaps, aileron, and spoiler panels were found relatively intact, other than impact damage to and around the inboard end of the inboard flap.

#### FLIGHT CONTROLS:

Photographs of the airplane prior to ground contact show the flaps down, elevators in the airplane nose up orientation (trailing edge up), and ailerons in the roll-left orientations. The rudder position was initially to the left of center and then near neutral. The wing spoilers were in the stowed positions when photographed in flight.

The elevators were found trailing edge down. The pitch controls could be moved from the cockpit after the accident. There was friction in movement of the elevators and the cockpit control yoke did not freely return to the forward stop when released. The cable route was found impeded by impact damage to surrounding structure in the fuselage. The cables were routed beneath the cockpit floor and exterior examination found where the fuselage had damage from the wing impact along the sub-floor route. The route was also not intact where the tail had separated from the cabin at the leading edge of the engines.

An external indication for pitch trim position in the Model 390 is shown by the relative positions of the horizontal stabilizer with a black painted mark on the vertical stabilizer. The leading edge of the stabilizer was found about a half inch above the center of the black mark, which is an approximate take-off trim setting.

The rudder was found to move freely by hand and the rudder pedals were used to move the rudder fully to the right. Moving toward left from the full right position, the control cables went slack at the break in the fuselage near the engines and disruption of the cable path was found. Holding the cables to account for the broken fuselage, the pedals stopped before reaching the centered position, such that the right pedal remained slightly forward of the left pedal. Further examination found the pedals connected indirectly to the nose steering link assembly at the top of the broken nose landing gear. The steering assembly had broken through the structure of the nose landing gear box and the impeded travel was the stopping point of the rudder pedal movement. (See Figure 7)




Figure 7. Arrow points to the nose steering link assembly broken at the top of the nose landing gear structure. View looks upward.

The rudder trim was found near the faired position when the rudder was centered.

The roll control system was found broken where the wing had separated from the fuselage. The cockpit control yoke could not be moved from slightly left of center. From the left main landing gear well, a slight rocking could be seen at the aileron control quadrant that was crushed between the fuselage and wing. A bellcrank arm was seen broken at the transition to the control tubing in the wing center section. The tube connecting the left and right wing roll controls was intact and the system had continuity through the wings. The left aileron was found near the faired position. The control path was pinched at the upward bend in the right wing and the right aileron was found trailing edge up.

The left aileron trim actuator measured 1.31 inches from the actuator to the bolt centerline. The right aileron trim actuator measured 1.37 inches from the actuator to the bolt centerline. According to Hawker Beechcraft:

When the ROLL TRIM switch on the pedestal is set to NORM and the TRIM switch is depressed and held, the left aileron roll trim surface will move. When the ROLL TRIM switch is set to AUX and the TRIM switch is depressed and held, both aileron roll trim surfaces will move. The pictures taken onsite show the ROLL TRIM switch set to NORM, and the right aileron roll trim surface appears faired. So assuming the right aileron roll trim surface is at 0 degrees, and the

difference in roll trim actuator extension measured is 1/16 inch, the following is determined:

Left Aileron Tab: 3.1 degrees down (left aileron up / left wing down)

The cockpit indicators for the trim and flap positions were electronic and had no indication without power. Power was not applied to the airplane electrical systems, due to the broken wires and leaking fuel.

The wing flaps were found in the fully extended positions (31.8 +/-1.7 degrees nominal) and impact marks were found in the tracks at the fully extended alignments with the flap rollers. The cockpit flap control was found in the fully extended position. The wing flap actuators were measured with the following extensions to the bolt centers. Hawker Beechcraft related the measurements into degrees of flap extension, which came to fully extended flap, as shown by the set of numbers on the right:

	Left flaps: (inches/degrees)	Right flaps: (inches/degrees)
Outboard flap, outboard actuator:	5.75"/31.79 degrees	5.69"/ 30.53 degrees
inboard actuator:	9.25	9.25
Inboard flap, outboard actuator:	9.25"/ 32.77 degrees	9.25"/ 32.77 degrees
inboard actuator:	Damage area	Broken

The wing spoilers were found in the stowed positions and the cockpit lift dump handle was not found extended.

#### ELECTRICAL AND AVIONIC:

In the right nose avionics compartment, the slot was empty for Flight Management Computer #2, an option that this airplane had not been delivered with. The compartment did contain a Honeywell Enhanced Ground Proximity Warning System (EGPWS) with the following markings and summary information from the EGPWS is attached:

Mark V  
Part number 965-0976-040-210-210  
Serial number 22054  
Loadable databases: Terrain, Envelope Modulation  
Mod Status: 1 through 8  
Sticker 132690-12

All cockpit circuit breakers were found the closed (operational) positions.

Extensive wiring damage was seen in the exposed areas where the fuselage was broken between the engines and near the wing.

In the compartment beneath the right engine, a firefighter disconnected the battery. The emergency locator transmitter (ELT) could not be reached at first, so the antenna coax cable was cut and both cables broken to limit transmissions. The switch was turned off at 1:20 am on July 28. Circuit breakers found open were labeled for the:

HYD PRESS IND  
STROBE LT  
L LNDG

The cockpit voice recorder was a Fairchild Model FA2100, marked with:

Part number 2100-1010-51,  
Serial number 000352608,  
MFR 06141  
DMF 112005

Hardware modifications 010, 020, 050

Software PN 840-E1663-040

#### ENGINES:

In multiple amateur videos of the accident, at least one engine can be heard running after the accident. The longest recording heard lasted for 25 seconds after the airplane coming to rest. The engine(s) sounds can be heard shutting down while the main cabin door is shut. The engine power levers were found in the Idle Cut Off (ICO) positions.

Both engines turned freely in the wind as a storm approached. Feeling the rotation by hand, no grinding was felt. No debris was found in either inlet or exhaust and no damage, or discoloration was seen in either exhaust. Both engines had fire fighting foam in the inlets and exhausts when first seen. Neither engine had case ruptures or other penetrations. Both cowlings were found intact, closed, and unremarkable.

After the accident, the inlet of the right engine had small soft body impact marks near the 6 and 12 o'clock positions. Flecks of dirt were adhered to fan blades and one had light scratches that had a brighter look than the surrounding material.

#### SURVIVABILITY, DOORS, AND WINDOWS:

Internet photos and videos show the main cabin door handle ajar after the first impact and a firefighter opening the main cabin door by pulling on the aft edge. The door normally does not have space for fingers along the edges. The pilot comes to the door from the aft cabin area and can be seen to have injuries near his left eye. The pilot exited the airplane

through the main cabin door. Firefighters and other personnel then helped the female passenger from the cockpit.

The main cabin door was open when investigators arrived within a half hour, and the open door could not be fully closed. The top edge of the door was displaced forward and the door did not align with the door opening. The direction of displacement was consistent with the damage to the hinge assembly, along the bottom of the fuselage.

Photos show the overwing exit from the right side of the airplane was closed in flight and open after the initial ground contact. (See Figure 8) The hatch was found inside of the cabin, on the left side second passenger seat, with the latch in the stowed orientation. (See Figure 9)



Figure 8. Cropped section of photo shows the overwing escape hatch opening during the impact sequence.




Figure 9. View toward aft of cabin. The left cabin ceiling is on the left row of seats. The skewed door to the aft lavatory is visible between the seats and the rollers which are normally concealed by the wall are visible. The overwing hatch is visible on a seat.

Prior to this accident, Hawker Beechcraft received reports about opening of overwing exits during ground operations. The hatches are held firmly shut by pressurization during flight. Company review into the previous openings resulted in Premier 1A Communiqué #27, dated August 2010. The communiqué points out that revision A30 of the Premier Airplane Maintenance Manual provides additional rigging instructions.

Both the cockpit and aft lavatory interior doors were designed to slide to one side for concealment behind a side panel (also known as a pocket door style). Each of the interior doors was found off of the rollers and each had to be physically lifted and rattled to move. The cockpit doors had been in the open positions and the aft lav door was in the near shut position, from which it needed to be picked up to open.

The left cabin ceiling had fallen into the occupiable head space of the left cabin seats. (See Figure 9)

#### COCKPIT SEATS:

The cockpit seats were left in the airplane and were not disassembled. Visual inspections to the assemblies beneath and behind the seats revealed no bent components or tubes. The seat positions were measured from the aft corner of the center pedestal. The vertical measurement was to the top of the pan that supports the cushion. The aft measurement was to the centerline of the chrome shafts and seat jackscrews. The cockpit seat adjustment measurements were:

	Vertical:	Aft:
Captain seat:	.75 inches above	9.69 inches
P/N: 390-530151-008 FO 7 (The 8 and 7 were slightly illegible), Manufactured: 6/7/2006 (or 2008)		

	Vertical:	Aft:
First Officer seat:	3 inches below	11 inches aft
P/N: 390-530151-008 FO 7 (The 8 and 7 were slightly illegible), Manufactured: 6/7/2006 (or 2008)		

Detailed examination of exterior photos in the impact sequence showed the cockpit interior through the windshield. The male occupant of the captain seat can be seen with an arm stretched forward of his shoulder. The person in the first officer seat is not similarly visible. (See Figure 10)



Figure 10. Cropped section of an attached photo that shows the airplane colliding with the drainage ditch, showing the captain's arm stretched forward of the shoulder. The person in the first officer seat is not similarly visible. Also shown are displacement of the main cockpit door handle and a fuselage fracture near the forward pressure bulkhead.

The shoulder harness set for the seat of the captain was found to be locked, so that neither strap would extend further when lightly pulled. Each of the harness straps for the captain was brought to the belt buckle and the extensions were about correct to pass over a pilot's shoulders. (See Figure 11)

The shoulder harness on the side of the first officer was not locked, the straps had a fold that was not creased into the material, and the buckles were inverted from a usable orientation. (See Figures 12) None of the shoulder harness sets were disassembled to examine for stretch marks in the webbing.



Figure 11. Shoulder harness of captain seat.



Figure 12. Shoulder harness of first officer seat.

On the ground and in a level attitude, using the shoulder harnesses as a vertical reference, the position of an investigator's head placed the eye level vertically near the center of the windshield. At this vertical position, the view out of the side window placed the eye level near the top of the side window and the top of the head near the track for the window shade. A similar head position can be seen in a marketing photo of the airplane. (See Figure 13)



Figure 13. Cropped marketing photo that shows pilot head positions with respect to the side windows and window track components for orientation in the next two photos.



The sun visor assembly was found oriented vertically, along the aft edge of the window pillar. Blood distribution had silhouetted the visor in the position where it was found. The round adjustment knob for the pilot's sun visor was the highest point at which blood was found. Radiating from this point was a pattern down and forward. (See Figure 14)



Figure 14. Sun visor mounting assembly and adjustment knob, side view, with spray pattern forward of adjustment knob.

At the head position found with the shoulder harnesses and seat adjustment, the sun visor mounting assembly and adjustment knob was approximately in front of the pilot's forehead, near the hairline and above the left eye. (See Figure 15)



Figure 15. Sun visor mounting assembly and adjustment knob, as viewed aft and from above the centerline of the control yoke. The photo is slightly rotated and the dashed line has been added to provide vertical orientation, as copied from the door frame.

A pair of men's prescription sunglasses were found on the floor under the pilot's left knee position and the pair resembled a pair that the pilot was wearing in a newspaper photo. The left lens was found near the captain's cup holder and had blood on it. The frame had the left nose piece crushed and the left hinge was displaced aft.

Across the aisle from the main cabin door was an unused "Airline First Aid Kit," manufactured by DME Corporation, with the following markings:

P/N S6-01-005-312  
Alternate P/N P8-02-0004-307  
Inspected 10/23/08

#### COCKPIT DOCUMENTATION:

Following this are switch and control positions, as well as indications found in the cockpit, generally using the markings nomenclature that was found.

Left radio panel:  
Transmit 1

MIC – NORM  
AUTO – COM  
SPEAKER – Selected upward  
DME – BOTH  
AUDIO – NORM  
MARKER – LOW  
DG - NORM  
CDU – NORM (centered)  
AHRS – NORM (centered)  
PFD/MFD – NORM (centered)

STATIC SOURCE:

Normal

Ice protection panel:

STALL WARN – OFF  
STABILIZER – AUTO  
WING ICE – (both) OFF  
PITOT – (both) ON  
ENGINE ICE – (both) OFF  
WINDSHIELD – OFF

Landing gear handle – down

Antiskid – NORM

Electrical panel – All switches to OFF and rotary switch to EXT (external)

Alternate gear selector red T-handle found extended.

Fuel panel:

Rotary selector – OFF  
BOOST PUMPS – (both) AUTO

Environmental control panel:

Cabin altitude display – Approximately 800 feet  
Differential pressure – zero  
BLEED AIR – NORM  
TEMP selector – CABIN  
TEMP controller (rotational clock nomenclature) – 12:30 position  
Cockpit and cabin blowers – LOW

Right radio panel:

MIC – (both) NORM  
COM – OFF  
SPKR – OFF  
DME – BOTH  
DG - NORM

All three electronic flight displays appear to be intact.  
The Collins NAV/COM radio selector switches found at COM and STDBY  
The pressurization found set to AUTO

Standby airspeed indicator overspeed (barber pole) observed at about 322 knots. Standby attitude indicator OFF flag is in view, with the display at about 10 degrees right roll and 25 degrees down.

Standby altimeter displayed 665 feet and 29.75 Hg.

Across the top of the instrument panel are five push buttons that control the engine fire protection system and firewall shutoff valves. None of the clear covers were displaced or otherwise different than the set in a new Premier that was examined.

The autopilot panel has the engagement switch at the disconnect position.

Of the overhead panel rocker switches, all were found set at OFF, with the following exceptions (ON):

- LIGHTS MASTER
- LANDING LIGHT
- RECOGNITION
- BEACON
- STROBE

Center pedestal:

- Ignition switches – (both) ARM
- ECU – (both) ON
- SYNC – SYNC
- PITCH TRIM – NORM
- Lift dump toggle at UNLOCK
- Lift dump handle stowed
- Flaps handle at full down
- Throttles at Idle Cut OFF, with the left lever found slightly ahead of the right.
- Rudder boost - NORM
- Rudder trim – NORM
- Roll Trim – NORM

#### MAINTENANCE RECORDS:

The manufacturer built the airplane with registration N71761 applied and the Standard Airworthiness Certificate was dated September 20, 2006. The airplane was repainted to enter service with Roush/Fenway Racing LLC (also known as Roush Aviation) on March 26, 2007, with 223.4 flight hours and 146 landing cycles.

The N6JR Certificate of Registration was dated July 18, 2007.

A log page found in the airplane showed that at on July 25, 2010, the airplane had 1264.8 flight hours and the last landing had been number 930. According to the Director of Maintenance for Roush Fenway Racing LLC, the last record at the hangar for the airplane showed 1255 flight hours and 925 takeoff/landing cycles.

The basis of maintenance is defined by 14 CFR Part 91.409. With the exception of unscheduled replacements, such as tires and individual instruments, the majority of the scheduled maintenance was performed by Raytheon Aircraft / Hawker Beechcraft service centers. The majority of the unscheduled items were also released by signatures associated with the service centers or Roush Aviation. No outstanding AD items were found for the time of the accident. The logbook showed compliance with numerous service bulletins, including those not categorized as Mandatory or Recommended.

The airplane logbooks showed the following took place within the six months prior to the accident:

Date	Hours	Cycles	Item
July 17, 2010	1255.0		Last log entry. Replacement of tires.
May 12, 2010	1223.0	899	Replaced autopilot elevator servo.
Feb 16, 2010	1163.1	847	HawkerBeechcraft Services performed 6 pages of inspections and maintenance, including checks specified by the maintenance manual for 200, 400, 600, and 1200 flight hours. Cable tensions were checked and reset. The pitot-static and avionics systems tests were completed for FAR 91.411 and the transponder to 91.413. The standby altimeter was replaced and a pitot-static leakdown test was completed.  Also performed was a Williams Check 1 and Check 2, per FJ44-2A, MM 05-20-00, Table 601. The left engine fuel flow transmitter fittings were retorqued and following seals were replaced: hydraulic pump drive carbon seals (p/n 73312, 66846, and 73312), and Garlock seal (p/n 66846).

The Certification of Conformance was dated March 2, 2006 for each engine. The engines had the same hours and cycles as the airframe.

# APPENDIX A

## PHOTOGRAPHS OF IMPACT SEQUENCE

The following photographs are a collection of samples about the impact sequence that were found on the internet. Where known, attribution has been provided for the original source. However, most are available on multiple websites, so the original source is not known.















Photo by Brian Flanagan



Photo by Brian Flanagan





























# APPENDIX B

ENGINE PERFORMANCE RECORDS  
(INCLUDES ACCELERATION TIMES)

FJ44-2A TURBOFAN ENGINE  
ACCEPTANCE TEST PERFORMANCE SUMMARY  
WILLIAMS INTERNATIONAL CO., L.L.C.

Eng P/N: 56000	Eng S/N: 105233	Eng Bld: 1	Test Date: 03/01/06
Prog Ver: CP173.04	Date: 06/04/02	Acq Ver: CP169.03	Date: 06/15/00
Bellmouth -	Sn: 9314	Cd: 0.987	Dia: 18.80
ATP Doc: 59624 Rev.E	Exh Noz: icn10462	Thrust Tare: 0.8	Test Cell 05
Fuel Type: JETA	Oil Type: mobil jet 2	Pc1: 2.0010	Pc2: 2.0200
LHV: 18598	Spec Grav: 0.7942	Temp Slope: 0.00040800	Dir: 0603010751

ELECTRONIC MODE

TAKEOFF THRUST @ 85 deg PLA (+/- 2 deg., Uncorrected, Uninstalled)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Measured N1	17949 rpm	17895 (min) (fig 5)	0
Recovered FN	2270.7 lbf	2213.8 (min) (fig 6)	0.0
		2324.5 (max)	0.0
ECU TT2 (CED_TT2)	45.0 F	N/A	N/A
ECU Pamb (CED_P0)	12.600 psia	N/A	N/A

PERFORMANCE @ 17800 rpm N1 (Referred to Sea Level, Static, 72F Dry Day, Uninstalled)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Referred ITT	1840 R	1880 (max)	0
Referred FN	2416.5 lbf	N/A	N/A
Referred WA	68.4 lbf/sec	N/A	N/A
Referred N2	39891 rpm	N/A	N/A

PERFORMANCE @ 2339 lbf RATED THRUST (Referred to Sea Level, Static, 72F Dry Day, Uninstalled)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Referred SFC	0.498 lbm/hr/lbf	0.522 (max)	0.000
Referred N1	17605 rpm	N/A	N/A

GROUND IDLE THRUST

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Recovered FN	123.7 lbf	140.0 (max)	0.0

ACCELERATION TIME

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Corrected Time	5.4 seconds	5.7 (fig 14)	0.0
Inlet Temp.	45.6 F	N/A	N/A
Test Cell Pressure	12.612 psia	N/A	N/A

MECHANICAL SYSTEMS PERFORMANCE (Steady-State)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Max Main Oil Temp	170.4 F	275.0	0.0
Min Main Oil Press	41.5 psig	35.0	0.0
Max Main Oil Press	73.5 psig	90.0	0.0

FJ44-2A TURBOFAN ENGINE  
ACCEPTANCE TEST PERFORMANCE SUMMARY  
WILLIAMS INTERNATIONAL CO., L.L.C.

Eng P/N: 56000	Eng S/N: 105233	Eng Bld: 1	Test Date: 03/01/06
Prog Ver: CP173.04	Date: 06/04/02	Acq Ver: CP169.03	Date: 06/15/00
Bellmouth -	Sn: 9314	Cd: 0.987	Dia: 18.80
ATP Doc: 59624 Rev.E	Exh Noz: icn10462	Thrust Tare: 0.8	Test Cell O5
Fuel Type: JETA	Oil Type: mobil jet 2	Pc1: 2.0010	Pc2: 2.0200
LHV: 18598	Spec Grav: 0.7942	Temp Slope: 0.00040800	Dir: 0603010751

MECHANICAL MODE

TAKEOFF THRUST (Referred to Sea Level, Static, 72F Dry Day, Uninstalled)

PARAMETER	ACTUAL	MIN ALLOWABLE	DEVIATION
Referred N1	18252 rpm	N/A	N/A
Referred FN	2630.3 lbf	2522.7 (fig 10)	0.0

IDLE N2 SPEED - PLA in idle detent (17.5 +/- 2 deg)

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Measured N2	23761 rpm	24468 (fig 11)	0
Inlet Temp.	46.4 F	N/A	N/A
Test Cell Pressure	12.612 psia	N/A	N/A

ACCELERATION TIME

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Corrected Time	3.7 seconds	5.7 (figure 14)	0.0
Inlet Temp.	44.8 F	N/A	N/A
Test Cell Pressure	12.611 psia	N/A	N/A

MECHANICAL SYSTEMS PERFORMANCE (Steady-State)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Max Main Oil Temp	172.7 F	275.0	0.0
Min Main Oil Press	45.4 psig	35.0	0.0
Max Main Oil Press	74.3 psig	90.0	0.0

FJ44-2A TURBOFAN ENGINE  
ACCEPTANCE TEST PERFORMANCE SUMMARY  
WILLIAMS INTERNATIONAL CO., L.L.C.

Eng P/N: 56000	Eng S/N: 105233	Eng Bld: 1	Test Date: 03/01/06
Prog Ver: CP173.04	Date: 06/04/02	Acq Ver: CP169.03	Date: 06/15/00
Bellmouth -	Sn: 9314	Cd: 0.987	Dia: 18.80
ATP Doc: 59624 Rev.E	Exh Noz: icn10462	Thrust Tare: 0.8	Test Cell 05
Fuel Type: JETA	Oil Type: mobil jet 2	Pc1: 2.0010	Pc2: 2.0200
LHV: 18598	Spec Grav: 0.7942	Temp Slope: 0.00040800	Dir: 0603010751

VIBRATION SURVEY (PEAK LEVELS)

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Max 1E HP rad vib	0.28 ips @ 37515 rpm	0.85	0.00
Max 1E LP rad vib	0.15 ips @ 17913 rpm	0.37	0.00
Max 1E LP tan vib	0.38 ips @ 16083 rpm	1.00	0.00
Max OA Rear Mt rad vib	0.54 ips @ 17951 rpm	2.50	0.00

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Oil Consumption	<u>.008</u> gal/hr	0.023 (max)	<u>0.0</u>
Engine Dry Weight	<u>505.0</u> lbm	510.5 (max)	<u>0.0</u>

TOTAL ENGINE RUN TIME 2:31

TOTAL ENGINE CYCLES 6.10



ENGINEERING [Signature] Date 3-2-06

Q. A. [Signature] Date 3/2/06 (230)

FJ44-2A TURBOFAN ENGINE  
ACCEPTANCE TEST PERFORMANCE SUMMARY  
WILLIAMS INTERNATIONAL CO., L.L.C.

Eng P/N: 56000	Eng S/N: 105232	Eng Bld: 1	Test Date: 03/01/06
Prog Ver: CP173.04	Date: 06/04/02	Acq Ver: CP169.03	Date: 06/15/00
Bellmouth -	Sn: 9314	Cd: 0.987	Dia: 18.80
ATP Doc: 59624 Rev.E	Exh Noz: icn10462	Thrust Tare: 0.0	Test Cell O5
Fuel Type: JETA	Oil Type: mobil jet 2	Pc1: 2.0010	Pc2: 2.0200
LHV: 18598	Spec Grav: 0.7942	Temp Slope: 0.00040800	Dir: 0602282004

ELECTRONIC MODE

TAKEOFF THRUST @ 85 deg PLA (+/- 2 deg., Uncorrected, Uninstalled)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Measured N1	17948 rpm	17895 (min) (fig 5)	0
Recovered FN	2329.4 lbf	2267.9 (min) (fig 6)	0.0
		2381.3 (max)	0.0
ECU TT2 (CED_TT2)	35.5 F	N/A	N/A
ECU Pamb (CED_P0)	12.573 psia	N/A	N/A

PERFORMANCE @ 17800 rpm N1 (Referred to Sea Level, Static, 72F Dry Day, Uninstalled)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Referred ITT	1821 R	1880 (max)	0
Referred FN	2420.7 lbf	N/A	N/A
Referred WA	68.4 lbm/sec	N/A	N/A
Referred N2	39840 rpm	N/A	N/A

PERFORMANCE @ 2339 lbf RATED THRUST (Referred to Sea Level, Static, 72F Dry Day, Uninstalled)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Referred SFC	0.496 lbm/hr/lbf	0.522 (max)	0.000
Referred N1	17598 rpm	N/A	N/A

GROUND IDLE THRUST

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Recovered FN	123.9 lbf	140.0 (max)	0.0

ACCELERATION TIME

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Corrected Time	5.5 seconds	5.7 (fig 14)	0.0
Inlet Temp.	39.4 F	N/A	N/A
Test Cell Pressure	12.560 psia	N/A	N/A

MECHANICAL SYSTEMS PERFORMANCE (Steady-State)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Max Main Oil Temp	158.6 F	275.0	0.0
Min Main Oil Press	44.3 psig	35.0	0.0
Max Main Oil Press	73.1 psig	90.0	0.0

FJ44-2A TURBOFAN ENGINE  
ACCEPTANCE TEST PERFORMANCE SUMMARY  
WILLIAMS INTERNATIONAL CO., L.L.C.

Eng P/N: 56000	Eng S/N: 105232	Eng Bld: 1	Test Date: 02/28/06
Prog Ver: CP173.04	Date: 06/04/02	Acq Ver: CP169.03	Date: 06/15/00
Bellmouth -	Sn: 9314	Cd: 0.987	Dia: 18.80
ATP Doc: 59624 Rev.E	Exh Noz: icn10462	Thrust Tare: 0.0	Test Cell O5
Fuel Type: JETA	Oil Type: mobil jet 2	Pc1: 2.0010	Pc2: 2.0200
LHV: 18598	Spec Grav: 0.7942	Temp Slope: 0.00040800	Dir: 0602282004

MECHANICAL MODE

TAKEOFF THRUST (Referred to Sea Level, Static, 72F Dry Day, Uninstalled)

PARAMETER	ACTUAL	MIN ALLOWABLE	DEVIATION
Referred N1	18315 rpm	N/A	N/A
Referred FN	2660.9 lbf	2549.4 (fig 10)	0.0

IDLE N2 SPEED PLA in idle detent (17.5 +/- 2 deg)

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Measured N2	23424 rpm	24485 (fig 11)	0
Inlet Temp.	40.6 F	N/A	N/A
Test Cell Pressure	12.553 psia	N/A	N/A

ACCELERATION TIME

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Corrected Time	3.6 seconds	5.7 (figure 14)	0.0
Inlet Temp.	39.6 F	N/A	N/A
Test Cell Pressure	12.558 psia	N/A	N/A

MECHANICAL SYSTEMS PERFORMANCE (Steady-State)

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Max Main Oil Temp	165.1 F	275.0	0.0
Min Main Oil Press	40.7 psig	35.0	0.0
Max Main Oil Press	72.1 psig	90.0	0.0

FJ44-2A TURBOFAN ENGINE  
ACCEPTANCE TEST PERFORMANCE SUMMARY  
WILLIAMS INTERNATIONAL CO., L.L.C.

Eng P/N: 56000	Eng S/N: 105232	Eng Bld: 1	Test Date: 02/28/06
Prog Ver: CP173.04	Date: 06/04/02	Acq Ver: CP169.03	Date: 06/15/00
Bellmouth -	Sn: 9314	Cd: 0.987	Dia: 18.80
ATP Doc: 59624 Rev.E	Exh Noz: icn10462	Thrust Tare: 0.0	Test Cell 05
Fuel Type: JETA	Oil Type: mobil jet 2	Pc1: 2.0010	Pc2: 2.0200
LHV: 18598	Spec Grav: 0.7942	Temp Slope: 0.00040800	Dir: 0602282004

VIBRATION SURVEY (PEAK LEVELS)

PARAMETER	ACTUAL	MAX ALLOWABLE	DEVIATION
Max 1E HP rad vib	0.48 ips @ 39154 rpm	0.85	0.00
Max 1E LP rad vib	0.08 ips @ 17749 rpm	0.37	0.00
Max 1E LP tan vib	0.24 ips @ 17353 rpm	1.00	0.00
Max OA Rear Mt rad vib	0.72 ips @ 17905 rpm	2.50	0.00

PARAMETER	ACTUAL	ALLOWABLE	DEVIATION
Oil Consumption	<u>.004</u> gal/hr	0.023 (max)	<u>0.0</u>
Engine Dry Weight	<u>506.0</u> lbm	510.5 (max)	<u>0.0</u>

TOTAL ENGINE RUN TIME 3:31

TOTAL ENGINE CYCLES 8.63

ENGINEERING

*[Signature]*



Date

3-1-06

O. A.

*[Signature]*

Date

3/2/06 (230)



# APPENDIX C

## DOCUMENTATION FOUND IN AIRPLANE

# AIRCRAFT FLIGHT LOG



A/C UNIT NO. <b>261</b>		A/C REGISTRATION NO. <b>N6JR</b>				OPERATOR OF AIRCRAFT <b>ROUSH</b>				MAINTENANCE BASE <b>Ind/28P</b>			
DATE	FLIGHT FROM → TO	FLT. DUR HRS/THS	ACCUMULATION TOTAL TIME						LAND-INGS THIS FLIGHT	ACCUMULATED TOTAL			CREW PILOT/COPILOT
			AIRCRAFT		ENG. NO. 1		ENG. NO. 2			LANDINGS	ENG. 1 CYCS	ENG. 2 CYCS	
ACCUM. TOTALS BROUGHT FORWARD →			HRS.	THS.	HRS.	THS.	HRS.	THS.	HRS.				THS.
			1249	7	1249	7	1249	7	X	920	920	920	X
7/1	YJP-PAB		1251	6	1251	6	1251	6		921	921	921	ROUSH
7/4	PAB-JQF		1252	8	1252	8	1252	8		922	922	922	ROUSH
7/7	JQF-LOT		1254	3	1254	3	1254	3		923	923	923	ROUSH
7/11	LOT-JQF		1255	9	1255	9	1255	9		924	924	924	ROUSH
7/13	JQF-YJP		1257	1	1257	1	1257	1		925	925	925	ROUSH
7/15	YJP-MIV		1258	4	1258	4	1258	4		926	926	926	ROUSH
7/16	MIV-LOT		1260	0	1260	0	1260	0		927	927	927	ROUSH
7/18	LOT-JQF		1262	2	1262	2	1262	2		928	928	928	ROUSH
7/21	JQF-YJP		1263	5	1263	5	1263	5		929	929	929	ROUSH
7/22	YJP-EXC		1264	2	1264	2	1264	2		930	930	930	ROUSH
7/25	EXC-YJP		1264	8									ROUSH

VOR RECEIVER OPERATION CHECKED IN ACCORDANCE WITH PAR 91.171					COMMENTS	SPECIALIZED CYCLES
DATE	BEARING ERROR		PLACE	SIGNATURE		
	VOR 1	VOR 2				
7/1	267°	267°	US SMB FLW 170	[Signature]		FLIGHT LOG SECTION 3 49

**REGISTRATION NOT TRANSFERABLE**

UNITED STATES OF AMERICA  
DEPARTMENT OF TRANSPORTATION - FEDERAL AVIATION ADMINISTRATION  
CERTIFICATE OF AIRCRAFT REGISTRATION

NATIONALITY AND REGISTRATION MARKS <b>N6JR</b>	AIRCRAFT SERIAL NO. <b>RB-161</b>	This certificate must be in the aircraft when operated.
MANUFACTURER AND MANUFACTURER'S DESIGNATION OF AIRCRAFT <b>RAYTHEON AIRCRAFT COMPANY 390</b> ICAO Aircraft Address Code: 51741545		
I S S U E D  T O	<b>ROUSH FENWAY RACING LLC</b> <b>4600 ROUSH PL NW</b> <b>CONCORD NC 28027-7116</b>	This certificate is issued for registration purposes only and is not a certificate of title. The Federal Aviation Administration does not determine rights of ownership as between private persons.
<b>CORPORATION</b>		
It is certified that the above described aircraft has been entered on the register of the Federal Aviation Administration, United States of America, in accordance with the Convention on International Civil Aviation dated December 7, 1944, and with Title 49, United States Code, and regulations issued thereunder.		
DATE OF ISSUE <b>July 18, 2007</b>	 <b>ADMINISTRATOR</b>	 U.S. Department of Transportation <b>Federal Aviation Administration</b>

Form 8050-3(10/2003) Supersedes previous editions

Certificate of Aircraft Registration from airplane.

UNITED STATES OF AMERICA  
DEPARTMENT OF TRANSPORTATION—FEDERAL AVIATION ADMINISTRATION  
**STANDARD AIRWORTHINESS CERTIFICATE**

1 NATIONALITY AND REGISTRATION MARKS <b>N6JR</b>	2 MANUFACTURER AND MODEL <b>Raytheon Aircraft Company 390</b>	3 AIRCRAFT SERIAL NUMBER <b>RB-161</b>	4 CATEGORY <b>Normal</b>
5 AUTHORITY AND BASIS FOR ISSUANCE This airworthiness certificate is issued pursuant to the Federal Aviation Act of 1958 and certifies that, as of the date of issuance, the aircraft to which issued has been inspected and found to conform to the type certificate therefor, to be in condition for safe operation, and has been shown to meet the requirements of the applicable comprehensive and detailed airworthiness code as provided by Annex 8 to the Convention on International Civil Aviation, except as noted herein. Exceptions: <b>EXEMPTION #6558 Landing Gear Loads</b> <b>#7190 Partial exemption from the requirements of 23.181 (b)</b>			
6 TERMS AND CONDITIONS Unless sooner surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator, this airworthiness certificate is effective as long as the maintenance, preventative maintenance, and alterations are performed in accordance with Parts 21, 43, and 91 of the Federal Aviation Regulations, as appropriate, and the aircraft is registered in the United States.			
DATE OF ISSUANCE <b>R 09/20/2006</b>	FAA REPRESENTATIVE  <b>Mark W. Hanly</b>	DESIGNATION NUMBER <b>G123</b>	

Any alteration, reproduction, or misuse of this certificate may be punishable by a fine not exceeding \$1,000, or imprisonment not exceeding 3 years, or both. THIS CERTIFICATE MUST BE DISPLAYED IN THE AIRCRAFT IN ACCORDANCE WITH APPLICABLE FEDERAL AVIATION REGULATIONS.

FAA Form 8100-2 (8-82) U.S. GOVERNMENT OFFICE 2006-553

Standard Airworthiness Certificate from airplane.

# APPENDIX D



TotalStation Data

Pt	North	East	Elev	Description	RawDat
1	0.000	0.000	0.000	Inst Point	I:54.504,R:0.000,D:0.000
2	25.015	0.000	-0.251	REF	I:54.504,R:0.000,D:006
3	232.229	98.529	-4.568	t	I:54.504,R:60.000,D:006
4	230.252	100.156	-4.524	t	I:54.504,R:60.000,D:006
5	227.693	97.727	-4.645	t	I:54.504,R:60.000,D:006
6	229.408	95.298	-4.650	t	I:54.504,R:60.000,D:006
7	231.140	96.800	-4.595	t	I:54.504,R:60.000,D:006
8	232.236	98.446	-4.628	t	I:54.504,R:60.000,D:006
9	237.876	95.679	-4.579	u	I:54.504,R:60.000,D:006
10	241.288	96.868	-4.650	v	I:54.504,R:60.000,D:006
11	243.682	96.480	-4.651	v	I:54.504,R:60.000,D:006
12	243.711	99.140	-4.515	v	I:54.504,R:60.000,D:006
13	242.743	98.863	-4.556	v	I:54.504,R:60.000,D:006
14	242.487	98.258	-4.549	v	I:54.504,R:60.000,D:006
15	241.319	96.847	-4.600	v	I:54.504,R:60.000,D:006
16	245.409	93.808	-4.649	w	I:54.504,R:60.000,D:006
17	245.345	92.396	-4.640	w	I:54.504,R:60.000,D:006
18	247.382	92.376	-4.632	w	I:54.504,R:60.000,D:006
19	246.588	93.807	-4.583	w	I:54.504,R:60.000,D:006
20	245.468	93.837	-4.567	w	I:54.504,R:60.000,D:006
21	223.874	86.024	-4.702	x	I:54.504,R:60.000,D:006
22	223.137	84.929	-4.654	x	I:54.504,R:60.000,D:006
23	224.137	84.291	-4.667	x	I:54.504,R:60.000,D:006
24	224.836	85.270	-4.679	x	I:54.504,R:60.000,D:006
25	223.864	85.940	-4.667	x	I:54.504,R:60.000,D:006
26	222.466	90.579	-4.866	y	I:54.504,R:60.000,D:006
27	222.351	89.272	-4.675	y	I:54.504,R:60.000,D:006
28	221.117	88.870	-4.647	y	I:54.504,R:60.000,D:006
29	220.445	89.283	-4.881	y	I:54.504,R:60.000,D:006
30	221.200	91.247	-4.745	y	I:54.504,R:60.000,D:006
31	222.451	90.579	-4.843	y	I:54.504,R:60.000,D:006
32	217.134	100.266	-3.861	z	I:54.504,R:60.000,D:006
33	206.972	90.298	-4.575	aa	I:54.504,R:60.000,D:006
34	202.481	89.722	-4.431	bb	I:54.504,R:60.000,D:006
35	200.031	89.787	-4.503	cc	I:54.504,R:60.000,D:006
36	198.659	90.406	-4.458	cc	I:54.504,R:60.000,D:006
37	201.637	94.740	-4.385	dd	I:54.504,R:60.000,D:006
38	180.491	95.503	-4.206	ee	I:54.504,R:60.000,D:006
39	180.761	92.893	-4.311	ee	I:54.504,R:60.000,D:006
40	178.324	92.588	-4.350	ee	I:54.504,R:60.000,D:006
41	177.840	95.213	-4.282	ee	I:54.504,R:60.000,D:006
42	180.383	95.503	-4.229	ee	I:54.504,R:60.000,D:006
43	164.796	99.444	-4.112	ff	I:54.504,R:60.000,D:006
44	160.925	98.207	-4.119	ff	I:54.504,R:60.000,D:006
45	156.979	90.673	-4.304	gg	I:54.504,R:60.000,D:006
46	156.236	90.547	-4.354	gg	I:54.504,R:60.000,D:006
47	155.922	91.453	-4.341	gg	I:54.504,R:60.000,D:006
48	156.154	91.808	-4.353	gg	I:54.504,R:60.000,D:006
49	156.303	92.228	-4.299	gg	I:54.504,R:60.000,D:006
50	157.042	90.754	-4.293	gg	I:54.504,R:60.000,D:006
51	201.875	84.503	-4.517	hh	I:54.504,R:60.000,D:006
52	200.186	84.122	-4.490	hh	I:54.504,R:60.000,D:006
53	199.585	85.611	-4.538	hh	I:54.504,R:60.000,D:006
54	201.464	85.839	-4.429	hh	I:54.504,R:60.000,D:006
55	201.830	84.468	-4.510	hh	I:54.504,R:60.000,D:006
56	184.154	75.084	-4.822	ii	I:54.504,R:60.000,D:006
57	183.427	74.492	-4.619	ii	I:54.504,R:60.000,D:006
58	182.872	75.136	-4.662	ii	I:54.504,R:60.000,D:006
59	183.422	75.456	-4.858	ii	I:54.504,R:60.000,D:006
60	184.122	75.217	-4.783	ii	I:54.504,R:60.000,D:006
61	156.494	70.993	-4.658	jj	I:54.504,R:60.000,D:006
62	158.972	69.816	-4.731	jj	I:54.504,R:60.000,D:006
63	158.361	68.926	-4.784	jj	I:54.504,R:60.000,D:006
64	157.868	68.379	-4.788	jj	I:54.504,R:60.000,D:006
65	158.105	68.095	-4.790	jj	I:54.504,R:60.000,D:006
66	157.826	67.500	-4.811	jj	I:54.504,R:60.000,D:006
67	155.434	68.636	-4.837	jj	I:54.504,R:60.000,D:006
68	156.629	71.023	-4.640	jj	I:54.504,R:60.000,D:006
69	158.941	69.825	-4.743	jj	I:54.504,R:60.000,D:006
70	162.563	65.570	-3.790	kk-hub	I:54.504,R:60.000,D:006
71	165.053	64.057	-4.987	kk-end	I:54.504,R:60.000,D:006
72	201.798	65.914	-4.838	ll	I:54.504,R:60.000,D:006
73	201.423	66.398	-4.834	ll	I:54.504,R:60.000,D:006
74	197.971	63.895	-4.916	ll	I:54.504,R:60.000,D:006
75	198.449	63.344	-4.892	ll	I:54.504,R:60.000,D:006
76	201.808	65.945	-4.879	ll	I:54.504,R:60.000,D:006
77	200.753	70.275	-4.676	mm	I:54.504,R:60.000,D:006
78	201.491	69.997	-4.688	mm	I:54.504,R:60.000,D:006
79	203.631	73.457	-4.604	mm	I:54.504,R:60.000,D:006
80	203.102	73.890	-4.597	mm	I:54.504,R:60.000,D:006
81	200.825	70.268	-4.652	mm	I:54.504,R:60.000,D:006
82	222.078	79.388	-4.466	nn	I:54.504,R:60.000,D:006
83	238.900	87.635	-4.579	oo	I:54.504,R:60.000,D:006
84	209.644	110.585	-3.716	pp	I:54.504,R:60.000,D:006
85	205.018	110.526	-3.665	qq	I:54.504,R:60.000,D:006
86	203.556	111.155	-3.640	rr	I:54.504,R:60.000,D:006
87	199.216	106.576	-3.985	ss	I:54.504,R:60.000,D:006
88	229.890	113.473	-4.044	GOU15	I:54.504,R:60.000,D:006
89	221.040	109.892	-3.971	GOU15	I:54.504,R:60.000,D:006
90	216.627	83.348	-4.571	GOU16	I:54.504,R:60.000,D:006
91	216.137	81.569	-4.670	GOU17	I:54.504,R:60.000,D:006
92	208.297	77.425	-4.628	GOU17	I:54.504,R:60.000,D:006
93	210.733	77.425	-4.622	GOU18	I:54.504,R:60.000,D:006
94	204.087	73.784	-4.604	GOU18	I:54.504,R:60.000,D:006
95	172.284	64.381	-4.940	GOU19	I:54.504,R:60.000,D:006
96	181.260	69.862	-4.763	GOU19	I:54.504,R:60.000,D:006

97	181.983	72.369	-4.679	GOU19	I:54.504,R:60.000,D:006
98	175.475	73.268	-4.732	GOU19	I:54.504,R:60.000,D:006
99	159.009	64.558	-4.994	GOU19	I:54.504,R:60.000,D:006
100	165.316	68.054	-4.862	tt	I:54.504,R:60.000,D:006
101	166.200	66.321	-4.957	tt	I:54.504,R:60.000,D:006
102	165.428	66.013	-4.984	tt	I:54.504,R:60.000,D:006
103	164.144	67.534	-4.908	tt	I:54.504,R:60.000,D:006
104	165.216	68.102	-4.825	tt	I:54.504,R:60.000,D:006
105	188.291	78.271	-4.695	GOU20	I:54.504,R:60.000,D:006
106	208.118	91.111	-4.556	GOU21	I:54.504,R:60.000,D:006
107	205.866	89.507	-4.572	GOU21	I:54.504,R:60.000,D:006
108	208.263	89.621	-4.564	GOU22	I:54.504,R:60.000,D:006
109	221.745	95.836	-4.663	GOU22	I:54.504,R:60.000,D:006
110	418.243	107.451	-4.635	road_edge	I:54.504,R:60.000,D:006
111	169.622	119.366	-3.515	road_edge	I:54.504,R:60.000,D:006
112	19.656	126.805	-3.286	road_edge	I:54.504,R:60.000,D:006
113	18.872	124.293	-3.512	road_edge	I:54.504,R:60.000,D:006
114	-30.787	125.618	-3.199	road_edge	I:54.504,R:60.000,D:006
115	-31.158	128.735	-3.165	road_edge	I:54.504,R:60.000,D:006
116	-111.752	132.579	-2.787	road_edge	I:54.504,R:60.000,D:006
117	-202.881	137.504	-2.282	road_edge	I:54.504,R:60.000,D:006
118	-252.979	139.764	-0.563	road_edge	I:54.504,R:60.000,D:006
119	-257.087	139.958	-0.437	road_edge	I:54.504,R:60.000,D:006
120	-262.520	138.639	-0.156	road_edge	I:54.504,R:60.000,D:006
121	-267.028	136.041	0.014	road_edge	I:54.504,R:60.000,D:006
122	-269.491	133.069	0.154	road_edge	I:54.504,R:60.000,D:006
123	-270.370	130.080	0.189	road_edge	I:54.504,R:60.000,D:006
124	-270.735	128.957	0.189	road_edge	I:54.504,R:60.000,D:006
125	-272.531	128.987	0.192	road_edge	I:54.504,R:60.000,D:006
126	-274.220	97.818	0.262	road_edge	I:54.504,R:60.000,D:006
127	-276.679	44.138	0.629	road_edge	I:54.504,R:60.000,D:006
128	-274.689	43.950	0.621	road_edge	I:54.504,R:60.000,D:006
129	-275.376	31.091	0.853	road_edge	I:54.504,R:72.000,D:006
130	-273.513	23.435	0.918	road_edge	I:54.504,R:72.000,D:006
131	-269.937	15.709	1.000	road_edge	I:54.504,R:72.000,D:006
132	-264.798	7.955	1.156	road_edge	I:54.504,R:72.000,D:006
133	-256.795	-0.423	1.250	road_edge	I:54.504,R:72.000,D:006
134	-248.978	-5.765	1.259	road_edge	I:54.504,R:72.000,D:006
135	-240.947	-10.257	1.249	road_edge	I:54.504,R:72.000,D:006
136	-237.436	-11.099	1.210	road_edge	I:54.504,R:72.000,D:006
137	-230.746	-11.543	1.253	road_edge	I:54.504,R:72.000,D:006
138	-221.791	-11.796	1.148	road_edge	I:54.504,R:72.000,D:006
139	-221.977	-13.960	1.038	road_edge	I:54.504,R:72.000,D:006
140	-162.380	-16.924	1.158	road_edge	I:54.504,R:72.000,D:006
141	-97.931	-20.016	0.978	road_edge	I:54.504,R:72.000,D:006
142	43.250	-26.755	0.508	road_edge	I:54.504,R:72.000,D:006
143	251.671	-36.796	-0.102	road_edge	I:54.504,R:72.000,D:006
144	407.485	-44.327	-0.613	road_edge	I:54.504,R:72.000,D:006
145	168.393	49.016	-4.889	uu	I:54.504,R:72.000,D:006
146	221.881	95.557	-4.743	GOU23	I:54.504,R:72.000,D:006
147	220.791	93.670	-4.650	GOU23	I:54.504,R:72.000,D:006
148	217.885	91.758	-4.725	GOU23	I:54.504,R:72.000,D:006
149	214.070	89.956	-4.678	GOU23	I:54.504,R:72.000,D:006
150	214.580	89.437	-4.659	GOU23	I:54.504,R:72.000,D:006
151	219.862	91.726	-4.646	GOU23	I:54.504,R:72.000,D:006
152	225.679	92.641	-4.669	GOU23	I:54.504,R:72.000,D:006
153	225.979	91.627	-4.721	GOU23	I:54.504,R:72.000,D:006
154	216.274	86.832	-4.611	GOU23	I:54.504,R:72.000,D:006
155	205.992	81.905	-4.613	GOU23	I:54.504,R:72.000,D:006
156	204.088	81.549	-4.585	GOU23	I:54.504,R:72.000,D:006
157	205.311	83.653	-4.495	GOU23	I:54.504,R:72.000,D:006
158	209.757	86.438	-4.582	GOU23	I:54.504,R:72.000,D:006
159	212.664	88.735	-4.575	GOU23	I:54.504,R:72.000,D:006
160	212.552	89.197	-4.576	GOU23	I:54.504,R:72.000,D:006
161	211.034	88.921	-4.600	GOU23	I:54.504,R:72.000,D:006
162	210.725	89.538	-4.600	GOU23	I:54.504,R:72.000,D:006
163	209.288	88.993	-4.601	GOU23	I:54.504,R:72.000,D:006
164	208.940	89.798	-4.556	GOU23	I:54.504,R:72.000,D:006
165	218.979	94.357	-4.707	GOU23	I:54.504,R:72.000,D:006
166	221.938	95.613	-4.756	GOU23	I:54.504,R:72.000,D:006
167	218.978	95.366	-4.666	GOU23	I:54.504,R:72.000,D:006
168	211.261	91.774	-4.618	GOU23	I:54.504,R:72.000,D:006
169	415.021	167.141	-3.833	road_edge	I:54.504,R:72.000,D:006
170	245.367	175.405	-3.096	road_edge	I:54.504,R:72.000,D:006
171	52.834	184.710	-2.413	road_edge	I:54.504,R:72.000,D:006
172	-168.479	194.898	-1.608	road_edge	I:54.504,R:72.000,D:006
173	-216.580	197.620	-1.209	road_edge	I:54.504,R:72.000,D:006
174	-254.155	199.761	-0.392	road_edge	I:54.504,R:72.000,D:006
175	-248.785	109.519	-0.891	sign	I:54.504,R:72.000,D:006
176	-239.593	108.824	-0.948	sign	I:54.504,R:72.000,D:006
177	-307.760	130.830	0.601	road_edge	I:54.504,R:72.000,D:006
178	-309.601	88.777	0.697	road_edge	I:54.504,R:72.000,D:006
179	-348.872	-42.956	2.121	road_edge	I:54.504,R:72.000,D:006
180	-324.986	-44.196	1.977	road_edge	I:54.504,R:72.000,D:006
181	-319.885	-45.970	2.005	road_edge	I:54.504,R:72.000,D:006
182	-316.221	-48.922	1.885	road_edge	I:54.504,R:72.000,D:006
183	-313.149	-53.160	1.660	road_edge	I:54.504,R:72.000,D:006
184	-312.168	-57.395	1.543	road_edge	I:54.504,R:72.000,D:006
185	-312.347	-65.474	1.056	road_edge	I:54.504,R:72.000,D:006
186	-313.051	-78.133	0.505	road_edge	I:54.504,R:72.000,D:006
187	-313.607	-94.227	-0.029	road_edge	I:54.504,R:72.000,D:006
188	-290.027	-96.237	0.023	road_edge	I:54.504,R:72.000,D:006
189	-288.125	-76.851	0.508	road_edge	I:54.504,R:72.000,D:006
190	-287.189	-60.375	1.345	road_edge	I:54.504,R:72.000,D:006
191	-286.394	-56.087	1.549	road_edge	I:54.504,R:72.000,D:006
192	-283.829	-52.356	1.683	road_edge	I:54.504,R:72.000,D:006
193	-280.142	-48.837	1.782	road_edge	I:54.504,R:72.000,D:006


194	-273.237	-46.678	1.868	road_edge	I:54.504,R:72.000,D:006
195	-205.970	-49.909	1.753	road_edge	I:54.504,R:72.000,D:006
196	-47.906	-57.478	1.286	road_edge	I:54.504,R:72.000,D:006
197	-16.691	-58.988	1.156	road_edge	I:54.504,R:72.000,D:006
198	-14.853	-62.214	1.144	road_edge	I:54.504,R:72.000,D:006
199	-13.209	-64.571	1.031	road_edge	I:54.504,R:72.000,D:006
200	-12.941	-66.834	1.013	road_edge	I:54.504,R:72.000,D:006
201	-13.201	-71.065	0.780	road_edge	I:54.504,R:72.000,D:006
202	-13.806	-87.525	0.022	road_edge	I:54.504,R:72.000,D:006
203	-15.366	-119.309	-0.262	road_edge	I:54.504,R:72.000,D:006
204	9.627	-120.130	-0.342	road_edge	I:54.504,R:72.000,D:006
205	10.875	-89.682	-0.076	road_edge	I:54.504,R:72.000,D:006
206	11.682	-70.146	0.867	road_edge	I:54.504,R:72.000,D:006
207	11.716	-67.292	1.028	road_edge	I:54.504,R:72.000,D:006
208	13.314	-64.974	1.006	road_edge	I:54.504,R:72.000,D:006
209	15.220	-62.256	1.088	road_edge	I:54.504,R:72.000,D:006
210	15.941	-61.472	1.066	road_edge	I:54.504,R:72.000,D:006
211	15.930	-60.517	1.093	road_edge	I:54.504,R:72.000,D:006
212	62.734	-62.795	0.963	road_edge	I:54.504,R:72.000,D:006
213	196.960	-69.253	0.496	road_edge	I:54.504,R:72.000,D:006
214	242.230	-54.126	0.317	road_ctr	I:54.504,R:72.000,D:006
215	-205.964	-32.662	1.616	road_ctr	I:54.504,R:72.000,D:006
216	24.970	0.081	-0.247	REF	I:54.504,R:0.000,D:006

WINNEBAGO COUNTY SHERIFF'S OFFICE  
 07-27-10 10-2829 WITTMAN FIELD  
 OSHKOSH, WI BEECHCRAFT PREMIER 1A  
 MEASURED BY: LUKER W45 & PUTZER W20  
 (TOPCON TOTAL STATION GPT3107W)  
 TOPCON FC-120 DATA COLLECTOR)  
 DRAWN BY: D. PUTZER W20 (CRASHZONE 7.5.4)





# OLD RUNWAY 36





# APPENDIX E

Enhanced Ground Proximity Warning System

# NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety  
505 South 336th Street, Suite 540  
Federal Way, Washington 98003



September 21, 2010

EGPWS Examination Report

## A. ACCIDENT

Place : Oshkosh, Wisconsin  
Date : July 27, 2010  
Vehicle : Hawker Beechcraft 390, N6JR  
NTSB Accident Number: CEN10FA443  
NTSB Investigator : Andrew Todd Fox

## B. ATTENDEES

Joshua Cawthra, Aviation Accident Investigator  
National Transportation Safety Board

Bill Pickins  
Honeywell Aerospace

## C. DETAILS OF EXAMINATION

Examination of the Enhanced Ground Warning Proximity System (EGPWS) was conducted at the facility of Honeywell Aerospace, Redmond, Washington, on September 21, 2010. The EGPWS was received in a secure unopened box. The EGPWS unit, a Honeywell Mark V, part number 965-0976-040-210-110, serial number 22054 was removed and examined. The EGPWS unit visually appeared to be undamaged. The unit was disassembled and all internal printed circuit boards (PCB) and memory chips appeared to be undamaged. The EGPWS unit was reassembled and subsequently installed on a test bench. Power was applied to the EGPWS unit, which allowed for any retained data to be extracted. A binary file was successfully downloaded from the flash memory chips within the unit.

The downloaded binary file data was decoded using a company software program. Examination of the downloaded data revealed that the most recent takeoff leg was recorded in flight leg 1001 at a unit operating time of 1847:40:43 from the Willow Run Airport, Detroit, Michigan. A landing record for flight leg 1001 was recorded at a unit operating time of 1848:28:15 at the Wittman Regional Airport, Oshkosh, Wisconsin.

Review of the EGPWS warning log revealed that a Terrain Clearance Alert was recorded at a unit operating time of 1848:28:00. Three bank angle warnings were recorded at unit operating times of 1848:28:11, 1848:28:20, and 1848:28:30 respectively. In

addition, a sink rate and pull up warning was recorded at a unit operating time of 1848:28:32. An additional sink rate warning was recorded at a unit operating time of 1848:28:33.



Photo 1: View of the EGPWS unit as received.



Photo 2: View of the internal PCB that contains the flash memory chips.

Summary

EGPWC CONFIGURATION:  
PART NUMBER: 965-0976-040-210-210  
MOD STATUS: 08  
SERIAL NUMBER: 22054  
  
APPLICATION S/W VERSION: 210.2  
CONFIGURATION S/W VERSION: 210  
TERRAIN DATABASE VERSION: 445  
ENVELOPE MOD DATABASE VERSION: B06  
BOOT CODE VERSION: B101.2

Takeoff Record:

FLIGHT LEG 1001: ( 1847:40:43)  
Lat/Long: 42.23608 / -83.53626  
Geometric Alt: 764.00 True Hdg: -136.41  
GPS Alt: 756.00 VFOM: 80.00  
Pos. Uncert: 0.0125 Pos. Source: GPS1  
Airport: KYIP

Landing Record:

FLIGHT LEG 1001: ( 1848:28:15)  
Lat/Long: 43.98256 / -88.55650  
Geometric Alt: 884.00 True Hdg: -158.91  
GPS Alt: 842.00 VFOM: 76.00  
Pos. Uncert: 0.0107 Pos. Source: GPS1  
Airport: KOSH

Counts

Part Number: 965-0976-040  
Serial Number: 22054  
Mod Status: 08  
Boot Software: B101.2

WARNING COUNTERS:

- 66P - Mode 1 Outer Curve Voice
- 20P - Mode 1 Inner Curve Voice
- 28 - Mode 2 Terrain Voice
- 20 - Mode 2 Pull-Up Voice
- 13 - Mode 3 Voice
- 25 - Mode 4 Too Low Terrain Voice
- 16 - Mode 4 Too Low Gear Voice
- 19 - Mode 4 Too Low Flap Voice
- 5 - Mode 4 C Too Low Terrain Voice
- 254 - Mode 5 Voice
- 50P - Mode 6 Bank Angle Alert
- 19 - Terrain Clearance Floor Voice
- 16 - Terrain Awareness Caution
- 15 - Terrain Awareness Pull-Up
- 3 - Obstacle Caution
- 3 - Obstacle Pull-Up
- 4 - Mode 7 Windshear Warning
- 2 - Mode 7 Windshear Caution
- 0 - Speed Brake Alert
- 0 - Improper Takeoff Flaps

ACTIVITY COUNTERS:

- 32 - Glideslope Cancel
- 999 - Number of Flights
- 4: 27: 55 - GPW INOP Time
- 535: 04: 33 - Windshear INOP Time
- 13: 02: 22 - TA&D INOP Time
- 17: 25: 47 - TA&D Not Available Time
- 2: 09: 33 - Terrain Inhibit Time
- 1268: 31: 21 - Flight Time
- 1848: 30: 19 - Operating Time

PROGRAM PINS:

- 1 - Program Pin 1
- 7 - Program Pin 2
- 2 - Program Pin 3
- 8 - Program Pin 4
- 2 - Program Pin 5
- 2 - Program Pin 6
- 2 - Program Pin 7
- 1 - Program Pin 8
- 1 - Program Pin 9
- 1 - Program Pin 10
- 3 - Program Pin 11
- 1 - Program Pin 12
- 2 - Program Pin 13
- 2 - Program Pin 14
- 1 - Program Pin 15
- 2 - Program Pin 16
- 2 - Program Pin 17
- 1 - Program Pin 18
- 1 - Program Pin 19
- 1 - Program Pin 20
- 1 - Program Pin 21
- 1 - Program Pin 22
- 1 - Program Pin 23
- 1 - Program Pin 24

Counts

Decoded by FLT\_HIST V2.7.3.2 on Tue Sep 21 10:48:47 2010



Line No	Rec ID	Flt Leg	Oper Time	Lat	Long	Pos		CAS	TAS	Gspd	VFOM	Uncorr		Rad Alt	Terr Elv	
						Uncert						Alt	TACAAlt			
10079	DATA	1001	1848:27:40	43.97483	-88.53418	0.0093		143.2	148.2	164.2	70	1318	1346	1344	585.5	800
10080	DATA	1001	1848:27:41	43.97483	-88.53418	0.0093		142	147.5	164.2	70	1318	1336	1344	566.5	800
10081	DATA	1001	1848:27:42	43.97552	-88.53452	0.0093		140.4	145.2	161.6	70	1304	1328	1334	550.8	800
10082	DATA	1001	1848:27:43	43.97621	-88.53487	0.01		138.6	143.2	159.6	74	1294	1316	1322	543.8	800
10083	DATA	1001	1848:27:44	43.97689	-88.53521	0.0093		136.4	140.8	157.5	70	1282	1306	1312	543	800
10084	DATA	1001	1848:27:45	43.97741	-88.53572	0.01		134.2	139.2	154.8	74	1264	1294	1298	523	800
10085	DATA	1001	1848:27:46	43.97861	-88.53675	0.01		133.2	139.6	152	72	1234	1280	1266	490.5	800
10086	DATA	1001	1848:27:47	43.97861	-88.53675	0.01		133.3	140.1	152	72	1234	1266	1266	470.5	800
10087	DATA	1001	1848:27:48	43.97964	-88.53812	0.0098		133.8	140.8	147	72	1194	1246	1228	434.8	800
10088	DATA	1001	1848:27:49	43.97964	-88.53812	0.0098		133.9	140	147	72	1194	1230	1228	394.8	800
10089	DATA	1001	1848:27:50	43.98016	-88.53881	0.0093		132.2	135.7	145	70	1168	1212	1204	403.5	800
10090	DATA	1001	1848:27:51	43.9805	-88.5395	0.0093		130.9	136.9	142.8	70	1144	1196	1180	393.2	800
10091	DATA	1001	1848:27:52	43.98101	-88.54018	0.0093		131	137.4	141.2	70	1128	1178	1162	349	800
10092	DATA	1001	1848:27:53	43.98136	-88.54087	0.0093		131	136.9	139.9	70	1104	1164	1140	335.2	800
10093	DATA	1001	1848:27:54	43.98153	-88.54173	0.0093		130.6	135.9	139.9	68	1084	1152	1122	316	800
10094	DATA	1001	1848:27:55	43.98187	-88.54259	0.01		129.9	135.4	138.4	72	1072	1142	1108	300.8	800
10095	DATA	1001	1848:27:56	43.98239	-88.54414	0.0098		129.6	135.6	135.1	72	1058	1126	1090	288.8	800
10096	DATA	1001	1848:27:57	43.98239	-88.54414	0.0098		129.9	135.7	135.1	72	1058	1114	1090	275.8	800
10097	DATA	1001	1848:27:58	43.9829	-88.54568	0.0093		128.5	132.9	131.5	70	1030	1100	1064	217.5	800
10098	DATA	1001	1848:27:59	43.9829	-88.54568	0.0093		127.2	131.9	131.5	70	1030	1088	1064	215.8	800
10099	TCF	1001	1848:28:00									0x0002	'57:208			
10100	DATA	1001	1848:28:00	43.98307	-88.54636	0.0093		126.1	131.5	129.5	70	1018	1078	1054	231.2	800
10101	DATA	1001	1848:28:01	43.98342	-88.54723	0.0093		124.8	129.4	127.8	70	1008	1070	1044	215.5	800
10102	DATA	1001	1848:28:02	43.98359	-88.54791	0.0093		123.8	129.8	125.9	70	1004	1060	1038	224.8	800
10103	DATA	1001	1848:28:03	43.98376	-88.54877	0.0093		123.5	128.6	123.4	70	994	1052	1030	221.8	800
10104	DATA	1001	1848:28:04	43.98393	-88.54945	0.0093		121.8	126.3	121.2	70	988	1038	1020	205.2	800
10105	DATA	1001	1848:28:05	43.98393	-88.55032	0.0093		118.6	120.8	119.6	70	980	1026	1014	195.8	800
10106	DATA	1001	1848:28:06	43.9841	-88.55169	0.0093		115.4	119.9	116.5	72	954	1010	990	185.2	800
10107	DATA	1001	1848:28:07	43.9841	-88.55169	0.0093		113.7	118.4	116.5	72	954	996	990	182.8	800
10108	DATA	1001	1848:28:08	43.9841	-88.55323	0.01		113.1	118.7	114.4	74	916	982	958	146	800
10128	DATA	1001	1848:28:09	43.9841	-88.55323	0.01		113.4	119.8	114.4	74	916	970	958	131.2	800
10129	DATA	1001	1848:28:10	43.98393	-88.55392	0.0103		113	118.1	112.1	74	896	960	940	104.2	800
10130	M6BA	1001	1848:28:11									0x0002	'57:208			
10131	DATA	1001	1848:28:11	43.98376	-88.55444	0.0103		112	116.9	109.8	74	886	950	930	97	800
10132	DATA	1001	1848:28:12	43.98359	-88.55512	0.0098		111.5	117	106.4	72	876	940	918	84	800
10133	DATA	1001	1848:28:13	43.98325	-88.55563	0.01		110.7	114.1	109.4	74	864	928	906	68.8	800
10134	DATA	1001	1848:28:14	43.98256	-88.5565	0.0107		108.5	113.4	105.9	76	842	914	884	47.2	800

10135	DATA	1001	1848:28:15	43.98256	-88.5565	0.0107	107.9	113	105.9	76	842	908	884	37.5	800
10136	DATA	1001	1848:28:16	43.9817	-88.55684	0.0105	108.9	115.5	106	74	816	906	864	36.5	800
10137	DATA	1001	1848:28:17	43.98136	-88.55701	0.011	109.8	115.7	99.5	78	834	914	878	48.8	800
10138	DATA	1001	1848:28:18	43.98136	-88.55701	0.011	109.4	113.9	99.5	78	834	922	878	65.8	800
10139	DATA	1001	1848:28:19	43.98084	-88.55735	0.0107	108.2	111.4	96.5	76	860	928	896	85	800
10140	M6BA	1001	1848:28:20								0x0002	'57:208			
10141	DATA	1001	1848:28:20	43.9805	-88.55753	0.01	105.5	107.1	92.4	74	880	932	912	105.2	800
10142	DATA	1001	1848:28:21	43.98016	-88.55769	0.0095	101.9	102.2	88.8	72	888	932	924	116.2	800
10143	DATA	1001	1848:28:22	43.97964	-88.55769	0.01	98.2	101.1	87.1	74	898	928	932	117	800
10144	DATA	1001	1848:28:23	43.9793	-88.55769	0.0105	97.8	101.3	86.2	76	894	924	932	105.8	800
10145	DATA	1001	1848:28:24	43.97844	-88.55753	0.0103	97.1	102	83.8	74	882	920	924	96.8	800
10146	DATA	1001	1848:28:25	43.97844	-88.55753	0.0103	97.7	103.1	83.8	74	882	918	924	95	800
10147	DATA	1001	1848:28:26	43.97775	-88.55753	0.0105	97.8	101.6	81.8	76	872	914	912	86.8	800
10148	DATA	1001	1848:28:27	43.97775	-88.55753	0.0105	96.4	98.6	81.8	76	872	910	912	78.8	800
10149	DATA	1001	1848:28:28	43.97741	-88.55735	0.0103	94.2	97.6	80.6	74	864	904	906	68.8	800
10150	DATA	1001	1848:28:29	43.97707	-88.55735	0.0098	94.7	100	79.5	74	848	898	894	63	800
10151	M6BA	1001	1848:28:30								0x0002	'57:208			
10152	DATA	1001	1848:28:30	43.97672	-88.55735	0.0095	95.8	101.1	78.9	72	842	884	886	57.8	800
10153	DATA	1001	1848:28:31	43.97621	-88.55735	0.0095	95.7	98.3	77.5	72	830	866	876	41	800
10154	M1SK	1001	1848:28:32								0x0002	'57:208			
10155	M1PU	1001	1848:28:32								0x0002	'57:208			
10156	DATA	1001	1848:28:32	43.97586	-88.55735	0.0103	89.6	79	76.8	74	812	868	854	*9.8	800
10157	M1SK	1001	1848:28:33								0x0002	'57:208			
10158	DATA	1001	1848:28:33	43.97569	-88.55769	0.011	*65.1	*66.9	80	78	774	*0.0	784	*4.8	800
10159	DATA	1001	1848:28:34	43.97535	-88.55787	0.0103	*65.1	*66.9	83.1	74	748	*0.0	748	*4.8	800
10160	DATA	1001	1848:28:35	43.97518	-88.55804	0.0103	*65.1	*66.9	56.8	74	758	*0.0	758	*4.8	800
10161	DATA	1001	1848:28:36	43.97518	-88.55821	0.0117	*65.1	*66.9	28.6	78	790	*0.0	790	*4.8	800
10162	DATA	1001	1848:28:37	43.97535	-88.55821	0.0107	*65.1	*66.9	20.9	76	796	*0.0	796	*4.8	800
10163	DATA	1001	1848:28:38	43.97535	-88.55804	0.0105	*65.1	*66.9	23.9	76	798	*0.0	798	*4.8	800
10164	DATA	1001	1848:28:39	43.97535	-88.55804	0.0105	*65.1	*66.9	23.9	76	802	*0.0	802	*4.8	800
10165	DATA	1001	1848:28:40	43.97518	-88.55804	0.0105	*65.1	*66.9	7.1	76	788	*0.0	788	*4.8	800
10166	DATA	1001	1848:28:41	43.97518	-88.55804	0.0103	*65.1	*66.9	0.1	74	792	*0.0	792	*4.8	800
10167	DATA	1001	1848:28:42	43.97518	-88.55804	0.0098	*65.1	*66.9	0.2	74	790	*0.0	790	*4.8	800

Alt Rte	Mag		Tru				BAOA	L. Accl	N. Accl	Glides	Loc	Pos Src	SAT	TotShear	Gr	Flp	Apprc	
	Trk	Trk	Tru Hd	Pitch	Roll	Dn									Sel	InAir	h	
-683	-18.2	-13.2	-20.8	-2.1	-23.9	-0.70313	-0.13477	1.15381	*-3.750	0	GPS1	29	-0.02356	1	1	1	1	
-589	-18.2	-13.2	-22.1	-1.4	-27.4	0	-0.12134	1.17322	*-3.750	0	GPS1	29	-0.01929	1	1	1	1	
-608	-19.8	-16.7	-25.2	-2.1	-28.8	-1.40625	-0.14038	1.02734	*-3.828	0	GPS1	29	-0.01355	1	1	1	1	
-695	-24.6	-21.3	-31	-2.1	-31.6	-0.70313	-0.10425	1.18506	*-3.906	0	GPS1	29	-0.01257	1	1	1	1	
-710	-30.3	-25.5	-35.3	-1.4	-33.8	0	-0.09241	1.15466	*-3.906	0	GPS1	29	-0.01489	1	1	1	1	
-742	-34	-28.9	-39.2	-2.8	-29.5	0	-0.10474	1.0863	*-3.984	0	GPS1	29	-0.01868	1	1	1	1	
-815	-43.8	-39.6	-44.9	-4.2	-26.7	-0.70313	-0.11182	1.08923	*-4.062	-0.078	GPS1	29	-0.01074	1	1	1	1	
-897	-43.8	-39.6	-48.7	-4.2	-28.8	-0.70313	-0.12781	1.00378	*-4.141	-0.078	GPS1	29	0.00171	1	1	1	1	
-1105	-51.3	-45.5	-52.9	-2.8	-26.7	-1.40625	-0.1134	1.09399	*-4.219	-0.078	GPS1	29	0.01794	1	1	1	1	
-1050	-51.3	-45.5	-57.3	-3.5	-23.9	0	-0.08826	1.1731	*-4.219	-0.078	GPS1	29	0.02441	1	1	1	1	
-1013	-56.6	-49.2	-61.8	-4.2	-23.2	0	-0.06885	1.12756	*-4.297	-0.078	GPS1	29	0.01709	1	1	1	1	
-941	-59.6	-52.2	-63.1	-3.5	-23.2	0	-0.09119	1.10706	*-4.453	-0.078	GPS1	29	0.00549	1	1	1	1	
-859	-60	-56.3	-64.8	-2.1	-16.9	0	-0.0697	1.20874	*-4.531	-0.078	GPS1	29	0.01147	1	1	1	1	
-510	-63.9	-59.9	-68.6	-2.1	-13.4	1.40625	-0.06836	1.17249	*-4.609	-0.078	GPS1	29	0.01599	1	1	1	1	
-307	-66	-63.5	-69.4	-1.4	-11.3	0	-0.08386	1.05371	*-4.688	-0.078	GPS1	29	0.02234	1	1	1	1	
-384	-65.5	-64.4	-68.8	-2.1	-8.4	-1.40625	-0.11865	0.89343	*-4.766	-0.078	GPS1	29	0.02795	1	1	1	1	
-469	-71.6	-67.4	-72.9	-2.1	-4.9	-0.70313	-0.1123	1.01208	*-4.844	-0.078	GPS1	29	0.03711	1	1	1	1	
-430	-71.6	-67.4	-76.6	-2.1	-7	0	-0.10535	0.9823	*-4.844	-0.078	GPS1	29	0.04761	1	1	1	1	
-442	-73.1	-67.5	-76.5	-0.7	-9.1	0	-0.08423	1.0719	*-4.922	-0.078	GPS1	29	0.04578	1	1	1	0	
-375	-73.1	-67.5	-77.4	0	-7.7	0	-0.0835	1.07532	*-5.000	0	GPS1	29	0.0376	1	1	1	0	
-281	-75.5	-69.8	-80.4	0	-6.3	0	-0.10681	0.953	*-5.000	0	GPS1	29	0.03491	1	1	1	0	
-318	-78.2	-71	-82.1	0	-7.7	0	-0.06555	1.08618	*-5.078	0	GPS1	29	0.03186	1	1	1	0	
-233	-78.6	-71.7	-81.6	-1.4	-9.8	0.70313	-0.10339	0.94543	*-5.078	0	GPS1	29	0.03076	1	1	1	0	
-498	-78.5	-73.2	-83.6	-1.4	-14.8	-1.40625	-0.11047	0.86328	*-5.156	0	GPS1	29	0.03967	1	1	1	0	
-560	-82.7	-75.2	-88.6	0	-21.1	2.10938	-0.01465	1.16492	*-5.156	0	GPS1	29	0.03174	1	1	1	0	
-626	-86.7	-76.9	-90.3	-1.4	-26.7	2.10938	-0.07153	0.92944	*-5.234	0	GPS1	29	0.00757	1	1	1	0	
-926	-94.4	-86.5	-95.4	0	-31.6	2.10938	-0.03186	1.06433	*-5.234	0	GPS1	29	-0.01599	1	1	1	0	
-990	-94.4	-86.5	-101.8	0	-32.3	4.21875	0.00952	1.2915	*-5.312	0	GPS1	29	-0.02783	1	1	1	0	
-835	-110.3	-97.5	-110.9	1.4	-33	5.625	0.01953	1.27173	*-5.312	0	GPS1	29	-0.02563	1	1	1	0	
-733	-110.3	-97.5	-116.7	2.1	-33.8	4.92188	0.04504	1.34741	*-5.391	0	GPS1	29	-0.0144	1	1	1	0	
-636	-117.4	-104	-124.2	2.8	-39.4	6.32813	0.04565	1.32178	*-5.469	0	GPS1	29	-0.0033	1	1	1	0	
-635	-125.4	-113	-132.8	2.8	-41.5	7.73438	0.07019	1.37134	*-5.547	0	GPS1	29	0.00122	1	1	1	0	
-648	-134.6	-121	-142.6	2.1	-43.6	7.03125	0.06775	1.34851	*5.469	0	GPS1	29	0.01025	1	1	1	0	
-718	-144.4	-129	-151.8	2.8	-42.9	7.73438	0.10437	1.30481	*4.531	0	GPS1	29	0.01367	1	1	1	0	
-564	-158.7	-151	-159.9	6.3	-31.6	9.14063	0.17859	1.2782	*4.531	0	GPS1	30	0.00293	1	1	1	0	

-207	-158.7	-151	-163.2	9.8	-12.7	9.84375	0.2738	1.24451	*4.453	0	GPS1	30	0	1	1	1	0
533	-156.3	-170	-160.7	13.4	3.5	9.14063	0.23401	1.30054	*-3.516	0	GPS1	30	0.00391	1	1	1	0
976	-155.4	-166	-159	12.7	-5.6	8.4375	0.12512	1.15405	*-5.625	0	GPS1	30	0.01489	1	1	1	0
979	-155.4	-166	-159.6	11.3	-21.1	4.21875	0.03992	1.021	*-5.781	0	GPS1	30	0.02991	1	1	1	0
670	-158.5	-158	-165.2	9.8	-27.4	2.8125	0.01953	0.97717	*-5.781	0	GPS1	30	0.03748	1	1	1	0
341	-166.1	-161	-173.2	7.7	-30.2	4.92188	0.04211	0.99756	*-5.703	0	GPS1	30	0.02808	1	1	1	0
-30	-173.3	-168	-178.9	6.3	-27.4	5.625	0.03699	0.8988	*-5.703	0	GPS1	30	0.00647	1	1	1	0
-328	-178.4	-172	175.9	4.9	-20.4	7.03125	0.0387	0.96631	*-5.625	0	GPS1	30	-0.01794	1	1	1	0
-472	177.2	176.7	173.2	4.9	-15.5	6.32813	0.04956	0.96765	*-5.625	0.078	GPS1	30	-0.01294	1	1	1	0
-532	177.4	170.1	174.2	5.6	-2.1	7.73438	0.0592	1.00342	*-5.625	0.078	GPS1	30	-0.00696	1	1	1	0
-526	177.4	170.1	173.2	4.9	0	7.03125	0.0376	0.9585	*-5.625	0.078	GPS1	30	0.00452	1	1	1	0
-615	178.6	169.9	173.9	5.6	-0.7	5.625	0.06189	0.96704	*-5.625	0.078	GPS1	30	0.01807	1	1	1	0
-629	178.6	169.9	176.8	7	0.7	8.4375	0.1167	1.03333	*-5.625	0.078	GPS1	30	0.00732	1	1	1	0
-646	-177.9	171.6	-180	6.3	12	11.25	0.08435	0.98218	*-5.625	0.078	GPS1	30	-0.01147	1	1	1	0
-922	-174.5	171.3	-175.8	6.3	33.8	9.14063	0.09888	1.02124	*-5.703	0.078	GPS1	30	-0.00232	1	1	1	0
-1342	-168.1	173.8	-166.2	6.3	44.3	11.25	0.08362	1.0238	*-5.703	0.078	GPS1	30	0.01208	1	1	1	0
-1972	-154.8	-178	-154.2	0	36.6	*16.17188	0.05603	0.75842	*-5.781	0.078	GPS1	30	0	1	1	1	0
-806	-146.6	-173	*-	*24.6	*0.0	*4.92188	*0.00000	*0.35645	*-5.859	*0.078	GPS1	30	0	1	1	1	0
*0.0	-137.3	-154	*-	*55.5	*0.0	*0.00000	*0.00000	*2.60840	*-5.859	*0.078	GPS1	31	0	1	1	1	0
*0.0	-97.9	-147	*-	*71.0	*0.0	*-	*0.00000	*-0.13086	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*102.4	-132	*-	*54.8	*0.0	*-	*0.00000	*0.32422	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*74.5	-96.6	*-	*22.5	*0.0	*-	*0.00000	*1.40332	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*58.9	-38	*-	*3.5	*0.0	*-	*0.00000	*0.96875	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*52.5	-1.2	*-	*2.1	*0.0	*-	*0.00000	*0.98926	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*52.2	33.6	*-	*2.1	*0.0	*-	*0.00000	*0.98535	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*52.2	67.6	*-	*2.1	*0.0	*-	*0.00000	*0.98535	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*52.2		*-	*2.1	*0.0	*-	*0.00000	*0.98438	*-5.859	*0.078	GPS1		0	0	1	1	0
*0.0	*52.2		*-	*2.1	*0.0	*-	*0.00000	*0.98242	*-5.859	*0.078	GPS1		0	0	1	1	0