ACCESSION NUMBER
DATE OF OCCURRENCE : 288796 : 9411

REPORTED BY

: FLC; ; ; ; : FLC, FO; FLC, PIC.CAPT; PERSONS FUNCTIONS

TRACON, AC;

FLIGHT CONDITIONS : VMC REFERENCE FACILITY ID : SFO FACILITY STATE : CA

FACILITY TYPE : TRACON; ARPT;

: OAK; SFO; FACILITY IDENTIFIER : MLG; LRG; AIRCRAFT TYPE

ANOMALY DESCRIPTIONS : IN-FLT ENCOUNTER/OTHER; OTHER;

ANOMALY DETECTOR : COCKPIT/FLC;
ANOMALY RESOLUTION : FLC REGAINED ACFT CONTROL; OTHER;
ANOMALY CONSEQUENCES : FLC/ATC REVIEW;
NAPPATIVE : STRONG WAKE TURB FOLLOWING B757 OF

: STRONG WAKE TURB FOLLOWING B757 ON NARRATIVE

VISUAL APCH TO SFO, REQUIRED FULL AILERON TO MAINTAIN CTL. POS --INBOUND Q B APCH SFO RWY 28R. 095 DEG RADIAL SFO AT OR ABOVE PROFILE ABOUT 18 DME. ALT 7000-6000 FT DSNDING, 160 KIAS ASSIGNED, FLAPS 15 DEGS, NICE DAY, WORKLOAD LOW. WX -- CLR, VISIBILITY 20 PLUS, ATIS WIND CALM. EVENT -- WITH B757 ON TIP TOE APCH TO RWY 28L. 5-7 MI AHEAD, ACFT BEGAN A MODERATE RATE ROLL (CANNOT RECALL DIRECTION) REQUIRING FULL AILERON INPUT TO CTL ACFT ROLL. ACFT

CONTINUED TO ROLL. LARGE THRUST INCREASE APPLIED, SOME RUDDER AND LEVELED OFF. REGAINED IMMEDIATE CTL. REQUESTED AND RECEIVED APPROVAL FOR S TURNS. CHK TWR WINDS (140/ABOUT 6 KTS). REQUESTED RWY 28L (UPWIND) AND LANDED. HAD AVIATION SAFETY INSPECTION (AIRWORTHINESS). AFTER LNDG: ADVISED BAT TRACON TO 1) DESCRIBE SIT AND S TURNS AND RWY 28L REQUEST. 2) RE-EMPHASIZE PLTS CONCERNS REGARDING B757 WAKE TURB. 3) SUGGEST STAGGERING APCH ACFT SO THAT ACFT IMMEDIATELY FOLLOWING B757 IS ON THE UPWIND SIDE. SUGGESTIONS: 1) INVOLVE ATC MORE REGARDING OUR DESIRE TO BE UPWIND (THIS INCIDENT ATIS RPT CALM BUT TWR RPT 140/6 KTS) B-757. 2)

RE-EVALUATE AIM FOR CRITERIA FOR WAKE TURB SEPARATION. WE WERE NEVER CLOSER THAN 5 MI ON TCASII.

MAKE-MODEL NAME : COMMERCIAL FIXED WING; B757 UNSPEC

FAR PART NUMBER : 121;121

SYNOPSIS : WAKE TURB ENCOUNTER BEHIND 757 LNDG ON

PARALLEL RWY.

REFERENCE FACILITY ID : SFO FACILITY STATE : CA DISTANCE & BEARING FROM REF. : 17, E MSL ALTITUDE : 6000,7000