74

```
299779
ACCESSION NUMBER
DATE OF OCCURRENCE
                            9503
                           : FLC; ; ; ;
REPORTED BY
PERSONS FUNCTIONS
                          : FLC.FO; FLC.PIC.CAPT; TRACON,AC; FLC,
    PIC.CAPT;
                            : MXD
FLIGHT CONDITIONS
REFERENCE FACILITY ID
                            : SMO
FACILITY STATE
                            : CA
                           : TRACON; ARPT:
FACILITY TYPE
                          : LAX; LAX;
FACILITY IDENTIFIER
AIRCRAFT TYPE
                           : MIG: WDB;
                          : IN-FLT ENCOUNTER/OTHER; LOSS OF ACFT
ANOMALY DESCRIPTIONS
    CONTROL; OTHER;
                           : COCKPIT/FLC;
ANOMALY DETECTOR
ANOMALY RESOLUTION
                            : FLC REGAINED ACFT CONTROL; FLC RETURNED
    ACFT TO ORIGINAL CLNC OR INTENDED COURSE;
ANOMALY CONSEQUENCES
                            : NONE:
                            : WHILE BEING VECTORED IN-TRAIL FOR LAX.
NARRATIVE
    AN ACR 747-400 WAS VECTORED OVER TOP OF US AND DSNDED IN FRONT.
    SPACING WAS NEVER LESS THAN 8 MI. WE RECEIVED BUFFET AND ROLL FROM
    PREVIOUS ACFT THAT WAS STRONG ENOUGH AT ONE POINT TO INDUCE 45 DEG
    BANK AND DISCONNECT AUTOPLT. CORRECTIVE ACTION: REQUESTED SLOWER
    SPD AND MORE SPACING BEHIND ACFT. ATC REPEATEDLY STATED THAT
    PRECEDING ACFT WAS 8 MI AHEAD. CONTRIBUTING FACTORS: NEWER WING
    DESIGNS PRODUCE WAKE THAT IS POTENTIALLY HAZARDOUS TO LARGER ACFT
    AND IN- TRAIL SPACING BEHIND THESE NEWER ACFT NEEDS TO BE
    REEVALUATED. CALLBACK CONVERSATION WITH RPTR REVEALED THE
    FOLLOWING INFO: AS RPTR AND FLC WERE DSNDING THROUGH 8000 FT THEY
    ENCOUNTERED WAKE TURB FROM A PRECEDING B-747-400 THAT WAS 8 MI
    AHEAD OF THEM. THE TURB WAS STRONG ENOUGH TO ROLL THE ACFT INTO A
    45 DEG BANK. RPTR'S ACFT WAS BEING FLOWN BY AUTOPLT WHICH
    DISENGAGED AS THE ACFT APCHED 45 DEGS OF BANK ANGLE. FLT PATH
   DISPLACEMENT WAS 200 FT. EVENT WAS DISTURBING TO FLC AND PAX.
    AFTER THE 5 SECOND EVENT THE ACFT WAS RIGHTED AND CONTINUED
    UNEVENTFULLY FOR A LNDG. PRECEDING ACFT WAS ALWAYS ANNOUNCED AS 8
    MI AHEAD. THIS DISTANCE WAS VERIFIED BY TCASII.
SYNOPSIS
                            : WAKE TURB ENCOUNTER.
                            : SMO
REFERENCE FACILITY ID
FACILITY STATE
                            : CA
DISTANCE & BEARING FROM REF. : 5,261
                            : 8000,8000
AIRCRAFT INVOLVEMENT
                           : ANOMALY; ANOMALY;
                            : MLG; WDB;
AIRCRAFT TYPE
                            : 2; 2;
CREW SIZE
WINGS, GEAR, SURFACE, ENGINE : LOW, RETRACT, LAND, TURBOJET; LOW, RETRACT,
    LAND, TURBOJET;
NUMBER OF ENGINES
                           : 2; 4;
                           : NON; DISPLAY, NAVCTL;
ADVANCED COCKPIT
OPERATOR ORGANIZATION
                           : ACR; ACR;
OPERATION
                           : PAX; PAX;
FLIGHT PLAN TYPE
                           : IFR; IFR;
                           : DSCNT; APCH, LNDG;
FLIGHT PHASE
SPECIAL ROUTE
                      : A1; A2;
AIRCRAFT HANDLE
```