




# Continental Motors

## ENGINE FIELD INSPECTION REPORT

<b>ENGINE MODEL</b>	E225-8
<b>ENGINE SERIAL NUMBER</b>	35818-D-0-8-R
<b>AIRCRAFT MAKE &amp; MODEL</b>	Beechcraft 35G Bonanza
<b>AIRCRAFT SERIAL NUMBER</b>	D-4863
<b>AIRCRAFT REGISTRATION</b>	N394CW
<b>CMI FILE NUMBER</b>	15-238

<b>NAME</b>	<b>SIGNATURE</b>	<b>DATE</b>
Mike Council		11-17-2015

**ENGINE FIELD INSPECTION REPORT****FILE NUMBER:**

15-238

**ENGINE S/N:**

35818

**PAGE 2 of 19****GENERAL INFORMATION**

<b>EXAMINATION</b>		<b>ACCIDENT DATA</b>	
<b>DATE</b>	10-13-2015	<b>NTSB ACCIDENT #</b>	CEN16FA011
<b>FACILITY</b>	Beegles Aircraft Services	<b>NTSB INVESTIGATOR</b>	Josh Lindberg
<b>ADDRESS</b>	[REDACTED]	<b>FAA INVESTIGATOR</b>	Wesley R. Dollahite
		<b>ACCIDENT DATE</b>	10-13-2015
		<b>ACCIDENT LOCATION</b>	Eaton, Colorado

**ENGINE INFORMATION**

<b>ENGINE POSITION</b>	Single
<b>TOTAL TIME</b>	5288.19 according to NTSB
<b>TIME SOH</b>	479.5 according to NTSB
<b>TYPE &amp; TIME SLI</b>	100 Hour Inspection 5/17/2015
<b>BUILD DATE</b>	Not in record
<b>IN SERVICE DATE</b>	Not in record

**ENGINE FIELD INSPECTION REPORT**

<b>FILE NUMBER:</b>	15-238	<b>ENGINE S/N:</b>	35818	<b>PAGE 3 of 19</b>
---------------------	--------	--------------------	-------	---------------------

**Significant logbook information:**

<b>Subject:</b>	<b>AIRFRAME</b>	<b>ENGINE</b>	<b>PROPELLER</b>
<b>Make:</b>	Beechcraft	Continental	Hartzell
<b>Model:</b>	G-35	E225-8	HC-A2V20-4A1
<b>Serial Number:</b>	D-4863	35818-D-O-8-R	AK837
<b>Times as of Date:</b>	May 7, 2015	May 7, 2015	May 7, 2015
<b>Times Verified By:</b>	Logbook Entry	Logbook Entry	Logbook Entry
<b>Tach Time</b>	778.60	778.60	778.60
<b>Total Time:</b>	5091.00	5288.19	UNK
<b>TSOH:</b>	NA	778.60	70.50
<b>OH Date:</b>	NA	July 7, 1992	December 8, 2011
<b>TSLightOH:</b>	NA	479.50	NA
<b>TSTOH:</b>	NA	87.00	NA
<b>TOH Date:</b>	NA	January 25, 2011	NA
<b>Last Inspection:</b>	Annual	100 Hr.	100 Hr.
<b>Last Inspection Date:</b>	May 7, 2015	May 17, 2015	May 17, 2015

<b>ENGINE NOTES:</b>			
	<i>Major Overhaul</i>	<i>July 7, 1992</i>	<i>0.00</i>
	<i>#4 Cyl replaced</i>	<i>May 3, 1996</i>	<i>147.90</i>
	<i>R&amp;R All Cyl.</i>	<i>June 20, 1997</i>	<i>270.50</i>
	<i>Engine Teardown</i>	<i>February 2, 1999</i>	<i>299.10</i>
	<i>Engine Teardown</i>	<i>February 28, 2002</i>	<i>454.30</i>
	<i>#1 &amp; 3 Cyl replaced</i>	<i>November 11, 2004</i>	<i>556.10</i>
	<i>#6 Cyl replaced</i>	<i>March 3, 2006</i>	<i>566.00</i>
	<i>R&amp;R All Cyl.</i>	<i>November 15, 2007</i>	<i>599.80</i>
	<i>Rehoned All Cyl.</i>	<i>June 19, 2009</i>	<i>626.50</i>
	<i>R&amp;R All Cyl.</i>	<i>January 25, 2011</i>	<i>691.60</i>
	<i>#4 Cyl replaced</i>	<i>April 1, 2013</i>	<i>763.00</i>

**ENGINE FIELD INSPECTION REPORT****FILE NUMBER:**

15-238

**ENGINE S/N:**

35818

**PAGE 4 of 19****Report Summary:**

Search Code(s):

Examination of the engine was performed by the CMI Investigator under supervision of the NTSB Investigator. The inspection of this engine did not reveal any pre-impact anomalies which would have prevented its ability to produce rated horsepower.

**Disposition of engine following exam:** The engine remains at Beegles Aircraft Services until released by the NTSB IIC to the insurance company.

**INSPECTION WITNESSES**

<b>NAME</b>	Mike Council	<b>NAME</b>	Paul Yoos
<b>ADDRESS</b>	██████████ Mobile, Alabama	<b>ADDRESS</b>	██████████ ██████████ Wichita, KS 67206-2556
<b>ORGANIZATION</b>	Continental Motors, ASI	<b>ORGANIZATION</b>	Textron ASI
<b>PHONE</b>	██████████	<b>PHONE</b>	██████████
<b>NAME</b>	Wesley R. Dollahite	<b>NAME</b>	Brad Bigelow
<b>ADDRESS</b>	██████████ ██████████	<b>ADDRESS</b>	██████████ ██████████
<b>ORGANIZATION</b>	FAA, Safety Inspector	<b>ORGANIZATION</b>	NTSB, ASI
<b>PHONE</b>	██████████	<b>PHONE</b>	██████████

**EXTERNAL INSPECTION OF ENGINE**

The engine data tag remained attached to the crankcase. The data tag indicated that the engine was a model E225-8 engine, serial number 35818-D-0-8-R. No mechanical or impact damage was noted on the crankcase halves.

The combination oil tank/ cooler was impact damaged and was removed to gain access to the remaining engine components. The engine oil rod was removed, wiped and reinserted into the oil rod sleeve. The oil rod indicated approximately five quarts of dark, oily substance was contained in the oil sump.

Right and left exhaust components were impact damaged and crushing was noted to the mufflers. The induction system exhibited impact damage. The air box and induction filter separated and were impact damaged.

The engine driven fuel pump separated from the accessory case but remained attached by a fuel hose. The fuel pump housing was impact damaged and could not be rotated manually. The drive coupling and gear were separated and not recovered.

The pressure carburetor was intact and in place with damage noted to the attach pad. The carburetor throttle control and mixture arms remained attached and secured.

## ENGINE FIELD INSPECTION REPORT

FILE NUMBER:

15-238

ENGINE S/N:

35818

PAGE 5 of 19

The aftermarket propeller governor and "T" pad adapter separated from the accessory case due to impact forces. The accessory case housing exhibited impact damage.

The electric starting motor remained attached with a slight amount of impact damage to the rear casing. The engine driven generator remained attached and intact. The engine driven "wet" type vacuum pump remained attached and intact. The air/oil separator was impact damaged. Right and left magnetos remained intact and mounted to the accessory case.



**ENGINE FIELD INSPECTION REPORT**

**FILE NUMBER:**

15-238

**ENGINE S/N:**

35818

**PAGE 6 of 19**



ENGINE FIELD INSPECTION REPORT

FILE NUMBER:

15-238

ENGINE S/N:

35818

PAGE 7 of 19

ENGINE TEARDOWN AND COMPONENT EXAMINATION

EXHAUST SYSTEM

Condition:

Right and left mufflers and right tailpipe were crushed by impact forces but remained attached. The left tailpipe separated. Muffler flame cones were intact.



# ENGINE FIELD INSPECTION REPORT

FILE NUMBER:

15-238

ENGINE S/N:

35818

PAGE 8 of 19

## INDUCTION SYSTEM

Condition:

The induction system was impact damaged but remained attached. The front mounted air box and induction filter was impact damaged





## ENGINE FIELD INSPECTION REPORT

<b>FILE NUMBER:</b>	15-238	<b>ENGINE S/N:</b>	35818	<b>PAGE 9 of 19</b>
---------------------	--------	--------------------	-------	---------------------

### IGNITION SYSTEM

<b>LEFT MAGNETO</b>	Manufacturer: TCM	P/N: S6LN-21	S/N: E189201DR
Condition:	The magneto received impact damage. The bushing cup was cracked. The magneto was removed and manually rotated using a drill motor. Spark was produced to each ignition lead.		



<b>RIGHT MAGNETO</b>	Manufacturer: TCM	P/N: S6LN-???	S/N: Undetermined
Condition:	The magneto did not display damage. The magneto was removed and manually rotated using a drill motor. Spark was produced to each ignition lead. The data decal was damaged and the serial number was not legible.		




## ENGINE FIELD INSPECTION REPORT

<b>FILE NUMBER:</b>	15-238	<b>ENGINE S/N:</b>	35818	<b>PAGE 10 of 19</b>
---------------------	--------	--------------------	-------	----------------------

<b>IGNITION HARNESS</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
-------------------------	----------------------------	-------------------	-------------------

**Condition:** The ignition harness remained intact with the exception of leads to cylinders one and six which were separated. (top sparkplugs)



<b>SPARK PLUGS</b>	Manufacturer: Champion	P/N: REM40E
--------------------	------------------------	-------------

**Condition:** When compared to a Champion "Check A Plug" chart, sparkplugs from cylinder one was "worn out severe", while sparkplugs from cylinders 2, 3, 4, 5 and 6 exhibited "normal" wear signatures. Sparkplugs from cylinders 2, 4, and 6 were wet with oil. Note: the engine was positioned with cylinders 2, 4, and 6 positioned downward for nearly 24 hours.



ENGINE FIELD INSPECTION REPORT

FILE NUMBER:

15-238

ENGINE S/N:

35818

PAGE 11 of 19



# ENGINE FIELD INSPECTION REPORT

<b>FILE NUMBER:</b>	15-238	<b>ENGINE S/N:</b>	35818	<b>PAGE 12 of 19</b>
---------------------	--------	--------------------	-------	----------------------

## FUEL SYSTEM

<b>FUEL PUMP</b>	Manufacturer: Thompson Products, Inc.	P/N: M128983A	S/N: 444249W
Condition:	The engine driven fuel pump separated from the accessory case but remained attached by a fuel hose. The fuel pump housing was impact damaged and could not be rotated manually. The drive coupling and gear were separated and not recovered.		



<b>CARBURATOR</b>	Manufacturer: Bendix	P/N: PS-5C	S/N: 772805
Condition:	The pressure carburetor was intact and in place with damage noted to the mounting flange. The fuel screen was removed and a small quantity of contamination was noted. No fuel was released from the carburetor during the bench inspection. The carburetor throttle control and mixture arms remained attached and secured.		



**ENGINE FIELD INSPECTION REPORT**

**FILE NUMBER:**

15-238

**ENGINE S/N:**

35818

**PAGE 13 of 19**



**LUBRICATION SYSTEM**

<b>OIL SCREEN</b>	Manufacturer: TCM	P/N:A25131
Condition:	A small amount of carbon was found on the screen surface.	



## ENGINE FIELD INSPECTION REPORT

FILE NUMBER:

15-238

ENGINE S/N:

35818

PAGE 14 of 19

### OIL TANK/ COOLER

Manufacturer: Undetermined

P/N: Undetermined

S/N: Undetermined

Condition:

The combination oil tank and cooler was impact damaged



## CYLINDERS

Condition:

All six cylinders remained intact and in place with little or no impact damage. All six cylinders displayed orange paint on each mounting pad indicating that the internal cylinder barrels were "channel chrome" plated. All six cylinders achieved thumb compression when the engine was manually rotated. . A lighted borescope inspection was performed and all exhaust and intake valves were noted to be intact. Cylinder rocker covers were removed and rocker arm movement was noted when the crankshaft was manually rotated.



**ENGINE FIELD INSPECTION REPORT**

**FILE NUMBER:**

15-238

**ENGINE S/N:**

35818

**PAGE 15 of 19**



# ENGINE FIELD INSPECTION REPORT

FILE NUMBER:

15-238

ENGINE S/N:

35818

PAGE 16 of 19

## CRANKSHAFT ASSEMBLY

<b>CRANKSHAFT</b>	Forging Number: Undetermined	S/N: Undetermined	Heat code: Undetermined
Condition:	The crankshaft appeared to be undamaged. Continuity was established by manually rotating the engine and observing timing gear, magneto and camshaft rotation.		

## ACCESSORIES

<b>STARTER</b>	Manufacturer: Delco Remy- Serviced by EMI Aviation Parts	P/N: Undetermined	S/N: Undetermined
Condition:	The starter motor was impact damaged.		





# ENGINE FIELD INSPECTION REPORT

<b>FILE NUMBER:</b>	15-238	<b>ENGINE S/N:</b>	35818	<b>PAGE 17 of 19</b>
---------------------	--------	--------------------	-------	----------------------

<b>ALT/GEN #1</b>	Manufacturer: Delco Remy	P/N: 11018885	S/N: 5428
<b>Condition:</b>	The engine driven generator remained attached and intact		



<b>VACUUM PUMP</b>	Manufacturer: Garwin	P/N: G45?	S/N:2260
<b>Condition:</b>	The engine driven "wet" type vacuum pump remained attached and intact. The air/oil separator was impact damaged.		



**ENGINE FIELD INSPECTION REPORT**

<b>FILE NUMBER:</b>	15-238	<b>ENGINE S/N:</b>	35818	<b>PAGE 18 of 19</b>
---------------------	--------	--------------------	-------	----------------------

**PROPELLER**

<b>PROPELLER GOVERNOR</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
Condition:	The aftermarket propeller governor and "T" pad adapter separated from the accessory case due to impact forces.		
<b>PROPELLER</b>	Manufacturer: Hartzell	M/N: HC-A2V20-4A1/V8433	S/N:AK847
Blade 1 S/N:	87993		
Blade 2 S/N:	85703		
Condition:	<p>Blade A remained attached to the propeller hub but was loose in the hub assembly. Blade A displayed heavy scratching and scoring on the cambered face and the blade displayed a smooth rearward bending signature beginning approximately 16 inches from the blade root.</p> <p>Blade B separated from the hub and exhibited a smooth forward bending signature beginning approximately eight inches from the blade hub. There was a deep gouge on the trailing edge approximately five inches from the blade tip.</p>		



**ENGINE FIELD INSPECTION REPORT**

**FILE NUMBER:**

15-238

**ENGINE S/N:**

35818

**PAGE 19 of 19**

