

| | | | | | |
|-------------------|---------------|---------|-----------|------------|----|
| Post-it® Fax Note | 7671 | Date | 4/29 | # of pages | 15 |
| To | Geo. Peterson | From | S. Wilson | | |
| Co./Dept. | NTSB | Co. | Cessna | | |
| Phone # | | Phone # | | | |
| Fax # | 5666 | Fax # | 1816 | | |

| Item No. | | No. | No. | | Page No. |
|----------|---------------------|-----|-----|----------------------------|----------|
| 1. | General Information | 1 | 9. | Weather Data | 6 |
| 2. | Summary | 1 | 10. | Airplane History | 6 |
| 3. | Flight Data | 2 | 11. | Wreckage Data | 7 |
| 4. | Occupants | 3 | 12. | Narrative | 11 |
| 5. | Crew History | 3 | 13. | Field Modifications | 15 |
| 6. | Mishap Site | 4 | 14. | Wreckage Disposition | 15 |
| 7. | Mishap Data | 4 | 15. | Investigative Participants | 15 |
| 8. | Wreckage Diagram | 5 | 16. | Attachments | 16 |

DRAFT COPY
GENERAL INFORMATION

Year 1976 Model 421C Serial Number 421C0138 Registration Number N3911C

Mishap Date 9/2/95 Mishap Time 1215 MST Mishap Location Phoenix, AZ

Cessna Investigator Stephen T. Wilson Engine Manufacturer Teledyne Continental

Registered May Industries, Inc. Operator Same as owner.
Owner 3640 West Osborne
Phoenix, AZ 85019

2 SUMMARY

The pilot, flying alone, was on short final approach to Runway 7R at the Deer Valley Airport in Phoenix, Arizona, when four air traffic tower controllers observed the aircraft turn left and descend into a commercial lot. Other witnesses observed the aircraft roll right and left before descending into the ground. The aircraft was destroyed and came to rest along the airport perimeter road. Fire erupted immediately. The pilot and one person on the ground were fatally injured. The temperature was 101° Fahrenheit, and density altitude was approximately 4,700 feet. The aircraft was almost entirely consumed by the post-mishap fire. Subsequent examinations of the airframe, engines, and propellers revealed no evidence of pre-mishap conditions that were attributed to the cause of the mishap. Symmetrical damage to both propellers, including chordwise scoring and substantial twisting and bending, was observed. Subsequent autopsy toxicology analysis of the pilot revealed "mild focal patchy bronchopneumonia" and "therapeutic amounts" of diphenhydramine, a chemical ingredient of common over-the-counter drugs. According to the NTSB, other drugs were detected by the Civil Aeromedical Institute in Oklahoma City, although their report was not complete at the time of this report. Alcohol was not detected.

LEGEND: UNK = Unknown N/A = Not Applicable
 N/R = Not Reliable N/O = Not Obtainable
 D = Destroyed

3. FLIGHT DATA

Type of Flight: Local X Cross Country _____
 PIC/Solo _____ Dual _____
 Purpose: Pleasure _____ Business _____
 Instruction _____ Air Taxi _____
 Practice _____ Other (Specify) _____

Flight Plan Filed? ☐ Yes ☒ No Type of Flight Plan _____

Departure Point Deer Valley, AZ (DVT) Date 9/2/95 Time _____

Destination DVT ETA _____ ETE _____

Routing UNK Altitude _____

Weather Briefing? Prior to takeoff? ☐ Yes ☒ No ☐ Unknown Method of Briefing _____

After takeoff? ☐ Yes ☒ No ☐ Unknown

Last Known Refueling Location: Westwind Aviation, DVT, 6/19/95

Amount of Fuel Added 103.6 gallons Type of Fuel Added 100LL

Amount of Fuel at Takeoff UNK Estimated Amount of Fuel at Occurrence _____

Center of Gravity Within Limits At Takeoff ☒ Yes ☐ No Inches _____

At Occurrence ☒ Yes ☐ No Inches _____

Gross Weight Within Limit At Takeoff ☒ Yes ☐ No Pounds _____

At Occurrence ☒ Yes ☐ No Pounds _____

Baggage Number/Description of Items None observed.

Weight _____ Arm _____

4. OCCUPANTS

| Seat | Name | Address | Status | Age | Injury |
|------|------------------|------------------|--------|-----|--------|
| 1 | Charles Gene May | Peoria, AZ 85345 | PIC | 59 | Fatal |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

DRAFT COPY

5. CREW HISTORY

Name Charles Gene May Date of Birth Seat Occupied 1
 Certificate No. Date Issued 1/28/87 Type of Medical III Date Issued 7/19/94
 Limitations Corrective lenses for near and distant vision.
☐ ATP ☒ Airplane ☒ SE Land
☐ Commercial ☐ Rotorcraft ☐ SE Sea
☒ Private ☐ Glider ☒ ME Land
☐ Student ☒ Instrument ☐ ME Sea
☐ Flt Instructor ☐ Other
☐ Other ☐ Type Ratings
 (See Narrative for details on 'Other' and 'Type Ratings')
Flight Time
 Total Time 879.2 SE 112.5 ME 762.0 PIC 747.5
 Actual Instrument 21.9 Dual 218 Day 852.4 Night 288
 Simul. Instrument 24.5 This Model Last 90 Days Last Biennial 3/22/94
 Source of Information ☒ Logbook ☐ FAA ☒ NTSB ☐ Other

Name Date of Birth Seat Occupied
 Certificate No. Date Issued Type of Medical Date Issued
 Limitations
☐ ATP ☐ Airplane ☐ SE Land
☐ Commercial ☐ Rotorcraft ☐ SE Sea
☐ Private ☐ Glider ☐ ME Land
☐ Student ☐ Instrument ☐ ME Sea
☐ Flt Instructor ☐ Other
☐ Other ☐ Type Ratings
 (See Narrative for details on 'Other' and 'Type Ratings')
Flight Time
 Total Time SE ME PIC
 Actual Instrument Dual Day Night
 Simul. Instrument This Model Last 90 Days Last Biennial
 Source of Information ☐ Logbook ☐ FAA ☐ NTSB ☐ Other

6. MISHAP SITE☐ On Airport ☒ Off Airport Elevation 1,480 ft. MSLLatitude 33° 41' N Longitude 112° 5' W**Terrain Features**☒ Level ☐ Rolling ☐ Hilly ☐ Mountainous ☐ Wooded ☐ Plowed Field☐ Crops ☐ Brush ☐ Swamp ☐ Desert ☐ Water ☒ City Area☐ Other (specify) _____**Conditions of Terrain**☒ Hard ☒ Dry ☐ Soft ☐ Wet ☐ Snow Covered☒ Other (specify) Paved commercial lot**Light Conditions**☒ Day Remarks _____☐ Night Remarks _____**DRAFT COPY****7. MISHAP DATA****Obstacles Struck Before Principal Impact**☐ Wires ☐ Trees ☐ Brush ☐ Buildings ☒ None☐ Other (specify) _____**Approximate Attitude at Impact**

Pitch _____ Roll _____ Yaw _____

Flight PathMagnetic Heading 360° Vertical Angle _____

8. WRECKAGE DIAGRAM

Elevation: _____

Latitude: _____

Longitude: _____

Terrain Profile: _____

The wreckage was recovered prior to the arrival of the writer.

DRAFT COPY

9. WEATHER DATA

Weather at Nearest Reporting Point

Location Deer Valley ATCT Time 1217 MST

Cloud Cover Clear Visibility 30 Temperature 101°F

Dew Point 51°F Wind Direction 130° Wind Velocity 5 knots Altimeter Setting inHg

Remarks Aircraft mishap

Estimated Weather at Accident Site

Cloud Cover _____ Visibility _____ Temperature _____ °F

Dew Point _____ °F Wind Direction _____ Wind Velocity _____ Altimeter Setting _____ inHg

Mishap Site Weather Data Source Same as above.

Remarks _____

DRAFT COPY

10. AIRPLANE HISTORY

Year 1976 Model 421C Serial Number 421C0138 Registration Number N3911C

Airframe Total Time at Occurrence UNK hours Airframe Total Time at Last 100-hr Inspection _____ hours Date _____

Airframe Total Time at Last Periodic Inspection UNK hours Date 12/20/94

| | Manufacturer | Model | Serial Number | Total Time | Total Time Since New or Overhaul |
|--------------|--------------|-------------|---------------|------------|----------------------------------|
| #1 Engine | TCM | GTSIO-520-L | 246013-R | | |
| #2 Engine | TCM | GTSIO-520-L | 272089-R | | |
| #1 Propeller | McCauley | 90UMB-0 | 783225 | | |
| #2 Propeller | McCauley | 90UMB-0 | 783221 | | |

| | | | | |
|-----------------------------------|---------|----------------|---------|--------|
| #1 Propeller Blade Serial Numbers | Blade 1 | K56995 | Blade 2 | K57064 |
| | Blade 3 | K57442 | Blade 4 | |
| #2 Propeller Blade Serial Numbers | Blade 1 | K56991 | Blade 2 | K57458 |
| | Blade 3 | K57444 missing | Blade 4 | |

Source of Information ☒ Logbooks ☒ Parts ☐ Other (specify) _____

Flight Manual on Board? ☒ Yes ☐ No ☐ Unk Logbooks on Board? ☒ Yes ☐ No ☐ Unk

Last Pitot/Static System Check UNK

11. WRECKAGE DATA

| Communication and Navigational Aids | | | | Engine Instruments | | |
|--|--------------------------|--------------------------|------|--------------------------------|---------------|-----------|
| | On | Off | Freq | | #1 Engine | #2 Engine |
| COM 1 | <input type="checkbox"/> | <input type="checkbox"/> | | Hourmeter | | |
| COM 2 | <input type="checkbox"/> | <input type="checkbox"/> | | Tachometer - RPM | 0 | 0 |
| DME | <input type="checkbox"/> | <input type="checkbox"/> | | Tachometer - Hours | | |
| ADF | <input type="checkbox"/> | <input type="checkbox"/> | | Manifold Pressure | 28.5" | 28.5" |
| NAV 1 | <input type="checkbox"/> | <input type="checkbox"/> | | Cylinder Head Temp | OSB | OSB |
| NAV 2 | <input type="checkbox"/> | <input type="checkbox"/> | | Oil Pressure | >0 <10 | 0 |
| RNAV | <input type="checkbox"/> | <input type="checkbox"/> | | Oil Temperature | OSB | OSB |
| Loran | <input type="checkbox"/> | <input type="checkbox"/> | | Fuel Pressure | | |
| GPS | <input type="checkbox"/> | <input type="checkbox"/> | | Exhaust Gas Temperature | | |
| Autopilot | <input type="checkbox"/> | <input type="checkbox"/> | | Turbine Inlet Temperature | | |
| Transponder <input type="checkbox"/> Off <input type="checkbox"/> Sby <input type="checkbox"/> On <input type="checkbox"/> Alt | | | | Ammeter | | |
| Flight Instruments | | | | Environmental Controls | | |
| | Left | Right | | Voltmeter | | |
| Airspeed Indicator | 0 | 80 | | Vacuum Pressure | Red | Red |
| Altimeter | 2,500 | | | Fuel Pressure | OSL | OSL |
| Altimeter Setting | | | | Oil Temperature | | |
| Directional Gyro | 330° | 130° | | N1 Tachometer | | |
| Heading Bug | 185° | | | N2 Tachometer | | |
| Vertical Speed Indicator | +1,100 | +250 | | Pressurization Controls | | |
| Attitude Indicator (pitch) | 10° Dn | Slit up | | Cabin VSI | 0 | |
| Attitude Indicator (roll) | 65° L | 5° L | | Cabin Altitude | < 2,000 | |
| Turn & Bank Indicator (Needle) | 1/2 std R | | | Differential Pressure | 0 | |
| Turn & Bank Indicator (Ball) | Left | | | Pressurization Safety Valve | Pressurize on | |
| Turn Coordinator (Airplane) | | | | Pressurization Dump Valve | | |
| Turn Coordinator (Ball) | | | | | | |
| Magnetic Compass | | | | | | |
| NAV1 OBS | 170° | | | | | |
| NAV2 OBS | | | | | | |
| RNAV Bearing | | | | | | |
| RNAV Distance | | | | | | |
| Clock | | | | | | |
| Fuel Management | | | | | | |
| | Left | Right | | | | |
| Fuel Quantity (Main Tanks) | 25 lbs. | D | | | | |
| Fuel Quantity (Aux Tanks) | | | | | | |
| Fuel Quantity Gauge Selection | | | | | | |
| Fuel Selector Handles | D | D | | | | |
| Fuel Selector Valve | Off | Off | | | | |

| Ignition and Electrical Switches | | | | Engine Control Positions (Engine) | | | |
|----------------------------------|-----|-------|-----|------------------------------------|-----------|-----------|------------|
| Left | | Right | | #1 Engine | | #2 Engine | |
| On | Off | On | Off | | | | |
| Magnetos (#1 Engine) | | X | | | | | |
| Magnetos (#2 Engine) | X | | X | | | | |
| Ignition | | | | | | | |
| Alternator/Generator | X | | X | | | | |
| Fuel Boost Pumps | | X | | | | | |
| | | | | Throttle | | | |
| | | | | Power Lever | | | |
| | | | | Emer Power Lever | | | |
| | | | | Mixture Control | | | |
| | | | | Fuel Control Unit | | | |
| | | | | Propeller Governor | | | |
| | | | | Cowl Flaps | | | |
| | | | | Carburetor Heat | | | |
| | | | | Alternate Air | | | |
| | | | | Inertial Separator | | | |
| | | | | | | | |
| | | | | Engine Control Positions (Cockpit) | | | |
| On | | Off | | #1 Engine | | #2 Engine | |
| | | | | | | | |
| Master Switch | X | | | Throttle | Full | | Full |
| Avionics Switch (#1) | X | | | Power Lever | | | |
| Avionics Switch (#2) | | | | Emer Power Lever | | | |
| Inverter Switch (#1) | | | | Mixture Control | Full rich | | Full rich |
| Inverter Switch (#2) | | | | Fuel Condition Lever | | | |
| Pitot Heat | | | X | Propeller Control | High RPM | | Back 1/2" |
| Navigation Lights | | | X | Cowl Flaps | | | |
| Rotating Beacon (s) | | | | Carburetor Heat | | | |
| Landing Lights | | | X | Alternate Air | | | |
| Taxi Lights | | | X | Primer | | | |
| Strobe Lights | X | | | Inertial Separator | | | |
| Instrument Lights | | | | | | | |
| Stall Heat | | | X | | | | |
| | | | | | | | |
| Icing Equipment | | | | Landing Gear and Flap Positions | | | |
| On | | Off | | Up | | Down | |
| | | | | | | | |
| Surface De-Ice | | | X | Left Main | | | |
| Surface Anti-Ice | | | | Right Main | | | |
| Windshield De-Ice | | | | Nose Gear | | | |
| Windshield Anti-Ice | | | X | Gear Selector | N/R | | |
| Propeller Anti-Ice | | | X | Gear Actuator | | | |
| Propeller De-Ice | | | | | | | |
| Propeller Sync/Phase | | | | Left Flap | | | |
| Autofeather | | | | Right Flap | | | |
| | | | | Flap Indicator | | | 30° |
| | | | | Flap Actuator | | | |
| | | | | Flap Selector | | | Btwn 0&15° |

| Flight Controls | | Aircraft Damage Assessment | |
|---|-------------------------|-----------------------------|-----------|
| | Continuity Established? | | |
| Rudder | No | Engine #1 | Destroyed |
| Elevator | No | Engine #2 | Destroyed |
| Ailerons | No | Propeller #1 | Destroyed |
| Flaps | No | Propeller #2 | Destroyed |
| Rudder Tab | No | Fuselage | Destroyed |
| Elevator Tab | No | Wing Center Section | Destroyed |
| Aileron Tab | No | Tailcone | Destroyed |
| | Position? | Left Wing | Destroyed |
| Rudder Tab | Actuator: 2.7" | Right Wing | Destroyed |
| Elevator Tab | Actuator: 1.7" | Left Flap | Destroyed |
| Aileron Tab | | Right Flap | Destroyed |
| Rudder Tab Indicator | D | Left Aileron | Destroyed |
| Elevator Tab Indicator | D | Right Aileron | Destroyed |
| Aileron Tab Indicator | D | Left Horizontal Stabilizer | Destroyed |
| Remarks | | Right Horizontal Stabilizer | Destroyed |
| DRAFT COPY | | Left Elevator | Destroyed |
| | | Right Elevator | Destroyed |
| | | Vertical Stabilizer | Destroyed |
| | | Rudder | Destroyed |
| | | Aileron Tab | Destroyed |
| | | Rudder Tab | Destroyed |
| | | Elevator Tab | Destroyed |
| | | Left Main Gear | Destroyed |
| | | Right Main Gear | Destroyed |
| | | Nose/Tail Wheel | Destroyed |
| Miscellaneous Information | | | |
| Dual Controls Installed? | Yes | | |
| Oxygen installed? | Yes | | |
| De-Ice Boots Installed? | Yes | | |
| Certified into known icing? | Yes | | |
| Emergency Locator Transmitter Information | | | |
| ELT Installed | UNK | | |
| ELT Type | | | |
| ELT Serial Number | | | |
| ELT Battery Due Date | | | |
| ELT armed? | | | |
| ELT activated? | | | |

| Seats | | | | | | | | | |
|--------|--------------------------|--------------------------|--------------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|--|
| Seat # | Seat Feet Intact? | | Seat Back Intact? | | Seat Base Intact? | | Seat Rail Intact? | | |
| | Yes | No | Yes | No | Yes | No | Yes | No | |
| 1 | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |

| Lap Belts | | | | | | Shoulder Harnesses | | | | | | | | |
|-----------|--------------------------|--------------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|-------------------------------------|-------------------------------------|--------------------------|--------------------------|--|
| Seat # | Used? | | | Intact? | | Used? | | | Intact? | | Installed? | | | |
| | Yes | No | Unk | Yes | No | Yes | No | Unk | Yes | No | Yes | No | Unk | |
| 1 | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |

DRAFT COPY

| Aircraft and Occupant Configuration | | | | | | | | | |
|-------------------------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|----------|--|--|--|
| Seat # | Occupied? | | Seat Orientation? | | | Comments | | | |
| | Yes | No | Fwd | Aft | Side | | | | |
| 1 | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | |
| | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | | | | |

Note: Further descriptions of the seats, lapbelts, and shoulder harnesses may be found in 12. Narrative under Seats/Restraint Systems/Cabin Environment

12. NARRATIVE

HISTORY OF FLIGHT

The pilot, owner of May Industries, was flying alone during day VFR conditions. According to NTSB Investigator, George Petterson, the pilot's wife knew her husband was at the Deer Valley Airport in north Phoenix, Arizona, cleaning their company owned aircraft, but she did not know he was going to fly. The pilot contacted the Deer Valley Air Traffic Control Tower and reported 15 miles northwest of the airport inbound for landing. The pilot was instructed to enter a left base for Runway 7R. The tower controller observed the aircraft turn onto final approach approximately one mile out. After the aircraft was established on final, four air traffic controllers observed the aircraft turn left and descend into a commercial lot. Other witnesses observed the aircraft roll right and left before descending into the ground. The aircraft was destroyed and came to rest beneath utility lines along the airport perimeter road, North 19th Avenue. Fire erupted immediately. Temperature was 101° F. Density altitude was approximately 4,700 feet.

INJURIES TO PERSONS

32 year-old, Robert Glen Jones, [REDACTED] Phoenix, AZ, [REDACTED] was closing a gate at the close of business at the commercial lot when the mishap occurred. Witnesses observed Mr. Jones being involved by the fire and rushed to his assistance. The Phoenix Police Department report indicated Mr. Jones received burns on 92% of his body. He was taken to Maricopa County Medical Center in critical condition. According to insurance adjuster, Bob McMullin, Mr. Jones succumbed to his injury the next morning when life support was removed. Mr. McMullin also advised that Mr. Jones was a superintendent for his father's business, C.S. Construction.

The pilot was fatally injured. The Maricopa County Medical Examiner's autopsy report reads, "Autopsy revealed extensive thermal burns and evidence of smoke inhalation with soot in the airway. The heart was enlarged and microscopic study of the heart showed old fibrosis. Microscopic sections of the lungs showed mild focal patchy bronchopneumonia as well as soot inhalation. Carbon monoxide level was 8%, which was too low for carbon monoxide toxicity." The report listed the cause of death as smoke inhalation and thermal burns. Maricopa County toxicology detected "therapeutic amounts" of diphenhydramine, a chemical ingredient of drugs such as Bufferin, Excedrin P.M., Benadryl, Tylenol PM, and Unisom. According to NTSB Investigator Petterson, other drugs were detected by the Civil Aeromedical Institute in Oklahoma City, although their report was not complete at the time of this report. Alcohol was not detected.

INVESTIGATION

The writer traveled to Phoenix on the evening the mishap occurred. Before his arrival the aircraft was recovered from the site and taken to Air Transport, a Phoenix aircraft salvage company, at the direction of NTSB Investigator Petterson. Per Mr. Petterson's instruction, the writer met FAA Inspector Larry Jones and AlliedSignal Engineer Mike Cummings at the Air Transport facility the following morning for a post-salvage examination of the wreckage. Murle Williams, of Air Transport, assisted. Following the examination at Air Salvage, the writer drove to the mishap site and took photographs.

Damage to Aircraft: The entire aircraft was thermally destroyed, although the cockpit area remained generally intact for the purpose of examination. Switch positions on the electrical console were examined after debris was carefully removed. The annunciator panel and landing gear position lights were removed for NTSB examination. Cabin structure aft of the wing area was not present except for the cabin door and adjacent door structure. The outboard section of the left wing stub was not present. The inboard section of the wing stub was swept aft and detached at the forward attach

point. The right wing stub remained attached to the fuselage. Attached to the right wing stub were the following: a portion of the right engine nacelle, the air conditioner hydraulic pump, the landing gear hydraulic pump, the right turbo system, the a fuel pump, a portion of the right induction system, and the right fuel metering valve. A lower outboard section of the left wing including the wing tip was present. The left aileron was present, and exhibited comparatively less thermal damage. Other major sections of the wings were not found. The tailcone was not present. Only the most inboard sections of the empennage remained.

Landing Gear and Flaps: All three landing gear were detached from the aircraft structure. Both lower main landing gear struts were detached from the upper trunions. The left main wheel assembly and lower strut were not thermally damaged. The left main gear door was present. The nose wheel assembly appeared to have burned from the strut. The nose strut drag link remained attached to the upper trunion and was bent, forming an acute angle. Neither flap was present, nor the adjacent wing structure. The flap actuator was present but detached from airframe structure. Neither flap chain was engaged in the actuator cogs.

Left Engine and Propeller: The left engine exhibited thermal damage and sooting throughout. The accessories remained attached, except the propeller governor was detached from the left forward side. Both magnetos were thermally destroyed. All ignition leads appeared in place except one left lead was cut. The outboard side of the oil cooler was melted away. The exhaust risers on the right side appeared intact. The left exhaust risers were crushed upward. The induction system was burned away. The propeller hub remained attached to the engine with two propeller blades (K57442 and K56995) in place, but loose. The pitch change links were detached from the blades. The outboard half span of blade K57442 was melted away. It exhibited diagonal scoring and no leading edge damage in the inboard section. It was bent aft in the root section and forward in the most outboard section. Blade number K56995 was curled aft about 180° in the outboard section. It exhibited some leading edge damage and chordwise scoring which was greatest within 4 inches of the tip. Blade number K57064 was detached from the hub and exhibited very similar deformation to two of the right propeller blades, except it was sooted and burned in appearance. See description of the right propeller, below.

Right Engine and Propeller: Like the left engine, the right engine exhibited thermal damage and sooting throughout. The alternator, starter, vacuum pump, propeller governor, and magnetos remained attached. The hydraulic pumps were detached. As previously reported, the hydraulic pumps remained attached to the right wing stub. The ignition leads appeared in place. The induction manifold was in place. The right induction tubes were melted away. The left tubes were intact, but detached from the manifold. The right side exhaust risers were crushed upward. The left side exhaust risers were intact. The propeller hub was broken from the engine, except the aft wall of the hub remained bolted to the crankshaft flange. Two of the right propeller blades (K57458 and K57444) were present and detached from the hub. The third right blade was missing. As mentioned above, the two right blades and the detached left blade were very similar in appearance. They were each curled aft and twisted (toward low pitch). Each blade exhibited heavy chordwise scoring in the outboard third span on the cambered surface. Blade K57458 exhibited no fire damage. Blade K57444 was sooted.

Seats and Seat Belts: The left front seat remained attached to the cabin floor. It was partially burned. The lap belt was unclasp. The male fitting was evenly sooted. The female lap belt fitting left a burn shadow on the seat cushion. See photograph 3-AIDN-1. The shoulder harness was not attached to the lap belt fitting.

SUBSEQUENT EXAMINATIONS

On October 5, 1995, both engines were disassembled and examined at the Teledyne Continental Motors (TCM) Analytical facility in Mobile, Alabama, under the supervision of NTSB investigator Tom Wilcox. TCM's inspection reports are included as Attachment 8 to this report. It should be noted that the engines were mismarked as received. Throughout the TCM reports, the left engine as-written

should be right, and the right engine as-written should be left. In summary, no evidence of discrepancy was noted with either engine that was attributed to the cause of the mishap.

At the direction of NTSB Investigator Petterson, the turbocharger system was examined on October 17, 1995, at the AlliedSignal Aerospace Equipment Facility in Torrance, California. AlliedSignal Engineer Mike Cummings reported, "no pre-existing were found that would prevent normal operation." According to Mr. Cummings, rub marks were present in both turbochargers which evidenced rotation at the moment of the mishap.

On October 24, 1995, the writer met NTSB Investigator Tom Wilcox; FAA Inspectors Bruce Smith and John Sills; Allied Signal Investigator Mike Cummings; and McCauley Engineers Tom Knopp and Wayne Edmonds for a propeller examination at Air Transport in Phoenix. By examining deformation to the butt-end of the propeller blades, Mr. Knopp determined that the right propeller was in an operating position, but he was not able to determine the blade angle. According to Mr. Knopp, the left propeller was in a low pitch operating position indicated by damage to the butt-end of blade K56995. A copy of Mr. Knopp's report to NTSB Investigator Petterson is included as Attachment 7 of this report. In the conclusion section of the report, Mr. Knopp stated, "...All propeller damage was of the type associated with impact forces, with gross deflections, was of sudden failure type, and there were no indications of any type of fatigue failure. ...Blade bending and overall propeller damage was of the type and extent indicative of power at impact, with blade bending damage similar for each propeller indicating symmetrical power."

According to NTSB Investigator Petterson, no information was obtained from the NTSB examination of annunciator panel and landing gear position lights.

CREW INFORMATION

DRAFT COPY

The pilot's logbook indicated he completed a biennial flight review on March 22, 1994, which included 1.5 hours of flight. In February, 1995, the pilot logged three flights with instructor Harry Oliphant. Investigator Petterson talked with Mr. Oliphant who reported the pilot was "behind the aircraft." In addition to seven flights logged in 1995, the pilot's wife advised Mr. Petterson of one flight to Bullhead City on June 10, 1995. Flight times listed on Page 3 of this report were taken from the pilot's logbook. It was noted that columns of total day flight plus total night flight did not equal total "duration of flight." According to Mr. Petterson the pilot began flying on November 10, 1981, and started his multi-engine flying on August 9, 1982. Copies of the last page of the pilot's logbook and a copy of his medical certificate application were provided by Mr. Petterson. They are included as Attachment 3 of this report.

AIRCRAFT INFORMATION

A copy of invoices pertaining to the aircraft were provided by Mr. Petterson, and are included as Attachment 4 of this report. The last annual inspection was performed by Alberto Marin, an employee of Sawyer Aviation, on his own time. According to Mr. Petterson, Mr. Marin worked "out of his car." Mr. Marin billed May Industries for 69 hours labor which included the following in addition to the inspection: both oil and air filters were changed, the left main wheel was replaced, the right and nose gear uplock actuators were resealed, the left landing light motor and gears were replaced, and the fuel inlet valves in both wings were replaced. A copy of Mr. Marin's written statement is included in Attachment 4 of this report. The pilot logged 17.3 hours in addition to the one known unlogged trip to Bullhead City since the date of the annual inspection.

The following notes were taken from the burned remains of the aircraft logbooks during the propeller examination on October 24, 1995:

- Tag - Krisley Welding Inc., Repair station number NJ3R712L, 3450 Swetzer Rd., Loomis, CA, 95650, 916-652-5891.
- 1986 logbook entry, Time 539.3.