



## Continental Motors, Inc. Component Analysis Report

N/R = Not Reported / N/A = Not Applicable


Exhibit #:	N/A	Analytical Date:	04/10/2014
Warranty Claim #:	N/A	RMA/AV-18 #:	N/A
Engine Model:	IO-550-B39	Engine S/N:	684677
Component P/N:	655469B	Component S/N:	AC04AB154
Engine:	Component: <input checked="" type="checkbox"/> New: <input type="checkbox"/>	Rebuilt: <input type="checkbox"/>	Overhaul: <input type="checkbox"/> Date: <input type="text"/>
Aircraft Make/Model:	Beech A36	Aircraft S/N:	E-3380 Reg. #: N999PK
Engine Position:	Single-Engine		
Engine Build Date:	11/22/2000	Date in Service:	03/06/2001 Date Removed: N/A
Date of Occurrence:	05/28/2013		Engine/Component Hours: 893.2
Inspection Performed By:	Phillip Grice, Greg Eastburn, and Nicole Charnon, with Ralph Hicks (NTSB)		Search Code: 59-01-34

**Components Returned:** #5 Cylinder

**Returned By:** Mike Huhn

### Analytical Report:


The visual examination of the cylinder revealed that the exhaust valve displayed a localized yellow-green discoloration on a 1/3<sup>rd</sup> of its circumference, indicative of a burnt valve condition. No other anomalies with the cylinder were visually noted. The dimensional examination of the cylinder revealed that the exhaust valve guide was wider than the new part limits toward the valve head (bell-mouthing). The exhaust valve stem was narrower than new part limits toward the valve head (necking). There were no anomalies noted with the valve tips or rocker faces. Some guide wear and valve necking is considered normal and the extent is usually dependent on total time and operating conditions.



It should be noted that the engine was built in 2000 and the #5 cylinder was built in 2004. The total time listed for the engine and airframe during the last annual inspection (June 1, 2012) was 893.2 hours. However, the total time accrued on cylinder #5 is unknown, as maintenance records have not been located for the accident airplane.


The cause for exhaust valve burning could not be determined.





Cylinder P/N:	655469B	Head Date and S/N:	1-04, AC04AB154	Position:	5	
DIMENSIONAL EXAMINATION						
Component	A - 0°	A - 90°	B - 0°	B - 90°	C - 0°	C - 90°
Intake Valve	0.4336	0.4345	0.4337	0.4336	0.4335	0.4336
Intake Guide	0.4365	0.4350	0.4357	0.4358	0.4356	0.4358
Exhaust Valve	0.4335	0.4334	0.4329	0.4329	0.4319	0.4314
Exhaust Guide	0.4374	0.4374	0.4375	0.4382	0.4454	0.4434
Intake valve stem diameter, new limits = 0.4330 - 0.4340						
Intake valve guide inside diameter, new limits = 0.4350 - 0.4362 (installed in cylinder)						
Exhaust valve stem diameter, new limits = 0.4334 - 0.4341						
Exhaust valve guide inside diameter, new limits = 0.4370 - 0.4380 (installed in cylinder)						

VISUAL EXAMINATION	
Intake Valve Tip	The intake valve tip displayed a normal circular wear pattern. Some mechanical damage was noted on the edges and was likely a result of valve removal at the salvage facility.
Intake Valve Seat	The intake valve seat displayed uniform seating signatures with a small amount of seat recession.
Intake Valve Face	The intake valve face displayed a dark sooty appearance consistent with the rest of the cylinder head and likely a result from the post-crash fire and heat damage. There were little-to-no combustion deposits on the intake valve face.
Exhaust Valve Tip	The valve tip displayed a normal circular wear pattern. Some coked oil residue was noted on the valve tip in an area in which the rocker was not touching the valve tip. No other anomalies were noted.
Exhaust Valve Seat	The exhaust valve seat displayed signs of seat recession in the area behind the discoloration. Minute cracks were also visible in the recession area.
Exhaust Valve Face	The exhaust valve face displayed a localized yellow-green discoloration over 1/3 of its outside circumference, consistent with a burned valve.



New Part Tolerances	Diameter Middle of Ring Travel	Diameter Top of Ring Travel
	5.247 - 5.250	5.244 - 5.247
Cylinder Bore Diameters – Cylinder #5		
Measurement Location	Vertical Plane - Inches	Horizontal Plane - Inches
Bottom of Ring Travel	5.2522	5.2516
Middle of Ring Travel	5.2525	5.2499
Top of Ring Travel	5.2523	5.2480