

To <u>DOUG TWINHAM</u>	From <u>B.T. STEWART</u>
Co.	Dept / Sta. <u>563/ATL</u>
Dept. / Sta.	Phone # <u>4-1096</u>
Fax # <u>5-1165</u>	Fax # <u>4-3304</u>

0412-20334 sticker 7/93

FILE CODE: 32-40  
March 17, 1993*Barry*

TO: Supervisor - FAA/NTSB Liaison

FROM: Manager - Mechanical Engineering

SUBJECT: Condition of Wheels, Brakes and Tires removed from Ship 678

Per your request, the following describes the condition of the wheels, brakes, and tires removed from ship 678 after landing in FLL.

Wheels and Tires

The two wheel/tire assemblies removed from the inboard side of the right-hand main landing gear (positions 3 and 7) showed signs of being overheated. Much of the tread and sidewall were discolored and there was some melting of the rubber where it came in contact with the wheel. In addition, the thermal fuse plugs in both wheels were blown.

The two wheel/tire assemblies removed from the outboard side of the right-hand main landing gear (positions 4 and 8) had skidded completely through the carcass, resulting in a blowout. There are no signs of excessive heat soak into the wheel or tire.

Brakes

All four brakes were removed from the right-hand main landing gear (positions 3, 4, 7, and 8). The brake removed from position 7 showed signs of overheating, as evidenced by the bulged pistons and accelerated oxidation on the pressure plate. One of the pistons had ruptured. In addition, one of the disk drive blocks had fractured and separated from the carbon disk. The bulged pistons were most likely caused by softening of the metal due to heat soak from the carbon disks into the brake head. The brake removed from position 3 also showed signs of excessive heat, although no pistons were bulged. Brakes removed from positions 4 and 8 showed no signs of excessive heat or any abnormalities.

After initial examination of the wheels, brakes, and tires, Engineering believes the skidded tires had locked up sometime during the landing, due to anti-skid system failure possibly due to electrical power loss which occurred upon contact with the runway. The other two tires on the right-hand main landing gear were then required to support all weight and braking loads, thus causing the overheat condition. The bulged pistons most likely occurred after the landing, and were the result of heat soak into a pressurized brake.

The wheels brakes and tires are currently on hold in Dept. 391 and await your word to begin teardown and further investigation. Should you have any questions, please do not hesitate to contact me.

Original signed by:  
Joseph C. Kilpatrick

Joseph C. Kilpatrick

JCK/BTS:wc

filename: Ship678

JUL 30 1993

*HAASB*  
*FOLLOW UP ON*  
*WHEELS & BRAKE*  
*SEE PG. 3*  
*Joe 5/3*

*[Redacted Signature]*  
*[Redacted Signature]*  
DATE: May 3, 1993

TO: Staff Manager - Aircraft Maintenance - Shops  
FROM: Technical Analyst - Component Shops *DBD*  
SUBJECT: Report on A/C 678: Findings of Wheels and Brakes

As per your request, I have reviewed the shop findings of the tires, wheels and brakes removed from aircraft 678, right main landing gear on February 23, 1993, in FLL. After detailed disassembly, inspection and analysis of these findings in Department 391 - Wheel and Brake Shop, Maintenance believes the follows events took place upon landing:

Upon landing, the two outboard tires (positions #4 & #8) locked up possibly due to anti-skid system failure caused by the possible momentary loss of electric power as a result of the hard landing. The two outboard tires skidded through the casings and blew as a result. The two inboard tires (positions #3 & #7) then were required to provide all braking from the right main landing gear as well as support of the aircraft. During the landing roll-out, excessive heat built up in the two inboard brake assemblies resulting in an overheat condition. The two inboard wheel and brake assemblies suffered extensive heat damage caused by heat soak into the pressurized brakes after stopping the aircraft. The two outboard brakes suffered no damage. The status of the Anti - Skid and Auto - Brake systems is not indicated in the flight data recorder information supplied to Delta's Performance Engineering by the NTSB.

A detailed summary of the shop findings is attached for your review.

*[Redacted Signature]*  
David DeSantis

Attachments:

Shop Findings Summary  
Figure A

cc: General Foreman - Aircraft Maintenance Support - Shops  
Foreman - Department 391 - Wheel & Brake Shop

## Aircraft 678 Shop Findings Summary

\*\*\*\*\*

The following is a detailed breakdown of the shop findings.  
The right main landing gear positions are numbered as follows:

# 3 - Forward Inboard

# 4 - Forward Outboard

# 7 - Rear Inboard

# 8 - Rear Outboard

# 3 - Forward Inboard: Vendor S/N - QB 070  
DAL S/N - DL 842

## Tire:

- \* Received in shop flat due to melting of the thermal fuse plugs that melt at 390 degrees Fahrenheit (3 each per inner wheel half)
- \* Shows signs of overheating by discoloration of sidewall and tread, also by some melting of the rubber where it contacts the wheel

## Wheel Assembly:

- \* Shows signs of overheating by discoloration of finish
- \* Thermal fuse plug melted due to overheating
- \* Both wheel halves failed NDT hardness tests as a result of overheating (scrapped)

## Brake Assembly:

- \* Shows signs of excessive heat build-up in all brake assembly components (Ref. Figure A)
- \* Torque tube discolored and warped (scrapped)
- \* Heat shields delaminated (burned)
- \* Spreader plate warped by excessive heat and failed NDT eddy current test (scrapped)
- \* No pistons damaged in brake housing assembly
- \* No torque plate (brake housing) damage per NDT
- \* Temp sensor tested and returned to service

## Aircraft 678 Shop Findings Summary

\*\*\*\*\*

# 7 - Rear Inboard: Vendor S/N - QB 081  
DAL S/N - 840

## Tire:

- \* Received in shop flat due to melting of the thermal fuse plugs that melt at 390 degrees Fahrenheit (3 each per inner wheel half)
- \* Shows signs of overheating by discoloration of sidewall and tread, also by some melting of the rubber where it contacts the wheel

## Wheel:

- \* Shows signs of overheating by discoloration of finish
- \* Thermal fuse plug melted due to overheating
- \* Both wheel halves failed NDT hardness tests as a result of overheating (scrapped)

## Brake Assembly:

- \* Shows signs of excessive heat build-up in all brake assembly components (Ref. Figure A)
- \* Torque tube discolored and warped (scrapped)
- \* Heat shields delaminated (burned)
- \* Pistons bulged in all seven positions in brake housing. #3 piston ruptured due to internal pressure build-up (Ref. below & Figure A-A)

## Piston diameters at largest point:

(all measurements taken starting at quick disconnect fitting proceeding clockwise, Max. allowable diameter: 1.373 in.)

Piston #1 - 1.401  
#2 - 1.514  
#3 - 1.085  
#4 - 1.525  
#5 - 1.467  
#6 - 1.428  
#7 - 1.382

Hole blown in side

- \* Spreader plate warped by excessive heat and failed NDT eddy current test (scrapped)
- \* No torque plate (brake housing) damage per NDT
- \* Temp sensor tested and returned to service

I HAVE NEVER  
SEEN THIS  
BEFORE. THE  
HOLE LOOKED  
LIKE A RUPTURED  
BLISTER.

for  
5/3

## Aircraft 878 Shop Findings Summary

\*\*\*\*\*

# 4 - Forward Outboard: Vendor S/N ~ QB089  
DAL S/N ~ 843

## Tire:

- \* Skidded through casing and blown

## Wheel:

- \* No damage found to wheel assembly
- \* Tested and returned to service

## Brake Assembly:

- \* No damage found to brake assembly
- \* Temp sensor tested and returned to service
- \* Restored, tested and returned to service

# 8 - Rear Outboard: Vendor S/N ~ QB083  
DAL S/N ~ 841

## Tire:

- \* Skidded through casing and blown


## Wheel:

- \* No damage found to wheel assembly
- \* Tested and returned to service

## Brake Assembly:

- \* No damage found to brake assembly
- \* Temp sensor tested and returned to service

# 757 MAINTENANCE MANUAL




**Figure A**  
Hydraulic Brake Assembly

DUNLOP CARBON BRAKES


AWABS-3 RWS MSG FOR FLL FLT-1086/23FEB SH- 678-D 1541Z/23FEB  
LOAD PLANNER - R-WILLIAMS EXT - 8009 POS - BA  
DOWNLINE STNS- ATL  
FLIGHT ORIGINATES - FLL LOCAL ETD 1050 GMT ETD 1550  
PLANNED LOAD BREAKDOWN NBR 1  
THRU PSGRS ORIG  
LOCAL PSGRS 32/200 ATL 32/200  
TOTAL PSGRS 32/200 CAPACITY 26/156  
LOCAL CARGO 10847 BAGS 302/07097 EST CARGO 03750  
TOTAL CARGO 10847  
MIN/MAX IN BINS 1 AND 2 PREF 2340/6187 LIMITS 798/8848  
MAX CARGO AS BOOKED 21710 MAX CARGO WITH FULL PSGRS 21710  
END OF RAMP WORKSHEET

OU FLLFMDL FLLRRDL ATLFMDL ATLRRDL  
.FLLOODL 231610  
FDM  
FLL 1086/23 PLND 1115  
TPS.25 PSGR BRDG  
231611  
RES 9880

FUEL DISTRIBUTION ADVISORY MESSAGE NUMBER 1  
FLT-1086/23 FLL-ATL SH- 678-D 1313Z/23FEB  
LOAD PLANNER - R-WILLIAMS EXT - 8009 POS- BA  
----- FUEL DISTRIBUTION -----  
TANK ID TANK WGT  
LM- 11500  
RM- 11500  
CA- 0  
TTL FUEL 23000  
FUEL REMARKS  
\*\* FOB \*\* PLZ VERIFY BEFORE HOOK-UP. IF LOAD IS LESS THAN  
PLANNED OR OVER 3000 LBS MORE - NOTIFY AGENT IN CHARGE  
END OF FUEL DISTRIBUTION ADVISORY MESSAGE

<b>FUEL SERVICE RECORD</b>  0412-81151 RECORD 8-92	STATION:	FLIGHT NO.	DESTINATION:	SHIP NO.	DATE:	DELTA AGENT:
	FLL	1086	ATL	678	2-23-93	Leisy
AIRCRAFT TYPE:				FUEL TYPE:		
B-757				<input checked="" type="checkbox"/> JET A <input checked="" type="checkbox"/> OTHER _____ <input type="checkbox"/> JET A-1    (SPECIFY)		

[illegible]

 <b>DELTA AIR LINES</b>		# Of Pages <b>1</b>
To <b>R. ORR</b>	From <b>A. ROMAN</b>	
Co. <b>DL. ATL</b>	Dept. / Sta. <b>110-FLL</b>	
Dept. / Sta.	Phone # <b>351-1721</b>	
Fax # <b>404-715-1725</b>	Fax # <b>305-354-7818</b>	

0412-20254 Sticker 7/92

23000		23400	
TOTAL DISPATCH POUNDS		TOTAL POUNDS	
TOTAL ACTUAL POUNDS ON BOARD		23400	
SUBTRACT TOTAL POUNDS ON ARRIVAL		23400	
EQUALS POUNDS ADDED		0	
DIVIDED BY ACTUAL FUEL DENSITY LBS/GAL (USE 6.7 IF NOT AVAILABLE)		6.72	
EQUALS CALCULATED GALLONS ADDED		0	
SUBTRACT TOTAL GALLONS PUMPED		0	
EQUALS DIFFERENCE		0	
ALLOWABLE DIFFERENCE (TOLERANCE)		0	
REMARKS: ESTG F.O.B.			

IF STICKS ARE USED COMPLETE THE FOLLOWING	
PRE-SERVICE: PITCH =	ROLL =
AFTER SERVICE: PITCH =	ROLL =
INOP GAUGE FUELING METHOD USED:	
AGENT VERIFYING STICKS:	

FUEL BOARDED PER SERVICING VEHICLE METER(S)										
GALLONS PUMPED					WING	VEHICLE NO.				
					LEFT					
					RIGHT					
FDS					FUELING AGENT					
					[Signature]					

(NOTE: LITERS x 0.26417 = U.S. GALLONS)

FLEET	FUELING TOLERANCE	SP REFERENCE
DC-9	+/- 150 GALLONS	SP 3589
MD-88	+/- 150 GALLONS	SP 3584
B-727	+/- 150 GALLONS	SP 3592
B-737	+/- 150 GALLONS	SP 3588
B-757	+/- 200 GALLONS	SP 3582
B-767	+/- 250 GALLONS	SP 3587
A-310	+/- 250 GALLONS	SP 3581
L-1011	+/- 4% OF CALC. GALS	SP 3583
MD-11	+/- 4% OF CALC. GALS	SP 3585

COPY: WHITE YELLOW



COPY FROM 031D3B 23FEB/1054

23FEB15470P B13313

WDR TRANSMITTED TO B13304 -SMRS

FLT 1086/23 FLL-ATL 3142 LD PLNR R-WILLIAMS 4B1514  
FINAL WEIGHT DATA RECORD DATE/TIME 23FEB 1547Z  
GATE B5 - SMRS

130350 DEW 757 SHIP 678 INCLUDES 6 FLT ATT W/BAGS

1000 ADD ON UP TO 4 PSGRS AND 320 LB

4420 26 FC  
26520 156 YC  
195 1 JS

0 B1 CARGO  
3750 B2 CARGO  
4442 B3 CARGO  
470 B4 CARGO

171147 ZERO FUEL WEIGHT MAX 184000  
171123.6 ADJUSTED ZFW 23.3 PCT MAC ZFW

23402 FUEL/LM- 11701/RM- 11701/CA- 0  
-350 LESS TAXI FUEL

194199 ACTUAL TAKEOFF WEIGHT AI 49 25.4 PCT MAC

\*\*\*\*\*  
194225.4 ADJUSTED TAKEOFF WEIGHT FLL TAKEOFF WEATHER /NWS  
TEMP 71F ALT 29.94  
WIND 334/ 6 KTS

210680 MAX TAKEOFF WT THIS FLIGHT  
LIMITED BY MAX STRUCT LANDING WT

MAX T/O WT LDG ATL MAX LDG WT BURNOFF 12680 FCST 49 F  
210680 FLAP 30 198000

223800 MAX STRUCTURAL TAKEOFF WEIGHT

\*\*\*\*\*  
FLL RWY 9L / 9001 FT 71F/ 22C 3TW 5XW

STANDARD PROFILE

RWY COND	THRUST/FLAP	PERF LIM	RATOW	STAB	V1	VR	V2
*DRY *	*ATO2/15*	*194752 TW 03	194752*	3.8	133	136	139*
*DRY *	*ATO1/15*	*195260 TW 10	195260*	3.8	131	134	139*
*DRY *	* TO/15*	*216522 TW 10	216522*	3.8	127	133	138*
SLWET	TO/15	206554 TW 10	206554	3.8	120	133	138
ICY	TO/15	199254 TW 10	199254	3.8	108	133	138
25CTR	TO/15	195819 TW 06	195819	3.8	114	133	138
50CTR	TO/15	OVERWT	OVERWT	---	---	---	---