

Geschäftsbereich
Montage

BABCOCK

DEUTSCHE BABCOCK
WERKE
AKTIENGESELLSCHAFT

~~NTSB DOOB~~

NTSB DO8

Dokumentation

Kennwort SS Norway

Kom.-Nr. 18-9790-999

mm

mm

NCL-139375

Box 3

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Repair to the Steam and Lateral Drum of Boiler 21 in the
 SS Norway from 7.11. - 21.11.1987

On the above-mentioned drums, the signs detected by the VETCO
 Co. in September 1987 were to be repaired by building up. For
 the work, working instructions were drawn up (Appendix 1) which
 were handed in to the Veritas office for authorization.

Repair of the Lateral Drum

The straight seams were prepared for inspection by means of
 slight grinding at those points previously ground and they
 were subsequently subjected to a surface cracking test.

An MP Test was firstly carried out which did not result in a
 satisfactory result as the corrosion pitting was too deep and
 sharp-edged.

Following that, a FE Test was effected. Here again, an assessment
 was very difficult. Photos 1 - 4 show the upper seam.

The lengths refer to the distance from the rear circumferential
 seam to the front. Phot 5 shows the area of the indications
 recorded in the report at approx. 2280 mm. As the area was ground
 prior to the testing, only a 7 mm. long sign remains. To the
 left on the photo, corrosion pitting is recognizable which,
 despite the most thorough cleaning, resulted in indistinct signs.

After the surface crack test, wall thickness measurements were
 carried out on a random basis with the result that partial
 areas had to be applied.

NCL-139376

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
Ausgabe

Erection division

Date

11.2.88

Signature



Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

As welding could not be avoided, the deep corrosion pitting was ground. The large extent of corrosion pitting was in the transitional zone of filler metal to basic material.

Photos 6 - 8 show a part of the deeply grounded points of the upper seam and photos 9 - 11 reveal the grounded sections of the lower seam. A list of the grounded sections is attached in Appendix 2. The absence of defects of the grounded sections was proven by means of a MP Test.

Working in sections, the seams were pre-heated from inside, welded and post-heated for 1 hour. Photo 12 shows the upper seam and photo 13 the lower seam with the resistive elements provided. A welded seam can be seen on photo 14. Photos 15 - 22 show sections of the upper seam.

After post-heating and cooling the seam, the annealing layers were smoothed and the build-up was worked for as long as it was flush to the metal.

After grinding, a MP Test was carried out which revealed no inadmissible indications. The test report is attached in Appendix 3.

A dimensional report (Appendix 4) was drawn up for the subsequent wall thickness measurements.

A hardness test for the completed seam was carried out by means of the EQUOTIP appliance of the PRECEY SA company. The result has been compiled in Appendix 5, Pages 1 - 4. No inadmissibly high hardness values were detected.

NCL-139377

Verdruck
Ausgabe

Erection division

Date

18.2.77

Signature

DEUTSCHE BABCOCK WERKE AG
 G. ZACHAU
 12

Date

Signature

J. [Signature]

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Photos 24 - 29 show the finished upper seam and the photos 30 - 32 show the finished lower seal.

On photos 33 and 34, corroded sections of the lower seam are to be seen which were left as they were.

Repair of the Steam Drum

The front circumferential seam of the steam drum according to the inspection report of the VETCO Co. revealed an indication which could not be removed without going under the minimum wall thickness. This sign was also checked from the BK Werkstofftechnik Co.. The defect position was stated approx. 14 mm beside the welding seam melting line in the course and as a 7 mm length.

During the inspection for the repair, there were doubts raised as to the defect position. At the same time at a distance of around 300 mm a grounded trough was found which was to be filled in when proceeding with the designated repair.

The position of both troughs is given in Appendix 6. As the preparation for a FE Test, both points were lightly ground. At trough 1, the following signs were found on a length of 13 mm (from l. to r.): linear 1mm; point-shaped; linear 2mm; point-shaped. Photo 35 shows the result.

At trough 2, 4 point-shaped signs were found which are to be seen on photo 36. Photo 37 shows both troughs.


NCL-139378

Vordruck
Ausgabe

Erection division

Date

18.2.78

Signature  BABCOCK WERKE AG
G. ZACHAU
12

Date

Signature

Code.

Job No.

18 - 9790 - 999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

The signs were removed in both troughs by grinding and the absence of cracks was established by means of a MP Test.

In both troughs, the signs were found at the melting line between circumferential seam and coating metal.

The trough was in a section which had already been repaired once before.

This repair is in the base section and is probably the reason for the wrong indication of the defective position by the BK Werstofftechnik Co. Appendix 7 shows a diagram of the situation and photo 38 shows the grounded trough and, on the right, one can make out the circumferential seam made visible through macro-etching.

Prior to welding, the repair area was subjected to a hardness test and the result is compiled in Appendix 8. The grounded point as such could not be checked with the EQUOTIP appliance used as it was not possible to support the appliance in view of the prevailing shape. For welding, both points were jointly heated from outside with resistor elements. Appendix 9 shows the arrangement of the elements. The temperature readings were taken from inside.

NCL-139379


Vordruck
Ausgabe

Erection division

Date

11.2.77

Signature



Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

After the post-heating, the annealing layers were ground and a hardness test was carried out. The result is compiled in Appendix 10. Appendix 11 contain the measured results of the wall thickness measurements. The final MP Test revealed no signs and the test report is attached in Appendix 12.

Photos 39 and 40 show the finished defective position 1. On the photos, the course of the melting line is marked in chalk.

NCL-139380

Vordruck
Ausgabe

Erection division

Date

18.2.78



Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 1

Upper seam lateral Drum



Photo 2

NCL-139381


Vordruck

Ausgabe

Erection division

Date

Signature



Date

Signature

Code

Job No.

18 - 9790 - 999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 3



Photo 4

NCL-139382


Vordruck

Ausgabe

Erection division

Date

Signature



Date

Signature


Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Indication at approx. 2280 mm.

Photo 5




Photo 6

NCL-139383

Deeply grounded points of the upper seam

Vordruck
Ausgabe

Erection division

Date

DEUTSCHE BABCOCK WERKE AG
 G. ZACHAL
J. [Signature]

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 7




Photo 8

NCL-139384

Vordruck
 Ausgabe

Erection division

Date

Signature **BABCOCK WERKE AG**
 G. ZACHAR
 12
 ST. GEMERIN

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 9

Deeply grounded points of the lower seam




Photo 10

NCL-139385

Vordruck

Ausgabe

Erection division

Date

Signature

DEUTSCHE BABCOCK WERKE AG
 G. ZACHS
 12
 J. Schmal

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 11



Photo 12

Upper seam with the resistive elements provided

NCL-139386

Vordruck

Ausgabe

Erection division

Date

Signature

DEUTSCHE BABCOCK WERKE AG
 G. ZACHAR
[Handwritten Signature]

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 13

Lower seam with the resistive elements provided



Photo 14

Welded seam

NCL-139387

Vordruck
 Ausgabe

Erection division

Date

Signature

DEUTSCHE BABCOCK WERKE AG
 G. ZAC
 1910
 1911
 1912
 1913
 1914
 1915
 1916
 1917
 1918
 1919
 1920
 1921
 1922
 1923
 1924
 1925
 1926
 1927
 1928
 1929
 1930
 1931
 1932
 1933
 1934
 1935
 1936
 1937
 1938
 1939
 1940
 1941
 1942
 1943
 1944
 1945
 1946
 1947
 1948
 1949
 1950
 1951
 1952
 1953
 1954
 1955
 1956
 1957
 1958
 1959
 1960
 1961
 1962
 1963
 1964
 1965
 1966
 1967
 1968
 1969
 1970
 1971
 1972
 1973
 1974
 1975
 1976
 1977
 1978
 1979
 1980
 1981
 1982
 1983
 1984
 1985
 1986
 1987
 1988
 1989
 1990
 1991
 1992
 1993
 1994
 1995
 1996
 1997
 1998
 1999
 2000

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 15

Section of the upper seam



Photo 16

NCL-139388

Vordruck
Ausgabe

Erection division

Date

Signature

[Circular stamp: BABCOCK WERKE AG, DEUTSCHE BABCOCK WERKE AG, 1890, 1950, 1955, 1960, 1965, 1970, 1975, 1980, 1985, 1990, 1995, 2000, 2005, 2010, 2015, 2020, 2025, 2030, 2035, 2040, 2045, 2050, 2055, 2060, 2065, 2070, 2075, 2080, 2085, 2090, 2095, 2100]
[Handwritten signature]

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 17




Photo 18

NCL-139389

Vordruck

Ausgabe

Erection division

Date

Signature

DEUTSCHE BABCOCK WERKE AG
 G. 230924
 KARLSRUHE
J. ...

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 19



Photo 20

NCL-139390

Vordruck
Ausgabe

Erection division

Date

Signature

J. Schell

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 21



Photo 22

NCL-139391

Vordruck

Ausgabe

Erection division

Date

Signature

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 23

Upper seam lateral Drum



Photo 24

Section of the upper seam

NCL-139392

Vordruck

Ausgabe

Erection division

Date

Signature



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 25



Photo 26

NCL-139393

Vordruck

Ausgabe

Erection division

Date

Signature
 DEUTSCHE BABCOCK WERKE AG
 G. ZACHAU
 12
 1901-1971

Date

Signature

Code _____ Job No. **18-9790-999**

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 27




Photo 28

NCL-139394

Vordruck
 Ausgabe

Erection division

Date

Signature

DEUTSCHE BABCOCK WERKE AG
 G. ZACHAU
 12
 J. [Signature]

Date

Signature

Code

Job No.

18 - 9790 - 999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 29



Photo 30

Lower seam Lateral Drum

NCL-139395

Vordruck
Ausgabe

Erection division

Date

Signature

G. ZACHAU

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 31

Finished lower seam



Photo 32

NCL-139396

Vordruck

Ausgabe

Erection division

Date

Signature
 DEUTSCHE BABCOCK WERKE AG
 G. ZACHAU
 12
G. Zachau

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG




Photo 33

Lower seam with corroded sections



Photo 34

NCL-139397

Verdruck
Ausgabe

Erection division

Date

Signature
DEUTSCHE BABCOCK WERKE AG
G. ZACHAU
12
G. Zachau

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 35

Upper Drum defective position 1 with indications



Photo 36

Upper Drum defective position 2
 with indications


NCL-139398

Vordruck
 Ausgabe

Erection division

Date

Signature



Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 37



Melting Line

Photo 38

NCL-139399


Vordruck

Ausgabe

Erection division

Date

Signature



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Photo 39

Finished defective position 1



Photo 40

NCL-139400

Vordruck
Ausgabe

Erection division

Date

Signature

DEUTSCHE BABCOCK WERKE AG
G. ZACHAU
 12
 Montage / Schweisstechnik
G. Zachau

Date

Signature

Welding and Repair Instructions for the Upper and Lateral Drum of Boiler 21 of the SS Norway

During a surface crack inspection of the drums, there were readings which made a repair necessary. For the position and extent of the indicators, refer to the reports of the Vetco Services firm from 15. and 18.09.1987. Below, the course of the repair work is separately described for upper and lateral drum.

Upper Drum

Description of damage

In the upper part of the circumferential seam 2, an approx. 7 mm long crack was discovered which can not be removed by grinding without undercutting the minimum wall thickness.

Working the damaged area

The crack is to be worked in a through shape by milling and/or grinding. The absence of cracks is to be demonstrated through a magnetic crack test detection procedure. Furthermore, a hardness test is to be carried out to ensure that the hardening detected during the inspection was removed.

Pre-heating and Welding

The welding point and the surrounding area of at least drum wall thickness is to be pre-heated to about 150°C. Resistive heating is employed for the pre-heating. Thermocouples measure the temperature from the inner side of the drum.

For the filler metal, an electrode E Mo B according to DIN 8575, trade name SH Schwarz 3 MK is to be used. Welding is to follow in string beads. On the worked area having been filled, "annealing layers" of basic material are welded on. Subsequently, the annealing layers are again worked off.

The completed welding area is then subjected to a surface crack inspection.

NCL-139401

Lateral Drum

Description of damage

The longitudinal seam No. 1 of the lateral drum reveals signs that cannot be removed by grinding without undercutting the minimum wall thickness. It is evident that cracks are not involved from all indications.

Working the damaged area

The signs will be prepared in a trough form and the absence of defects of the areas is to be shown by means of magnetic crack test detection. Subsequently, the wall thickness will be measured. On going below the min. wall thickness, filling will have to occur.

Pre-heating and Welding

The point of application and a surrounding area of at least drum wall thickness is to be pre-heated to about 150°C. Resistive heating is employed for the pre-heating. Thermocouples measure the temperature from the inner side of the drum. For the filler material, the electrode SH Schwarz 3 MK is to be used and string beads are to be welded. On the required wall thickness being reached, additional annealing layers are to be welded which are then re-worked. The completed welding area is finally subjected to a surface crack inspection.

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



G. ZACHAU

NCL-139402

Code

Job No.

18-9790-999

SS NORWAY

Component

Lateral drum boiler 21

Position of the deeper grinding points measured from the circumferential seam 1 [rear] towards the front:

A) upper seam:

1,34 - 1,44
 1,65 - 1,73
 2,03 - 2,25
 2,28 - 2,39
 2,43 - 2,49
 2,99 - 3,28
 3,40 - 3,50
 3,65 - 3,98
 4,02 - 4,07

Welding between
 1.32 m - 4.08 m

B) lower seam:

1,91 - 2,16
 2,34 - 2,40
 2,46 - 2,52
 2,55 - 2,81
 3,11 - 3,18

Welding between
 1.90 m - 3.94 m

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

NCL-139403

Vordruck
Ausgabe

Erection division

Date

17.2.78



Date

Signature

Kennwort : *SS NORWAY*
 Code word :
 Kom. : *18-9790-999* Blatt : *1* Pos. :
 Job. : Sheet : Item :

AK-Nr.:
 Plant identification No.:

Gegenstand :
 Subject : *Boiler No. 21*

System:
 System:

Bauteil : *side Drum*
 Component :

Abmessung :
 Dimension :

Fabr.-Nr.:
 Fabrication No.:

Zeichn.-Nr. :
 Drawg.-No. :

Schweißverfahren :
 Welding process : *E*

Bgr.: TE:
 Ass: Term unit:

Prüflflächenzustand / Nahtoberfläche
 Surface condition of test area / Surface of seam *grind*

Prüfung nach
 Test according to *HPS13*

Wärmebehandlung : vor nach keine
 Heat treatment : before after no

Beurteilung durch :
 Evaluation by :

Prüfung an : Grundwerkstoff
 Test on : Base material

Schweißkante
 Weld edge

Schweißnaht
 Weld seam

MAGNETPULVERPRÜFUNG nach: *DIN 54130*
 MAGNETIC particle test acc. to

Testkörper:
 Testbody: *Bert hold*

Prüfgerät: *Deutroplus 3443.042*
 Test equipment:

Stromstärke:

Prüfmittel: *MP 315 Fa. Peters*
 Medium for testing:

Magnetisierungsart:

naß / trocken
 wet / dry

Kind of magnetization: *JEW*

fluoreszierend: / nein
 fluorescent: *yes* / no

Kontrastmittel:

Medium of contrast:

Tangentialfeldstärke:

Tangential field intensity: *2,0-6,5* KA/m

Pos. / Item or Naht-Nr. Weld-No.	Gesamtstückzahl Total Quantity	Prüfmfang Test volume %	geprüfte Stückzahl tested quantity	Abmessung Dimension [mm]	Werkstoff Material	Beurteilung / evaluation		
						erfüllt satisfactory	erfüllt not satisfactory	erfüllt not satisfactory
						anzeigenfrei no indication	keine unzul. Anzeigen no indic. to be recorded	nicht erfüllt not satisfactory
<i>LN 1</i>	<i>1</i>	<i>100</i>	<i>1</i>		<i>~ 1911a 5</i>	<i>X</i>		
<i>LN 2</i>	<i>1</i>	<i>100</i>	<i>1</i>				<i>X</i>	

Bemerkungen :
 Remarks :

Ort : *SS Norway*
 Place :

den : *19.11.1987*
 dated :

Sachverständiger :
 Expert :

Prüfer :
 Operator :



Prüfaufsicht :
 Test Supervision :

NCL-139404

Code

Job No.

18-9790-999

SS NORWAY

Component

Lateral drum Boiler 21

Wall thickness upper seam:

Position*	Filler metal	Basic material	Comments
0.31	22.4 mm	23.1 mm	only ground
0.48	22.6	23.6	"
1.06	21.0	23.4	"
1.40	23.0	22.6	filled in
2.00	21.8	23.8	"
2.50	22.6	23.2	"
2.85	22.6	23.4	"
3.00	22.4	23.2	"
3.27	21.6	24.3	"
3.50	22.5	23.4	"
4.00	23.3	23.8	"
4.07	22.4	23.7	"
4.64	21.6	23.4	only ground

Wall thickness lower seam:

Position*	Filler metal	Basic material	Comments
2.00	25.1 mm	24.0	filled in
2.50	26.4	23.6	"
3.00	25.9	24.9	"
3.50	24.4	24.6	"
4.00	24.0	24.6	"
4.23	23.1	24.5	only ground

* Distance to the rear circumferential seam in meters.


NCL-139405

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
Ausgabe

Erection division

Date
17. 2. 78

Signature

J. [Signature]

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Component

Lateral drum Boiler 21

Upper Seam :

Position	Filler metal		HEZ		Base metal	
	L _D gem.	HV	L _D gem.	HV	L _D gem.	HV
1.5 m	456	174	489	203	424	147
	423	146	513	227	409	135
1.75 m	441	160	605	328	444	163
	438	158	589	309	426	148
	458	175	551	267		
			527	241		
2.0 m	428	150	575	293		
	432	153	587	306		
	442	161	564	281		
2.5 m	495	209	619	345		
	488	202	589	309		
	468	184	583	302		
			558	274		
3.0 m	485	200	606	330	430	151
	444	163	553	268	425	147
	496	210	605	328	414	139
3.5 m	482	197	529	243		
	506	220	538	252		
4.0 m	451	170	593	313		
	463	180	575	293		

Note !

The measured L_D-values have to be corrected by the corrective value.

Impact direction: ~~XXXX~~

NCL-139406

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
Ausgabe

Erection division

Date

17.2.88

Signature



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Component

Lateral drum Boiler 21

Lower Seam:

Position	Filler metal		HEZ		Base metal	
	L _D µm	HV	L _D µm	HV	L _D µm	HV
2.0 m	453	182	584	315	426	159
	451	180	565	294	435	166
	450	179	*491	216	408	144
	452	181	*496	221	413	148
	460	188	*508	233	418	152
	447	176	602	337		
2.5 m	451	180	*507	232	431	163
	473	200	575	305	427	159
	450	179	*501	226	415	150
	465	192	571	300		
	479	205	577	307		
			582	313		
3.0 m	451	180	603	338	435	166
	462	190	*519	244	431	163
	449	178	576	306		
	471	198				
	455	183				
3.5 m	439	170	*511	236	428	160
	457	185	*485	211	410	146
	446	176	562	289	411	147
	465	192	564	292	409	145
	469	200	575	305		

Note!

The measured L_D-values have to be corrected by the corrective value.

Impact direction: 

NCL-139407

* Measuring point approx. 1mm next to the melting line

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
Ausgabe

Erection division

Date

18.2.88

Signature



Date

Signature

Code

Job No.

18-9790-999


SS NORWAY

Component

Lateral drum Boiler 21

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

"Hole" 1:



<i>L₀ gem.</i>	<i>Correction</i>	<i>L₀ dist</i>	<i>HV</i>
394	6	388	133
412	5	407	148
427	5	422	159
432	5	427	164
449	5	444	178
461	5	456	189
498	5	493	223
503	5	498	228
506	5	501	231
516	5	511	241
571	4	567	301
581	4	577	312

Position:

Above the lower seam in the thick metal at the front end.

NCL-139408

Vordruck
Ausgabe

Erection division

Date

11.2.98



Date

Signature

Code

Job No.


18-9790-999

SS NORWAY

Component

Lateral drum boiler 21

"Hole" 2:



Logem	Correction	Dist	HV
445	5	440	175
455	5	450	183
469	5	464	196
520	5	515	245
547	5	542	273
552	4	548	280
556	4	552	284
572	4	568	302
575	4	571	305
587	4	583	319

Position:

Next to the lower seam in the sheet metal at the front end.

NCL-139409

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
Ausgabe

Erection division

Date

19.2.88

Signature



Date

Signature

Code

Job No.


18-9790-999

SS NORWAY

Component

Upper Drum Boiler 21

Reproduction, even in an abridged form, only permitted with the approval of DBW AG



Defective position, upper drum, boiler 21, front circumferential seam seen from the back.

NCL-139410

Vordruck
Ausgabe

Erection division

Date

19.2.78

Signature
 DEUTSCHE BABCOCK WERKE AG
 G. ZACHAU
 1921
 SCHWEDEN

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9

SS NORWAY

Component

Upper Drum Boiler 21


Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Defective position 1:

ground trough and defective position:

Defects:

*2 point shaped and
 2 longitudinal
 [1 and 2 mm]
 signs on melting line
 to the shell plate*



NCL-139411

Vorprodukt

Ausgabe

Erection division

Date

19.2.88



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY


Component

Upper Drum Boiler 21

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Defective position 1:

Position of the measuring points prior to welding



NCL-139412

Vordruck

Ausgabe

Erection division

Date
 19.2.78



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Component

Upper Drum Roller 21

Hardness test of the defective location 1 prior to welding:

Position	Legem.	correction	Dist	HV
1	395	27	368	119
	404	25	379	127
	385	27	358	112
	400	27	373	122
1	396	27	369	120
2	505	22	483	214
	513	22	491	221
	489	24	465	197
	506	22	484	215
	502	22	480	211
	483	24	459	192
	510	22	488	218
2	498	24	474	205
3	404	25	379	127
1	412	25	387	132
3	418	25	393	137
HEZ	434	25	409	149
	419	25	394	137
	409	25	384	130
	467	24	443	177
HEZ	461	24	437	172
4	427	25	402	143
4	441	25	416	155
5	413	25	388	133
6	446	25	421	159
7	448	25	423	160
7	437	25	412	151

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
Ausgabe

Erection division

Date

17.2.88



Date

Signature

NCL-139413

Code

Job No.


18-9790-999

SS NORWAY

Component

Upper Drum Boiler 21

Position of the Pre-Heater Elements:



*○ No of the annealing pad
 Centre of the drum*

*Pads 1+2 and 3+4 arranged in series.
 Pads fixed and insulated on the drum from outside.
 The temperature was measured from inside.*

NCL-139414

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
 Ausgabe

Erection division

Date
 19.2.88

Signature

G. Zachau

Date

Signature

Code

Job No.

1 8 - 9 7 9 0 - 9 9 9


SS NORWAY

Component

Upper Drum Boiler 21

Defective location 1:

Position of the measuring points, completed repair point



Centre Drum

NCL-139415

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

Vordruck
 Ausgabe

Erection division

Date
 19. 2. 88

Signature **BABCOCK WERKE AG**
 G. ZACHAU
 12
[Signature]

Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Component

Upper Drum Boiler 21

Hardness test of the completed repair point 1:

Measuring point	L _D	correction	L _{0.02}	HV
1	375	27	348	106
2	395	27	368	119
3	392	27	365	117
4	405	25	380	127
5	490	24	466	198
6	445	25	420	158
7	437	25	412	151
8	489	24	465	197
9	459	24	435	170
10	460	24	436	171
11	400	25	375	124
12	485	24	461	193
13	471	24	447	181
14	458	24	434	170
15	460	24	436	171
16	401	25	376	124
17	545	22	523	251
18	437	25	412	151
19	517	22	495	225
20	456	24	432	168
21	491	24	467	199

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

NCL-139416

Vordruck
Ausgabe

Erection division

Date

19.2.88

Signature



Date

Signature

Code

Job No.

18-9790-999


SS NORWAY

Component

Upper Drum Boiler 21

Defective location 2:

Position of the measuring points, completed repair point



Reproduction, even in an abridged form, only permitted with the approval of DBW AG

NCL-139417

Wiedruck
Ausgabe

Erection division

Date

17.2.88



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Component

Upper Drum Boiler 21

Hardness test of the completed repair point 2:

Measuring point	L ₀	correction	L _{dist}	HV
1	444	-18	426	163
2	447	-18	429	165
3	494	-17	477	208
4	455	-17	438	173
5	491	-17	474	205
6	451	-17	434	170
7	467	-17	450	173
8	420	-18	402	143
9	470	-17	453	186
10	484	-17	467	199
11	443	-18	425	162

Reproduction, even in an abridged form, only permitted with the approval of DBW AG

NCL-139418

Vordruck
Ausgabe

Erection division

Date
23.2.78



Date

Signature

Code

Job No.

18-9790-999

SS NORWAY

Component

Upper Drum Boiler 21

Wall thickness of the defective points after welding:

Defective location 2:

Filler metal : 52.3 - 53.1 mm
 Basic material front : 54.4
 rear : 55.2
 left : 53.1
 right : 53.7

Defective location 1:

Filler metal : 55.5 - 56.1 mm
 Basic material front : 55.6
 rear : 57.3
 left : 55.5
 right : 55.8


Reproduction, even in an abridged form, only permitted with the approval of DBW AG

NCL-139419

Vordruck
Ausgabe

Erection division

Date
27.2.78



Date Signature

Kennwort : *SS NORWAY*
 Code word :

Kom. : *18-9790-999* Blatt : *1* Pos. :
 Job. : Sheet : Item :

AK-Nr.:
 Plant identification No.:

Gegenstand :
 Subject : *Boiler No. 21*

System:
 System:

Bauteil :
 Component : *Upper Drum*

Abmessung :
 Dimension :

Fabr.-Nr.:
 Fabrication No.:

Zeichn.-Nr. :
 Drawg.-No. : Schweißverfahren :
 Welding process : *E*

Bgr.: TE:
 Ass: Term unit:

Prüflächenzustand / Nahtoberfläche
 Surface condition of test area / Surface of seam *grind* Prüfung nach
 Test according to *HP 513*

Wärmebehandlung : vor nach keine
 Heat treatment : before after no & Beurteilung durch :
 Evaluation by :


Prüfung an : Grundwerkstoff Schweißkante Schweißnaht
 Test on : Base material Weld edge Weld seam &

MAGNETPULVERPRÜFUNG nach: *DIN 54130* Testkörper:
 MAGNETIC particle test acc. to Testbody: *Berthold*
 Prüfgerät: *Deutroplus 3443.042* Stromstärke:
 Test equipment: Current intensity:
 Prüfmittel: *MP 315 Fa. Peters* Magnetisierungsart:
 Medium for testing: Kind of magnetization: *DEW*
 naß / trocken Kontrastmittel:
 wet / dry Medium of contrast:
 fluoreszierend: / nein Tangentialfeldstärke:
 fluorescent: *yes* / no Tangential field intensity: *20-6,5* KA/m

Pos. / Item or Naht-Nr. Weld-No.	Gesamtstückzahl Total Quantity	Prüfumfang Test volume %	geprüfte Stückzahl tested quantity	Abmessung Dimension [mm]	Werkstoff Material	Beurteilung / evaluation				
						anzeigenfrei no indication	erfüllt satisfactory	keine unzul. Anzeigen no indic. to be recorded	nicht erfüllt not satisfactory	
<i>P1</i>	<i>1</i>	<i>100</i>	<i>1</i>	<i>~ 30 x 85</i>	<i>~ 1911a 5</i>	<input checked="" type="checkbox"/>				
<i>P2</i>	<i>1</i>	<i>100</i>	<i>1</i>	<i>~ 40 x 85</i>	<i>"</i>	<input checked="" type="checkbox"/>				

Bemerkungen :
 Remarks :

Ort : *SS Norway* den : *19.11.87* Sachverständiger :
 Place : dated : Expert :

Prüfer :  Prüfaufsicht :
 Operator : Test Supervision : *NCL-139420*