

DCA15MA019

Attachment #3 to Group Chairman's Electronic Devices and Flight
Data Factual Report

Integrated Electronics Engineering Center (IEEC) Report

Author: Stephen R. Cain

Prepared for the National Transportation Safety Board

DCA15MA019

Stephen R. Cain

Integrated Electronics Engineering Center (IEEC), Binghamton University

Prepared for the Nation Transportation Safety Board

December 11, 2014

Section 1

Overview and Summary of Results

Personnel and Methods

- All analyses were performed by Stephen Cain, IEEC, 607-777-5467
- Instruments
 - ✓ Optical microscopy
 - Wild M420 zoom stereoscope
 - ✓ X-ray
 - Fein Focus FXS 100.23
 - Tube set to 65 – 80 kV
 - 255 integrations
 - ✓ Sonic imaging – SamTec Evolution II
 - Done only when X-rays were good
 - 50 MHz transducer
 - Pulse echo mode
- Samples received (IEEC added label to the bags)
 - ✓ 1 Card
 - 1 processor
 - 16 memory modules
 - Back to back configuration
 - ✓ 2 flash memory units
 - 1 processor
 - 2 memory modules
 - Back to back configuration
- Handling to avoid ESD
 - ✓ Grounded wrist strap
 - ✓ Metal tweezers

Results for Contents of Bag 1

Front	Optical	X-Ray	C-SAM	Likely Data Retrieval	Back	Optical	X-Ray	C-SAM	Likely Data Retrieval
U19	Cracked	Good	Cracked die	Poor	U23	Thin crack	Good	Cracked die	Poor
U20	Cracked	Good	Cracked die	Poor	U24	Broken	Suspect wires	Not done	Poor
U21	Good	Good	Good	Good	U25	Good	Good	Cracked die	Poor
U22	Good	Good	Good	Good	U26	Cracked	Good	Cracked die	Poor
U27	Cracked	Good	Cracked die	Poor	U31	Cracked	Broken wires	Not done	Poor
U28	Cracked	Good	Cracked die	Poor	U32	Badly cracked	Broken wires	Not done	Poor
U29	Broken	Broken wires	Not done	Poor	U33	Badly cracked	Broken wires	Not done	Poor
U30	Cracked	Broken wires	Not done	Poor	U34	Badly cracked	Broken wires	Not done	Poor
					U15	Good	Good	Good	NA

U21 and U22 are the only memory modules on the card for which data recovery is recommended

U15 is a Sand Force 2281 processor (probably no useful data)

Results for Contents of Bag 2 and Bag 3

Bag 2	Optical	X-Ray	C-SAM	Likely Data Retrieval
U1	Good	Good	Likely OK	Fair
U3	Fine crack	Good	Good	Good
U5	Good	Good	Good	NA

U5 is a Silicon Systems processor

Bag 2

- U3 is recommended as a candidate for data recovery
- U1 may also work, but successful data recovery is questionable

Bag 3	Optical	X-Ray	C-SAM	Likely Data Retrieval
U1	Cracked	Good	Cracked die	Poor
U3	Cracked	Broken wires	Not done	Poor
U5	Cracked	Broken wires	Not done	NA

U5 is a Silicon Systems processor


Bag 3

- Data recovery from this memory device is unlikely


Section 2

Catalog of Contents




Bag 1: Casing and Connector






Casing badly bent,
components inside
badly fractured







Bag 1: Card and Components



Bag 2: Casing and Card





Bag 3: Casing and Card



Section 3

Modules in Bag 1


Layout of the Card



Front	Back
U19	U23
U20	U24
U21	U25
U22	U26
U27	U31
U28	U32
U29	U33
U30	U34


- U15 was separated completely from the card
- U27 was separated completely from the card
- U29 was broken and partly separated from the card
- The degree of damage to the card precludes using it as is for data recovery
- A module by module assessment was performed to determine if data could be recovered from certain modules

Basic Construction from Module U27 X-ray and Micrograph




When stamped manufacturer's information is upright, the wire bonds are on the bottom side of the module only. This allows a determination of which module in the back to back configuration has the broken wires


Basic Construction from Module U27 X-rays





Soldered leads



Edge view shows stacked die and rows of wire bonds




Module U15 Photos



Other than separation from the card, there is no visual evidence of damage to the module



Module U15 X-rays

Typical x-ray showing good wire integrity





12/11/2014

DCA15MA019





Module 15 C-SAMs


In the overmold



Top of the chip




Top of the laminate




No evidence of cracking or delamination

Module U19 / U23 Pair - Photos





Obvious crack in U19
Subtle crack in U23

12/11/2014



DCA15MA019

Module U19 / U23 Pair – X-rays




X-rays (typical ones are given above) show good integrity of wire bonds on both modules (wire bonds are on one side of the module, hence appear on opposite edges in the X-rays in the back to back configuration on the card)

Module U19 C-SAMs





In overmold



Top chip




Bottom chip



Given the flex of the module, the C-SAM anomaly is probably from a crack in the chip, not just a shadow of the crack in the overmold



Module U23 C-SAMs

In overmold




Chip is badly damaged from the flexing


Top chip





Bottom chip





Module U20 / U24 Pair - Photos



Obvious cracks in U20
U24 broke apart



Module U20 / U24 Pair – X-rays




X-rays show good integrity of wire bonds on one side (U20), but evidence of stress and displacement on the other side (U24). The complete fracture of U24 missed the wire bonds in that module. Wire bonds on U20 are all good

Module U20 C-SAMs





In overmold



Top chip



Bottom chip




Chip is badly damaged from flexing



Module U21 / U25 Pair - Photos



Cracks were not found in either module
U25 pulled pads from the card




Module U21 / U25 Pair – X-rays




X-rays (typical ones are given above) show good integrity of wire bonds on both modules (wire bonds are on one side of the module, hence appear on opposite edges in the back to back configuration on the card)

Module U21 C-SAMs



In overmold



Top chip



Bottom chip



Chip appears to be in tact – no evidence of cracking or catastrophic delamination

Module U25 C-SAMs





In overmold



Top chip



Bottom chip





Corner of the chip is crushed from flexing

Module U22 / U26 Pair - Photos



No cracks in U22
Obvious cracks in U26

Module U22 / U26 Pair – X-rays



X-rays (typical ones are given above) show good integrity of wire bonds on both modules (wire bonds are on one side of the module, hence appear on opposite edges in the back to back configuration on the card)

Module U22 C-SAMs





In overmold



Top chip




Bottom chip




Chip appears to be in tact – no evidence of cracking or catastrophic delamination

Module U26 C-SAMs



In overmold



Top chip



Bottom chip




Chip is cracked, and the corner of the chip is crushed from flexing

Module U27 - Photos




Cracks in the top side
No cracks on the bottom side




Solder pads
torn from
the card


Module U27 – X-rays



Wires pulled from the card;
can be removed if necessary



2014.12.02
Though bent,
the leads
appear to
have good
connectivity,
and can be
reshaped
without
damage to
the part




Typical X-rays show good integrity of wire bonds

Module U27 C-SAMs





In overmold



Top chip



Bottom chip




Given the flex of the module, the C-SAM anomalies are probably from cracks in the chip, not just a shadow of the cracks in the overmold

Module U31 - Photos




Obvious cracks in U31




Mating module (U27) removed
from the card

Module U31 – X-rays



Broken wires




Broken wire

Module U28 / U32 Pair - Photos




Obvious cracks in U28
Cracks in U32 expose internal features

Module U28 / U32 Pair – X-rays



Broken wires (U32)



Kinked and likely broken wires (U32)






Wire bonds on the other side (U28 – X-rays not shown here) are good

Module U28 C-SAMs

In overmold



Top chip

Bottom chip




Given the flex of the module, the C-SAM anomaly is probably from a crack in the chip, not just shadows of the cracks in the overmold

Module U29 / U33 Pair - Photos




U29 is broken into 2 parts
U33 is badly cracked, exposing
internal features

Module U29 / U33 Pair – X-rays





Broken wires in U33




Broken wires in U33

Module U30 / U34 Pair - Photos




Obvious cracks in U30
U34 is badly cracked, exposing internal features

Module U30 / U34 Pair – X-rays



Broken wire in U34




Broken wire in U30

Section 4




Modules in Bag 2

Layout of the Card




U1 and U3: Samsung Memory Modules
U5: Silicon Systems Processor


Basic Construction from U1 (and U3) X-rays



Micrographs of U1 and U3



Solder pads pulled from card




Subtle crack

No cracks in U1, solder pads pulled from card
Very fine crack in overmold of U3

2014.12.02

X-rays of U1

2014.12.02



2014.12.02 15:



All wire bonds show good integrity
(high mag X-rays are given in the corners)

Broken solder joints



49

Module U1 C-SAMs



In overmold



Top chip



Lower chip and leads







C-SAMs of deeper levels were taken, but gave no additional information

The anomaly may be a crack in the die, or an imaging artifact – overall, the top two chips appear to be intact (and very likely, the underlying ones as well)

X-rays of U3


Circuitry is obscured by module U5, but the wire bonds are not

All wire bonds show good integrity (typical high mag x-rays are given)




Module U3 C-SAMs



In overmold



Top chip (taken with lower gain to avoid saturation)



Lower chip and leads




C-SAMs of deeper levels were taken, but gave no additional information

Overall, the top two chips appear to be intact (and very likely, the underlying ones as well)

Micrographs of U5




No cracks in U5




Bend appears to miss module U5

2014.12.02 14:56




X-rays of U5


2014.12.02 14:57




2014.12.02



2014.12.02 14:59



2014.12.02 14:58



All wire bonds show good integrity
(high mag X-rays are given in the
corners)

DCA15MA019







Module U5 C-SAMs

In overmold

Top of chip

Top of laminate


No evidence of cracking or delamination



Section 5



Modules in Bag 3

Layout of the Card




U1 and U3: Samsung Memory Modules
U5: Silicon Systems Processor

Basic Construction from U1 (and U3) X-rays




2014.12.02 16:05



Micrographs of U1 and U3



Crack in U1 exposing internal features




Crack in U3 exposing internal features

2014.12.02 15:55

X-rays of U1

Displaced leads, but these seem to be "dummy" leads; not connected by design

2014.12.02 15:58



All wire bonds show good integrity (high mag X-rays are given in the corners)

2014.12.02 15:59

Broken solder joints

60

12/11/2014


DCA15MA019

Module U1 C-SAMs


In overmold




Gate Pos.: 24 ns Width: 38 ns 20%




Top chip (taken with low gain to avoid saturation)




Gate Pos.: 64 ns Width: 70 ns 67%



Lower chip and leads



Gate Pos.: 156 ns Width: 94 ns 43%






C-SAMs of deeper levels were taken, but gave no additional information

The anomalies may be imaging artifacts, but it is more likely that they are cracks

X-rays of U3

Circuitry is obscured by module U5, but the wire bonds are not




Broken wires were found in U3

12/11/2014


DCA15MA019

62

High Mag X-rays of Broken Wires in U3




Micrograph of U5



Obvious cracks in U5


2014.12.02 15:44




X-rays of U5

Broken wires found

2014.12.02 15:45




2014.12.02 15:44



2014.12.02 15:43



2014.12.02 15:45



Broken wires

Broken wires

12/11/2014

DCA15MA019

65