



Effectivity: ADUA; ADUE; ADUI; ADUO; ADUC

B. Test Maximum Airspeed Warning Push-to-Test

Operation	Desired Results
(1) Close applicable MAX SPEED WARN circuit breakers.	
(2) Place MAX AIRSPEED WARN selector switch to "cargo".	
(3) Press MAX AIRSPEED WARNING PUSH FOR SYS TEST lamp.	MAX AIRSPEED WARN lamp should light and audible signal should be heard.
(4) Pull WARN LT dimming switch.	MAX AIRSPEED WARN lamp should dim.
(5) Release MAX AIRSPEED WARNING PUSH FOR SYS TEST lamp.	Horn and light should go off.

Effectivity: ADUA; ADUE; ADUI; ADUO; ADUC

TEST POINT			1	2	3	4	5	6	7
Static Pressure (Absolute)	Inches, Hg		28.855	20.577	16.217	13.750	8.488	6.712	5.538
	Altitude, Feet		1,000	10,000	16,000	20,000	31,000	36,000	40,000
Pitot Pressure (Absolute)	Inches, Hg		29.492	22.535	18.715	16.850	12.927	10.210	6.629
	Knots		115	200	225	250	297	265	150
Decade Resistor Settings, Ohms				507.0	574.3	480.1	474.1	446.0	417.9
Airspeed Indicator, Knots	Airspeed Pointer	Min	113	197	222	247	293	262	147
		Max	117	203	228	253	301	268	153
	Maximum Airspeed Pointer	Min		344	344	344	322	287	261
		Max		353	352	352	331	296	270
True Airspeed Indicator, Knots	Min			222	295	324	453	150	284
	Max			242	319	348	79	474	308
True Airspeed Indicator (Slave) Knots	Min			221	294	323	452	149	283
	Max			243	320	349	480	475	309
Static Air Temp., Degrees Cent.	Min			-8	+22	-27	-47	-57	-57
	Max			0	+29	-21	-41	-51	-51
Machmeter	Min				0.447	0.537	0.789	0.788	
	Max				0.467	0.557	0.809	0.808	
Captain's Drag-Cup Type Altimeter, Feet	Min			9,960	15,955	19,950	30,938	35,930	39,925
	Max			10,040	16,045	20,050	31,062	36,070	40,075
First Officer's Baro. Altimeter, Feet	Min			9,920	15,800	19,870	30,795	35,770	39,770
	Max			10,080	16,110	20,130	31,205	36,230	40,230

Air Data System Test Parameters
Figure 201



Effectivity: ADUA; ADUE; ADUI; ADUO; ADUC

C. Functional Test

Operation

Desired Results

- (1) Using screwdriver, adjust air-speed indicator in CW direction until letter "C" is clearly visible in window.
- (2) Slowly adjust variable resistance settings, and static and pitot pressures per each test point as shown in figure 201 and check all indicator readings.

NOTE: Always decrease static pressure first to maintain pitot pressure higher than static pressure; however, do not exceed airspeed or mach maximum indications while changing pressures.

- (3) Increase airspeed until maximum airspeed warning light comes ON and horn actuates. Check instruments per figure 203
- (4) At completion of test point 6 of figure 203 return pressure settings to zero.

TEST POINT	1	2	3	4	5	6
	1,000	10,000	16,000	31,000	36,000	40,000
		Min Max	Min Max	Min Max	Min Max	Min Max
Captain's or First Officer's indicated airspeed pointers in knots at maximum allowable speed warning		348 362	348 362	326 339	291 304	266 277
Captain's or First Officer's maximum allowable speed pointer		344 352	344 352	322 331	287 296	261 270
Captain's or First Officer's machmeter in Mach at maximum allowable speed warning		.623 .653	.698 .730	.870 .900	.870 .900	.870 .900

Maximum Airspeed Parameters (Cargo)

Figure 203



Effectivity: ADUA; ADUC; ADUE; ADUI; ADUO

D. Leakage Test

Operation	Desired Results
(1) Set altitude to 23,000 feet and airspeed to 370 knots. Seal off pressure source to static and pitot ports for one minute.	The airspeed pointer on each airspeed indicator should not change by more than 5 knots and the altimeter should not change by more than 100 feet.
(2) Slowly return pitot and static pressure to normal atmospheric pressure.	
(3) Place static selector valves in ALTERNATE position and set altitude to 23,000 feet and airspeed to 370 knots.	The spread between altimeter should not be more than 100 feet.
(4) Seal off pressure source to static and pitot ports for one minute.	The altimeters should not change by more than 100 feet.
(5) Open AIR DATA-1 circuit breaker.	The captain's drag-cup type altimeter COFR flag should disappear from view and BARC flag appear.
(6) Slowly return pitot and static pressure to normal atmospheric pressure and turn air data calibrator OFF.	
(7) Place static selector valves in NORM position and open all applicable circuit breakers.	
(8) De-energize airplane electrical buses and remove all test connections. Connect aircraft wiring to temperature probe and secure.	Test completed.



Effectivity: ADUA; ADUC; ADUE; ADUI; ADUO


CORRECTED ALTIMETER - MAINTENANCE PRACTICES

1. General

- A. The captain's corrected (servo) altimeter with automatic pressure standby (altimeter) furnishes corrected pressure-altitude when used in conjunction with the air data computer. In the event of an electrical malfunction, in either the computer or the altimeter, the instrument will operate as an uncorrected precision pressure altimeter.

NOTE: Identical corrected altimeters are installed in the captain's and first officer's instrument panels. However, only the captain's instrument is capable of being used in the corrected mode with servoed altitude from the Air Data Computer. The first officer's instrument is used in barometric mode only, until a second air data computer is installed and wires terminated.

- B. The altimeter has two modes of operation: servo and barometric (pressure). An ON-OFF switch knob on the right side of the instrument determines mode of operation. When in the ON position (servo mode), the pressure mechanism operates as a course altitude locating device which is further corrected by an accurate, remote, altitude synchro input to the servo. This input causes the motor to drive the mechanism gearing so that the altimeter indicates the corrected altitude. Integral fault circuitry continuously monitors the barometric altitude sensed by the altimeter and the transmitted altitude from the air data computer. A discrepancy between the barometric and transmitted altitudes beyond acceptable limits will activate the fault circuit to search for synchronization.
- C. Loss of air data computer excitation or monitor, or monitor signal voltage will result in the corrected altimeter reversion to barometric mode. Placing the ON-OFF switch to OFF position removes power to allow only barometric mode operation.
- D. This condition will be noted by the proper mode "notation" in the dial window and is accompanied by a steady altitude pointer indication and will continue until the interrupted power is restored and the altimeter synchronized. During barometric mode of operation, an integral instrument vibrator operates to assist in providing an accurate indication. During servo mode the vibrator is disconnected.
- E. Ground station barometric pressure is available from an interpolating sub-dial or odometer type counter. Calibration is in inches and millibars of mercury and is adjustable by turning the instrument left side knob.

 **German Cargo**
Maintenance Manual DC 8 - 70 Series

Chapter: 34-11-2
 Page: 202
 Date: 23.03.88

Effectivity: UA, UC, UE, UI, UO

2. Adjustment/Test Corrected Altimeter

A. Refer to Air Data System - Section 34-11-0 Maintenance Practices to determine equipment preparation requirements, and observe all CAUTION and NOTES.

(1) Requires connection to pitot and static sources as follows:

(a) When testing captain's corrected altimeter, connect test equipment pressure input to captain's and first officer's pitot tubes. Connect static vacuum to captain's and first officer's static system.

(b) Using approved pressure sensitive tape, seal off pitot tubes drain holes and the static ports.

(2) Place static selector valve to NORM position.

(3) Verify both air data computer, air data computer failure, and corrected altimeter circuit breakers are closed.

(4) Turn instrument ON-OFF switch to the on position; hold for 5 to 10 seconds to enable instrument to function in corrected mode.

(5) Regulate test equipment to maintain airspeed below 300 knots and adjust static pressure to test values shown below. The airplane altimeter, when operating in either corrected or barometric (standby) modes, should agree with test equipment within the respective tolerances. Use ON-OFF switch to check barometric and corrected modes.

CAUTION: THE POSITIVE PRESSURE IN THE PITOT LINES MUST ALWAYS BE GREATER THAN OR EQUAL TO PRESSURE IN THE STATIC LINES.

Test Equipment Altimeter Setting (Feet)

Altimeter Mode

Tolerance (\pm Feet)

0	Barometric (standby)	20
	Corrected	20
1,000	Barometric (standby)	20
	Corrected	20
5,000	Barometric (standby)	35
	Corrected	50
25,000	Barometric (standby)	155
	Corrected	50
35,000	Barometric (standby)	200
	Corrected	70



Effectivity: ADUA; ADUC; ADUE; ADUI; ADUO

- (6) Open air data computer circuit breaker. Corrected altimeter should indicate uncorrected altitude and display appropriate flag. Air data computer fail light should come on in failure annunciator panel. Close circuit breaker and hold ON-OFF switch in ON position for several seconds; corrected altimeter should again indicate corrected altitude.
- (7) Return test equipment to ambient pressure at a rate not greater than 5,000 feet per minute.
- (8) Remove test equipment. Remove all pressure sensitive tape from pitot drain holes and from static ports.
- (9) Instruments failing to operate within the above specified tolerance, should be replaced. The instrument is clamp mounted, has one hose connection, and one electrical connector. For detailed instructions see Section 31-00.
- (10) If any pressure/static lines have been disconnected, perform system leak test (see 34-12-0).



Effectivity: ADUA; ADUE; ADUI; ADUO

AIR TRAFFIC CONTROL TRANSPONDER SYSTEM - MAINTENANCE PRACTICES

1. General

A. The air traffic control transponder system identifies the airplane by transmitting coded signals at 1090 mc when interrogated with coded signals at 1030 mc. The basic system consists of an antenna mounted on lower surface of forward fuselage, two transponders mounted in the radio rack, and a control panel on the overhead switch panel.

2. Tools and Equipment Required

NOTE: Equivalent substitutes may be used instead of the following listed items.

- (1) Transponder/DME Test Set, IFR Model ATC-600A
- (2) Portable pressure equipment to simulate 0 to 35,000 feet altitude and 0 to 400 knots airspeed.

3. Adjustment/Test ATC System

A. Prepare to test ATC system

NOTE: The test set is a source of interference for radio and L-band radar equipment operating on airplanes located in the vicinity of the test set. Turn test set off as soon as the test is completed or when other radio checks are being performed on the airplane.

- (1) Position remote test set antenna approximately 21 inches from ATC antenna for system under test. Test set antenna should be approximately same height as the airplane antenna.

CAUTION: NEVER PLACE REMOTE TEST SET ANTENNA CLOSER THAN 15 INCHES TO THE AIRCRAFT ANTENNA WITH TEST SET "ON". DAMAGE TO THE TEST SET WILL RESULT.

- (2) Route and connect coax from remote test set antenna to Test Set.

- (3) Position controls on test set as follows:

PWR Switch	OFF
Mode Switch	A/C Code
SLS Switch	Center position
Framing Control	0
INTERR Control	0
XPDR SIG Control	FULLY CCW
XMTR FREQ Control	0



Effectivity: ADUA; ADUE; ADUI; ADUO

CAUTION: IN THE FOLLOWING TESTS DO NOT SELECT CODES 3100, 7500, 7600 OR 7700. THESE ARE EMERGENCY CODES.

Note: In the following tests the reply light on the ATC control panel shall illuminate whenever the ATC transponder transmits a reply to the test set, unless otherwise stated. Also, the % reply meter on the test set shall indicate 100 % when the transponder is replying (unless specified otherwise).

B. Test ATC System

(1) Close the following circuit breakers

- (a) ATC-1 Radio Bus - 1 (S46, T46)
- (b) ATC-2 Radio Bus - 4 (I46, J46)
- (c) Air Data Computer Radio Bus - 2 (O54, P54)

(2) Activate ATC system No. 1 in Mode A with ALT RPTG off and code 0000 selected.

(3) After system warm up, press and hold TEST switch on ATC control panel. Verify REPLY light comes on.

(4) Place PWR switch on test set to AC or BAT as appropriate. Test set display shall indicate 0000.

NOTE: For information regarding battery testing, timing and recharging refer to operation section of ATC-600A test set operators manual.

(5) Test receiver sensitivity as follows:

- (a) On test set, verify % REPLY meter indicates 100.
- (b) Slowly rotate XPDR SIG control clockwise until % REPLY meter indicates 90. The XPDR SIG control shall be between 69 and 77 (Note control reading. This is transponder system minimum triggering level.)
- (c) Place ALT RPTG switch on ATC control panel to the No. 1 position and select A/C ALT on test set.
- (d) Repeat step (b). XPDR SIG control reading shall not differ from reading in step (b) by more than 1.
- (e) Return XPDR SIG control fully counter clockwise. Position test set mode switch to A/C CODE.



Effectivity: ADUA; ADUE; ADUI; ADUO

(6) Test Side Lobe Suppression as follows:

- (a) Adjust the XPDR SIG control on test set to 3 db above minimum triggering level. (The control reading in step 5.(b) minus 3).

NOTE: If the transponder's sensitivity is near the insensitive limit, it may be necessary to move antennas closer together in order to get 3 db above minimum triggering level. At closer than normal antenna spacing, re-establish the dial setting for MTL and adjust the dial 3 db above MTL and make the SLS test.

- (b) Position SLS switch on test set to 0 db. Transponder shall stop all replies.
- (c) Position SLS switch on test panel to -9 db. Transponder shall reply to at least 90% (minimum) to 100% as indicated on test set % REPLY meter.
- (d) Turn test set XPDR SIG control fully counterclockwise.

(7) Test transmitter frequency as follows:

- (a) Set test set FREQ/POWER meter switch to FREQ.
- (b) On ATC control panel, select code 0000 and position ALT RPTG switch to OFF.
- (c) Adjust gain control on test set for a mid-scale indication of FREQ/POWER meter. Rotate frequency control for a peak indication of meter. Frequency control dial shall read 0 ± 3 .

- (8) On ATC control panel, rotate code selector knobs to any code desired. Test set numerical display should readout selected code.

- (9) Change code selection on ATC control panel to test code compliment. Compliment of test code is 7777 minus test code being used. This checks full code capability of transponder under test.

EXAMPLE: If test code being used is 0340, compliment is

$$\begin{array}{r} 7777 \\ -0340 \\ \hline 7347 \text{ compliment} \end{array}$$

- (10) On ATC control panel, activate IDENT. IDENT lamp on test set should come on.

Effectivity: UA, UE, UI, UO

(11) Test altitude reporting as follows.

- (a) On ATC control panel, place ALT RPTG switch to No. 1 position.
- (b) Connect air data test set to FIO'S (No.2) PITOT/STATIC system
- (c) Position test set mode switch to A/C ALT.

NOTES: 1. In A/C position, numerical display of test set will indicate airplane altitude in thousand feet, being reported by transponder.

2. In following tests ALT INVALID light shall remain off. When on, light indicates an unassigned altitude code is being transmitted.


(d) Using air data test set, apply a static pressure to obtain altitude reading on test set as specified in following table. Verify captain's altimeter indicates ± 100 feet of test altitude.

T A B L E

ALTITUDE REPORTING TEST ALTITUDES

<u>ALT Feet</u>	<u>CODE</u>
1,000	0320
4,100	4730
15,000	3440
31,000	1024

(12) Repeat steps B. (1) thru B. (11) for No. 2. ATC transponder (if installed).




2.11.06 Left and right elevators overhauled by Northwings Repair Station were installed by Tennessee Tech on RRXA aircraft N8084U, during the course of a "D" check. During the course of this same "D" check, numerous non-routine cards were generated against these elevators. The overhaul of the elevators was not done in accordance with 14CFR 43.2, which requires that the item be disassembled, cleaned, inspected and repaired as necessary.

RRXA RESPONSE: *The finding is correct in that the elevator overhauled by Northwings Repair Station was unsatisfactory. This is evident based on the number of non-routine cards prepared by Tennessee Technical Services, during their QC acceptance check. The elevator was not installed on the aircraft until all non-routine items were corrected.*

EWA's Director of Heavy Maintenance was at Tennessee Tech. When this elevator was returned from overhaul and he addressed the QC findings with Northwing at that time.

EWA and Tennessee Tech procedures worked.

RRXA CONCLUSION: *No finding*


Bill Owens
EWA Director-Quality Assurance

09 February 2001



U. S. Department
of Transportation

Federal Aviation
Administration


cc: Jerry Sumiaco
Jim Owens
Bob Dell

FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

February 12, 2001

FILE NUMBER: 2001GL050031

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377



Dear Mr. Scott:

On January 22, 2001, you were advised that the Federal Aviation Administration was investigating a possible violation of a Federal Aviation Regulation involving Emery Worldwide Airlines Inc. Certificate (RRXA). The alleged violation was, the left and right elevators overhauled by Northwings Repair Station were installed by Tennessee Tech on RRXA aircraft N8084U during the course of a "D" check. During the course of this same "D" check numerous non-routine cards were generated against these elevators. The overhaul of the elevators was not done in accordance with 14CFR 43.2, which requires that that the item be disassembled, cleaned, inspected and repaired as necessary.

This letter is to inform you that the investigation has not established a violation of the Federal Aviation Regulations and you may consider this matter closed.

Sincerely,

Leslie Korody
Principal Avionics Inspector

Chaplin, Tracy L

From: Mike Jarm [REDACTED]
Sent: Tuesday, July 25, 2000 4:20 PM
To: 'Chaplin, Tracy [REDACTED]'; 'Basine, Jennifer [REDACTED]'
Subject: FW: Elevator

Tracy / Jennifer:

Please review the following information that was passed along to me from our QC Department this afternoon. When the elevator is release back to Emery will you still require another unit ? I would like a copy of Tennessee Tech receiving inspection report for our records on this unit when this information is available. Please do not hesitate to contact me if there are any questions.

Mike

2.11.06

> -----Original Message-----

> From: Tom Carroll
> Sent: Tuesday, July 25, 2000 4:04 PM
> To: Mike Jarm
> Cc: Al Frase; Steve Destefano; Matthew Murrin; Mike Lefebvre; Caryn Lapinski; Paul Nemeth; Bill Cote
> Subject: Elevator

> Mike

> The elevator was not in quarantine, but on hold pending an investigation by the FAA for possible non compliance with the Federal Aviation Regulations.

> The elevator was balanced today with the FAA observing the entire process. It will require three 1.17 weight to bring in into acceptable limits.

> The FAA did not state that unapproved parts or military parts were used. They based their decision on the receiving inspection accomplished by TN Tech.

> The control service will be release to service after Tn Tech performs the required maintenance and installed on the aircraft.

> Thomas Carroll

3.51 LBS PUTS IT ON THE
EDGE OF BAL.

MID. RANGE BAL WOULD TAKE
APPOX 6 LBS.

OPEN W.O. TO BAL SEND TOTAL
COST TO TRACY.

TENNESSEE TECHNICAL SERVICES, L.L.C.

634 Fitzhugh Boulevard Smyrna, TN 37167
 TELEPHONE: 615-223-7801 FAX: 615-223-0373
 CRS T64R1640 CRS T64R1640

DISPOSITION REPORT (Tear Down)

Page: 1

FOR:	YOUR P.O. No....: 1376/12556
EMERY WORLDWIDE AIR SERVICES ONE EMERY PLAZA VANDALIA, OH 4537 TEL.: 937-415-7624 FAX.: 937-415-7630	WORK ORDER DATE: Jul03-2000 DUE: Jul09-2000 STATUS/WORK.....: REPAIRED Aircraft RN.....: N991CF
Terms: UPON RECEI:1 COND:RE
Part Number.:55972	IAL #:EB0001
Description.:CYLIN	CE TO:1376/12556
Manufacturer:	DATE:07/03/00
	00637 (WO)

*FYI
Tear down on Tab
lock out cylinder.*

*Removed from
8084 left inboard
Aileron -*

REPORTED BY CUSTO
LT AILERON TAB LC
IRAN

TRACT FULLY REQUIRES

PRELIMINARY INSP
DISASSEMBLED, CLEANED
PISTON NOT TO RETRACT FULLY.

STALLED IMPROPERLY CAUSING

CORRECTIVE ACTION.....:
REPAIRED BY INSTALLING PISTON PROPERLY, LEAK AND OPS CHECKED GOOD IAW DC-8 OHM
-3-6

Item	Part Number / Description	Qty	COND	Discrepancy	Disposition
Parts & Material					
1	NAS1611-216 O-RING	1	NE		
2	MS28774-216 RETAINER	1	NE		
3	AN815-4 UNION	1	NE		

The aircraft, airframe, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Agency and is approved for service. Pertinent details of the repair are on file at the repair station under

Order No.: 500637 Date: 7-03-00

Signed: [Signature]
 Tennessee Technical Services, L.L.C.
 634 Fitzhugh Boulevard
 Smyrna, Tennessee 37167
 T64R1640

8130-3 Attached

Accomplished By [Signature] Emp# [Redacted] Insp By [Signature] Date 7-03-00



DOUGLAS AIRCRAFT CO., INC

DC-B OVERHAUL MANUAL

6. Assembly (see Figure 3)

NOTE: For special tool and installation procedures for slipper rings (22A and 39A) see Chapter 13.

- A. Install packing (40A) in barrel (44), and insert slipper ring (39A) with special tool.
- B. Install fitting (36) in rod (38) and slide rod assembly (36, 37, and 38) in barrel (44).

NOTE: If replacement of bearing (37) in rod (38) is necessary, press in and stake new one. Apply 50 pounds force to test staking effectiveness.

- C. Install expander (33), piston rings (32), and pin (31) on piston (34) and slide assembled piston in barrel (44) and on rod (38).

CAUTION: MAKE CERTAIN PISTON (34) IS INSTALLED ON ROD (38) WITH HOLLOW PORTION OF PISTON (34) CUPPER ON ROD (38).

- D. Fasten piston (34) on rod (38) with washer (30) and nut (29), and tighten to 20 (± 2) foot-pounds.

- E. Apply antiseize lubricant (MIL-T-5544) to threads, install packing (27) and retainer (26) on barrel end (28), and install assembled end in barrel (44) with special tool (see Section 27-3-3 Figure 3).

- F. Install slide (43) in barrel (44) and position spring (21) against slide (43).

- G. Install gasket (20) on stop (19) and install in barrel (44). (Typical in two places).


- H. Install packings (23A) in glands (24 and 25), insert slipper rings (22A) with special tool and slide assembled gland on barrel (44).

NOTE: Step H is typical two places.

- I. Align holes in support (16) with holes in glands (24 and 25) and fasten with bolts (12 and 13), washers (14) and nuts (15).
- J. Install bolt (11), washer (14), and nut (15) on gland (24) and support (16).
- K. Install bolt (3), washer (5), spacer (4), link (10), washer (5), and nut (6).

(See NOTE on Page 4)

DOUGLAS AIRCRAFT CO., INC
DC-8 OVERHAUL MANUAL



118-221B

Aileron Tab Lockout Cylinder Assembly
Figure 3

ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
CRS T64R1640

W/O NO. 1512	TASK NO. 3A055
A/C TYPE/MODEL DC-8-71	A/C TAIL NO. N80544
CUSTOMER REQUEST? YES (NO/CIRCLE ONE)	

LOCATION (CIRCLE ONE) LEFT CABIN RT WING	TAIL LG & WW	ENG. DOORS/HATCHES	FUNCTION: (CIRCLE ONE) MECH ELEC RADIO S/M CLEAN NDT INSP PAINT CABIN SHOP
---	-----------------	-----------------------	---

DESCRIPTION
 LT GEAR TAB I/B + O/B (control Rod end)

has CORROSION

34010	WRITTEN BY: G. Blue	EMP. NO. 126	DAY 17	MO 05	YR 00
-------	------------------------	-----------------	-----------	----------	----------

(CIRCLE ACTIONS TO BE TAKEN)

CHECK	LUBE	SERVICE	TREAT	PAINT	REMOVE	REPAIR	TIGHTEN	SECURE	STOW	REPLACE	RESET	TEST	ADJUST
-------	------	---------	-------	-------	--------	--------	---------	--------	------	---------	-------	------	--------

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DALC DC-8 SRM A.T.A. 51-1-8

BY G. Blue	EMP. NO. 011	O.T. AUTH. (CIRCLE) YES (NO)	PARTS AUTH. (CIRCLE) YES (NO)	REQD INSPN ITEM YES (NO) (CIRCLE)	CUSTOMER APPROVAL 2.0
---------------	-----------------	---------------------------------	----------------------------------	--------------------------------------	--------------------------

ACTION
 REMOVED CORROSION ON LH GEAR TAB INBD AND OUT BD ROD END'S

DC-8 SRM 51-1-8 Traded with LPS 2

BY G. Blue	EMP. NO. 011	SUPERVISOR/LEAD RECHECK G. Blue	EMP. NO.	CHECKED BY 28	DAY 19	MO 05	YR 00
---------------	-----------------	------------------------------------	----------	------------------	-----------	----------	----------



ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC						TASK NO.	
CRS T64R1640						3A056	
LOCATION (CIRCLE ONE)		FUNCTION: (CIRCLE ONE)		AVG TYPE MODEL		AVG TAIL NO.	
CABIN RT WING		MECH ELEC RADIO S/M CLEAN NDT INSP PAINT CABIN SHOP		DC-8-71		N80841P	
TAIL LG & WW		ENG. DOORS/HATCHES		CUSTOMER REQUEST? YES NO (CIRCLE ONE)			
DESCRIPTION LT GEAR TAB OIB eye bolt has 1 thread engagement							
DATE: 34010		WRITTEN BY: EWA		EMP. NO. 126		DAY MO YR 17 05 00	
ACTION (CIRCLE ACTIONS TO BE TAKEN)							
CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST							
REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DACO DC-8 mm A.T.A. 27-30-3							
INSTRUCTIONS							
PERFORMED BY: [Signature]		EMP. NO. 519209349m		O.T. AUTH (CIRCLE) YES NO		PARTS AUTH (CIRCLE) YES NO	
REQD INSPN ITEM (YES) NO (CIRCLE)		CUSTOMER APPROVAL		4097			
POSITIVE ACTION							
REMOVED upper elevator trim TAB JAW DC-8 mm 27-30-3 Paul Wright							
28 INSP REMOVED AND REPLACED eye bolt with LH TAB OTBD. JAW DC-8 mm 27-30-3							
O. Paul Wright AA 515520394 OK TO INSTALL OTBD LH TRIM TAB Elev. 28 INSP							
FILED LH OTBD Elev. Trim TAB JAW DC-8 mm 27-30-3							
PART NUMBER "OFF" SER.#		PART NUMBER "ON" SER.#		PART NUMBER "OFF" SER.#		PART NUMBER "ON" SER.#	
-SE1-502 NSW		SMDK-501-504 NSW					
PERFORMED BY: [Signature]		EMP. NO. [Redacted]		SUPERVISOR/LEAD RECHECK [Signature]		EMP. NO. [Redacted]	
CHECKED BY: R11		DATE: 19 05 00		ITS 28 INSP			

ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC

26

CRS T64R1640

TASK NO.

3A 057

W/O NO.
1542

LOCATION (CIRCLE ONE)

ICT

CABIN
RT WING

TAIL
LG & WW

ENG.
DOORS/HATCHES

FUNCTION: (CIRCLE ONE)

MECH ELEC RADIO S/M CLEAN
 NDT INSP PAINT CABIN SHOP

A/C TYPE: MODEL
DC-8-71F

A/C TAIL NO.
N80844

CUSTOMER REQUEST? YES NO (CIRCLE ONE)

DESCRIPTION

"5" panel on lower side of LH ele has bare metal (panel was not treated and primed at

tail)

EWA

3601

WRITTEN BY:

EMP. NO.

DAY MO YR
16 05 00

WORK (CIRCLE ACTIONS TO BE TAKEN)

CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DACO DC-8 SRM A.T.A. 51-1-8
INSTRUCTIONS CHPT SECT SUBJ

WRITTEN BY:

EMP. NO.

O.T. AUTH. (CIRCLE)
YES NO

PARTS AUTH. (CIRCLE)
YES NO

REQD. INSTR. ITEM
YES NO (CIRCLE)

CUSTOMER APPROVAL
2.0

REVISION

Removed paint and prep'd for treat and prime IAW DC-8 SRM 51-1-8
K TO TREAT AND PRIME TREAT AND PRIME IAW DC-8 SRM 51-1-8

TTS
28
INSP.

SER "OFF"	SER #	PART NUMBER "ON"	SER #	PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #
-----------	-------	------------------	-------	-------------------	-------	------------------	-------

SHED BY

EMP. NO.

SUPERVISOR/LEAD RECHECK

EMP. NO.

CHECKED BY

23

DAY MO YR
20 5 00

ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
 CRS T64R1640

TASK NO.
 3A 058

W/O NO. 1942	A/C TYPE MODEL DC-8-71F	A/C TAIL NO. N30344
FUNCTION: (CIRCLE ONE) MECH ELEC RADIO <u>SM</u> CLEAN	CUSTOMER REQUEST? YES <input checked="" type="checkbox"/> (CIRCLE ONE)	

DESCRIPTION
 Lt and Rt elec mount bushings need to be sized IAW overhaul manual

35030/35040 **EWA** WRITTEN BY: [Signature] EMP. NO. [Redacted] DAY 18 MO 05 YR 00

(CIRCLE ACTIONS TO BE TAKEN)
 CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DACO DC-8 OHM A.T.A. 27-16-1
 INSTRUCTIONS CHPT SECT SUBJ 40

BY [Signature]	EMP. NO. <u>046</u>	O.T. AUTH. (CIRCLE) YES () NO ()	PARTS AUTH. (CIRCLE) YES () NO ()	REQD. INSPN ITEM YES () NO (CIRCLE)	CUSTOMER APPROVAL <u>2.0/3</u>
----------------	---------------------	---------------------------------------	--	---	--------------------------------

ACTION
 Sized LT and RT elec mount bushings IAW DC 8 OHM 27-16-1. Rechecked to .4435 IAW 279 DC8 OHM 27-16-1.

ORDER "OFF" SER #	PART NUMBER "ON" SER #	PART NUMBER "OFF" SER #	PART NUMBER "ON" SER #
ORDERED BY [Signature]	EMP. NO. <u>219</u>	SUPERVISOR/LEAD RECHECK [Signature]	EMP. NO. [Redacted] CHECKED BY: [Signature]
		115 23 INSPECTION DAY 15 MO 6 YR 00	

NON-ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC							TASK NO.				
FORM NO. 26							CRS T64R1640			W/O NO. 1542	3A059
ITEM LOCATION (CIRCLE ONE) FUSE STRUCT CABIN <input type="checkbox"/> LT WING <input type="checkbox"/>			CABIN <input type="checkbox"/> RT WING <input type="checkbox"/>		ENG. <input type="checkbox"/> LG & WW <input checked="" type="checkbox"/>		FUNCTION: (CIRCLE ONE) <input checked="" type="checkbox"/> MECH <input type="checkbox"/> ELEC <input type="checkbox"/> RADIO <input type="checkbox"/> S/M <input type="checkbox"/> CLEAN <input type="checkbox"/> NDT <input type="checkbox"/> INSP <input type="checkbox"/> PAINT <input type="checkbox"/> CABIN <input type="checkbox"/> SHOP			A/C TYPE MODEL 11-8-77	A/C TAIL NO. 180844
ITEM DESCRIPTION LH Elev GEAR TAB Crank arms upside DOWN											
S/N 0277			EWA			WRITTEN BY: <i>[Signature]</i>		EMP. NO. 126		DAY MO YR 14 05 00	
EVALUATION (CIRCLE ACTIONS TO BE TAKEN) CLEAN <input type="checkbox"/> CHECK <input type="checkbox"/> LUBE <input type="checkbox"/> SERVICE <input type="checkbox"/> TREAT <input type="checkbox"/> PAINT <input type="checkbox"/> REMOVE <input checked="" type="checkbox"/> REPAIR <input type="checkbox"/> TIGHTEN <input type="checkbox"/> SECURE <input checked="" type="checkbox"/> STOW <input type="checkbox"/> REPLACE <input type="checkbox"/> RESET <input type="checkbox"/> TEST <input type="checkbox"/> ADJUST <input checked="" type="checkbox"/>											
REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DACO DC-8 mm A.T.A. 27-30-3											
SPECIAL INSTRUCTIONS Reinstall											
EVALUATION BY <i>[Signature]</i>		EMP. NO. 126		O.T. AUTH (CIRCLE) YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		PARTS AUTH (CIRCLE) YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		REQD INSPN ITEM YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		CUSTOMER APPROVAL 1.0	
CORRECTIVE ACTION Removed and replaced LH elev gear tab crank arms IAW DACO DC-8 mm 27-30-3 See NA 1542-6A122 For cert's											
PART NUMBER "OFF" 4710 541		SER # NSN		PART NUMBER "ON" 3802767-3		SER # NSN		PART NUMBER "OFF" 4710 542		SER # NSN	
ACCOMPLISHED BY <i>[Signature]</i>		EMP. NO. 166		SUPERVISOR/LEAD RECHECK <i>[Signature]</i>		EMP. NO.		CHECKED BY: 23		DAY MO YR 6 6 00	

NON-ROUTINE WORK CARD				TENNESSEE TECHNICAL SERVICES, LLC				FORM NO. 26		TASK NO.				
				CRS T64R1640				W/O NO. <u>1542</u>		<u>3A 3006</u>				
ITEM LOCATION (CIRCLE ONE)			FUNCTION: (CIRCLE ONE)			AC TYPE/MODEL		AC TAIL NO.						
FUSE STRUCT	CABIN	<input checked="" type="radio"/> TAIL	ENG.	<input checked="" type="radio"/> MECH	<input type="radio"/> ELEC	<input type="radio"/> RADIO	<input type="radio"/> S/M	<input type="radio"/> CLEAN	<u>DC-8-11</u>		<u>1120844</u>			
LT WING	RT WING	LG & WW	DOORS/HATCHES	<input type="radio"/> NOT	<input type="radio"/> INSP	<input type="radio"/> PAINT	<input type="radio"/> CABIN	<input type="radio"/> SHOP	CUSTOMER REQUEST? YES <input type="radio"/> NO <input checked="" type="radio"/> (CIRCLE ONE)					
ITEM DESCRIPTION														
<u>LH Elev Geared Tab IB Crank arm has</u>														
<u>2 cracks</u>														
EWA														
Ref: <u>3503D</u>				WRITTEN BY: <u>[Signature]</u>				EMP. NO. <u>126</u>		DAY <u>24</u> MO <u>05</u> YR <u>00</u>				
EVALUATION (CIRCLE ACTIONS TO BE TAKEN)														
CLEAN	CHECK	LUBE	SERVICE	TREAT	PAINT	<input checked="" type="radio"/> REMOVE	REPAIR	TIGHTEN	SECURE	STOW	<input checked="" type="radio"/> REPLACE	RESET	TEST	ADJUST
REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) <u>DACU DC-8 MM</u> A.T.A. <u>27-30-3</u>														
SPECIAL INSTRUCTIONS														
EVALUATION BY: <u>[Signature]</u>														
EMP. NO. <u>5190</u>		O.T. AUTH (CIRCLE) YES <input type="radio"/> NO <input checked="" type="radio"/>		PARTS AUTH (CIRCLE) YES <input type="radio"/> NO <input checked="" type="radio"/>		REQD INSPN ITEM YES <input type="radio"/> NO <input checked="" type="radio"/> (CIRCLE)		CUSTOMER APPROVAL <u>[Signature]</u>						
CORRECTIVE ACTION														
<u>Removed and replaced LH elev geared tab IB crank arm IAW DACU</u>														
<u>DC-8 mm 27-30-3 See NR 1542-6A122 for certis</u>														
PART NUMBER "OFF" SER # PART NUMBER "ON" SER # PART NUMBER "OFF" SER # PART NUMBER "ON" SER #														
<u>4710541</u>		<u>NSN</u>		<u>3802767-4</u>		<u>NSN</u>								
ACCOMPLISHED BY: <u>[Signature]</u>		EMP. NO. <u>166</u>		SUPERVISOR/LEAD RECHECK: <u>[Signature]</u>		EMP. NO. <u>[Signature]</u>		CHECKED BY: <u>RH</u>		TTS 23 INSP				
		DAY <u>6</u>		MO <u>6</u>		YR <u>00</u>								

NON-RC
FORM NO. 26

WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
CRS T64R1640

TASK NO.

W/O NO.
1542

3A 06/16/00

TYPE LOCATION (CIRCLE ONE)

FUSE STRUCT
LT WING

CABIN
RT WING

TAIL
LG & WW

ENG.
DOORS/HATCHES

FUNCTION: (CIRCLE ONE)

MECH
ELEC RADIO S/M CLEAN
NDT INSP PAINT CABIN SHOP

A/C TYPE: MODEL
DC-8-71

A/C TAIL NO.
N30846

CUSTOMER REQUEST? YES (CIRCLE ONE)

ITEM DESCRIPTION

LH elevator requires balance for installation of steel crank arms

Ref: 1542-6A-122

EWA

WRITTEN BY:

EMP. NO.

DAY MO YR
05 06 00

EVALUATION (CIRCLE ACTIONS TO BE TAKEN)

CLEAN CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC.) DACO DC-8 SRM A.T.A. 51-4-4
SPECIAL INSTRUCTIONS CHPT SECT SUBJ

EVALUATION BY

EMP. NO.

O.T. AUTH (CIRCLE)
YES NO

PARTS AUTH (CIRCLE)
YES NO

REQD INSPN ITEM
(YES) NO (CIRCLE)

CUSTOMER APPROVAL
20,9

CORRECTIVE ACTION

Balanced LH elevator IAW DACO DC-8 SRM 51-4-4. New moment is 1450.8 inch-pounds and is within limits IAW DACO DC-8 SRM 51-4-4

PART NUMBER "OFF"

SER #

PART NUMBER "ON"

SER #

PART NUMBER "OFF"

SER #

PART NUMBER "ON"

SER #

ACCOMPLISHED BY

EMP. NO.

SUPERVISOR/LEAD RECHECK

EMP. NO.

CHECKED BY:

TTS
27
INSP

DAY MO YR
16 06 00

NON-ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
 FORM NO. 26 **CRS T64R1640**

W/O NO. 1542

TASK NO. 3A 065

ITEM LOCATION (CIRCLE ONE)

FUSE STRUCT CABIN
 LT WING RT WING

TAIL
 LG & WW

ENG. _____
 DOORS/HATCHES

FUNCTION: (CIRCLE ONE)
 MECH ELEC RADIO CLEAN
 NDT INSP PAINT CABIN SHOP

A/C TYPE: MODEL

DC-8

A/C TAIL NO.

N60844

CUSTOMER REQUEST? (YES/NO (CIRCLE ONE))

ITEM DESCRIPTION

Left hand elevator 2 each fairings missing at STA xE 149.00

EWA

WRITTEN BY: [Signature]

EMP. NO. 219

DAY MO YR 14 06 00

EVALUATION (CIRCLE ACTIONS TO BE TAKEN)

CLEAN CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC)

DC-8 SR

A.T.A. 51-1-4

SPECIAL INSTRUCTIONS

Machine fairings

CHPT SECT SUBJ 6.0 hr

EVALUATION BY: [Signature]

EMP. NO. 219

O.T. AUTH (CIRCLE)
 YES NO

PARTS AUTH (CIRCLE)
 YES NO

REQD INSPN ITEM
 YES NO (CIRCLE)

CUSTOMER APPROVAL [Signature] 10.0

CORRECTIVE ACTION

FABRICATED FAIRINGS IAW. DC-8 S.R.M. 51-1-4 MATERIAL
IS .063 P.O.# 2024 T3 P.O.# 8967 O.K. TO TREAT & PRIME
TREAT & PRIME IAW. DC-8 SRM. 51-1-8
O.K. TO INSTALL
INSP
IN STALLED IAW. DC-8 SRM. 51-3-0
FAIRINGS

ITS
 23
 INSP

PART NUMBER "OFF"

SER #

PART NUMBER "ON"

SER #

PART NUMBER "OFF"

SER #

PART NUMBER "ON"

SER #

ACCOMPLISHED BY: [Signature]

EMP. NO. 9194

SUPERVISOR/LEAD RECHECK [Signature]

EMP. NO.

CHECKED BY: [Signature]

ITS
 23
 INSP

DAY MO YR 20 06 00

NON-ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
FORM NCR 26 **CRS T64R1640**

W/O NO. 1542 TASK NO. 3A 064

ITEM LOCATION (CIRCLE ONE) CABIN LG & WW ENG. _____ DOORS/HATCHES _____

FUNCTION: (CIRCLE ONE) MECH _____ ELEC _____ RADIO CLEAN _____ NDT _____ INSP _____ PAINT _____ CABIN _____ SHOP _____

A/C TYPE: MODEL DC-8 A/C TAIL NO. N80544

CUSTOMER REQUEST? YES NO (CIRCLE ONE)

ITEM DESCRIPTION Left hand elevator fairing missing at St-A X E 221

EWA

WRITTEN BY: [Signature] EMP. NO. 219 DAY 14 MO 06 YR 00

EVALUATION (CIRCLE ACTIONS TO BE TAKEN)

CLEAN _____ CHECK _____ LUBE _____ SERVICE _____ TREAT _____ PAINT _____ REMOVE _____ REPAIR _____ TIGHTEN _____ SECURE _____ STOW REPLACE _____ RESET _____ TEST _____ ADJUST _____

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DC8 SR A.T.A. 51-1-4

SPECIAL INSTRUCTIONS machine fairing CHPT _____ SECT _____ SUBJ 3.0

EVALUATION BY: [Signature] EMP. NO. 219 O.T. AUTH (CIRCLE) YES NO PARTS AUTH (CIRCLE) YES NO REQD INSPN ITEM YES NO (CIRCLE) _____ CUSTOMER APPROVAL [Signature] 8.0

CORRECTIVE ACTION

FABRICATED FAIRINGS IAW DC-8 SRM. 51-1-4 MATERIAL

IS .063 2024 T3 P.O. # 8967 OK. TO TREAT & PRIME **23 INSP**

TREAT & PRIME IAW DC-8 SRM. 51-1-8

OK. TO INSTALL **23 INSP**

INSTALLED IAW DC-8 SRM. 51-3-0

FAIRINGS

PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #	PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #

ACCOMPLISHED BY: [Signature] EMP. NO. 9194 SUPERVISOR/LEAD RECHECK: [Signature] EMP. NO. _____ CHECKED BY: [Signature] **23 INSP** DAY 20 MO 06 YR 00

ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
CRS T64R1640

W/O NO. 1542	TASK NO. 3A067
A/C TYPE: MODEL DC 8	A/C TAIL NO. N80844
CUSTOMER REQUEST? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (CIRCLE ONE)	

ON (CIRCLE ONE) <input type="checkbox"/> CABIN <input type="checkbox"/> RT WING	<input checked="" type="checkbox"/> TAIL LG & WW	ENG. DOORS/HATCHES	FUNCTION: (CIRCLE ONE) <input type="checkbox"/> MECH <input type="checkbox"/> ELEC <input type="checkbox"/> RADIO <input checked="" type="checkbox"/> CLEAN <input type="checkbox"/> NDT <input type="checkbox"/> INSP <input type="checkbox"/> PAINT <input type="checkbox"/> CABIN <input type="checkbox"/> SHOP
---	---	-----------------------	--

DESCRIPTION
 Left hand elevator 2 each fairings missing at 9A XE 272

EWA

WRITTEN BY: D. B. Smith	EMP. NO. 219	DAY 14	MO 06	YR 00
----------------------------	-----------------	-----------	----------	----------

(CIRCLE ACTIONS TO BE TAKEN)

CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DC 8 SRM A.T.A. 51-1-4
 INSTRUCTIONS Machine 2 ea fairings CHPT SECT SUBJ 60 hr

BY <u>D. B. Smith</u>	EMP. NO. 219	O.T. AUTH (CIRCLE) <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	PARTS AUTH (CIRCLE) <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	REQD INSPN ITEM <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (CIRCLE)	CUSTOMER APPROVAL <u>SR</u> 10.0
-----------------------	-----------------	---	--	---	-------------------------------------

ACTION
 REPLICATED FAIRINGS IAW DC-8 SRM. 51-1-4 MATERIALS
 063 2024 T3 RO.# 8967 OK TO TREAT + PRIME
 T + PRIME IAW DC-8 SRM. 51-1-8
 TO INSTALL
 TAILLED IAW DC-8 SRM. 51-3-0
 Fairings

SER #	SER #	PART NUMBER "ON"	SER #	PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #	
BY <u>D. B. Smith</u>	EMP. NO. 219	SUPERVISOR/LEAD RECHECK <u>[Signature]</u>	EMP. NO. 219	CHECKED BY: <u>[Signature]</u>	INS 23	DAY 14	MO 06	YR 00

ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
CRS T64R1640

W/O NO. 1542

TASK NO. 3A 068

WING (CIRCLE ONE)

CABIN
RT WING

TAIL
LG & W/W

ENG.
DOORS/HATCHES

FUNCTION: (CIRCLE ONE)
 MECH ELEC RADIO ND CLEAN
 NDT INSP PAINT CABIN SHOP

A/C TYPE: MODEL
DC-8

A/C TAIL NO.
N80844

CUSTOMER REQUEST? YES NO (CIRCLE ONE)

DESCRIPTION
 Left hand elevator fairing missing at STA XE 77.00

EWA

WRITTEN BY: *Greg P. H...*

EMP. NO. 219 DAY MO YR 14 06 00

(CIRCLE ACTIONS TO BE TAKEN)

CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DC8 SR. 51-1-4 A.T.A. 51-1-4

FUNCTIONS Machining fairing CHPT SECT SUBJ 30 hrs

BY *Greg P. H...* EMP. NO. 219 O.T. AUTH (CIRCLE) YES NO PARTS AUTH (CIRCLE) YES NO REQD INSPN ITEM YES NO (CIRCLE) CUSTOMER APPROVAL SAJ 8.0

ACTION
 LOCATED FAIRINGS I.A.W. DC-8 SR.M. 51-1-4 MATERIAL
 263 2024 T3 P.O. # 8967 O.K. TO TREAT & PRIME **TTS 23 INSP**
 4T & PRIME I.A.W. DC-8 SR.M. 51-1-8 **TTS 23 INSP**
 TO INSTALL

ALL I.A.W. DC-8 SR.M. 51-30
 1/22/05

OFF	SER #	PART NUMBER ON	SER #	PART NUMBER OFF	SER #	PART NUMBER ON	SER #

ED BY: *Bowal* EMP. NO. 9194 SUPERVISOR/LEAD RECHECK *[Signature]* EMP. NO. [Redacted] CHECKED BY: **TTS 23 INSP** DAY MO YR 20 06 00

NON-ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC

FORM NO. 26

CRS T64R1640

TASK NO.

W/O NO.

1542

3A 069

ITEM LOCATON (CIRCLE ONE)

FUSE/STRUCT

CABIN

TAIL

ENG.

FUNCTION: (CIRCLE ONE)

MECH

ELEC

RADIO

S/M

CLEAN

A/C TYPE: MODEL

DC8-71F

A/C TAIL NO.

NB084U

LT WING

RT WING

LG & WW

DOORS/HATCHES

NDT

INSP

PAINT

CABIN

SHOP

CUSTOMER REQUEST? YES (NO) (CIRCLE ONE)

ITEM DESCRIPTION

RT ELEV. L/E AT STA XE 120 HAS A DENT

REF 30

EWA

WRITTEN BY:

[Signature]

EMP. NO.

280

DAY

14

MO

06

YR

00

EVALUATION (CIRCLE ACTIONS TO BE TAKEN)

CLEAN

CHECK

LUBE

SERVICE

TREAT

PAINT

REMOVE

REPAIR

TIGHTEN

SECURE

STOW

REPLACE

RESET

TEST

ADJUST

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC)

SFM / EO 00-107

A.T.A.

SPECIAL INSTRUCTIONS

Check limits, repair if required - Eval time for checking ord eng.

CHPT

SECT

SUBJ

3.00.00

EVALUATION BY:

[Signature]

EMP. NO.

259

O.T. AUTH (CIRCLE)

YES (NO)

PART AUTH (CIRCLE)

YES (NO)

REQD INSPN ITEM

YES (NO) (CIRCLE)

CUSTOMER APPROVAL

CORRECTIVE ACTION

Dent is acceptable to return to service TAW EO 00-107 3A069

PART NUMBER "OFF"

SER #

PART NUMBER "ON"

SER #

PART NUMBER "OFF"

SER #

PART NUMBER "ON"

SER #

ACCOMPLISHED BY

[Signature]

EMP. NO.

259

SUPERVISOR/LEAD TECH

[Signature]

EMP. NO.

CHECKED BY:

R11

TTS

23

DAY

19

MO

6

YR

00

3A070 80

ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC
CRS T64R1640

W/O NO. 1342
TASK NO. 070
3A 136
A/C TYPE: MODEL 508-77
A/C TAIL NO. N80840
CUSTOMER REQUEST? YES NO (CIRCLE ONE)

LOCATION (CIRCLE ONE)
T CABIN (TAIL) LG & WW
RT WING
ENG. DOORS/HATCHES
FUNCTION: (CIRCLE ONE)
MECH ELEC RADIO (SIM) CLEAN
NDT INSP PAINT CABIN SHOP

DESCRIPTION
Left Elev Previous Repair Separated Upper T/E Pul. Just
+ Tab

WRITTEN BY: [Signature]
EMP. NO. 039 DAY 04 MO 06 YR 00

(CIRCLE ACTIONS TO BE TAKEN)

CHECK LUBE SERVICE TREAT PAINT REMOVE (REPAIR) TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DC8 SRM
INSTRUCTIONS Chat Damage - fb doubler.
A.T.A. 55-2-0 8.0
CHPT SECT SUBJ

BY: [Signature] EMP. NO. 257 O.T. AUTH. (CIRCLE) YES (NO) PARTS AUTH. (CIRCLE) YES (NO) REQD INSPN ITEM YES/NO (CIRCLE) CUSTOMER APPROVAL [Signature]

ACTION
Removed damage IAW DC8 SRM 55-2-0. Fabricated filler & doubler.
Oile 7075-T6 PO#009120 IAW DC8 SRM 51-4. OK to treat & prime.
primed filler & doubler IAW DC8 SRM 51-4. Weight of repair is .007 grams.
Install (INS) INSTALLED Filler & doubler IAW DC8-SERP 55-2-0
OF PREVIOUS REPAIR = weight of NEW REPAIR .007 GR WEIGHT +
ICE NEGLIGIBLY IAW DC8 SRM 51-4-8

REPAIR "OFF" SER # PART NUMBER "ON" SER # PART NUMBER "OFF" SER # PART NUMBER "ON" SER #

REQD BY [Signature] EMP. NO. 133 SUPERVISOR/LEAD RECHECK [Signature] EMP. NO. CHECKED BY [Signature] (INS) DAY 16 MO 06 YR 00

NON-ROUTINE WORK CARD **TENNESSEE TECHNICAL SERVICES, LLC**
 FORM NO. 26 **CRS T64R1640**

023

ITEM LOCATION (CIRCLE ONE) FUSE STRUCT LT WING		CABIN RT WING	<input checked="" type="radio"/> TAIL LG & WW	ENG. DOORS/HATCHES	FUNCTION: (CIRCLE ONE) <input checked="" type="radio"/> MECH ELEC RADIO SM CLEAN NOT INSP PAINT CABIN SHOP	W/O NO. 1542	TASK NO. 3A 072
ITEM DESCRIPTION R/H Elev Eyebolt lock tab broken					A/C TYPE: MODEL DC-8-71F	A/C TAIL NO. N2084U	
CUSTOMER REQUEST? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> (CIRCLE ONE)							

EWA

WRITTEN BY: *[Signature]*
 EMP. NO. 064 DAY 14 MO 06 YR 00

EVALUATION (CIRCLE ACTIONS TO BE TAKEN)
 CLEAN CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

REFERENCE DOCUMENT (I.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DC-8- m/m A.T.A. 27-30-4
 SPECIAL INSTRUCTIONS

EVALUATION BY: *[Signature]* EMP. NO. 5011 O.T. ALTH (CIRCLE) YES NO PARTS ALTH (CIRCLE) YES NO BEG. INSPN ITEM YES NO (CIRCLE) CUSTOMER APPROVAL *[Signature]* 2.0
 CHPT SECT SUBJ

CORRECTIVE ACTION
 Removed and Replaced R/H Elev Eyebolt Lock TAB IAW Daco DC-8 m/m 27-30-4

PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #	PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #
ACCOMPLISHED BY <i>[Signature]</i>	EMP. NO. 166	SUPERVISOR/LEAD RECHECK <i>[Signature]</i>	EMP. NO.	CHECKED BY <i>[Signature]</i>	DATE	DAY 20 MO 06 YR 00	

NON-ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC

FORM NO. 26

CRS T64R1640

W/D NO. 1542 TASK NO. 6A112
 A/C TYPE/MODEL DC-8-77 A/C TAIL NO. ASV84V
 CUSTOMER REQUEST? YES (CIRCLE ONE)

ITEM LOCATION (CIRCLE ONE) CABIN TAIL ENG. _____ FUNCTION: (CIRCLE ONE) MECH ELEC RADIO CLEAN
 LT WING _____ RT WING _____ LG & W/W _____ DOORS/HATCHES _____ NDT INSP PAINT CABIN SHOP _____

ITEM DESCRIPTION: RIH elec cover plate has several cracks

Ret. mett EWA 28. WRITTEN BY: Collier EMP. NO. 126 DAY 16 MO 05 YR 00

EVALUATION (CIRCLE ACTIONS TO BE TAKEN) CLEAN CHECK LUBE SERVICE TREAT PAINT REMOVE REPAIR TIGHTEN SECURE STOW REPLACE RESET TEST ADJUST

REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC) DC8 SRM A.T.A. 51 1 4 8.0
 SPECIAL INSTRUCTIONS Difficult to form. CHPT _____ SECT _____ SUBJ _____

EVALUATION BY: [Signature] EMP. NO. 259 O.T. AUTH (CIRCLE) YES NO _____ PARTS AUTH (CIRCLE) YES NO _____ RECD INSPN ITEM YES NO (CIRCLE) CUSTOMER APPROVAL

CORRECTIVE ACTION: Fab new cover plate out of 7075 +6 .025 PO.#7948 OK to treat & prime. Treated & primed I.A.W DC-8 SRM 51-1-8. Installed new cover plate I.A.W DC-8 SRM 51-3-10

PART NUMBER "OFF" _____ SER # _____ PART NUMBER "ON" _____ SER # _____ PART NUMBER "OFF" _____ SER # _____ PART NUMBER "ON" _____ SER # _____

ACCOMPLISHED BY: [Signature] EMP. NO. 681 SUPERVISOR/LEAD RECHECK: [Signature] EMP. NO. _____ CHECKED BY: TTS 23 DAY 25 MO 5 YR 00
 (INSP)

NON-ROUTINE WORK CARD TENNESSEE TECHNICAL SERVICES, LLC							TASK NO.							
FORM NO. 26							CRS T64R1640							
ITEM LOCATION (CIRCLE ONE)					FUNCTION: (CIRCLE ONE)		W/O NO.	A/C TAIL NO.						
FUSE STRUCT		CABIN	TAIL	ENG.	MECH	ELEC	RADIO	S/M	CLEAN					
LT WING	RT WING	LG & W/W	DOORS/HATCHES	NDT	INSP	PAINT	CABIN	SHOP	CUSTOMER REQUEST? YES NO (CIRCLE ONE)					
ITEM DESCRIPTION														
Lt. Elev. Gear Tab and Flight Tab eye bolts are misaligned														
Ref: 3501D EWA 28-261					WRITTEN BY:		EMP. NO.	DAY	MO	YR				
EVALUATION (CIRCLE ACTIONS TO BE TAKEN)														
CLEAN	CHECK	LUBE	SERVICE	TREAT	PAINT	REMOVE	REPAIR	TIGHTEN	SECURE	STOW	REPLACE	RESET	TEST	ADJUST
REFERENCE DOCUMENT (M.M./S.R.M./DRAWING/SERVICE BULLETIN/D.E.R. INSTRUCTION ETC)														
SPECIAL INSTRUCTIONS														
EVALUATION BY	EMP. NO.	O.T. AUTH. (CIRCLE)	PARTS AUTH. (CIRCLE)	REQD INSPN ITEM	CUSTOMER APPROVAL	CHPT	SECT	SUBJ						
CORRECTIVE ACTION														
Realigned LH Elev. Gear TAB AND Flight TAB eye bolts to proper alignment with #37 AND reTowed eye bolts with AW DC-9 mm 27-30-3														
PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #	PART NUMBER "OFF"	SER #	PART NUMBER "ON"	SER #							
ACCOMPLISHED BY	EMP. NO.	SUPERVISOR/LEAD RECHECK	EMP. NO.	CHECKED BY	DAY	MO	YR							

28
INSP

7/12/00 2:50:39PM

Work Order # 1542, 1543, 1544, 1545, 1558 N8084U Non-Routine Tally

Non-Routine	Description of Non-Routine	Skill	Date Issued	Issued By	Date Closed	Closed By
3A046	R/H HORZ STAB L/E CHANEL NUTS MISSING 3201 (7-254)	SMTL	4/26/00	467 Swackhamer, Gary	5/9/00	257 Shear, Joseph
3A047	L/H HORZ STAB FWD ROLLER BEARING TO FUSE RUSTED AND WILL NOT TURN 3201D (7-262)	MECH	4/26/00	467 Swackhamer, Gary	5/9/00	257 Shear, Joseph
3A048	L/H HORZ STAB L/E MISSING NUTPLATES IN CHANEL SEVERAL PLACES 3201D (7-261)	SMTL	4/26/00	467 Swackhamer, Gary	5/22/00	257 Shear, Joseph
3A049	R/H HORZ STAB LOWER SKIN PLANKS HAS LOOSE RIVITS FRONT SPAR XE76 TO XE 220 3201D (7-260)	MECH	4/26/00	467 Swackhamer, Gary	5/18/00	467 Swackhamer, Gary
3A050	L/H HORZ STAB TRAILING EDGE UPPER PNL CORROSION ON SURFACE AND BULDGE FRXE252- XE -272 REF 3201D (7-264)	SMTL	4/26/00	467 Swackhamer, Gary	5/12/00	257 Shear, Joseph
3A051	L/H HORZ STAB UPPER TRAILING EDGE PNL FRAME XE 221 HAS CHERRY MAX RIVITS AND FINGER DOUBLER PULLED LOOSE 3201 (7-265)	SMTL	4/26/00	467 Swackhamer, Gary	5/25/00	257 Shear, Joseph
3A052	L/H HORZ STAB UPPER TRAILING EDGE PNL XE99 SKIN WRINKLED TRAILING EDGE 3201D (7-266)	SMTL	4/26/00	467 Swackhamer, Gary	5/12/00	257 Shear, Joseph
3A053	L/H HORZ STAB UPPER BODY FAIRING RAIN CHANEL CRACKED AND PIECES MISSING REF 3201D	SMTL	4/26/00	704 Williamson, Brian	6/17/00	735 Cafarella, William
3A054	R/H I/B HORTZ STAB L/E HAS FOUR CRACKED RIVITS REF MECH	SMTL	5/15/00	257 Shear, Joseph	5/22/00	257 Shear, Joseph
3A055	LT GEAR TAB I/B & O/B CONTROL ROD END HAS CORROSION REF 3401D	MECH	5/18/00	022 Dawson, Amy	5/22/00	257 Shear, Joseph

All I. Accounted For Mgr  /Insp.



7/12/00 2:50:39PM

Work Order # 1542, 1543, 1544, 1545, 1558 N8084U Non-Routine Tally

Non-Routine	Description of Non-Routine	Skill	Date Issued	Issued By	Date Closed	Closed By
3A056	LT GEAR TAB O/B EYEBOLT HAS 1 THREAD ENGAGEMENT REF 3401D	MECH	5/18/00	022 Dawson, Amy	5/22/00	257 Shear, Joseph
3A057	"J" PANEL ON LOWER SIDE OF L/H ELE HAS BARE METAL (PANEL WAS NOT TREATED AND PRIMED AT OVERHAUL)-REF 3601	MECH	5/18/00	022 Dawson, Amy	5/22/00	257 Shear, Joseph
3A058	LT AND RT ELE MOUNT BUSHINGS NEED TO BE SIZED IAW OVERHAUL MANUAL REF 3503D/3504D	SMTL	5/18/00	257 Shear, Joseph	6/19/00	467 Swackhamer, Gary
3A059	L/H ELEV GEAR TAB CRANK ARMS UPSIDE DOWN S/N 0277 REF 3403D	MECH	5/19/00	257 Shear, Joseph	6/7/00	257 Shear, Joseph
3A060	R/H HORZ STAB INBD L/E SCREW HAS DIMPLED WASHER XFS 178.7 REF 3601D	MECH	5/19/00	257 Shear, Joseph	6/13/00	257 Shear, Joseph
3A061	L/H ELEV GEARED TAB I/B CRANK ARM HAS 2 CRACKS REF 3503D	MECH	5/24/00	257 Shear, Joseph	6/12/00	257 Shear, Joseph
3A062	LH LINK FOR DAMPER SHIPPED TO OVERHAUL REF 3503D	MECH	5/25/00	467 Swackhamer, Gary	6/15/00	217 Pitts, William
3A063	RH LINK FOR DAMPER SHIP TO OVERHAUL REF 3504D	MECH	5/25/00	467 Swackhamer, Gary	6/18/00	217 Pitts, William
3A064	L/H ELEVATOR REQUIRES BALANCE FOR I INSTALLATION OF STEEL CRANK ARMS REF 1542-6A122	MECH	6/5/00	467 Swackhamer, Gary	6/18/00	217 Pitts, William
3A065	LEFT HAND ELEVATOR 2 EACH FAIRINGS MISS- ING AT STA XE 149.00	SMTL	6/14/00	257 Shear, Joseph	6/21/00	257 Shear, Joseph

All ; Accounted For Mgr.  /Insp.

7/12/00 2:50:39PM

Work Order # 1542, 1543, 1544, 1545, 1558 N8084U Non-Routine Tally

Non-Routine	Description of Non-Routine	Skill	Date Issued	Issued By	Date Closed	Closed By
3A066	LEFT HAND ELEVATOR FAIRING MISSING AT STA 221	SMTL	6/14/00	257 Shear, Joseph	6/20/00	257 Shear, Joseph
3A067	LEFT HAND ELEVATOR 2 EACH FAIRINGS MISSING AT STA 272	SMTL	6/14/00	257 Shear, Joseph	6/21/00	257 Shear, Joseph
3A068	LEFT HAND ELEVATOR FAIRING MISSING AT STA XE 77.00	SMTL	6/14/00	257 Shear, Joseph	6/21/00	257 Shear, Joseph
3A069	RT ELEV L/E AT STA XE120 HAS A DENT	SMTL	6/15/00	467 Swackhamer, Gary	6/19/00	257 Shear, Joseph
3A070	LEFT ELEV PREVIOUS REPAIR SEPERATED UPPER T/E PANEL JUST FWD OF GEAR TAB 3503D	SMTL	6/15/00	467 Swackhamer, Gary	6/16/00	467 Swackhamer, Gary
3A071	ROBBED HORIZONTAL STAB HYD CONTROL VALVE P/N 5710133-5501 FOR A/C 961R	MECH	6/15/00	467 Swackhamer, Gary	6/22/00	257 Shear, Joseph
3A072	R/H ELEV EYEBOLT LOCKTAB BROKEN	MECH	6/16/00	467 Swackhamer, Gary	6/20/00	467 Swackhamer, Gary
4A001	EXTERNAL PWR NOT IN USE LITE DOES NOT LITE UP WHEN PWR IS APPLIED AND NOT TURNED ON IN COCKPIT-PRE 10	AVON	4/11/00	022 Dawson, Amy	5/12/00	257 Shear, Joseph
4A002	EXTR PWR NOT IN USE LITE MISSING PRE 10	AVON	4/11/00	022 Dawson, Amy	5/12/00	257 Shear, Joseph
4A003	L/H NOSE CHIN SCOOP / SHUT-OFF VALVE CLAMP NOT INSTALLED AROUND VALVE STICKER # 71 REF W/C 4201	MECH	4/20/00	467 Swackhamer, Gary	5/4/00	257 Shear, Joseph

All s Accounted For Mgr.  /Insp.



7/12/00 2:50:39PM

Work Order # 1542, 1543, 1544, 1545, 1558 N8084U Non-Routine Tally

Non-Routine	Description of Non-Routine	Skill	Date Issued	Issued By	Date Closed	Closed By
6A103	MIDDLE RUDDER DAMPNER ARM BEARING WORN AND RATCHES 9A010 SHELF INSP L/H OF A/C	MECH	5/6/00	022 Dawson, Amy	5/11/00	732 Heath, Thomas
6A104	BOTTOM CHANNELS FOR RUDDER CRACKED	SMTL	5/9/00	735 Cafarella, William	5/29/00	257 Shear, Joseph
6A105	VERTICAL STAB/REAR SPAR/HAT CHANNEL COVER CRACKED DOT 15-274 (PART LOCATED IN PAINT SHOP) REF N/R 6A023	SMTL	5/10/00	257 Shear, Joseph	5/18/00	467 Swackhamer, Gary
6A106	REMOVE RUDDER POWER PACK TO ACTUATOR LINE TO FOM (FOR REF FOR LINE MANF)	MECH	5/12/00	467 Swackhamer, Gary	6/17/00	217 Pitts, William
6A107	ROB RUDDER TAB CONTROL PUSH ROD FOR AIRCRAFT N995CF	MECH	5/12/00	467 Swackhamer, Gary	5/15/00	257 Shear, Joseph
5A108	ROB RUDDER POWER VALVE CONTROL PUSH ROD FOR ACFT N995CF	MECH	5/12/00	467 Swackhamer, Gary	5/15/00	257 Shear, Joseph
5A109	ROB GUST LOCK PUSH ROD FOR ACFT N995CF	MECH	5/12/00	467 Swackhamer, Gary	6/18/00	257 Shear, Joseph
A110	ANTI-ICE DUCT COMPT 60 NEXT TO DOOR WELD CRACKED REF 1542-6A077 (07-434)	SMTL	5/15/00	257 Shear, Joseph	6/19/00	257 Shear, Joseph
A111	SHIM FOR RUDDER IS CRACKED	SMTL	5/16/00	735 Cafarella, William	6/15/00	217 Pitts, William
A112	R/H ELEV COVER PLATE HAS SEVERAL CRACKS	SMTL	5/16/00	735 Cafarella, William	5/26/00	257 Shear, Joseph


All Items counted For Mgr. [Signature] /Insp. _____



7/12/00 2:50:39PM

Work Order # 1542, 1543, 1544, 1545, 1558 N8084U Non-Routine Tally

Non-Routine	Description of Non-Routine	Skill	Date Issued	Issued By	Date Closed	Closed By
6A123	LT ELEV GEARED TAB AND FLIGHT TAB EYEBOLTS ARE MISALIGNED REF 3501D	MECH	5/18/00	022 Dawson, Amy	5/22/00	257 Shear, Joseph
6A124	RIVET HEAD SHEARED OFF SIDE OF VERT. STAB. ON FIBERGLASS COVER ABOVE ACCESS PANEL #57-REF 6002D	SMTL	5/18/00	022 Dawson, Amy	5/22/00	257 Shear, Joseph
6A125	CORROSION L/H AFT COVER OF COCKPIT FOR HF ANT. COMPLING ACCESS PANEL #57 REF 6602D	SMTL	5/18/00	022 Dawson, Amy	5/19/00	257 Shear, Joseph
6A126	INSIDE PANEL # 57 L/H SIDE OF VERT STAB HF ANT COUPLER CORROSION ON STIFFENER REF 6602D	SMTL	5/17/00	467 Swackhamer, Gary	5/23/00	257 Shear, Joseph
6A127	VERT STAB ISOLATION BAND BOOT DETERIORAT 6202	PAINT	5/17/00	467 Swackhamer, Gary	6/22/00	257 Shear, Joseph
6A128	TOP AND BOTTOM PLANKS OF CONSTANT SECT HAVE LOOSE PRIMER REMOVE AND REPRIME REF 6202D (07-459)	MECH	5/18/00	257 Shear, Joseph	5/23/00	257 Shear, Joseph
6A129	CLEAN AND LUB ELEV CABLES AND PULLYS UNDER CONSTANT SECT REF 6202D (07-458)	MECH	5/18/00	257 Shear, Joseph	5/31/00	257 Shear, Joseph
5A130	AREAS ABOVE AND BELOW CONSTANT SECT NEED PRIME AFTER LOOSE PRIMER REMOVED REF 6202D (07-457)	MECH	5/18/00	257 Shear, Joseph	5/23/00	257 Shear, Joseph
5A131	AREA ABOVE AND BELOW CONSTANT SECT NEED CLEAN REF 6202D (07-456)	MECH	5/18/00	257 Shear, Joseph	5/31/00	257 Shear, Joseph
5A132	RUDDER MOUNT BUSINGS NEED TO BE SIZED IAW OVERHAUL MANUAL REF 6602D	SMTL	5/18/00	257 Shear, Joseph	6/14/00	217 Pitts, William

All Item counted For Mgr.  /Insp.



NORTHWINGS ACCESSORIES CORP.

A SUBSIDIARY OF HEICO AEROSPACE CORPORATION
 7075 NW 64TH STREET • MIAMI, FLORIDA 33166 U.S.A.
 PHONE (305) 463-0455 • FAX (305) 463-9339
 F.A.A. REPAIR STATION #NWQR356K • E-mail: northw@bellsouth.net



WORK ORDER 00-1006

CUSTOMER: AGE001 AGES-AIR GROUND EQUIPMENT SALE
 P.O. #: 8270399005R30RX7/33HATE: 02/23/00
 P/N: 5644420-508 S/N: 007
 DESCRIPTION: ELEVATOR TABS
 MANUAL #: AGE 1322

MFG: Douglas
 REV: 46
 DATE: 12-15-73

SPECIAL INSTRUCTIONS
FOR OVERHAUL CONDITION

TEAR DOWN REQUIRED Y ADVISE COST Y
 WORK REQUESTED 03 BENCH/CK
 TROUBLE REPORTED: SEE ATTACHED RO.
 AIRCRAFT: T.S.O.

DEFECT CONDITION RECEIVED: None

TROUBLE FOUND:

LOWER AND UPPER SKIN DIFFERENT AREAS PRESENT DENTS, 2 PLACE IMPROPER
 RIPPER. RIVETS LOOSE, INSIDE PAINTING CRACKED, EYE BOLT DAMAGE 3 PLACE,
 O/B ELEVATOR T/EDGE CRACKED, CABLE STITCH MISSING AND SUPPORT DAMAGE, DAMPER
 CORRODED NEED REPAIR, CRANK ASSY CORRODED AND BEARING DAMAGE, NEED IT BALANCING
 AND WEIGHTS
 CORRECTIVE ACTION: J.A.W. SEM 51-45, 51-48, 51-3-3, REV. 98 OHY 27-16-1

Removed & replaced lower skin, repaired upper skin as required,
 installed new bearings, fasteners, static support, eye bolt, primer, paint
 sealant, repaired tie as required, cleaned collector and treated, balance
 and weight applied, damper overhauled as required.

WORK PERFORMED OVERHAUL REPAIR BENCH CHECK WARRANTY OTHER

LABOR RECORD:

TECHNICIAN	DATE	TIME	FUNCTION
<u>[Signature]</u>	<u>4/30/00</u>	<u>12 PM</u>	TEARDOWN/EVALUATION
<u>[Signature]</u>	<u>4/30/00</u>	<u>12 PM</u>	BUILD UP/FUNCT. TEST
<u>H Rodriguez</u>	<u>5-1-02</u>		FINAL INSPECTION

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
-------------	-------------	-----	------------	--------

SEE ATTACHED PARTS BREAKDOWN

RECEIVING INSP. DATE 2-24-00 T.D. INSP. DATE 4/30/00 RELEASE INSP. DATE 5/1/00








NORTHWINGS ACCESSORIES-ASSOCIATED COMPOSITES
 7875 NW 64th Street
 Miami, Florida 33166

FINAL Q.C. INSPECTION
 CHECKLIST

FAA Repair Station #NWQR356K

PART NUMBER: 5644420-508
 DESCRIPTION: ELEVATOR
 CUSTOMER PO: 8270399005R
 DATE: 4/30/00

SERIAL NUMBER: 007
 CUSTOMER: AGES AIR
 NAAC WO: 00-7006

CHECKLIST	INSPECTOR
WEIGHT AND BALANCE COMPLETED YES <input checked="" type="checkbox"/> NOT REQ'D <input type="checkbox"/> IF YES ENTER THE WEIGHT AND BALANCE COMPUTATIONS BELOW AND ON THE 8130-3. <u>CONTROL TAB = WEIGHT = 26.73, BALANCE = 7.59 Inch/LBS</u> <u>GEARD TAB = WT = 10.59 LBS — ELEVATOR = BALANCE 1446.36 Inch/LBS</u>	
ALL COMPANY FORMS COMPLETED AND IN WORK PACKAGE	
FAA FORM 8130-3 COMPLETE, INCLUDING WEIGHT AND BALANCE WHEN APPLICABLE	
DATA PLATE INSTALLED	
REQUIRED PICTURES TAKEN OF REPAIRED AREA AND/OR COMPONENT IN GENERAL	
TEARDOWN REPORT COMPLETED	
WORK ORDER FORM COMPLETED	
OTHER: _____ _____ _____ _____ _____ _____ _____	

NAAC FORM 0007

DONALD BEECHER CO., INC
DC-3 STRUCTURAL REPAIR MANUAL

ELEVATOR CONTROL TAB BALANCE CHECK AND CORRECTION
AND GEARED TAB WEIGHT LIMITS (DC-3-ALL)

1. Description

The tab assemblies to be balance checked or weighed should be painted (where paint is required) and complete with drive fittings. See Figure 59L, Section 51-4-4, for correct condition for balancing and weighing.

2. Procedure for Checking Tab Weight and Balance

- A. Support the control tab assembly by the first and second hinge from the in-board end. The hinge line must be in a horizontal position. The geared tab is not a balanced tab.
- B. Check for freedom of movement. The tab must swing freely about its hinge line. See the balance check note, Section 51-4-0, paragraph 4.
- C. Establish the correct tab balance check position by use of a protractor level placed on the upper external surface of the tab normal to the hinge line and set at 5°6' (see Figure 59M, Section 51-4-4).
- D. Measure the overbalance moment of the tab about its hinge line with the tab in the correct balance check position.
- E. Check the overbalance moment obtained against the ELEVATOR CONTROL AND GEARED TAB WEIGHT AND BALANCE LIMITS TABLE.
- F. Weigh each complete tab assembly and check the weights against the ELEVATOR CONTROL AND GEARED TAB WEIGHT AND BALANCE LIMITS TABLE.

Printed in U.S.A.

1 May 1967

51-4-5
Page 1

DOUGLAS AIRCRAFT CO.
DC-8 STRUCTURAL REPAIR MANUAL

ELEVATOR CONTROL AND GEARED TAB WEIGHT AND BALANCE LIMITS TABLE

Tab Assembly	Reference	**Recommended Limits				**Critical Limits	
		Weight, (Lb)		Nose Heavy Balance (In.-Lb)		Weight, (Lb)	Nose Heavy Balance (In.-Lb)
		Min	Max	Min	Max		
Control Tab	Figure 59L, Section 51-4-4	26.0	30.3	7.3	7.7	31.0 +33.0	6.3 6.3
*Geared Tab	Figure 59L, Section 51-4-4	10.5	11.4	---	---	11.6 ++13.6	--- ---

- NOTES:**
- * (1) The geared tab is not balanced.
 - ** (2) The recommended limits should be used whenever a tab is rebalanced. A tab balanced within the critical limits is safe but has no margin for service growth.
 - + (3) An overweight repaired control tab with a Maximum Critical Limit of 33.0 Lb may be used if elevator leading edge Sta. XE 89.718 to XE 132.750 has 5701580-501 weight and 5701581-13 retainer installed, and 5701580-503 weight and 5701581-15 retainer installed.
 - ++ (4) An overweight repaired geared tab with a Maximum Critical Limit of 13.6 Lb may be used if elevator leading edge Sta. XE 89.718 to XE 132.750 has 5701580-501 weight and 5701581-13 retainer installed, and 5701580-503 weight and 5701581-15 retainer installed.

3. Procedure for Correcting Elevator Control Tab Balance

- A. Determine the overbalance moment correction required.
- B. Remove the tab nose skin.
- C. To increase nose-heavy overbalance moment, add weights to the nose channel starting with the inboard end. Use the elevator control tab balance adjustment weights table to obtain the moment exerted by these weights on the tab.
- D. To decrease nose-heavy overbalance moment, remove weights from the nose channel starting with the outboard end of the tab.

Douglas Aircraft Co.
DC-3 STRUCTURAL REPAIR MANUAL

- E. Reinstall the tab nose skin.
- F. Reweigh the tab assembly after balance correction. Check the weight of the assembly against the elevator control and geared tab weight and balance limits table.

15 December 1973

51-4-5
Page 2A/6

Printed in U.S.A.

DOUGLAS AIRCRAFT CO., INC.
DC-8 STRUCTURAL REPAIR MANUAL

ELEVATOR CONTROL TAB BALANCE ADJUSTMENT WEIGHTS TABLE

Part Number	Location Sta Xc	Forward or Aft of Nose Channel	Weight, Lb per Weight	Nose-Heavy Moment, Inch-Pounds per Weight
2769712-3	99	Forward	0.40	-0.76
2769704	99	Aft	0.06	-0.13
4714620-507	91	Forward	0.66	-1.32
4714621-505	91	Aft	0.05	-0.09
4714620-507	83	Forward	0.66	-1.45
4714621-505	83	Aft	0.05	-0.09
4714620-507	73	Forward	0.91	-2.00
4714621-501	73	Aft	0.37	-0.67
4714621-505	73	Aft (Alternate)	0.05	-0.09
4714620-509	67	Forward	0.30	-0.69
4714621-503	67	Aft	0.18	-0.36
4714621-507	67	Aft (Alternate)	0.04	-0.08
4714620-505	62	Forward	0.67	-1.54
4714621-501	62	Aft	0.37	-0.70
4714621-505	62	Aft (Alternate)	0.05	-0.10
4714620-503	54	Forward	0.91	-2.15
4714621-501	54	Aft	0.37	-0.74
4714621-505	54	Aft (Alternate)	0.05	-0.10
4714620-1	43	Forward	0.87	-2.09
4714621-1	43	Aft	0.52	-0.99
4714620-501	36	Forward	0.78	-2.00
4714621-1	36	Aft	0.52	-1.04
4714620-1	29	Forward	0.87	-2.26
4714621-1	29	Aft	0.52	-1.04

4. Procedure for Correcting Elevator Control Tab Weight

NOTE: It is possible for the elevator control tab to be within the balance limits and yet weigh under the minimum weight limit. This condition must be corrected.

- A. Determine the weight correction required.
- B. To increase tab weight, add ballast weights to the inboard closing rib flanges. Refer to the DC-8 Illustrated Parts Catalog, Chapter 27, Flight Controls, for the location and attachment of these weights. Use the elevator control tab ballast weights table to obtain the weight and moment for these weights.
- C. To decrease tab weight, remove ballast weights from the inboard closing rib flanges, using the table referenced in step B.

DOUGLAS AIRCRAFT CO., INC
DC-3 STRUCTURAL REPAIR MANUAL

- D. Ballast weights are aft of the tab hinge line and induce a tail heavy moment. It may be necessary, therefore, to offset the moment change resulting from an adjustment of ballast weights by the addition or removal of compensating balance weights. The additional weight gained or lost thereby must be taken into consideration when determining the net weight added or removed.
- E. Rebalance and reweigh the assembly after weight correction. Check the weight and balance against the elevator control and geared tab weight and balance limits table, paragraph 2.

ELEVATOR CONTROL TAB BALLAST WEIGHTS TABLE

Part Number	Location Sta Xct	Weight, Lb per Weight	Tail-Heavy Moment, Inch-Pounds per Weight
564440-77	25	0.07	0.47
-79	25	0.24	0.94
-81	25	0.05	0.31
-83	25	0.11	0.65



MEMORANDUM

TO: Tom Wood
cc: Harold Camden, FAA PMI

FROM: Tim Alman *TJA*

SUBJECT: Aircraft 8084U

DATE: July 18, 2000

Aircraft 8084U at Tennessee Technical Services has experienced two (2) test flight failures due to elevator vibrations. Our investigation has found that the right elevator was out of balance.


Attached is the report from Tennessee Technical Services and the vendor paperwork where the surface was overhauled.

TJA/bl

TENNESSEE TECHNICAL SERVICES, L.L.C.

CRS T64R1640

634 Fitzhugh Blvd. • Smyrna, TN 37167 • (615) 223-7801 • Fax (615) 355-6472



TO: Tim J. Alman.
Director Heavy Maintenance

July 14, 2000

FROM: Ray Pigozzi

CC: Dave Hofstetter
Jack Ray

SUBJECT: N8084U Right Elevator

On Thursday Tennessee Technical Services balanced the right elevator and found it to at 1,398.255. The minimum is 1,440 to a maximum of 1,480. Our calculations indicate we would have to add 12.95 LBS. to the leading edge. All weight positions have the maximum amount of weights installed except for the base position.

The data plate on the right elevator indicated 1,466 which is within the allowed limits per SRM 51-4-4- page 1

Attached are copies of the
8130-3 for the elevator serial # 007, which had no weight and balance data
Tear down report with the elevator balance data

1/3

Florida 33106

Repair Station #NWQR350K

ATTN: CAROL DEERING LARNEY

FINAL Q.C. INSPECTION CHECKLIST

PART NUMBER: 5644420-508

DESCRIPTION: ELEVATOR

CUSTOMER PO: 22708990072

DATE: 07/30/00

SERIAL NUMBER: 007

CUSTOMER: AGE AIR

NAAC WO: 00-1066

CHECKLIST

INSPECTOR

WEIGHT AND BALANCE COMPLETED

YES

NOT REQ'D

IF YES ENTER THE WEIGHT AND BALANCE COMPUTATIONS BELOW AND ON THE 8130-3.



PORTING TABS = WEIGHT = 26.73, BALANCE = 7.55 INCHES/LBS
GRAND TABS WT = 10.59 LBS - ELEVATOR = BALANCE 1441.36 INCHES/LBS

ALL COMPANY FORMS COMPLETED AND IN WORK PACKAGE

FAA FORM 8130-3 COMPLETE, INCLUDING WEIGHT AND BALANCE WHEN APPLICABLE

DATA PLATE INSTALLED

REQUIRED PICTURES TAKEN OF REPAIRED AREA AND/OR COMPONENT IN GENERAL

TEARDOWN REPORT COMPLETED

WORK ORDER FORM COMPLETED

OTHER:

NAAC FORM 12807

JUL 14 '00 0.00000

0696 223 9890

ent By: Tennessee Technical Services;

1. UNITED STATES		2. FAA FORM 8130-3 AIRWORTHINESS APPROVAL TAG U.S. Department of Transportation Federal Aviation Administration			3. System Tracking Ref. No. 00-1006	
4. Organization NORTHWINGS ACCESSORIES - ASSOCIATED COMPOSITES, CORP.		A. SUBSIDIARY OF HECO AEROSPACE CORPORATION 1875 HWY 44 STREET - MIAMI, FLORIDA 33186			5. Work Order, Contract, or Invoice Number: 2762	
6. ITEM	7. DESCRIPTION	8. PART NUMBER	9. ELIGIBILITY	10. Qty	11. SERIAL / MATCH NUMBER	12. STATUS / WORK
1	ELEVATOR TAB	5644420-508	TBV BY INSTALLER	1	007	OVERHAULED
13. Remarks Mfg.: DOUGLAS ATA: JAW SRM 51-4-5, 51-1-8, 51-3-3 Rev. 78 OHN 276-1 <input checked="" type="checkbox"/> Overhauled <input type="checkbox"/> Modified <input type="checkbox"/> Inspected <input type="checkbox"/> Repaired <input type="checkbox"/> Functionally Tested Permanent data of the work is on file at this agency under the work order number referenced in block 3 Certifies that the work specified in block 13 was carried out in accordance with JAR 145 and with respect to that work the aircraft component is considered ready for return to service under JAR Acceptance Certificate Number: JAA.4705 AGES						
14. Limited life parts must be accompanied by maintenance history including total time / total cycles / time since new.						
14a. New <input type="checkbox"/> Newly Overhauled <input checked="" type="checkbox"/>			14b. Return to Service in Accordance with FAR 43.9 Certifies that the work specified in block 13 (or attached) above was carried out in accordance with FAA airworthiness regulations and in respect to the work performed the part(s) is (are) approved for return to service.			
15. Signature NA			16. FAA Authorization No. NA	20. Authorized Signature <i>[Signature]</i>	21. Certificate Number NW0325K	
17. Name (Title or Printed) NA			18. Date NA	22. Name, Title or Position Heidi Rodriguez	23. Date 5/1/00	

FAA Form 8130-3 0110

(Optional) Initial and cross check against applicable technical data

2/3

NORTHWINGS ACCESSORIES CORP.

A SUBSIDIARY OF HEICO AEROSPACE CORPORATION
 7275 NW 64TH STREET • MIAMI, FLORIDA 33166 U.S.A.
 PHONE (305) 463-0455 • FAX (305) 463-9339
 F.A.A. REPAIR STATION #NWQR356K • E-mail: northw@bellsouth.net



PD

WORK ORDER 00-1006

CUSTOMER: AGE001 AGES-AIR GROUND EQUIPMENT SALE
 P.O. #: 8270399005R 3ORX7133 DATE: 02/23/00
 P/N: 5644420-308 S/N: 007
 DESCRIPTION ELEVATOR TABS
 MANUAL #: ~~AGE~~ 1322

MFG: Douglas
 REV: 46
 DATE: 12-15-73

SPECIAL INSTRUCTIONS
for overhaul condition

TEAR DOWN REQUIRED Y ADVISE COST Y
 WORK REQUESTED 03 BENCH/CK
 TROUBLE REPORTED: SEE ATTACHED RO.
 AIRCRAFT: T.S.O.

DEFECT CONDITION RECEIVED: *None*

TROUBLE FOUND:

*COVER AND UPPER SKIN DIFFERENT AREAS PRESENT DENTS. 2 PLACE IMPROPER
 REPAIR. RIVETS LOOSE. INSIDE TRAINING CRACKED. EYEBOLT DAMAGE 3 PLACE.
 O/B ELEVATOR T/EDGE CRACKED. CABLE STITCH MISSING AND SUPPORT DAMAGE. DAMPER
 COILS NEED REPAIR, CRANK ASSY CORRODED AND BEARING DAMAGE. NEED IT BALANCE
 AND WEIGHT*
 CORRECTIVE ACTION: *J.A.W. SEM 51-45, 51-47, 51-48, 51-3-3, REV. 78 OHY 27-16-1*

*Removed & replaced lower skin, repaired upper skin as required,
 installed new bearings, fasteners, static supports, eye bolt, primer, paint
 sealant, repaired tie as required, cleared corrosion and treated, balance
 and weight applied, damper overhauled as required.*

WORK PERFORMED OVERHAUL REPAIR BENCH CHECK WARRANTY REPAIR OTHER


LABOR RECORD:

TECHNICIAN	DATE	TIME	FUNCTION
<i>[Signature]</i>	4/30/00	12 PM	TEARDOWN/EVALUATION
<i>[Signature]</i>	4/30/00	12 PM	BUILD UP/FUNCT. TEST
<i>H. Rodriguez</i>	5-1-02		FINAL INSPECTION

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
-------------	-------------	-----	------------	--------

SEE ATTACHED PARTS BREAKDOWN

RECEIVING INSP. DATE	T.D. INSP. DATE	RELEASE INSP. DATE
<i>2-24-00</i>	<i>4/30/00</i>	<i>5/1/00</i>










NORTHWINGS ACCESSORIES-ASSOCIATED COMPOSITES
 7875 NW 64th Street
 Miami, Florida 33166

FINAL Q.C. INSPECTION
 CHECKLIST

FAA Repair Station #NWQR3561K

PART NUMBER: 5644420-508
 DESCRIPTION: ELEVATOR
 CUSTOMER PO: 9270399007R
 DATE: 4/30/00

SERIAL NUMBER: 007
 CUSTOMER: ABES AIR
 NAAC WO: 60-7006

CHECKLIST	INSPECTOR
WEIGHT AND BALANCE COMPLETED YES <input checked="" type="checkbox"/> NOT REQ'D <input type="checkbox"/> IF YES ENTER THE WEIGHT AND BALANCE COMPUTATIONS BELOW AND ON THE 8130-3. <u>CONTROL TAB = WEIGHT = 26.73 , BALANCE = 7.59 INCH/LBS</u> <u>BOARD TAB = WT = 10.59 LBS — ELEVATOR = BALANCE 1.446,36 INCH/LBS</u>	
ALL COMPANY FORMS COMPLETED AND IN WORK PACKAGE	
FAA FORM 8130-3 COMPLETE, INCLUDING WEIGHT AND BALANCE WHEN APPLICABLE	
DATA PLATE INSTALLED	
REQUIRED PICTURES TAKEN OF REPAIRED AREA AND/OR COMPONENT IN GENERAL	
TEARDOWN REPORT COMPLETED	
WORK ORDER FORM COMPLETED	
OTHER: _____ _____ _____ _____ _____ _____ _____	

NAAC FORM 02007

ELEVATOR CONTROL TAB BALANCE CHECK AND CORRECTION
AND GEARED TAB WEIGHT LIMITS (DC-8-ALL)

1. Description

The tab assemblies to be balance checked or weighed should be painted (where paint is required) and complete with drive fittings. See Figure 59L, Section 51-4-4, for correct condition for balancing and weighing.

2. Procedure for Checking Tab Weight and Balance

- A. Support the control tab assembly by the first and second hinge from the in-board end. The hinge line must be in a horizontal position. The geared tab is not a balanced tab.
- B. Check for freedom of movement. The tab must swing freely about its hinge line. See the balance check notes, Section 51-4-0, paragraph 4.
- C. Establish the correct tab balance check position by use of a protractor level placed on the upper external surface of the tab normal to the hinge line and set at 5°6' (see Figure 59M, Section 51-4-4).
- D. Measure the overbalance moment of the tab about its hinge line with the tab in the correct balance check position.
- E. Check the overbalance moment obtained against the ELEVATOR CONTROL AND GEARED TAB WEIGHT AND BALANCE LIMITS TABLE.
- F. Weigh each complete tab assembly and check the weights against the ELEVATOR CONTROL AND GEARED TAB WEIGHT AND BALANCE LIMITS TABLE.

Printed - VLA

1 May 1967

51-4-5
Page 1

DOUGLAS AIRCRAFT CO.
DC-3 STRUCTURAL REPAIR MANUAL

ELEVATOR CONTROL AND GEARED TAB WEIGHT AND BALANCE LIMITS TABLE

Tab Assembly	Reference	**Recommended Limits				**Critical Limits	
		Weight, (Lb)		Nose Heavy Balance (In.-Lb)		Weight, (Lb)	Nose Heavy Balance (In.-Lb)
		Min	Max	Min	Max		
Control Tab	Figure 59L, Section 51-4-4	26.0	30.3	7.3	7.7	31.0 +33.0	6.3 6.3
*Geared Tab	Figure 59L, Section 51-4-4	10.5	11.4	---	---	11.6 ++13.6	---

NOTES: *(1) The geared tab is not balanced.

** (2) The recommended limits should be used whenever a tab is rebalanced. A tab balanced within the critical limits is safe but has no margin for service growth.

*(3) An overweight repaired control tab with a Maximum Critical Limit of 33.0 Lb may be used if elevator leading edge Sta. XE 89.718 to XE 132.750 has 5701580-501 weight and 5701581-13 retainer installed, and 5701580-503 weight and 5701581-15 retainer installed.

** (4) An overweight repaired geared tab with a Maximum Critical Limit of 13.6 Lb may be used if elevator leading edge Sta. XE 89.718 to XE 132.750 has 5701580-501 weight and 5701581-13 retainer installed, and 5701580-503 weight and 5701581-15 retainer installed.

3. Procedure for Correcting Elevator Control Tab Balance

- A. Determine the overbalance moment correction required.
- B. Remove the tab nose skin.
- C. To increase nose-heavy overbalance moment, add weights to the nose channel starting with the inboard end. Use the elevator control tab balance adjustment weights table to obtain the moment exerted by these weights on the tab.
- D. To decrease nose-heavy overbalance moment, remove weights from the nose channel starting with the outboard end of the tab.

DOUGLAS AIRCRAFT CO.
DC-3 STRUCTURAL REPAIR MANUAL

- E. Reinstall the tab nose skin.
- F. Reweigh the tab assembly after balance correction. Check the weight of the assembly against the elevator control and geared tab weight and balance limits table.

15 December 1973

51-4-5
Page 2A75

Printed in U.S.A.

DOUGLAS AIRCRAFT CO., INC.
DC-8 STRUCTURAL REPAIR MANUAL

ELEVATOR CONTROL TAB BALANCE ADJUSTMENT WEIGHTS TABLE

Part Number	Location Sta Xc	Forward or Aft of Nose Channel	Weight, Lb per Weight	Nose-Heavy Moment, Inch-Pounds per Weight
2769712-3	99	Forward	0.40	-0.76
2769704	99	Aft	0.06	-0.13
4714620-507	91	Forward	0.66	-1.32
4714621-505	91	Aft	0.05	-0.09
4714620-507	83	Forward	0.66	-1.45
4714621-505	83	Aft	0.05	-0.09
4714620-503	73	Forward	0.91	-2.00
4714621-501	73	Aft	0.37	-0.67
4714621-505	73	Aft (Alternate)	0.05	-0.09
4714620-509	67	Forward	0.30	-0.69
4714621-503	67	Aft	0.18	-0.36
4714621-507	67	Aft (Alternate)	0.04	-0.08
4714620-505	62	Forward	0.67	-1.54
4714621-501	62	Aft	0.37	-0.70
4714621-505	62	Aft (Alternate)	0.05	-0.10
4714620-503	54	Forward	0.91	-2.16
4714621-501	54	Aft	0.37	-0.74
4714621-505	54	Aft (Alternate)	0.05	-0.10
4714620-1	43	Forward	0.87	-2.09
4714621-1	43	Aft	0.52	-0.99
4714620-501	36	Forward	0.78	-2.00
4714621-1	36	Aft	0.52	-1.04
4714620-1	29	Forward	0.87	-2.26
4714621-1	29	Aft	0.52	-1.04

4. Procedure for Correcting Elevator Control Tab Weight

NOTE: It is possible for the elevator control tab to be within the balance limits and yet weigh under the minimum weight limit. This condition must be corrected.

- A. Determine the weight correction required.
- B. To increase tab weight, add ballast weights to the inboard closing rib flanges. Refer to the DC-8 Illustrated Parts Catalog, Chapter 27, Flight Controls, for the location and attachment of these weights. Use the elevator control tab ballast weights table to obtain the weight and moment for these weights.
- C. To decrease tab weight, remove ballast weights from the inboard closing rib flanges, using the table referenced in step B.

1 February 1965

51-4-5
Page 3

DOUGLAS AIRCRAFT CO., INC
 DC-3 STRUCTURAL REPAIR MANUAL

- D. Ballast weights are aft of the tab hinge line and induce a tail heavy moment. It may be necessary, therefore, to offset the moment change resulting from an adjustment of ballast weights by the addition or removal of compensating balance weights. The additional weight gained or lost thereby must be taken into consideration when determining the net weight added or removed.
- E. Rebalance and reweigh the assembly after weight correction. Check the weight and balance against the elevator control and geared tab weight and balance limits table, paragraph 2.

ELEVATOR CONTROL TAB BALLAST WEIGHTS TABLE

Part Number	Location Sta Xct	Weight, Lb per Weight	Tail-Heavy Moment, Inch-Pounds per Weight
564440-77	25	0.07	0.47
-79	25	0.24	0.94
-81	25	0.05	0.31
-83	25	0.11	0.65

43.2 Records of overhaul and rebuilding.

(a) No person may describe in any required maintenance entry or form an aircraft, airframe, aircraft engine, propeller, appliance, or component part as being overhauled unless -

(1) Using methods, techniques, and practices acceptable to the Administrator, it has been disassembled, cleaned, inspected, repaired as necessary, and reassembled; and

(2) It has been tested in accordance with approved standards and technical data, or in accordance with current standards and technical data acceptable to the Administrator, which have been developed and documented by the holder of the type certificate, supplemental type certificate, or a material, part, process, or appliance approval under § 21.305 of this chapter.

(b) No person may describe in any required maintenance entry or form an aircraft, airframe, aircraft engine, propeller, appliance, or component part as being rebuilt unless it has been disassembled, cleaned, inspected, repaired as necessary, reassembled, and tested to the same tolerances and limits as a new item, using either new parts or used parts that either conform to new part tolerances and limits or to approved oversized or undersized dimensions.

2.11.06



A J

2.11.07 On 10/23/00 RRXA personnel approved for return to service and operated N602AL, after maintenance had been performed due to compressor stalls. The corrective action taken was not done in accordance with manufacturer's maintenance manual. This is contrary to 14CFR 121.709(b)(2)(i) and 43.13(a).

RRXA RESPONSE:

The CFM 56 Manufacturers M/M 71-00-00 page 101 Fault 50 states "Stalls may occur if there is inlet air distortion due to wings or if the Thrust Reverser was used at aircraft airspeeds lower than those specified in the aircraft flight manual. If inlet air distortion is confirmed troubleshooting for cause is not required. Inlet/Exhaust visual inspection will be done." United M/M 71-00-47 page 202 Item "B" states "The following sequence is progressive. All checks need not be accomplished if the fault is found and corrected". This is contrary to CFM M/M 72-00-00. This difference was discussed with GE Zachary Kamen and he agreed that a revision to their manual is necessary to clarify the required procedures. A memo to all maintenance personnel has been distributed stating that if an Engine Compressor Stalls the engine must be boroscoped prior to being returned to service.

RRXA CONCLUSION: No finding.



U. S. Department
of Transportation

Federal Aviation
Administration

January 23, 2001

2:11, 07 ✓

FILE NUMBER: 2001GL050032

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

On 10/23/00 Emery Worldwide Airlines Inc. Certificate (RRXA) personnel approved for return to service and operated N602AL, after maintenance had been performed due to compressor stalls. The corrective action taken was not done in accordance with the manufacturer's maintenance manual.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.


Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

cc: *Jim Owens*
Gary Sumarso
Bob Doll



21.709 Airworthiness release or aircraft log entry.

(a) No certificate holder may operate an aircraft after maintenance, preventive maintenance or alterations are performed on the aircraft unless the certificate holder, or the person with whom the certificate holder arranges for the performance of the maintenance, preventive maintenance, or alterations, prepares or causes to be prepared -

- (1) An airworthiness release; or
- (2) An appropriate entry in the aircraft log.

(b) The airworthiness release or log entry required by paragraph (a) of this section must -

(1) Be prepared in accordance with the procedures set forth in the certificate holder's manual;


(2) Include a certification that -

(i) The work was performed in accordance with the requirements of the certificate holder's manual;

2. 11.0 7

(2) Include a certification that -

(i) The work was performed in accordance with the requirements of the certificate holder's manual;



A N

2.11.08 RRXA has removed three (3) aircraft components from aircraft DC-10, N68044. This aircraft is not on RRXA OPSS, therefore, not being maintained under a CAMP. This is contrary to 14CFR part 91.409(e), which states in part; large aircraft; turbojet multiengine airplanes not operated under part 121 must be inspected in accordance with an inspection program selected under 14CFR 91.409(f).

RRXA RESPONSE:

The aircraft in question was on long term lease to RRXA even though it was undergoing conformity inspection at the time the aircraft components were removed. 14CFR part 91.409(f) (1) allows a part 121 carrier to perform maintenance on aircraft of the same make and model operated by the carrier.

CVG PMI was aware of the removal of the components prior to the RASIP.

RRXA CONCLUSION: *No finding.*

(e) *Large airplanes (to which part 125 is not applicable), turbojet multiengine airplanes, turbopropeller-powered multiengine airplanes, and turbine-powered rotorcraft.* No person may operate a large airplane, turbojet multiengine airplane, turbopropeller-powered multiengine airplane, or turbine-powered rotorcraft unless the replacement times for life-limited parts specified in the aircraft specifications, type data sheets, or other documents approved by the Administrator are complied with and the airplane or turbine-powered rotorcraft, including the airframe, engines, propellers, rotors, appliances, survival equipment, and emergency equipment, is inspected in accordance with an inspection program selected under the provisions of paragraph (f) of this section, except that, the owner or operator of a turbine-powered rotorcraft may elect to use the inspection provisions of § 91.409(a), (b), (c), or (d) in lieu of an inspection option of § 91.409(f).

(f) *Selection of inspection program under paragraph (e) of this section.* The registered owner or operator of each airplane or turbine-powered rotorcraft described in paragraph (e) of this section must select, identify in the aircraft maintenance records, and use one of the following programs for the inspection of the aircraft:


(1) A continuous airworthiness inspection program that is part of a continuous airworthiness maintenance program currently in use by a person holding an air carrier operating certificate or an operating certificate issued under part 121, 127 *{Part 127 was removed at Amdt. 127-45, 60 FR 65832, Dec. 20, 1995 - Ed.}*, or 135 of this chapter and operating that make and model aircraft under part 121 of this chapter or operating that make and model under part 135 of this chapter and maintaining it under § 135.411(a)(2) of this chapter.

(2) An approved aircraft inspection program approved under § 135.419 of this chapter and currently in use by a person holding an operating certificate issued under part 135 of this chapter.



U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

*cc: Jim Owens
Gerry Sumarco
Bill Hall*

January 23, 2001

2, 11, 00 ✓

FILE NUMBER: 2001GL050033

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

Emery Worldwide Airlines Inc. Certificate (RRXA) has removed three (3) aircraft components from aircraft DC-10, N68044. This aircraft is not on RRXA Operations Specifications (OPSS), therefore, not being maintained under a CAMP. This is contrary to 14CFR Part 91.409(e), which states in part; large aircraft; turbojet multieengine airplanes not operated under part 121 must be inspected in accordance with an inspection program selected under 14CFR 91.409(f).

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

Wood, Thomas M


From: Jones, Edward B
Sent: Tuesday, October 31, 2000 3:59 PM
To: Brauchler, Ben H; Northup, Robert J
Cc: Farnsworth, Wayne E; Smith Jr, Jack L; Ungemach, David W; Wood, Thomas M
Subject: Robbing Parts From Aircraft N68044

FAA has informed me that EWA cannot rob any parts from aircraft N68044 until aircraft has been added to EWA's OPS SPEC. All the parts listed below that were robbed from aircraft N68044 and installed on the aircraft listed must be removed (robbed) and reinstalled back onto aircraft N68044 as soon as possible. The parts that have been ordered for aircraft N68044 will be used to replace the parts removed from these aircraft.

N833LA - See log sheet # 09326-11, Forward Lower Belly Light Assy. P/N P71471-1, S/N NSN
N831LA - See log sheet # 09303-01, L/H Main Gear Door P/N NN6086-503, S/N NSN.
N68043 - See log sheet # 7624-06, #2 Engine Reverser Directional Solenoid P/N 320358-2, S/N 9000.

Thank you for your anticipated immediate response to comply with this concern.

Edward B. Jones, Jr.
Director, Quality Control
One Emery Plaza
Vandalia, OH 45377



Wood, Thomas M

From: Wood, Thomas M
Sent: Tuesday, October 31, 2000 4:10 PM
To: 'd.funk [REDACTED]
Subject: Robbing parts, N68044

Dick: As you know, EWA has taken technical acceptance, and or signed the lease for N68044, parked at Dayton. The FAA RASIP and our PMI is concern, with regard to proposing a violation, because we robbed a MLG door, reverser valve solenoid, and a lower beacon light, and installed it on our other aircraft. Their position is, since it is not on our OPS SPEC, we cannot do this. I advised them that it was a US reregistered aircraft under EWA FAA APPROVED maintenance program, continued from a 121 aircarrier program. This e-mail is to ask you, if you purchased the DAC MSG3 DC-10 Program, as you intended a couple years ago, to which this would represent it is on a FAA APPROVED program at this time. Please respond or call if you can help in this matter. [REDACTED] thank you Dick.

Thomas M. Wood
Senior Director Quality Control
Emery Worldwide Airlines
[REDACTED]

FINDING: 2.12.01 The reliability section does not utilize the entire corrective action process outlined in Chapter 6.1.A of the Maintenance Reliability Program Document, No. EWA-51990.

RRXA RESPONSE: *Paragraph 6.1.A states the "The Reliability Section will submit all corrective actions to EWA MRB for Review/Approval. Corrective actions may include, but are not limited to the following." The items listed in sub paragraphs 1 through 8 are examples of corrective actions that could be presented to the EWA MRB. This does not mean that each of these types of corrective actions have to be accomplished. The type of corrective action is based on the problem, and the urgency to facilitate a corrective action. During the past 12 months Reliability has issued four (4) Fleet Campaign Directives and submitted thirteen (13) inspection program changes.*

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

closed 3/13/01

B

RASIP FINDINGS

217-01


2.12 RELIABILITY PROGRAM

DESCRIPTION: The operation of the RRXA Maintenance Reliability Program is contained in the Maintenance Reliability Document No EWA-51990. The program tracks unscheduled engine removals, engine shutdowns, delays and cancellations and pilot reports. A monthly fleet report is published that provides various statistical data depicting the actual operational performance of the aircraft and powerplant systems.

INSPECTION DATA: Maintenance Reliability Document No EWA-51990 was reviewed. Reliability reports for July, August and September were reviewed. Inspectors attended the October Reliability Meeting. Interviews were conducted with the Manager of Reliability and Maintenance Control.

FINDING: 2.12.01: The reliability section does not utilize the entire corrective action process outlined in Chapter 6.1.A of the Maintenance Reliability Program Document, No. EWA-51990.

ANSWER: Paragraph 6.1.A states that "The Reliability Section will submit all corrective actions to the EWA MRB for Review/approval. Corrective actions may include, but are not limited to the following." The items listed in sub paragraphs 1 through 8 are examples of corrective actions that would be presented to the EWA MRB for review/approval. This does not mean that each of these type of corrective actions have to be accomplished. The type of corrective action is based on the problem, and the urgency to facilitate a corrective action. During the past 12 months Reliability has issued four (4) Fleet Campaign Directive's and submitted thirteen (13) inspection program changes.



FINDING: 2.13.01 The RRXA Time Limits Manual states that altimeters (barometric and encoding) will be inspected on each B, C and D inspection. A review of the RRXA inspection program revealed that there is no procedure to test and/or recertify the altimeters. The only test in the inspection program is to leak test the pitot and static system components and plumbing on 'C' check card #5502. The RRXA Inspection Program does not assure that altimeters are properly maintained to meet the standards of 14CFR 91.411.

RRXA RESPONSE: *Federal Aviation Regulations (FAR) 91.401, subpart E "Maintenance, Preventive Maintenance, and Alterations under 91.401(b)", states that section 91.411 of this subpart does not apply to an aircraft maintained in accordance with a continuous airworthiness maintenance program as provided in Part 121 of this chapter.*

However, in order to clarify how Transponder checks are performed and when, I have attached the procedures for the required tests.

RRXA CONCLUSION: *No finding.*

*Jim Owens
EWA Director-Quality Assurance
October 10, 2001*

FINDING: 2.13.01 The RRXA Time Limits Manual states that altimeters (barometric and encoding) will be inspected on each B, C and D inspection. A review of the RRXA inspection program revealed that there is no procedure to test and/or recertify the altimeters. The only test in the inspection program is to leak test the pitot and static system components and plumbing on 'C' check card #5502. The RRXA Inspection Program does not assure that altimeters are properly maintained to meet the standards of 14CFR 91.411.

RRXA RESPONSE: *Federal Aviation Regulations (FAR) 91.401, subpart E "Maintenance, Preventive Maintenance, and Alterations under 91.401(b)", states that section 91.411 of this subpart does not apply to an aircraft maintained in accordance with a continuous airworthiness maintenance program as provided in Part 121 of this chapter.*

RRXA CONCLUSION: *No finding.*



Jim Owens
EWA Director-Quality Assurance
September 25, 2001

EO

FINDING: 2.13.01 The RRXA Time Limits Manual states that altimeters (barometric and encoding) will be inspected on each B, C and D inspection. A review of the RRXA inspection program revealed that there is no procedure to test and/or recertify the altimeters. The only test in the inspection program is to leak test the pitot and static system components and plumbing on 'C' check card #5502. The RRXA Inspection Program does not assure that altimeters are properly maintained to meet the standards of 14CFR 91.411.

RRXA RESPONSE: *Federal Aviation Regulations (FAR) 91.401, subpart E "Maintenance, Preventive Maintenance, and Alterations under 91.401(b)", states that section 91.411 of this subpart does not apply to an aircraft maintained in accordance with a continuous airworthiness maintenance program as provided in Part 121 of this chapter.*

RRXA CONCLUSION: *No finding.*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

- EO Change -
IPC CAMA

Les Keady

OPW

91.411 Altimeter system and altitude reporting equipment tests and inspections.

(a) No person may operate an airplane, or helicopter, in controlled airspace under IFR unless -

(1) Within the preceding 24 calendar months, each static pressure system, each altimeter instrument, and each automatic pressure altitude reporting system has been tested and inspected and found to comply with appendix E of part 43 of this chapter;

(2) Except for the use of system drain and alternate static pressure valves, following any opening and closing of the static pressure system, that system has been tested and inspected and found to comply with paragraph (a), appendices E and F, of part 43 of this chapter; and

(3) Following installation or maintenance on the automatic pressure system of the ATC transponder where data correspondence error integrated system has been tested, inspected, and found to comply with appendix E, of part 43 of this chapter. x

(b) The tests required by paragraph (a) of this

(1) The manufacturer of the airplane, or helicopter, to be performed;

(2) A certificated repair station properly equipped

(i) An instrument rating, Class I;

(ii) A limited instrument rating appropriate to be tested;

(iii) A limited rating appropriate to the test to be

(iv) An airframe rating appropriate to the airplane, or helicopter, to be tested; or

(v) A limited rating for a manufacturer issued for the appliance in accordance with § 145.101(b)(4) of this chapter; or

(3) A certificated mechanic with an airframe rating (static pressure system tests and inspections only).

(c) Altimeter and altitude reporting equipment approved under Technical Standard Orders are considered to be tested and inspected as of the date of their manufacture.

(d) No person may operate an airplane, or helicopter, in controlled airspace under IFR at an altitude above the maximum altitude at which all altimeters and the automatic altitude reporting system of that airplane, or helicopter, have been tested.

August 18, 1990
91-211

91.401

FEDERAL AVIATION REGULATIONS - PART 91

SUBPART E

MAINTENANCE, PREVENTIVE MAINTENANCE, AND ALTERATIONS

91.401 APPLICABILITY.

(a) This subpart prescribes rules governing the maintenance, preventive maintenance, and alterations of U.S.-registered civil aircraft operating within or outside of the United States.

(b) Sections 91.405, 91.409, 91.411, 91.417, and 91.419 of this subpart do not apply to an aircraft maintained in accordance with a continuous airworthiness maintenance program as provided in Part 121, 127, 129, or §135.411(a)(2) of this chapter.

(c) Sections 91.405 and 91.409 of this part do not apply to an airplane inspected in accordance with Part 125 of this chapter.

91.403 GENERAL.

(a) The owner or operator of an aircraft is primarily responsible for maintaining that aircraft in an airworthy condition, including compliance with Part 39 of this chapter.

(b) No person may perform maintenance, preventive maintenance, or alterations on an aircraft other than as prescribed in this subpart and other applicable regulations, including Part 43 of this chapter.

(c) No person may operate an aircraft for which a manufacturer's maintenance manual or instructions for continued airworthiness has been issued that contains an airworthiness limitations section unless the mandatory replacement times, inspection intervals, and related procedures specified in that section or alternative inspection intervals and related procedures set forth in an operations specification approved by the Administrator under Parts 121, 127 or 135 of this chapter or in accordance with an inspection program under §91.409(e) have been complied with.

91.405 MAINTENANCE REQUIRED.

Each owner or operator of an aircraft—

(a) Shall have the aircraft inspected as prescribed in Subpart E of this part and shall between required inspections, except as provided in paragraph (c) of this section, have discrepancies repaired as prescribed in Part 43 of this chapter;

91.410(e)

May 25, 2000
91-264

FEDERAL AVIATION REGULATIONS-PART 91

- (e) For all models of the Boeing 727, the flight cycle implementation time is 45,000 flights.
- (f) For all models of the Boeing 737, the flight cycle implementation time is 60,000 flights.
- (g) For all models of the Boeing 747, the flight cycle implementation time is 15,000 flights.
- (h) For all models of the McDonnell Douglas DC-8, the flight cycle implementation time is 30,000 flights.
- (i) For all models of the McDonnell Douglas DC-9/MD-80, the flight cycle implementation time is 60,000 flights.
- (j) For all models of the McDonnell Douglas DC-10, the flight cycle implementation time is 30,000 flights.
- (k) For all models of the Lockheed L-1011, the flight cycle implementation time is 27,000 flights.
- (l) For the Fokker F-28 Mark 1000, 2000, 3000, and 4000, the flight cycle implementation time is 60,000 flights.

91.411 **ALTIMETER SYSTEM AND ALTITUDE REPORTING
EQUIPMENT TESTS AND INSPECTIONS.** (Added 91-211,
8/18/90)

- (a) No person may operate an airplane, or helicopter, in controlled airspace under IFR unless- (Added 91-211, 8/18/90)
 - (1) Within the preceding 24 calendar months, each static pressure system, each altimeter instrument, and each automatic pressure altitude reporting system has been tested and inspected and found to comply with Appendix E of Part 43 of this chapter; (Added 91-211, 8/18/90)
 - (2) Except for the use of system drain and alternate static pressure valves, following any opening and closing of the static pressure system, that system has been tested and inspected and found to comply with paragraph (a), Appendices E and F of Part 43 of this chapter; and (Added 91-211, 8/18/90)
 - (3) Following installation or maintenance on the automatic pressure altitude reporting system of the ATC transponder where data correspondence error could be introduced, the integrated system has been tested, inspected, and found to comply with paragraph (c), Appendix E, of Part 43 of this chapter. (Added 91-211, 8/18/90)

(b) The tests required by paragraph (a) of this section must be conducted by- (Added 91-211, 8/18/90)

[Next Page is No. F-78a]

91.411(b)(1)

FEDERAL AVIATION REGULATIONS-PART 91

- (1) The manufacturer of the airplane, or helicopter, on which the tests and inspections are to be performed; (Added 91-211, 8/18/90)
- (2) A certificated repair station properly equipped to perform those functions and holding- (Added 91-211, 8/18/90)
 - (i) An instrument rating, Class I; (Added 91-211, 8/18/90)
 - (ii) A limited instrument rating appropriate to the make and model of appliance to be tested; (Added 91-211, 8/18/90)
 - (iii) A limited rating appropriate to the test to be performed; (Added 91-211, 8/18/90)
 - (iv) An airframe rating appropriate to the airplane, or helicopter, to be tested; or (Added 91-211, 8/18/90)
 - (v) A limited rating for a manufacturer issued for the appliance in accordance with § 145.101(b)(4) of this chapter; or (Added 91-211, 8/18/90)
- (3) A certificated mechanic with an airframe rating (static pressure system tests and inspections only). (Added 91-211, 8/18/90)

(c) Altimeter and altitude reporting equipment approved under Technical Standard Orders are considered to be tested and inspected as of the date of their manufacture. (Added 91-211, 8/18/90)

(d) No person may operate an airplane, or helicopter, in controlled airspace under IFR at an altitude above the maximum altitude at which all altimeters and the automatic altitude reporting system of that airplane, or helicopter, have been tested. (Added 91-211, 8/18/90)

91.413 ATC TRANSPONDER TESTS AND INSPECTIONS.

(Added 91-211, 8/18/90)

(a) No person may use an ATC transponder that is specified in § 91.215(a), § 121.345(c), § 127.123(b), or § 135.143(c) of this chapter unless, within the preceding 24 calendar months, the ATC transponder has been tested and inspected and found to comply with Appendix F of Part 43 of this chapter; and (Added 91-211, 8/18/90)

(b) Following any installation or maintenance on an ATC transponder where data correspondence error could be introduced, the integrated system has been tested, inspected, and found to comply with paragraph (c), Appendix E, of Part 43 of this chapter. (Added 91-211, 8/18/90)

(c) The tests and inspections specified in this section must be conducted by- (Added 91-211, 8/18/90)

[Next Page is No. F-79]

August 18, 1990
91-211

91.413(c)(1)

FEDERAL AVIATION REGULATIONS - PART 91

- (1) A certificated repair station properly equipped to perform those functions and holding—
 - (i) A radio rating, Class III;
 - (ii) A limited radio rating appropriate to the make and model transponder to be tested;
 - (iii) A limited rating appropriate to the test to be performed;
 - (iv) A limited rating for a manufacturer issued for the transponder in accordance with §145.101(b)(4) of this chapter; or
- (2) A holder of a continuous airworthiness maintenance program as provided in Part 121, 127, or §135.411(a)(2) of this chapter; or
- (3) The manufacturer of the aircraft on which the transponder to be tested is installed, if the transponder was installed by that manufacturer.

91.415 CHANGES TO AIRCRAFT INSPECTION PROGRAMS.

(a) Whenever the Administrator finds that revisions to an approved aircraft inspection program under §91.409(f)(4) are necessary for the continued adequacy of the program, the owner or operator shall, after notification by the Administrator, make any changes in the program found to be necessary by the Administrator.

(b) The owner or operator may petition the Administrator to reconsider the notice to make any changes in a program in accordance with paragraph (a) of this section.

(c) The petition must be filed with the FAA Flight Standards district office which requested the change to the program within 30 days after the certificate holder receives the notice.

(d) Except in the case of an emergency requiring immediate action in the interest of safety, the filing of the petition stays the notice pending a decision by the Administrator.



ENGINEERING ORDER

Task Code 834111

Number AI-3411-02:00 Priority A Author Trevor Nenninger

Title Altimeter and Altitude Reporting Equipment Test

Subject Altimeter system and Altitude Reporting Equipment Test to ensure compliance
With FAR 43 Appendix E & F

Equipment/Aircraft Affected All DC-8 Acft

Drawing #'s Attached None

Manuals Affected None

Est. Man Hours/Elapsed Hours _____

WEIGHT AND BALANCE CHANGES

DRAFT

	Station	Arm	Pounds
Add	N/A	N/A	N/A
Remove	N/A	N/A	N/A
Net Gain/Loss	N/A	N/A	N/A

<p>Special Notes: Immediate Accomplishment Required by May 1st then inspection every C Check. Inspection to be done accomplished every 24 calender months.</p> <p>Reference: Douglas M/M EWA IS&S Air Data Supplement Manual FAR 43 Appendix E & F</p>	<p><u>Work Accomplished</u></p> <p>Aircraft: _____</p> <p>Date: _____</p> <p>Station: _____</p> <p>Accomp. by: _____</p> <p>_____</p>
---	---

Approved by _____

Date _____

Approved by _____

Date _____

FAA Acceptance/Approval _____

Date _____

Kit List/Spares

N/A

DRAFT

Strip List

NONE

Disposition: The disposition of the stripped part(s) must be handled in accordance with Chapter 3, Section XI of this manual.

1. General

- A. This document provides a simplified accuracy check of the altimeters, each static system and each automatic pressure altitude reporting system to be accomplished every 24 calendar months.
- B. Required test equipment
 - 1. Pitot-Static tester
 - 2. ATC TIC Tester

Note: Use applicable m/m effective for a/c setup procedures and operating manuals for equipment being used.

LOG BOOK ENTRY:

"Performed Altimeter and and Altitude Reporting test per FAR 43 Appendix E and F IAW EWA AI-3411-02:00."

Enter N/A and EWA Employee Number for procedural steps not applicable. If contract Personnel perform this E.O then see EWA Inspection Program Manual Volume 1 for proper Procedures to follow for documentation of work.

DRAFT

2. Equipment Verification

- A. Inspect all altimeters and transponders for certification dates of 24 months within todays date. List equipment P/N's, S/N's, and equipment certification dates below.

M

2. Power up

Ensure that all circuit breakers for the Flight Systems, the Transponder Systems, and the CADC/DADC are in an energized condition.

3. ALTIMETER/TRANSPONDER TEST IS&S Equipped A/C

- A. Connect pitot static tester to the pitot system and static system associated with components being tested. Refer to IS&S Supplement manual for plumbing schematics and testing procedures.

M

Note: Allow transponders 5 min warm up time before proceeding.

B. Captains altimeter, Transponder-1 selected. Verify that the indicator and transponder match the air data tester to within plus/minus 50 ft. Refer to IS&S supplement manual for normal and stby modes. Record values in Table 1.

M

CAUTION: PITOT PRESSURE MUST ALWAYS BE APPLIED WHEN CONDUCTING ANY CHECK ABOVE 5,000FT EXTREME CARE MUST BE USED WHEN MAKING THE FOLLOWING CHECKS. THE APPLICATION OF INCORRECT PRESSURES OR RAPID PRESSURE CHANGES CAN DAMAGE AIRCRAFT FLIGHT INSTRUMENTS CONNECTED TO THE PITOT STATIC SYSTEMS.

TABLE 1

Test Attitude	Captains Altimeter Reading		Transponder -1 Reading ± 125 ft
	Normal	STBY	
500 ft			± 20
1000 ft			± 20
2000 ft			± 30
4000 ft			± 35
6000 ft			± 40
8000 ft			± 60
10000 ft			± 80
15000 ft			± 105
20000 ft			± 130
25000 ft			± 155
30000 ft			± 180
35000 ft			± 205
40000 ft			±230

- C. First officers altimeter, transponder -2 selected. Verify that the indicator and transponder match the air data tester to within plus/minus 50 ft. Refer to IS&S supplement manuals for normal and stby modes. Record values in Table 2 :

M
I

TABLE 2

Test Attitude	FO's Altimeter Reading		Transponder -2 Reading ± 125 ft
	Normal	STBY	
500 ft			± 20
1000 ft			± 20
2000 ft			± 30
4000 ft			± 35
6000 ft			± 40
8000 ft			± 60
10000 ft			± 80
15000 ft			± 105
20000 ft			± 130
25000 ft			± 155
30000 ft			± 180
35000 ft			± 205
40000 ft			±230

4. ALTIMETER/TRANSPONDER TEST Non IS&S equipped A/C

- A. Connect pitot static tester to the pitot system and static system associated with components being tested. Refer to applicable m/m for test procedures for transponder altitude reporting and altimeter maintenance practices.

M

Note: Allow transponders 5 min warm up time before proceeding.

Note: Label N/A in blocks not effective for aircraft in table 3 & 4.

B. Record values for Captains correlation test in tables 3 .

M
I

TABLE 3

Test Attitude	Captain's Altimeter Reading	Transponder -1 ± 125 ft	Transponder -2 ± 125 ft
500 ft	± 20		
1000 ft	± 20		
2000 ft	± 30		
4000 ft	± 35		
6000 ft	± 40		
8000 ft	± 60		
10000 ft	± 80		
15000 ft	± 105		
20000 ft	± 130		
25000 ft	± 150		
30000 ft	± 180		
35000 ft	± 205		
40000 ft	± 230		

DRAFT

C. Record values for FO's correlation test in Table 4 .

M
I

TABLE 4

Test Attitude	FO's Altimeter Reading	Transponder -1 ± 125 ft	Transponder -2 ± 125 ft
500 ft	± 20		
1000 ft	± 20		
2000 ft	± 30		
4000 ft	± 35		
6000 ft	± 40		
8000 ft	± 60		
10000 ft	± 80		
15000 ft	± 105		
20000 ft	± 130		
25000 ft	± 155		
30000 ft	± 180		
35000 ft	± 205		
40000 ft	± 230		

D. Record values for STBY Altimeter (if equipped) correlation Test in Table 5.

M

TABLE 5

Test Attitude	STBY Altimeter Reading	Transponder -1 ± 125 ft	Transponder -2 ± 125 ft
500 ft	_____	± 20	_____
1000 ft	_____	± 20	_____
2000 ft	_____	± 30	_____
4000 ft	_____	± 35	_____
6000 ft	_____	± 40	_____
8000 ft	_____	± 60	_____
10000 ft	_____	± 80	_____
15000 ft	_____	± 105	_____
20000 ft	_____	± 130	_____
25000 ft	_____	± 150	_____
30000 ft	_____	± 180	_____
35000 ft	_____	± 205	_____
40000 ft	_____	± 230	_____

DRAFT

Note: Any system found to be out of tolerance must be repaired and retested.

D. Return Pitot Static tester to sea level and vent all systems to ground

M

5. Close up

A. Turn transponders off

M

B. Disconnect pitot - static tester

M

C. Remove tape installed for test from pitot tubes and static ports.

M

--

D. Open circuit breakers closed for power up.

M

6. Complete the "Work Accomplished" section on page 1 of this EO and make a log book entry indicating compliance with this EO. Attach EO to log page to be sent to records.

M

Log page Number _____

NOTE: Any questions regarding this EO contact EWA Engineering department.


DRAFT



U. S. Department
of Transportation

Federal Aviation
Administration

2.13.02



cc: Jerry Sumner
Bud Duce
Jim Owens

FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

February 13, 2001

FILE NUMBER: 2001GL050034

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

On January 22, 2001, you were advised that the Federal Aviation Administration was investigating a possible violation of a Federal Aviation Regulation involving Emery Worldwide Airlines Inc.(EWA) Certificate (RRXA). During the RASIP it was contended that EWA had not organized to separate the required inspection functions from other maintenance functions. Emery Policy and Procedures Manual states that every effort should be made to avoid a required Inspection Item (RII) inspector from being involved in the work or supervision of an RII item.

This letter is to inform you that the investigation has not established a violation of the Federal Aviation Regulations and you may consider this matter closed.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

A N

2.13.02 RRXA does not have adequate separation between maintenance and inspection. The RRXA MPPM states that every effort should be made to avoid a Quality Control (QC) inspector, RII inspector or Designated QC Inspector being involved in the work or supervision of an RII. RRXA does not have sufficient inspectors; of the 63 RII authorized inspectors at DAY; six (6) are in the QC/QA departments and four (4) of these are directors or managers. This is contrary to 14CFR 121.365(c).


RRXA RESPONSE: EWA meets the FAR requirements of 121.365(c) providing a separation of maintenance and inspection by the use of delegated Inspection (RII) authority (MPP, Chapter 4, page 121). EWA currently employs 465 mechanics to which 128 are designated RII personnel. This number only represents 27% of the mechanics, as qualified, authorized designated RII personnel. EWA's MOO procedures administer and control the required separation of the maintenance and inspection functions.

RRXA CONCLUSION: No finding.



U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

cc: *Jim Owens*
Gerry Lomaco
Bob Dall

January 23, 2001

2.13.02 ✓

FILE NUMBER: 2001GL050034

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

Emery Worldwide Airlines Inc. Certificate (RRXA) does not have adequate separation between maintenance and inspection. The RRXA Maintenance Policy & Procedures Manual states that every effort should be made to avoid a Quality Control (QC) inspector, RII inspector or Designated QC Inspector being involved in the work or supervision on an RII. RRXA does not have sufficient inspectors; of the 63 RII authorized inspectors at Dayton; six (6) are in the QC/QA departments and four (4) of these are directors or managers. This is contrary to 14CFR 121.365 (c).

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector


121.365 Maintenance, preventive maintenance, and alteration organization.

(a) Each certificate holder that performs any of its maintenance (other than required inspections), preventive maintenance, or alterations, and each person with whom it arranges for the performance of that work must have an organization adequate to perform the work.

(b) Each certificate holder that performs any inspections required by its manual in accordance with § 121.369(b)(2) or (3) (in this subpart referred to as "required inspections") and each person with whom it arranges for the performance of that work must have an organization adequate to perform that work.

(c) Each person performing required inspections in addition to other maintenance, preventive maintenance, or alterations, shall organize the performance of those functions so as to separate the required inspection functions from the other maintenance, preventive maintenance, and alteration functions. The separation shall be below the level of administrative control at which overall responsibility for the required inspection functions and other maintenance, preventive maintenance, and alteration functions are exercised.

2.13.02




MPL 3-30?

FINDING: 2.14.01 Maintenance Control uses a different report than the one used by Reliability for monitoring pilot write-ups and it does not capture aircraft subsystems that exhibit three (3) or more repeat write-ups in the previous 24 hours. This is contrary to RRXA MPPM, Chapter 4, Page 1 0, Item 6.a.

RRXA RESPONSE *The report that Maintenance Control uses to identify 3 in 10 write ups is generated from the MERIT daily report. Maintenance Control now utilizes both the daily report and the program that reliability uses (EWAREL2) to identify repeat items. The program is 3 in 10 days not 3 in 24 hours as stated in the alleged finding. The EWA program has now been changed to 3 in 30 days see attached manual revision request.*

RRXA CONCLUSION: *No finding.*


[Redacted]
Kim Owens
EWA Director-Quality Assurance
21 February 2001

OIC

EMERY WORLDWIDE AIRLINES ENGINEERING POLICIES & PROCEDURES MANUAL

3. Repeat Pilot Report Control System

a. General

The Repeat Pilot Report Control System is administered to provide an effective means of monitoring and controlling repeated and chronic problems reported with specific aircraft sub-systems. The objective of the system is to provide absolute control of redundant or repeated maintenance actions. The system proves as a valuable tool in facilitating troubleshooting complex systems and significantly minimizing occurrences of unnecessary of redundant component removals. This program is part of the EWA Reliability Program Document No. EWA-51990.

b. Definitions

- 1) Repeat Write-Up - a write-up is defined when a discrepancy is reported on an aircraft with a specific ATA sub-system three (3) times or more within a consecutive thirty (30) day period.
- 2) Chronic - a system is defined when a repeated condition recurs on an aircraft with a specific ATA sub-system within a consecutive ninety (90) day period.

c. Responsibility

- 1) The Directors of Maintenance, Engineering, and Quality Assurance are responsible for ensuring that continual monitoring of pilot reports is maintained to effectively control repeated and chronic write-ups.
- 2) It is the joint responsibility of the Flight Crew, Maintenance, Engineering, and Quality Assurance personnel to ensure adequate and accurate information is communicated to effectively identify and control repeated write-ups.

d. Pilot Reports

- 1) Flight crew personnel record observed aircraft system and component malfunctions or discrepancies in the Aircraft Maintenance Log Book.
- 2) All entries should be legible, concise, and sufficient in detail to fully describe the observed malfunction or discrepancy to facilitate system troubleshooting and fault isolation.

EMERY WORLDWIDE AIRLINES ENGINEERING POLICIES & PROCEDURES MANUAL

e. Pilot Report Data Processing

- 1) Reliability and/or Aircraft Records processes pilot report data from the aircraft maintenance log sheets into the computer database system on a daily basis. All entries are assigned specific sub-system ATA codes by Reliability.
- 2) The computer database maintains a historical file of pilot reports categorized by primary system and sub-system ATA codes.
- 3) Maintenance Control and Reliability generate Repeat Pilot Reports summaries regularly to enable prompt identification of specific aircraft sub-systems that exhibit repeated write-ups which may require remedial action(s).

f. Maintenance Control

- 1) Maintenance Control monitors the pilot report database daily to promptly identify specific aircraft sub-systems that exhibit three (3) or more repeated write-ups within a consecutive thirty (30) day period.
- 2) Write-ups are monitored and evaluated to determine appropriate troubleshooting steps and/or other maintenance action(s) as required.
- 3) When repeated write-ups are identified, Work Requests may be released to the field to direct specific troubleshooting or other maintenance action(s) to correct the repeated discrepancies as warranted.
- 4) When action notices are received leaving the specified action(s) to the field. As all specified actions are completed, Maintenance Control closes out the original Reliability Action Notice and returns it to the Manager of Reliability within ten (10) days after the release date.
- 5) In the event that an aircraft continues to exhibit repeated or chronic problems with a system or systems after unsuccessful attempts have been made to correct the problems, the Director of Maintenance, Engineering or Quality Control determines the necessity of removing the aircraft from service until causes of the specific problems are successfully isolated and completely rectified.



2.14.02 RRXA quarterly self-audits of the Dayton materials departments are not conducted. This is contrary to 14CFR 121.373.

RRXA RESPONSE: Quarterly Self-audits have always been accomplished using the MEO63 report. However, there were no instructions to send the report to QA or QC. Instructions have now been implemented to send the completed report to QA and QC.

RRXA CONCLUSION: No finding.

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

closed 3/13/01

.373 Continuing analysis and surveillance.

(a) Each certificate holder shall establish and maintain a system for the continuing analysis and surveillance of the performance and effectiveness of its inspection program and the program covering other maintenance, preventive maintenance, and alterations and for the correction of any deficiency in those programs, regardless of whether those programs are carried out by the certificate holder or by another person.

(b) Whenever the Administrator finds that either or both of the programs described in paragraph (a) of this section does not contain adequate procedures and standards to meet the requirements of this part, the certificate holder shall, after notification by the Administrator, make any changes in those programs that are necessary to meet those requirements.

(c) A certificate holder may petition the Administrator to reconsider the notice to make a change in a program. The petition must be filed with the FAA certificate-holding district office charged with the overall inspection of the certificate holder's operations within 30 days after the certificate holder receives the notice. Except in the case of an emergency requiring immediate action in the interest of safety, the filing of the petition stays the notice pending a decision by the Administrator.

2.14.02



2.14.03 RRXA 24-month hub/fine station audit follow-up procedure is not being followed for Dayton stores. This is contrary to RRXA MPPM, Chapter 4.

RRXA RESPONSE: EWA Quality Assurance performed an internal audit of the Dayton Hub/Line Station in September and August of 2000. After the audit, Quality Assurance was in constant contact the Directors and Managers who were responsible for correcting noted deficiencies. However, no records were maintained concerning the follow-up discussions. Since the audit, Quality Assurance has performed two follow-up audits and all findings were corrected. In the future follow-up procedures as shown in the MPPM will be complied with.

RRXA CONCLUSION: Finding was valid.

*Jim Owens
EWA Director-Quality Assurance
23 February 2001*

e10rd 3/13/01



MEMORANDUM

TO: Jim Owen

FROM: Ronald E. Moody, Manager Quality Assurance

SUBJECT: FAA RASIP Finding

DATE: February 23, 2001

2.14.03

Emery Worldwide Airlines's Quality Assurance performed an internal audit of the Dayton Hub/Line Station the month of August and September, 2000. After performing the audit, Quality Assurance was in constant contact with Managers and Directors verbally, and by phone follow-up to resolve all of the open audit findings that were not answered in the allotted time given by the auditors. Since the audit, Quality Assurance has been performing a full follow-up audit on the previous audit performed. Quality Assurance in the future will be focusing more on the follow-up procedures listed in the Maintenance Policy and Procedures Manual, Chapter 4, Pager 27, Item H.

REM/bl





2.14.04


cc: Jerry Jimarico
Don Owens
Bob Hall

U. S. Department
of Transportation

Federal Aviation
Administration

FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

February 12, 2001



FILE NUMBER: 2001GL050035

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

On January 24, 2001, you were advised that the Federal Aviation Administration was investigating a possible violation of a Federal Aviation Regulation involving Emery Worldwide Airlines Inc. Certificate (RRXA). This alleged violation was, Emery Worldwide Airlines Inc. Certificate (RRXA) Maintenance Policy and Procedures Manual (MPPM) Chapter 4, Section F.3 defers to Coordinating Agency for Supplier Evaluation (CASE) for intervals of audits. CASE performs audits, they do not establish intervals.

This letter is to inform you that the investigation has not established a violation of the Federal Aviation Regulations and you may consider this matter closed.

Sincerely,

Leslie Korody
Principal Avionics Inspector

A N

2.14.04 RRXA MPPM, Chapter 4, Section F.3 defers -to CASE for intervals of audits. CASE performs audits, they do not establish intervals. This is contrary to 14CFR121.373 and the 24 months that's been established by RRXA in their MPPM.


RRXA RESPONSE: MPP, Chapter 4, page 26 provides a 24 calendar month audit interval for Vendor/ Contract agencies. Page 39, of the same chapter, item E "C.A.S.E. Vendor Performance Monitoring (FAR 121.373), provides an FAA acceptable means of vendor surveillance and analysis compliance per 121.373(a). The audit intervals are controlled by the Air Carrier Section of the C.A.S.E. Policy and Procedures Manual.

RRXA CONCLUSION: No finding.



U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

*cc: Jim Owens
Jerry Trunardo
Bob Hall*

January 24, 2001

2,14.04 ✓

FILE NUMBER: 2001GL050035

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

Emery Worldwide Airlines Inc. Certificate (RRXA) Maintenance Policy and Procedures Manual (MPPM) Chapter 4, Section F.3 defers to Coordinating Agency for Supplier Evaluation (CASE) for intervals of audits. CASE performs audits; they do not establish intervals. This is contrary to the 24 months that's been established by RRXA in their MPPM.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

for

Harold R. Camden
Principal Maintenance Inspector

§ 121.373 Continuing analysis and surveillance.

(a) Each certificate holder shall establish and maintain a system for the continuing analysis and surveillance of the performance and effectiveness of its inspection program and the program covering other maintenance, preventive maintenance, and alterations and for the correction of any deficiency in those programs, regardless of whether those programs are carried out by the certificate holder or by another person.

(b) Whenever the Administrator finds that either or both of the programs described in paragraph (a) of this section does not contain adequate procedures and standards to meet the requirements of this part, the certificate holder shall, after notification by the Administrator, make any changes in those programs that are necessary to meet those requirements.

(c) A certificate holder may petition the Administrator to reconsider the notice to make a change in a program. The petition must be filed with the FAA certificate-holding district office charged with the overall inspection of the certificate holder's operations within 30 days after the certificate holder receives the notice. Except in the case of an emergency requiring immediate action in the interest of safety, the filing of the petition stays the notice pending a decision by the Administrator.

[Doc. No. 6258, 29 FR 19210, Dec. 31, 1964, as amended by Amdt. 121-207, 54 FR 39293, Sept. 25, 1989; Amdt. 121-253, 61 FR 2611, Jan. 26, 1996]

2, 14, 04



FINDING: 2.15.01 The Director of Quality Control and the Director of Engineering were not aware of their responsibility for reporting MRR's to the FAA. This is contrary to their MPPM.

RRXA RESPONSE: *These Directors have reviewed their responsibilities for ensuring that MRR's are reported as required by the EWA MPPM and FAR 121.703 and are meeting their responsibilities.*

The Manager of Reliability, who reports to the Director of Engineering, is responsible for determining that each report is received and for submitting it to the FAA. This is being accomplished.

The Director of Quality Control is responsible for ensuring that the reports are audited to reflect accurate and sufficient information. He has reviewed his responsibilities and believes this is being accomplished.

As an improvement to the procedure, the Manager of Reliability now forwards all MRR's submitted to both the Directors of Quality Control and Engineering at the time of submission for review and use.

RRXA CONCLUSION: No finding

closed 8/13/01

R

RASIP Finding Item 2.15.01

February 9, 2001


"The Director of Quality Control and the Director of Engineering were not aware of their responsibility for reporting MRR's to the FAA. This is contrary to their MPPM."

These Directors have reviewed their responsibilities for ensuring that MRRs are reported as required by the Emery MPPM and FAR 121.703 and believe they are meeting those responsibilities.

The Manager of Reliability, who reports to the Director of Engineering, is responsible for determining that each report is required and for submitting it to the FAA. This is being accomplished. *Accepted*

The Director of Quality Control is responsible for ensuring reports are audited to reflect accurate and sufficient information is being submitted. He has reviewed his responsibilities and believes this is being accomplished.

As an improved procedure, the Manager of Reliability now forwards all MRRs submitted to both the Directors of Quality Control and Engineering at the time of submission for their department's review and use.



AH

FINDING: 2.16.01 RRXA does not maintain a list of major alterations to each airframe, engine and appliance. This is contrary to 14CFR 121.380(a)(2)(vii).

RRXA RESPONSE: *121.380(a)(1)(vii) requires "A list of current major alterations to each airframe, engine, propeller and appliance", however not a list of major repairs.*

121.707 requires EWA to prepare a report of each major alteration and submit to the FSDO FAA Principal and keep a copy of each report of a major repair available for inspection by the FSDO FAA Principal.

EWA maintains a record of all major repairs to which ni lists are required by the FARS's. A list of all major alterations was maintained, however, not complete. This review was underway during the RASIP and is complete.


RRXA CONCLUSION: *No finding.*



U. S. Department
of Transportation

Federal Aviation
Administration

FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420



cc: *Jim Adams*
Jerry Sumasco
Bob Hall

January 24, 2001

2.16.01 ✓

FILE NUMBER: 2001GL050036

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.


Emery Worldwide Airlines Inc. Certificate (RRXA) does not maintain a list of major alterations to each airframe, engine and appliance.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,


HR

Harold R. Camden
Principal Maintenance Inspector




U. S. Department
of Transportation

Federal Aviation
Administration

2,16,02

cc: Jerry Sumarco
Bob Dale
~~Jim Owens~~



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

February 14, 2001

FILE NUMBER: 2001GL050037

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

On January 22, 2001, you were advised that the Federal Aviation Administration was investigating a possible violation of a Federal Aviation Regulation involving Emery Worldwide Airlines Inc. Certificate (RRXA). The alleged violation was, RRXA Maintenance Authorization (MA)/Engineering Order's (EO) are being classified as minor alterations, when the alteration is actually a major alteration. The lack of proper classification impacts the recording requirements of 14CFR 121.380(a)(2)(vii), which requires the certificate holder to maintain a listing of current major alterations to each airframe, engine and/or appliance.

This letter is to inform you that the investigation has not established a violation of the Federal Aviation Regulations and you may consider this matter closed.

Sincerely,

Leslie Korody
Principal Avionics Inspector

A N

2.16.2 RRXA MA/EO's are being classified as minor alterations, when the alteration is actually a major alteration. The lack of proper classification impacts the recording requirements of 14CFR 121.380(a)(2)(vii), which requires the certificate holder to maintain a listing of current major alterations to each airframe, engine and/or appliance.


RRXA RESPONSE: This alleged finding does not address any specific MA/EO which makes it difficult to respond. However, it is believed that this is in regards to the Livestock Restraint Installation STC SA1602SO. This is installed as a unit load device, and is not a major alteration or design change (FAR21.113) to the aircraft.

RRXA CONCLUSION: No finding.



U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

cc: Jim Owens
Jerry Sumner
Bob Hall

January 24, 2001

2.16.01 ✓

FILE NUMBER: 2001GL050037

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

Emery Worldwide Airlines Inc. Certificate (RRXA) Maintenance Authorization (MA)/Engineering Order's (EO) are being classified as minor alterations, when the alteration is actually a major alteration. The lack of proper classification impacts the recording requirements of 14CFR 121.380(a)(2)(vii), which requires the certificate holder to maintain a listing of current major alterations to each airframe, engine and/or appliance.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

FAA 8/21/01

FINDING: 2.17.01 The monthly spot check on fueling equipment required by RRXA MPPM, Chapter 4, Page 85 is not done IAW with the manual. The MPPM requires this check to be done by the 15th of the month. The check for September was completed on 09/21/00. The check for October had not been accomplished.

RRXA RESPONSE: *This issue was not discussed in the out briefing or in the Preliminary Rasip Finding Report. However, documentation provided by the FAA does confirm that the Finding was correct.*

Timeliness of these audits was emphasized with all concerned and the December, 2000 Audit was completed on the 5th and January, 2001 was accomplished on the 8th.

RRXA CONCLUSION: *Finding.*

*Jim Owens
Director-Quality Assurance
7/26/01*

FINDING: 2.17.01 The monthly spot check on fueling equipment required by RRXA MPPM, Chapter 4, Page 85 is not done IAW with the manual. The MPPM requires this check to be done by the 15th of the month. The check for September was completed on 09/21/00. The check for October had not been accomplished.

RRXA RESPONSE: *This issue was not discussed in the out briefing or in the Preliminary Rasip Finding report. Per policy the previous months Fueling Equipment Inspection Checklist form MEO57 is discarded when the next inspection is accomplished. Since we had no advance knowledge of this finding we are unable to verify the accuracy of the finding. However, the December inspection was done on the 5th and January, 2001 was accomplished on the 8th.*

*A manual change request has been submitted to emphasize the audit finding process and change reference to Quality Control to Quality Assurance.
(Copy attached).*

RRXA CONCLUSION: *No finding.*

*Jim Owens
Director-Quality Assurance
2/09/01*

B N

FINDING: 2.17.01 The monthly spot check on fueling equipment required by RRXA MPPM, Chapter 4, Page 85 is not done IAW with the manual. The MPPM requires this check to be done by the 15th of the month. The check for September was completed on 09/21/00. The check for October had not been accomplished.

RRXA RESPONSE: *This issue was not discussed in the out briefing or in the Preliminary Rasip Finding report. Per policy the previous months Fueling Equipment Inspection Checklist form MEO57 is discarded when the next inspection is accomplished. Since we had no advance knowledge of this finding we are unable to verify the accuracy of the finding. However, the December inspection was done on the 5th and January, 2001 was accomplished on the 8th.*

RRXA CONCLUSION: *No finding.*

QC change TO QA -

Check for 2.17.01

EMERY WORLDWIDE AIRLINES MAINTENANCE POLICY & PROCEDURES MANUAL

FUELING EQUIPMENT INSPECTION CHECKLIST -- FORM ME057

EMERY WORLDWIDE AIRLINES FUELING EQUIPMENT INSPECTION CHECKLIST

Fueler Jim Fuller Driver Jim Fuller
 Address KDAY Date 12-5-00
 Phone No. XXXXXXXXXX

Station/Systems _____

- A. Equipment: (Trucks, Carts, Pits)
 B. Check and Record (S - Satisfactory, U - Unsatisfactory)

Identification Number	0025	0024	9007	B002-1	862-11
1. Sumps	S	S	S	S	S
2. Ground Wire Condition	S	S	S	S	S
3. Check and Record Filter/Dates	8-1-00	5-2-00	12-28-99	4-28-00	10-10-00
4. Fire Extinguisher	S	S	S	S	S
5. Dust Caps	S	S	S	S	S
6. Meter Calibration (Date)	9-11-00	9-11-00	1-28-00	1-28-00	1-28-00
7. Delivery Pressure (50 psi max)	40	40	40	40	40
8. Check and Record Diff. Press. (15 psi max)	3.0	3.0	2.0	3.0	2.5
9. Hose, Swivel, Nozzle Condition	S	S	S	S	S
10. Markings (type fuel/no smoking)	S	S	S	S	S
11. Muffler/Flame Arrestor	S	S	S	S	S
12. General Appearance and Condition	S	S	S	S	S

Remarks _____

Jim Fuller Jim Fuller 12-5-00
 Checked by Reviewed by Date

ME057 (R3 07/09/92)

**EMERY WORLDWIDE AIRLINES
MAINTENANCE POLICY & PROCEDURES MANUAL**

FUELING EQUIPMENT INSPECTION CHECKLIST -- FORM ME057

**EMERY WORLDWIDE AIRLINES
FUELING EQUIPMENT INSPECTION CHECKLIST**

Fueler Jim Fuller Driver _____
 Address KDAY Date 1-8-01
 Phone No. _____

Station/Systems _____

- A. Equipment: (Trucks, Carts, Pits)
 B. Check and Record (S - Satisfactory, U - Unsatisfactory)

Identification Number	0025	0024	9007	B000-1	868-11
1. Sumps	S	S	S	S	S
2. Ground Wire Condition	S	S	S	S	S
3. Check and Record Filter/Dates	8-1-00	5-2-00	12-28-00	4-28-00	10-10-00
4. Fire Extinguisher	S	S	S	S	S
5. Dust Caps	S	S	S	S	S
6. Meter Calibration (Date)	9-11-00	9-11-00	1-28-00	1-28-00	1-28-00
7. Delivery Pressure (50 psi max)	40	40	40	40	40
8. Check and Record Diff. Press. (15 psi max)	3.0	3.0	2.0	3.0	3.0
9. Hose, Swivel, Nozzle Condition	S	S	S	S	S
10. Markings (type fuel/no smoking)	S	S	S	S	S
11. Muffler/Flame Arrestor	S	S	S	S	S
12. General Appearance and Condition	S	S	S	S	S

Remarks _____

Jim Fuller [Signature] 01-08-01
 Checked by Reviewed by Date

ME057 (03 07/09/97)

(V)


over

FINDING: 2.17.01 The monthly spot check on fueling equipment required by RRXA MPPM, Chapter 4, Page 85 is not done IAW with the manual. The MPPM requires this check to be done by the 15th of the month. The check for September was completed on 09/21/00. The check for October had not been accomplished.

RRXA RESPONSE: This issue was not discussed in the out briefing or in the Preliminary Rasip Finding report. Per policy the previous months Fueling Equipment Inspection Checklist form MEO57 is discarded when the next inspection is accomplished. Since we had no advance knowledge of this finding we are unable to verify the accuracy of the finding. However, the December inspection was done on the 5th and January, 2001 was accomplished on the 8th.

*A manual change request has been submitted to emphasize the audit finding process and change reference to Quality Control to Quality Assurance.
(Copy attached).*

RRXA CONCLUSION: No finding.


Mike Owens
Director-Quality Assurance
2/09/01

EMERY WORLDWIDE AIRLINES
Request for Manual/Publication Revision

____ ERROR X SUGGESTION FOR CHANGE (check appropriate space) No. _____
DATE 03-14-01

MANUAL/PUBLICATION TITLE Maintenance Policy and Procedures Manual

CHAPTER/SECTION/PAGE REFERENCE ch 4 pag 85 PARAGRAPH 3 (a)

DESCRIPTION OF ERROR OR SUGGESTED CHANGE

It has been noted during an FAA audit that the procedures regarding the Q.C. Review of the MEOS7 form should contain an Action Requirement by the Q.C. Inspector reviewing this form. I request that the MRBP change for Paragraph or item 3.(a) last sentence to be changed to state "The Q.A. Inspector reviewing the ~~MEOS7~~ MEOS7 issue an audit finding report to the Vendor for any items or blocks that are not satisfactory completed. Reverts of the information contained in the station file.

Name Richard Parsons

Signature [Signature]

Station Location KDAY

Phone [Redacted]

Supervisor Approval _____

Director Maint. Approval _____

Director QC Approval _____

Instructions:

1. Attach drawings, sketches, diagrams, etc.
2. Forward to Director of Quality Control

MRB Approval Required (Check One) YES NO

Mgr. Of Reliability _____

EMERY WORLDWIDE AIRLINES MAINTENANCE POLICY & PROCEDURES MANUAL

3. Fueling Equipment Inspection Reports

a. EWA Fueling Equipment Inspection Checklist Form MEO57 will be used as a guide for the inspection of fueling equipment and vehicles. The EWA Line Supervisor or his designee performing the inspection shall enter, in the respective blanks, the date of the last filter change, contamination check, and fuel sample. Any discrepancies, remarks, and recommendations are also to be entered on this form. The completed form will be forwarded to Quality Control for review to determine if any follow-up action is required. *ASSURANCE*

b. EWA Jet Fuel Vendor Checklist (Form MEO64) will be used as a guide by the Quality Control Auditor or representative to perform a full audit on the fuel vendors. Any discrepancies, remarks, and recommendations will be documented. A copy of the completed form will be forwarded to the Manager of Quality Control for review to determine if any follow-up action is required. *ASSURANCE*

c. Frequency of Inspection: The EWA Line Station Supervisor or his designee at each EWA class I or II Line Station will perform a monthly spot check on fueling equipment prior to the 15th of the month. Additionally, a Quality Control Auditor or Representative will perform a full audit at each station each twenty-four (24) calendar months or at the discretion of the Director of Quality Control. Quality Control in Dayton will keep the completed inspection forms on file. *ASSURANCE*

d. Form MEO57 that is completed by the EWA Line Station Supervisor or his designee will be forwarded to Quality Control. This form will be retained on file for 30 days and then discarded. *ASSURANCE*

e. Form MEO64 that is completed by Quality Control Auditors or Representative will be retained on file at Quality Control in Dayton until repeated. *ASSURANCE REPRESENTATIVE*

4. Fueling Equipment Inspection Checklist Guide Completion Instructions (MEO 57).

a. Complete the entire heading of the fueling spot checked.

b. Equipment (Circle: Trucks, Carts, Pits, as applicable). Enter identification number of equipment inspected.

2.17.01

**EMERY WORLDWIDE AIRLINES
FUELING EQUIPMENT INSPECTION CHECKLIST**

Fueler Emery worldwide

Driver _____

Address _____

Date 9-21-00

Vandalia, OH, 45377

Phone No. _____

Station/Systems 15 DAY

A. Equipment: (Trucks, Carts, Pits)

B. Check and Record (S - Satisfactory, U - Unsatisfactory)

Identification Number	Bass Jet 12	7	9	15	
1. Sumps	S	S	S	S	
2. Ground Wire Condition	S	S	S	S	
3. Check and Record Filter/Dates	4-28-00	9-14-99	9-11-99	8-1-00	
4. Fire Extinguisher	S	S	S	S	
5. Dust Caps	S	not attached	S	S	
6. Meter Calibration (Date)	unrecalable	unrecalable	unrecalable	9-11-2000	
7. Delivery Pressure (50 psi max)	30	30	40	45	
8. Check and Record Diff. Press. (15 psi max)	2.5	2.5	2.5	2.5	
9. Hose, Swivel, Nozzle Condition	S	S	S	S	
10. Markings (type fuel/no smoking)	S	S	S	S	
11. Muffler/Flame Arrestor	S	S	S	S	
12. General Appearance and Condition	S	S	S	S	

Remarks TRUCK 7 Fwd FIRE EX. WATER IN GAGE

[Signature] 30287



Checked by

Reviewed by

Date

2,17,01

**EMERY WORLDWIDE AIRLINES
FUELING EQUIPMENT INSPECTION CHECKLIST**

Fueler Emery worldwide

Driver _____

Address _____

Date 9-21-00

Vandiver, OH 45377

Phone No. _____

Station/Systems 15 DAY

A. Equipment: (Trucks, Carts, Pits)

B. Check and Record (S - Satisfactory, U - Unsatisfactory)

Identification Number	Boss JET 12	7	9	15	
1. Sumps	S	S	S	S	
2. Ground Wire Condition	S	S	S	S	
3. Check and Record Filter/Dates	4-28-00	9-14-99	9-11-99	8-7-00	
4. Fire Extinguisher	S	S	S	S	
5. Dust Caps	S	^S not attached	S	S	
6. Meter Calibration (Date)	unreadable	unreadable	unreadable	9-11-2000	
7. Delivery Pressure (50 psi max)	30	30	40	45	
8. Check and Record Diff. Press. (15 psi max)	2.5	2.5	2.5	2.5	
9. Hose, Swivel, Nozzle Condition	S	S	S	S	
10. Markings (type fuel/no smoking)	S	S	S	S	
11. Muffler/Flame Arrestor	S	S	S	S	
12. General Appearance and Condition	S	S	S	S	

Remarks TRUCK 7 Fwd FIRE EX. WATER IN GAGE

[Signature] 30284



Checked by


Reviewed by

Date

CUSTOMER:
 Emery Worldwide
 One Emery Plaza/Dayton International Airport
 Vandalia, Ohio 45377

BOB'S METER TESTING

DIV. OF PETROLEUM EQUIPMENT SERVICE, INC.
 1776 MORGAN ROSS RD. * HAMILTON, OHIO 45013
 PHONE: (513) 738-3940 * FAX: (513) 738-3940



ATTN: Mr. Jim Davis

CALIBRATION RECORD

DATE 9-11-2000

METER #	TYPE	SERIAL NUMBER	MAKE & MODEL	PRODUCT	TANK #	LAST CAL	RESULT	ADJ. TO	GPM
1	Truck 888-10	8412-27295-1-1A	Brodie B-80 CAL	Jet-A	Refueler	1-28-2000	1.33	-0.20	NT.
2	Truck Boss-1	None	L.C. M-30	Jet-A	Refueler	1-28-2000	2.28	-0.16	NT.
3	Truck 888-307	BM-96658	Smith AFS-6R-NF	Jet-A	Refueler	1-28-2000	0.05	0.05	NT.
4	Truck 888-306	128065	L.C. M-60	Jet-A	Refueler	1-28-2000	-0.65	-0.16	NT.
5	Truck 888-9007	None	Brodie B-82	Jet-A	Refueler	1-28-2000	1.16	-0.06	NT.
6	Truck 888-9	8412-27295-1-2A	Brodie B-80 CAL	Jet-A	Refueler	1-28-2000	1.38	-0.04	NT.
7	Truck 888-1	119785	L.C. M-60	Jet-A	Refueler	1-28-2000	-2.50	-0.16	NT.
8	Truck 888-2	123281	L.C. M-60	Jet-A	Refueler	1-28-2000	0.86	-0.16	NT.
9	Truck 888-11	8702-10922-1-1A	Brodie B-80 CAL	Jet-A	Refueler	2-11-2000	2.07	-0.16	NT.
10	Truck #14	9910-U001057-1-1A	Brodie B80CAL	Jet-A	Refueler	New	2.21	-0.06	413
12	Truck #15	0001-U001-418-1-1A	Brodie B80CAL	Jet-A	Refueler	New	-1.26	-0.01	460
14	Fuel Farm #1	AH 134890	Smith F4-S1	Jet-A		Unknown	-7	0	326
15	Fuel Farm #2	AH 90475	Smith F4-S1	Jet-A		Unknown	-44	0	334

Note: Meters were checked with a prover calibrated and sealed by N.I.S.T. Frankfort, KY. August 2000.
 Note: "Results" and Adjusted To" columns are shown in gallons per 1000 gallons unless indicated otherwise.
 NT=NOT TESTED

Certified Technician: Robert M. Etsch

Moody, Ronald E

From: Parsons, Richard A
Sent: Wednesday, March 14, 2001 1:43 PM
To: Moody, Ronald E; Owens, James H
Cc: Porter, Andrew C
Subject: MEO57 Monthly fueling equipment inspection

Regarding the question of why I did not write an audit finding for the blocks that were marked unreadable. I do not recall if I did or did not issue an audit finding report for the MEO57 form at the DAY station. A closer review indicated that 3 of the 4 trucks looked at had the same blocks completed in the same way. After a review of the previous quality control audit and knowing the history of the DAY fueler this did not indicate a problem with the fueling equipment. To the best of my recollection the previous MEO57 did not indicate a problem either. It is my understanding that the MEO57 is a tool that is to be used by the QC department as a means to monitoring the EWA fuel vendors. IAW the EWA MP&P chapter 4 page 85, item 3 (a) this form is to be "**reviewed to determine if any follow-up action is required**". With the history of the DAY fuel vendor, (as reviewed in the file) and the recently completed Quality Control audit. This isolated incident did not require any further action at that time. The Quality Control audit was completed in August of that year with no findings issued for this problem. I assisted with this audit and found no deficiencies in this area at that time. To the best of my recollection the previous form did not indicate a problem. This situation was monitored for recurrence and none was noted.

EMERY WORLDWIDE AIRLINES
Request for Manual/Publication Revision

No. _____

_____ ERROR SUGGESTION FOR CHANGE (check appropriate space) DATE 3-15-01

MANUAL/PUBLICATION TITLE Maintenance Policy and Procedures Manual

CHAPTER/SECTION/PAGE REFERENCE Chapter 4, Page 85 PARAGRAPH 3 (a), (b), (c), (d), (e).

DESCRIPTION OF ERROR OR SUGGESTED CHANGE
Paragraph 3(a)- Change the last sentence to
read. "The completed form will be forwarded to Quality Assurance for review. An audit finding report (MEO57)
will be issued to the fuel vendor for any discrepancies noted .
Paragraph 3 (b)
Change two references to Quality Control to Quality Assurance. First reference is in the first paragraph.
The second reference is in the third paragraph.
Paragraph 3 (c)
Change three references to Quality Control to Quality Assurance. First two references are in the second para.
The third reference is in the third paragraph.
Paragraph 3 (d)
Change the reference to Quality Control to Quality Assurance. First sentence
<i>Also change Retention time of MEO 57 from 30 day to 60 days</i>
Paragraph 3(e) Change ref. Of Quality Control to Quality Assurance.
<i>Also change Retention time from 30 to 45 days 58016</i>

Name Richard Parsons Signature *Richard Parsons*

Station Location KDAY- Quality Assurance Phone ██████████

R. Parsons 58016
 Manager Approval

 Director of Engineering Approval

 Director Maint. Approval

 Director of Quality Control Approval

- Instructions: 1. Attach drawings, sketches, diagrams, etc.
 2. Forward to Director of Engineering.

MRB Approval Required (Check One) YES NO Mgr. Of Reliability _____

EMERY WORLDWIDE AIRLINES MAINTENANCE POLICY & PROCEDURES MANUAL

3. Fueling Equipment Inspection Reports
 - a. EWA Fueling Equipment Inspection Checklist Form MEO57 will be used as a guide for the inspection of fueling equipment and vehicles. The EWA Line Supervisor or his designee performing the inspection shall enter, in the respective blanks, the date of the last filter change, contamination check, and fuel sample. Any discrepancies, remarks, and recommendations are also to be entered on this form. The completed form will be forwarded to ~~Quality Control~~ ^{Assurance} for review to determine if any follow-up action is required.
 - b. EWA Jet Fuel Vendor Checklist (Form MEO64) will be used as a guide by the ~~Quality Control~~ ^{Assurance} Auditor or representative to perform a full audit on the fuel vendors. Any discrepancies, remarks, and recommendations will be documented. A copy of the completed form will be forwarded to ~~the Manager of Quality Control~~ ^{Assurance} for review to determine if any follow-up action is required.
 - c. Frequency of Inspection: The EWA Line Station Supervisor or his designee at each EWA class I or II Line Station will perform a monthly spot check on fueling equipment prior to the 15th of the month. Additionally, a ~~Quality Control~~ ^{Assurance} Auditor or Representative will perform a full audit at each station each twenty-four (24) calendar months or at the discretion of the Director of ~~Quality Control~~ ^{Assurance}. ~~Quality Control~~ ^{Assurance} in Dayton will keep the completed inspection forms on file.
 - d. Form MEO57 that is completed by the EWA Line Station Supervisor or his designee will be forwarded to Quality Control. This form will be retained on file for ~~30~~ ⁹⁰ days and then discarded.
 - e. Form MEO64 that is completed by ~~Quality Control~~ ^{Assurance} Auditors or Representative will be retained on file at ~~Quality Control~~ ^{Assurance} in Dayton until repeated.
4. Fueling Equipment Inspection Checklist Guide Completion Instructions (MEO 57).
 - a. Complete the entire heading of the fueling spot checked.
 - b. Equipment (Circle: Trucks, Carts, Pits, as applicable). Enter identification number of equipment inspected.




FAA #102


2.17.02 The inspections and filter change requirement specified in the RRXA MPPM, Chapter 4 are not accomplished at proper intervals at the Dayton facility.

RRXA RESPONSE: This issue was not discussed in the out briefing or in the Preliminary Rasip Finding report. The Dayton facility does have an extension for filter changes per procedures which were correctly accomplished. (see attached reports)..

RRXA CONCLUSION: No finding



*Jim Owens
Director Quality Assurance
25 June 2001.*



FAA 8/7/01

2.17.03 RRXA maintains the Dayton fuel storage farm by following an uncontrolled EWW Fuel Farm Procedures Manual. This is contrary to the RRXA MPPM and ATA Spec 103.

RRXA RESPONSE: Emery Worldwide Airlines does not maintain the Dayton fuel storage farm. This is controlled by Emery Worldwide Ground Maintenance (the freight company). After an inspection of the Dayton Fuel Farm it has been determined that the manual in use is was controlled. A copy of the control sheet has been provided..

RRXA CONCLUSION: No finding.

*Jim Owens
Director Quality Assurance
25 June 2001*


Review Response

2.17.03 RRXA maintains the Dayton fuel storage farm by following an uncontrolled EWW Fuel Farm Procedures Manual. This is contrary to the RRXA MPPM and ATA Spec 103.

RRXA RESPONSE: *Emery Worldwide Airlines does not maintain the Dayton fuel storage farm. This is controlled by Emery Worldwide Ground Maintenance The EWW Fuel Farm Manual is controlled as evidenced by the attached revision page. This fuel farm is in compliance with ATA Specification 103 and it is audited to the ATA standard.*

As a provider (not that minimum) approved.

RRXA CONCLUSION: No finding.


Jim Owens
Director-Quality Assurance

Approved

EMERY WORLDWIDE AIRLINES FUELING MANUAL

REVISION LISTING

FUELING MANUAL

ISSUE NUMBER

117

Rev.	Date	Signature	Rev.	Date	Signature
1	3/89	Previously Incorp.	18		
2	8/90	Previously Incorp.	19		
3	5/92	Previously Incorp.	20		
4	10/92	Previously Incorp.	21		
5	12/93	Previously Incorp.	22		
6	3/94	Previously Incorp.	23		
7	5/96	Complete Reissue	24		
8	8/97	Previously Incorp.	25		
9	11/98	Previously Incorp.	26		
10	7/00	Complete Reissue	27		
11			28		
12			29		
13			30		
14			31		
15			32		
16			33		
17			34		

May 31, 1996
Revision 7

COPY

Revision List
Page ii

EMERY WORLDWIDE AIRLINES JET FUEL VENDOR CHECKLIST

Vendor: Emery Worldwide Station I.D.: KDAY Date: 8-3-01
 Address: One Emery Plaza Phone: XXXXXXXXXX
 City: Vandalia State: OH Zip: 45377
 Contact: Rick Newland Auditor: LOUIS E GUODE

COMMENT CODES

Y = YES N = NO S = SATISFACTORY C = COMMENT
 NA = NOT APPLICABLE NP = NOT PERFORMED

I. GENERAL

1. Does the vendor have Emery Worldwide Airlines Fueling Manual available, in current status and in good condition? (ATA 103, Introduction Page 1) Fuel Manual #: 117 Rev. #: 10.
2. Does the vendor have a procedure for notifying the airline when new, additional, replacement, or modified equipment is placed into service? (ATA 103, 1-1 Page 1, 1-6 Page 1, 1-9 Page 1)
3. Have any waivers been issued by Emery Worldwide Airlines and are they available for review? (ATA 103, 1-1 Page 1)
4. Does the vendor maintain records of employee training? (ATA 103, 1-1 Page 1)
5. Do personnel performing inspections and tests exhibit appropriate knowledge? (ATA 103, 1-1 Page 1)
6. Does the vendor have a procedure for handling fuel removed for suspected contamination? (ATA 103, 1-1 Page 1)
7. Is de-fueled product for purposes other than contamination returned to the same airline? (ATA 103, 1-1 Page 2)
8. If vendor de-fuels into a hydrant system, is it in accordance with ATA 103 requirements? (ATA 103, 1-1 Page 2)
9. Does vendor have all the necessary equipment available to perform the required inspections, tests and checks? (ATA 103, Applicable Sections)

COPY

**EMERY WORLDWIDE AIRLINES
JET FUEL VENDOR CHECKLIST**

10. Are all checks/tests and findings recorded on ATA 103 forms 103.01 through 103.09 or equivalent? (ATA 103 1-1 Page 1)

y

II. FUEL ACCEPTANCE BY DEDICATED PIPELINE

1. Prior to receipt, is receiving tank designated and gauged? (ATA 103, 1-3 Page 1)
2. Prior to receipt, is the receiving tank sumped? (ATA 103, 1-3 Page 1)
3. Are pipeline company personnel contacted to verify correct destination, grade and volume of fuel? (ATA 103, 1-3 Page 1)
4. During receipt, are all tests performed and recorded as required? (ATA 103, 1-3 Page 1)
5. Are recommended settling times observed before gauging and recording tank volume? (ATA 103, 1-3 Page 1)
6. Is recommended settling time observed before dispensing fuel from the receiving tank? (ATA 103, 1-3 Page 1)

N/A

N/A

N/A

N/A

N/A

N/A

III. FUEL ACCEPTANCE BY TRANSPORT TRUCK

1. Prior to receipt, is receiving tank designated and gauged? (ATA 103, 1-4 Page 1)
2. Prior to receipt, is the receiving tank sumped? (ATA 103, 1-4 Page 1)
3. Is the Bill of Lading checked for proper grade of fuel, correct destination and quantity? (ATA 103, 1-4 Page 1)
4. Is the delivery truck and fuel system bonded/grounded prior to off-loading? (ATA 103, 1-4 Page 1)
5. During receipt, are all tests performed and recorded as required? (ATA 103, 1-4 Page 2)
6. If transport truck hose is used, is it inspected prior to off-loading? (ATA 103, 1-4 Page 2)

N

N

X

y

y

N

**EMERY WORLDWIDE AIRLINES
JET FUEL VENDOR CHECKLIST**

- 7. Are recommended settling times observed before gauging and recording tank volume? (ATA 103, 1-4 Page 2)
- 8. Is recommended settling times observed before dispensing fuel from the receiving tank? (ATA 103, 1-4 Page 2)

IV. FUEL STORAGE FACILITY REQUIREMENT

- 1. Is storage facility properly identified and color coded in accordance with API 1542? (ATA 103 1-5 Page 2; API 1542)
- 2. Are filter/separators equipped with all required equipment? (ATA 103, 1-5 Page 1)
- 3. Do filter vessel/element combinations meet current API 1581 Specifications? (ATA 103, 1-5 Page 1)
- 4. Is the filter change date marked on the vessel? (ATA 103, 1-5 Page 1)
- 5. Is fuel filtered into storage? (ATA 103, 1-5 Page 1)
- 6. Is fuel filtered when dispensed from storage? (ATA 103, 1-5 Page 1)
- 7. Is there a segregated system to prevent accidental mixing of products? (ATA 103 1-5 Page 2)
- 8. Are fuel emergency shutoff valves and switches clearly marked and kept free of obstructions? (ATA 103, 1-5 Page 2)
- 9. Does facility have a deadman control for loading refuelers? (ATA 103, 1-5 Page 2)
- 10. Are bottom loading nozzle screens 60 mesh or finer? (ATA 103, 1-5 Page 2)
- 11. Do refueler loading hoses meet API 1529 NFPA 407 standards? (ATA 103, 1-5 Page 2)

V. FUEL FACILITY CHECKS

- 1. Is general condition of tank yard satisfactory? (ATA 103, 1-6 Page 1)

COPY

EMERY WORLDWIDE AIRLINES JET FUEL VENDOR CHECKLIST

- | | | |
|--|--|---------|
| 2. Are there any security, fire and safety deficiencies? (ATA 103, 1-6 Page 1) | <input style="width: 100px; height: 20px;" type="text" value="N"/> | |
| 3. Any fuel leaks noted? (ATA 103, 1-6 Page 1) | <input style="width: 100px; height: 20px;" type="text" value="N/A"/> | |
| 4. Storage tank sumps - perform White Bucket Test of tank sumps. (ATA 103, 1-6 Page 1) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 5. Filter vessel sumps - perform White Bucket Test on filter vessel sumps. (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 6. Filter differential pressure, under normal flow conditions. (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="4.0"/> | #8 Filt |
| 7. Is condition of hoses, swivels and nozzles satisfactory? (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 8. Is condition of grounding reels, cables and clamps satisfactory? (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 9. Is ground cable continuity check performed monthly? (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 10. Is location/accessibility and serviceability of fire extinguishers satisfactory? (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 11. Are waste fuel tanks gauged and drained as required to prevent overflow and spillage? (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 12. Check downstream color membrane of filter/separators vessels. (Verified by documented records.) (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 13. Check downstream free water test of filter/separator vessels. (Verified by documented records.) (ATA 103, 1-6 Page 2) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 14. Is all fueling equipment properly identified and has required placards, instructions, signs, etc., in place. (ATA 103, 1-6 Page 2; API 1542) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 15. Is floating suction satisfactory? (ATA 103, 1-6 Page 3) | <input style="width: 100px; height: 20px;" type="text" value="S"/> | |
| 16. Is fuel meter seal intact? (ATA 103, 1-6 Page 3) | <input style="width: 100px; height: 20px;" type="text" value="N/A"/> | |

COPY

EMERY WORLDWIDE AIRLINES JET FUEL VENDOR CHECKLIST

17. Are line strainers installed? (Verified by documented records.) (ATA 103, 1-6 Page 3)

Y

18. Perform operational check of emergency shutdown system. (Verified by documented records) (ATA 103, 1-6 Page 3)

? Y

19. Is water defense system checked annually? (ATA 103, 1-6 Page 3)

Y

VI. FUELING VEHICLE CHECKS

Veh.#	Veh.#	Veh.#	Veh.#
14			

868-0024

1. Check vehicle general condition? (ATA 103, 1-9 Page 1)

5			
---	--	--	--

2. Check condition of grounding reels, cables and clamps. (ATA 103, 1-9 Page 2)

C			
---	--	--	--

3. Check for location/accessibility and condition of fire extinguishers. (ATA 103, 1-9 Page 2)

5			
---	--	--	--

4. Bleed air tanks. (ATA 103, 1-9 Page 2)

5			
---	--	--	--

5. Check that filter/separator vessel is equipped with all required equipment. If full flow fuel monitor, check that spare elements are available. (ATA 103, 1-8 Page 1)

5			
---	--	--	--

6. Check that filter/vessel combination meets current API 1581 Specifications. (ATA 103, 1-8 Page 1)

5			
---	--	--	--

7. Record filter change dates from filter vessel. (ATA 103, 1-8 Page 1)

5-2-00			
--------	--	--	--

8. Check vehicle signs and placards. (ATA 103, 1-8 Page 2)

5			
---	--	--	--

COPY

EMERY WORLDWIDE AIRLINES JET FUEL VENDOR CHECKLIST

- | | |
|--|---------|
| 9. Record meter calibration date and check for seal condition. (ATA 103, 1-9 Page 3) | 1-22-01 |
| 10. Check condition and operation of lift platform. (ATA 103, 1-9 Page 3) | N/P |
| 11. Check refueler tank trough. (ATA 103, 1-9 Page 2) | 5 |
| 12. Check refueler tank interior. (ATA 103, 1-9 Page 4) | 5 |
| 13. Check condition of tank, vents, cover latches, seals and gaskets. (ATA 103, 1-9 Page 4) | 5 |
| 14. Check condition of nozzle screens. (Verified by documented records) (ATA 103, 1-9 Page 3) | 5 |
| 15. Perform White Bucket Test of each tank compartment. (ATA 103, 1-9 Page 3) | 5 |
| 16. Check condition of hoses, swivels and nozzles. (ATA 103, 1-9 Page 3) | 5 |
| 17. Perform operational test of deadman | N/P |
| 18. Check primary fueling pressure. (ATA 103, 1-9 Page 2) | 4.5 |
| 19. Check that filter differential pressure is within limits under normal flow conditions. (ATA 103, 1-9 Page 1) | N/P |
| 20. Perform White Bucket Test of filter sump. (ATA 103, 1-9 Page 1) | 5 |
| 21. Drain surge tanks. (Hydrant Trucks) (ATA 103, 1-9 Page 2) | N/P |
| 22. Perform check of secondary pressure controller. (ATA 103, 1-9 Page 4) | N/P |

COPY

**EMERY WORLDWIDE AIRLINES
JET FUEL VENDOR CHECKLIST**

- 23. Check operation of emergency shutdown system. (ATA 103, 1-9 Page 3) N/P
- 24. Perform downstream color membrane test of filter/separator vessel. (Verified by documented records.) (ATA 103, 1-9 Page 3) 5
- 25. Perform downstream free water test of filter/separator vessel. (Verified by documented records.) (ATA 103, 1-9 Page 3) 5
- 26. Check operation of brake safety interlock system. (ATA 103, 1-9 Page 2) 5
- 27. Check operation of bottom loading system. (ATA 103, 1-9 Page 3) N/P
- 28. Is monthly fuel hose check performed? (ATA 103, 1-9 Page 3) 5

VII. HYDRANT SYSTEM CHECK

- 1. Check hydrant valve pits for leaks, cleanliness and component condition. (ATA 103, 1-7 Page 1) N/A
- 2. Check isolation valve pits. (ATA 103, 1-7 Page 2) N/A
- 3. Where installed, check surge absorbers for general condition and operating pressure setting. (ATA 103, 1-7 Page 2) N/A
- 4. Check that emergency fuel shutdown stations have clear access, proper identification and locator lights, if installed. (ATA 103, 1-7 Page 1) N/A
- 5. Perform an emergency shutdown system test. (Verified by documented records) (ATA 103, 1-7 Page 2) N/A
- 6. Check low point drains. (ATA 103, 1-7 Page 2) N/A

COPY

EMERY WORLDWIDE AIRLINES JET FUEL VENDOR CHECKLIST

VIII. AIRCRAFT FUELING

1. Are all safety procedures properly followed - position of vehicle, grounding, deadman operation etc.?
2. Does fueler monitor differential pressure, fuel nozzle pressure?
3. Does fueler accomplish fueling in accordance with airline's procedures?

 y y y

IX. RECORDS

1. Verify that records are:
 - a. Current
 - b. Complete
 - c. Meet the task and frequency requirements of ATA 103.
 - d. Do records reflect conditions observed during the audit?

 y c y y

X. JET VENDOR INSPECTION COMMENTS

AUDIT FINDING REPORT

Date 8-6-01 Auditor LOUIS E GUDRE Ph [REDACTED]
 Vendor/Station EWV / HDY Contact J.R. EATON
 Address One Emery Plaza Ph [REDACTED]
 City, State Vandalia, OH FAX [REDACTED]

Internal
 Use
 Only

Finding THE FORMS FOR THE AIRCRAFT FUELING EQUIPMENT DAILY CHECKS ARE NOT BEING FILLED OUT CORRECTLY (no date, no TRUCK number, and NOT used entered)
ATA 103 128 B
 Corrective Action _____

 Action Taken to Prevent Reoccurrence _____

Accept

Reject

Finding THE EMERY CORP. TRUCK NUMBER IS NOT BEING ENTERED ON THE DAILY INSPECTION FORMS
 Corrective Action _____

 Action Taken to Prevent Reoccurrence _____

Accept

Reject

Note: All corrective actions must be root cause (prevent reoccurrence) corrective actions. Attach any supporting documentation to this form.

Please return white copy plus any attachments within 15 days to:
 Emery Worldwide Airlines, Quality Control, One Emery Plaza, Vandalia, OH 45377

COPY

AUDIT FINDING REPORT

Date 8-6-01 Auditor LOUIS E. GUODE Ph [REDACTED]
 Vendor/Station EWU 1 HDY Contact J.R. Eaton
 Address _____ Ph [REDACTED]
 City, State _____ FAX [REDACTED]

Internal
 Use
 Only

Finding THE Fuel Tanks are NOT Being gauged & sampled Everytime Product is delivered.

ATA 103 1-3 Item C.1.

Corrective Action _____

Action Taken to Prevent Reoccurrence _____

Accept

Reject

Finding PRIOR TO Testing & unloading OF TRANSPORT TRUCKS THE 10 minute settling Time is NOT Being observed

ATA 103 1-3 Item C.5

Corrective Action _____

Action Taken to Prevent Reoccurrence _____

Accept

Reject

*e: All corrective actions must be root cause (prevent reoccurrence) corrective actions. Attach any supporting documentation to this form.

Please return white copy plus any attachments within 15 days to:
 Emery Worldwide Airlines, Quality Control, One Emery Plaza, Vandalia, OH 45377

COPY

AUDIT FINDING REPORT

Date 8-6-01 Auditor LOUIS E GUDDÉ Ph [REDACTED]
 Vendor/Station EWV / HDY Contact J.R. EATON
 Address _____ Ph _____
 City, State _____ FAX _____

Internal
 Use
 Only

Finding THE Grounding cables on TRK 868-0024
ARE Frayed, Corroded and The Clamps are
Smashed

 Corrective Action _____

 Action Taken to Prevent Reoccurrence _____

Accept

Reject

Finding _____

 Corrective Action End

 Action Taken to Prevent Reoccurrence _____

Accept

Reject

Note: All corrective actions must be root cause (prevent reoccurrence) corrective actions. Attach any supporting documentation to this form.

Please return white copy plus any attachments within 15 days to:
 Emery Worldwide Airlines, Quality Control, One Emery Plaza, Vandalia, OH 45377

COPY

Checked

FINDING: 2.18.01 Mechanic performed DC-10 maintenance and signed the logbook without being trained on that aircraft.

RRXA RESPONSE: *The maintenance performed required no specialized knowledge of DC-10 systems. One log book entry was for deferral of a belly net and the other was for applying tape to a belly door sill.*

Lead Mechanic Ishaq has had DC-8 RII authority since 8/94 and received DC-10 training in 11/00.

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

11/27/00

EMERY WORLDWIDE AIRLINES AUTHORIZED MAINTENANCE PERSONNEL LISTING

LAST NAME FIRST NAME ICAO STAT POSITION STP CERT NO RA REC EMP INSP 1 2 3 4 5 6 AWR RI JT3 R1 T1 D1 B1 56 CFM R2 T2 D2 B2 AWR RI DC-10 CF6 R3 T3 D3 B3 Other

LAST NAME	FIRST NAME	ICAO	STAT	POSITION	STP	CERT NO	RA	REC	EMP	INSP	1	2	3	4	5	6	AWR	RI	JT3	R1	T1	D1	B1	56	CFM	R2	T2	D2	B2	AWR	RI	DC-10	CF6	R3	T3	D3	B3	Other		
HOSIC	MIRSAD	KBOS	K	MECH				AP	41198	X	X	X					02/99		06/01	X	X			06/01	X	X														
HUBBARTT	DONALD	ZZZZ	F	PFE				AP	37845		X	X						04/92																						
HUFF	DAVID	KFLL	P	MECH				AP	37968	X	X	X						10/99																						
HUGHES	JOSEPH	KDAY	F	R&E MECH				AP	50837		X																													
IACULLO	PASQUALE	KDAY	F	MX MGR				AP	38955	X	X	X	X	X			05/00	05/00	09/02	X	X	X			09/02	X	X	X	X											
ISHAQ	SHAIKH	KENR	F	LEAD MECH				AP	39180	X	X	X	X	X	X		08/94	08/94						04/02	X	X											11/00			
JACKSON	DAVID	KDAY	F	MECH				AP	39529	X	X	X	X	X	X		02/99	08/00L	07/01	X	X			07/01	X	X														
JACKSON	DEANTHONY	KATL	F	MECH				AP	01953	X	X	X					11/00																							
JACOBS	SAMUAL	ZZZZ	F	PFE				AP	39623		X	X					04/92																							
JEBENS	DENNIS	KDAY	F	QA REP	QC 07			AP	40076	X	X	X	X	X	X		11/91	11/91																		02/99	02/99			
JECKERING	ROBERT	KDAY	F	MECH				AP	40078	X	X	X	X	X	X		09/00		09/02	X	X			09/02	X	X														
JENKINS	TERRY	KPDJ	K	MECH				AP	40250		X	X																												
JENNINGS	WILLIAM	KBOS	F	MX SUPR				AP	62237	X	X	X					08/00		09/02	X				10/02	X															
JMORSON	WAYNE	KORD	F	MECH				AP	48557		X																													
JOHNSON	JOE	ZZZZ	F	PFE				AP	41374		X	X					04/92																							
JONES	GREGORY	ZZZZ	F	PFE				AP	41998		X	X					11/94																							
JONES	HAL	KSLC	F	MECH				AP	59553	X	X	X					03/00																							
JONES, JR.	EDWARD	KDAY	F	DIR QC	QC 06			AP	42248	X	X	X	X				05/91	05/91																						
JULIAN	BRIAN	KPIA	F	MX SUPR				AP			X	X																												
KALICK	JERRY	KSAN	F	MX MGR				AP	42525	X	X	X	X	X			03/94	03/94	11/01	X	X	X		11/01	X	X	X													
KEENAN	ANDREW	KBDL	C	MECH				AP	N/A	X	X	X					09/96	01/00																						
KILPATRICK	WILLIAM	ZZZZ	F	PFE				AP	43989		X	X					05/92																							
KINDER	JERRY	KDAY	F	MECH				AP	44148	X	X	X	X	X	X		11/97		07/01	X	X			07/01	X	X										02/99				
KING	JAMES	KDAY	F	HVY MX				AP	44155	X	X	X	X				11/96		10/01	X	X			10/01	X	X														
KINNEY	THEODORE	KDAY	F	MX SUPR				AP	44127	X	X	X	X	X			02/92	02/92	11/01	X	X			11/01	X	X														
KIRK	CHRISTOPHER	KDAY	F	MECH				AP	58727		X	X																												
KIRKPATRICK	THOMAS	ZZZZ	F	PFE				AP	44266		X	X					04/92																							
KLEINSTUBER	GEORGE	ZZZZ	F	PFE				AP	44420		X	X					02/94																							
KLIX	KRISTOPHER	KAUS	F	MECH				AP	18392		X	X	X																											
KONOZSI	OTTO	KORD	F	MECH				AP	45060	X	X	X		X			03/96		10/02	X				10/02	X															

COURSE HISTORY

1= BASIC INDOC
2= DC-8 SYSTEMS
3= JT3 POWERPLANT
4= CFM56 POWERPLANT
5= DC-10 SYSTEMS
6= CF6 POWERPLANT

NOTES

R11 AND AWR DATES ARE ISSUE DATES
ENGINE QUALIFICATION DATES ARE EXPIRATION DATES

ENGINE QUALIFICATION KEY

R1= JT3 ENGINE RUN ONLY
R2= CFM ENGINE RUN ONLY
R3= CF6 ENGINE RUN ONLY
T1= JT3 TAXI
T2= CFM TAXI
T3= CF6 TAXI
D1= RUN/TAXI DESIGNEE
D2= RUN/TAXI DESIGNEE
D3= RUN/TAXI DESIGNEE
B1= BORESCOPE
B2= BORESCOPE
B3= BORESCOPE

(P)werplant (P)at Time (P)ul Time (C)ontract (K)asual (L)imited R11 Authority (A)irframe (AP) Airframe and Powerplant (RP) Repairman

FINDING: 2.18.01 Mechanic performed DC-10 maintenance and signed the logbook without being trained on that aircraft.

RRXA RESPONSE: *Since the mechanic is not named and no flight number, aircraft number, or date is supplied EWA is unable to respond to this alleged finding.*

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

Per attached Training Record EWR Mechanic Shaikh Ishag had not received

Copy To Jack Smith

2009 23

AIRCRAFT MAINTENANCE LOG

AIR-0082 (10/97) LHM U.S.A.



7639-16

ACFT. NO. N 68042 ACFT. TYPE DC-10-10F

FLY	FLT.	DATE	STATION		GMT	IN	BLOCK HOURS	GMT		FLT. HOURS	FUEL DATA			DEP. GAL'S	CARGO DATA	
			FROM	TO				OFF	ON		UNLIT (LBS)	DEPART (LBS)	ARRIVAL (LBS)		CARGO	MAIL
1	341	10-17-00	KSEWR	KJAY							3524					
2																
3																
4																

No FLIGHT

17 1000

DEPT. DELAY	TRASH PETS	OIL ADD	AIR	CREW	EMP	TO	LOD	A/B	CREW	EMP
			0/1							
			0/2							
			0/3							

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	RECH
1.	P/M	ON CHECK FOUND MIAH CARGO DOOR SEEL GARD TURN 7" AFT CONER	1.	REPAIRED WITH CARGO PIT TAP 11 PER DEID MM 20-10-00	10-12-00	SEWR	39180
2.	P/M	AFTER LODED AFT PIT, FOUND NET MISSING	2.	TRANSMIT TO DMI NO-7639162-10-17-00 Kewk 39180 8009 IAW MEL 25-30 DUE DATE 10-27-00 PLACED INSIDE			
3.	P/M		3.				
4.	P/M		4.				
5.	P/M		5.				
6.	P/M		6.				

NO.	PART NOMENCLATURE	PART NO.	SER. NO.	PART NO. ON	SER. NO. ON	POS.

CHECK C/W: N/R	STATION:	3011	0	31011	1-DIST.	2-DIST.	3-DIST.
DATE:	CERT. NO.:	8818657	0	8818657			
GMT TIME:	AUTH SIG.:						

DISC. ON MAINT ACTION CARRIED FWD TO: BOOK CHANGED NEW LOG PAGE NO: CAPTAIN'S SIGNATURE

LAST NAME	FIRST NAME	ICAO	STAT	POSITION	STP	CERT NO	RAT	EMP	INSP	1	2	3	4	5	6	AWR	R11	JT3	R1	T1	D1	B1	56	R2	T2	D2	B2	AWR	R11	C	
HARRISON	BOBBY	KATL	F	MECH			AP	56520	X	X	X					03/00															
HART	WARREN	KATL	F	LEAD MECH			AP	32454	X	X	X	X		X		01/94	11/95	08/02	X	X				08/02	X	X		X	07/00	08/00	01
HART, II.	KENNETH	KPHL	F	MX SUPR			AP	13382		X	X																				
HARTLEY	ROBERT	KDAY	F	LEAD MECH			AP	32465	X	X	X	X	X	X	X	10/97	04/00	02/02	X	X				02/02	X	X			02/99	02/99	01
HATTON	BILL	KDAY	F	MECH			AP	37179	X	X	X					08/00															
HAVENHILL	DOUGLAS	KDEN	F	MX SUPR			AP	32981	X	X	X	X	X			06/94	10/96	12/01	X	X	X			12/01	X	X	X				
HEATH	CHARLES	KDAY	F	MGR PDPL			AP	62259																							
HECKROTH	FREDERICK	ZZZZ	F	PFE			AP	33666		X	X					06/92															
HENDRICKSON	DALE	ZZZZ	F	PFE			AP	34354	X	X	X					04/98															
HENDRICKSON	MICHAEL	KAUS	P	MECH			AP	26139		X																					
HENDRICKSON	SVEN	KAUS	F	MECH			AP	05676		X	X	X																			
HESS	CORY	KPDX	K	MECH			AP	68298																							
HICKMAN	JOHN	ZZZZ	F	PFE			AP	35118		X	X					10/97															
HILL	MARTY	ZZZZ	F	PFE			AP	35488		X	X					04/92															
HCFMAN	DAVID	KRNO	F	MECH			AP	37177		X																					
HCLDER	DARRYL	KOAK	F	MECH			AP	36305	X	X	X					05/94		01/02	X	X				02/02	X	X					
HCLDER, JR.	ROBERT	KMCO	F	MECH			AP	36308	X	X	X					07/94		11/01	X	X				11/01	X	X					
HCOGLAND	ROBERT	ZZZZ	F	PFE			AP	36892		X	X					04/92															
HCSIC	MIRSAD	KBOS	K	MECH			AP	41198	X	X	X					02/99		06/01	X	X				06/01	X	X					
HUBBARTT	DONALD	ZZZZ	F	PFE			AP	37845		X	X					04/92															
HUFF	DAVID	KFLL	P	MECH			AP	37968	X	X	X					10/99															
HUGHES	JOSEPH	KDAY	F	R&E MECH			AP	50837		X																					
IACULLO	PASQUALE	KDAY	F	MX MGR			AP	38955	X	X	X	X	X			05/00	05/00	09/02	X	X	X			09/02	X	X	X	X			
ISHAQ	SHAIKH	KEWR	F	LEAD MECH			AP	39180	X	X	X	X	X			08/94	08/94							04/02	X	X					
JACKSON	DAVID	KDAY	F	MECH			AP	39529	X	X	X	X	X			02/99	09/00L	07/01	X	X				07/01	X	X					
JACOBS	SAMUAL	ZZZZ	F	PFE			AP	39623		X	X					04/92															
JEBENS	DENNIS	KDAY	F	QA REP	QC 07		AP	40076	X	X	X	X	X			11/91	11/91											02/99	02/99		
JECKERING	ROBERT	KDAY	F	MECH			AP	40078	X	X	X	X				09/00		09/02	X	X				09/02	X	X					
JENKINS	TERRY	KPDX	K	MECH			AP	40250		X	X																				
JENNINGS	WILLIAM	KBOS	F	MX SUPR			AP	62237	X	X	X					08/00		09/02	X					10/02	X						

COURSE HISTORY

NOTES

ENGINE QUALIFICATION KEY

1= BASIC INDOC 4=CFM56 POWERPLANT R11 AND AWR DATES ARE ISSUE DATES R1= JT3 ENGINE RUN ONLY T1= JT3 TAXI D1= RUN/TAXI DE.
 2= DC-8 SYSTEMS 5= DC-10 SYSTEMS ENGINE QUALIFICATION DATES ARE EXPIRATION DATES R2= CFM ENGINE RUN ONLY T2= CFM TAXI D2= RUN/TAXI DE.
 3= JT3 POWERPLANT 6= CF6 POWERPLANT R3= CF6 ENGINE RUN ONLY T3= CF6 TAXI D3= RUN/TAXI DE.

(P)owerplant (P)art Time (F)ull Time (C)ontract (K)asual (L)imited R11 Authority (A)irframe (AP) Airframe and Powerplant (R)

FINDING: 2.18.01 Mechanic performed DC-10 maintenance and signed the logbook without being trained on that aircraft.

RRXA RESPONSE: *Since the mechanic is not named and no flight number, aircraft number, or date is supplied EWA is unable to respond to this alleged finding.*

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

Check OUT Per Attached. —

Denny
AP

NASIP/RASIP
WORK SHEET
FOR
FINDINGS

The following work sheet has been developed so NASIP/RASIP team members may list their Findings categorically.

It is important to remember that the Findings should have specific document references, i.e., the source that validates and supports the Finding.

Findings are numbered sequentially in relation to the Inspection Area. An example would be a Finding in Inspection Area 2.2 Certificate & Operations Specifications. The first Finding would be 2.2.1, the second 2.2.2, etc.

An Inspector's Statement is often required to adequately describe how the Finding was discovered.

FINDING: 2.18.01 MECHANIC "~~SHAIKH ISHAQ~~"

PERFORMED MTC WITHOUT BEING TRAINED ON THE DC-10 AIRCRAFT

Description of items of proof for this Finding.

MPPM Chap 5 (D)(1) FAR 121.367(B)
Log Sheet 7639-16
Course history Sheet

RECOMMENDATION FOR CATEGORIZING THE FINDING:

- Category A: Non-compliance with FAR
- Category B: Contrary to guidance developed by the Certificate Holder and approved or accepted by the FAA.

EMERY WORLDWIDE AIRLINES MAINTENANCE POLICY & PROCEDURES MANUAL

D. Types of Training

The need for training/qualification generally originates from four sources:

- Hiring new personnel.
- Acquiring new and/or changing existing equipment.
- Implementing new procedures or inspection techniques.
- Returning to or requalifying in a job.

To satisfy the needs for training various types of training are used. Types of training used by EWA include, but are not limited to:

- Indoctrination Training
- Initial Training
- Recurrent Training
- Special Training
- On-the-Job Training
- Quality Control OJT
- Field Training

These types of training consist of varied subject matter, covering a multitude of topics and may be presented in a formal and/or on-the-job training format.

1. Indoctrination Training

This training is designed primarily for new employees. Indoctrination training content may vary depending on the individual's position, but in all cases will cover policies and procedures as stated in the EWA Maintenance Policy and Procedure Manual. It will be performed for all new hired mechanics at the next scheduled class, or as scheduled by his/her immediate supervisor. All new hired mechanics will work under the direct supervision of his/her supervisor until this class has been taken. At a minimum, Indoctrination Training will consist of four hours of instruction covering the following material.

- Maintenance Policy & Procedures Manual
- Logbook Familiarization
- Forms and Tags Introduction
- RII Procedures Familiarization
- Airworthiness Release Duties

2. Initial Training

Initial training shall consist primarily of systems introduction on the type of aircraft operated by EWA. Requirements for this training are based on an employee's prior experience on the type of aircraft operated by EWA. This experience must be verifiable in the form of previous training records and/or certificates. Employees with prior experience may only require

17 FUELING AND SERVICING

DESCRIPTION: RRXA accomplishes aircraft fueling and aircraft de-icing/anti-icing by utilizing the procedures contained in the RRXA Fueling Manual and De-icing/Anti-icing Manual.

INSPECTION DATA:

FINDING:

CHDO ACTION:

2.18 AIRCRAFT RAMP INSPECTION

DESCRIPTION: Emery Worldwide Airlines operates 36 aircraft. Aircraft ramp inspections were performed on the following aircraft: DC-10-10F, DC-10-30F and DC-8-73F.

INSPECTION DATA:

FINDING: 2.18.01: Mechanic performed DC-10 maintenance without being trained on that aircraft.

*Corrected 10/24
mk*

*Not in accordance with MPM Chap 2-7
This is contrary to MPM Chptr 3 pg 52 para C*

*copy given to
George
Ballard
10/24*

2.18.02: During ramp inspections, it was found that RRXA was carrying aerosol deodorizer in the lavatories on several aircraft. The aircraft also had 32 oz. containers of an alcohol based hand sanitizer. The aerosol cans were removed from the aircraft. This finding was turned over to FAA Security/Hazardous Materials.

2.18.03: Several DC-8-70 aircraft were inspected; found numerous engine cowling - external markings missing. This is contrary to 14CFR 15.1557 and 121.153.

2.18.04: On 10/22/00, ULD #AAA3962EB and AAA3444EB arrived for loading on Flt. N9966E. The TSO tags did not have the required info: part #, s/n, date of manufacturing. This is contrary to 14CFR 21.607(d). Pallet PIP 7447EB arrived to be loaded on N9966E. It had improperly secured corners of the net, poor routing of the lashing line. Pallet #PAJ 7930CO arrived with a net that had damage beyond allowable limits. One broken rope and several ropes were frayed beyond limits. All of the above were removed from service.

DO ACTION:

EMERY WORLDWIDE AIRLINES MAINTENANCE POLICY & PROCEDURES MANUAL

B. Aircraft Airworthiness Release for Pilot/Maintenance Discrepancy Write-Ups

Aircraft being released following the correction of a pilot/maintenance discrepancy write-ups will be returned to an airworthiness status by virtue of the FAA Certificated Mechanic certifying the corrective action for each item. The mechanic signing off each item is responsible only for the proper completion and airworthiness of that item. The corrective action sign-off revalidates the airworthiness as certified by the previous aircraft airworthy signature in the Aircraft Maintenance Log.

1. If the **ONLY** maintenance being performed is the action taken to clear a pilot/maintenance discrepancy write-ups, and that item does not require an RII buy-off, the Airworthiness Release is not required to be signed. The corrective action of the certificated mechanic performing the work constitutes the declaration of airworthiness.
2. If the pilot/maintenance discrepancy write-ups requires an RII buy-off, the Airworthiness Release is required to be signed by an authorized individual.

Note: See Chapter 3, Aircraft Maintenance log section VII, for approved sign-off procedures.

C. Authorized Personnel Qualifications

Aircraft Airworthiness certification shall be signed only by persons who are trained and authorized, in writing, by the Director of Quality Control or his designee and who possess the following qualifications.

1. Hold an FAA Airframe and Power Plant Certificate, or a FAA Repairman Certificate. In the case of an individual holding a Repairman Certificate, his limitations for signing the Airworthiness Release will be within the same realm as their authorization as a Repairman.
2. Possess knowledge of EMERY WORLDWIDE AIRLINES inspection concepts, principles; and have a knowledge of the FARs.

D. Airworthiness Release Procedures

1. By Maintenance Personnel

Maintenance personnel, designated and authorized under the provisions of this Chapter and Section, will certify an aircraft airworthy by completing the following procedures on the log page that contains the record of the maintenance performed (the inbound log page(s) when:



2.18.2 During ramp inspections, it was found that RRXA was carrying aerosol deodorizer in the lavatories on several aircraft. The aircraft also had 32 oz. containers of an alcohol based hand sanitizer. This is contrary to 14CFR 49 part 175. The aerosol cans and hand sanitizer were removed from the aircraft. This finding was referred to FAA Security/Hazardous Materials.

RRXA RESPONSE: As mentioned in the finding the aerosol cans of hand sanitizer were removed from the aircraft identified during the RASIP. A fleet inspection was also performed to make sure that aircraft not identified did not have the aerosol cans on-board.

RRXA CONCLUSION: Finding valid.

*Jim Owens
Director Quality Assurance.*

Wood, Thomas M

From: Wood, Thomas M
Sent: Monday, November 06, 2000 3:26 PM
To: Massie, Mike A
Subject: RASIP Finding, Suspect Hazmat

Mike: The RASIP team wrote this item up. Lavatory soap and deodorant aerosol cans installed in the aircraft lavs suspected Hazmat material (FAR Part 49). Please respond to me on this finding, thank you.

Thomas M. Wood
Senior Director Quality Control
Emery Worldwide Airlines




2.18.03 Several DC-8-70 aircraft were inspected and it was noted that the "oil" placard required by 14CFR 25.1557(b)(2) was missing. The aircraft were also operated contrary to 14CFR 121.153(a)(2).

RRXA RESPONSE: A fleet campaign has been conducted and missing "oil" placards are being replaced as required. EWA Has stressed the importance of inspecting aircraft for these required placards so that they will be replaced whenever necessary.


RRXA CONCLUSION: Finding valid.

*Jim Owens
Director Quality Assurance*



U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

cc: Jim Owens
Jerry Sumner
Bud Hall

January 24, 2001

2,18,03

FILE NUMBER: 2001GL050038

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

Several DC-8-70 aircraft were inspected and it was noted that the "oil" placard required by 14 CFR 25.1557(b)(2) was missing.

Operations of this type are contrary to the Federal Aviation Regulations.


This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

for

Harold R. Camden
Principal Maintenance Inspector



B y

2.18.04 On 10/22/00, ULD #AAA3962EB and AAA3444EB arrived for loading on aircraft N996GE. The TSO tags did not have the required info: part #, s/n, date of manufacturing. This is contrary to 14CFR 21.607(d). Pallet #PIP 7447EB arrived to be loaded on N996GE. The lashing line was improperly routed and secured. Pallet #PAJ 7930CO had net damage beyond allowable limits. All of the above were removed from service.

RRXA RESPONSE:

All of the above discrepancies were noted prior to the loading process being started. However, all of the observations were correct and they were corrected immediately. Emery Worldwide responded immediately to the missing TSO tag issue and worked around the clock for several days to identify pallets with the missing information. It appears that the problem encountered was due to the pallet manufacturer using an inking process for TSO information rather than engraving the information.

We have procedures in place to inspect ULD's for airworthiness prior to loading them on an aircraft and I am confident that the cargo nets would have been identified during this process. I am equally confident that the missing TSO information would not have been identified.

RRXA CONCLUSION: *The finding is valid.*

Close 3/13/01

21.607 General rules governing holders of TSO authorizations.

Each manufacturer of an article for which a TSO authorization has been issued under this part shall -

- (a) Manufacture the article in accordance with this part and the applicable TSO;
- (b) Conduct all required tests and inspections and establish and maintain a quality control system adequate to ensure that the article meets the requirements of paragraph (a) of this section and is in condition for safe operation;
- (c) Prepare and maintain, for each model of each article for which a TSO authorization has been issued, a current file of complete technical data and records in accordance with § 21.613; and
- (d) Permanently and legibly mark each article to which this section applies with the following information:
 - (1) The name and address of the manufacturer.
 - (2) The name, type, part number, or model designation of the article.
 - (3) The serial number or the date of manufacture of the article or both.
 - (4) The applicable TSO number.

2, 18, 04



B Y

FINDING 2.18.05

On 10/31/00 Flt. 542 arrived at Memphis. During the off load the forward belly cargo door would not open. The door net had not been secured. When the ground crew attempted to open the door the net jammed the cargo door. RRXA Aircraft Loading Manual requires the nets to be secured.


RRXA RESPONSE:

FAA Inspector George Ballard did call from Memphis concerning the door net. He was not certain if the net had not been secured in Dayton or if it had worked loose. Emery Worldwide took the position that if the net had be properly secured that it would not have come loose.

The person responsible for securing this net was counseled and given a Major infraction.

RRXA CONCLUSION: The finding was valid.


closed 3/13/01





U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

cc: Jim Owens
Gerry Truiano
Bob Dell

January 24, 2001

2,18,06

FILE NUMBER: 2001GL050039

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

A ramp inspection of aircraft DC-8, N606AL revealed the use of Teflon tape for the repair of the oxygen system with no reference to repair data. The use of Teflon tape is not listed as an approved repair in the manufacturer's maintenance manual.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

§ 43.13 Performance rules (general).

(a) Each person performing maintenance, alteration, or preventive maintenance on an aircraft, engine, propeller, or appliance shall use the methods, techniques, and practices prescribed in the current manufacturer's maintenance manual or Instructions for Continued Airworthiness prepared by its manufacturer, or other methods, techniques, and practices acceptable to the Administrator, except as noted in § 43.16. He shall use the tools, equipment, and test apparatus necessary to assure completion of the work in accordance with accepted industry practices. If special equipment or test apparatus is recommended by the manufacturer involved, he must use that equipment or apparatus or its equivalent acceptable to the Administrator.

2.18.06

121.709 Airworthiness release or aircraft log entry.

(a) No certificate holder may operate an aircraft after maintenance, preventive maintenance or alterations are performed on the aircraft unless the certificate holder, or the person with whom the certificate holder arranges for the performance of the maintenance, preventive maintenance, or alterations, prepares or causes to be prepared -

- (1) An airworthiness release; or
- (2) An appropriate entry in the aircraft log.

(b) The airworthiness release or log entry required by paragraph (a) of this section must -

(1) Be prepared in accordance with the procedures set forth in the certificate holder's manual;

(2) Include a certification that -

(i) The work was performed in accordance with the requirements of the certificate holder's manual;

(ii) All items required to be inspected were inspected by an authorized person who determined that the work was satisfactorily completed;

(iii) No known condition exists that would make the airplane unairworthy; and

(iv) So far as the work performed is concerned, the aircraft is in condition for safe operation; and

(3) Be signed by an authorized certificated mechanic or repairman except that a certificated repairman may sign the release or entry only for the work for which he is employed and certificated.

Notwithstanding paragraph (b)(3) of this section, after maintenance, preventive maintenance, or alterations performed by a repair station certificated under the provisions of Subpart C of Part 145, the airworthiness release or log entry required by paragraph (a) of this section may be signed by a person authorized by that repair station.

(c) When an airworthiness release form is prepared the certificate holder must give a copy to the pilot in command and must keep a record thereof for at least two months.

(d) Instead of restating each of the conditions of the certification required by paragraph (b) of this section, the air carrier may state in its manual that the signature of an authorized certificated mechanic or repairman constitutes that certification.

[Doc. No. 6258, 29 FR 19226, Dec. 31, 1964, as amended by Amdt. 121-6, 30 FR 6432, May 8, 1965; Amdt. 121-21, 31 FR 10613, Aug. 9, 1966]



U. S. Department
of Transportation


Federal Aviation
Administration

cc: Jerry Sumiano
John Camden
Bob Hall

FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

February 13, 2001

FILE NUMBER: 2001GL050039




Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

On January 22, 2001, you were advised that the Federal Aviation Administration was investigating a possible violation of a Federal Aviation Regulation involving Emery Worldwide Airlines Inc. Certificate (RRXA). The alleged violation was the use of Teflon tape to repair an oxygen system leak on N606AL, according to the aircraft maintenance log. After further investigation it was determined that the DC-8 Maintenance Manual does allow for the use of Teflon tape on tapered thread fittings. It could not be determined that the tape was used on other than tapered thread fittings in this application.

This letter is to inform you that the investigation has not established a violation of the Federal Aviation Regulations and you may consider this matter closed.

Sincerely,



Harold R. Camden
Principal Maintenance Inspector

A N

2.18.06 A ramp inspection of aircraft DC-8, N606AL revealed the use of Teflon tape for the repair of the oxygen system with no reference to repair data. The use of Teflon tape is not listed as an approved repair in the manufacturer's maintenance manual. This is contrary to 14CFR 43.13(a) and 121.709.

RRXA RESPONSE: EWA does not repair Oxygen bottles. These are sent to the manufacturer for service.

RRXA CONCLUSION: No finding

Owens, James H

From: Ungemach, David W
Sent: Monday, February 05, 2001 3:04 PM
To: Owens, James H
Subject: RASIP finding 2.18.06

The OXY bottle received has a form of tape that may be Teflon sealing the regulator to the bottle. This repair is done at the repair facility and not by line maintenance. The item was received with a serviceable tag.

David W Ungemach
Director, Line Maintenance
EWA
[Redacted]



A Y

FINDING: 2.19.01 During a spot check of A/C N996GE, mechanics were observed troubleshooting #2 engine exhaust gas temperature (EGT) without proper test equipment and without following proper procedures. This is contrary to 14CFR part 121.369(b) and RRXA MPPM. Test leads 8563317 and 856A3318 were not available. When the mechanic was asked about the procedure for testing he returned with a copy of a work card DC8-77-20-02-001. The proper procedure is EO #AM-772202:00. This is contrary to 14CFR 121.369(b) and RRXA MPPM.


RRXA RESPONSE: *The alumel chromel test leads were unserviceable. The mechanic pushed the pins out of the plug and took a direct reading from the Barfield tester. The correct tester was used and this method will not alter the integrity of the test. The leads have been repaired and are available for use. All mechanics have been instructed not to use EO #AM-77-20-02-001 provided by EWA Engineering Department and to use EO #AM-7722-02:00.*

RRXA CONCLUSION: *Finding valid.*



U. S. Department
of Transportation

Federal Aviation
Administration



FLIGHT STANDARDS DISTRICT OFFICE
4240 Airport Road
Cincinnati, Ohio 45226
513-533-8110
FAX 513-533-8420

cc: Jim Owens
Jerry Sumner
Bob Dell

January 24, 2001

2,19,01 ✓

FILE NUMBER: 2001GL050040

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

During a spot check of Aircraft N996GE, mechanics were observed troubleshooting #2 engine exhaust gas temperature (EGT) without proper test equipment and without following proper procedures. This is contrary to 14CFR part 121.369(b) and RRXA Maintenance Policy and Procedures Manual (MPPM). Test leads 8563317 and 856A3318 were not available. When the mechanic was asked about the procedure for testing he returned with a copy of a work card DC8-77-20-02-001. The proper procedure is Engineering Order (EO) #AM-7722-02-00. This is contrary to 14CFR 121.369(b) and RRXA MPPM.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

§ 121.369 Manual requirements.

(a) The certificate holder shall put in its manual a chart or description of the certificate holder's organization required by § 121.365 and a list of persons with whom it has arranged for the performance of any of its required inspections, other maintenance, preventive maintenance, or alterations, including a general description of that work.

(b) The certificate holder's manual must contain the programs required by § 121.367 that must be followed in performing maintenance, preventive maintenance, and alterations of that certificate holder's airplanes, including airframes, aircraft engines, propellers, appliances, emergency equipment, and parts thereof, and must include at least the following:

2, 19.01

NO.	DATE	STATION	CHT	IN	OUT	BLOCK HOURS	OFF	ON	TIME	UPPER	LOWER	REMARKS
1	10-20-00	KDAY KOAK	1737	2209	4:33	1745	2156	4:11	8000	14.0	26.5	5474
2												
3												
4												

NO.	DELAY	FROM	TRAIN	FLTS	OIL ADD	WASL	REMARKS
1	02	580			1 2 1 1	-	011 D. ENGINE 39037 1 1
2							012 E. SOBOL 78556
3							013 R. ARMSTRONG 02111
4							

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE
1.	O/M	#2 EGT FLUCTUATES (INDIC) IRRATICALLY, ALL OTHER ENGINE PARAMETERS STABLE. SECURED EGT INDIC. SAME PROBLEM.	1.	SECURED #2 ENG EGT LEAD (HARNES) FROM PYLON TO EGT HARNES. OPS OK ON ENGINE RWI PER M/M 27-20-00	11/20/00 KOAK 31305
2.	O/M	RADAR FAIL LITE CAME ON AFTER 30 MINUTES OF USE. TR FAIL, TURN OFF THEN ON STILL DOES FAIL	2.	R&R RADAR ANTENNA OPS NOW NORMAL PER M/M 34-41-1	10/21/00 KOAK 36305
3.	O/M	MOISTURE INSIDE STBY ATTITUDE INDICATOR	3.	R&R STBY ATTITUDE INDICATOR FAW DC8 71 SERIES MH 34-28-0.	10/20/00 KOAK 69030
4.	O/M	BOTH VOR NEEDLES WANDER IN PRECIP.	4.	RE-RACKED 1 & 2 VOR RECEIVERS OPS NOW NORMAL PER TIC RAMP TEST UNIT PER M/M 34-52-0	11/20/00 KOAK 36305
5.	P/M		5.		
6.	P/M		6.		

NO.	PART NO	MANUFACTURE	PART NO OFF	BEH NO OFF	PART NO ON	BEH NO ON	POS
3	ATTITUDE INDICATOR		1976910-1	7204103	1976910-1	7204100	STBY
2	RADAR ANTENNA		622-5125-001	1044	622-5125-001	1193	

AIRWORTHINESS RELEASE		AIRCRAFT TIME / CYCLES				INS READOUT				
CHECK CW: TERM	STATION: KOAK	PREVIOUS LANDINGS	32202	LANDINGS THIS PAGE	1	TOTAL LANDINGS	32203	1-DIST.	2-DIST.	3-DIST.
DATE: 10-21-00	CERT. NO.:	REV AND FLT HRS	91978.47	FLT HRS THIS PAGE	4:11	TOTAL A/G FLT HRS	91978.58			
GMT TIME: 0820	AUTH. SG.:	DISC. OR MAINT. ACTION CARRIED FWD TO:		BOOK CHANGED NEW LOG PAGE NO:		CAPTAIN'S SIGNATURE				

AIP

MAINTENANCE LOG

02202

9) Ulho U.S.A.

EME
WORLWIDE
 A CTF COMPANY

09695-25

ACFT. NO.

N9966E

3FT. TYPE

JCB-71F

NO.	DATE	STATION	GMT	BLOCK HOURS	GMT	HOURS	FLIGHT NO.	DEPART (EST)	ARRIVAL (EST)	LEAVE	ARRIVAL	SPEC	MAIL		
														FROM	TO
1	381	KOAK	KDAY	0934	1400	4:26	0954	1355	4:01	7442	760	28.6	φ	49515	φ
2															
3															
4															

NO.	TIME	RELAY	MODE	ADDS	STATION	FREQ	FREQ	FREQ	FREQ	LEV	FVI	OBS	VIA	TRW	EVI
1										011	M. FOWELL				
2										012	R. MCLEOD				
3										013	T. BOULAN				
4										DIT	D. ENGLE				

NO.	G/DG	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MEDIA
1	P/M	#2 CAPT FREQ SEL KNOB WONT TYPE ZLS	1	TIGHTENED #2 ILS FREQUENCY SELECT KNOB AS REQUIRED.	10/21/00	KMY	SORSZ
2	P/M		2				
3	P/M		3				
4	P/M		4				
5	P/M		5				
6	P/M		6				

NO.	PART NO	ENG. OFF.	PART NO	ENG. OFF.	PART NO	ENG. OFF.	PART NO	ENG. OFF.

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES				INS HEADOUT		
CHECK CW	STATION	PREVIOUS LANDINGS	LANDINGS THIS PAGE	TOTAL LANDINGS	1-DIST.	2-DIST.	3-DIST.			
TRANSIT CV	KDAY	32203	1	32204						
DATE: 10-21-00	CERT. NO.: [REDACTED]	PREV. AIR FT. HRS: 91978.8	FLY HRS THIS PAGE: 4:01	TOTAL AIR FT. HRS: 91982.8						
GMT TIME: 1430Z	AUTH. SIG.: [REDACTED]									
DISC. OR MAINT. ACTION CARRIED FWD TO:				BOOK CHANGED NEW LOG PAGE NO: 9457-01		CAPTAIN'S SIGNATURE: [REDACTED]				

LOG PAGE DIST.

1. ORIGINAL WHITE - MAINTENANCE

2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE)

3. PINK COPY - RETAIN IN BINDER

AIRCRAFT MAINTENANCE LOG

D2202-16 (2/89) I.I. No. U.S.A.



09457-01

ACFT. NO. **N9966E** ACFT. TYPE **D28-71**

FLIGHT NO.	DATE	FROM	TO	FLIGHT TIME	ENROUTE	ARRIVAL	DEPARTURE	ENROUTE	ARRIVAL	DEPARTURE	ENROUTE	ARRIVAL	DEPARTURE	ENROUTE	ARRIVAL	DEPARTURE
1	382	0-21-00	KOAK KOAK	1154	2230	4+36	1800	2215	4+15	7460	79.0	25.4	-	51,483	-	-
2																
3																
4																

NO.	DELAY	REASON	LOGS	STATION	APU	TIME	BY	TIME	BY	TIME	BY	TIME	BY
1	0:9	500					01	J. BUCKLEY	9988				
2	:						02	J. BURNETT	60471	1	1		
3	:						03	B. MURRAY	60460				
4	:						D/H	E. HERB	34656				

NO.	SOURCE	DESCRIPTION	NO.	DATE	STA.	INITIALS
1.	Ⓞ/M	#2 ALT. BOOST PUMP POPPED CR IN FLIGHT.	1.			
2.	Ⓞ/M	WX RADAR FAILED IND. RT FAIL	2.			
3.	Ⓞ/M	#2 EGT GUAGE FLUCTUATES BETWEEN 620 & 750. VERY ERRATIC IN CLIMB.	3.			
4.	P/M		4.			
5.	P/M		5.			
6.	P/M		6.			

NO.	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	POST

AIRWORTHINESS RELEASE		AIRCRAFT TIME CYCLES			MILEAGE		
CHECK CW:	STATION:	PREVIOUS	THIS	TO	1-DIST.	2-DIST.	3-DIST.
DATE:	CERT. NO.:	32204	32205	1			
GMT TIME:	AUTH. SIG.:	91482 59	91487 14	4:15			

PAGE 01/01

KOAK AIRCRAFT MX

1/2000 16:03 5105350690

AIR FT MAINTENANCE LOG

02202-4b (2/89) Litho U.S.A.



09457-02

FT. TYPE
1991 GE JCS-71

FLY	DATE	STATION		GMT	BLDG	HOURS	DEPARTURE			ARRIVAL			
		FROM	TO				TIME	INSTR	TIME	INSTR	TIME	INSTR	
1	381 10-22-00	KOAK	KDAY	0730	1425	4555	1005	1416	1411	7576	81.0	3515	70, 86
2													
3													
4													

FLY	DEPT. DELAY		TRAIN FILTER		OIL ADD		EMP	TO	TIME
	CODE	REASON	REASON	REASON	REASON	REASON			
1							0	0	0
2							01	01	01
3							03	03	03
4									

NO	SOURCE	DISCREPANCY	CORRECTIVE ACTION	DATE	BY	TIME
1.	P/M	#2 EGT GAUGE ERRATIC FLUCTUATES BETWEEN 650 + 1000 IN CLIMB + AT CRUISE. WORKS FINE ON GROUND.	Removed and replaced 5 Esch E.G.T. Thermocouple #2 Eng. T.A.W/M let 77-20-3. Performed E.G.T. system check CFMS6-25. No defects noted. #2 E.G.T. ops check good upon enroute.	10/22/00	KDAY	0544
2.	P/M	WX RADAR WORKS WELL FOR APPROX. 1.5 HRS. THEN R/T FAIL OCCURS. TURN OFF 20-30 MIN. THEN BACK ON + WORKS AGAIN FOR 1.5 HRS THEN FAILS.	Wx radar would not come on. Cleaned dirt on P/RH pack. Fan inside fan. Cleaned all electrical connections on fan and common plus fan grounds. Normal operation. Checked system gas checks good. DC-8 M/M 74-41-03.	10/22/00	KDAY	0544
3.	P/M	BAD SMELL COMING FROM OVERHEAD AIR VENTS IN COCKPIT IN DESCENT. SMELLS LIKE HOT OVERHEATING DUCTS + OILY RAGS.	Performed operational check of both L/H and R/H packs with mix valves in both cold and hot positions and variable flow settings. Also checked pneumatic ducts on both packs for security. No defects found. Could not duplicate discrepancy. No overheating smell noted. Let DC-8 M/M 21-55-0.			
4.	P/M	Crew reported O2 system press. 1550psi. insufficient pressure.	Service crew O2 bottles to 1800psi. No leaks noted. Pressure and leak check good. Let M/M 12-70-01.	10/22/00	KDAY	0544
6.	P/M					

NO	PART NOMENCLATURE	PART NO OFF	SERIAL NO OFF	PART NO ON	SERIAL NO ON	POS
1	Thermocouple Assy.	301-775-902-0	2809	301-775-902-0	4278	2
1	Thermocouple PK Assy.	301-775-902-0	5060	301-775-902-0	2432	2
1	Thermocouple Assy.	TC153-01	2016	TC153-01	4782	2
1	Thermocouple Assy.	301-775-902-0	1098	301-775-902-0	2283	2
1	Thermocouple Assy	301-775-902-0	2559	301-775-902-0	2427	2

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES				INSURANCE		
CHECK CW:	STATION:	PREVIOUS LANDINGS	LANDINGS THIS PAGE	TOTAL LANDINGS	1-DIST.	2-DIST.	3-DIST.			
Transit	KDAY	32205	1	32206						
DATE: 10/22/00	CERT. NO.:	PREV. AIR FLT HRS	FLT HRS THIS PAGE	TOTAL A/C FLT HRS						
GMT TIME: 1915Z	AUTH. SIG.:	91987.14	4:11	91991						
DISC. OR MAINT. ACTION CARRIED FWD TO:				BOOK CHANGED NEW LOG PAGE NO.:		CAPTAIN'S SIGNATURE:				

LOG PAGE DIST. 1. ORIGINAL WHITE - MAINTENANCE 2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE) 3. PINK COPY - RETAIN IN BINDER

121
344
2122
1264

FLIGHT NO.	DATE	TIME	STATION		GMT		BLOCK HOURS		PILOT		FUEL		ARRIVAL		CARGO		MAIL
			FROM	TO	DEPT	ARR	IN	OUT	REF	TYPE	DEPART	ARRIVAL	WEIGHT	WEIGHT			
1	10/22/00	10:22	KDAY	KDAY	2037	2140	1703	2045	2135	0+48	3000	55.6	46.2	0	52460	NA	
2																	
3																	
4																	

NO.	DEPART DELAY		TRAIN FLTS		OIL ADD		A/P	CREW	EMP	TO	LOG	A/P	CREW	TIME
	REAR	CODE	LDGS	STATION	BAR	BAR								
1	1:22	612/50			0	0	0	01	S. Zettler	92075	1	1		
2							02	D. McInnis	54632					
3							03	K. Hollan	61996					
4							NP	P. MARSTERS	52294					

772L
 71B
 5430

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MECH
1.	P(M)	#2 EGT erratic in climb 680-1000 Precaution Engine Shutdown	1.	RIP'D 1 EA Thermocouple ASSY 1/1W m/n 77-20-3 - RIP'D Lead ASSY from EGT Harness held to Pylon Repaired wires in Pylon Performed 35min High Power CUL	10/22/00	KDAY	25956
2.	P(M)	#2 Eng. Cowls opened to facilitate maintenance	2.	Closed & secured cowl 1/1W m/n 71-10	10/22/00	KDAY	25956
3.	P(M)	#2 Eng. Pylon Panels off to facilitate maintenance	3.	Reinstalled panels 1/1W m/n 1/20 STANDARD Practices	10/22/00	KDAY	25956
4.	P(M)		4.	1 - continued from block #1 1/1W DC-9 FWA RUN HANDBOOK OPS CKS GOOD NO DEFECTS NOTED			
5.	P/M		5.				
6.	P/M		6.				

NO.	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	QTY
1	Thermocouple Probe	TC153-01	5068	TC153-01	1295	2

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES				INSURE ABOUT			
CHECK CW:	STATION:	PREVIOUS LANDINGS	LANDINGS THIS PAGE	TOTAL LANDINGS	1-DIST.	2-DIST.	3-DIST.				
Term	KDAY	32206	1	32207							
DATE: 10/22/00	CERT. NO.: [REDACTED]	PREV. A/C FLT HRS	FLY HRS THIS PAGE	TOTAL A/C FLT HRS							
GMT. TIME: 0830	AUTH. SIG: [REDACTED]	91991.25	18	91992.13							
DISC. OR MAINT. ACTION CARRIED FWD TO:				BOOK CHANGED NEW LOG PAGE NO:				CAPTAIN'S SIGNATURE: [Signature]			

AIRCRAFT MAINTENANCE LOG
 b2202-46 (2/2004) Litho U.S.A.



09457-04

ACFT. NO. N996GE ET. TYPE C-8-71F

NO.	DATE	TIME	STATION		GMT		BLOCK HOURS		FLY HOURS	FUEL DATA			WEIGHT		CARGO DATA	
			FROM	TO	OFF	ON	OFF	ON		UP (LBS)	DOWN (LBS)	GAUGES	WEIGHT			
1	10/23/00	10:00	KDMX	KMCO	1205	1352	1+52	1212	1352	140	1900	57.3	35.2	0	52.460	NA
2																
3																
4																

NO.	DEBAY	TRAINING	ELITE	OIL ADD		A/P	CREW	EMP	T/O	T/O	A/P	CREW	EMP
				TYPE	AMOUNT								
1	NK	NK					01 S. Zetter	92075					
2							02 D. McINNIS	54632					
3							03 K. Hollan	61996					
4							NR P MARSTERS	52294					

52-72

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MECH
2.	P/M		2.				
3.	P/M		3.				
4.	P/M		4.				
5.	P/M		5.				
6.	P/M		6.				

NO.	PART NO	DESCRIPTION	PART NO	OFF	SER. NO	OFF	PART NO	SER. NO	OFF	PART NO	SER. NO	OFF	PART NO	SER. NO	OFF

AIRCRAFT RELEASE				AIRCRAFT TIME / CYCLES				INS READOUT		
CHECK CW:	STATION:	PREVIOUS LANDINGS	32207	LANDINGS THIS PAGE	1	TOTAL LANDINGS	32208	1-DIST.	2-DIST.	3-DIST.
DATE:	CERT. NO.:	PREV. AIRC. TIME	91992.13	TOTAL AIRC. TIME	1:40	TOTAL AIRC. TIME	91993.53			
GMT TIME:	AUTH. SIG.:	DISC. OR MAINT. ACTION CARRIED FWD TO:				BOOK CHANGED NEW LOG PAGE NO:		CAPTAIN'S SIGNATURE:		

LOG PAGE DIST. 1. ORIGINAL WHITE - MAINTENANCE 2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE) 3. PINK COPY - RETAIN IN BINDER

AIRCRAFT MAINTENANCE LOG

02202-46 (2/99) Utho U.S.A



09457-05

ACFT. NO. N 9966E ACFT. TYPE DC-8-71F

LEG	FLT	DATE	STATION		GMT		BLOCK HOURS	GMT		FLT. HOURS	FUEL DATA			CARGO DATA		
			FROM	TO	OUT	IN		OFF	ON		UPLIFT (USA)	DEPART (LBS)	ARRIVAL (LBS)	GAL'S	CARGO	MAIL
1	334	10/23/00	KRCD	KTPA	1540	1612	0132	1545	1602	0123	0	35.2	29.8	0	0	NA
2																
3																
4																

LEG	DEPT. DELAY		TRAIN. FLT.		CHK. ADD					A/P	CREW	EMP #	T.O.	LDG	A/P	CREW	EMP #	
	DELAY	CODE	LDGS	STATION	1	2	3	4	APU									
1	NA	NA			0	0	0	0		01	S. Zettler	92075	1	1				
2										02	D. McInnis	94632						
3										03	K. Hollan	61596						
4										NR	P. Macster	52294						

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MECH
2	P/M	FO needs AIS Bug	2	RESEVICED LAMP FOR NOT AT FILTERS W/OZ FOR AD LEAKS NOTED. U/V/W O/U/W 35-10-04	10/23/00	KTPA	0211Z
3	P/M	REFE DMI# 9457041-9293 Pit Drain Light MEL 52-1	3	CLEARED CANAL AT SWITCH RESEVICED O2'S O/KS NORMAL THIS CLEAR DUIZ 9457041-9293 - PLACED REMOVED. U/V/W SP/W	10/23/00	KTPA	0211Z
4	P/M		4				
5	P/M		5				
6	P/M		6				

NO.	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	POB

AIRWORTHINESS RELEASE			AIRCRAFT TIME / CYCLES				INS READOUT			
CHECK CW: <i>SEVICED</i>	STATION: <i>KTPA</i>	PREVIOUS LANDINGS: 32208	LANDINGS THIS PAGE: 1	TOTAL LANDINGS: 32209	1-DIST.	2-DIST.	3-DIST.			
DATE: <i>10-24-00</i>	CERT. NO.: [REDACTED]	PREV. AIS: 01001-01	FLY. HRS: .23	TOTAL AIS: 91994.16						

AIRCI

MAINTENANCE LOG

EMER
WORLDWID.
A CTF COMPANY

09457-06

ACFT N 996 GE, TYPE 1-8-71F

02202-48 (2/99) Litho U.S.A.

FLIGHT NO.	DATE	FROM	TO	GMT		FLOG HOURS	DEF	CON	HOURS	FUEL DATA		PRICE	CARGO DATA		
				IN	OUT					DEPART	ARRIVAL		KG	MAIL	
1	10/24/60	KTPA	KHCO	0153	0234	741	0209	0230	721	4548	60.0	55.3	0	11635	0
2	10/24/60	KHCO	KDMY	0311	0526	2+15	0327	0518	1+57	0	55.3	30.0	0	46932	0
3															
4															

NO.	DEPT	AREA	CODE	TRAINING STATION		OIL ADD	TYPE	GHEV	TIME	TO	FROM	REMARKS
				ADGE	STATION							
1								0-1	D. RUSSELL	72676	1	N-R SPANO INSTONE
2								0-2	D. WHEELER	88212	1	
3								0-3	Z. SERFOZO	75195		
4								N-R	M. DENNIS	INSTONE		

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	BY
2	(P/M)	SECOND OBSERVERS O2 REGULATOR RAPIDLY LOSES PRESSURE WHEN SWITCH IS TAPPED OFF	2	REMOVED AND REPLACED SECOND OBSERVERS O2 REGULATOR AND ILS-B MIN 35-10-7	10/24/60	KDMY 03:958
3	P/M		3			
4	P/M		4			
5	P/M		5			
6	P/M		6			

NO.	DESCRIPTION	PLAT NO	SERIAL NO	PART NO	SERIAL NO
2	O2 REGULATOR	15830L	20107	15830A	20504
					ADP 265

AIRWORTHINESS RELEASE		AIRCRAFT TIME / CYCLES				INS/HEADQUARTERS				
CHECK C/W: TRAVIS	STATION: KDMY	PREVIOUS LANDINGS	32209	LANDINGS THIS PAGE	2	TOTAL LANDINGS	32211	1-DIST.	2-DIST.	3-DIST.
DATE: 10-24-60	CERT. NO.: [REDACTED]	PREV AVG FLT HRS	91994.16	FLT HRS THIS PAGE	2:12	TOTAL AVG FLT HRS	91996.28			
GMT TIME: 0615Z	AUTH. SIG: [REDACTED]	DISC OR MAINT. ACTION CARRIED FWD TO: [REDACTED]				CAPTAIN'S SIGNATURE: [REDACTED]				

LOG PAGE DIST. 1. ORIGINAL WHITE - MAINTENANCE 2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE) 3. PINK COPY - RETAIN IN BINDER

33K
3512

FLY	DATE	STATION		GMT		BLOCK HOURS		GMT		FLT HOURS	FUEL DATA			DENOBS		BARGO DATA		
		FROM	TO	OUT	IN	OFF	ON	WGT (LBS)	DEPART (HRS)		ARRIVAL (HRS)	CLASS	CO	CLASS	MAIL			
1																		
2																		
3																		
4																		

MX ONLY

FLY	OVERTIME		TRAIN/FLTS		OIL ADD		A/P	CHEW	TEMP	MO	T/BG	A/B	OR/W	TEMP
	NEW	CODE	AGES	STATION	TYPE	TAPE								
1														
2														
3														
4														

Ø Ø Ø Ø MA

NO FLT

NO	EG/HC	DISCREPANCY		NO	CORRECTIVE ACTION		DATE	BY	MECH
		DESCRIPTION	REMARKS		DESCRIPTION	REMARKS			
1.	P/M		Reference FCD #52-22 Task Code 825210, Inspection of Cargo Floor and Aft Restraints	1.		Inspected Cargo Floor and Aft Restraints per FCD #52-22 Task Code 825210 with Pemco Engineers; No Intermixed parts on floor and Aft Restraints per Pemco Engineers, Floor and Aft Restraints Ops Check Good.			
2.	P/M								
3.	P/M								
4.	P/M								
5.	P/M								
6.	P/M								

NO	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	POS

AIRWORTHINESS RELEASE		AIRCRAFT TIME / CYCLES				INS READOUT				
CHECK CW: <i>N/A</i>	STATION:	PREVIOUS LANDINGS	32211	LANDINGS THIS PAGE	0	TOTAL LANDINGS	32211	1-DIST.	2-DIST.	3-DIST.
DATE:	CERT. NO.:	PREV. A/C FLT HRS	91996.28	FLT HRS THIS PAGE	0	TOTAL A/C FLT HRS	91996.28			
GMT TIME:	AUTH. SIG.:									
DISC. OR MAINT. ACTION CARRIED FWD TO:		BOOK CHANGED NEW LOG PAGE NO:			CAPTAIN'S SIGNATURE					

AIRCRAFT MAINTENANCE LOG

12222-48 (2-89) I - In U.S.A.

EMERY
WORLDWIDE
a GIP COMPANY

09457-08

ACFT NO. N 9966E ACFT. TYPE DCB-71F

FLY	DATE	STATION		IN	OUT	BLOCK HOURS	DEPT		FLT HOURS	FLIGHT DATA		COSTS	REMARKS	
		FROM	TO				OFF	ON		REPORT HRS	ACTUAL HRS			
26	10-24-00	KDAY	KSEA	939	1419	4739	953	1908	4715	7291	80.5	265	8	61269

DEPT. RELAY	THRU. RELAY	THRU. RELAY		SL. ADD				APU	A/P	Crew	EMP #	T.O.	LBR	A/P	Crew	EMP #	
		FROM	TO	1	2	3	4										
						3	4	2	1	✓	011	J. AH	871	1	X4	Holmquist	36704
											012	G. Turcot	64017				
											013	B. Huescher	61987				
											JS	S. Hewitt	35027				

NO.	SOURCE	DESCRIPTION	NO.	CORRECTIVE ACTION	DATE	BY	MISC.
2.	OM	Requires 2 units right rudder	2.	Rechecked Rudder Trim potentiometer checks good TAW MM 27-23-1.	10/24/00	KSEA	04503
3.	OM	Standby Attitude Indicator processes 50 nose up in level flight in 20 minutes	3.	PER'd SAI per MM 41-21-102400 KSEA 24674. Checks normal per MM 41-70-02.	10/24/00	KSEA	24674
4.	OM	#2 alternate tank reads 2000# low in flight	4.	572 Att Fuel Quantity Checks good on ground TAW MM 28-41-0.	10/24/00	KSEA	04503
5.	OM	loud air noise in nose wheel well	5.	Secured NET Right nose wheel well. Checks good.	10/24/00	KSEA	04503
6.	OM	#6 #2 CMM indicated 135.52 actually received 135.5	6.	Retracted comm. control panels - checks normal per MM 27-20-03	10-24-00	KSEA	24674

NO.	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	REMARKS
3	Stanby Attitude Indicator	1976910-1	7204100	1976910-3	7103142	only

AIRWORTHINESS RELEASE		AIRCRAFT TIME / CYCLES				DIS. REPORT		
CHECK OFF:	STATION:	PREVIOUS LANDINGS	LANDINGS THIS PAGE	TOTAL LANDINGS	1-DIST	2-DIST	3-DIST	
DATE:	CER. NO.:	32211	1	32212				
GMT TIME:	AUT. SIG.:	PREV. A/C FLT. HRS. 91996.28	FLT. HRS. THIS PAGE 4.15	TOTAL A/C FLT. HRS. 92000.43				

DISC. OR MAINT. ACTION CARRIED FWD TO 9457-08 BOOK CHANGED NEW LOG PAGE NO. CAPTAIN'S SIGNATURE

LOG PAGE DIST. 1. ORIGINAL WHITE - MAINTENANCE 2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE) 3. PINK COPY - RETAIN IN BINDER

AIRCRAFT MAINTENANCE LOG

12202-45 (2-99) - IFO JSA

EMERY
WORLDWIDE
A GTE COMPANY

09457-09

ACFT. NO. **N 996GE** ACFT. TYPE **DC8-71**

NO.	FLT	DATE	STATION		DEPART	ARRIVE	BLOCK	GMT		FLT	FUEL DATA			OBSERV	REMARKS
			FROM	TO				OFF	ON		HOORS	UNPT. TOL	DEPART. LB		
1		10-25-00	KSEA												
2															
3															
4															

No Flight

NO.	DEPT. DELAY	CODE	EDOS	STATION	DEPART				ARRIVE	TO	LOG	A/P	OTHER	EMP
					1	2	3	4						
1														
2														
3														
4														

NA USE

NO.	OFFICE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	BY
2	P/M		2			
3	P/M		3			
4	P/M		4			
5	P/M		5			
6	P/M		6			

NO.	PART NOMENCLATURE	PART NO. OFF	REF. NO. OFF	PART NO. ON	QTY. NO. ON	PR.
1	Transformer	7612266-501	1014	7838	2831	Capt's

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES				INS. RES. COPT.		
CHECK OFF: Tenn.	STATION: KSEA	PREVIOUS LANDINGS	32212	LANDINGS THIS PAGE	0	TOTAL LANDINGS	32212	1-O.ST.	2-DIST.	3-D
DATE: 10-25-00	CFR. NO. [REDACTED]	PREV. AC FLT. HRS.	92000:48	FLT. HRS. THIS PAGE	0	TOTAL AC FLT. HRS.	92000:48			
GMT TIME: 0044Z	ALT. S.G. [REDACTED]									

DISC. OR MAINT. ACTION CARRIED FWD TO: _____ BOOK CHANGED NEW LOG PAGE NO: _____ CAPTAIN'S SIGNATURE _____

LOG PAGE DIST. 1. ORIGINAL WHITE - MAINTENANCE 2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE) 3. PINK COPY - RETAIN IN BINDER

FLT	DATE	STATION		GMT		BLOCK HOURS	GMT		FLT. HOURS	FUEL DATA			DE-ICE		CARGO DATA	
		FROM	TO	OUT	IN		OFF	ON		UPLIFT (USG)	DEPART. (LBS)	ARRIVAL (LBS)	GAL'S	CARGO	MAIL	
1	025	SFA	DAY	0127	0540	350	0139	0535	4+13	7110	75.8	27.7	Ø	45360	NA	
2																
3																
4																

DEPT. DELAY	TRAIN. FLTS.	OIL ADD					A/P	CREW	EMP #	T.O.	LDG	A/P	CREW	EMP #
		CODE	LDGS	STATION	1	2								
							01	D. Vanderhule	84722	1		DH	Holmgust	36701
							02	S. Hewitt	35007			DH	K. Ange	01834
							03	S. Sandquist	66725					

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MECH
1.	(P/M)	Standby attitude indicator processes to 4° Pitch up after 1 hr flight time	1.	RESEATED PIN ON PLUG P10-5172 AT SAI BATTERY. SYSTEM OPS CHECKS GOOD INW DC-3 WIRING DIAGRAM 34-2-6. AND M/M CH 34-28-0	10/25/00	KDAY	28126
2.	(P/M)	#2 alt tank reads 2,000# Low during flight	2.	Sumped #2 ALT TANK compared master stick to IND at several levels no defects noted	10/25/00	KDAY	25236
3.	(P/M)	Right pneumatic manifold indicating 135° with flow control at 80%	3.	Performed OPS CK of both #3 & #4 pneumatic system	10/25/00	KDAY	25956
4.	(P/M)	#4 N2 guage seal on top of guage is protruding out	4.	REMOVED AND REPLACED #4 ENGINE N2 INDICATOR	10-25-00	KDAY	46958
5.	(P/M)	Pilot forward windscreen completely fogged, can't see for landing	5.	Removed and replaced capt's side windshield	10-25-00	KDAY	70761
6.	(P/M)	#4 Thrust Reverser did not deploy till 20 sec. after 123.	6.	Performed OPS CK of #4 TRC	10/25/00	KDAY	75456

NO.	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	POS.
4	N2 INDICATOR	8DT324WAE1	T0076	8DT324WAE1	X1011A	4
5	SIDE WINDOW	5593704-501	NSN	5593704-501	106282	ONLY

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES				INS READOUT		
CHECK CW: N/A	STATION: KDAY	PREVIOUS LANDINGS	LANDINGS THIS PAGE	TOTAL LANDINGS	1-DIST.	2-DIST.	3-DIST.			
DATE: 10-25-00	CERT. NO. [REDACTED]	PREV. A/C FLT. HRS.	FLT. HRS. THIS PAGE	TOTAL A/C FLT. HRS.						
GMT TIME: 2330Z	AUTH. SIG. [REDACTED]									
DISC. OR MAINT. ACTION CARRIED FWD TO:				BOOK CHANGED NEW LOG PAGE NO:				CAPTAIN'S SIGNATURE [REDACTED]		

AIRCRAFT MAINTENANCE LOG

02202-46 (2/89) Lillo U.S.A.

EMERY
WORLDWIDE
A CTF COMPANY

09457-11

ACFT. NO. **N 996GE** ACFT. **DC-8 71**

FLTS	DATE	STATION		GMT		BLOCK HOURS	GMT		FLT. HOURS	FUEL DATA		DE-ICE GAL'S	CARGO DATA	
		FROM	TO	OUT	IN		OFF	ON		UPLIFT (USG)	DEPART (LBS)		ARRIVAL (LBS)	CARGO
1	10/25/00													
2														
3														
4														

DEPT. DELAY	TRAIN. FLTS	OIL ADD				A/P	CREW	EMP #	T.O.	LDG	A/P	CREW	EMP #
		LDGS	STATION	1	2								

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MECH
1.	P/M	REF DMI # C 9695196-9059 #3 Main FQI Reads 10,000 low when full	1.	R&R Fuel Box Probe, Lo-Z on AFT Vol 10/25/00 DAY 89936 Inboard probe and Replaced Lo-Z on Fuel Box Probe. AFT TAN DC-8 MM 28-41. This does not clear DMI. Tank reads 13,600 lbs when full. (12,500 lbs)			
2.	P/M	See Logpage 9457-10 item 5. Remove tape captain's side window after cure time of 8 hours. (8:00pm)	2.	Tape removed as required 10/26/00 DAY 25756			
3.	P/M	Ref DMI # C 9695163-9032. Capt's window Heat INOP.	3.	R&R windshield Heat Controller 10-25-00 DAY 61467 Operation check of Capt's Window Heat Tank DC-8 MM 30-40-0. This clears DMI # C 9695163-9032. Placer & Remove			
4.	P/M	REF DMI # C 9695196-9059 #3 MAIN FQI READS 10,000 LOW WHEN FULL	4.	REPAIRED HI-Z & LO-Z CONN. FWD OTBD PROBE 10/26/00 DAY 51464 & LO-Z CONN. AFT OTBD PROBE, R&R'D FWD OTBD PROBE & R&R'D #3 MAIN FUEL QTY INDICATOR SYSTEM OPS CK GOOD TAN DC-8 - MM. CH 28-41-00 WITH KNOWN QTY			
5.	P/M	NOT USED	5.	AT VARIOUS LEVELS THIS CLEARS DMI # C 9695196-9059 PLACARD REMOVED			

NO.	PART NOMENCLATURE	PART NO. OFF	SER. NO. OFF	PART NO. ON	SER. NO. ON	POB.
1	Probe	B 277-1574	124905-14X	B 277-1574	B 4308-7	Fuel Box
3	Controller	1339-1	37575	1339-1	3855B	Capt
4	PROBE	B 277-1570	A 85691-1	B 277-1570	B 15684-4X	#3 FWD OTBD
4	FUEL QTY IND	206-009-005	166	206-009-005	195	#3 MAIN

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES			INS READOUT		
CHECK C/W:	STATION:	PREVIOUS LANDINGS	LANDINGS THIS PAGE	TOTAL LANDINGS	1-DIST.	2-DIST.	3-DIST.		
NA									
DATE:	CERT. NO.:	PREV. A/C FLT. HRS.	FLT. HRS. THIS PAGE	TOTAL A/C FLT. HRS.					
GMT TIME:	AUTH. SIG.:								

DISC. OR MAINT. ACTION CARRIED FWD TO: BOOK CHANGED NEW LOG PAGE NO: CAPTAIN'S SIGNATURE

AIRC. MAINTENANCE LOG
02202-46 (2/99) Litho U.S.A.

EMIE
WORLDWIDE
A CTF COMPANY

09457-12

ACFT. NO.
N996GE

T. TYPE
C-8-71

LOG	FLT. DATE	STATION		GMT		BLOCK HOURS	GMT		FLT. HOURS	FUEL DATA			DE-ICE		CARGO DATA	
		FROM	TO	OUT	IN		OFF	ON		UPLIFT (USG)	DEPART (LBS)	ARRIVAL (LBS)	GAL'S	CARGO	MAIL	
1	10/25/00															
2																
3																
4																

NO FLT

LOG	DEPT. DELAY	CODE	TRAIN. FLTS.		OIL ADD				A/P	CREW	EMP #	T.O.	LDG	A/P	CREW	EMP #
			LDGS	STATION	1	2	3	4								
1																
2																
3																
4																

000 RTX ONLY

2930

NO.	SOURCE	DISCREPANCY	NO.	CORRECTIVE ACTION	DATE	STA	MECH
1.	P/M	HYD QTY IND DOES NOT GO TO "0" WHEN BKR IS PULLED	1.	R&R'D HYD QTY IND SYSTEM OPS CK GOOD ON GRD DWN DC-8 MH CA 29-30-00	10/25/00	KDAY	24504
2.	P/M		2.				
3.	P/M		3.				
4.	P/M		4.				
5.	P/M		5.				
6.	P/M		6.				

AIRWORTHINESS RELEASE				AIRCRAFT TIME / CYCLES				INS READOUT		
CHECK CW: Service	STATION: KDAY	PREVIOUS LANDINGS		LANDINGS THIS PAGE		TOTAL LANDINGS		1-DIST.	2-DIST.	3-DIST.
DATE: 10/26/00	CERT. NO. [REDACTED]	PREV. A/C FLT. HRS.		FLT. HRS. THIS PAGE		TOTAL A/C FLT. HRS.				
GMT TIME: 0730	AUTH. SIG. [REDACTED]	DISC. OR MAINT. ACTION CARRIED FWD TO:				BOOK CHANGED NEW LOG PAGE NO:		CAPTAIN'S SIGNATURE		

LOG PAGE DIST. 1. ORIGINAL WHITE - MAINTENANCE 2. WHITE COPY - OPS (SEND WITH TRIP ENVELOPE) 3. PINK COPY - RETAIN IN BINDER

A N

2.19.02 RRXA AMM, Chapter 12, Section V, JT3D-7 Power Plant Removal and Installation Form ME077, Paragraph G, I calls for checking the calibration of the exhaust gas temperature (EGT) indicating system using the Wheatstone Bridge as stated in the DC-8 MM, 77-20-0. EGT calibration check was accomplished on N950R, #2 and 3 engines on approximately 10/30/00 using an ohms meter. This is contrary to 14CFR 43.13(a) and 121.709(b)(2)(1).

RRXA RESPONSE: *The DC-8 Maintenance Manual 77-20-0, item two says that a Wheatstone Bridge or equivalent be used to test the exhaust gas temperature system. The test is to determine that a resistance value of 21.95 to 22.05 be obtained when the system is set up in the outlined configuration. The Fluke 87 ohms meter is capable of verifying that reading.*

RRXA CONCLUSION: *No finding.*



U. S. Department
of Transportation

Federal Aviation
Administration


FLIGHT STANDARDS DISTRICT OFFICE

4240 Airport Road
Cincinnati, Ohio 45226

513-533-8110

FAX 513-533-8420

cc: Jim Owens
Amy Sumner
Bob Hall



January 24, 2001

2,119,02 ✓

FILE NUMBER: 2001GL050041

Mr. Kent Scott
President
Emery Worldwide Airline Inc.
One Emery Plaza
Vandalia, Ohio 45377

Dear Mr. Scott:

The Great Lakes Regional RASIP Inspection performed October 16, 2000 through November 2, 2000 had the following finding which personnel of this office are investigating.

Emery Worldwide Airlines Inc. Certificate (RRXA) Aircraft Maintenance Manual (AMM), Chapter 12, Section V, JT3D-7 Power Plant Removal and Installation Form ME077, Paragraph G, I calls for checking the calibration of the exhaust gas temperature (EGT) indicating system using the Whetstone Bridge as stated in the DC-8 Maintenance Manual, 77-20-0. EGT calibration check was accomplished on N950R, #2 and #3 engines on approximately 10/30/00 using an ohmmeter.

Operations of this type are contrary to the Federal Aviation Regulations.

This is to inform you that this matter is under investigation by the Federal Aviation Administration. We wish to offer you an opportunity to discuss the matter personally or submit a written statement. If you desire to do either, this should be accomplished within 10 days following receipt of this letter. Your statement should contain all pertinent facts and any mitigating circumstances, which you believe may have a bearing on this matter. If we do not hear from you within the specified time, our report will be processed without the benefit of your statement.

Thank you for your attention to this matter.

Sincerely,

Harold R. Camden
Principal Maintenance Inspector

121.709 Airworthiness release or aircraft log entry.

(a) No certificate holder may operate an aircraft after maintenance, preventive maintenance or alterations are performed on the aircraft unless the certificate holder, or the person with whom the certificate holder arranges for the performance of the maintenance, preventive maintenance, or alterations, prepares or causes to be prepared -

- (1) An airworthiness release; or
- (2) An appropriate entry in the aircraft log.

(b) The airworthiness release or log entry required by paragraph (a) of this section must -

(1) Be prepared in accordance with the procedures set forth in the certificate holder's manual;

(2) Include a certification that -

(i) The work was performed in accordance with the requirements of the certificate holder's manual;

(ii) All items required to be inspected were inspected by an authorized person who determined that the work was satisfactorily completed;

(iii) No known condition exists that would make the airplane unairworthy; and

(iv) So far as the work performed is concerned, the aircraft is in condition for safe operation; and

(3) Be signed by an authorized certificated mechanic or repairman except that a certificated repairman may sign the release or entry only for the work for which he is employed and certificated.


2.19.02

43.13 Performance rules (general).

(a) Each person performing maintenance, alteration, or preventive maintenance on an aircraft, engine, propeller, or appliance shall use the methods, techniques, and practices prescribed in the current manufacturer's maintenance manual or Instructions for Continued Airworthiness prepared by its manufacturer, or other methods, techniques, and practices acceptable to the Administrator, except as noted in § 43.16. He shall use the tools, equipment, and test apparatus necessary to assure completion of the work in accordance with accepted industry practices. If special equipment or test apparatus is recommended by the manufacturer involved, he must use that equipment or apparatus or its equivalent acceptable to the Administrator.

(b) Each person maintaining or altering, or performing preventive maintenance, shall do that work in such a manner and use materials of such a quality, that the condition of the aircraft, airframe, aircraft engine, propeller, or appliance worked on will be at least equal to its original or properly altered condition (with regard to aerodynamic function, structural strength, resistance to vibration and deterioration, and other qualities affecting airworthiness).

(c) Special provisions for holders of air carrier operating certificates and operating certificates issued under the provisions of Part 121, 127 *{Part 127 was removed at Amdt. 127-45, 60 FR 65832, Dec. 20, 1995 - Ed.}*, or 135 and Part 129 operators holding operations specifications. Unless otherwise notified by the administrator, the methods, techniques, and practices contained in the maintenance manual or the maintenance part of the manual of the holder of an air carrier operating certificate or an operating certificate under Part 121, 127 *{Part 127 was removed at Amdt. 127-45, 60 FR 65832, Dec. 20, 1995 - Ed.}*, or 135 and Part 129 operators holding operations specifications (that is required by its operating specifications to provide a continuous airworthiness maintenance and inspection program) constitute acceptable means of compliance with this section.



2.19.03 On 11/01/00, a spot inspection on aircraft N8087U revealed a contractor performing fuel tank leak repairs without the proper maintenance manual references for repairs performed.

RRXA RESPONSE:

The following actions are performed upon arrival of all fuel tank teams.

- 1. Coordination with the EWA Supervisors and the Tank Team to explain the nature of the discrepancies.*
- 2. The Tank Team is given confined space entry paperwork.*
- 3. Required manuals are distributed to the Tank Team and they are instructed where required materials are located.*

Procedures will be changed and published in the EWA MP&P rewrite that will provide oversight by EWA Maintenance Supervision of work performed by contract maintenance See attached..

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
04 September 2001*

MP&P Revision

ADD CHAPTER 3-01-3, B. 4

When substantial maintenance is performed, at EWA Line Stations, by outside vendor, EWA will provide the following oversight of the maintenance being accomplished.

EWA will assign a Line Maintenance Mechanic or Supervisor to the contract maintenance team to provide the following support and oversight.

1. Provide and in-briefing detailing the work that is to be performed, provide applicable maintenance manual references, and instruct the team as to the location of materials necessary to perform the required functions.
2. Provide supervision of the work being performed and the use of proper maintenance procedures and manuals.
3. Provide EWA policies and procedures, including documentation, to the vendor. Ensure that all maintenance performed is properly documented using EWA approved procedures.

3-01-3 ADD B. 4.

2.19.03 On 11/01/00, a spot inspection on aircraft N8087U revealed a contractor performing fuel tank leak repairs without the proper maintenance manual references for repairs performed.

RRXA RESPONSE:

The following actions are performed upon arrival of all fuel tank teams.

1. Coordination with the EWA Supervisors and the Tank Team to explain the nature of the discrepancies.
2. The Tank Team is given confined space entry paperwork.
3. Required manuals are distributed to the Tank Team and they are instructed where required materials are located.

RRXA CONCLUSION: No finding

Jim Owens
EWA Director-Quality Assurance
21 February 2001

MPTP CHAP 4, P 41

EWA MNTC Supervisor over outside
overweight
Vendor + Counter-sign work.

- 1. CONTRACTOR WITH OWN PAPERWORK? WE WILL ACCEPT?
- 2. MANUAL
- 3. MNTC SUPV.

OPEN

B

Owens, James H

From: Northup, Robert J

Sent: Friday, February 09, 2001 2:02 PM

To: Owens, James H


Subject: RACIP 2.19.03

Jim, RACIP finding 2.19.03 indicates that a spot inspection on aircraft N8087U revealed a contractor performing fuel tank leak repairs without the proper maintenance manual references for repairs performed.

The following actions are performed upon arrival of all fuel tank teams.

- Coordination with the Supervisors to give an explanation of the discrepancy.
- They are given confined space entry paperwork.
- They are debriefed on the facility rules.
- Distribution of all required maintenance manuals required and shown where to get required material.

Rob Northup
Manager
Hub Line Maintenance



Rev

2.19.03 On 11/01/00, a spot inspection on aircraft N8087U revealed a contractor performing fuel tank leak repairs without the proper maintenance manual references for repairs performed.

RRXA RESPONSE:

The following actions are performed upon arrival of all fuel tank teams.

- 1. Coordination with the EWA Supervisors and the Tank Team to explain the nature of the discrepancies.*
- 2. The Tank Team is given confined space entry paperwork.*
- 3. Required manuals are distributed to the Tank Team and they are instructed where required materials are located.*

Procedures will be changed and published in the EWA MP&P rewrite that will provide oversight by EWA Maintenance Supervision of work performed by contract maintenance.

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

2.19.03 On 11/01/00, a spot inspection on aircraft N8087U revealed a contractor performing fuel tank leak repairs without the proper maintenance manual references for repairs performed.

RRXA RESPONSE: *The following actions are performed upon arrival of all fuel tank teams.*

- 1. Coordination with the EWA Supervisors and the Tank Team to explain the nature of the discrepancies.*
- 2. The Tank Team is given confined space entry paperwork.*
- 3. Required manuals are distributed to the Tank Team and they are instructed where required materials are located.*

RRXA CONCLUSION: *No finding*

*Jim Owens
EWA Director-Quality Assurance
21 February 2001*

NEED MPP REVISION CH4, P41

EWA MAINTENANCE WILL PROVIDE OVERSIGHT OF WORK PERFORMED BY CONTRACT VENDORS.

