


Engine Investigation

Rolls-Royce Corporation Model 250-C30 Engine CAE 900098

MD 369FF

Registration: N530RL



Pima County Sheriff's Department Tucson, Arizona

David W. Riser

David W. Riser Air Safety Investigator

Accident date: January 31, 2011 Investigation date: February 3-7, 2011 Report date: February 25, 2011 Pima County Arizona Sheriff's Department, N530RL, M250-C30, S/N CAE 900098 --- January 31, 2011

Report Enclosures:

Report Narrative

Appendix A, Photographs at Air Transport, Phoenix, Arizona

Appendix B, Engine Run Data

Appendix C, Engine Records

Background Information:

On January 31, 2011 at approximately 11:19 am local time, an MD 369FF helicopter, N530RL was involved in an accident. The helicopter was owned and operated by the Pima County Arizona Sheriff's Department. The weather conditions were reported to be VFR with an approximate temperature of 50 F. The helicopter was operating in mountainous terrain at an elevation of approximately 3550 feet MSL on a survey mission for tower locations. The helicopter was in the process of a pinnacle landing, when for unknown reasons the helicopter crashed. The helicopter was occupied by the pilot, a right front seat passenger and two rear seat passengers. The pilot sustained fatal injuries. The right front seat passenger sustained serious injuries. The left rear passenger sustained minor injuries and the right rear seat passenger was uninjured.

Airframe observations:

The author did not view the wreckage on site but was shown and provided photos of the accident scene. The author did examine the wreckage at the recovery location in Phoenix, Arizona. The airframe had received extensive overall crush damage resultant from rolling downhill with the most prevalent damage appearing on the nose of the aircraft in front of the left front seat position. Both left and right landing skids had been torn from the airframe. (Fig 1) All five main rotor blades had separated from the rotor head at or near the blade roots. Fractures were noted at each grip on the main rotor head with tearing and separation of the blades strap packs. (Fig 2) The tail boom had separated just forward of the vertical stabilizer with the tail rotor gear box remaining attached the tail boom. Both tail rotor blades exhibited rotational impact damage but remained attached to the gearbox. (Fig 3) The tail rotor drive shaft separated in overload forward of the tail rotor gearbox with circumferential scoring noted at various locations along the shafts length. (Fig 4)

Engine Observations:

An Allison Engine Company M250-C30 gas turbine engine, S/N CAE 900098, powered the helicopter. Initial inspection revealed the engine to have remained securely attached to the airframe. All mounting arms remained in position and exhibited no visible damage. (Fig 5) An Intec inlet barrier filter was incorporated in this application. (Fig 6) Upon removal of the engine from the airframe, the compressor module and turbine module were in position and exhibited no visible damage. (Fig 7) The accessory gearbox and exhaust collector support were also in position and displayed no visible damage. (Fig 8) The outer combustion case exhibited crush damage on the right shoulder area with additional denting to the dome area from the exhaust stack being forced down and into the dome. The right side compressor air discharge tube exhibited impact damage on the outboard side mid length with additional crush damage at and just forward of the outer combustion case mounting flange. (Fig 9) Engine accessories consisting of the fuel pump, compressor bleed

valve, fuel control unit, power turbine governor and fuel nozzle were all in position and displayed no visible damage. (Fig 10) Manual operation of the fuel control throttle arm and the power turbine governor arm resulted in smooth operation from stop to stop.

Engine Information:

The engine was installed on the accident airframe November 14, 2006 with 3478.4 hours engine TT. No recent major maintenance or component change was reflected in engine log books.

Manufacturer Allison Engine Company

Engine Model 250-C30

Rating: 650 Shaft Horsepower

Serial Number CAE900098

Engine Total Hours 3991.0

Last 150-Hour Inspection April 13, 2010 @ 3881.9 engine TT

Component	Serial Number	Part Number	TSO	Total Time
Engine	CAE900098	23009300	3991.0	
Gearbox	CAG90067S	23035179	512.6	3951.0
Compressor	CAC91258	23033193	512.6	3991.0
Turbine	CAT90677	23033195	512.6	5709.1
Fuel Control	330294	23065125	1323.1	Unknown
Governor	30424	23065125	512.6	Unknown
Fuel Pump	T300126	6896810	1848.0	Unknown
Fuel Nozzle	AG42359	23077188	512.6	Unknown
Bleed Valve	FF34550	23073359	580.1	Unknown

^{*} All engine and component times were compiled from engine log and status sheet entries.

Engine Investigation:

On February 7, 2011 operational testing and power check of the engine was conducted at AeroMaritime, Mesa, Arizona in accordance with Rolls-Royce M250-C30 overhaul manual. Prior to the test the outer combustion case and the right side compressor air discharge tube were replaced with serviceable OEM parts for testing due to accident damage. (Fig 11) Examination at removal of both air discharge tubes and the outer combustion prior to installation of serviceable OEM parts revealed all components to have been properly positioned and secure. Visual examination into the compressor inlet revealed light scoring at the inducer in the impeller blade path of an approximate

90 degree arc between 3 and 6 o'clock positions, aft looking forward. (Fig 12) Examination of the combustor liner revealed it to be serviceable with no unusual burn patterns or streaking. External examination of the fuel nozzle revealed it to be serviceable with no excessive carbon on outer air shroud. A visual examination into the N1 turbine section through the number 1 turbine nozzle revealed no damage or anomalies. (Fig 13) The engine was then examined thoroughly with no discrepancies noted which would preclude the engine run. The engine was then placed into the test cell where it was motored and with a positive indication of oil pressure the engine started within both time and temperature specifications. During engine warm up at ground idle, vibration scans revealed all components to be within specification. A five point power calibration check was then conducted during which the engine met or exceeded specification at each point. A governor droop check was then conducted where the power turbine governor responded normally and within specification. The engine was then shut down normally with no discrepancies noted.

Summary of Findings:

During operational and performance testing, this engine was found to meet or exceed specification in both horsepower production and specific fuel consumption in accordance with the Rolls-Royce M250-C30 overhaul manual.

Appendix A, Photographs at recovery Location



Tai rotor with gear box / tail rotor drive shaft

Tail rotor components (Return)



Tail rotor drive shaft separation



Tail rotor drive shaft scoring



Inlet barrier filter (Return)





Exhaust collector support and accessory gear box (Return)



Outer combustion case / right side compressor air discharge tube



Compressor inlet

(Return)




Scoring at tip path


Appendix B, Engine Run Data

Engine Model	250-C30	Compressor SN	CAC-91258	Accel: X					Cruise C	Cruise B	Cruise A	Normal Cruise Max C	ont 2	½ Min	
Manufacturer	Rolls Royce	Gearbox SN	CAG-900675	BV Chk: OK			SPEC GPTOT		0				1368	1424	
Serial Number	CAE-900098	Turbine SN	CAT-90677	Al Chk: OK			PRED SHP @	SPEC MGT	0				672	724	
Vork Order	W318394	Fuel Control SN	330294	Preserved: OK			SPEC SHAFT		334				650	700	
Intry Date	2/7/2011	Governor SN	30424	Comment OK				M SPEC PWR	0.0				3.3	3.5	
Customer	Rolls-Royce	Fuel Temp	72	# Starts: 1			Predicted SFO		0.700				0.572	0,567	
Operator : Andrew Wong		SG at Fuel Temp		Coastdn:			SPEC SFC		0.719				0.592	0.588	
Assistant : Charlie Hall		LHV (BTU/LB)	18280	Orifice: AR			% DELTA FRO	M SDEC SEC	-2.7				-3.3	-3.6	
Run Number	4	Engine TT	N/K	Office, Art			1% DELIA FAC	INI SPEC SPC	-4.1	70.0	-2.4	1 0.41	-0.0	-0.0	10
Oil Flow in CCs		Linguis II	INIC												
Run Comments	Eunctional tas	t of engine plus five	nointe for nous												
late	i unicuonal tes	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	2/7/2011	_		
ime		1:22:43 PM	1:35:09 PM	1:38:03 PM	1:40:30 PM	1:42:59 PM	1:45:37 PM	1:48:33 PM	1:51:28 PM	1:52:06 PM		2:12:16 PM			
Settina		Ground idle	Seal Run In												
	111111111111111111111111111111111111111					3rd Power Poir				Anti ice On		Idle Before Shutdown			
lun Time	HH:MM:SS	00:03:40	00:16:06	00:19:00	00:21:28	00:23:56	00:26:34	00:29:30	00:32:25	00:33:03	00:33:58	00:53:13			
1 RPM	RPM	33342													
I1 PCT	%	65.4													
I1 RPM Corrected	RPM		91001				- 100	The second secon	A CONTRACTOR	1111111111					
I2 RPM	RPM	21049													
12 PCT	96	68.7	1000			0.0000									
Dyno Torque	FT-LBS	38.0				117777									
lyno Out Temp	°F	62.0	10000	100.0	107.0	113.0	119.0	123.0	116.0	116.0					
yno RPM	RPM	4141	6018	6019	6018	6018	6018	6018	6018	6018	6250	4320			
lyno HP	HP	29.9	664.5	458.8	516.1	567.5	613.8	660.2	543.9	540.8	153.1	29.5			
Ingine Torquemeter	PSIG	6.8	94.3	65.5	73.6	80.8	87.2	93.6	77.3	76.8	21.6	5.8			
IP Corrected	HP	0.0	688.6	473.6	533.1	587.2	636.2	684.6	561.9	559.1	230.4	230.4			
uel Temp	°F	72.0	62.0	63.0	63.0	62.0			63.0	63.0	64.0	68.0			
Vf Observed	PPH	103.1													
Vf Corrected	PPH	0.0		57777					1,000,000	A 10 M 10 M 10 M					
FC Corrected	LBS/HP/HR	0.0000							2.57.117						
IP .	" HGA	28.70													
xhaust Static Prs	" HGA	28.68													
aro	* HGA	28.70				Contract Con	2000								
TI	oF.	70.7													
DT	°F	317.5													
OP	* Hg	48.6						The second secon							
SPTOT	eF e	985							100000						
SPTOT Corrected	°F	980					1,000		2.0						
fain Oil Pressure		120.0				1.000	100								
	psig	1000000				1,100,000				5					
cavenge Oil Pressure	psig	24.0					-								
Oil In Temp		115.0	575555												
Oil Out Temp	°F	137													
Bear Box ST Prs	* H2O	5.30					20000								
Compressor Vibration	IPS	0.17													
Searbox Vibration	IPS	0.08	The second secon		100000		10000								
urbine Vibration	IPS	0.08													
ccel/ Decel Time	Seconds	0.0	201	0.0	0.0	0.0	0.0	0.0	0.0	0.0					
nti Ice Line	°F	80.0	112.0	111.0	112.0	115.0	119.0	118.0	119.0	208.0	215.0	105.0			
Comp Seal Vent Press	" Hg	5.1	25.9	17.8	19.0	19.8	20.0	20.0	17.3	17.3	8.2	2.4			
Airflow Corrected	PPM	0.00	5.78	5.22	5.38	5.56	5.67	5.80	5.50	5.41	3.84	3.84			
Comments 1		8.75			1		0.01				-				
Comments 2															
Comments 3															





AeroMaritime America Inc. Repair Station #XZNR915L



AeroMaritime America Inc. Repair Station #XZNR915L