




# Continental Motors

## ENGINE EXAMINATION REPORT LEFT

ENGINE MODEL	TSIO520EB (8B)
ENGINE SERIAL NUMBER	271215-R
AIRCRAFT MAKE & MODEL	Cessna 335
AIRCRAFT SERIAL NUMBER	335-0023
AIRCRAFT REGISTRATION	N2707J
FILE NUMBER	18-174

NAME	SIGNATURE	DATE
Mike Council		1-2-2019

**ENGINE EXAMINATION REPORT****FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 2 of 20****GENERAL INFORMATION**

<b>EXAMINATION</b>		<b>ACCIDENT DATA</b>	
<b>DATE</b>	9-10-2018 On-Site 9-11-2018 Recovery	<b>NTSB ACCIDENT #</b>	ERA18FA244
<b>FACILITY</b>	Florida Air Recovery	<b>NTSB INVESTIGATOR</b>	Doug Brazy
<b>ADDRESS</b>	Fort Pierce, FL	<b>FAA INVESTIGATOR</b>	NA
		<b>ACCIDENT DATE</b>	9-9-2018
		<b>ACCIDENT LOCATION</b>	Lake Worth, FL

**ENGINE INFORMATION**

<b>ENGINE POSITION</b>	Left
<b>TOTAL TIME</b>	1808.9 at last 100-hour inspection dated 7-23-2018
<b>TIME SOH</b>	NA
<b>TYPE &amp; TIME SLI</b>	Undetermined. No recording tach or hobbs was located in the wreckage
<b>BUILD DATE</b>	9-6-1992
<b>IN SERVICE DATE</b>	9-18-1992

# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 3 of 20

## Significant logbook information:

September 3, 2014 South Florida Aircraft Maintenance, LLC

N2707J  
Twin Cessna

MM-CE-335 U  
AC SR-325-0823

Left Engine  
Engine Model No.: TCM TS10-320-EB (8) Hobbs: 865.4  
Engine S/N: 271215-R TTSMOH: 865.4 AF Total Time: 3 160.4

Left Engine Log Book Entry:

Removed three cylinders from port side of engine, cylinders #1, #3, & #5. All 3 cylinders overhauled by Tropic Airpower, Inc WO # T3451, CRS# T7KR187Y and re-installed by BFAM co. WO # 14-2606 101. Performed oil and filter change. Replaced filter with new Champion 48109-1 oil filter, safety wire in place with 0.031" wire. Serviced engine with 12 quarts of Astroshell 100 (SAE 50) mineral oil.

Run up left engine after cylinder change to temperature, no oil leaks observed, left engine and left propeller performed satisfactorily. Initial oil pressure 60 psig. When hot 50 psig.

All work was accomplished in accordance with the appropriate sections of FAA AC 43.13-1B, & 2B and TCM X30575 (12-2012) engine overhaul manual with respect to the work performed above.

This engine is approved for return to service with respect to the work performed.

David James Fogarty A&P

**NOTE:** The total time on this engine at this maintenance event was 1763.50 hours. The hobbs meter was replaced with zero-time unit 9-12-2002 with instructions to add 868.1 to hobbs for actual left engine time since factory rebuilt.

## Report Summary:

Search Code(s):

Examination of this engine was performed by the CMI Investigator under supervision of the NTSB Investigator. The inspection of this engine did not reveal any pre-impact anomalies that would have prevented its ability to produce rated horsepower.

## Disposition of engine following exam:

The engine will remain in the care, custody and control of Florida Air Recovery until released by the NTSB IIC.



**ENGINE EXAMINATION REPORT****FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 4 of 20****INSPECTION WITNESSES**

<b>NAME</b>	Mike Council	<b>NAME</b>	Doug Brazy, IIC
<b>ADDRESS</b>	2039 South Broad Street Mobile, Alabama	<b>ADDRESS</b>	Eastern Region
<b>ORGANIZATION</b>	Continental Motors	<b>ORGANIZATION</b>	NTSB
<b>PHONE</b>	2 [REDACTED]	<b>PHONE</b>	[REDACTED]
<b>NAME</b>	Andrew Hall	<b>NAME</b>	NA
<b>ADDRESS</b>	Wichita, KS	<b>ADDRESS</b>	
<b>ORGANIZATION</b>	Textron Aviation	<b>ORGANIZATION</b>	
<b>PHONE</b>	[REDACTED]	<b>PHONE</b>	

**EXTERNAL INSPECTION OF ENGINE**

The left engine exhibited impact and thermal damage. The propeller separated on impact by breaking the propeller attachment bolts. The engine crankshaft propeller flange remained intact.





# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 5 of 20



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 6 of 20**

**ENGINE AND COMPONENT EXAMINATION**

**EXHAUST  
SYSTEM**

**Condition:** The exhaust components were impact damaged.



**INDUCTION  
SYSTEM**

**Condition:** The induction components were impact damaged including broken intake elbows, hoses and balance tube crushed.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 7 of 20**

**IGNITION SYSTEM**

<b>LEFT MAGNETO</b>	Manufacturer: Bendix	P/N: 10-163-020-3	S/N:640654
Condition:	The left magneto produced sparks at all ignition leads when the magneto was manually rotated using a drill motor.		



<b>RIGHT MAGNETO</b>	Manufacturer: Bendix	P/N: 10-163060-1	S/N: 801229
Condition:	The right magneto produced sparks at all ignition leads when the magneto was manually rotated using a drill motor.		





# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 8 of 20

## SPARK PLUGS

Manufacturer: Undetermined

P/N: Undetermined

### Condition:

The top sparkplugs were removed and inspected. When compared to a Champion "Check-A-Plug" chart, all six top sparkplugs appeared to be "Normal" in both wear condition and coloration. The sparkplugs had been painted black and the manufacturer's name and part number were unreadable. The sparkplugs featured three massive electrodes instead of the usual two or a single fine-wire type electrode.





**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 9 of 20**

**FUEL SYSTEM**

**FUEL PUMP**

Manufacturer: TCM

P/N: 646201-11

S/N: H2192-56

Condition:

The fuel pump was rotated manually, and no fuel was expelled. The pump input shaft was thermally damaged and the pump impeller blades were intact. The unmetered fuel adjustment screw was impact damaged. The fuel pump case at the bellows assembly was broken.



ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 10 of 20





# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 11 of 20

## THROTTLE BODY METERING UNIT

Manufacturer: TCM

P/N: 1032916-8

S/N: 4219216AR

### Condition:

The fuel metering unit was intact but exhibited thermal damage. The control cable was attached properly, and the fastener was tight on the shaft. The fuel screen was not secured with safety wire as required. The fuel screen was removed and was damaged during the removal process. The solder from the assembly of the screen melted attaching the mesh to the throttle body housing. The screen appeared to be uncontaminated.





**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 12 of 20**

**FUEL MANIFOLD VALVE**

Manufacturer: TCM

P/N: 634632-10A7

S/N: 11209214CR

**Condition:**

The assembly screws were correctly secured with safety wire and a lead seal was intact. The assembly screws were removed, and the spring and diaphragm were intact. The fuel screen was uncontaminated, but the manifold cavity contained a small amount of unidentified debris. The debris was attracted to a test magnet.





ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 13 of 20



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 14 of 20**

**LUBRICATION SYSTEM**

**OIL SUMP**

**Condition:** The oil sump was impact damaged due to contact with the ground.

**OIL FILTER**

**Manufacturer:** Undetermined

**P/N:** Undetermined

**Condition:** The exterior of the filter exhibited thermal distress and was correctly secured with safety wire. The paper filter media was thermally damaged inside the canister where exposed to the post impact fire. The less damaged filter media was cut from the assembly and examined. No contamination was noted.





# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 15 of 20

OIL COOLER

Manufacturer: Undetermined

P/N: Undetermined

S/N: Undetermined

Condition:

No data plate was attached to the oil cooler. The oil cooler was intact with thermal distress to the lower portion where it had been exposed to the post impact fire.



## ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 16 of 20

### CYLINDERS

An engine maintenance logbook entry dated 9-3-2014 indicated that cylinders 1, 3, and 5 had been removed, overhauled and reinstalled. See "*Significant logbook Information*" entry on page 3 of this report.

All six cylinders produced thumb compression when the engine was manually rotated. The cylinder rocker covers were removed, and all rocker arms were observed to move normally when the engine was rotated. Camshaft, valve train and crankshaft continuity were confirmed.

A lighted electronic borescope examination was performed on each cylinder. Piston domes exhibited normal combustion signatures. All intake and exhaust valves exhibited normal combustion patterns and were intact.





## ENGINE EXAMINATION REPORT

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	271215-R	<b>PAGE 17 of 20</b>
---------------------	--------	--------------------	----------	----------------------

### CRANKCASE ASSEMBLY

<b>CRANKCASE</b>	Casting Number:	1-3-5: Undetermined	2-4-6: Undetermined	S/N: Undetermined
Condition:	The crankcase exhibited impact damage on the lower portion of the left and right casting. The lower portion of the crankcase assembly was thermally damaged.			

### ACCESSORIES

<b>STARTER</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
Condition:	The starter motor separated from the starter adapter was not presented for inspection.		
<b>STARTER ADAPTER</b>	P/N: Undetermined		
Condition:	The starter adapter was thermally damaged. The starter motor separated and the starter mount was broken. The oil scavenge pump remained intact and attached to the starter adapter.		





**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	271215-R	<b>PAGE 18 of 20</b>
---------------------	--------	--------------------	----------	----------------------

<b>ALT/GEN #1</b>	Manufacturer: TCM	P/N: 649304	S/N: L129403
Condition:	The engine driven alternator received impact damage.		



<b>VACUUM PUMP</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
Condition:	The data label was thermally destroyed. The pump was disassembled and inspected. Impeller blades were intact. Drive shaft was intact.		

<b>TURBO</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
Condition:	The turbocharger was exposed to the post impact fire. The compressor and turbine wheels were free to rotate.		





# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

271215-R

PAGE 19 of 20

## PROPELLER

<b>PROPELLER</b>	Manufacturer: McCauley	P/N: Undetermined	S/N: 650681
Blade 1 S/N:	Undetermined		
Blade 2 S/N:	Undetermined		
Blade 3 S/N:	Undetermined		
Condition:	The propeller hub and spinner received impact damage. The propeller blades were relatively straight without cordwise scratching or gouging. Blade C exhibited paint transfer from contact with the ground.		



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

271215-R

**PAGE 20 of 20**








# Continental Motors

## ENGINE EXAMINATION REPORT RIGHT

ENGINE MODEL	TSIO-520EB (9A)
ENGINE SERIAL NUMBER	510540
AIRCRAFT MAKE & MODEL	Cessna 335
AIRCRAFT SERIAL NUMBER	335-0023
AIRCRAFT REGISTRATION	N2707J
FILE NUMBER	18-174

NAME	SIGNATURE	DATE
Mike Council		2-3-2019

**ENGINE EXAMINATION REPORT****FILE NUMBER:**

18-174

**ENGINE S/N:**

510540

**PAGE 2 of 22****GENERAL INFORMATION**

<b>EXAMINATION</b>		<b>ACCIDENT DATA</b>	
<b>DATE</b>	9-10-2018 On-Site 9-11-2018 Recovery	<b>NTSB ACCIDENT #</b>	ERA18FA244
<b>FACILITY</b>	Florida Air Recovery	<b>NTSB INVESTIGATOR</b>	Doug Brazy
<b>ADDRESS</b>	Fort Pierce, FL	<b>FAA INVESTIGATOR</b>	NA
		<b>ACCIDENT DATE</b>	9-9-2018
		<b>ACCIDENT LOCATION</b>	Lake Worth, FL

**ENGINE INFORMATION**

<b>ENGINE POSITION</b>	Right
<b>TOTAL TIME</b>	3215.9
<b>TIME SOH</b>	1809.9 according last 100-hour inspection dated 7-23-2018
<b>TYPE &amp; TIME SLI</b>	Annual Inspection dated 7-23-2018 at (tach) time 9784.1
<b>BUILD DATE</b>	8-27-1979
<b>IN SERVICE DATE</b>	Engine was overhauled 11-2-1992 and installed on N27074 same date. This engine only accumulated 288.7 hours between 11-2-1992 and 11-4-1998. No logbooks are available between those dates.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

510540

**PAGE 3 of 22**

**Significant logbook information:**

*Note: Subtract 6.0 From A/C Hobbs For ENG TSO*

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
11/2/92	1406	0	6.0	TOTALS brought forward from previous page
				Engine overhauled, New Camshaft, PISTONS, PINS, All cylinders Cermichrome by ECI, New Valves, Lifters, installed; Case, Crankshaft, Connecting Rods O/A by ECI
				New AeroPump hoses & Fire Sleeves, New oil Pump Gears, Overhauled Turbo, Turbo Controller, Waste Gate, Prop Gear, Starter adapter
				(Complied w/AD 89-24-01-R1) & installed New SCAV Pump Gears), oil Cooler O/A # X-109c/w
				SB M92-14 N/A BY PN# 636900, New engine mounts & Hduw installed, O/A Magnets & Seal Seals, New wiring harnesses (Plugs)
				O/A Alternator, O/A Condenser Fuel System, Calibrated <u>All</u> Engine Instruments
				Installed Engine on AEF N2709J and Ran I/O/w SB 89-7
				[Redacted] IA
				Entered BY: [Redacted] AEP
				SEE #1 LOG For Entries Between 11/98 and 11/98

**Report Summary:**

Search Code(s):

Examination of this engine was performed by the CMI Investigator under supervision of the NTSB Investigator. The inspection of this engine did not reveal any pre-impact anomalies that would have prevented its ability to produce rated horsepower.

**Disposition of engine following exam:**

The engine will remain in the care, custody and control of Florida Air Recovery until released by the NTSB IIC.

**ENGINE EXAMINATION REPORT****FILE NUMBER:**

18-174

**ENGINE S/N:**

510540

**PAGE 4 of 22****INSPECTION WITNESSES**

<b>NAME</b>	Mike Council	<b>NAME</b>	Doug Brazy, IIC
<b>ADDRESS</b>	2039 South Broad Street Mobile, Alabama	<b>ADDRESS</b>	Eastern Region
<b>ORGANIZATION</b>	Continental Motors	<b>ORGANIZATION</b>	NTSB
<b>PHONE</b>	██████████	<b>PHONE</b>	██████████
<b>NAME</b>	Andrew Hall	<b>NAME</b>	NA
<b>ADDRESS</b>	Wichita, KS	<b>ADDRESS</b>	
<b>ORGANIZATION</b>	Textron Aviation	<b>ORGANIZATION</b>	
<b>PHONE</b>	██████████	<b>PHONE</b>	



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 5 of 22

## EXTERNAL INSPECTION OF ENGINE

The right engine exhibited impact and thermal damage. The damaged propeller assembly was removed, and the crankshaft propeller flange was impact damaged with a portion of the flange separated. Cylinder # 5 exhibited impact and thermal damage.



**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

510540

**PAGE 6 of 22**

**ENGINE AND COMPONENT EXAMINATION**

**EXHAUST SYSTEM**

**Condition:** The exhaust components were impact damaged with upward crushing due to impact forces.



**INDUCTION SYSTEM**

**Condition:** The induction components were impact damaged including broken intake elbows, hoses and balance tube crushed.



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 7 of 22

## IGNITION SYSTEM

### LEFT MAGNETO

Manufacturer: Bendix  
Overhauled by Quality  
Aircraft Accessories, Inc.

P/N: 10-163020-3

S/N: 8035069

Condition:

The left magneto did not produce sparks when manually rotated. The left magneto was disassembled and inspected. Both sets of points operated normally, and the capacitor and wiring were intact. The plastic drive gears were intact. No internal thermal damage was noted and the reason for this magneto not producing spark normally was not determined.



# ENGINE EXAMINATION REPORT

FILE NUMBER:	18-174	ENGINE S/N:	510540	PAGE 8 of 22
--------------	--------	-------------	--------	--------------

<b>RIGHT MAGNETO</b>	Manufacturer: Bendix	P/N: 10-163020-3	S/N: 8035069
----------------------	----------------------	------------------	--------------

Condition: The right magneto produced sparks at all ignition leads when the magneto was manually rotated using a drill motor.





**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	510540	<b>PAGE 9 of 22</b>
---------------------	--------	--------------------	--------	---------------------

<b>IGNITION HARNESS</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
-------------------------	----------------------------	-------------------	-------------------

Condition: The ignition harness exhibited thermal distress near both of the magneto terminal attachments. Several individual leads were cut/pinched by impact forces.



# ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 10 of 22

## SPARK PLUGS

Manufacturer: Undetermined

P/N: Undetermined

### Condition:

When compared to a Champion "Check-A-Plug" chart, all six top sparkplugs appeared to be "Normal" in both wear condition and coloration. The sparkplugs had been painted black and the manufacturer's name and part number were unreadable. The sparkplugs featured three massive electrodes instead of the usual two or a single fine-wire type electrode.





ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 11 of 22

FUEL SYSTEM

FUEL PUMP

Manufacturer: TCM

P/N: 632818-11

S/N: J138107RB

Condition:

The engine driven fuel pump exhibited thermal and impact damage. The lower portion of the pump was dark and the surfaces sooty from a post-impact fire. The unmetered fuel pressure adjustment bolt and lock nut received impact damage. The drive coupler was broken, and a sharp edge was evident around the circumference of the separated shaft. The broken area was concave/convex in shape. The broken portion of the drive coupler was removed, and the impeller shaft rotated smoothly when manually manipulated. A minute amount of fuel leaked from the pump cavity when the pump was disassembled. The pump shaft and impeller blades were intact. The outer mounting flange was partially broken. Fuel fittings were broken and remained with the thermally damaged flexible fuel hoses. The fuel pump and drive coupling will be examined at CMI at a later date and a metallurgical report prepared.





ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 12 of 22





ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 13 of 22





**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	510540	<b>PAGE 14 of 22</b>
---------------------	--------	--------------------	--------	----------------------

<b>FUEL MANIFOLD VALVE</b>	Manufacturer: TCM	P/N: 634326-1	S/N: ?127932C
----------------------------	-------------------	---------------	---------------

**Condition:** The assembly screws were correctly secured with safety wire and a lead seal was intact. The spring and diaphragm were intact. The fuel screen was uncontaminated, and the pump cavity was clean. No fuel was present in the valve cavity.





**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

510540

**PAGE 15 of 22**



**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	510540	<b>PAGE 16 of 22</b>
---------------------	--------	--------------------	--------	----------------------

**LUBRICATION SYSTEM**

<b>OIL FILTER</b>	Manufacturer: Tempest	P/N: AA48109
Condition:	The canister exterior was thermally damaged.	



<b>OIL COOLER</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
Condition:	The data tag was thermally damaged and part number/serial number unreadable. The oil cooler remained intact		





## ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 17 of 22

### CYLINDERS

All six cylinders produced thumb compression when the engine was manually rotated. The cylinder rocker covers were removed, and all rocker arms were found to move normally when the engine was rotated except cylinder 5. Cylinder 5 rocker cover was impact damage and the lower portion of the cover separated. The push rod (intake valve) was damaged and curled over. The lower portion of the intake valve rocker arm separated. Camshaft, valve train and crankshaft continuity was confirmed.

A lighted electronic borescope examination was performed on each cylinder. Piston domes exhibited normal combustion signatures. All intake and exhaust valves exhibited normal combustion patterns and were intact.





**ENGINE EXAMINATION REPORT**

**FILE NUMBER:**

18-174

**ENGINE S/N:**

510540

**PAGE 18 of 22**

**ROCKER ARMS  
AND SHAFTS**

**Condition:**

All rocker arms, springs and pushrods operated normally when the engine was manually rotated except # 5 which exhibited impact damage.





**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	510540	<b>PAGE 19 of 22</b>
---------------------	--------	--------------------	--------	----------------------

**CRANKCASE ASSEMBLY**

<b>CRANKCASE</b>	Casting Number:	1-3-5: Undetermined	2-4-6: Undetermined	S/N: Undetermined
Condition:	The crankcase halves were impact damaged on the lower front portion. Engine mounts were broken.			

**CRANKSHAFT ASSEMBLY**

<b>CRANKSHAFT</b>	Forging Number: Undetermined	S/N: Undetermined	Heat code: Undetermined
Condition:	The forward portion of the crankshaft including the propeller flange was impact damaged.		



**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	510540	<b>PAGE 20 of 22</b>
---------------------	--------	--------------------	--------	----------------------

**ACCESSORIES**

<b>ALT/GEN #1</b>	Manufacturer: TCM	P/N: 642056	S/N: E090358-539
-------------------	-------------------	-------------	------------------

Condition: The alternator remained attached but exhibited thermal damage.



<b>VACUUM PUMP</b>	Manufacturer: NA	P/N: NA	S/N: NA
--------------------	------------------	---------	---------

Condition: No vacuum pump was installed on the RIGHT engine

<b>TURBO</b>	Manufacturer: Undetermined	P/N: Undetermined	S/N: Undetermined
--------------	----------------------------	-------------------	-------------------

Condition: The turbine wheel was free to rotate in the housing.





**ENGINE EXAMINATION REPORT**

<b>FILE NUMBER:</b>	18-174	<b>ENGINE S/N:</b>	510540	<b>PAGE 21 of 22</b>
---------------------	--------	--------------------	--------	----------------------

**PROPELLER**

<b>PROPELLER GOVERNOR</b>	Manufacturer: Overhauled by H&H Propeller Services	P/N: Undetermined	S/N: Undetermined
Condition:	The pitch change arm and shaft separated due to impact forces. The control cable was properly attached and secured.		



<b>PROPELLER</b>	Manufacturer: McCauley	M/N:3AF32087-N2R	S/N: Undetermined
Blade 1 S/N:	Undetermined		
Blade 2 S/N:	Undetermined		
Blade 3 S/N:	Undetermined		
Condition:	All three propeller blades exhibited s-bending, paint transfer and cordwise scratching/gouging. All three blades were loose inside the hub due to impact forces.		

ENGINE EXAMINATION REPORT

FILE NUMBER:

18-174

ENGINE S/N:

510540

PAGE 22 of 22

