




Continental Motors

ENGINE RUN REPORT

| | |
|----------------------------------|--------------|
| ENGINE MODEL | TSIO520R |
| ENGINE SERIAL NUMBER | 294045-R |
| AIRCRAFT MAKE & MODEL | Cessna T210M |
| AIRCRAFT SERIAL NUMBER | 21061884 |
| AIRCRAFT REGISTRATION | N732YQ |
| FILE NUMBER | 14-491 |

| NAME | SIGNATURE | DATE |
|---------------|--|-------------|
| Phillip Grice |  | 06-16-2015 |

ENGINE RUN REPORT**FILE NUMBER:**

14-491

ENGINE S/N:

294045

PAGE 2 of 11**GENERAL INFORMATION**

| EXAMINATION | | ACCIDENT DATA | |
|--------------------|--|--------------------------|----------------|
| DATE | June 15, 2015 | NTSB ACCIDENT # | WPR15FA143 |
| FACILITY | Mobile Alabama | NTSB INVESTIGATOR | Zoe Keliher |
| ADDRESS | 2039Broad Street Mobil, Alabama 36615 | FAA INVESTIGATOR | Not reported |
| | | ACCIDENT DATE | 04/10/2015 |
| | | ACCIDENT LOCATION | Challis, Idaho |

ENGINE INFORMATION

| | |
|----------------------------|--------------------------------------|
| ENGINE POSITION | Single |
| TOTAL TIME | 12/08/2014 3669.4 last annual entry. |
| TIME SOH | 12/08/2014 1341.1 last annual entry. |
| TYPE & TIME SLI | Not Reported |
| BUILD DATE | 02/04/1999 |
| IN SERVICE DATE | 02/24/1999 |

Significant logbook information: Last 100 hour inspection was completed 12/08/2014. There were no anomalies noted in the last log book entry.

Report Summary:

Search Code(s):

15-12-68

There were no pre-impact conditions found that would have prevented the engine from producing rated power.

Disposition of engine following exam:

Engine was returned to AP Aircraft Boise ID.

ENGINE RUN REPORT

FILE NUMBER: 14-491 **ENGINE S/N:** 294045 **PAGE 3 of 11**

INSPECTION WITNESSES

| | | | |
|---------------------|--------------------|---------------------|--------------------|
| NAME | Phillip Grice | NAME | Johnny Little |
| ADDRESS | Mobile, AL | ADDRESS | Mobile, AL |
| ORGANIZATION | Continental Motors | ORGANIZATION | Continental Motors |
| PHONE | 251-436-8310 | PHONE | 251-436-8481 |
| | | | |
| NAME | Zoe Keliher | NAME | Greg Eastburn |
| ADDRESS | Portland OR 97209 | ADDRESS | Mobile, AL |
| ORGANIZATION | NTSB | ORGANIZATION | Continental Motors |
| PHONE | 208-352-0235 | PHONE | 251-436-8481 |

EXTERNAL INSPECTION OF ENGINE

The engine exhibited impact damage to the left front side of the engine. The number six cylinder push rod housing seat was fractured away and the cylinder was replaced for test run. The oil sump was crushed upward to the bottom of the engine and was replaced for the test run. The inlet fuel fitting on the fuel pump was fracture and replaced for the test run. The throttle arm was not returned with the engine and was replaced. The induction runners and exhaust system were impact damaged and replaced with slave units for the test run. The left front and rear engine mounts were fractured and replaced. The number six rocker cover was fractured and replaced for the test run. The right magneto was impact damaged and the flange fractured at the mount hold down clip. The oil cooler lower mounting studs were fractured and replaced for the test run.



ENGINE RUN REPORT

FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 4 of 11



ENGINE RUN REPORT


FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 5 of 11



ENGINE RUN REPORT

FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 6 of 11

ENGINE PREPARATION PRIOR TO RUN

There were a number of airframe related items removed in preparation for operation on the CMI test bed.

Items removed:

Cooling baffles

Vacuum pumps.

Alternator.

Propeller deice block.

Propeller governor.

Turbo Controller and Waste gate

Exhaust system.

The following substitute or repaired parts were required for engine operation:

Oil Sump

Number six cylinder and piston. (Original cylinder was P.015)

Fitting inlet fuel pump

Throttle Arm

Exhaust System

Induction runners Number 3 and 2, 4, 6 side.

Induction elbow and balance tube.

Engine mount legs.

Oil cooler mount studs.

Push rod housing seals number two intake valve.

The cylinders were bore-scoped and the following was observed:

All of the cylinders, pistons, and valves displayed normal operating and combustion signatures.

There were no anomalies noted during the bore-scope inspection.

ENGINE RUN REPORT

FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 7 of 11

The magneto-to-engine timing was checked and with the following results: The left magneto was impact damaged and the flange fractured from the magneto case. The timing was reset to match the right magneto at 24° before the test run.

| Magneto-to-Engine Timing (Specified): | Left Magneto: | Right Magneto: |
|---------------------------------------|---------------|----------------|
| 22° BTDC | 27° BTDC | 24° BTDC |

A cylinder leakage test was performed prior to the test run in accordance with the latest revision of CMI Service Bulletin SB03-3 with the engine at room temperature with the following results:

Cylinder #1 - 08/80 PSI (exhaust valve/rings)

Cylinder #2 - 14/80 PSI (exhaust valve)

Cylinder #3 - 25/80 PSI (exhaust valve/rings)

Cylinder #4 - 32/80 PSI (exhaust valve)

Cylinder #5 - 45/80 PSI (exhaust valve/rings)

Cylinder #6 - 20/80 PSI (exhaust valve)

(*) – Leakage Source

The engine was not disassembled prior to the engine run. The crankshaft end-play measured 0.013" and the run-out was 0.002".

The engine was then prepared for operation by installing the appropriate thermocouples, pressure lines and test pads for monitoring purposes. The engine was then moved to CMI test cell number 43 and mounted for operation. The engine was fitted with a test club propeller for the TSIO520R engine model.

DESCRIPTION OF RUN

The engine experienced a normal start on the first attempt without hesitation or stumbling in observed RPM. The engine RPM was advanced in steps for warm-up in preparation for full power operation. The engine throttle was advanced to 1200 RPM and held for five (5) minutes to stabilize. The engine throttle was advanced to 1600 RPM and held for five (5) minutes to stabilize. The engine throttle was advanced to 2450 RPM and held for five (5) minutes to stabilize. The engine throttle was advanced to full open position and held for five (5) minutes to stabilize. The engine throttle was rapidly advanced from idle to full throttle five times where it performed normally without any hesitation, stumbling or interruption in power. Turbo boost was slow to advance; slave exhaust manifold was inspected for leaks and corrected. Turbo response was rapid and capable of in excess of 40" manifold pressure. Number two intake push rod housing had impact damage and leaked oil. The seals were replaced and the run completed with no leaks observed.

Throughout the test phase, the engine accelerated normally without any hesitation, stumbling or interruption in power and demonstrated the ability to produce rated horsepower.

The turbo controller was disassembled and no anomalies noted. The waste gate actuator was inspected and determined to be at or near full extension, indicating waste gate closed.

ENGINE RUN REPORT

FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 8 of 11



ENGINE RUN REPORT

FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 9 of 11



ENGINE RUN REPORT

FILE NUMBER:

14-491

ENGINE S/N:

294045

PAGE 10 of 11



A cylinder leakage test was performed after the test run in accordance with the latest revision of CMI Service Bulletin SB03-3 with the engine hot with the following results:

Cylinder #1 - 63/80 PSI (rings)

Cylinder #2 - 65/80 PSI (rings)

Cylinder #3 - 66/80 PSI (rings)

Cylinder #4 - 60/80 PSI (rings)

Cylinder #5 - 70/80 PSI (rings)

Cylinder #6 - 74/80 PSI (rings)

(*) – Leakage Source

ENGINE RUN PARAMETERS

| Time | | RPM | MP / TDP " Hg | Oil | | Fuel | | | | Cell °F | Cylinder Head Temperature °F | | | | | |
|-------------------------------|---------|-------------------------|------------------|------------------------|-----|---|---------------|-----------------------|-------------|---------------|------------------------------|-----|-----|-----|-----|-----|
| Reading | Minutes | | | PSI | °F | Lbs./Hr. | Nozzle PSI | Pump PSI | Fuel °F | | # 1 | # 2 | # 3 | # 4 | # 5 | # 6 |
| 1 | 5 | 1200 | 17/30 | 20 | 238 | 25 | 4.7 | 14.8 | 95 | 99 | 298 | 349 | 316 | 305 | 312 | 249 |
| 2 | 5 | 1600 | 19/30 | 25 | 220 | 37 | 5.1 | 16.5 | 94 | 98 | 291 | 341 | 301 | 298 | 304 | 248 |
| 3 | 5 | 2100 | 24.7/31.7 | 40 | 209 | 81 | 8.0 | 20.4 | 94 | 91 | 317 | 361 | 329 | 324 | 333 | 283 |
| 4 | 5 | 2450 | 29.5/33.5 | 44 | 213 | 124 | 10.9 | 24.6 | 94 | 91 | 350 | 388 | 375 | 349 | 380 | 321 |
| 5 | 5 | F/T 2708 | 36.5/38.8 | 35 | 241 | 183 | 19.8 | 41 | 95 | 91 | 353 | 423 | 415 | 384 | 422 | 357 |
| 6 | 5 | Idle 660 | 17.8/30.3 | 10 | 232 | 20 | 3.8 | 9.8 | 93 | 97 | 319 | 356 | 328 | 322 | 299 | 238 |
| Ambient Air Temperature °F | | Ambient Air Pressure | | Transfer Collar Δ P | | Maximum Rated Power Engine Operational Parameters | | | | | | | | | | |
| 90.1 | | 29.29 | | IN | OUT | RPM | " Hg MP | Fuel Flow Lbs./Hr. | Metered PSI | Unmetered PSI | | | | | | |
| | | | | 35 | 33 | 2700 | 36.5 | 170-186 | 16.9-19.9 | 33-37 | | | | | | |

Notes: Operator – Johnny Little, 30524. Transfer collar pressure delta measured at full throttle power setting.

| Engine Performance Test | | | | |
|-------------------------|--------------|--------------|---------------|---------------|
| Test RPM | Left Magneto | Left Magneto | Right Magneto | Right Magneto |
| | RPM | RPM Drop | RPM | RPM Drop |
| 2100 | 2132 | 76 | 2124 | 88 |