

DOCKET No.: SA-521
EXHIBIT No. 2S

NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.

Boeing DC-8 Elevator Presentation

DC-8 Elevator Position Indicator (EPI) and Elevator Flight Control Checks

Capt. Nicholas A. Gentile


Chief Pilot Flight Crew Training

Boeing Long Beach Division

Agenda

- **Elevator Control System Overview**
- **Elevator Position Indicator History**
- **Elevator Control Check Evolution**
- **Elevator Control Check Current Procedures**
- **“80 knot” Check During Takeoff**
- **Summary**

Elevator Control System Overview



DC-8 Elevator and Elevator Tabs


Gust Lock On



Gust Lock Off




Simplified DC-8 Elevator Control System




Elevator Position Indicator History

DC-8 Elevator Position Indicator (EPI)



DC-8 Elevator Position Indicator (EPI)



Elevator Position Indicator History

Occurrences of FOD jammed in elevator hingeline

1970: TIA takeoff accident

1972: F/E walkaround discovered hingeline FOD

1972-1974: Reports of cracked/fractured control columns

1974: Operator/ALPA reports of snow/ice FOD

EPI development

1970: NTSB recommended consideration of EPI

1971: DAC/FAA conclusion EPI not necessary

1973: DAC engineering renews EPI study

1974: ALPA requests EPI system

1974: In-service evaluation of EPI begins

1975: DAC EPI Service Bulletin released

Elevator Position Indicator History

1977: PAL RTO Accident

- Geared tab crank arm failed
- Elevator jammed trailing edge up

1978: EPI mandated by AD 78-01-15

- Installation of EPI
- Elevator check procedures
(when EPI is not available)

Elevator Control Check Evolution

DC-8 Elevator Control Check

Baseline “rollout” check:

Full aft column followed by full forward column, checking for full and free movement, no binding

Elevator Control Check Evolution

- 1970: DAC baseline check reiterated after the TIA accident (Know Your DC-8 Letter No. 43)**
- 1973: Recommendation to accomplish rollout check into the wind (Know Your DC-8 Letter No. 43A)**
- 1973: Inspect the area between the stabilizer and elevator for FOD after engine ground runs (AOL 8-645)**
- 1974: To prevent control column fatigue, both pilots must simultaneously apply full aft then full forward pressure during the rollout checks (AOL 8-686)**

Elevator Control Check Evolution

- 1975: DAC-recommended rollout check procedures with EPI installation:**
- Check that EPI needle moves down into or transitions through the white band with full AND elevator
 - Accomplish elevator rollout check into the wind if tailwind prevents a valid rollout check
 - Accomplish a positive visual check to verify proper elevator operation if a valid rollout check is not achieved

(Know Your DC-8 Letter No. 53)

1975: Installation of the EPI as an aid for the flight crews during elevator checks (Service Bulletin 27-254)

1975: Flight crew apply forward column pressure slowly during the rollout checks (AOL 8-715)

Elevator Control Check Evolution

1977: For airplanes not equipped with an EPI:

- Recommend prompt incorporation of SB 27-254
- Accomplish elevator rollout check into the wind
- Introduce optional “80-knot” check during initial takeoff roll

(Service Bulletin A27-264)

1977: Reiterated information in:

- Know Your DC-8 Letter No. 53
- SB A27-264

(Know Your DC-8 Letter No. 53A)

Elevator Control Check Evolution

1978: EPI mandated (AD 78-01-15)

- **Install EPI per SB 27-254**
- **For airplanes not yet equipped with an EPI:**
 - Utilize elevator control check procedure of SB A27-264
- **For airplanes with an inoperative EPI:**
 - Utilize elevator control check procedure of SB A27-264
 - Verify proper elevator operation by a ground observer

Elevator Control Check Evolution

2001: Amplification of elevator control check procedures (Flight Operations Bulletin DC-8-01-02)

- Reiteration of previous recommendations plus recommends:
 - Check for position of elevator and tabs during walkaround
 - Check that EPI needle moves to a point below the white band with full AND elevator during the rollout check
 - If the rollout check is unsatisfactory a positive check must be made with a trained observer prior to takeoff
- **Advises operators that the “80-knot” control check is not an adequate substitute for the control rollout check**

Elevator Control Check Current Procedures

Elevator Control Check Current Procedures

- **The elevator system is checked during:**
 - **Flight engineer’s “walkaround” inspection (prior to starting engines; once or twice depending on the operator)**
 - **Cockpit check (after engine start)**
 - **Rollout check**

DC-8 Flight Engineer's "Walkaround"

- **Visually checks elevator and tab position and condition:**
 - **With the gust lock on**
 - Elevator and tabs are "faired" with stabilizer
 - **With the gust lock off (and no control column input)**
 - Elevator goes trailing edge up (mass balanced)
 - Control tabs go symmetrically trailing edge up
 - Geared tabs go symmetrically trailing edge down

“Walkaround” Video

DC-8 Cockpit Check After Engine Start

- **Rollout check (elevator, ailerons, rudder)**
 - **Performed after engines start because the ailerons and rudder are hydraulically actuated**
 - **Elevator check calls for both pilots to simultaneously apply full aft control column followed by full forward control column**
 - **Checking for freedom of control column movement and appropriate elevator motion on the elevator position indicator (EPI)**

Rollout Check Video

“80 knot” Check During Takeoff

- **Optional “80-knot” control check during initial takeoff roll**
- **Small up and down elevator motions to check weight distribution**
 - **Crew observes airplane pitch response**
 - **Use of EPI not recommended by DAC/Boeing**
- **Not a substitute for elevator control rollout check**

Summary

- **The DC-8 elevator control checks have evolved with service experience**
- **The EPI was designed to aid the flight crew during pre-takeoff control checks**
- **The “80-knot” control check is not a substitute for the elevator control rollout check**