System Service Review LVK-S-2013/10/20-0001

A1. FAC ID			A2. Date UTC (mm/dd/yyyy)						A3. S	A3. Start Time UTC			A4. End Time UTC			A5. Position			
L	V	K	1	0	2	0	2	0	1	3	2	0	4	5	2	1	1	5	GC/CD
A6. Ai	rcraft #	1									A7	. Aircr	aft #2						-
Aircraf	t ID		Airc	raft Ty	/pe/Su	ıffix		IFR	/VFR		Air	craft ID)		Aircr	aft Typ	e/Suff	X	IFR/VFR
N698SP				C172	!			VFF	R		N	15TA			ı	PTS2		VFR	

NOSOSP	C172	VFK	NISIA	P132	VFK
		Trai	ning		
B1. Were any training	issues identified?				
Yes No					
			ather		
	evailing weather condition	ons?			
☐IFR ☑VFR	Other				
If Other, explain					
C2. Was any pertinent	t precipitation depicted	on the radar?			
Yes No					
If Yes, explain					
C3. Did LLWAS alert?					
	□ N/A				
If Yes, explain					
ii roo, oxpiaiii					
C4. Were weather phe	enomena a factor?				
Yes No					
Select all that apply	If Other, explain				
Turbulence					
☐ Icing					
Thunderstorms					
Low Ceilings					
☐ Braking Conditions					
Wind Shear					

Other

Weather (continued)
C5. Were any SIGMETs or PIREPs in effect? Yes No
If Yes, explain
Efficiency
D1. Were any efficiency issues identified? ☐ Yes ☑ No
Airspace/Airport
E1. Were any airspace/airport issues identified? ☐ Yes ☑ No
Procedures
F1. Were any procedural issues identified? Yes No
Directives
G1. Were any directive issues identified? Yes No
Equipment H1. Were any equipment issues identified?
Yes No
H2. Was all communications equipment functioning properly? ☐ Yes ☑ No
If No, explain Position 4 training jack was out of service. Position 1 did not have the ability to transmit. Flight data has no access to landlines or ability to monitor frequencies. The CIC can not monitor more than one position at the same time. The equipment outages have been repaired. The tower equipment capabilities are projected to improve when the IVSR system is installed in March of 2014.
CIC was plugged into PSN 1 wearing a headset. LC1 and LC 2 were combined at PSN 2. GC and FD were combined at PSN3 due to the training jack at PSN 4 being OTS. PSN 4, is the normal GC/FD location. The CIC was monitoring LC which was at PSN 2.
H3. was all airborne radar equipment functioning properly? ☐ Yes ☐ No ☐ N/A
If No, explain

	Equipment (continued)
	e detection radar equipment functioning properly?
Yes No	⊠ N/A
If No, explain	
	and MANAID and formation and formation in a managed of
Yes No	ach NAVAID equipment functioning properly?
	□ IV/A
If No, explain	
HC Was all alimin	t lighting equipment functioning properly?
Yes No	Trighting equipment functioning properly? □ N/A
If No, explain	
	tional automation radar equipment functioning properly? (i.e. HOST, STARS, ARTS, ASDE, etc.)
H7. Was all opera ☑ Yes □ No	tional automation radar equipment functioning properly? (i.e. HOST, STARS, ARTS, ASDE, etc.)
Yes No	□ N/A
Yes No If No, explain H8. Was all opera	□ N/A
Yes No If No, explain H8. Was all opera Yes No	□ N/A
Yes No If No, explain H8. Was all opera	□ N/A
Yes No If No, explain H8. Was all opera Yes No	□ N/A
Yes No If No, explain H8. Was all opera Yes No	□ N/A
Yes No If No, explain H8. Was all opera Yes No	□ N/A
Yes No If No, explain H8. Was all opera Yes No	□ N/A

Equipment (continued)								
H9. Was all inoperative equipment properly coordinated as out of service across ATO organizations? (i.e. En-Route, Terminal, Sys Ops, Tech Ops, etc.)								
Yes □ No □ N/A								
If No, explain								
H10. Was all inoperative equipment properly NoTAMed as out of service? Yes No N/A								
If No, explain								
H11. Were any potential systemic equipment issues identified? Yes No								
If Yes, explain CIC is only able to monitor one position at a time. This is a limitation of the equipment. The installation of the new IVSR equipment in March 2014 does not have this limitation.								
Customer Feedback								
Customer Feedback I1. Was there customer feedback regarding the operation during this review session? Yes No								
I1. Was there customer feedback regarding the operation during this review session? ☐ Yes ☑ No								
I1. Was there customer feedback regarding the operation during this review session? ☐ Yes ☑ No Resource Management								
I1. Was there customer feedback regarding the operation during this review session? ☐ Yes No Resource Management J1. Were any resource management issues identified? ☐ Yes ☐ No								
I1. Was there customer feedback regarding the operation during this review session? ☐ Yes ☑ No Resource Management J1. Were any resource management issues identified?								
I1. Was there customer feedback regarding the operation during this review session? Yes No								
I1. Was there customer feedback regarding the operation during this review session? Yes No								
II. Was there customer feedback regarding the operation during this review session? Yes								
II. Was there customer feedback regarding the operation during this review session? Yes								

	Resource Management (continued)								
	J4. Were any positions not properly staffed? Yes No								
	If Yes, explain When the CIC became aware that	If Yes, explain When the CIC became aware that the CPC-IT was falling behind the CIC should have opened the FD position.							
	J5. Were positions/sectors combined/decombined in an appropriate/timely manner? Yes No								
	If No, explain								
	J6. Were there any distractions in ☐ Yes No	n the operation?							
	If Yes, explain								
	J7. Were any potential systemic ∈	J7. Were any potential systemic resources management issues identified? ☐ Yes ☑ No							
	I/A Mas and notable individual na	Individual Perfo							
	Yes No	erformance identified? (Exemplary an	a/or needing improvement)						
	K2. Employee #1:								
	Employee Name	Position OSCIC	ATSAP Filed ☑ Yes ☐ No						
	Explanation The CIC was engaged in the operation. CIC was plugged into PSN 1 wearing a headset. LC1 and LC 2 were combined at PSN 2. and FD were combined at PSN3 due to the training jack at PSN 4 being OTS. The CIC was monitoring LC which was at PSN 2. TICIC was aware that the CPC-IT was falling behind at GC/FD. CIC offered to record ATIS for GC/FD. The OJTI at GC/FD declined to offer and recorded the ATIS herself while the CPC-IT continued to talk to aircraft.								
		affic. Splitting the LC position would	LC was moderate with routine complexity and is normally have required termination of OJT on GC because GC was						
		prities at the GC/FD position. When t	FD combined during OJT due to staffing limitations or as he CIC became aware that the CPC-IT was falling behind the						

	Individual	Performance (continued)
K2. Employee #2:		
Employee Name	Position LC1	ATSAP Filed ☑ Yes ☐ No
controller assumed that I traffic information to N15 LC had several options: 1. Coordinate with GC to 2. Instruct N15TA to beg		n.
K2. Employee #3:	ne runways until there was room	Closs runway 23L.
Employee Name	Position GC/CD	ATSAP Filed ☑ Yes ☐ No
	provide timely assistance to the ance with JO 7110.65 2-1-2.	aircraft involved after the accident had occurred. The prioritization
K2. Employee #4:		
Employee Name	Position GC/CD	ATSAP Filed ☑ Yes ☐ No
	1	
		attention away from the position. The OJTI did not take over the assist the aircraft involved in the accident.
The OJTI made the ATIS		

QC Findings
Local controller did not advise the Pitts of the Cessna ahead. JO 7110.65 3-1-6. Situations where advisories to taxiing aircraft are appropriate will be covered in a team briefing.
The Position 4 training jack and Position 1 problem with transmitting have been repaired. Remind all CIC's in team briefing to keep the tower staffed appropriately which would include the option of openning FD even if training is in progress at GC. Team briefing will include a refresher on the requirements of JO 7210.3X 2-6-1. Watch Supervision. Emphasis will be placed on 2-6-1 (10) Situational awareness.
After becoming aware of the accident the CPC-IT was very slow in responding to the aircraft involved. The OJTI did not take over the position. The OJTI's FLM with discuss the importance of using good judgement in taking control of a position during training with the OJTI.
Collaborated lessons learned uploaded.
the tower staffed appropriately which would include the option of openning FD even if training is in progress at GC. Team be will include a refresher on the requirements of JO 7210.3X 2-6-1. Watch Supervision. Emphasis will be placed on 2-6-1 (10) Situational awareness. After becoming aware of the accident the CPC-IT was very slow in responding to the aircraft involved. The OJTI did not take the position. The OJTI's FLM with discuss the importance of using good judgement in taking control of a position during trawith the OJTI.

Review Team
Matthew Zizzo, Douglas Jones, Troy White, Timothy Johnson, ,