
1. Reporting FAC ID	2. Date UTC (dd/mm	/уууу)		3. Tin	ne UTC	;		4. Significan	nt Occurrence?
F L G	0 5 0 9	2 0	1 5	1	7	1	2	0	Yes No
5. MOR reported by Controller provid CIC External Facility	ling services	Ξ	M craft Owner/ tline (Descril	•		·)		O Electron	I Facility Review nically Detected Describe in summar
			•				<u> </u>		Describe in summar
Brasher warr	ning given? Yes			raining	, ,	-	0	′es No	
I1 MOP type - airno	rt environment MOPs		ORT ENVIR					Ita Occur	rrence location:
I1. MOR type - airport environment MORs involving aircraft on the airport surface: Aircraft on movement area/runway safety area other than expected/intended						Tra. Occur	Terree location.		
- Other aircraft within one-mile of landing threshold? • Yes • No					FLG AIRPORT				
O Canceled take	off clearance or flight c	ew aborted	takeoff afte	r crossi	ng holo	d-short	line		
Aircraft uninter	ntionally maneuvered o	ff runway or	taxiway						
_	LS protected area othe			ed					
•	on final approach – ID			Type/Si	uffix _			Describe where on the airport surface the occurrence occurred	
I1b. Aircraft informa								occurrence o	ocuiteu
Aircraft ID	Aircraft type/suffix	Facility co	ommunicatir	ng with	Positi A/C	on con	nmunio	cating with	Frequency
N1099Q	C310	A/C	FLG		7,0		LC		134.55
I1b. Aircraft informa Aircraft ID	and within 1/2 mile of an attion:  Aircraft type/suffix	Facility co	ommunicati		Positi	on con	nmunic	occurrence o	Frequency
		A/C			A/C				
I3. MOR type - airpo surface:	rt environment MORs	involving	vehicles on	the air	port		13a. (	Occurrence	location:
_									
O Vehicle on movement area/runway safety area other than expected/intended									
- Aircraft within one-mile of landing threshold? O Yes O No									
O Vehicle within ILS protected area other than expected/intended									
				Desci		airport surface the occurre			
Vehicle information Vehicle type:	tion:	la ID	Facility	commun	nicatino	n Posi	ition co	mmunicating	g with vehicle Frequ
Airport Operator		ie iD	with veh		licating	y FOS	ILIOIT CC	minumcaung	y with vehicle in requ
O FAA O A	/C not for flight								
O Tug O T	ug with aircraft								
Other (summary	,								
I4. MOR type - airpo surface:	rt environment MORs	involving	pedestrian	on the	airport	t	I4a. (	Occurrence	location:
O Pedestrian on	movement area/runway	safety area	a other than	expect	ed/inte	nded	1		
						Describe where on the airport surface the occurrence			
I4b. Pedestrian nam		conoid:	<b>U</b> 163	<u> </u>	•		occur	red	
	- (								



SEPARATION						
Was this a loss of separation	on?					
O Yes O No	Applicable Separation Rule:					
Separation Used: O Course Divergence	MARSA Mode C Interlace	O Opposit	e Course (Report	Passing) Other Facility		
O Procedure/Waiver	Report/Observe Leaving Altitude	O Termina	al Transition	O Tower Visual Separation		
<b>O</b> VFR Aircraft	O VFR Aircraft O Visual Approach		Separation	O Other		
RISK ANALYSIS						
Was this a Risk Analysis Ev	vent?		ı			
O Yes No	RAE Score:					
PILOT DEVIATION						
Was this a possible pilot deviation?						
O Yes No	Preliminary Number:					
SURFACE EVENT						
Was this a possible Surface	e Event?		1			
Yes O No	Classification:					
VEHICLE/PEDESTRIAN DEVIATION						
Was this a possible Vehicle	P/Pedestrian Deviation?		1			
O Yes O No	Preliminary Number:					
NMAC						
Was this a NMAC?	I		T			
O Yes O No	NMAC Number:					

 1 LO W 2010/03/03 0001
Runway Safety Findings
09/05/2015 RI 1012L (1712Z) Flagstaff Pulliam / Flagstaff, AZ (FLG) Runway Incursion
N1099Q/C310 was observed taxiing northbound on Taxiway Alpha without any communication with ATC. Local/Ground Control (LC) made several transmissions to C310 without a response. When C310 turned onto Taxiway Alpha 2 and continued towards the runway, LC instructed SKW2992/CRJ2, on a 1.5 mile final, to go around. C310 initiated takeoff roll and then advised they had just turned their radio on. LC instructed C310 to cancel their takeoff and exit the runway. METAR: KFLG 051657Z 23007KT 10SM BKN040 OVC050 16/13 A3026

 1 EO W 2013/03/00 0001
QA SUMMARY
N1099Q was observed taxiing northbound on Taxiway Alpha without any communication with ATC. Local/Ground Control made several transmissions to N1099Q without a response. When N1099Q turned onto Taxiway Alpha 2 and continued towards the runway, LC instructed SKW2992, on a 1.5 mile final, to go around. N1099Q initiated takeoff roll and then advised they had just turned their radio on. LC instructed N1099Q to cancel their takeoff and exit the runway. N1099Q was not consistently communicating so an Airport vehicle escorted them to the ramp. N1099Q later taxied out and departed. The flight terminated in a fatal accident. A pilot deviation will not be filed.