



**HIGHWAY FACTORS AND RAILROAD GRADE CROSSING  
GROUP CHAIRMAN'S FACTUAL REPORT  
ERRATA**

**Valhalla, NY**

**DCA15MR006**

**(7 pages)**

**NATIONAL TRANSPORTATION SAFETY BOARD  
OFFICE OF HIGHWAY SAFETY  
AND  
OFFICE OF RAILROAD, PIPELINE &  
HAZARDOUS MATERIALS INVESTIGATIONS  
WASHINGTON, D.C.**

**HIGHWAY FACTORS AND RAILROAD GRADE CROSSING  
GROUP CHAIRMAN'S FACTUAL REPORT ERRATA**

---

**A. CRASH INFORMATION**

Location: Commerce Street Grade Crossing on the Metro-North Harlem Line,  
Valhalla, Westchester County, New York

Vehicle #1: 2011 Mercedes ML350

Vehicle #2: Metro-North passenger train 659

Operator #2: Metro-North Railroad

Date: February 3, 2015

Time: Approximately 06:28 p.m. EST

NTSB #: **DCA15MR006**

**B. HIGHWAY FACTORS AND RAILROAD GRADE CROSSING INVESTIGATIVE  
GROUP**

Ruben Payan, Railroad S&TC Investigator, Group Co-Chairman  
NTSB Office of Railroad, Pipeline, and Haz-Mat Investigations  
490 L'Enfant Plaza SW, Washington, D.C. 20594

Dan Walsh, P.E., Senior Highway Factors Investigator, Group Co-Chairman  
NTSB Office of Highway Safety  
P.O. Box 822271, North Richland Hills, TX 76182

Anthony Forcina, Assistant Chief Engineer – C&S  
Metro-North Railroad  
24 Fisher Lane, White Plains, NY 10603

Tom Weiler, S&TC Inspector  
Federal Railroad Administration, Region 1  
55 Broadway, Room 1077, Cambridge, MA 02142

Lou Frangella, Grade Crossing Manager  
Federal Railroad Administration, Region 1  
55 Broadway, Room 1077, Cambridge, MA 02142

Robert Maraldo, Supervisor, Rail Safety – Railroads and Transit  
Public Transportation Safety Board, New York State Department of Transportation  
Hunters Point Plaza, 47-40 21st Street  
Long Island City, NY 11101

Maureen Kuinlan, P.E., Traffic Signal Engineer in Charge  
New York State Department of Transportation  
4 Burnett Boulevard  
Poughkeepsie, NY 12603

Gregory G. Hart, Railroad Coordinator  
New York State Department of Transportation  
4 Burnett Boulevard  
Poughkeepsie, NY 12603

David Smyth, P.E., Town Engineer  
Town of Mount Pleasant  
One Town Hall Plaza  
Valhalla, NY 10595

### **C. CRASH SUMMARY**

For a summary of the crash, refer to the *Crash Summary Report* in the docket for this investigation.

### **D. PURPOSE OF ERRATA**

The purpose of this errata is to ensure the accuracy of the factual content in the Highway Factors and Railroad Grade Crossing Factual Report. New factual information was received by the New York State Department of Transportation (NYSDOT) on June 9, 2017 and June 13, 2017 as it relates to post-crash actions taken by the NYSDOT after the crash.

The errata is organized so that the entire paragraph or sentence is taken from the Highway Factors and Railroad Grade Crossing Factual Report. The page number, paragraph number, and sentence are shown for reference. Deletions are shown with a strikethrough and additions are shown with an underline.


## E. ERRATA

### Page 19, 2<sup>nd</sup> and 3<sup>rd</sup> paragraphs.

Preemption #2 - Preemption #2 is activated by the railroad (See Figure 5) and provides green time for vehicles traveling eastbound on Commerce Street to clear the queue (cars). If the train preemption is activated the traffic signal will terminate the active green phase, run the corresponding yellow and red clearances, and turn green for vehicles traveling eastbound on Commerce Street only. This phase will remain green for a minimum of 2.6 seconds and a maximum of 10 seconds. ~~Once a vehicle moves off of the loop detector (see Figure 5) located in the pavement of the eastbound lane of Commerce Street between the grade crossing and Taconic State Parkway, or it reaches its maximum time~~ Once the maximum of 10 seconds is reached the traffic signal will run the yellow and red clearance times and turn green on the Taconic State Parkway and cycle normally.

~~Figure 5 illustrates the location of the loop detectors at the Commerce Street and Taconic State Parkway intersection.~~

Page 20, Delete Figure 5 and add a new Figure 5.



**Figure 5** – Illustration showing the location of the loop detector for Preemption #1 and the railroad train detection circuit for Preemption #2 at the intersection of the Commerce Street grade crossing and Taconic State Parkway.

Page 22, 1<sup>st</sup> paragraph, add a new section entitled “9.2 Post-crash Actions taken by the New York State Department of Transportation (NYSDOT) on May 1, 2015”.

**9.2. Post-crash Actions taken by the New York State Department of Transportation (NYSDOT) on May 1, 2015**

The NYSDOT informed NTSB investigators after the crash that on May 1, 2015, the NYSDOT adjusted the traffic signal preemption at the Commerce Street and Taconic State Parkway intersection to ensure railroad preemption is the highest priority and that successive preemptions cannot interrupt the railroad preemption (see Attachment 23 - Email from the New York State Department of Transportation (NYSDOT) to NTSB Investigators dated June 9, 2017 at 7:37 a.m.).

While adjusting the traffic signal preemption on May 1, 2015, the NYSDOT also adjusted the clearance time for vehicles traveling northwest on Commerce Street under Preemption #2. NYSDOT changed the clearance time from its range of 2 to 10 seconds, which was in effect at the time of the accident, to 29 seconds of clearance time, followed by 4 seconds of yellow (see Attachment 23 - Email from the New York State Department of Transportation (NYSDOT) to NTSB Investigators dated June 9, 2017 at 7:37 a.m.). This change, according to NYSDOT, was based on the “Guide for Determining Time Requirements for Traffic Signal Preemption at Highway-Rail Grade Crossings” contained in the *August 2007 Railroad-Highway Grade Crossing Handbook*. This guideline uses an intermediate semi-trailer, serving as a “worst-case vehicle” to assess the time it would take to move from a stopped position on the far side of the crossing, clear the tracks, and proceed through the intersection (see Attachment 24 - Email from the New York State Department of Transportation (NYSDOT) to NTSB Investigators dated June 9, 2017 at 11:34 a.m.).

The interconnection for the traffic signal preemption was installed on October 27, 2008, and at that time the NYDOT chose to use a range of 2 to 10 seconds as the clearance time at the grade crossing. Although guidance documents were available in the *August 2007 Railroad-Highway Grade Crossing Handbook*, it does not appear that NYSDOT used them to establish the clearance time. When questioned by NTSB investigators, NYSDOT staff could not explain why the preemption timing range was chosen at that time, nor could they identify what guidance, if any, was used when making that decision (see Attachment 25 - Email from the New York State Department of Transportation (NYSDOT) to NTSB Investigators dated June 12, 2017 at 12:27 p.m.).

The NYSDOT identified another traffic signal in Region 8 that is “similar” to the one at Taconic State Parkway and Commerce Street that has a maximum clearance time of 10 seconds. The traffic signal is located at River Road and Global Terminal in New Windsor, New York (see Attachment 25 - Email from the New York State Department of Transportation (NYSDOT) to NTSB Investigators dated June 12, 2017 at 12:27 p.m.). The NYSDOT is currently examining

whether grade crossings with preempted traffic signals at intersections in the state's other regions have the 10-second maximum clearance time.

**9.3.   ~~9.2.~~   Closure of the Commerce Street Grade Crossing**

**END OF HIGHWAY FACTORS AND RAILROAD GRADE CROSSING FACTUAL  
REPORT ERRATA**

---