



Secure Mailbox SIGN OUT ? HELP

- MESSAGES**
- » Inbox
- Sent Items
- Search
- Compose
- MY FOLDERS**
- Cosco Busan
- Manage Folders
- ACCOUNT INFO**
- Preferences

VIEW MESSAGE

SUBJECT: Re: Cosco Busan investigation
FROM: RPaetzold@edptlaw.com
TO: rothrot@ntsb.gov
SENT: Thu 20 Nov 2008 12:41:49 EST
EXPIRES: Thu 04 Dec 2008 12:41:49 EST

Dear Tom:

At Board President Miller's request, I am forwarding the following attachments:

The Addendum to the Board's Party Submission along with the four enclosures mentioned therein.

Enclosure (1) - the complete IRC report, is broken down into multiple parts because of its length and the amount of memory required. The text of the report is included with the Addendum and the other enclosures (legislation dealing with pilot physicals and with Board oversight and its incident investigation procedures and the Oregon Pilot Commission Symposium agenda). The attachments and exhibits to the IRC report are divided into six parts, most of them in 30-page blocks and are attached as noted above.

Kindly let me know if you would also like a hard copy or a CD of the above, or if we can be of any further assistance.




Best regards

Ray

Raymond M. Paetzold
 Emard Danoff Port Tamulski & Paetzold LLP
 49 Stevenson Street, Suite 400
 San Francisco, CA 94105
 Tel: (415) 227-9455

- >
- >
- > "Thomas Roth-Roffy" <rothrot@ntsb.gov> wrote:
- > Mike,
- > You can you use this secure mail system to send large attachments back to NTSB.

ATTACHMENT FILENAME	TYPE	SIZE
<input checked="" type="checkbox"/> Addendum_of_11-18-08_with_encl.pdf	Adobe Acrobat Document	2.25 MB
<input checked="" type="checkbox"/> AE_part_1.pdf	Adobe Acrobat Document	1.27 MB
<input checked="" type="checkbox"/> AE_Part_2.pdf	Adobe Acrobat Document	1.49 MB
<input checked="" type="checkbox"/> AE_Part_3.pdf	Adobe Acrobat Document	3.21 MB
	Adobe Acrobat	

<input checked="" type="checkbox"/>	 AE_Part_4.pdf	Document	4.53 MB
<input checked="" type="checkbox"/>	 AE_Part_5.pdf	Adobe Acrobat Document	5.12 MB
<input checked="" type="checkbox"/>	 AE_Part_6.pdf	Adobe Acrobat Document	5.02 MB
<input type="checkbox"/> All	Save Checked Files		

Addendum

to

Party Submission

by

**BOARD OF PILOT COMMISSIONERS FOR THE BAYS
OF SAN FRANCISCO, SAN PABLO AND SUISUN**

NTSB Investigation

COSCO BUSAN Allision with the

San Francisco – Oakland Bay Bridge,

San Francisco, California

November 7, 2007

TABLE OF CONTENTS

The Board's Incident Investigation	1
Pilot Training In And Use of Electronic Navigation Systems	1
Rulemaking re Use of Portable Pilot Units	2
Pilot Fitness Issues	2
Incident Investigation Procedures	2
Communications Among Pilot Commissions	5

1 **The Board of Pilot Commissioners for the Bays of San Francisco, San**
2 **Pablo and Suisun provides the following addendum to its Party**
3 **Submission, which was submitted on August 14, 2008.**

4 **The Board's Incident Investigation**

5 Captain Cota retired effective October 1, 2008. The IRC's report was
6 presented to the Board at its October 23 meeting at which the Board voted to accept
7 the report. With the exception of the pilot's statement to the IRC and the investigator's
8 confidential report which are precluded from public disclosure by state law, the
9 complete IRC report is now a public document and is attached as Encl. (1).

10 For the reasons set forth in the Party Submission, the accusation against
11 Captain Cota's state pilot license was dismissed upon his retirement and resignation as
12 a state licensed pilot. That license remained suspended from November 30, 2007 until
13 the date of his retirement.

14 **Pilot Training In And Use of Electronic Navigation Systems**

15 The Curriculum Committee has held several meetings to develop specific
16 recommendations for changing the pilot training curriculum and is scheduled to meet
17 November 19, 2008 to receive and evaluate several proposals to provide
18 comprehensive training which includes enhanced training in advanced electronic
19 navigation systems. A copy of the revised training curriculum will be forwarded upon
20 adoption by the Board.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22

Rulemaking re Use of Portable Pilot Units

The AGPA (Associate Government Policy Analyst) referred to in the Board's Party Submission has now been hired and commenced work on the rulemaking to require pilots to be equipped and trained in the use of portable pilot units. Delay in hiring an AGPA was occasioned by the California budget process and the unprecedented delay in passing a state budget this year.

Pilot Fitness Issues

The legislation referred to in the Board's Party Submission regarding pilot physicals and interim reporting requirements for changes in medication was passed. A chaptered copy of the bill is attached as Encl. (2).

Incident Investigation Procedures

1. Issues regarding the frequency and severity of Captain Cota's pre-COSCO BUSAN incident record (and the perception that both were increasing) were re-evaluated. The following additional observations are provided:

At the outset, it should be noted that the Board must apply a very specific standard in considering whether to suspend or revoke a pilot's state license. Under California law, the standard which applies to cases seeking the suspension or revocation of a professional license is "clear and convincing evidence to a reasonable certainty." See, e.g., Hughes v. Board of Architectural Examiners, CA Supreme Court, 17 Cal. 4th 763 (1998). This contrasts with the "preponderance of the evidence" standard that applies to suspending or revoking a Coast Guard license. 33 CFR Section 20.701.

1 The IRC was established in 1993. As detailed in the Board's comments on the
2 NTSB Technical Review Draft Factual Report, Captain Cota was involved in four
3 shiphandling incidents between 1993 and 2007, two of which did not involve pilot
4 error, and one incident which was treated as a medical issue (the TARAWA):

5 4/97 - MARE CASPIUM - contact with gantry crane (which was out of
6 position) while ship was being docked by a pilot trainee under Captain Cota's
7 supervision - minimal damage - Minor Pilot Error

8 7/02 - CHIMBORAZO - springline caught on dock due to longshore and
9 crew error in handling mooring line - minimal damage - no pilot error

10 10/02 - GINGA KITE - vessel interaction reported after both vessels had left
11 - caused moored vessel to pull off dock to extent of slack in mooring lines - no
12 damage - no attributable pilot error

13 10/04 - TARAWA - shiphandling was not in issue as Captain Cota
14 reportedly did a very good job of docking the vessel under adverse conditions. His
15 over-reaction to the crew's refusal to remove the tag line - which he deemed a safety
16 hazard - was the issue.

17 2/06 - PIONEER - grounding in the mud at a sharp turn in the river at very
18 slow speed - no damage - pilot error

19 As noted in the Board's earlier comments and submissions, data for incidents
20 investigated before the establishment of the IRC is limited and inconclusive regarding
21 pilot error. Eight incidents involving Captain Cota were investigated between 1983
22 and 1991. The last such incident was 11/91 involving the report of wake damage from

1 a passing vessel piloted by Captain Cota. The Board's record only notes "pilot
2 counseled."

3 The next shiphandling incident in which there was a finding of pilot error was
4 5.5 years later in 4/97 (involving minimal damage and minor pilot error), followed by
5 the PIONEER 8.8 years later in 2/06 (involving no damage but a finding of pilot
6 error). Two of the intervening incidents did not find pilot error - one involving minor
7 damage and the other no damage.

8 The TARAWA is the only other intervening incident. It did not involve
9 damage or pilot error but was investigated because of Captain Cota's reportedly
10 unprofessional conduct. Captain Cota's job performance was closely monitored for
11 five months after he was cleared by medical professionals to return to work with no
12 evidence of further unprofessional conduct.

13 While Captain Cota's incident frequency involving pilot error did not appear to
14 show a substantial increase in frequency or severity, the Board recognized that
15 improvements in its investigation procedures can be made. In conducting its
16 investigations, the IRC has implemented a more detailed and systematic review of a
17 pilot's prior incident history pending completion of a comprehensive review of the
18 IRC's investigation and reporting procedures.

19 2. Legislation significantly effecting the Board's incident investigation,
20 oversight of the Board and other aspects of the Board's functions was passed and
21 signed into law in the period since the Board's Party Submission. That legislation will
22 go into effect on January 1, 2009. A chaptered copy of that legislation is attached as
23 Encl. (3).

1

Communications Among Pilot Commissions

2 On November 6 and 7, 2008, a conference of Pilot Commissions from the
3 states of California, Oregon, Washington, and Alaska, and from British Columbia was
4 hosted by the Oregon Commission. A copy of the agenda is attached hereto as Encl.
5 (4). Further efforts to maintain regular communication among these pilot
6 commissions are anticipated.

Enclosure 1

WHILE INCLUDED IN THE REPORT, THE
COMPLETE IRC REPORT IS ATTACHED
SEPARATELY DUE TO ITS LENGTH

*Board of Pilot Commissioners for the
Bays of San Francisco, San Pablo
and Suisun*



INCIDENT REVIEW COMMITTEE REPORT:

**NOVEMBER 7, 2007 ALLISION WITH THE
SAN FRANCISCO-OAKLAND BAY BRIDGE**

VESSEL: *M/V COSCO BUSAN*
PILOT: CAPT. JOHN COTA

Presented: October 23, 2008

TABLE OF CONTENTS

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA - NOVEMBER 7, 2007

REPORT

EXECUTIVE SUMMARY	1
FINDINGS OF FACT.....	4
1 VESSEL INFORMATION.....	4
2 ENVIRONMENTAL CONDITIONS.....	5
3 INCIDENT & MISCONDUCT UNDER INVESTIGATION....	7
4 ESTIMATED DAMAGES RESULTING FROM INCIDENT... ..	7
5 NAMES OF WITNESSES	8
6 NATURE AND EXTENT OF INJURIES.....	8
7 SUMMARY OF PRIOR INCIDENTS INVOLVING SAME PILOT.....	8
8 RELEVANT INFORMATION FROM U.S. COAST GUARD... ..	8
9 CHRONOLOGY OF INVESTIGATION & ACTION TAKEN PURSUANT TO HARBORS & NAVIGATION CODE 1180.6. .	9
10 SUMMARY OF FACTUAL BACKGROUND.....	9
ANALYSIS AND RESPONSE.....	14
11 FINDINGS OF PILOT ERROR.....	14
12 RESPONSE OF THE IRC.....	16

TABLE OF CONTENTS

13	OTHER ACTIONS TAKEN.....	17
14	CONCLUSION.....	18

SUPPLEMENTAL MATERIALS

(Maintained in Separate Binder)

APPENDICES:

- APPENDIX 1: Names of Witnesses
- APPENDIX 2: Summary of Prior Incidents Involving Same Pilot
- APPENDIX 3: Chronology of Investigation & Action Taken Pursuant to Harbors & Navigation Code 1180.6
- APPENDIX 4: NTSB Party Submission - Board of Pilot Commissioners-S F Bay

EXHIBITS:

- 1. Preliminary Incident Report
- 2. USCG Documents
 - A. Photos of Electronic Chart
 - B. CG-2692, M/V COSCO BUSAN
 - C. CG-2692 REVOLUTION
 - D. Statement of Capt. John Cota
- 3. Pilot's Report
 - A. November 8, 2007
 - B. November 19, 2007
- 4. M/V COSCO BUSAN Documents
 - B. Copy of Bridge Log
 - C. Copy of Bell Book
 - F. Copy of Course Recorder
 - I. Vessel's Particulars.
 - L. Crew List

TABLE OF CONTENTS

5. Engineer's Report
 - C. Copy of Engine Recorder
 - D. Copy of Engine Alarm Records
6. Tide Information
7. Overview of Area
8. Investigator's Report
9. Photos/Drawings of Vessel
10. Lloyds/Jane's Information
11. Tug REVOLUTION Information
12. Human Factors Checklist
13. Investigation Checklist.

EXECUTIVE SUMMARY

The Board of Pilot Commissioners for the Bays of San Francisco, San Pablo and Suisun (the "Board") licenses and regulates the approximately 60 San Francisco bay pilots and one inland pilot who provide pilotage services on San Francisco Bay and its tributaries and on Monterey Bay. The Board has many duties, one of which is the responsibility to review all reports of misconduct or navigational incidents involving bay pilots or inland pilots or other matters for which a license issued by the Board may be revoked or suspended. This responsibility is delegated to the Board's Incident Review Committee ("IRC"). (Harb. & Nav.Code § 1180.3(b)). Following its investigation, the IRC must present a written report to the Board. (Harb. & Nav.Code § 1180.3(b) &(c)).

This report constitutes the findings and conclusions of the IRC based on its investigation of the *M/V COSCO BUSAN*'s allision with the fendering system around the Delta Tower of the San Francisco-Oakland Bay Bridge ("Bay Bridge") at 0830 hours on November 07, 2007. At the time of the allision, the *M/V COSCO BUSAN* was transiting from her berth in the Oakland Inner Harbor to sea under the navigational control of Captain John Cota, a Board-licensed pilot.

The purpose of the IRC's investigation was to determine whether there was pilot error or "misconduct" on the part of Captain Cota, and if so, whether such misconduct was sufficient to warrant the suspension or revocation of his state pilot license.

The IRC has not been tasked with determining whether there was misconduct, negligence or errors on the part of other individuals or parties. To that end, any comments on the actions of other individuals or entities appear in this report only to the extent that they help explain whether pilot error was involved. Consequently, any such comments are not intended to reflect, and should not be interpreted as, the IRC's opinion with respect to the relative culpability, if any, of other individuals or parties.

It should also be noted that, as Captain Cota has turned in his state pilot license and retired, this matter did not go through a full evidentiary hearing before an administrative law judge. Accordingly, this report reflects only the findings and conclusions of the IRC without having afforded the pilot an opportunity to test the evidence relied upon by the IRC in an administrative hearing. Furthermore, because of ongoing litigation, many witnesses were inaccessible. Under the Board's regulations, this report by the IRC is nevertheless required.

As a result of its investigation, the IRC concluded that pilot misconduct was a factor in the allision. The IRC's conclusions are summarized as follows:

- (1) That, prior to getting underway, Captain Cota failed to utilize all available

resources to determine visibility conditions along his intended route when it was obvious that he would have to make the transit to sea in significantly reduced visibility;

(2) That Captain Cota had exhibited significant concerns about the condition of the ship's radar and a lack of familiarity with the ship's electronic chart system, but then failed to properly take those concerns into account in deciding to proceed;

(3) That, considering the circumstances of reduced visibility and what Captain Cota did and did not know about the ship and the conditions along his intended route, he failed to exercise sound judgment in deciding to get underway;

(4) That Captain Cota failed to ensure that his plans for the transit and how to deal with the conditions of reduced visibility had been clearly communicated and discussed with the master;

(5) That, once underway, Captain Cota proceeded at an unsafe speed for the conditions of visibility;

(6) That, when Captain Cota began making his approach to the Bay Bridge, he noted further reduced visibility and then reportedly lost confidence with the ship's radar. While he could have turned south to safe anchorage to await improved visibility or to determine what, if anything was wrong with the radar, Captain Cota failed to exercise sound judgment and instead continued on the intended transit of the M/V Cosco Busan, relying solely on an electronic chart system with which he was unfamiliar; and

(7) That Captain Cota failed to utilize all available resources to determine his position before committing the ship to its transit under the Bay Bridge.

Based on the nature of the misconduct and after considering the factors listed in Section 210(e) of the Board's regulations, the IRC recommended a temporary suspension of Captain Cota's state pilot license pending a hearing, as authorized by Harbors and Navigation Code Section 1180. The Board followed this recommendation and voted to suspend the license pending the hearing. Thereafter the IRC filed an Accusation. The Accusation recommended the suspension or revocation of Captain Cota's license. He then filed a timely Notice of Defense denying the allegations of misconduct.

The Office of Administrative Hearings assigned an Administrative Law Judge and set a hearing date. The Board elected to hear the matter sitting with the administrative law judge, as provided by law. The hearing date was postponed twice by order of the administrative law judge to permit the parties to obtain necessary evidence for the hearing.

On June 30, 2008, before the matter could be heard, Captain Cota gave notice of his retirement as a San Francisco bar pilot on the earliest effective date permitted by the

applicable statute. He cited as reasons that pending criminal charges against him arising out of this incident made it impossible for him to defend the administrative action against his state license.

By operation of law, his state pilot license, which had remained suspended in the interim, would cease to exist upon his retirement. Thus Captain Cota's retirement effectively rendered moot any action the Board could have taken against his license if it had found pilot error. Captain Cota's retirement became effective on October 1, 2008, and the Accusation has now been dismissed.

THIS SPACE LEFT BLANK INTENTIONALLY.

FINDINGS OF FACT

1. VESSEL INFORMATION

- 1.1. Ownership/Registration/Management. *M/V COSCO BUSAN* is a motor container vessel registered in Hong Kong, with Hong Kong Chinese crew and officers. Regal Stone, Ltd. owns the vessel and Fleet Management, Ltd. manages it. The vessel's agent in San Francisco is Norton Lilly. (See, Exhibits 1, 4 and 8)
- 1.2. Mechanical Specifications. The vessel is single screw; right turning, fixed pitch propeller. There is a 2,700 hp bow thruster. The vessel was built in 2001 by Hyundai Heavy Industries, Ulsan, South Korea. Its general specifications are as follows:

Length:	901'	Beam:	131'
Draft:	39' 09" fwd,	40' 04" aft	
Tonnage:	65,131 grt	34,078 net	
Engine:	Man B&W,	77,600hp	

Its engine command specifications are as follows:

<u>Bell Signal</u>	<u>RPM</u>	<u>Speed</u>
Dead Slow	24	6
Slow	35	9
Half	50	13
Full	65	17
Sea speed	104	25.9

(See, Exhibits 3, 4 and 10)

- 1.3. Master & Pilot. The master of the *M/V COSCO BUSAN* was Capt. M. C. Sun. (See, Exhibits 4, 8) The pilot of the *M/V COSCO BUSAN* was Captain John Cota, SFBP. (See, Exhibits 1, 3, 8)
- 1.4. Planned Transit. The *M/V COSCO BUSAN* was en route from Oakland, Berth 56 to sea. (See, Exhibits 3, 8)

1.5. Assisting Vessel: The tug assisting at the time of the Incident was:

Name: *REVOLUTION*

Operator: Douglas Alfors

Owner: American Navigation

Length: 78' Beam: 34' Draft: 14'

Tonnage: 144 grt

Propulsion configuration: Twin Z drive, 5,080 bhp Bollard pull: 135,000#

(See Exhibits 3, 4 and 8)

2. ENVIRONMENTAL CONDITIONS

On the day of the Incident, Captain Cota boarded the *M/V COSCO BUSAN* at 0600 hours at Port of Oakland, Berth 56, with an anticipated departure time of 0630 hours. The actual time of departure was 0748 hours and the time of the collision was approximately 0830 hours. The relevant environmental conditions during these time periods were as follows:

2.1. Relevant Conditions at Berth 56:

Sunrise was expected at 0641 hours. At the time of Captain Cota's boarding of the *M/V COSCO BUSAN*, a "dense fog" was present. Prior to departure Captain Cota saw the tug *SOLANA* from a distance of at least 0.25 miles. He could not confirm if visibility extended to 0.5 miles, but could see across the channel prior to departure.

At approximately 0800 hours the Tug *SOLANA* approached the middle harbor channel. After passing buoys 7 and 8 at the Oakland Inner Harbor Entrance, the Tug *SOLANA* reported seeing the bow of the *M/V COSCO BUSAN* at a distance of approximately 1000 feet (0.18 miles).

At the time of the *M/V COSCO BUSAN*'s departure, at most, there was a slight lifting of the fog.

2.2. Visibility Along Intended Route as Reported Prior to Departure:

Captain Cota had no information regarding the visibility along his intended route from Berth 56 to the Pilot Station, and did not contact anyone to ascertain such visibility.

Cota did not inquire of Tug *SOLANA* what conditions were in the outer channel, even though the tug had just traversed that region of the Bay. On its transit from the Bay Bridge construction site to the Oakland Inner Harbor, the Tug *SOLANA* experienced visibility as low as 200 yards.

The crew boat *PROWLER* reported conditions as "very foggy" along its route from Port of San Francisco, Pier 50 to the Bridge construction site.

Multiple vessels were scheduled to depart or transit the Bay between 0600 and 0900 hours on November 7, 2007. Pilots on these vessels reported limited visibility:

<u>Visibility</u>	<u>Pilot</u>	<u>Vessel</u>	<u>Location</u>	<u>Est. Time</u>
0.125 miles (660 feet)	Lobo	SEA LAND METEOR	Oakland Berth 23	0600
Less than 0.5 miles	Gates	CHEMBULK BARCELONA	Richmond Berth 11	0700
0.15 miles (800 feet)	Gans	STROFADES	Anchorage 9	0730
Ranging from 0.17 miles (900 feet) to 0.25 miles (1320 feet)	Dohm	ITAL LIBERA	Oakland Berth 37	0830
Ranging from less than 0.75 mile to 0.25 mile	Villas	LIHUE	Oakland Berth 68	0900
No more than 0.2 miles (1056 feet)	S. Teague	S H BRIGHT	Inbound from Golden Gate to Anchorage 8	0830

At Richmond Berth 11 visibility did not improve until 1015 hours. At Oakland Berth 37, the *ITAL LIBERA* delayed its scheduled 0830 departure until 1100 hours due to poor visibility.

2.3. Relevant Conditions During Transit From Berth 56 to Yerba Buena Island

Captain Cota reported no greater than 0.25 nautical mile of visibility during his transit from Oakland Berth 56 to Yerba Buena Island.

2.4. Relevant Conditions in Vicinity of Yerba Buena Island at 0830 hours.

Wind: SW, 7-10 kts.
 Visibility: fog, 1/4 mile or less
 Tide Height: 5.6 feet, rising
 Current: 0.8 kt, flood

(See, Exhibits 3, 6, 8)

Immediately before the allision, *PROWLER* noted visibility of approximately 0.1 miles in the vicinity of the "C" tower of the Bay Bridge. This puts visibility at just over half the length of the *M/V COSCO BUSAN*.

3. INCIDENT & MISCONDUCT UNDER INVESTIGATION

The specific incident investigated is the allision of the *M/V COSCO BUSAN* with the Delta Tower of the Bridge, at 0830 hours on November 07, 2007. Besides the allision itself, the actions of Captain Cota leading up to the allision were also investigated. Thus, the investigation reviewed Captain Cota's actions from the time he boarded the *M/V COSCO BUSAN* at 0600 hours on the morning of November 07, 2007 until he left the vessel at 0945.

4. ESTIMATED DAMAGES RESULTING FROM INCIDENT

One of the factors the IRC must consider in determining the appropriate corrective action to be imposed, (and to consider when going outside the guidelines provided by Section 210(f) of the Board's regulations), is "the nature and extent of any injuries, property damage or harm to the environment resulting from the incident." The purpose of this section of the report is to provide information regarding the order of magnitude of the consequences resulting from Incident. It is not intended to quantify exact damages of individual parties or determine liability therefor.

4.1 Physical Damage

The *M/V COSCO BUSAN* sustained a gash approximately 220 feet long, 14 feet high and 8 feet deep. The depth of the gash varied from scraping and bending of the shell plating, to penetration of voids, ballast and fuel tanks. The longitudinal bulkhead in way of #2 cargo hold was partly buckled and punctured. Two fuel oil tanks were penetrated, allowing bunker fuel to gravitate to the lowest level of contact with the fendering. Approximately over 50,000 gallons of heavy fuel oil were discharged. This reasonably equates in volume to the capacity of four and a half 40 foot shipping containers.

The allision also damaged the fendering system of the Delta Tower of the Bridge.

4.2 Valuation of Damages

The heavy fuel oil spilled following the allision dispersed over much of the greater San Francisco Bay and affected a combined 26 miles of coastline inside the Bay and outside the Golden Gate. Extensive clean up efforts were undertaken by the vessel's owners and operator, and by federal, state and local governments, private concerns and volunteers. The oil spill has been blamed for the contamination of wildlife habitat and protected marine resources and for the deaths of thousands of birds.

The opening of the normal fishing and crabbing season was delayed, causing substantial losses to the fishermen and related industries. Two class actions were filed on behalf of various fishermen and crabbers claiming to represent some 1500 class members for their losses. Their losses have not been quantified.

The federal government and three municipalities filed suits in federal and state courts. These law suits seek clean up and response costs, natural resource damages and other losses and civil penalties. The suits name as defendants the vessel, its owners, operator and the pilot.

The California Department of Transportation filed suit for the costs of repairs to the Bay Bridge, which it estimated at \$2 million.

The ship owner, operator and cargo interests have all suffered losses as a result of the damage to the vessel and her detention. The ship owner has estimated its current and future losses as a result of this incident, including its liability for the actions of the pilot, to exceed \$80 million. Such damages include repair to the vessel (estimated to be in excess of \$2.5 million), loss of hire, and clean up and recovery costs.

5 WITNESSES & INFORMATION OBTAINED FROM SAME

See Appendix 1.

6 NATURE AND EXTENT OF INJURIES

No physical injuries were reported or came to the attention of the IRC.

7 SUMMARY OF PRIOR INCIDENTS INVOLVING SAME PILOT

See Appendix 2.

8 RELEVANT INFORMATION FROM U.S. COAST GUARD

The IRC obtained information and materials directly from the US Coast Guard. In addition, the IRC gained benefit from other materials obtained by the U.S. Coast Guard and ultimately released to other agencies or entities. These materials include:

- A. Photos of the navigational bridge, including the radar, electronic chart and other navigational equipment on board the *M/V COSCO BUSAN*;
- B. Information regarding the operational status of buoys in the vicinity of the Bay Bridge Delta tower. This included a report that the San Francisco Sector conducted a survey and found the following buoys were operational:
 - a. Pier D North Buoy (LLNR-4450)
 - b. Pier D South Buoy (LLNR-4455)
 - c. Yerba Buena Lt / Sound Signal (LLNR-4595);

- C. Information regarding the damage to the fendering system on the Bay Bridge Delta tower;
- D. Information regarding the operational status of the RACON above the Delta-Echo span of the Bay Bridge. This information indicated that the last reported malfunction of any Bay Bridge RACON occurred in July of 2007, and that as of November 7, 2007 all RACONs were operating;
- E. Information regarding the horizontal clearance available for navigation, between the fenders of the Bay Bridge towers.

9 CHRONOLOGY OF INVESTIGATION & ACTION TAKEN PURSUANT TO HARBORS & NAVIGATION CODE 1180.6

See Appendix 3.

10 SUMMARY OF FACTUAL BACKGROUND

10.1. Boarding And Pre-Departure Activities

At about 0600 on Wednesday November 7, 2007, Captain John Cota boarded the container vessel *M/V COSCO BUSAN* at Oakland Berth 56, to take it to sea. The vessel was scheduled to sail at 0630 hours. Once aboard, Captain Cota was escorted to the bridge where he met the master, Captain Sun, along with a mate. He and Captain Sun discussed the dense fog and decided to wait for visibility to improve before sailing. At 0630 Stand By Engine was ordered in preparation for departure. Sunrise was at 0641, but visibility remained very poor. (See, Exhibits 3, 5, 6, 8)

Captain Cota and Captain Sun reviewed the SFBP Master-Pilot Exchange Card. Captain Cota found the tuning of the two radars to be unacceptable. He, the master, and the mate spent 45-60 minutes tuning the radars and testing the automatic plotting features (ARPA), until they were able to successfully acquire, track, and plot a target. (However, Captain Cota stated prior to departure. "I've tried to target five times, never plots. That's not good for fog." Captain Cota observed that the heading flasher of the radars was correct for the channel heading as moored. The radars were set on either 1.5 or 3-mile scale. (See, Exhibits 2, 3)

After convincing himself that he could rely on the radar, Captain Cota examined the electronic chart (EC). Captain Cota noted that the symbols on the electronic chart were not familiar to him and he did not see any track lines appearing on it. He also did not

review any paper chart on the bridge. He asked Captain Sun to point out the center of the D-E span of the Bay Bridge. Captain Sun pointed to what he said was the center of the span. Captain Cota failed to recognize that Captain Sun was pointing to the buoys marking Delta Tower, midway between the prominently marked RACONs (RADAR beaCONs) on C-D and D-E spans.

Captain Cota considered Captain Sun's command of English nominal, and only sufficient enough to understand navigational terms. Captain Cota was unaware that Captain Sun and his crew had only joined the vessel on Oct 24 (two weeks previously) when there was a change in the vessel's ownership. (Exhibit 3)

10.2. Layout And Navigational Equipment Of M/V COSCO BUSAN Bridge

The bridge layout of the *M/V COSCO BUSAN* consisted of a midship helm station with consoles to port and starboard. The port console was the navigation station. From midship outboard, it consisted of a radar monitor, a ship control function monitor, an electronic chart display and another radar monitor. Captain Cota was unable to distinguish between the 3 cm radar and 10 cm radar monitors. While he asked the Captain for clarification, he was not able to understand the response. Captain Cota did not have or use a personal computer with charting software and AIS interface. He was under the incorrect impression that the American Pilots' Association discourages the use of such devices due to potential liability issues.

The starboard console was the engine/machinery control area and had the engine order telegraph and bow thruster controls as well as engine function readouts.

10.3. Departure From Berth 56

By 0630, visibility had gradually improved and Captain Cota believed he could see across the estuary for a distance of about 0.25 mile. That distance was hard to quantify due to the flat land in the area.

At 0645 Captain Cota directed the assist tug *REVOLUTION* into position and to put up a headline to the vessel's port quarter. The tug was fast at 0648. He visually observed the tug *SOLANA* and two barges proceeding up the estuary and noted the tug's range to be 0.25 mile. *SOLANA* had just entered the estuary after passing Oakland berth 38. The operator stated that while he passed close to it, he had been unable to see that berth. The tug operator also noted that he had passed Buoy 6 in the Inner Harbor Entrance Channel at 200 yards without being able to see it. Indeed, the *SOLANA*'s operator stated he had 0.25 mile of visibility or less throughout his transit from the Bay Bridge construction site to the Oakland Inner Harbor entrance.

After determining visibility to be about 0.25 mile at the vessel, Captains Cota and Sun agreed to depart. Captain Cota contacted the operator of the *SOLANA* and agreed to remain at the berth until the tug and barges were past and clear.
(See, Exhibits 2, 3, 8)

At 0714 lines were singled up aft. (That is, the only mooring lines remaining aft were a single stern line, a breast line and a spring line). At 0745 lines were singled up forward and all lines were ordered to be let go. The last line was let go at 0748. At 0755, with the tug and barges clear astern and all lines clear, the *REVOLUTION* was directed to back and using the bow thruster, the vessel was moved off the berth to mid-channel.

At 0800 the tug *REVOLUTION* was directed to let go and put a headline up to the center chock on the stern of the *M/V COSCO BUSAN* and follow the vessel and to keep a slack line. Captain Cota advised the tug he would keep them there until the vessel was clear of the Oakland Bar Channel.

At 0808 slow ahead was ordered and the vessel began to move out of the estuary.
(See, Exhibits 2, 4, 5)

As the vessel moved out of the estuary, Captain Cota visually observed Lights 7 and 8 at the edge of the channel, as well as Lights 5 and 6. A review of AIS readouts shows the vessel favoring the north side of the channel. Captain Cota purposely held to the right side of the channel due to the flood current. At 0820 hours, in the vicinity of Buoys 1 and 2, speed was increased to half ahead. Captain Cota did not see Buoys 1 and 2, but later stated he was not looking for them since he was concentrating on the radar picture. The tug *REVOLUTION* continued to follow the *M/V COSCO BUSAN*, maintaining a slack line. However, after clearing the Oakland Bar Channel, Captain Cota did not release the tug. He later acknowledged this was because he had forgotten about its presence.
(See, Exhibits 2, 3, 5)

10.4. Approach To Yerba Buena Island

Captain Cota planned to set the radar's variable range marker (VRM) to 0.33 mile and to maintain that distance from Yerba Buena Island (YBI) as he approached the Bay Bridge. This is consistent with the practice of other pilots in transiting under the D-E span of the Bay Bridge in reduced visibility.
(See, Exhibits 2, 3)

Captain Cota believes he was using the radar monitor located next to the helmsman most of the time. He set the VRM and maneuvered the vessel to 0.33 mile south of the tip of YBI and began his starboard turn per his plan. After commencing the turn he again asked Captain Sun for the location of the center of D-E span on the electronic chart. Captain Sun did so, but apparently pointed to the Delta Tower, rather than the D-E span.

Captain Cota noted he would be turning short of that point and steadied the vessel briefly, checking the turn and deviating from his plan of turning 0.33 mile off the shoreline of YBI. However, Captain Cota had again failed to recognize that Captain Sun was pointing to the buoys between that marked the Delta Tower. (See, Exhibits 2, 3)

10.5. Allision With Bridge

Captain Cota maintains that, as he was beginning his starboard turn, the radar picture on both radars began to deteriorate. He stated the radar was not displaying the RACON on the D-E span of the Bay Bridge, nor was it displaying the towers, or the buoys near the Delta Tower. The Bay Bridge image had, according to Captain Cota, become a thick green ribbon on the radar screens. He stated that he lost confidence in the accuracy of the radar and did not trust the radar image, including the VRM. He believes that at about the same time the fog became thicker, further reducing visibility. (See, Exhibits 2, 3)

As the vessel approached the Bay Bridge, the Westar Marine Services 41-foot crew boat *PROWLER* was proceeding from San Francisco Pier 50 to the Bay Bridge construction site to pick up surveyors. Its operator reported conditions as "very foggy" and he proceeded along the SF waterfront to Alpha Tower and waited there for an inbound vessel to pass. That vessel was the *M/V S. H. BRIGHT*, which diverted to Anchorage 8. From there *PROWLER* proceeded to Charlie Tower and held position waiting for the *M/V COSCO BUSAN* to pass through D-E span. From the vicinity of Charlie Tower the operator could see a faint outline of Delta Tower, a distance of 0.20 mile. (See, Exhibits 8)

Captain Cota resumed the turn and shortly thereafter received a radio call from USCG Vessel Traffic Service (VTS). After making contact with Captain Cota, VTS radioed him stating: "AIS shows you on 235 heading. What are your intentions? Over." Captain Cota was standing at a radar consol and looked at the heading flasher. It showed the vessel passing through 280°T and still swinging to starboard. Captain Cota replied to VTS, "Um, I'm coming around. I'm steering 280 right now." VTS radioed in response, "Roger, understand you're still intending the Delta-Echo span, over." Captain Cota replied, "Yeah, we're still Delta-Echo."

Having lost confidence in the radars, Captain Cota moved to the electronic chart to see what it showed. He again asked Captain Sun to point out the center of D-E span, which he did. According to what Captain Sun pointed to on the electronic chart, Captain Cota believed that the vessel was headed to the center of D-E span. Captain Cota again failed to recognize that, in reality, Captain Sun had pointed to the Delta Tower itself. (See, Exhibits 2, 3)

At 0827 Captain Cota ordered full ahead and hard right rudder to steer the vessel in a direction that he believed would be closer to Echo Tower. The increased speed and

propeller wash caused the line to the tug *REVOLUTION* to tighten and the operator released the winch brake to let the towline run to avoid tripping the boat and to maintain a slack line. (See, Exhibits 2, 3, 5)

Shortly after the speed increase and change of rudder, Captain Cota heard a call to Captain Sun on his handheld radio. The exchange was apparently in Chinese and Captain Cota was unable to understand what was said. Soon after that, Captain Cota observed Delta Tower looming out of the fog close on the port bow. He then finally realized that Captain Sun had been pointing to the tower instead of the center of the span. He could see that the vessel's port side was going to contact the tower's fendering system and ordered hard left rudder to lift the stern away. At 0830 the vessel contacted the fendering system on the East-South-East corner of the Delta Tower. (See, Exhibits 2, 3, 4, 8)

Captain Cota reported that he did not feel the vessel shudder or heel or otherwise show that they were scraping along the fendering system. At 0830.5 he ordered dead slow ahead. The tug *REVOLUTION* also slowed. As the tug passed the Delta Tower, its operator observed floating fender pile debris and oil in the water. At 0832 the *M/V COSCO BUSAN* crew reported oil leakage to the bridge. Captain Sun advised Captain Cota who advised the USCG. At 0834 the engine was stopped. (See, Exhibits 3, 4, 5)

10.6. Post-Allision Events

At 0836 the engine was ordered slow ahead. Captain Cota radioed VTS and advised them that he had contacted the fendering system on Delta Tower and was proceeding to Anchorage 7 off Treasure Island ("TI"). Captain Cota used his cell phone to call the Port Agent (Captain McIsaac) and advise him of the incident. At 0855, using the ship's radar to determine range, the *M/V COSCO BUSAN* was anchored 0.5 mile off the North-West corner of TI in Anchorage 7. At 0858 the *REVOLUTION* was let go. Captain Cota told the operator "*REVOLUTION*, you're released. I guess I forgot about you in all of the excitement." (See, Exhibits 2, 3, 4)

Captain McIsaac gathered several other pilots from the Pilot Station and embarked in the *P/V GOLDEN GATE* to inspect the fendering system and go to the vessel. When the *P/V GOLDEN GATE* arrived at Anchorage 7 he noted that there was still a small amount of oil leaking from a long gash in the vessel's side. This was the first direct observation of the damage. At about 0900 Captain Frank Hoburg boarded the vessel and went to the bridge to relieve Captain Cota. While the *P/V GOLDEN GATE* was alongside, Captain McIsaac noted that the flow of oil from the vessel had stopped. (See, Exhibits 2, 3, 8)

At about 0905 Captain Coney also boarded the *M/V COSCO BUSAN* to assist. When Captain Coney arrived on the bridge he found that Captain Cota was preparing to conduct an alcohol swab test on himself. Captain Coney witnessed the test. He noted

visibility to be about 0.25-0.5 mile. At 0945 hours Captains Cota and Coney departed the *M/V COSCO BUSAN* aboard the *P/V DRAKE*. They proceeded to the Pilot Station where, at approximately 1030 Captain Cota was given a drug screening test by a contract service retained to perform such screenings. All screening tests came back negative for the presence of drugs and/or alcohol.

11. FINDINGS OF PILOT ERROR

Based on its investigation, the IRC found misconduct on the part of Captain John Cota in relation to the Incident. The misconduct found is as follows:

- 11.1. Failure to Utilize All Available Resources to Determine Conditions Along His Intended Route. Captain Cota, while recognizing the extremely limited visibility caused by the fog on the morning of November 7, 2007, did not take advantage of any of several sources to determine the visibility along his proposed route. He did not attempt contact other vessels and did not ask VTS for information regarding conditions along his intended route. In fact, visibility was less than 0.25 nautical miles in the vicinity of the Bay Bridge and at other locations along his route. According to the operator of the *PROWLER*, the visibility at the Bay Bridge was approximately 1000 feet. If accurate, that meant that Captain Cota, from his position on the vessel's bridge, would have been able to see only about 200 feet beyond the bow of the *M/V COSCO BUSAN*.
- 11.2. In Deciding to Depart, Failed to Properly Take Into Account Concerns Regarding the Vessel's Navigational Equipment. Captain Cota had exhibited significant concerns about the condition of the ship's radar and a lack of familiarity with the ship's electronic chart system, but then failed to properly take those concerns into account in deciding to proceed. For instance, Captain Cota noted it took upwards of 45 minutes of work with the radar system to allow it to operate as he believed it should. Even so, he noted "I've tried to target five times, never plots. That's not good for fog." There was apparently no effort to determine what had caused the issues that prevented the radar from operating in its intended manner, nor whether the radar had exhibited any malfunctions in the recent past. Furthermore, Captain Cota failed to clarify for himself the bandwidth of the radar monitors. Finally, Captain Cota did not examine the electronic chart closely enough to become familiar with, and assure himself that he understood the symbols used on the electronic chart. It appears that in the end Captain Cota never gained complete confidence in the radar system, as he instructed the tug *REVOLUTION* to tie a stern line to the vessel. In addition, when he saw a "band" on the radar as he approached the Bay Bridge, he immediately disregarded the positional fix he

had just obtained from the radar relative to Yerba Buena Island. He abandoned this fix even though there was no indication that it was erroneous when obtained. These facts indicate that, considering the limited visibility, Captain Cota never reached an appropriate level of confidence in the vessel's navigational equipment.

- 11.3. Failure to Exercise Sound Judgment in Deciding to Depart. At the time of departure, Captain Cota had, at most, 0.25 nautical miles of visibility, with no indication that visibility would improve during transit. The operator of the tug *SOLANA* estimated the visibility in the vicinity of the *M/V COSCO BUSAN* as low as 200 yards, and no more than 0.25 nautical miles, if that. Nevertheless, Captain Cota participated in the decision to depart, even though there was no pressure on the vessel to leave at or near its scheduled departure time. Captain Cota agreed to depart despite his knowledge of the crew's limited language ability, his unfamiliarity with the Electronic Chart, the 45 minute effort needed to adjust the radar, and his failure to refer to (and/or note the presence of) a paper chart. In fact, Captain Cota's own concern about the conditions at the time of departure is evidenced by his instruction to the tug *REVOLUTION* to attach a stern line to the *M/V COSCO BUSAN*. In light of the known conditions, Captain Cota failed to exercise sound judgment in deciding to depart.
- 11.4. Failure to Ensure That His Plans for Transit, And His Plans For Dealing with Reduced Visibility Were Clearly Communicated with the Master. As far as Captain Cota knew, the crew had nominal English abilities, and perhaps no more than the ability to understand basic maneuvering commands. He was unable to get all the information he sought regarding the conditions and settings of the radar prior to departure. Prudence would have dictated that Captain Cota use extra care in ensuring that the master understood their plan for navigating in such reduced visibility, in instructing the members of the bridge team in what was expected of them, and in instructing the lookouts as to what they should be looking for and reporting. Prudence would have also dictated that a bridge team member be instructed to take periodic fixes of the vessel's location.
- 11.5. Proceeding at an Unsafe Speed. Notwithstanding the extremely limited visibility, Captain Cota ordered "Half Ahead" when the ship exited the Oakland Inner Harbor Entrance Channel and maintained that engine order for seven minutes. That engine order brought the ship's speed under prevailing circumstances to between 10 and 11 knots, and perhaps as high as 12 knots. The approximate speed of the ship when it allided with the Bay Bridge was 11 knots. (The Full Ahead order minutes before the allision, coupled with a hard right rudder, and then left full rudder moments before the allision, would not have appreciably increased the ship's speed at the time of contact with the Bay Bridge's fendering system.) Under the circumstances, with as little as 200 feet of visibility beyond the bow of the vessel, this represents an unsafe speed.

11.6. Failure to Exercise Sound Judgment in Continuing His Transit Under the Bay Bridge. After Captain Cota had guided the vessel to a distance of .33 miles from the southern tip of YBI and was ready to make his final approach to transit under the center of the D-E span of the Bay Bridge, Captain Cota lost confidence in what he described as a malfunctioning radar. (The IRC found no evidence that the radar actually malfunctioned, although it was not in a position to determine what, if anything was done with the radar prior to its inspection by government authorities, and will leave that to others to address.) As a result, Captain Cota shifted his reliance to an electronic chart with which he was not familiar, and on the master's misinterpretation of the center of the span – an interpretation that Captain Cota had reason to doubt. In fact, by that time, Captain Cota had asked three different times for Captain Sun to point to the center of the D-E span on the electronic chart. In addition, he had received an indication from VTS of a heading significantly different from that which was being read on the vessel. At that point, prudence would have dictated that he abort the attempted transit and turn south to a safe anchorage, either to determine what was wrong with the radar (if anything) or to await better visibility conditions. Instead of aborting the attempted transit, Captain Cota altered his intended route to a point further west along the Bay Bridge, a point that turned out to be the Delta Tower of the Bay Bridge rather than the center of the D-E span.

11.7. Failure to Utilize Available Resources Prior to Allision. As Captain Cota approached the Bay Bridge, visibility began to deteriorate. At that juncture (and perhaps even as the radar picture deteriorated), Captain Cota still had the option of utilizing VTS to fix his position and/or abandon the transit and use the availability of Anchorage 8 or 9. In addition, he had the availability of crew members to fix the vessel's position, and potentially the vessel's lookouts to identify any structures. None of these resources were utilized. Instead, Captain Cota continued to rely exclusively on resources in which he had limited or no confidence.

12. RESPONSE OF THE IRC

Based on its findings, the IRC determined that the corrective actions it has the power to administer were insufficient with respect to the level of pilot error. Consequently, the IRC exercised its option to file an Accusation seeking suspension or revocation of Captain Cota's license. This Accusation was filed within 30 days of the Incident, on December 6, 2007. In response, Captain Cota filed a timely Notice of Defense.

A preliminary hearing date in April 2008 was set. This date was set primarily in response to the Office of Administrative Hearing's ("the OAH") internal requirement to immediately set a hearing date. At the first status conference, the hearing was moved to July, 2008. At the next status conference Captain Cota sought, and was granted, a continuance to and until September 2, 2008. The OAH granted the continuance to allow

the parties adequate time to complete discovery, especially in light of the multiple legal proceedings filed in relation to the Incident.

In the meantime, on June 30, 2008, Captain Cota gave notice of his retirement effective October 1, 2008. (As the Board knows, a pilot must give at least three months notice of retirement, and such retirement must begin the first day of a fiscal quarter.)

By giving notice of his retirement, Captain Cota rendered moot the two actions the Board could have taken - suspension or revocation - had it found misconduct. Accordingly, the parties entered into a stipulation that voided the September, 2008 hearing schedule and set the matter to be closed once Captain Cota's retirement went into affect. Accordingly, the case pending in front of the OAH was closed shortly after Captain Cota's retirement became effective on October 1, 2008.

13. OTHER ACTIONS TAKEN

Following the Incident, the Board, the Board's President, the Board's Executive Director, and/or the IRC have taken other actions beyond the investigation. They are listed here in order to provide a historical record of such actions. The actions taken include:

- 13.1. Participation in NTSB on-site investigation and hearings;
- 13.2. Participation in the Harbor Safety Committee's Review of the *San Francisco, San Pablo and Suisun Bays Harbor Safety Plan* ;¹
- 13.3. Initiation of a review of issues having to do with Pilot Fitness, including a review of the Board's existing procedures to assure the good physical and mental health of pilots;
- 13.4. Initiation of a review of the Board's Incident Review process;
- 13.5. Participation in efforts to increase communication among pilot commissions;


¹ In connection with this, the IRC recommends that the Port Agent ensure that all pilots review the Harbor Safety Plan, including minimum visibility standards.

- 13.6. Involvement in the Harbor Safety Committee's analysis of certain issues related to the use of shipboard and portable electronic navigation systems by pilots; and
- 13.7. Formation of a Navigation Technology Committee to investigate the different types of navigation systems found on ships calling on the San Francisco Bay Area and the sufficiency of pilot training in the use of such systems, and to evaluate portable electronic navigation chart systems that can be brought aboard by pilots to assist in navigation. This committee has already presented its preliminary report to the Board, and the Board has acted upon it.


Further details of these actions can be found in Appendix 4.

14. CONCLUSION

Having concluded its investigation, and having followed the recommended course of action through to its final conclusion, the IRC respectfully submits this report for the Board's review and acceptance pursuant to the Board's Regulations (Title 7, California Code of Regulations, § 210(g)).



Captain Patrick Moloney
Executive Director
State Board of Pilot Commissioners
Member, Incident Review Committee



Knute Michael Miller
President
State Board of Pilot Commissioners
Member, Incident Review Committee

Enclosure 2

SB 1217, Chaptered

Senate Bill No. 1217

CHAPTER 568

An act to add Section 1157.5 to, and to repeal and add Section 1176 of, the Harbors and Navigation Code, relating to vessels, and making an appropriation therefor

[Approved by Governor September 29, 2008 Filed with
Secretary of State September 29, 2008]

LEGISLATIVE COUNSEL'S DIGEST

SB 1217, Yee. Vessels: Board of Pilot Commissioners: pilots: fitness for duty.

Existing law establishes in state government the Board of Pilot Commissioners, with jurisdiction over Monterey Bay and the Bays of San Francisco, San Pablo, and Suisun. Existing law authorizes the board to appoint an executive director to perform various duties.

This bill would require the board, on or before April 15, 2010, and annually thereafter, to submit to the Secretary of the Senate and the Chief Clerk of the Assembly a report containing specified information describing its activities for the preceding calendar year.

Existing law continuously appropriates the funds in the Board of Pilot Commissioners' Special Fund for the payment of the compensation and expenses of the board, its officers and employees, and training programs.

By imposing the duty to submit an annual report of the board's activities, the bill would make an appropriation.

Existing law requires pilots and inland pilots to undergo physical examinations in accordance with standards prescribed by the board in conjunction with the renewal of their licenses. Existing law requires that the examination designate that each pilot or inland pilot is fit to perform his or her duties as a pilot.

This bill would, instead, require the board to appoint a physician or physicians who are qualified to determine the suitability of a person to perform his or her duties as a pilot, an inland pilot, or a pilot trainee in accordance with specified requirements, that include, among other things, an evaluation of the effects of the prescription medications that the pilot, inland pilot, or pilot trainee is taking, and would require the appointed physician to designate to the board whether the pilot, inland pilot, or pilot trainee is fit to perform his or her duties as a pilot, inland pilot, or pilot trainee.

The bill would require the board to terminate a pilot trainee or suspend or revoke the license of a pilot or an inland pilot who fails to submit the prescribed medication information required by these provisions.

This bill would also provide that certain provisions would be operative only if SB 1627 and this bill are both enacted and become effective on or before January 1, 2009, and other provisions would be operative only if this bill is enacted and becomes effective on or before January 1, 2009, and SB 1627 is not enacted

Appropriation: yes.

The people of the State of California do enact as follows:

SECTION 1 Section 1157.5 is added to the Harbors and Navigation Code, to read:

1157.5 On or before April 15, 2010, and annually thereafter, the board shall submit to the Secretary of the Senate and the Chief Clerk of the Assembly a report describing the board's activities for the preceding calendar year. The report shall include, but not be limited to, all of the following:

(a) The number of vessel movements across the bar, on the bays, and on the rivers within the board's jurisdiction.

(b) The name of each licensed pilot, inland pilot, and pilot trainee, and the status of each person. If a person has had more than one status during the reporting year, each status and the length of time in that status shall be indicated. For the purposes of this section, "status" includes all of the following designations:

- (1) Licensed and fit for duty.
- (2) Licensed and not fit for duty.
- (3) Licensed and on authorized training.
- (4) Licensed and on active military duty.
- (5) Licensed and on leave of absence.
- (6) Licensed but license suspended.

(c) A summary of each report of misconduct or a navigational incident involving a pilot, inland pilot, or pilot trainee, or other matters for which a license issued by the board may be revoked or suspended. For those cases that have been closed, the summary shall include a description of findings made by the incident review committee and of the resulting action taken by the board. For those cases that are still under investigation, the summary shall include a description of the reported incident and an estimated completion date for the investigation. For those closed cases involving a pilot who has been involved in a prior incident where a finding of pilot error had been made, the report shall also include a summary of that incident.

SEC 2 Section 1157.5 is added to the Harbors and Navigation Code, to read:

1157.5 On or before April 15, 2010, and annually thereafter, the board shall submit to the Secretary of the Senate, the Chief Clerk of the Assembly, and the Secretary of Business, Transportation and Housing a report describing the board's activities for the preceding calendar year. The report shall include, but not be limited to, all of the following:

(a) The number of vessel movements across the bar, on the bays, and on the rivers within the board's jurisdiction.

(b) The name of each licensed pilot, inland pilot, and pilot trainee, and the status of each person. If a person has had more than one status during the reporting year, each status and the length of time in that status shall be indicated. For the purposes of this section, "status" includes all of the following designations:

- (1) Licensed and fit for duty.
- (2) Licensed and not fit for duty.
- (3) Licensed and on authorized training.
- (4) Licensed and on active military duty.
- (5) Licensed and on leave of absence.
- (6) Licensed but license suspended.

(c) A summary of each report of misconduct or a navigational incident involving a pilot, inland pilot, or pilot trainee, or other matters for which a license issued by the board may be revoked or suspended. For those cases that have been closed, the summary shall include a description of findings made by the incident review committee and of the resulting action taken by the board. For those cases that are still under investigation, the summary shall include a description of the reported incident and an estimated completion date for the investigation. For those closed cases involving a pilot who has been involved in a prior incident where a finding of pilot error had been made, the report shall also include a summary of that incident.

SEC. 3. Section 1176 of the Harbors and Navigation Code is repealed.

SEC. 4. Section 1176 is added to the Harbors and Navigation Code, to read:

1176 (a) The board shall appoint a physician or physicians who are qualified to determine the suitability of a person to perform his or her duties as a pilot, an inland pilot, or a pilot trainee in accordance with subdivision (c).

(b) An applicant for a pilot trainee position or for a pilot or inland pilot license as well as a pilot or inland pilot seeking renewal of his or her license shall undergo a physical examination by a board appointed physician in accordance with standards prescribed by the board. Within 30 days prior to the examination, the applicant or licensee shall submit to the physician conducting the physical examination a complete list of all prescribed medications being taken by or administered to the applicant or licensee.

(c) On the basis of both the examination and an evaluation of the effects of the prescription medications named on the submitted list, the physician shall designate to the board whether or not the pilot, inland pilot, or pilot trainee is fit to perform his or her duties as a pilot, inland pilot, or pilot trainee.

(d) The license of a pilot or inland pilot shall not be renewed unless he or she is found fit for duty pursuant to subdivision (c).

(e) Whenever a pilot, inland pilot, or pilot trainee is prescribed either a new dosage of a medication or a new medication, or suspends the use of a prescribed medication, he or she shall, within 10 days, submit that

information to the board appointed physician having possession of the prescribed medication list submitted pursuant to subdivision (b). Whenever the physician receives the updated information, the physician shall determine whether or not the medication change affects the licensee's or trainee's fitness for duty. If the physician determines that the medication change results in the pilot, inland pilot, or pilot trainee being unfit for duty, the physician shall inform the board.

(f) The board may terminate a pilot trainee or suspend or revoke the license of a pilot or an inland pilot who fails to submit the prescribed medication information required by this section.

SEC 5 (a) Section 1 of this bill shall only become operative if this bill is enacted and becomes effective on or before January 1, 2009, and Senate Bill 1627 is not enacted, in which case Section 2 of this bill shall not become operative.

(b) Section 2 of this bill shall only become operative if both this bill and Senate Bill 1627 are enacted and become effective on or before January 1, 2009, in which case Section 1 of this bill shall not become operative.

Enclosure 3

SB 1627, Chaptered

BILL NUMBER: SB 1627 CHAPTERED
BILL TEXT

CHAPTER 567

FILED WITH SECRETARY OF STATE SEPTEMBER 29, 2008

APPROVED BY GOVERNOR SEPTEMBER 29, 2008

PASSED THE SENATE AUGUST 29, 2008

PASSED THE ASSEMBLY AUGUST 22, 2008

AMENDED IN ASSEMBLY AUGUST 20, 2008

AMENDED IN ASSEMBLY AUGUST 15, 2008

AMENDED IN ASSEMBLY AUGUST 8, 2008

AMENDED IN ASSEMBLY JUNE 5, 2008

AMENDED IN SENATE MAY 5, 2008

AMENDED IN SENATE APRIL 22, 2008

AMENDED IN SENATE APRIL 2, 2008

INTRODUCED BY Senator Wiggins

(Coauthor: Senator Alquist)

(Coauthors: Assembly Members DeVore, DeSaulnier, Evans, Huffman,
and Lieber)

FEBRUARY 22, 2008

An act to amend Section 13975 of the Government Code, to amend Sections 1130, 1137, 1150, 1152, 1153, 1154, 1155, 1156, 1156.5, 1156.6, 1157, 1158, 1159, 1159.1, 1171.5, 1180.6, 1181, and 1182 of, and to add Sections 1117, 1157.1, 1157.2, 1157.3, 1157.4, 1159.5, 1195.1, 1195.3, 1196.1, and 1196.3 to, and to add and repeal Section 1159.4 of, the Harbors and Navigation Code, relating to pilot commissioners, and making an appropriation therefor.

LEGISLATIVE COUNSEL'S DIGEST

SB 1627, Wiggins. Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, Suisun, and Monterey.

(1) Existing law provides for the regulation and licensing of pilots for the Bays of San Francisco, San Pablo, Suisun, and Monterey by the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun. Under existing law, the board consists of 7 members who are appointed by the Governor, with the consent of the Senate. Existing law requires the board to appoint and license the number of pilots needed to carry out these provisions and requires the board to consider various factors in making this determination. Existing law specifies that the board has the sole authority to determine the qualifications and requirements for obtaining a pilot license, and it also authorizes the board to suspend or revoke licenses for misconduct, and it specifies procedures for that action. Existing law establishes various rights and duties of these pilots. Existing law provides for an administrative assistant/secretary of the board and assigns various duties to that position. Existing law also prescribes pilotage rates for vessels and requires vessels inward or outward bound to pay a specified rate of bar pilotage through the Golden Gate and into or out of the Bays of San Francisco, San Pablo, and Suisun, and vessels navigating the waters of Monterey Bay are also required to pay a specified rate. Under existing law,

there is a San Francisco Bar Pilot Pension Plan, and existing law specifies benefits, administration, eligibility, financing, and other matters relating to the operation of the plan. Existing law also imposes various surcharges for, among other things, pilot trainee training, pilot training, and board operations. Existing law authorizes the board to appoint an executive director who serves at the pleasure of the board.

This bill would revise and recast those provisions by making the board a part of the Business, Transportation and Housing Agency, to be renamed the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun. The bill would eliminate the position of the administrative assistant/secretary and reassign its duties to the board. The bill would establish the position of an assistant director who is appointed by, and serves at the pleasure of, the Governor. The bill would make the Secretary of the Business, Transportation and Housing Agency an ex officio member of the board. The bill would also require the Secretary of the Business, Transportation and Housing Agency to act as the executive director during the absence of the executive director from the state or during a vacancy.

The bill would, until January 1, 2011, require that the Bureau of State Audits complete specified audits of the board by December 1, 2009, and January 1, 2010, respectively. The bill would also require the Business, Transportation and Housing Agency to provide comments and recommendations, if any, to the board and the Legislature based on the final audits by the Bureau of State Audits no later than 6 months from the date of the receipt of the audits. The bill would provide for reimbursement of the bureau's actual costs in conducting these audits to the extent that these costs are not covered by a legislative appropriation. The bill would make an appropriation of \$350,000 for this purpose.

(2) Existing law provides for the appointment of a port agent by a majority of the licensed pilots subject to the approval of the board and assigns to the port agent various duties, including carrying out the orders of the board and other applicable laws and otherwise administering the affairs of the pilots.

This bill would specify additional duties of the port agent.

(3) Existing law authorizes the board to issue a subpoena for a witness in a case pending before the board. A witness who disobeys the subpoena is subject to a civil penalty of \$100.

This bill would increase the civil penalty to \$500.

(4) Existing law requires that a register of pilots appointed by the board be kept.

This bill would, instead, require the board to keep specified records of each pilot appointed and licensed by the board and would require pilots to provide the board with a notice of change of specified records within 30 days of the change. The bill would specify that personal information in the records is confidential and would require the board to establish procedures for access to that information. An agent of the board who, without authorization, willfully discloses confidential information is subject to a civil penalty not to exceed \$2,500.

(5) Existing law authorizes an incident review committee to take certain action after full consideration of the evidence related to an incident, misconduct, or other matter for which a license may be revoked or suspended.

This bill would, instead, authorize the board, after full

consideration of the evidence, report, and recommendations from the incident review committee, to take certain action, including remanding the matter to the incident review committee for further investigation. The executive director would be required to notify the board of any pilot or inland pilot who fails, or refuses, to complete training, practice trips, or other corrective action imposed by the board.

(6) Existing law authorizes the revocation or suspension of a pilot or inland pilot license under specified circumstances.

This bill would, additionally, authorize the revocation or suspension of a license for a pilot's or inland pilot's failure or refusal to complete corrective action imposed by the board.

Appropriation: yes.

THE PEOPLE OF THE STATE OF CALIFORNIA DO ENACT AS FOLLOWS:

SECTION 1. The Legislature finds and declares that providing transparency and accountability to the Board of Pilot Commissioners is in the public interest and it is the intent of the Legislature to enhance, preserve, and continue the state's commitment to state licensure of pilotage on the Bays of San Francisco, San Pablo, and Suisun in order to ensure safe navigation, promote commerce, and protect the environment.

SEC. 2. Section 13975 of the Government Code is amended to read:

13975. The Business and Transportation Agency in state government is hereby renamed the Business, Transportation and Housing Agency. The agency consists of the State Department of Alcoholic Beverage Control, the Department of the California Highway Patrol, the Department of Corporations, the Department of Housing and Community Development, the Department of Motor Vehicles, the Department of Real Estate, the Department of Transportation, the Department of Financial Institutions, the Department of Managed Health Care, and the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun; and the California Housing Finance Agency is also located within the Business, Transportation and Housing Agency, as specified in Division 31 (commencing with Section 50000) of the Health and Safety Code.

SEC. 3. Section 1117 is added to the Harbors and Navigation Code, to read:

1117. "Commission investigator" means a person employed by or under contract with the board and assigned to investigate and report on a navigational incident involving a vessel piloted by a pilot or inland pilot licensed by the board, or other matter, incident, misconduct, suspected safety violation, or other activity reported to, or identified by, the board.

SEC. 4. Section 1130 of the Harbors and Navigation Code is amended to read:

1130. (a) A majority of all of the pilots licensed by the board shall appoint one pilot to act as port agent to carry out the orders of the board and other applicable laws, and to otherwise administer the affairs of the pilots. The appointment is subject to the confirmation of the board.

(b) The port agent shall be responsible for the general supervision and management of all matters related to the business and official duties of pilots licensed by the board.

(c) The port agent shall immediately notify the executive officer

of the board of a suspected violation, navigational incident, misconduct, or other rules violation that is reported to him or her or to which he or she is a witness. The board shall adopt regulations for the manner and content of a notice provided pursuant to this section.

SEC. 5. Section 1137 of the Harbors and Navigation Code is amended to read:

1137. (a) The account required pursuant to Section 1136 shall show all of the following:

- (1) The name of each vessel piloted.
- (2) The name of the vessel's master.
- (3) The name of each vessel for which pilotage has been charged or collected.
- (4) The amount charged to or collected for each vessel.
- (5) Any rebates made and allowed and for what amounts.
- (6) Where the vessel is registered.
- (7) The depth of each vessel's draft and its highest gross tonnage.

(8) Whether the vessel was inward or outward bound.

(b) The board shall record the accounts in full detail in a book prepared for that purpose. The account book is a public record.

SEC. 6. Section 1150 of the Harbors and Navigation Code is amended to read:

1150. (a) There is in the Business, Transportation and Housing Agency a Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun, consisting of seven members appointed by the Governor, with the consent of the Senate, as follows:

(1) Two members shall be pilots licensed pursuant to this division.

(2) Two members shall represent the industry and shall be persons currently engaged as owners, officers, directors, employees, or representatives of a firm or association of firms that is a substantial user of pilotage service in the Bay of San Francisco, San Pablo, Suisun, or Monterey, one of whom shall be engaged in the field of tanker company operations, and one of whom shall be engaged in dry cargo operations. The board of directors of a regional maritime trade association controlled by West Coast vessel operators that specifically represents the owners and operators of vessels or barges engaged in transportation by water of cargo or passengers from or to the Pacific area of the United States shall nominate, rank, and submit to the Governor the names of three persons for each category of industry member to be appointed.

(3) Three members shall be public members. Any person may serve as a public member unless otherwise prohibited by law, except that during his or her term of office or within the two years preceding his or her appointment, no public member appointed may have (A) any financial or proprietary interest in the ownership, operation, or management of tugs, cargo, or passenger vessels, (B) sailed under the authority of a federal or state pilot license in waters under the jurisdiction of the board, (C) been employed by a company that is a substantial user of pilot services, or (D) been a consultant or other person providing professional services who had received more than 20 percent in the aggregate of his or her income from a company that is a substantial user of pilot services or an association of companies that are substantial users of pilot services. Ownership of less than one-tenth of 1 percent of the stock of a publicly traded corporation is not a financial or proprietary interest in the ownership of tugs,

cargo, or passenger vessels.

(4) Notwithstanding any other provision of law, this chapter does not prohibit the Governor from notifying the nominating authority identified in paragraph (2) that persons nominated are unacceptable for appointment. Following that notification, the nominating authority shall submit a new list of nominees to the Governor, naming three persons, none of whom were previously nominated, from which the Governor may make the appointment. This process shall be continued until a person nominated by the nominating authority and satisfactory to the Governor has been appointed.

(b) Each of the members appointed pursuant to paragraphs (1) and (2) of subdivision (a) shall be appointed for a four-year term, and may not be appointed for more than two terms. Members appointed pursuant to paragraph (3) of subdivision (a) shall be appointed with staggered four-year terms with the initial four-year terms expiring on December 31 of the years 1988, 1990, and 1991, respectively, and a person may not be appointed for more than two terms. Vacancies on the board for both expired and unexpired terms shall be filled by the appointing power in the manner prescribed by subdivision (a).

(c) A quorum of the board members consists of four members. All actions of the board shall require the vote of four members, a quorum being present.

(d) The Secretary of the Business, Transportation and Housing Agency shall serve as an ex officio member of the board who, without vote, may exercise all other privileges of a member of the board.

SEC. 7. Section 1152 of the Harbors and Navigation Code is amended to read:

1152. (a) The public members of the board shall receive, as compensation for their services, the amount that the board may, from time to time, determine, which shall not exceed six hundred dollars (\$600) each per month.

(b) The appointed members and employees of the board shall also be allowed necessary traveling and other verified expenses incurred by them in the performance of their duties.

SEC. 8. Section 1153 of the Harbors and Navigation Code is amended to read:

1153. (a) The board shall organize itself by electing a president, and shall provide offices in San Francisco or Alameda County, in which it shall meet once a month, and it may adjourn its regular meetings from time to time.

(b) Meetings of the board are subject to the Bagley-Keene Open Meeting Act (Article 9 (commencing with Section 11120) of Chapter 1 of Part 1 of Division 3 of Title 2 of the Government Code).

SEC. 9. Section 1154 of the Harbors and Navigation Code is amended to read:

1154. (a) The board is vested with all functions and duties relating to the administration of this division, except those functions and duties vested in the Secretary of Business, Transportation and Housing.

(b) The board's vested powers include the power to make and enforce rules and regulations that are reasonably necessary to carry out its provisions and to govern its actions. These rules and regulations shall be adopted in accordance with Chapter 3.5 (commencing with Section 11340) of Part 1 of Division 3 of Title 2 of the Government Code.

SEC. 10. Section 1155 of the Harbors and Navigation Code is amended to read:

1155. The president of the board may administer oaths in regard to any matter properly before it and he or she may issue subpoenas for witnesses in like cases. A witness disobeying the subpoena served on him or her shall incur a penalty of five hundred dollars (\$500), for which judgment may be recovered by the board in a civil action. This section shall not apply to proceedings conducted in accordance with Chapter 5 (commencing with Section 11500) of Part 1 of Division 3 of Title 2 of the Government Code.

SEC. 11. Section 1156 of the Harbors and Navigation Code is amended to read:

1156. (a) The board may appoint, fix the compensation of, and from time to time adjust the compensation of, an executive director who is exempt from the civil service laws, and other employees as may be necessary. The executive director shall be well qualified for the position, with experience in government. The executive director may perform all duties, exercise all powers, discharge all responsibilities, and administer and enforce all laws, rules, and regulations under the jurisdiction of the board, with the approval of the board, including, but not limited to, all of the following:

(1) The administration of personnel employed by the board in accordance with the civil service laws.

(2) To serve as treasurer of the board and keep, maintain, and provide the board with all statements of accounts, records of receipts, and disbursements of the board in accordance with the law.

(3) The issuance and countersigning of licenses that shall also be signed by the president of the board.

(4) The administration of matters and the maintenance of files pertaining to action taken against licenses issued by the board.

(5) The administration of investigations of, and reporting on, a navigational incident or other matter for which a license issued by the board may be revoked or suspended.

(6) To work with board members, staff, and other interested stakeholders to recommend improvements in the pilot training program.

(7) Under the direction of the board, to coordinate with other state and federal agencies charged with protecting the environment and with the oil and hazardous chemical shipping industry.

(8) Any other function, task, or duty as may reasonably be assigned by the president of the board, including, but not limited to, performing research and obtaining documents and other evidence for board activities, including rate hearings.

(b) The Governor shall appoint one assistant director to serve at the pleasure of the Governor. The assistant director shall have the duties as assigned by the executive director, and shall be responsible to the executive director for the performance of his or her duties.

(c) The board may employ personnel necessary to carry out the purposes of this chapter. All personnel shall be appointed pursuant to the State Civil Service Act (Part 1 (commencing with Section 18000) of Division 5 of Title 2 of the Government Code), except for the executive director and the assistant director, who shall be exempt from state civil service. The board may fix the compensation of, and from time to time adjust the compensation of, any employees as may be necessary.

(d) All personnel of the board shall be appointed, directed, and controlled by the board, the executive director, or the board's authorized deputies or agents to whom it may delegate its powers.

(e) The board may contract and employ commission investigators. The board shall adopt regulations for the minimum standards for a commission investigator that shall include, but are not limited to, a basic knowledge of investigative techniques and maritime issues.

SEC. 11.5 Section 1156.5 of the Harbors and Navigation Code is amended to read:

1156.5. (a) The executive director shall serve at the pleasure of the board and shall be under the direct supervision of the board. The term of office to which the executive director is appointed is five years.

(b) The Secretary of Business, Transportation and Housing, or his or her designee, shall act as the executive director during the absence from the state or other temporary absence, disability, or unavailability of the executive director, or during a vacancy in that position.

SEC. 12. Section 1156.6 of the Harbors and Navigation Code is amended to read:

1156.6. (a) Whenever suspected safety standard violations concerning pilot hoists, pilot ladders, or the proper rigging of pilot hoists or pilot ladders are reported to the board, the executive director shall assign a commission investigator to personally inspect the equipment for its compliance with the relevant safety standards promulgated by the United States Coast Guard and the International Maritime Organization. The commission investigator shall report preliminary conclusions, including an assessment of the equipment's compliance with the relevant safety standards, to the executive director as soon as possible. If, in the preliminary report, the equipment is found to be in violation, or in likely violation in the opinion of the commission investigator, of the relevant safety standards, the executive director shall immediately alert the Coast Guard Marine Safety Office. The commission investigator shall submit a written report to the incident review committee as established by subdivision (a) of Section 1180.3 that shall remain confidential until reported to the board. The incident review committee, in turn, shall report its findings and recommendations, if any, to the board. The board shall receive the incident review committee's findings, which may include other reports, information, or statements from interested parties. The board shall specify, by regulation, the information that shall be contained in the report.

(b) This section applies to the pilotage grounds, as defined in Section 1114.5. Whenever a vessel passes outside of the pilotage grounds, the commission investigator's report shall include that fact along with a description of the incident.

(c) The record of the investigation and the board's findings and recommendations, if any, shall be a public record maintained by the board.

SEC. 13. Section 1157 of the Harbors and Navigation Code is amended to read:

1157. The board shall keep a written record of all the board's proceedings and acts.

(a) The board shall also keep a complete record of each pilot appointed and licensed by the board that includes at a minimum, his or her current mailing address, residence, the date of the initial issuance and renewal of the license, the date of completion for initial and any subsequent training, and a record of any reports of meritorious activities, commendation, misconduct, safety violations,

or other incidents or information related or relevant to the issuance and use of his or her pilot license.

(b) All pilots or inland pilots licensed by the board shall provide the board with written notice of any change of name, mailing address, or residence within 30 days of that change in a manner prescribed by the board.

SEC. 14. Section 1157.1 is added to the Harbors and Navigation Code, to read:

1157.1. (a) Except as provided in Section 1157.4, all records of the board relating to the personal information of a pilot, collected pursuant to subdivision (b) of Section 1157, are confidential and shall not be open to public inspection.

(b) For purposes of this section, "personal information" means information, other than the name and mailing address, that identifies an individual, including an individual's photograph, social security number, address, telephone number, and medical or disability information, but does not include other information related to licensing such as incidents, rules or safety violations, misconduct, training records, commendations, and license status.

SEC. 15. Section 1157.2 is added to the Harbors and Navigation Code, to read:

1157.2. The board shall establish procedures for access to confidential or restricted information from its records to protect the confidentiality of its employees and licensees. If confidential or restricted information is released to an agent of a person authorized to obtain information, the person shall require the agent to take all steps necessary to ensure confidentiality and prevent the release of information to a third party. An agent shall not obtain or use confidential or restricted records for any purpose other than the reason the information was requested.

SEC. 16. Section 1157.3 is added to the Harbors and Navigation Code, to read:

1157.3. A member of the board, the executive director, the assistant director, or an employee of the board who willfully discloses confidential information from the board record to a person not authorized to receive it shall be liable for a civil penalty not to exceed two thousand five hundred dollars (\$2,500) for each violation, which may be assessed and recovered in a civil action.

SEC. 17. Section 1157.4 is added to the Harbors and Navigation Code, to read:

1157.4. Upon a request to the board by a federal, state, or local law enforcement agency, the executive director shall make available to the requesting agency any information contained in the board's records.

SEC. 18. Section 1158 of the Harbors and Navigation Code is amended to read:

1158. The public members, the executive director, the assistant director, and employees of the board shall not engage in an employment, activity, or enterprise that is clearly inconsistent, incompatible, in conflict with, or inimical to his or her duties as a state officer or employee or make, participate in making, or attempt to use his or her official position to in any way influence a governmental decision in which he or she knows or has reason to know that he or she, or any member of his or her immediate family, has a financial interest.

SEC. 19. Section 1159 of the Harbors and Navigation Code is amended to read:

1159. (a) All moneys received by the board pursuant to the provisions of any law shall be accounted for at the close of each month to the Controller in the form that the Controller may prescribe and, at the same time on the order of the Controller, all these moneys shall be paid into the State Treasury to the credit of the Board of Pilot Commissioners' Special Fund.

(b) Notwithstanding Section 13340 of the Government Code, the moneys deposited in the State Treasury to the credit of the Board of Pilot Commissioners' Special Fund are appropriated without regard to fiscal years for the payment of the compensation and expenses of the board and its officers and employees.

SEC. 20. Section 1159.1 of the Harbors and Navigation Code, as added by Section 9 of Chapter 1423 of the Statutes of 1990, is amended to read:

1159.1. (a) The vessel shall pay a board operations surcharge, the purpose of which is to fully compensate the board and the Business, Transportation and Housing Agency for the official services, staff services, and incidental expenses of the board and agency. The amount of the surcharge shall be 7.5 percent of all pilotage fees charged by pilots and inland pilots, pursuant to Sections 1190 and 1191 unless the board establishes, with the approval of the Department of Finance, a lesser percentage, not to exceed any percentage consistent with subdivision (d).

(b) The surcharge shall be billed and collected by the pilots and inland pilots. The pilots and inland pilots shall pay all surcharges collected by them to the board monthly or at such later time as the board may direct.

(c) The board shall quarterly review its ongoing and anticipated expenses and adjust the surcharge to reflect any changes which have occurred since the last adjustment.

(d) The board operations surcharge shall not represent a percentage significantly more than that required to support the board and any costs of the Business, Transportation and Housing Agency related to the administration of the board pursuant to subdivision (a) in addition to the maintenance of a reasonable reserve.

SEC. 21. Section 1159.4 is added to the Harbors and Navigation Code, to read:

1159.4. (a) The Bureau of State Audits by January 1, 2010, shall complete a comprehensive performance audit of the Board of Pilot Commissioners, and by December 1, 2009, shall complete a comprehensive financial audit of the Board of Pilot Commissioners pursuant to Chapter 6.5 (commencing with Section 8543) of Division 1 of Title 2 of the Government Code.

(b) (1) The actual costs incurred by the Bureau of State Audits in conducting the audits required pursuant to this section shall be paid out of the operations surcharge collected pursuant to Section 1159.1.

(2) The Bureau of State Audits shall apprise the board of the estimated costs of each of the two audits prior to initiating each audit.

(3) Notwithstanding subdivision (d) of Section 1159.1, the board shall make surcharge adjustments pursuant to subdivision (c) of Section 1159.1, as necessary, to comply with this section. The actual costs incurred in conducting audits required by this section shall be considered official services and shall include the staff services and incidental expenses of both the board and the bureau.

(4) The board shall reimburse the Bureau of State Audits for the

actual costs incurred in conducting the audits required by this section. Reimbursement shall be made upon a demonstration by the bureau that any costs incurred in conducting the audits were not otherwise covered by an appropriation made by the Legislature for this purpose. If needed, these costs may be reimbursed through an interagency agreement between the board and the Bureau of State Audits.

(c) This section shall remain in effect only until January 1, 2011, and as of that date is repealed, unless a later enacted statute, that is enacted before January 1, 2011, deletes or extends that date.

SEC. 22. Section 1159.5 is added to the Harbors and Navigation Code, to read:

1159.5. The Business, Transportation and Housing Agency shall provide comments and recommendations, if any, to the board and the Legislature based on the final audits of the Bureau of State Audits completed pursuant to Section 1159.4 no later than six months from the date that the agency receives the final audit.

SEC. 23. Section 1171.5 of the Harbors and Navigation Code is amended to read:

1171.5. (a) The board shall adopt, by regulation, licensing standards that equal or exceed standards for obtaining federal endorsements and that conform with and support the state policy specified in Sections 1100 and 1101.

(b) The board shall adopt reasonable rules and regulations that require pilots to be qualified to perform all pilot duties.

(c) The board shall adopt, by regulation, training standards and a training program for pilots, inland pilots, and pilot trainees. In the case of pilot trainees, the training program shall be for a minimum of one year and a maximum of three years. In the case of pilots and inland pilots, the board shall specify the type, nature, duration, and frequency of the training required and the identity of the pilots or inland pilots who are required to undergo training in the next 12-month period. Pursuant to Section 1182, the license of a pilot or inland pilot may be revoked or suspended if he or she fails to complete the training required by this subdivision during the period specified. The board shall also require that an evaluation of the pilot's or inland pilot's performance be prepared by the institution selected by the board to provide pilot training, and the institution shall provide copies of the evaluation to the pilot or inland pilot and to the pilot evaluation committee.

(d) The board shall adopt, by regulation, the qualifications, standards, and rating criteria for admission of pilot trainees to the training program. Notwithstanding subdivision (f), the board shall administer and conduct the pilot trainee admission selection in accordance with the regulations for admission.

(e) The board shall establish a pilot evaluation committee consisting of five active pilots who each have at least 10 years' experience as a pilot on the Bays of San Francisco, San Pablo, and Suisun. The board shall select the members of the pilot evaluation committee. A member may not serve for more than two four-year terms, except that two of the initial members appointed to the pilot evaluation committee shall serve terms of two years.

(f) The pilot evaluation committee shall conduct and supervise the pilot training programs pursuant to the direction and regulation of the board and consistent with the intent of this division.

(g) The board shall issue a certificate of completion to each

pilot trainee who satisfactorily completes the training program. The board shall not issue a pilot's license to any person who does not receive a certificate of completion of the training program from the board, although the board may refuse to issue a pilot license to a pilot trainee who has received this certificate.

(h) The training and continuing education programs for pilots, inland pilots, and pilot trainees shall be funded from revenues collected for these purposes as determined by the board pursuant to Sections 1195 and 1196 and deposited into the Board of Pilot Commissioners' Special Fund pursuant to Section 1159.

SEC. 24. Section 1180.6 of the Harbors and Navigation Code is amended to read:

1180.6. (a) The board, after full consideration of the evidence, report, and recommendations presented by the incident review committee relating to an incident, misconduct, or other matter pursuant to Section 1180.3, shall take one or more of the following actions:

(1) Serve an accusation for suspension or revocation of the pilot's or inland pilot's license on the pilot or inland pilot, as provided in Chapter 5 (commencing with Section 11500) of Part 1 of Division 3 of Title 2 of the Government Code, pursuant to Sections 1181 and 1182.

(2) Enter into a written stipulation for corrective action to be performed by the pilot or inland pilot, which may include, but is not limited to, further training or supervised practice trips.

(3) Provide counseling for the pilot or inland pilot relating to the duties and obligations of a pilot.

(4) Issue a warning letter of reprimand to the pilot or inland pilot.

(5) Take any other action, as provided in the guidelines adopted pursuant to subdivision (e).

(6) Close the investigation without further action.

(7) Remand the matter to the incident review committee for further investigation.

(b) Action required pursuant to subdivision (a) shall be taken by a majority vote of the board.

(c) A member of the board shall not sit on the board as a trier of fact for those cases in which he or she has served on the incident review committee recommending action to the board.

(d) The executive director shall note any action taken by the board pursuant to this section in a pilot's or inland pilot's record and shall establish a suspense file to ensure that all training, practice trips, or other corrective action required to be performed pursuant to subdivision (a) by the pilot or inland pilot are completed as required. The executive director shall report to the board each month on the progress of any training, supervised practice trips, or other corrective action or the completion of any other action required pursuant to subdivision (a).

(e) The executive director shall notify the board of a pilot or inland pilot who fails, or refuses, to complete training, practice trips, or other corrective action imposed by the board pursuant to subdivision (a). If the board determines that the pilot or inland pilot has intentionally failed to complete training, practice trips, or other corrective action, the board may take additional action as specified in subdivision (a).

(f) The board shall adopt guidelines for the determination by the

incident review committee of the action to be taken pursuant to subdivision (a) at the completion of an investigation conducted pursuant to Section 1180.3.

SEC. 25. Section 1181 of the Harbors and Navigation Code is amended to read:

1181. The license of a pilot or inland pilot may be revoked or suspended before its expiration only for reasons of misconduct, which shall include, but not be limited to, the following:

(a) Neglect, for 30 days after it becomes due, to render an account to the board of all money received for pilotage.

(b) Neglect, for 30 days after it becomes due, to pay over to the board the percentage of all pilotage money received, as set by the board.

(c) Rendering to the board a false account of pilotage received.

(d) Absence from duty for more than one month at any one time without leave granted by the board, unless sickness or personal injury causes the absence. This subdivision does not apply to inland pilots.

(e) Refusing to exhibit the pilot or inland pilot license when requested to do so by the master of any vessel boarded.

(f) Intoxication or being under the influence of any substance or combination of substances that so affects the nervous system, brain, or muscles as to impair, to an appreciable degree, the ability to conduct the duties of a pilot or inland pilot while on duty.

(g) Negligently, ignorantly, or willfully running a vessel on shore, or otherwise rendering it liable to damage, or otherwise causing injury to persons or damage to property. However, this subdivision does not apply to a vessel of less than 300 gross tons unless a pilot or inland pilot is required by law.

(h) Willful violation of the rules and regulations adopted by the board for the government of pilots or inland pilots.

(i) Inability to comply with the standards of health or physical condition requisite to the duties of a pilot or inland pilot, but in that case the burden of proving compliance with these standards is upon the licensee, unless prior to the hearing the licensee takes and passes those tests or examinations required by the board.

(j) Failure or refusal, to complete training, practice trips, or other corrective action imposed on that pilot or inland pilot by the board pursuant to Section 1180.6.

SEC. 26. Section 1182 of the Harbors and Navigation Code is amended to read:

1182. If, after a hearing, the board finds that the pilot or inland pilot is guilty of misconduct sufficient for deprivation of the license, the board shall revoke or suspend the license of the pilot or inland pilot. The order shall be entered in the minutes and placed in the record of the pilot maintained pursuant to Section 1157. The proceedings shall be conducted in accordance with Chapter 5 (commencing with Section 11500) of Part 1 of Division 3 of Title 2 of the Government Code, and the board shall have all the powers granted pursuant to that chapter.

SEC. 27. Section 1195.1 is added to the Harbors and Navigation Code, to read:

1195.1. (a) The moneys charged and collected each month from the pilot trainee surcharge pursuant to Section 1195 shall be paid to the Board of Pilot Commissioners' Special Fund pursuant to Section 1159. The moneys shall be used only to fund the pilot trainee training program referred to in subdivision (h) of Section 1171.5 and Section

1195.3.

(b) Information regarding moneys remitted to the Board of Pilot Commissioners' Special Fund pursuant to Section 1159 collected from the surcharge authorized pursuant to Section 1195, or otherwise collected by the board for that purpose, and information regarding moneys spent as pilot trainee training program expenses authorized by Section 1195.3 shall be made available to the public upon request and to the board or its finance committee.

SEC. 28. Section 1195.3 is added to the Harbors and Navigation Code, to read:

1195.3. Expenses of the pilot trainee program shall include all costs incurred by the board in the operation and administration of the pilot trainee training program and all costs resulting from any contracts entered into for the purchase or lease of goods and services required by the board, including, but not limited to, the costs of testing, test preparation, advertising and soliciting for trainee applicants, trainee stipends, worker's compensation insurance premiums, reimbursement of costs of services provided to the board by other governmental entities, and for the costs for any other goods and services necessary for effectuating the purposes of training as determined by the board.

SEC. 29. Section 1196.1 is added to the Harbors and Navigation Code, to read:

1196.1. (a) The moneys charged and collected each month from the pilot and inland pilot continuing education surcharge pursuant to Section 1196 shall be paid to the Board of Pilot Commissioners' Special Fund pursuant to Section 1159. The moneys shall be used only to fund the pilot and inland pilot continuing education program referred to in subdivision (h) of Section 1171.5 and Section 1196.3.

(b) Information regarding moneys remitted to the Board of Pilot Commissioners' Special Fund pursuant to Section 1159 collected from the surcharge authorized pursuant to Section 1196, or otherwise collected by the board for that purpose, and information regarding moneys spent as pilot and inland pilot continuing education expenses authorized by Section 1196.3 shall be made available to the public upon request and to the board or its finance committee.

SEC. 30. Section 1196.3 is added to the Harbors and Navigation Code, to read:

1196.3. Pilot and inland pilot continuing education expenses shall include all costs incurred by the board in the operation and administration of the pilot and inland pilot continuing education program and all costs resulting from any contracts entered into for the purchase or lease of goods and services required by the board, including, but not limited to, the reimbursement of costs of services provided to the board by other governmental entities, and for the costs for any other goods and services necessary for effectuating the purposes of continuing education as determined by the board.

SEC. 31. The sum of three hundred fifty thousand dollars (\$350,000) is hereby appropriated from the operations surcharge collected pursuant to Section 1159.1 of the Harbors and Navigation Code to the Bureau of State Audits for the purpose of reimbursing the bureau for conducting the audits required pursuant to subdivision (a) of Section 1159.4 of the Harbors and Navigation Code.

Enclosure 4

Advance Agenda of November 6-7, 2008
Regional Meeting of Pilot Commissions

M E E T I N G N O T I C E

R E G I O N A L M E E T I N G

**Oregon Board of Maritime Pilots
Board of Pilot Commissioners for the Bays of San Francisco,
San Pablo & Suisun – California
Washington Board of Pilot Commissioners
Alaska Board of Marine Pilots
Pacific Pilotage Authority – British Columbia**

W H E R E :

**Port of Portland Commission Room
121 N.W. Everett
Portland Oregon
November 6-7, 2008
8:30 a.m.**

*If you would like to receive any of the documents referenced in this agenda, please contact the Board's office.
This meeting is being held in a facility that is accessible for persons with disabilities. If you need some form of assistance to participate in this meeting due to a disability, please notify the Administrator at 971-673-1530 at least two working days prior to the meeting.*

**REGIONAL MEETING
NOVEMBER 6-7, 2008
ADVANCE AGENDA**

November 6

8:30	Introductions by each Authority	
10:30	Break	
10:45	Navigation Technology	COLRIP Presentation Mike Miller, Pres., Board of Pilot Commissioners, S.F.
11:30	Zero Tolerance	Discussion All
12:00	Lunch	Phil Cummings, BMC, USCG - Presentation on the NVIC 04-08
1:30	Cosco Busan Update	Mike Miller, Pres., Pat Maloney, Exec. Dir., Board of Pilot Commissioners, S.F.
2:15	Best Practices for State Pilot Commissions in Preparing for and Responding to Major Marine Incidents	Paul Kirchner, Exec. Dir., American Pilots Association
2:45	Break	
3:00	Pilot Liability	Kevin Davis, Attorney at Law
4:00	Criminalization of the Marine Sector	Kevin Obermeyer, Pres. & CEO, Pacific Pilotage Authority, CA
4:30	Adjourn	

November 7

8:30	Ratemaking Process	Discussion All
9:15	Incident Review Process	Discussion All
10:15	Break	
10:30	Training & Continued Professional Development	Manned Model Evaluation Trip Report – Oregon Board of Maritime Pilots Pilot Assessments & Training – Kevin Obermeyer
11:30	Pilot Safety	Discussion All

12:30	Lunch Break	
2:00	Vessel Exemption Process	Discussion All
3:00	Wrap up discussion Adjourn	Possible mechanisms for communication among the Boards

APPENDIX 1

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

APPENDIX 1:
WITNESS INFORMATION

- I. PILOTS ON BOARD OTHER VESSELS ON MORNING OF NOVEMBER 7, 2007
 - A. Capt. Lobo
 - B. Capt. Gates
 - C. Capt. Gans
 - D. Capt. Dohm
 - E. Capt. Villas
 - F. Capt. S. Teague

- II. PILOTS ON BOARD *M/V COSCO BUSAN* DURING NOVEMBER 2007 CALL ON SAN FRANCISCO
 - A. Capt. Nyberg
 - B. Capt. Hoburg
 - C. Capt. Atthowe
 - D. Capt. Kelso
 - E. Capt. Carlier

- III. WITNESSES FROM OTHER VESSELS ON BAY DURING MORNING OF NOVEMBER 7, 2007
 - A. Capt. Coney
 - B. Capt. McNamara
 - C. Operator Albernez

- IV. OTHER WITNESSES
 - A. Capt. McIsaac

- V. OTHER AVAILABLE WITNESS INFORMATION

In addition to the witnesses above, the IRC had access to interview transcripts released by the National Transportation Safety Board. These include transcripts of interviews of Capt. John Cota, and various VTS personnel. The IRC could not obtain any meaningful access to any of the crew members of the *M/V COSCO BUSAN*.

APPENDIX 2

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

APPENDIX 2:
CAPTAIN COTA'S PRE-COSCO BUSAN INCIDENT RECORD

Captain Cota was first licensed as a state pilot in 1981. Due to changes in the Board's incident investigation and reporting practices, incident summaries are substantially more detailed and structured for incidents investigated since establishment of the Incident Review Committee in 1993 than for those investigated before its establishment.

INCIDENT INVESTIGATION REPORTING PROCEDURES

The Incident Review Committee (IRC) and the current procedures for investigating piloting incidents were established by statute in 1993. The IRC's responsibilities include investigating and reporting to the full Pilot Commission all reports of misconduct or navigational incidents involving a vessel piloted by a pilot licensed by the Commission.

Written guidelines for the conduct and reporting of investigations by the IRC and for determining appropriate corrective action are found at Title 7, California Code of Regulations (CCR), Section 210. When a vessel with an assigned pilot or inland pilot on board is involved in a navigational incident, including, but not limited to, "all incidents involving the grounding of a vessel, the striking of any object or injury or damage to persons or property" the pilot or inland pilot is required to report the incident. 7 CCR Section 219(g) and (h). Failure to report an incident can result in disciplinary action.

Before 1993, piloting incidents were investigated by one of the Commission members. The investigations were less structured and the results were generally reported orally to the Commission, leaving a relatively sparse record. There were no statutory or regulatory provisions or written guidelines for determining appropriate corrective action, or requiring a clear determination of whether pilot error was involved unless the incident resulted in the filing of an accusation seeking suspension or revocation of the pilot's license.

For incidents that did not result in the filing of an accusation, most were closed with a terse notation in the Board's minutes of "pilot counseled, case closed."

That notation appears to have been used both for incidents involving relatively minor pilot error, as well as for incidents in which there was no pilot error but which appeared to provide an opportunity for counseling on means to avoid a similar incident.

CAPTAIN COTA'S INCIDENT HISTORY BEFORE 1993

In the 13 years before the establishment of the IRC, Captain Cota was involved in a total of eight incidents. Three appeared to involve relatively minor damage during docking or undocking. One involved a flat tow (the movement of a ship without the aid of its engines) in which the ship's hull was dented when set down on a pier face by wind. One involved striking a submerged object in the channel off Potrero Point. One involved an anchor that fouled an underwater phone line in the vicinity of a terminal. One involved a soft grounding when there was poor response from the ship. One was a report of wake damage by a moored vessel. It is not possible from the sparse record to determine accurately how many of these involved some level of pilot error. The last of these incidents was in 1991.

The precise number of ship movements each pilot made was not tracked. But using averages, Captain Cota would have acted as pilot on an estimated 1500 ship movements between the time he was first licensed and the incident in 1991. The above incident record would equate to an incident-free rate of about 99.5%.

COTA INCIDENT HISTORY SINCE 1993

Since its establishment in 1993 (and before the COSCO BUSAN allision), the IRC investigated four navigational incidents involving Captain Cota, and one

incident on board the USS TARAWA, which was treated as a medical issue. Those incidents are summarized below:

A. 23 April 1997 - MARE CASPIUM - Allision with gantry crane at Oakland 37

- IRC finding: "Minor pilot error - positioning of crane contributed to incident."

The inbound, 642-foot long container ship MARE CASPIUM was being handled by a pilot trainee under Captain Cota's supervision. The ship's intended berth was in an exposed area of the Oakland Outer Harbor and onshore winds were of sufficient strength to make the docking challenging.

On the ship's final approach to the berth, a gust of wind pushed her bow in about two degrees from parallel, causing light contact between the cap rail and two containers on the ship and the outboard legs of the gantry crane. The contact was so light that none of the officers on the ship felt it or were otherwise aware of it until notified by shoreside personnel.

Damage was deemed primarily cosmetic and consisted of a one-inch gouge on the cap rail requiring only touch up paint, a one foot long 3" by 1" gouge on the interior corners of the crane's outboard legs (estimated repair costs were \$2,500) and a slight indentation to two containers. The damage did not result in any downtime for either the crane or the containers.

The Commission directed that a letter be written to the terminal operator advising that the Commission had concluded that the crane's position had contributed to the incident and recommending that cranes be moved away from the intended berth before a ship's arrival.

B. 15 July 2002 - M/V CHIMBORAZO - "*allision* with Amorco wharf"

- *IRC finding: "No pilot error."*

As the CHIMBORAZO was preparing to depart her berth, the ship's crew was taking in her mooring lines when one of the lines caught first on a metal strip on the pier and then on a pipe cover. The stern of the ship landed on the pier during the attempt by the crew to haul in the line (using the mechanical power of a winch) and the pilot's attempt to reduce the strain on the line. The hard landing jarred loose some outboard planking on the pier.

As was the case in the MARE CASPIUM incident, a number of forces are at play during a vessel's docking and undocking. In addition to wind and current, these forces can include those caused when a mooring line is being hauled in with the use of the ship's winches. If a line happens to foul (catch on a piece of equipment) and the crew is not immediately aware of it or does not respond quickly enough, it can cause the vessel to be pulled back against the dock.

During a vessel's undocking, the pilot may request that mooring lines be brought aboard in a particular order but oversight of the crew involved in line-handling is ordinarily left to the ship's officers. If the pilot becomes aware of a line coming under tension such as happened here, he or she may use the ship's engine or one of the tugs to try to ease that tension so that the line can be freed and brought aboard. If there is a possibility of a line in the water anywhere near the propeller, the pilot may not be able to use the ship's engine in response until that line has been cleared.

Here Captain Cota used a tug to help ease the tension on the fouled mooring line. It appears this would have been successful if the crew had stopped heaving in on the line. The IRC found no pilot error.

C. 6 October 2002 - M/V GINGA KITE - *vessel interaction* with moored tanker (ALLEGIANCE) at Avon Terminal

- *IRC finding: "No attributable pilot error."*

As used in this investigation, the term "vessel interaction" refers to the hydraulic effect on a moored vessel caused by the displacement of water as another vessel passes nearby. It does not involve any contact between the two vessels. The degree of vessel interaction will vary with a number of factors, including the number, elasticity and condition of the mooring lines on the moored vessel and how well those lines are being tended, as well as the size, speed and proximity of the passing vessel and the depth and contour of the navigation channel.

Here, both the moored vessel and the passing vessel had left before the matter was brought to the IRC's attention. The report of the incident came from the terminal operator, not the vessel that had been moored. There had been no damage to the terminal or the moored vessel, but the terminal operator reported that the passage of the GINGA KITE had caused the moored tanker to move more than two feet from the dock, requiring a temporary shut down of transfer operations in accordance with local regulations.

Based on the information that was available, the IRC determined that the GINGA KITE had passed another vessel moored at a terminal a half mile downstream from the ALLEGIANCE at Half Ahead (8 knots) with no observed effects on that moored vessel. GINGA KITE passed the

ALLEGIANCE five minutes later, still at Half Ahead. She was stemming a 0.8 kt. current. Under the circumstances, the IRC felt that her speed did not seem excessive, noting:

“The fact that a relatively small vessel (485 ft) caused a much larger vessel to move a modest distance (4 ft) off the berth tends to indicate that the moored vessel may have had breast lines that were not tight enough or were too elastic.”

Consistent with using the investigation report as an opportunity to remind pilots of means to reduce the risk of similar incidents, the IRC also noted: “Regardless of causes of this incident, pilots should pay close attention to potential vessel interaction situations and proceed at minimum speeds consistent with good vessel maneuverability.”

The term “No attributable pilot error” has been used by the IRC when the available evidence does not support a finding of pilot error but for one reason or another, corroborating information on some issues was unavailable and the circumstances did not warrant keeping the file open to obtain additional information.

In this instance, the speed at Half Ahead stemming a 0.8 knot current did not appear excessive for the circumstances. The piloted vessel passed another moored vessel and a dredge at the same speed and in the same general vicinity with no apparent adverse effects.

No damage was done to the ALLEGIANCE, the berth, the mooring lines or the cargo transfer hoses. The moored vessel stopped cargo operations during the passing, as would be good practice, given the vessel's exposed position only 100 yards from the main shipping channel.

Subsequent vessel calls at this terminal reportedly have required extra mooring lines.

D. USS TARAWA 09 October 2004 -

- IRC Finding: Treated as a medical issue

Captain Cota's reportedly irrational and offensive behavior as pilot of a Naval vessel was treated as a medical issue. He was ultimately found fit for duty (FFD) following evaluation by two psychiatrists (one retained by the Commission, one he retained), and after a trial period, was returned to unrestricted duty in August 2005.

The IRC commenced its investigation when the Port Agent reported what was reported to him to be irrational and/or unprofessional conduct by Captain Cota prior to and after boarding the USS TARAWA at the offshore pilot station for an inbound trip to the San Francisco waterfront.

Captain Cota had reportedly asked the crew to remove a tag line (used by the crew to hoist the pilot ladder when not in use), which is not permitted on commercial ships and which was deemed a safety hazard by the pilot. When the crew refused, he cut it off with a pocketknife. Once aboard the ship, Captain Cota reportedly used offensive and derogatory language with the TARAWA's captain and crew ("What are you trying to do, kill a **** pilot?").

Captain Cota was reported to have docked the ship safely under challenging environmental conditions, thus his ship handling was not considered to be in issue.

The IRC treated the matter as a medical issue as it did not appear to fit into any definition of "misconduct" in Harbors and Navigation Code (HNC) Section 1181. The Port Agent removed Captain Cota from normal assignment rotation until his fitness for duty could be assessed.¹

Evaluations and testing were conducted by both Captain Cota's own physicians, including a psychiatrist, and by Board-retained physicians (including an examining physician on the Board's approved list and a Qualified Medical Evaluator in Psychiatry). Additionally, Captain Cota underwent extensive psychological testing by a licensed psychologist.

In the opinion of each of the physicians who examined him, Captain Cota was found to have met the requisite physical and mental fitness standards applicable to state-licensed pilots

Following a period of re-entry and completion of a 5-month trial of performing duties without further incident, the matter was closed with a "letter of concern" issued to Captain Cota in August 2005 by the IRC. Among other things the letter noted: "While the IRC has treated this incident as a medical issue, it has informed you that the conduct described by the captain and officers of the TARAWA was, in the IRC's view, unprofessional and had the potential of distracting the bridge team from the safe navigation of the vessel." The letter of concern was made a part of Captain Cota's file with the Board.

¹ The Port Agent's duties are described in Section 218 of the Board's regulations, and include the assignment of pilots to ships and to report to the Board matters which affect the ability of a pilot to carry out his or her duties. Title 7, Calif. Code of Regulations, Section 218.

Most of the information as to what transpired on board the TARAWA came from e-mails and witness statements provided by the Navy. The captain of the TARAWA was interviewed by phone, but most of the witnesses were not interviewed in person. Captain Cota disputed some aspects of those statements and believed his conduct to have been understandable given what he felt to be a safety issue.

To place this in context, pilot ladder incidents involving serious injuries and a number of deaths have been of significant concern to pilots worldwide. Several years prior to this incident, the San Francisco Bar Pilots had been instrumental in having a state law passed requiring the IRC to investigate reports of pilot ladder violations. Captain Cota had reportedly participated in that effort.

While Captain Cota's safety concerns regarding the tag lines found on the TARAWA's pilot ladder did not excuse the unprofessional conduct reported by witnesses in this case, it did provide a mitigating factor.

E. 20 Feb. 2006 - M/V PIONEER *grounding* in New York Slough

- IRC Finding: issued letter of reprimand noting loss of situational awareness.

Captain Cota piloted a 730 ft single screw gypsum carrier with twin rudders from Anchorage 9 to Domtar Terminal, located on the Sacramento River in Antioch. Two tugs were made up to assist in maneuvering through New York Slough. Flood current was 0.9 kts.

The ship proceeded at Dead Slow Ahead, speed 6 kts over the ground. Approaching Light 10 in the East Reach, Captain Cota ordered a turn to port

for a 26 degree bend in the channel. The vessel did not turn as fast as the bend due to the slow speed and following current and grounded gently in the mud at the starboard bow. The vessel's bow was refloated after allowing another vessel to pass, and proceeded to terminal uneventfully.

There were several mitigating circumstances to this soft grounding of the bow in the mud at the edge of a channel in a river bend. The vessel was difficult to steer at slow speeds due to the unusual rudder configuration. The bend in the river at 26 degrees was a significant turn. The vessel had a following 0.9 knot current, adding to the steering difficulty. The pilot was proceeding at Dead Slow Ahead, the slowest the vessel could go and still have steerageway. With the following current, the vessel was making six knots. The vessel was being followed by another ship. The vessel was refloated without damage or delay after the trailing ship passed.

Nevertheless, the IRC concluded that the pilot had ample resources to safely maneuver the vessel through New York Slough. It felt that he should have been able to recognize more quickly that the vessel would not be able to make the turn unassisted and therefore did not take timely corrective action. It therefore issued a Warning Letter of Reprimand.

By November 2007, as Captain Cota prepared to pilot the COSCO BUSAN, the IRC estimated that Captain Cota had piloted in excess of 3400 ships over the course of his career. Thus up to the time of the COSCO BUSAN, over 99.6% of his transits would have been incident-free.

APPENDIX 3

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

APPENDIX 3:
COSCO BUSAN IRC/NTSB PARTICIPATION

<i>DATE</i>	<i>EVENT</i>
November 7, 2007 Wednesday	<i>M/V COSCO BUSAN</i> allides w/ San Francisco-Oakland Bay Bridge Board of Pilots (“BOP”) advised by Port Agent of allision. Executive Director visits San Francisco Bar Pilot’s (“SFBP”) office and is briefed by Port Agent.
November 8, 2007 Thursday	R. Reynolds assigned as IRC investigator.
November 9, 2007 Friday	R Reynolds boards <i>M/V COSCO BUSAN</i> while at anchor.
November 10, 2007 Saturday	Executive Director assigned to NTSP investigation team.
November 11, 2007 Sunday	Executive Director attends NTSB meetings and is assigned to Operations Group.
November 12, 2007 Monday (Holiday)	Executive director continues working with NTSB Operations Group. BOPC Investigator continues investigation.
November 13, 2007 Tuesday	Executive director continues working with NTSB Operations Group. BOPC Investigator continues investigation.
November 14, 2007 Wednesday	Executive director continues working with NTSB Operations Group. BOPC Investigator continues investigation.
November 15, 2007 Thursday	Executive director continues working with NTSB Operations Group. BOPC Investigator continues investigation.

<i>DATE</i>	<i>EVENT</i>
November 16, 2007 Friday	Executive director continues working with NTSB Operations Group. BOPC Investigator continues investigation. Executive Director on board <i>M/V COSCO BUSAN</i> for shift from Anchorage 9 to drydock at Pier 70.
November 17, 2007 Saturday	Begin preparation of IRC Report.
November 18, 2007 Sunday	Executive director interviewed by NTSB
November 19, 2007 Monday	Executive director continues working with NTSB Operations Group.
November 20, 2007 Tuesday	IRC meeting.
November 21, 2007 Wednesday	Preparation of IRC report.
November 22, 2007 Thursday (Holiday)	Preparation of IRC report.
November 23, 2007 Friday (Holiday)	IRC meeting. IRC interview of Captain John Cota.
November 24, 2007 Saturday	Preparation of IRC report.
November 25, 2007 Sunday	Preparation of IRC report.
November 27, 2007 Monday	Preparation of IRC report.
November 30, 2007 Friday	IRC recommends suspension of Captain Cota's license pending hearing. BOP votes to suspend license, as recommended.

<i>DATE</i>	<i>EVENT</i>
December 6, 2007 Thursday	IRC files Accusation.
June 6, 2008 Wednesday	IRC opposes Cota motion to continue hearing on Accusation set to begin on September 2, 2008.
July 24, 2008 Thursday	Following Capt. Cota's June 30, 2008 notice of retirement, IRC recommends that the BOP enter into a stipulation to ultimately dismiss Accusation upon effective date of Captain Cota's retirement. BOP votes to enter into the recommended stipulation.
October 1, 2008 Wednesday	IRC reports to Office of Administrative Hearing that Captain Cota's retirement became effective, and requests that Accusation matter be closed.
October 23, 2008 Thursday.	IRC presents its report to the Board.

APPENDIX 4

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

Party Submission

by

**BOARD OF PILOT COMMISSIONERS FOR THE BAYS
OF SAN FRANCISCO, SAN PABLO AND SUISUN**

NTSB Investigation

**COSCO BUSAN Allision with the
San Francisco – Oakland Bay Bridge,
San Francisco, California**

November 7, 2007

TABLE OF CONTENTS

Prior Board Participation in the NTSB Investigation.....	1
The Board's Incident Investigation.....	2
Pilot Training In And Use Of Electronic Navigation Systems.....	3
The Board's Navigation Technology Committee	4
Enhanced Training In Advanced Electronic Navigation Systems.....	6
Rulemaking Re Use Of Portable Pilot Units.....	7
Pilot Fitness Issues.....	8
Incident Investigation Procedures.....	10
Communications Among Pilot Commissions.....	11

1 **Party Submission by BOARD OF PILOT COMMISSIONERS FOR**
2 **THE BAYS OF SAN FRANCISCO, SAN PABLO AND SUISUN –**
3 **NTSB Investigation of COSCO BUSAN Allision with San Francisco-**
4 **Oakland Bay Bridge, San Francisco, California on November 7, 2007**

5 The Board of Pilot Commissioners for the Bays of San Francisco, San Pablo and
6 Suisun (hereinafter “the Board” or “Pilot Commission”) licensed the pilot, Captain
7 John J. Cota, who was piloting the COSCO BUSAN at the time of the allision. The
8 Commission is a party to the NTSB investigation. At the invitation of the NTSB, it
9 provides the following Party Submission.

10 **Prior Board Participation in the NTSB Investigation**

11 During the initial phase of the NTSB investigation following the allision of the
12 COSCO BUSAN with the San Francisco – Oakland Bay Bridge, the Board’s
13 President, Commissioner Knute Michael Miller, and its Executive Director, Captain
14 Patrick A. Moloney, met with the advance investigation team led by NTSB Member
15 Deborah Hersman and Chief Investigator Thomas Roth-Roffy and offered the Board’s
16 assistance and cooperation. Captain Moloney was asked to participate as a member of
17 NTSB investigation team that focused on vessel operations, which he did throughout
18 the team’s presence in the Bay Area.- Captain Moloney was also interviewed during
19 the same period in his capacity as the Board’s Executive Director, and again in
20 January 2008.

21 Both Board President Miller and Captain Moloney participated in the NTSB
22 public hearings held in Washington D.C. in April 2008. The Board also provided
23 comments on the NTSB Technical Review Draft Factual Report dated June 27, 2008.

1 license was ultimately rescheduled for September 2, 2008 to allow each party
2 additional time to gather the evidence. The pilot's state license would remain
3 suspended until the conclusion of the hearing. The hearing was estimated to take 16
4 court days and was scheduled over a four-week period.

5 In late June, after unsuccessfully seeking another continuance of the hearing, the
6 pilot issued his letter of intent to retire as a state licensed pilot effective October 1,
7 2008, the earliest date he could retire under existing state law. A stipulation was
8 entered into permitting the conditional dismissal of the IRC's charges, recognizing
9 that the pilot's state license would expire by operation of law upon the pilot's
10 retirement and would remain suspended until then, and that the only sanction the
11 Board could impose if it found pilot error was the suspension or revocation of his state
12 license. If for any reason the pilot withdraws his request before the effective day of
13 his retirement, the hearing would be rescheduled. A copy of the Administrative Law
14 Judge's Order, which includes the Stipulation to that effect, is attached as Encl. (2).

15 Once the pilot's retirement takes effect, and any potential for withdrawing the
16 notice of retirement is permanently removed, the IRC will submit its report to the full
17 Board. By law, the IRC cannot do so before then. It is currently anticipated that the
18 IRC's report will be submitted to the Board at its October 23 meeting, at which time it
19 would be come public and can be made available to the NTSB.

20 **Pilot Training In and Use of Electronic Navigation Systems**

21 One of the issues raised in the various investigations into the causes of the
22 allision focused on the electronic navigation system aboard the COSCO BUSAN and
23 whether the pilot was able to make full use of the information provided by it.

1 The Committee held well-attended public workshops in February, March and
2 April, 2008, with participation or presentations by experts in navigation technology
3 and in the training and education of mariners in that subject, including Professor Sam
4 Pecota of the California Maritime Academy, Executive Director Glen Paine of the
5 Maritime Institute of Technology and Graduate Studies, Training Director Scott
6 Humphrey of the Coast Guard Vessel Traffic Service for San Francisco Bay Area,
7 Human Factors Expert Dr. Richard Mogford from NASA and various commercial
8 providers of portable pilot navigation units.

9 The Committee also reviewed how portable pilot units are regulated in other
10 pilotage jurisdictions and various comprehensive reports on their use, liability issues
11 and interface with shipboard equipment.

12 The Committee presented its initial report to the Pilot Commission on April 17,
13 2008, recommending that the Commission's Pilot Training Curriculum Committee be
14 directed to consider incorporating enhanced training in advanced electronic navigation
15 systems that would provide exposure to a greater number of systems and variety of
16 presentations than what is provided by the current training program. In addition, the
17 Committee recommended that the Commission adopt by regulation a requirement that
18 pilots licensed by the Commission be equipped with, and trained in the use of,
19 portable electronic navigation equipment, commonly known as portable pilot units
20 (PPUs), with specified minimum capabilities and other relevant provisions.

21 At its May 22, 2008 meeting, the Pilot Commission voted unanimously to direct
22 its Curriculum Committee to consider incorporating enhanced training in advanced
23 electronic navigation systems and directed its staff to begin the formal rulemaking

1 process for adopting the regulation recommended by the Navigation Technology
2 Committee.

3 **Enhanced Training in Advanced Electronic Navigation Systems**

4 The Maritime Institute of Technology and Graduate Studies (MITAGS) has a
5 contract with the Pilot Commission to provide specified training to pilots as mandated
6 by current regulations. The curriculum is specified in the contract. That contract ends
7 June 30, 2009. (A copy of that contract was previously provided to NTSB
8 investigators.)

9 The Commission's Pilot Training Curriculum Committee will need to review the
10 current curriculum taught by MITAGS under the contract, possible options to provide
11 enhanced training in advanced electronic navigation systems, and how such training
12 can be incorporated into the current training program within the Commission's
13 regulatory and budget constraints.

14 Preliminary estimates are that it will take several meetings over a period of two
15 to three months to develop specific recommendations for changing the curriculum and
16 for the Board to take action on those recommendations, followed by possible contract
17 negotiations with MITAGS and the preparation and execution of contract
18 amendments. (Contract matters are handled through the California Department of
19 Consumer Affairs.)

20 If the resulting contract expenses remain within the Commission's budget, the
21 enhanced training, if adopted, could be in place by November 1, 2008. If the
22 additional training expenses would exceed the Board's budget, the Board may need to
23 seek an increase in its spending authorization unless spending on other program areas

1 can be reduced. Such a request could add a minimum of three to four months to the
2 process.

3 **Rulemaking Re Use of Portable Pilot Units**

4 The rulemaking process is governed by the California Administrative Procedures
5 Act (APA), and by budgetary constraints imposed by the Department of Finance
6 (DOF) and the Legislature. The Pilot Commission has been directed by DOF to use
7 temporary part time government employees known as AGPAs (Associate Government
8 Policy Analysts) to meet the Commission's future rulemaking needs. The Board's
9 current budget does not authorize expenditures for such employees, but there is such
10 authority in the proposed budget for F/Y 08/09, which has not yet been approved.
11 Once that budget has been approved (as part of the annual state budget approval
12 process), the Board can proceed with the retention of an AGPA and begin the
13 rulemaking process.

14 The AGPA will need to ensure compliance with APA requirements; prepare the
15 notice of proposed rulemaking and supporting documentation including a fiscal
16 analysis and have them approved by the Office of Administrative Law and, if
17 necessary, the Department of Finance; guide the Pilot Commission through the public
18 comment period (minimum of 45 days from the publication of the notice of proposed
19 rulemaking and 15 additional days following notice of any substantive amendments to
20 the original rulemaking language); guide the Board through the public rulemaking
21 hearing or hearings, until the rulemaking language has been adopted by the
22 Commission; prepare the final rulemaking package and supporting documents; and
23 guide the rulemaking through the approval process before the Office of Administrative

1 Law (OAL). Once approved by OAL, the rulemaking is filed with the Secretary of
2 State and ordinarily becomes law 30 days later.

3 The entire process can take from six to nine months or more. On an expedited
4 basis, it is possible that the rulemaking could be completed by early 2009.

5 The Harbor Safety Committee recently reviewed the Board's proposals relative
6 to providing enhanced training to pilots in advanced electronic navigation systems and
7 to the use of portable pilot units by pilots. It has also examined other operational
8 issues to help reduce the risk of a similar accident. Its report to the Office of Oil Spill
9 Prevention and Response, including a summary of its recommendations and its reports
10 on "Guidelines for Navigating San Francisco Bay in Reduced Visibility" and "Pilot
11 Use of Navigational Tools" are enclosed as Encl. (3).

12 **Pilot Fitness Issues**

13 By California law, pilots are required to be of good mental and physical health
14 and to undergo physical examinations in accordance with standards prescribed by the
15 Board. The Board's current procedures for determining physical and mental
16 competency of pilots are set forth in Title 7, California Code of Regulations § 217.

17 Pilots are also required to meet all Coast Guard standards, and hold and
18 maintain a Coast Guard license.

19 Following the allusion questions were raised regarding the standards used by
20 both the Board and the U.S. Coast Guard in determining pilots' physical and mental
21 competency, and the procedures used to ensure that pilots meet such standards.

22 In response, the Board's Pilot Fitness Committee has been tasked with:

1 (1) Conducting a comprehensive review of the physical and mental
2 fitness standards for pilots, including review of the Board's current standards as
3 outlined in the Reference Guide for Physicians for the Physical Examination
4 for Duty Status of Seafarers in the U.S. Merchant Marine adopted by the
5 Seafarers Health Improvement Program (SHIP); current U.S. Coast Guard
6 Physical Evaluation Guidelines for Merchant Mariner's Documents and
7 Licenses (NVIC 2-98); the proposed draft replacement to NVIC 2-98; any
8 other amendments to those guidelines currently under consideration; and
9 recommendations by the National Transportation Safety Board regarding the
10 fitness of pilots (including M-97-44);

11 (2) Preparing recommendations to the Board for the adoption of
12 standards that meet or exceed Coast Guard standards to ensure that each pilot
13 is physically and mentally fit to perform the duties of a pilot in light of the
14 above review and any lessons learned from the COSCO BUSAN incident;

15 (3) Preparing recommendations to the Board for the amendment of
16 its procedures to determine a pilot's physical and mental competency,
17 including procedures to ensure the disclosure and appropriate evaluation of the
18 history and presence of any medical conditions, symptoms or medication use
19 that would affect an individual's fitness to pilot a vessel;

20 (4) Addressing state of the art/methodology in detecting decline in
21 a pilot's situational awareness, including his or her ability to keep track of and
22 timely act on various communications and information relevant to the vessel's
23 safe navigation and to plan ahead for upcoming traffic and environmental
24 situations;

1 hearings in April have also been considered, including the degree to which current
2 incident review procedures, both at the IRC level and at the Board level, can be
3 improved to identify patterns of substandard performance or other problems that
4 warrant further Board action beyond the specific response to a single incident. The
5 Board has sought funding for an audit of the Board's incident review procedures and
6 anticipates receiving such funding for the current fiscal year, once the state budget is
7 approved. A copy of the Board's funding request ("Spring Finance Letter") is
8 attached as Encl. (5). It addresses the proposed IRC audit, as well as funding for the
9 Board's Pilot Fitness Committee review, and navigation technology rulemaking.

10 There have also been legislative initiatives that could effect the Board's review
11 of the IRC's reports, but those initiatives remain in flux. If legislation is adopted that
12 would significantly change the Board's incident investigation procedures prior to the
13 NTSB's report, a copy will be forwarded to the NTSB.

14 **Communications Among Pilot Commissions**

15 The COSCO BUSAN incident highlighted a number of challenges faced by
16 pilot commissions. Pilot commissions do not have a national organization to which
17 they belong or an existing mechanism to facilitate communications among them to
18 identify challenges and their solutions, best practices, and other items of mutual
19 interest.

20 Both preceding and following the NTSB hearings in April, Board President
21 Miller has participated in an effort to establish such communications, for the present,
22 concentrating on West Coast pilot commissions. A West Coast conference of pilot
23 commissions is currently scheduled for November 6 and 7, 2008 in Portland, Oregon.
24 The draft agenda currently includes: (1) update on the COSCO BUSAN incident; (2)

1 current issues being addressed by each authority; (3) developing best practices; (4)
2 protocols for sharing information; and (5) establishing a regular means of
3 communication among the West Coast pilotage oversight authorities. Representatives
4 from the pilot commissions in California, Oregon, Washington, British Columbia and
5 Alaska have been contacted and have placed the regional meeting on their respective
6 calendars.

ENCLOSURE 1

1 Filed 06 Dec. 2007

2
3 BEFORE THE BOARD OF PILOT COMMISSIONERS
4 FOR THE BAYS OF SAN FRANCISCO, SAN PABLO AND SUISUN

5 In re the Matter of the
6 Accusation Against:

7 Captain JOHN J. COTA,
8

) Case No.: No. 07-01
)
) ACCUSATION
)
)

9
10 To: Captain JOHN J. COTA, Pilot on the Bays of San Francisco, San Pablo and Suisun, State
11 License No. 902-27:

12
13 The Incident Review Committee of the Board of Pilot Commissioners for the Bays of San
14 Francisco, San Pablo and Suisun (hereinafter "the IRC" and "the Board," respectively), having
15 investigated the navigational incident described herein, under the authority of Section 1180.6 of the
16 California Harbors and Navigation Code (hereinafter "the Code") and Section 210 of the Board's
17 Regulations (Title 7, California Code of Regulations, § 210), makes the following accusation against
18 Captain John J. Cota (hereinafter "Captain Cota"), the Respondent,

19
20 **General Background**

- 21 1. At all times relevant, Captain Cota was the holder of Pilot License Number 902-27, issued on
22 February 1, 2007 by the Board pursuant to Chapter 4 of Division 5 the Code.
- 23
- 24 2. The Board has the authority to suspend or revoke a pilot license issued by it as provided by
25 Sections 1181 and 1182 of the Code.
- 26
- 27 3. Captain Cota has subjected his license to suspension or revocation in that, on 07 November
28 2007, while serving as the pilot of the outbound M/V COSCO BUSAN, he negligently caused the

1 allision of that vessel's port side with the fendering system of the "D" or "Delta" tower of the San
2 Francisco-Oakland Bay Bridge, as more fully described below.

- 3
4 4. The M/V COSCO BUSAN is a motor container vessel registered in Hong Kong. The vessel
5 has a gross registered tonnage of 65,301 GRT, a length of 901 feet, a beam of 131 feet, and at the
6 time of the allision had a draft of 39' 09" forward and 40' 04" aft. The vessel is configured with a
7 single, fixed pitch, right turning propeller and a 2,700 hp bow thruster.

8
9 **BASIS OF ACCUSATION**

- 10
11 5. At about 0600 on Wednesday, 07 November 2007, Captain Cota boarded the M/V COSCO
12 BUSAN at Oakland Berth 56 to act as its pilot for its transit from Berth 56 to sea. The vessel was
13 scheduled to sail at 0630.

- 14
15 6. Once aboard the vessel, Captain Cota was escorted to the bridge where he met the ship's
16 captain and bridge team, whose English skills were limited, as was their familiarity with the ship
17 and her navigation equipment.

- 18
19 7. Captain Cota was unfamiliar with the ship's electronic chart system and the markings thereon.
20 Additionally, Captain Cota had concerns regarding the operational status of the radars prior to
21 departure.

- 22
23 8. At 0748 the COSCO BUSAN left the safety of the berth under Captain Cota's guidance. At
24 the time of departure, he had reason to doubt whether the ship could proceed safely and he had
25 insufficient information about the level of visibility along his intended route. Under the
26 circumstances, the COSCO BUSAN's departure from Berth 56 was contrary to the guidelines in
27 the *San Francisco, San Pablo and Suisun Bays Harbor Safety Plan* ("HSP"), which provide for
28 various factors to be considered before moving a vessel (see Section XIV. Pilotage) and further

1 provide that: "Vessels within the Bay at a dock ... should not commence movement if visibility
2 is less than .5 nautical miles throughout the intended route, unless the operator's assessment of all
3 variables is that the vessel can proceed safely." HSP at pp. 5 and 43.

4
5 9. Once clear of the berth and in mid-channel, Captain Cota directed the assist tug,
6 REVOLUTION, to put up a line to the ship's stern and follow the ship with a slack line. He
7 planned to let the tug go once they were out of the estuary.

8
9 10. Captain Cota ordered "Half Ahead" when the ship exited the Oakland Inner Harbor Entrance
10 Channel. That engine order would bring the ship's speed under prevailing circumstances to about
11 11 knots as the ship would be stemming a one-knot flood current. The engine order remained at
12 Half Ahead for about 7 minutes, at which time Captain Cota ordered "Full Ahead." The ship
13 allided with the bridge less than 3 minutes after the Full Ahead bell.

14
15 11. During the period that the ship was at Half Ahead, the visibility in the approach to the bridge
16 was reduced to about 0.1 nm, the ship's radar pictures deteriorated to the point that Captain Cota
17 lost confidence in them, and he lost situational awareness to accurately assess the vessel's
18 position, although he had the means to do so.

19
20 12. Under the circumstances, prudence and compliance with Inland Navigation Rules 6, 7 and 19
21 would have dictated that Captain Cota reduce speed and/or proceed to Anchorage 9 rather than
22 continue to attempt to transit under the bridge between the Delta and Echo towers, which he could
23 not see on radar and which were not visible due to the dense fog.

24
25 13. The Bay Bridge has a fixed green light with 3 white lights in a vertical line on the bridge and a
26 radar beacon (RACON) above the center of the channel between the Delta and Echo towers. In
27 addition, there is a nun buoy with a radar reflector on each side of the Delta Tower, fog horns on
28 both the Delta and Echo towers and a bell marking the Charlie tower of the bridge. As the pilot

1 with local knowledge, Captain Cota should have ensured that the lookout had been properly
2 instructed as to what to look and listen for and what to report prior to approaching the bridge.

- 3
4
5 14. Captain Cota failed to make full use of all available resources, including the tug
6 REVOLUTION, which remained tethered to the stern and thus useless to him, of the Coast Guard
7 Vessel Traffic Service, which could have provided more information as to his position and
8 heading if he had requested it, and of his ship's lookout, who could have provided information on
9 the bridge's fog signals and lights if the lookout had been properly instructed.

10
11 **DAMAGES CAUSED BY ALLISION**

- 12
13 15. As a direct result of Captain Cota's piloting, the vessel struck the fendering system
14 surrounding the Delta Tower, damaging the ship and the bridge's fendering system, and spilling
15 an estimated 58,000 gallons of fuel oil from the ship's fuel tanks, which were ruptured by the
16 allision. The resulting property damage and damage to the marine environment is estimated in the
17 tens of millions of dollars.

18
19 **ACCUSATION OF MISCONDUCT**

- 20
21 16. Captain Cota's conduct, under all the circumstances described herein, constituted
22 "misconduct" within the meaning of HNC Section 1181(g), which states in relevant part:

23 The license of a pilot or inland pilot may be revoked or suspended before its
24 expiration only for reasons of misconduct, which shall include, but not be limited
to, the following:

25(g) Negligently, ignorantly, or willfully running any vessel on shore, or
26 otherwise rendering it liable to damage, or otherwise causing injury to
27 persons or damage to property....
28

1 Captain Cota's conduct also violated the provisions of Title 7, California
2 Code of Regulations, Section 219(t), (u) and (v) which state in relevant part:

3 (t) A pilot ... shall not, through ignorance, willfulness or neglect, run a
4 vessel on shore, or otherwise render a vessel liable for damage to persons,
5 property or the marine environment during the performance of his or her
6 duties as a pilot...;

7 (u) A pilot ... shall always obey the applicable Rules of the Road for the
8 navigation of vessels and shall, under all circumstances, perform his or her
9 duties in a manner so as not to endanger persons, property or the marine
10 environment or cause damage...; and

11 (v) While engaged in any piloting activity, a pilot ... shall obey all
12 applicable laws and conduct himself or herself so as not to cause injury or
13 damage to persons, property or the marine environment.

14 17. Captain Cota's misconduct as described above warrants the suspension or revocation of his
15 pilot license.

16 WHEREFORE, you are notified that the Board will determine whether revocation or
17 suspension of your pilot license, or other appropriate sanction, should be imposed.

18 [Add standard Admin. Procedures Act instructions re demand for hearing, etc.]

19 Dated: December 06, 2007

20 By THE INCIDENT REVIEW COMMITTEE

21 _____
22 /s/
23 Commissioner Gunnar Lundeberg
24 Public Member

25 _____
26 /s/
27 Captain P. A. Moloney
28 Executive Director, Member

ENCLOSURE 2

BEFORE THE
BOARD OF PILOT COMMISSIONERS
FOR THE BAYS OF SAN FRANCISCO, SAN PABLO AND SUISUN

In the Matter of the Accusation Against:

CAPTAIN JOHN J. COTA,

Respondent.

Case No. 07-01

OAH No. 2008010073

**ORDER GRANTING
CONTINUANCE**

This matter is currently set for hearing before the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun, September 2 to 5, 8 to 11, 15 to 18, 22 to 25, 2008, at the Elihu Harris State Building, 1515 Clay Street, Oakland, California. A further Prehearing Conference is scheduled for August 8, 2008. Complainant, the Incident Review Committee of the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo, and Suisun, is represented by Gary R. Gleeson, Attorney at Law. Respondent Captain John J. Cota is represented by John F. Meadows, Attorney at Law. A telephonic conference was held on July 30, 2008.

* * * * *

On July 25, 2008, the parties filed an executed stipulation. Under the terms of the stipulation, the parties agree to vacate the hearing dates in view of respondent's impending retirement. The stipulation is, in effect, an agreement to vacate the Prehearing Conference and to continue the hearing so that the parties may resolve this matter without the necessity of a hearing. Good cause for a continuance of the hearing within the meaning of Government Code section 11524 has been demonstrated, and the motion is granted.


The parties request that a status conference be set for the purpose of scheduling new hearing dates should the retirement fail to be effectuated in accordance with the terms of the stipulation. All parties are available on October 3, 2008. A telephonic status conference shall take place at 4:45 p.m. on that date.

ORDER

1. The parties' request for a continuance is GRANTED. The Prehearing Conference scheduled for August 8, 2008, and the hearing dates of September 2 to 5, 8 to 11, 15 to 18, and 22 to 25, 2008, are vacated.

2. A Telephonic Status Conference shall take place on October 3, 2008, at 4:45 p.m. The Office of Administrative Hearings will generate the call to counsel at their telephone numbers on file, unless the office is notified of alternate numbers.

DATED: 7-31-08


MELISSA G. CROWELL
Administrative Law Judge
Office of Administrative Hearings

PROOF OF SERVICE

Case Name: Captain John J. Cota

OAH No.: 2008010073

I, Helen Tsai, declare as follows: I am over 18 years of age and am not a party to this action. I am employed by the Office of Administrative Hearings. My business address is 1515 Clay Street, Suite 206, Oakland, CA 94612. On July 31, 2008, I served a copy of the following document(s) in the action entitled above:

ORDER GRANTING CONTINUANCE

to each of the person(s) named below at the addresses listed after each name by the following method(s):

Gary R. Gleason, Attorney at Law
Farbstein & Blackman
411 Borel Avenue, Suite 425
San Mateo, CA 94402


By Facsimile only: 650-554-6240

John F. Meadows, Attorney at Law
Jedeiken, Spaulding, Meadows & Schneider
333 Pine Street, 5th Floor
San Francisco, CA 94104

By Facsimile only: 415-421-5658

Fax Transmission. I personally transmitted the above-described document(s) to the person(s) at the fax number(s) listed above, from fax machine number (510) 622-2743, pursuant to Government Code section 11440.20 and California Code of Regulations, title 1, section 1008, subdivision (d). The fax transmission was reported as complete and without error. A copy of the transmission report showing the date and time of transmission, properly issued by the transmitting machine, is attached to this declaration of service.

I declare under penalty of perjury under the laws of the State of California that the foregoing is true and correct. This declaration was executed at Oakland, California on July 31, 2008.



Helen Tsai, Declarant

1 GARY R. GLEASON (SB#136167)
 2 FARBSTEIN & BLACKMAN
 3 A Professional Corporation
 411 Borel Avenue, Suite 425
 3 San Mateo, California 94402-3518
 TELEPHONE: (650) 554-6200
 4 FACSIMILE: (650) 554-6240

FILED

JUL 25 2008

Office of Administrative Hearings
By _____

5 Attorneys for Incident Review Committee

6
 7 **BEFORE THE BOARD OF PILOT COMMISSIONERS**
 8 **FOR THE BAYS OF SAN FRANCISCO, SAN PABLO AND SUISUN**
 9

<p>10 In re the Matter of the 11 Accusation Against:</p> <p>12 Captain JOHN J. COTA</p>	<p>) Case No.: No. 07-01</p> <p>) STIPULATION AND ORDER RE: DISMISSAL OF ACTION</p>
--	--

14
 15 This stipulation is entered into between Respondent, Captain John J. Cota and the Incident
 16 Review Committee of the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo
 17 and Suisun (hereinafter "the IRC" and "the Board" respectively) and is subject to the Board's
 18 approval.

19
 20 1. On 07 November 2007, the M/V COSCO BUSAN allided with the Delta Tower of the San
 21 Francisco-Oakland Bay Bridge causing substantial environmental and property damage. At the time
 22 of the incident, Captain Cota was piloting the vessel under the authority of his state pilot license
 23 issued by the Board.

24
 25
 26 2. After an investigation, the IRC preferred an accusation as authorized by California Harbors
 27 and Navigation Code Section 1180.6 alleging pilot misconduct associated with the allision. Captain
 28 Cota filed a timely Notice of Defense, denying the allegations and requesting a hearing. In the

1 interim, the Board suspended Captain Cota's state pilot license pending a hearing on the charges set
2 forth in the Accusation, as authorized by Harbors and Navigation Code Section 1180. By agreement
3 of the parties, that suspension remains in effect pending a resolution of the issues raised by the
4 Accusation and Captain Cota's Notice of Defense.

5
6 3. The hearing in this matter is currently scheduled to begin September 02, 2008 before the
7 Board sitting with an administrative law judge.

8
9 4. By letter dated June 23, 2008 Captain Cota gave written notice to the Board of his intent to
10 retire as a state licensed pilot effective October 1, 2008. By retiring, Captain Cota does not admit
11 fault for the allision.

12
13 5. In view of Captain Cota's impending retirement, and conditioned thereon, the parties
14 agree that continuing to proceed with a hearing under these circumstances would not be productive,
15 as in the event of a finding of pilot misconduct, the Board's authority to take any action against
16 Captain Cota's professional license is limited to its suspension or revocation and would become moot
17 upon his retirement.


18
19 6. In consideration of the IRC's agreement to seek a conditional dismissal of the hearing
20 herein, Captain Cota hereby agrees and stipulates that he will not withdraw his notice of retirement
21 prior to its effective date or request reissuance of his state pilot license from the Board. Captain Cota
22 further acknowledges that he is not authorized to pilot under his state license during the period of
23 suspension and that his license expires by operation of law on the effective date of his retirement.

24
25 7. For the reasons set forth above, the parties stipulate that the action against Captain Cota's
26 state pilot license pending herein may be conditionally dismissed pending Captain Cota's retirement,
27 and that the dismissal becomes final upon the effective date of such retirement.


1 Pursuant to Title 7, California Code of Regulations, §221(e), the parties jointly request Board
2 approval hereof, and request that the hearing scheduled for September 02, 2008 herein, be taken off
3 calendar.

4
5 **For Respondent:**

6 Date: 7-18-08
7



8 Captain John J. Cota
Respondent

9 Date: 7-18-08



10 John F. Meadows, Esq.
Counsel for Respondent

11 **For the IRC:**


12 Date: 7-24-08


13 Commissioner Knute Michael Miller
Chair, Incident Review Committee

14
15 Date: 24 July '08



16 Captain Patrick Maloney
17 Member, Incident Review Committee

18 Date: 7-21-08


19 Gary R. Gleason, Esq.
20 Counsel for Petitioner

21
22 The Board has reviewed and accepted the terms of the above stipulation and hereby requests
23 the Office of Administrative Hearings to take the hearing currently scheduled for September 02, 2008
24 off calendar.

25
26 Date: 7-24-08


27 Commissioner Knute Michael Miller
28 President

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28

IT IS SO ORDERED.

Date: 7/30/08



Hon. Melissa G. Crowell, Judge
Office of Administrative Hearings

ENCLOSURE 3

Harbor Safety Committee

of the San Francisco Bay Region

*Mandated by the California Oil Spill
Prevention and Response Act of 1990*

July 24, 2008

Lisa Curtis, Administrator
Office of Spill Prevention and Response
1700 K Street, Suite 250
Sacramento, CA 95811

Attn: Bud Leland, Deputy Administrator

SUBJECT: Harbor Safety Committee of the San Francisco Bay Region: Final Report, Response to Governor Schwarzenegger's Directive to Analyze the Cosco Busan Allision

Dear Ms. Curtis:

Following the November 7, 2007 Cosco Busan oil spill, Governor Schwarzenegger directed the Office of Spill Prevention and Response (OSPR) to investigate the causes of and response to the allision and resulting oil spill. OSPR called upon the Harbor Safety Committee of the San Francisco Bay Region (HSC) to analyze the navigational safety-related issues of the Governor's directive and make appropriate recommendations regarding the prevention aspects of the incident. The twenty-member committee, established by the state legislature, is comprised of port authorities; cargo, tanker, tug barge and ferry operators; labor; bar pilots; recreational boaters; environmental organizations; commercial fishermen; the Coast Guard Captain of the Port; BCDC; NOAA and the Corps of Engineers.

Beginning in late November 2007, the Harbor Safety Committee proceeded to address the following navigational and operational safety issues outlined in the Governor's directive: speed limit restriction, tugboat escorts, inclement weather sailing conditions, crew staffing, navigational equipment, Vessel Traffic Service system, and Physical Oceanographic Real time System (PORTS). The HSC Work Groups of maritime experts discussed the issues, and based on facts known of the allision at the time, developed recommendations to improve vessel transit in the Bay. (Public input is strongly encouraged: all meetings are open to the public, publicly noticed and agendized under the Ralph M. Brown Open Meeting Act).

Summary of Adopted Recommendations:

Physical Oceanographic Real Time System (PORTS): On January 10, 2008, the HSC adopted the PORTS Work Group recommendation to permanently fund the San Francisco Bay Region PORTS from the Oil Spill Prevention and Administration Fund (OSPAF), as PORTS has proven value to the maritime community. The Work Group also recommended a prioritized list of additional sensors to be deployed in critical locations in San Francisco Bay, which has a series of microclimates.

Harbor Safety Committee c/o Marine Exchange of the San Francisco Bay Region
Fort Mason Center, Building B, Suite 325, San Francisco, CA 94123-1380
(415) 441-7988 – hsc@sfmtx.org

Tug Escorting: The HSC on March 13, 2008 adopted the Tug Escorts Work Group finding that there was no evidence to suggest tug escorting would have prevented the Cosco Busan incident or similar incidents from occurring. Additionally, the Work Group concluded that the risks associated with using an escort tug as a "leader" in limited visibility outweighs potential benefits.

Navigating in Reduced Visibility: On March 13, 2008, the HSC adopted 'Guidelines for Navigating in Reduced Visibility' and designated Critical Maneuvering Areas, which were developed primarily by the San Francisco Bar Pilots and the Coast Guard, and reviewed by the Navigation Work Group, as Best Maritime Practices for large vessels. The guidelines will be incorporated into the San Francisco Bar Pilots' Operations Guidelines as well as the Pilots' Tide Book, the Coast Guard Vessel Traffic Service (VTS) Training Manual, U.S. Coast Pilot 7, and the San Francisco, San Pablo and Suisun Bays Harbor Safety Plan. Similar guidelines are being developed for vessels smaller than 1600 gross tons.

Vessel Traffic Service, Coast Guard Authority: The HSC on March 13, 2008 adopted the Prevention Through People Work Group finding that adequate Coast Guard authority to regulate shipping and control vessel movements already exists in current law, and that the best skills for maneuvering a vessel originate from onboard the ship itself, not from the Vessel Traffic Service. VTS Operators on Yerba Buena Island do not have instantaneous knowledge of the particular ship's characteristics (on average, more than 900 different ships enter the Bay each year) and of the tidal and wind forces acting on a vessel.

Navigational Safety for Commute Ferries: To increase the safe transport of commute passengers as a major segment of maritime traffic on San Francisco Bay, the HSC on May 8, 2008 adopted ferry routes developed by the Ferry Operations Work Group with ferry operators, ferry masters and the VTS, to be incorporated into the Harbor Safety Plan and by NOAA on area nautical charts. In 2007, commute ferries carried a total of five million passengers on six routes. Additional routes are planned within the next few years.

Speed Restrictions: On May 8, 2008, the HSC adopted the Navigation Work Group findings that federal regulations and international guidelines adequately limit the speed of large vessels transiting the Bay during periods of reduced visibility. The San Francisco Bay region, consisting of several bays and rivers, is one of the foggiest harbors in the United States. To aid mariners, the Coast Guard established Regulated Navigational Areas (RNAs) designed to improve safety by organizing traffic patterns and limiting vessel speeds.

Crewing Requirements: On May 8, 2008, the HSC adopted the Navigation Work Group findings that sufficient regulations and guidelines exist under federal and international law for crewing requirements.

Navigation Tools: The HSC voted on July 10, 2008 to urge the Board of Pilot Commissioners, which has oversight authority over licensed San Francisco Bar Pilots, to work with the Bar Pilots to incorporate in the Pilot training program enhanced training in advanced electronic navigation systems, providing exposure to a greater number of systems and variety of presentations, as a near-term priority. The HSC also supports adoption of a regulation to require that pilots licensed by the Board be equipped with portable electronic navigation equipment, commonly known as Portable Pilot Units ("PPUs") at all times while piloting San Francisco Bay.

The Harbor Safety Committee has begun developing "Best Maritime Practices" for safe navigation in the San Francisco Bay Region, a requirement by OSPR to incorporate in each committee's Harbor Safety Plan. "Best Practice" topics under discussion are policies for closing the Bar to shipping and for operation of tugs and barges and high speed commute ferries during inclement weather. Additionally, the Committee contacted the California Department of Transportation (Caltrans) to discuss the fendering protection of bridges adjacent to Bay Area shipping lanes; Caltrans representatives subsequently briefed the HSC on guidelines for bridge fendering. As a result of this discussion, the HSC then recommended in a letter that Caltrans engineers independently analyze the energy-absorbing capacities of key bridge fendering protection systems adjacent to high volume shipping lanes in the Bay Region to ensure adequate protection of the integrity of the bridges and to minimize damage to the vessel to reduce the chance of a possible oil spill.

The Committee is actively working to promote safe navigation in the San Francisco Bay Region to protect our environment. We are available for any further consultation you may require. I can be reached at (415) 461-4566.

Sincerely,

Joan L. Lundstrom, Chair
Harbor Safety Committee of the
San Francisco Bay Region

cc: Gary Toledo, OSPR
Steve Sawyer, OSPR
Larry Bowling, National Transportation Safety Board
Harbor Safety Committee

Enclosures: Work Group Reports sent to OSPR, as approved by the HSC

March 19, 2008

TO: Lisa Curtis, Administrator, Office of Spill Prevention and Response

FROM: Joan Lundstrom, Chair, Harbor Safety Committee of the San Francisco Bay Region

SUBJECT: Governor's Directive to Analyze the Cosco Busan Oil Spill Incident,

Harbor Safety Committee Recommendation: Guidelines for Navigating San Francisco Bay in Reduced Visibility

Introduction

In response to the Cosco Busan oil spill incident, Governor Schwarzenegger directed a state investigation into the causes of and response to the oil spill. The directive outlined a number of issues to ensure "any action necessary to prevent this from ever happening again." OSPR tasked the Harbor Safety Committee (HSC) of the San Francisco Bay Region to "analyze the navigational safety-related issues of the Governor's directive and make appropriate recommendations regarding the prevention aspects of the incident."

The HSC Work Groups addressed the issues raised in the Governor's directives based on information available, noting that the National Transportation Safety Board (NTSB) report on the cause is not expected to be completed until autumn 2008, and the State Board of Pilot Commissioners Accusation (Case No. 07-01) of the pilot is scheduled for hearing before an Administrative Law Judge beginning September 2, 2008. Other investigations are focused on oil spill response efforts.

The Navigation Work Group met January 23 and March 4, 2008, to address issues related to navigating San Francisco Bay in inclement weather, specifically, those affecting large vessels transiting during reduced visibility. To advance this effort, the San Francisco Bar Pilots and the Coast Guard developed Guidelines for Navigating in Reduced Visibility ("Guidelines"), which were reviewed by the Navigation Work Group, and which are part of this recommendation.

Note: The following findings and recommendations should be considered preliminary, as not all evidence was accessible. As new information becomes available, the Harbor Safety Committee may revisit or address other policy implications.

Report From the Navigation Work Group on Navigating San Francisco Bay in Reduced Visibility

Navigating the San Francisco Bay Region during periods of reduced visibility requires mariners to exercise additional caution and vigilance. The Bay region, consisting of several bays and rivers, is one of the foggiest harbors in the United States. In-Bay distances are long. There is not a single regional climate, but a series of microclimates with variable fog. During summer, 30 to 40 percent of parts of the Bay may experience foggy conditions. In winter, the fog may be denser, originating from a different direction than summer fog.

Role of Reduced Visibility in Cosco Busan Incident

Reduced visibility was a causal factor in the Cosco Busan incident: the State Board of Pilot Commissioners found in its Accusation (Case No. 07-01) that, "At the time of departure [from the dock], [the pilot] had reason to doubt whether the ship could proceed safely and...had insufficient information about the level of visibility along [the] intended route. Under the circumstances, the Cosco Busan's departure from Berth 56 was "contrary to the guidelines in the San Francisco, San Pablo and Suisun Bays Harbor Safety Plan ("HSP"), which provide for various factors to be considered before moving a vessel..." and further provide that "vessels within the Bay at a dock...should not commence movement if visibility is less than .5 nautical miles throughout the intended route, unless the operator's assessment of all variables is that the vessel can proceed safely."

In reviewing the Harbor Safety Plan guidelines quoted above, the Navigation Work Group determined there was a need to clarify and expand on the guidelines because, as was noted, the Bay region is a series of microclimates with variable fog conditions.

Recommended Guidelines for Navigating in Reduced Visibility

These guidelines should be used by the mariner when planning, initiating or navigating a transit in the Bay during periods of reduced visibility. These guidelines acknowledge that **Large Vessels** are not as maneuverable as smaller vessels and therefore define **Large Vessels** as power driven vessels of 1600 gross tons or more, and tugs with barges of 1600 gross tons or more. Mariners are at all times to comply with the requirement of the International Regulations for Avoiding Collisions at Sea, or COLREGS.

Critical Maneuvering Areas (CMAs): There are areas within the Bay where additional standards of care are required due to the restrictive nature of the channel, proximity of hazards, or the prevalence of adverse currents. Large vessels should not transit through CMAs when visibility is less than 0.5 nautical miles.

Locations within the Bay identified as Critical Maneuvering Areas:

- Redwood Creek
- San Mateo-Hayward Bridge
- Oakland Bar Channel*
- Islais Creek Channel
- Richmond Inner Harbor
- Richmond-San Rafael Bridge, East Span
- Union Pacific Bridge
- New York Slough, up-bound
- Rio Vista Lift Bridge

*Note: the Oakland Bar Channel is identified due to cross currents and its proximity to the Bay Bridge and Yerba Buena Island.

Vessels docked: Large vessels at a dock within the Bay should not commence a movement if visibility is less than 0.5 nautical miles at the dock.

Vessels proceeding to dock: Large vessels proceeding to a dock should anchor if visibility at the dock is known to be less than 0.5 nautical miles, unless, under all circumstances, proceeding to the dock is the safest option.

Note: Vessel pilots or operators should notify VTS upon determination that a scheduled movement will be delayed or cancelled. If underway, they shall make a sailing plan deviation report per VTS regulations.

Navigation Work Group Recommendations to the Harbor Safety Committee:

1. The Work Group recommends that the "Guidelines for Navigating in Reduced Visibility" developed by the San Francisco Bar Pilots and the Coast Guard be adopted as "Best Maritime Practices for Large Vessels" and that the guidelines be incorporated into the San Francisco Bar Pilots' Operations Guidelines as well as their Tide Book, the Coast Guard Vessel Traffic Service (VTS) Training Manual, U.S. Coast Pilot 7, and the San Francisco Harbor Safety Plan.

The Navigation Work group concluded the proposed guidelines would increase safe navigation in San Francisco Bay, and thereby respond in part to the Governor's directive to analyze navigational safety-related issues of the Cosco Busan incident and make appropriate recommendations regarding the prevention of future incidents.

2. The Work Group recommends the Harbor Safety Committee consider drafting guidelines for navigating in reduced visibility for certain vessels less than 1600 gross tons.

3. The Work Group recommends the Harbor Safety Committee review the "Guidelines for Navigating in Reduced Visibility" within one year of adoption.

4. The Work Group recommends that the Harbor Safety Committee address issues surrounding the capacity and management of Coast Guard designated anchorages in San Francisco Bay.

5. The Work Group recommends that the Harbor Safety Committee assess the use of and advances in navigational aid technology to improve safe transit on San Francisco Bay. The Board of Pilot Commissioners has formed a Navigation Technology Committee to investigate the different types of navigation systems generally found on ships calling the Bay Area. A preliminary report is expected June 1, 2008. The HSC Navigation Work Group will review the report in considering recommendations to the full HSC.

Harbor Safety Committee Action: The Harbor Safety Committee unanimously adopted the Navigation Work Group findings and recommendations at its March 13, 2008 regular meeting. (Note: as a committee established by the State of California, all Harbor Safety Committee meetings are open to the public and publicly noticed and agendaized under the provisions of the Ralph M. Brown Open Meeting Act).

July 15, 2008

TO: Lisa Curtis, Administrator, Office of Spill Prevention and Response
FROM: Joan Lundstrom, Chair, Harbor Safety Committee of the San Francisco Bay Region
SUBJECT: Governor's Directive to Analyze the Cosco Busan Oil Spill Incident,
Harbor Safety Committee Recommendation: Pilot Use of Navigational Tools

Attn: Bud Leland, Deputy Administrator

Introduction

In response to the Cosco Busan oil spill incident, Governor Schwarzenegger directed a state investigation into the causes of and response to the oil spill. The directive outlined a number of issues to ensure "any action necessary to prevent this from ever happening again." OSPR tasked the Harbor Safety Committee (HSC) of the San Francisco Bay Region to "analyze the navigational safety-related issues of the Governor's directive and make appropriate recommendations regarding the prevention aspects of the incident."

The HSC Work Groups addressed the issues raised in the Governor's directives based on information available, noting that the National Transportation Safety Board (NTSB) report on the cause is not expected to be completed until autumn 2008. Other investigations are focused on oil spill response efforts.

To date the Navigation Work Group completed recommendations to the HSC related to large vessel transit of the San Francisco Bay Region as well as the speed of large vessels the region during periods of reduced visibility.

To respond to the Governor's directive to develop recommendations regarding the use of advanced technology to aid pilots in navigating San Francisco Bay, the HSC agreed to coordinate with the San Francisco Board of Pilot Commissioners. The Navigation Work Group met June 27, 2008, to develop its recommendations to the HSC, based upon the adopted recommendations of the Board of Pilot Commissioners.

Note: the following findings and recommendations should be considered preliminary, as not all evidence was accessible. As new information becomes available, the Harbor Safety Committee may revisit or address other policy implications.

Report From Navigation Work Group on Pilot's Use of Navigational Tools

Background

In response to the Cosco Busan incident, the Governor directed OSPR to investigate the potential role of navigational technology in reducing the risk of vessel collisions in the San Francisco Bay Region. The HSC Navigation Work Group agreed to coordinate its review of the subject with the work of the Board of Pilot Commissioners ("Pilot Commission"), which formed a Navigation Technology Committee to develop recommendations for the enhancement of pilots' ability to safely navigate using shipboard and portable electronic navigation systems.

The State Board of Pilot Commission, created in 1850, regulates the Bar Pilots of the San Francisco Bay Region. The Commission consists of seven members appointed by the Governor with the consent of the Senate: three are public members who are neither pilots nor work for companies that use pilots, two are pilots licensed by the Pilot Commission and two are industry members - one from the tanker industry and one from the dry cargo industry.

Over the course of several months, in investigating different types of navigation systems found on ships calling on the San Francisco Bay Area and the sufficiency of pilot training in the use of such systems, the Pilot Commission Technology Committee considered presentations by experts in navigation technology and in the education of mariners in the use of the technology. The committee also evaluated portable electronic navigation chart systems that can be brought aboard by pilots, various comprehensive reports on their use, liability issues and interface with shipboard equipment and how portable pilot units are regulated in other jurisdictions.

Work Group Discussion

The HSC Navigation Work Group met June 27, 2008, to review the recommendations adopted by the Pilot Commission and to develop recommendations to the Harbor Safety Committee. (Attachment: *Draft Board of Pilot Commission status report on Pilot Commission's actions to enhance pilots' ability to safely navigate ships with the use of advanced navigation technology.*)

The Work Group noted that prudent mariners rely on an array of informational sources when navigating, including paper charts, electronic charts, Army Corps of Engineers charts, USCG Notices to Mariners, etc. Portable electronic navigation chart systems that can be brought aboard by pilots, or Portable Pilot Units ("PPUs"), are an additional navigational tool proposed to be carried by Pilot Commission-licensed pilots in San Francisco Bay. These units cannot supplant onboard systems; however, their use is appropriate in the Bay due to its variety of microclimates and periods of dense fog.

To further navigational safety, the Work Group agreed to support international efforts to standardize symbols used on onboard charts. Confusion can result when piloting the more than 900 different ships that transit the Bay, many of which carry different charting systems featuring proprietary symbology. Future training of Pilot Commission-licensed pilots will include the symbology used on different charts.

Conclusion: In discussing issues related to the use of advanced navigational technology systems, the Navigation Work Group found that Portable Pilot Units are an additional tool of value to increase navigation safety in the Bay Region, along with enhanced training of Pilot Commission-licensed pilots in advanced electronic navigation systems.

Navigation Work Group Recommendations to the Harbor Safety Committee

1. Urge the Board of Pilot Commissioners, as a near-term priority, to work with the San Francisco Bar Pilots to incorporate in the Pilot training program enhanced training in advanced electronic navigation systems, providing exposure to a greater number of systems and variety of presentations.

2. Support adoption by the Board of Pilot Commissioners of a regulation to require that pilots licensed by the Pilot Commission be equipped with, and trained in the use of, portable electronic navigation equipment, commonly known as Portable Pilot Units ("PPUs"). The regulation should require that pilots be equipped with PPU's at all times while piloting except when the pilot deems that embarking on or disembarking from a vessel while carrying a PPU may present an unacceptable safety hazard to the pilot or when circumstances would prevent its use.

Such PPU's shall, at a minimum, have the following capabilities:

- (a) Displaying approved electronic navigation charts (ENCs) issued by the cognizant U.S. government authority;
- (b) Displaying the vessel's position and heading on such ENCs to the accuracy required by the International Maritime Organization (IMO) for Automatic Identification Systems (AIS); and
- (c) Displaying other navigational information as provided through the vessel's AIS pilot plug.

Harbor Safety Committee Action: The Harbor Safety Committee unanimously adopted the Navigation Work Group findings and recommendations at its July 10, 2008 regular meeting. (Note: as a committee established by the State of California, all Harbor Safety Committee meetings are open to the public and publicly noticed and agendized under the provisions of the Ralph M. Brown Open Meeting Act).

Attachment

Draft Board of Pilot Commissions status report on Pilot Commission's actions to enhance pilots' ability to safely navigate ships with the use of advanced navigation technology

Following the COSCO BUSAN accident and oil spill in San Francisco Bay in November 2007, the state Board of Pilot Commissioners appointed a special committee to develop recommendations for the enhancement of pilots' ability to safely navigate ships with the use of advanced navigation technology. The Commission recently accepted the preliminary recommendations of its Navigation Technology Committee and commenced the process for incorporating enhanced training in advanced electronic navigation systems and for the adoption by regulation of a requirement that pilots licensed by the Commission be equipped with, and trained in the use of, portable electronic navigation equipment that the pilots would carry with them when they go aboard a ship. The development of these recommendations, progress to date and estimated timetable to full implementation are summarized below.

INTRODUCTION

In response to the COSCO BUSAN's allision with the fendering system of the Delta Tower of the San Francisco-Oakland Bay Bridge and the ensuing oil spill, Governor Schwarzenegger directed a state investigation into the causes of, and response to, the accident and the spill. The Governor's directive outlined a number of issues to ensure "any action necessary to prevent this from ever happening again." The state Office of Oil Spill Prevention and Response (OSPR) tasked the Harbor Safety Committee of San Francisco Bay Region (HSC) to "analyze the navigational safety-related issues of the Governor's directive and to make appropriate recommendations regarding the prevention aspects of the incident." The HSC agreed to consult with the state agency that licensed the pilot, the Board of Pilot Commissioners for the Bays of San Francisco, San Pablo and Suisun (the Pilot Commission), on certain issues related to the use of shipboard and portable electronic navigation systems by pilots.

BOARD OF PILOT COMMISSIONERS

Immediately following the incident, the Pilot Commission, through its Incident Review Committee (IRC), commenced an investigation to determine whether the incident was caused by pilot error. On December 6, 2007, the IRC filed charges against the pilot in the form of an Accusation alleging that the pilot had reason to doubt whether the ship could safely proceed under the prevailing circumstances, proceeded with insufficient information about the level of visibility along his intended route, proceeded at a speed that was excessive for the circumstances and failed to make full use of all available resources to determine the vessel's position prior to attempting a transit between the Delta and Echo towers of the bridge in conditions of reduced visibility. The pilot has denied the charges and requested a hearing. A hearing on the charges is currently scheduled for September 2, 2008.

The Pilot Commission summarily suspended the pilot's state license on November 30, 2007. That license remains suspended pending the hearing on the IRC's charges.

One of the issues raised in the investigation focused on the electronic navigation system aboard the COSCO BUSAN and whether the pilot was able to make full use of the information provided by it.

NAVIGATION TECHNOLOGY COMMITTEE OF THE BOARD OF PILOT COMMISSIONERS

In response to the incident, the Pilot Commission formed a Navigation Technology Committee to investigate the different types of navigation systems found on ships calling on the San Francisco Bay Area and the sufficiency of pilot training in the use of such systems; and to evaluate portable electronic navigation chart systems that can be brought aboard by pilots to assist in navigation.

The Navigation Technology Committee was chaired by RADM Frank X. Johnston, MARAD, (Ret.), who was appointed by Governor Schwarzenegger to the Pilot Commission in January 2008. Committee members included the chairs of the navigation technology committees for the San Francisco Bar Pilots, Captain Sean Gabe, and for the Jacobsen Pilot Service in Long Beach, Captain Vic Schissler, as well as a retired master mariner who helped Exxon develop an advanced electronic navigation system for its tanker fleet, Captain Tom Hill.

The Committee held well-attended public workshops in February, March and April, 2008, with participation or presentations by experts in navigation technology and in the training and education of mariners in that subject, including Professor Sam Pecota of the California Maritime Academy, Executive Director Glen Paine of the Maritime Institute of Technology and Graduate Studies, Training Director Scott Humphrey of the Coast Guard Vessel Traffic Service for San Francisco Bay Area, Human Factors Expert Dr. Richard Mogford from NASA and various commercial providers of portable pilot navigation units.

The Committee also reviewed how portable pilot units are regulated in other pilotage jurisdictions and various comprehensive reports on their use, liability issues and interface with shipboard equipment. (Copies of the Committee's meeting minutes and the various reports reviewed by the Committee are available from the Pilot Commission.)

The Committee presented its initial report to the Pilot Commission on April 17, 2008, recommending that the Commission's Pilot Training Curriculum Committee be directed to consider incorporating enhanced training in advanced electronic navigation systems that would provide exposure to a greater number of systems and variety of presentations than what is provided by the current training program. In addition, the Committee

recommended that the Commission adopt by regulation a requirement that pilots licensed by the Commission be equipped with, and trained in the use of, portable electronic navigation equipment, commonly known as portable pilot units (PPUs), with specified minimum capabilities and other relevant provisions.

At its May 22, 2008 meeting, the Pilot Commission voted unanimously to direct its Curriculum Committee to consider incorporating enhanced training in advanced electronic navigation systems and directed its staff to begin the formal rulemaking process for adopting the regulation recommended by the Navigation Technology Committee.

ENHANCED TRAINING IN ADVANCED ELECTRONIC NAVIGATION SYSTEMS

The Maritime Institute of Technology and Graduate Studies (MITAGS) has a contract with the Pilot Commission to provide specified training to pilots as mandated by current regulations. The curriculum is specified in the contract. That contract ends June 30, 2009.

The Commission's Pilot Training Curriculum Committee will need to review the current curriculum taught by MITAGS under the contract, possible options to provide enhanced training in advanced electronic navigation systems, and how such training can be incorporated into the current training program within the Commission's regulatory and budget constraints.

Preliminary estimates are that it will take several meetings over a period of two to three months to develop specific recommendations for changing the curriculum and for the Board to take action on those recommendations, followed by possible contract negotiations with MITAGS and the preparation and execution of contract amendments. (Contract matters are handled through the Department of Consumer Affairs.)

If the resulting contract expenses remain within the Commission's budget, the enhanced training, if adopted, could be in place by October 1, 2008. If the additional training expenses would exceed the Board's budget, the Board may need to seek an increase in its spending authorization unless spending on other program areas can be reduced. Such a request could add a minimum of three to four months to the process.

RULEMAKING RE USE OF PORTABLE PILOT UNITS

The rulemaking process is governed by the California Administrative Procedures Act (APA), and by budgetary constraints imposed by the Department of Finance (DOF) and the Legislature. The Pilot Commission has been directed by DOF to use temporary part time government employees known as AGPAs (Associate Government Policy Analysts) to meet the Commission's future rulemaking needs. The Board's current budget does not

authorize expenditures for such employees, but there is such authority in the proposed budget for F/Y 08/09, which begins July 1, 2008. Once that budget has been approved (as part of the annual state budget approval process), the Commission can proceed with the retention of an AGPA and begin the rulemaking process.

The AGPA will need to ensure compliance with APA requirements; prepare the notice of proposed rulemaking and supporting documentation including a fiscal analysis and have them approved by the Office of Administrative Law and, if necessary, the Department of Finance; guide the Pilot Commission through the public comment period (minimum of 45 days from the publication of the notice of proposed rulemaking and 15 additional days following notice of any substantive amendments to the original rulemaking language); guide the Board through the public rulemaking hearing or hearings, until the rulemaking language has been adopted by the Commission; prepare the final rulemaking package and supporting documents; and guide the rulemaking through the approval process before the Office of Administrative Law (OAL). Once approved by OAL, the rulemaking is filed with the Secretary of State and ordinarily becomes law 30 days later.

The entire process can take from six to nine months or more. On an expedited basis, it is possible that the rulemaking could be completed by early 2009.

It should be noted that investigations are ongoing at both the state and federal level, and that the reports and recommendations that will ultimately come out of those investigations, along with various legislation now under consideration, may result in changes or additions to the above actions.

June 5, 2008. Source: Board of Pilot Commission Navigation Technology Committee Report.

ENCLOSURE 4

68943

08/12/08 01:30 PM
RN 08 25254 PAGE 4
Substantive

Amendment 24

On page 4, between lines 13 and 14, insert:

SEC. 3. Section 1176 of the Harbors and Navigation Code is repealed.

~~1176. Pilots and inland pilots shall undergo physical examinations in accordance with standards prescribed by the board in conjunction with the renewal of their license. The examination shall designate that each pilot or inland pilot is fit to perform his or her duties as a pilot.~~

SEC. 4. Section 1176 is added to the Harbors and Navigation Code, to read:

1176. (a) The board shall appoint a physician or physicians who are qualified to determine the suitability of a person to perform his or her duties as a pilot, an inland pilot, or a pilot trainee in accordance with subdivision (c).

(b) An applicant for a pilot trainee position or for a pilot or inland pilot as well as a pilot or inland pilot seeking renewal of his or her license shall undergo a physical examination by a board appointed physician in accordance with standards prescribed by the board. Within 30 days prior to the examination, the applicant or licensee shall submit to the physician conducting the physical examination a complete list of all prescribed medications being taken by or administered to the applicant or licensee.

(c) On the basis of both the examination and an evaluation of the effects of the prescription medications named on the submitted list, the physician shall designate to the board whether or not the pilot, inland pilot, or pilot trainee is fit to perform his or her duties as a pilot, inland pilot, or pilot trainee.

(d) The license of a pilot or inland pilot shall not be renewed unless he or she is found fit for duty pursuant to subdivision (c).

(e) Whenever a pilot, inland pilot, or pilot trainee is prescribed either a new dosage of a medication or a new medication, or suspends the use of a prescribed medication, he or she shall, within 10 days, submit that information to the board appointed physician having possession of the prescribed medication list submitted pursuant to subdivision (b). Whenever the physician receives the updated information, the physician shall determine whether or not the medication change affects the licensee's or trainee's fitness for duty. If the physician determines that the medication change results in the pilot, inland pilot, or pilot trainee being unfit for duty, the physician shall inform the board.

(f) The board may terminate a pilot trainee or suspend or revoke the license of a pilot or an inland pilot who fails to submit the prescribed medication information required by this section.

Amendment 25

On page 4, line 14, strike out "SEC. 3." and insert:

SEC. 5.

AMENDED IN ASSEMBLY JUNE 11, 2008

AMENDED IN ASSEMBLY MAY 6, 2008

SENATE BILL

No. 1217

Introduced by Senator Yee

February 14, 2008

An act to add Section 1157.5 to the Harbors and Navigation Code, relating to vessels, and making an appropriation therefor.

LEGISLATIVE COUNSEL'S DIGEST

SB 1217, as amended, Yee. Board of Pilot Commissioners.

Existing law establishes in state government the Board of Pilot Commissioners, with jurisdiction over Monterey Bay and the Bays of San Francisco, San Pablo, and Suisun. Existing law authorizes the board to appoint an executive director to perform various duties.

This bill would require the board, on or before ~~February~~ *April* 15, 2010, and annually thereafter, to submit to the Secretary of the Senate and the Chief Clerk of the Assembly a report *containing specified information* describing its activities for the preceding calendar year. The bill would also require the board, on or before April 15, 2010, and annually thereafter, to submit to the Secretary of the Senate, the Chief Clerk of the Assembly, the Department of Finance, and the Joint Legislative Budget Committee a summary of the board's finances.

Existing law continuously appropriates the funds in the Board of Pilot Commissioners' Special Fund for the payment of the compensation and expenses of the board, its officers and employees, and training programs.

By imposing the duty to submit an annual report of the board's activities and a summary of the board's finances, the bill would make an appropriation.

This bill would provide that certain provisions would be operative only if SB 1627 and this bill are both enacted and become effective on or before January 1, 2009, and other provisions would be operative only if this bill is enacted and becomes effective on or before January 1, 2009, and SB 1627 is not enacted.

Vote: majority. Appropriation: yes. Fiscal committee: yes.
State-mandated local program: no.

The people of the State of California do enact as follows:

1 SECTION 1. Section 1157.5 is added to the Harbors and
2 Navigation Code, to read:

3 1157.5. (a) On or before ~~February~~ *April* 15, 2010, and annually
4 thereafter, the board shall submit to the Secretary of the Senate
5 and the Chief Clerk of the Assembly a report describing the board's
6 activities for the preceding calendar year. The report shall include,
7 but not be limited to, all of the following:

8 (1) The number of vessel movements across the bar, on the bays,
9 and on the rivers within the board's jurisdiction.

10 (2) The name of each licensed pilot, *inland pilot*, and pilot
11 trainee, and the status of each person. *If a person has had more*
12 *than one status during the reporting year, each status and the*
13 *length of time in that status shall be indicated. For the purposes*
14 *of this section, "status" includes all of the following designations:*

15 (A) *Licensed and fit for duty.*

16 (B) *Licensed and not fit for duty.*

17 (C) *Licensed and on authorized training.*

18 (D) *Licensed and on active military duty.*

19 (E) *Licensed and on leave of absence.*

20 (F) *Licensed but license suspended.*

21 (3) A summary of each report of misconduct or a navigational
22 incident involving a pilot, inland pilot, or pilot trainee, or other
23 matters for which a license issued by the board may be revoked
24 or suspended. For those cases that have been closed, the summary
25 shall include a description of findings made by the incident review
26 committee and of the resulting action taken by the board. For those
27 cases that are still under investigation, the summary shall include
28 a description of the reported incident and an estimated completion
29 date for the investigation. *For those closed cases involving a pilot*
30 *who has been involved in a prior incident where a finding of pilot*

1 *error had been made, the report shall also include a summary of*
2 *that incident.*

3 (b) On or before April 15, 2010, and annually thereafter, the
4 board shall submit to the Secretary of the Senate, the Chief Clerk
5 of the Assembly, the Department of Finance, and the Joint
6 Legislative Budget Committee a summary of the board's finances.
7 Information to be included in the summary and its format shall be
8 specified by the Department of Finance.

9 SEC. 2. Section 1157.5 is added to the Harbors and Navigation
10 Code, to read:

11 1157.5. (a) On or before ~~February~~ *April* 15, 2010, and annually
12 thereafter, the board shall submit to the Secretary of the Senate,
13 the Chief Clerk of the Assembly, and the Secretary of Business,
14 Transportation and Housing a report describing the board's
15 activities for the preceding calendar year. The report shall include,
16 but not be limited to, all of the following:

17 (1) The number of vessel movements across the bar, on the
18 bays, and on the rivers within the board's jurisdiction.

19 (2) The name of each licensed pilot, *inland pilot*, and pilot
20 trainee, and the status of each person. *If a person has had more*
21 *than one status during the reporting year, each status and the*
22 *length of time in that status shall be indicated. For the purposes*
23 *of this section, "status" includes all of the following designations:*

24 (A) *Licensed and fit for duty.*

25 (B) *Licensed and not fit for duty.*

26 (C) *Licensed and on authorized training.*

27 (D) *Licensed and on active military duty.*

28 (E) *Licensed and on leave of absence.*

29 (F) *Licensed but license suspended.*

30 (3) A summary of each report of misconduct or a navigational
31 incident involving a pilot, inland pilot, or pilot trainee, or other
32 matters for which a license issued by the board may be revoked
33 or suspended. For those cases that have been closed, the summary
34 shall include a description of findings made by the incident review
35 committee and of the resulting action taken by the board. For those
36 cases that are still under investigation, the summary shall include
37 a description of the reported incident and an estimated completion
38 date for the investigation. *For those closed cases involving a pilot*
39 *who has been involved in a prior incident where a finding of pilot*

1 *error had been made, the report shall also include a summary of*
2 *that incident.*

3 (b) On or before April 15, 2010, and annually thereafter, the
4 board shall submit to the Secretary of the Senate, the Chief Clerk
5 of the Assembly, the Secretary of Business, Transportation and
6 Housing, the Department of Finance, and the Joint Legislative
7 Budget Committee a summary of the board's finances. Information
8 to be included in the summary and its format shall be specified by
9 the Department of Finance. The summary shall set forth separate
10 reports for the following funds:

11 (1) Board of Pilot Commissioners' Special Fund.

12 (2) Pilot Trainee Fund.

13 (3) Pilot and Inland Pilot Continuing Education Fund.

14 SEC. 3. (a) Section 1 of this bill shall only become operative
15 if this bill is enacted and becomes effective on or before January
16 1, 2009, and Senate Bill 1627 is not enacted, in which case Section
17 2 of this bill shall not become operative.

18 (b) Section 2 of this bill shall only become operative if both this
19 bill and Senate Bill 1627 are enacted and become effective on or
20 before January 1, 2009, in which case Section 1 of this bill shall
21 not become operative.

68943

08/12/08 01:30 PM
RN 08 25254 PAGE 1
Substantive

AMENDMENTS TO SENATE BILL NO. 1217
AS AMENDED IN ASSEMBLY JUNE 11, 2008

Amendment 1

In line 1 of the title, after the second "to" insert:

, and to repeal and add Section 1176 of,

Amendment 2

On page 2, line 3, strike out "(a)"

Amendment 3

On page 2, line 3, strike out "(1)" and insert:

(a)

Amendment 4

On page 2, line 10, strike out "(2)" and insert:

(b)

Amendment 5

On page 2, line 15, strike out "(A)" and insert:

(1)

Amendment 6

On page 2, line 16, strike out "(B)" and insert:

(2)

Amendment 7

On page 2, line 17, strike out "(C)" and insert:

(3)



15 SEP 2008

68943

08/12/08 01:30 PM
RN 08 25254 PAGE 2
Substantive

Amendment 8

On page 2, line 18, strike out "(D)" and insert:

(4)

Amendment 9

On page 2, line 19, strike out "(E)" and insert:

(5)

Amendment 10

On page 2, line 20, strike out "(F)" and insert:

(6)

Amendment 11

On page 2, line 21, strike out "(3)" and insert:

(c)

Amendment 12

On page 3, strike out lines 3 to 8, inclusive

Amendment 13

On page 3, line 11, strike out "(a)"

Amendment 14

On page 3, line 17, strike out "(1)" and insert:

(a)

Amendment 15

On page 3, line 19, strike out "(2)" and insert:

(b)

68943

08/12/08 01:30 PM
RN 08 25254 PAGE 3
Substantive

Amendment 16
On page 3, line 24, strike out "(A)" and insert:

(1)

Amendment 17
On page 3, line 25, strike out "(B)" and insert:

(2)

Amendment 18
On page 3, line 26, strike out "(C)" and insert:

(3)

Amendment 19
On page 3, line 27, strike out "(D)" and insert:

(4)

Amendment 20
On page 3, line 28, strike out "(E)" and insert:

(5)

Amendment 21
On page 3, line 29, strike out "(F)" and insert:

(6)

Amendment 22
On page 3, line 30, strike out "(3)" and insert:

(c)

Amendment 23
On page 4, strike out lines 3 to 13, inclusive

68943

08/12/08 01:30 PM
RN 08 25254 PAGE 4
Substantive

Amendment 24

On page 4, between lines 13 and 14, insert:

SEC. 3. Section 1176 of the Harbors and Navigation Code is repealed.

~~1176. Pilots and inland pilots shall undergo physical examinations in accordance with standards prescribed by the board in conjunction with the renewal of their license. The examination shall designate that each pilot or inland pilot is fit to perform his or her duties as a pilot.~~

SEC. 4. Section 1176 is added to the Harbors and Navigation Code, to read:

1176. (a) The board shall appoint a physician or physicians who are qualified to determine the suitability of a person to perform his or her duties as a pilot, an inland pilot, or a pilot trainee in accordance with subdivision (c).

(b) An applicant for a pilot trainee position or for a pilot or inland pilot as well as a pilot or inland pilot seeking renewal of his or her license shall undergo a physical examination by a board appointed physician in accordance with standards prescribed by the board. Within 30 days prior to the examination, the applicant or licensee shall submit to the physician conducting the physical examination a complete list of all prescribed medications being taken by or administered to the applicant or licensee.

(c) On the basis of both the examination and an evaluation of the effects of the prescription medications named on the submitted list, the physician shall designate to the board whether or not the pilot, inland pilot, or pilot trainee is fit to perform his or her duties as a pilot, inland pilot, or pilot trainee.

(d) The license of a pilot or inland pilot shall not be renewed unless he or she is found fit for duty pursuant to subdivision (c).

(e) Whenever a pilot, inland pilot, or pilot trainee is prescribed either a new dosage of a medication or a new medication, or suspends the use of a prescribed medication, he or she shall, within 10 days, submit that information to the board appointed physician having possession of the prescribed medication list submitted pursuant to subdivision (b). Whenever the physician receives the updated information, the physician shall determine whether or not the medication change affects the licensee's or trainee's fitness for duty. If the physician determines that the medication change results in the pilot, inland pilot, or pilot trainee being unfit for duty, the physician shall inform the board.

(f) The board may terminate a pilot trainee or suspend or revoke the license of a pilot or an inland pilot who fails to submit the prescribed medication information required by this section.

Amendment 25

On page 4, line 14, strike out "SEC. 3." and insert:

SEC. 5.

ENCLOSURE 5

BOARD OF PILOT COMMISSIONERS
FOR THE BAYS OF SAN FRANCISCO, SAN PABLO AND SUISUN
FY 2008-09 SPRING FINANCE LETTER
M/V COSCO BUSAN Incident/Board Task Review
SFL # 8530-01
Priority #1

A. Nature of Request

The Board of Pilot Commissioners (Board) requests a special fund budget augmentation of \$367,000 in FY 2008-09, \$58,000 in FY 2009-10, and \$39,000 ongoing, to fund expenses incurred in the investigation and administrative hearing following the M/V (motor vessel) COSCO BUSAN allision with the San Francisco/Oakland Bay Bridge in November 2007, and also to review and assess Board procedures to address questions that have surfaced as a result of the incident.

M/V COSCO BUSAN

The Board's Incident Review Committee (IRC) has investigated the M/V COSCO BUSAN incident and brought charges (termed an "accusation") against the Board-licensed pilot who was directing navigation of the vessel at the time it struck the San Francisco/Oakland Bay Bridge. The accusation will result in an administrative hearing and may result in suspension or revocation of the pilot's state license. The Administrative Law Judge (ALJ) has scheduled the hearing for early September 2008.

Failure to proceed with the administrative action would undermine public confidence and the ability of the state to regulate pilotage in waters under its jurisdiction. Public interest in the incident and the Board's response justify the highest priority with respect to continued funding, expenditure authority and the ability to continue the administrative hearing to completion. A Deficiency Funding Request of \$255,000 for FY 2007/08 to meet unanticipated legal costs was previously submitted and is awaiting legislative approval.

BOARD TASK REVIEW

As a result of this incident, the Board has identified a number of areas in which its procedures can be strengthened to provide the public with increased assurance that steps will be taken to further reduce the risk of rare, but potentially catastrophic accidents such as the M/V COSCO BUSAN. These steps include a comprehensive review of pilot fitness standards, training in shipboard and portable electronic navigation systems that are intended to provide pilots with the best achievable means of safely navigating in reduced visibility conditions, and strengthening the Board's incident investigation procedures to ensure early identification of possible problem areas for pilots.

The Board's task review will include a review of navigation technology, pilot fitness standards, the Board's IRC, staff and commissioner training, drug and alcohol testing for pilot trainees, and selection diversity outreach.

B. Background/History

M/V COSCO BUSAN

On November 7, 2007, the M/V COSCO BUSAN, a 902-foot long container ship, struck a blow to the "Delta Tower" of the San Francisco-Oakland Bay Bridge. The vessel damaged the fendering system of the bridge and, in turn, suffered a gash in the shell plating approximately 100 feet long, 10 feet tall, and from several inches to several feet deep. The gash penetrated two fuel tanks, causing an oil spill of approximately 54,000 gallons of heavy bunker fuel into the bay. A board-licensed pilot was directing the vessel at the time of the accident. The IRC dispatched an investigator and began its review to determine whether pilot error was involved. The IRC subsequently determined that there was sufficient cause to file charges of negligence against the pilot and recommended summary suspension of his license pending a suspension or revocation hearing. On November 30, 2007, the Board voted to summarily suspend the pilot's state license. On December 6, 2007, the IRC filed an accusation.

During the course of the investigation, the Board incurred extraordinary legal expenses, which have exceeded current budgeted levels of funding. A hearing is scheduled for early September 2008. It is in the public's best interest that this hearing proceed. Outside counsel will present the case against the pilot at the administrative hearing in September. After two pre-hearing conferences with the ALJ, the ALJ has estimated that the hearing will take 16 court days allocated over four weeks to reach its conclusions. A criminal investigation by the U.S. Attorney's office that has resulted in criminal charges against the pilot, difficulties with accessing witnesses and processing admissible evidence from the ship, as well as various other ongoing lawsuits, have complicated and prolonged the process.

BOARD TASK REVIEW

Navigation Technology

As a result of the M/V COSCO BUSAN incident, the Board established a Navigation Technology Committee. The committee has been tasked with investigating the different types of navigation systems generally found on ships entering the San Francisco Bay Area, the sufficiency of pilot training in the use of these systems, and to evaluate Portable Pilot Units (portable electronic chart systems brought aboard a ship by a pilot to assist in navigation). The Navigation Technology Committee will also work with the regional Harbor Safety Committee's various subcommittees to help develop "best practices" in response

to lessons learned from the M/V COSCO BUSAN, particularly those dealing with navigation issues.

While much of the Committee's preliminary work should be completed during the current fiscal year, it is expected to continue evaluating this complex and evolving area on an ongoing basis. The committee's recommendations are likely to result in changes to the current training provided in shipboard electronic navigation systems and initiate training in portable pilot units. These recommendations are expected to result in new rulemaking, which will require additional regulations addressing these issues. Proposed changes to current training curriculum will be reviewed and evaluated by the Board's Pilot Training Curriculum Committee, which also evaluates potential vendors that provide such training. Currently, the Maritime Institute of Technology & Graduate Studies, as mandated by Title 7 California Code of Regulations (CCR) § 215(b) (2), is providing training in advanced electronic navigation systems.

Pilot Fitness Standards

Harbors and Navigation Code (HNC) §§ 1175 and 1176 require pilots to be of good mental and physical health and to undergo physical examinations in accordance with standards prescribed by the Board. The Board's current procedures for determining physical and mental competency of pilots are set forth in Title 7, CCR § 217.

Following the M/V COSCO BUSAN allision, questions were raised regarding the physical and mental competency of the pilot, the standards used by state and federal agencies in determining pilots' physical and mental competency, and the procedures used to ensure that pilots meet such standards. In response, the Board's Pilot Fitness Committee has been tasked with:

- 1) Conducting a comprehensive review of the physical and mental fitness standards for pilots, including review of the Board's current standards as outlined in the Reference Guide for Physicians for the Physical Examination for Duty Status of Seafarers in the U.S. Merchant Marine adopted by the Seafarers Health Improvement Program (SHIP); current U.S. Coast Guard Physical Evaluation Guidelines for Merchant Mariner's Documents and Licenses (NVIC 2-98); the proposed draft replacement to NVIC 2-98 published in the Federal Register on 9/28/06; recommendations by the National Transportation Safety Board regarding the fitness of pilots (including M-97-44).

- 2) Preparing recommendations to the Board for the adoption of standards that meet or exceed Coast Guard standards to ensure that each pilot is physically and mentally fit to perform the duties of a pilot.

- 3) Preparing recommendations to the Board for the amendment of its procedures to determine a pilot's physical and mental competency, including procedures to ensure the disclosure and appropriate evaluation of the history and presence of any medical conditions, symptoms, or medication use that would affect an individual's fitness to pilot a vessel.
- 4) Addressing state of the art methodology to proactively detect a decline in a pilot's situational awareness, that is, the ability to track and act on various communications and information relevant to the vessel's safe navigation, and to plan ahead for upcoming traffic and environmental situations.
- 5) Preparing recommendations to improve appeal procedures to ensure protection of the public and provide due process for pilots.
- 6) Evaluating the costs and benefits of requiring the opinion of a second medical examiner.

These tasks are likely to require a minimum of nine to twelve meetings over a one-year period. Current standards are not specific to pilots, but for the most part, apply to all mariners. Standards specific to pilots may be warranted. Sleep deprivation and fatigue issues are likely to be among those at the forefront and pose challenging issues that will need to be resolved.

Review of the Board's Incident Review Committee

The Board's Incident Review Committee (IRC) is established by HNC § 1180.3 to review and investigate all reports of misconduct or navigational incidents involving pilots. Its procedures are set forth in Title 7 CCR § 210.

Following the M/V COSCO BUSAN incident, questions were raised regarding the sufficiency of reviewing a pilot's incident history to determine whether there is a pattern of underlying problems that warrant follow up or further investigation. In addition, there has not been a comprehensive review of the Board's incident investigation procedures since the establishment of the IRC in 1993. As a result, the Board has initiated plans for a comprehensive review of the Board's investigation procedures and the guidelines for the IRC. The purpose is to ensure that the incident investigation and review process is sufficiently rigorous to enable the Board to carry out its functions of pilot oversight and to take steps to minimize the risk of recurrence of preventable incidents.

Staff/Commissioner Training

During FY 2007/08, the Board initiated its first staff training programs using CPS Human Resource Services as the vendor. The training programs are specific to matters affecting the administration of the Board. Examples include performance

appraisal, administrative writing, and an E-communications workshop. Current year training is focused on the state budget process and budget change proposals. CPS offers many courses that would be of use to the Board's staff and commissioners, increasing their knowledge and professionalism.

Additionally, questions have been raised concerning the use of electronic navigation devices by the pilot of the MV COSCO BUSAN. Recent changes in the rapidly evolving field of electronic navigation make it imperative that the Board's executive director, who also is the Board's chief investigator, obtain a thorough knowledge of electronic navigation and remain current in the developments of this field. The Board intends to maintain regular training programs for staff and commissioners in the future. The Board will require additional funding to accommodate the ongoing training needs.

Mandatory Trainee Drug and Alcohol Testing

Federal rules now require that the Board implement a mandatory pilot trainee drug and alcohol testing program. This is a new requirement for the Board. It is anticipated that regulations will be required to outline the procedures.

Pilot Trainee Selection Diversity Outreach

The Legislature has raised concerns about the diversity of the Board's licensees in subcommittee meetings. The Board has established an Ad Hoc Committee on Pilot Selection. The Ad Hoc Committee on Pilot Selection is expected to provide the Board with options intended to increase the diversity of pilot trainees and the pilots licensed by the Board. One mechanism to achieve greater diversity among pilots is to establish and maintain a recruiting program to encourage qualified women and minority cadets and mariners, to sit for the Board's trainee selection examination, which is administered every few years. The recruitment program may be a joint effort with the California Maritime Academy or the Board may contract with an independent contractor.

C. State Level Considerations

The Legislature has recognized the importance of the Board, as noted in Harbors and Navigation Code:

Section 1100. The Legislature finds and declares that it is the policy of the state to ensure the safety of persons, vessels, and property using the Bays of San Francisco, San Pablo, and Suisun, and the tributaries thereof, and to avoid damage to such waters and the surrounding ecosystems, as a result of vessel collision or damage by providing competent, efficient, and regulated pilotage for vessels required by this division to secure pilotage services.

Section 1101. The Legislature further finds and declares all of the following:

(c) The increase in vessel size and traffic, and the increase in cargoes carried in bulk, particularly oil and gas and hazardous chemicals, creates substantial hazards to the life, property, and values associated with the environment of such waters.

(e) A program of pilot regulation and licensing is necessary in order to ascertain and guarantee the qualifications, fitness, and reliability of qualified personnel who can provide safe pilotage of vessels entering and using the Bays of San Francisco, San Pablo, and Suisun.

(h) The individual physical safety and well being of pilots is of vital importance in providing required pilot services.

The M/V COSCO BUSAN allision and resulting oil spill, calls into focus all of the Legislature's findings and declarations. The Board's continuing response to the allision and the Board's task augmentation proposals are consistent with the Legislature's intention.

The Board of Pilot Commissioners for the Bays of San Francisco, San Pablo and Suisun is a specially funded agency. Funds are collected through user fees paid by shippers who use pilotage services. This proposal has no impact on other state departments and does not require funding from any other source, including the general fund.

D. Facility/Capital Outlay Considerations

There are no new facilities or capital needs. The Board office can be used for meetings or workshops and contractors provide their own facilities.

E. Justification

M/V COSCO BUSAN

The Board's legal counsel estimates additional expenses in FY 2008/09 of approximately \$96,335 to complete trial preparations and the administrative hearing. There will be an additional cost of \$5,000 for interpreter services. The crew of the M/V COSCO BUSAN speak Chinese or minimal nautical English. An interpreter will be needed to interview witnesses for the administrative hearing.

The Board anticipates additional Office of Administrative Hearing fees in the amount of \$36,100 for services of the ALJ during FY 2008/09 (190 hours at \$190 per hour for 16 days of hearing and decision preparation). The total estimated cost to complete the hearings for the M/V COSCO BUSAN allision in FY 2008/09 is \$137,435.

Attachment 1 provides a cost summary of this entire proposal.

BOARD TASK REVIEW

Total FY 2008/09 Estimated Cost: \$229,075

The Board requests funding for a temporary help position in the Associate Governmental Program Analyst (AGPA) classification to complete the necessary tasks related to rulemaking and to prepare required filing and documentation, as needed. The Board estimates the need for a 0.5 position and funding in the first two years and minimal funding ongoing. Specific tasks and associated costs for the AGPA are listed in Attachment 2.

The accumulated expansion of Board responsibilities over the years and the recent tasking in response to the M/V COSCO BUSAN incident are causing a burden to Board staffing and resources. This Spring Finance Letter (SFL) identifies those issues and provides cost estimates. The Navigation Technology, Pilot Fitness and IRC Review issues are discrete and once completed, will require a periodic review. The staff/commissioner training, drug testing program and outreach program are ongoing and will require an increase in the Board's ongoing expenditure authority. Each area of concern is listed below and is summarized on Attachment 1:

A) Navigation and Technology

The Navigation and Technology Committee has been directed to report and make recommendations to the Board with respect to its findings. It is anticipated that the committee will propose policy changes that will result in formal rulemaking. The rulemaking process would begin, and likely conclude in early FY 2008/09. Costs associated with committee meetings and review and advice from the Board's maritime attorney are expected to remain within the existing budget.

B) Pilot Fitness Standards

Review of the Board's physical and mental fitness standards and physical examination processes for licensees requires contracting with one or more medical specialists who have expertise in occupational medicine and who have or can acquire a thorough understanding of the profession and challenges of maritime piloting. This is a new one-time task and would be part of the Board's

operating expenses. It cannot be covered under the present pilot physical examination authority in FY 2008/09.

The Board anticipates working with the staff of the University of California at San Francisco Medical Center or other northern California teaching hospitals in connection with this study. Consulting physicians are expected to cost \$300 per hour.

This review is expected to result in recommendations for amendments to the current regulations and possibly in amendments to the authorizing statute. These regulatory activities would occur after FY 2008/09.

C) Review of the Board's Incident Review Committee

Review of the Board's IRC is an important element of the Board's overall review of its mission and practices. This review is likely to require a minimum of eight workshops and will commence early in FY 2008/09. The focus of the review will be to: ensure industry, pilot and public participation and input; develop directions for an audit; review audit results; and develop recommendations to the Board.

The first workshop will focus on bringing subject matter experts together to examine current IRC procedures and identify the general direction of the review. The second will be to develop the initial scope of work for the consulting contract; the third will be to finalize the scope of work. After the contractor completes its work, three workshops would be held to review the contractor's report and proposals. The last two workshops will finalize the report.

D) Staff/Commissioner Training

The Board seeks expenditure authority for staff and commissioner training to maintain and enhance skills needed to carry out the mandate of the Board.

The Board seeks expenditure authority for FY 2008/09 for thirteen days of CPS or equivalent training at \$150 per class day plus travel and per diem. Most courses are given in Sacramento. The Board anticipates that the training would be allocated as three days for the Executive Director, two days for the Administrative Assistant, five days for the analyst, and three days for commissioners. Further, the Board seeks expenditure authority to send its Executive Director to an electronic navigation training workshop. Generally, these courses are five days in duration and require out-of-state travel and per diem. Course cost is expected to be \$300 per day per participant. Total estimated cost for these training programs is \$5,000 including travel.

The Board seeks expenditure authority to send its Executive Director and the Chair of the Board's IRC to a training program focused on investigation of marine incidents, e.g., collisions and groundings, and the USCG and International

Maritime Organization requirements regarding pilot ladders and other pilot transfer equipment. These will likely be separate programs. Generally, these courses are expected to be five days in duration for investigation courses, and two days for pilot ladder courses. The Board seeks to continue ongoing training for the Executive Director and committee chairs, as needed, to maintain a level of competency in the evolving fields of marine investigation, navigation technology and pilot training. Courses are expected to cost \$300 per day per participant plus out-of-state travel and per diem. Total estimated cost is \$10,000 annually.

E) Mandatory Trainee Drug and Alcohol Testing

The Board seeks to establish a new line item to provide mandatory drug and alcohol testing for pilot trainees in accordance with recent changes in U.S. Coast Guard requirements. Presently there are 13 trainees in the training program. Annual costs are estimated at 13 trainees at \$75.00 per test or \$975.

F) Pilot Trainee Selection Diversity Outreach

The Board seeks to establish a new line item to fund an interagency agreement with the California Maritime Academy or to contract with an independent contractor to conduct recruiting and outreach to qualified minority and women mariners to compete for entry into the Board's pilot trainee training program. Estimated cost is \$25,000 in FY 2008/09 to cover initial development of the outreach program and first year recruitment efforts, and \$10,000 ongoing.

F. Outcomes and Accountability

This proposal is expected to have the following outcomes:

- Complete rulemaking proposals aimed at improving safety for the public, pilot trainees, and licensed pilots.
- Identify improvements to navigation technology and update pilot training.
- Audit incident review procedures.
- Establish new procedures for the evaluation of pilot fitness standards.
- Evaluate staff and commissioner training programs.
- Implement new drug and alcohol testing requirements.
- Achieve greater diversity in pilot recruitment programs.

The establishment of the identified committees will ensure that ongoing evaluations of technology, pilot fitness standards, staff and commissioner training, and increased diversity will meet the needs of increased public and pilot safety standards.

The Board's Navigation Technology Committee, Pilot Training Curriculum Committee, Pilot Fitness Committee, and Ad Hoc Committee on Pilot Selection will conduct periodic follow-up meetings to track the progress of implementation

and to assess the efficacy of the changes made as a result of their recommendations. Annual reports on the results of their assessments will be provided to the Board. Guidelines for these assessments are to be included in the committees' initial recommendations.

Board staff will report annually on all training provided to staff and commissioners to permit reassessment and planning for the following year's training.

The Executive Director will report annually to the Board on the results of random drug testing of pilot trainees consistent with the timeline required for providing such reports to the U. S. Coast Guard.

G. Analysis of Feasible Alternatives

Alternate 1: Approve a special fund expenditure authority budget augmentation of \$367,000 in FY 2008/09, \$58,000 in FY 2009/10, and \$39,000 ongoing. This alternative would provide the Board with the resources needed to address the concerns of the legislature and the public in the aftermath of the M/V COSCO BUSAN allision. It would also enable the Board to review and update current regulations, complete an audit review of Board procedures, proactively address increased pilot physical and mental fitness standards, improve the availability of new technology, improve ongoing staff and commissioner training needs, meet the new U.S. Coast Guard drug and alcohol testing requirements, and provide for a diversity outreach selection process.

Alternate 2: Approve only one of the major initiatives (Navigation Technology rulemaking, Pilot Fitness Standards, or Review of the Board's Incident Review Committee). This would reduce the cost and burden on Board members and staff. However, this alternate would limit the anticipated improvement to public and pilot safety. The Board believes that with the availability of part-time AGPA assistance it can successfully address the increased workload.

Alternative 3: Do nothing. This alternative would neglect to address the specific areas of concern raised by the legislature and the public. Public safety would remain at increased risk.

H. Timetable

Beginning July 1, 2008: Begin recruiting to fill the temp help AGPA position.

Board to act on initial recommendations of Navigation Technology Committee.

Pilot Training Curriculum Committee to review training contracts for possible changes in curriculum as recommended by Navigation Technology Committee and directed by Board.

Commence rulemaking process identified by Navigation Technology Committee and approved by Board following timetable required by Administrative Procedures Act and OAL regulations.

Upon recruitment of AGPA, commence scope of work and selection process for medical consultant(s).

September 2008: Administrative hearing on IRC's Accusation

October 2008: Decision rendered following hearing on IRC's Accusation

Commence or continue Pilot Fitness Committee workshops to guide, consider and evaluate the research and recommendations of medical consultant.

November 2008: Complete interagency agreement with CMA or independent contractor for recruitment/diversity outreach.

December 2008: Selection of IRC auditor, commence workshops to guide, consider and evaluate results of audit.

Board staff/commissioner training to be scheduled based on availability of classes throughout FY 08/09.

I. Recommendations

Alternative 1 is the only alternative that gives the Board the resources to address public and pilot protection needs.

EXHIBIT 1

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

PRELIMINARY INCIDENT REPORT

BY HAND DELIVERY OR FAX

State Board of Pilot Commissioners
for the Bays of San Francisco, San Pablo and Suisun
Pier 9, Suite 102
San Francisco, CA 94111

Commissioners:


This is a preliminary notice of the following incident.

Pilot: J. COYA
Date: 7-NOV-07 Time: 0830±
Vessel: COSCO BUSAN
Vessel's Agent: HANJIN
Location: SF BAY

Nature of Incident:

- grounding
- collision (name of other vessel _____)
- allision (object allided with DELTA TOWER BAYBRIDGE)
- other _____

The pilot involved will report further as may be appropriate under California State Harbors and Navigation Code and Commission regulations.







Port Agent

Encl: (1)

EXHIBIT 2

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007





SECTION III. PERSONNEL ACCIDENT INFORMATION

27. Person Involved <input type="checkbox"/> MALE or <input type="checkbox"/> FEMALE <input type="checkbox"/> DEAD <input type="checkbox"/> INJURED <input type="checkbox"/> MISSING		27a. Name (Last, First, Middle Name) 27b. Address (City, State, Zip Code)		27c. Status: <input type="checkbox"/> Crew <input type="checkbox"/> Passenger <input type="checkbox"/> Other	
28. Birth Date	29. Telephone No.	30. Job Position		31. (Check here if off duty) <input type="checkbox"/>	
32. Employer - (if different from Block 18, fill in Name, Address, Telephone No.)					
33. Person's Time			YEAR(S)	MONTH(S)	34. Industry of Employer (Towing, Fishing, Shipping, Crew Supply, Drilling, etc.)
A. IN THIS INDUSTRY -			_____	_____	35. Was the Injured Person Incapacitated 72 Hours or More? 36. Date of Death
B. WITH THIS COMPANY -			_____	_____	
C. IN PRESENT JOB OR POSITION -			_____	_____	
D. ON PRESENT VESSEL/FACILITY -			_____	_____	
E. HOURS ON DUTY WHEN ACCIDENT OCCURRED -			_____	_____	
37. Activity of Person at Time of Accident					
38. Specific Location of Accident on Vessel/Facility					
39. Type of Accident (Fall, Caught between, etc.)			40. Resulting Injury (Cut, Bruise, Fracture, Burn, etc.)		
41. Part of Body Injured			42. Equipment Involved in Accident		
43. Specific Object, Part of the Equipment in block 42., or Substance (Chemical, Solvent, etc.) that directly produced the Injury.					

SECTION IV. DESCRIPTION OF CASUALTY

44. Describe how accident occurred, damage, information on alcohol/drug involvement and recommendations for corrective safety measures. (See instructions and attach additional sheets if necessary).

VESSEL BOUND FROM DERTM OAKLAND 56 FOR SEA. UNDERWAY AT 0748 IN RESTRICTED VISIBILITY WITH PILOT JOHN COTR CONNING. TUG REVOLUTION ASSISTING. FOUR SIGNALS SOUNDED, AT 0830 PORT SIDE OF VESSEL STRUCK D PIER OF OAKLAND BAY BRIDGE. CAUSING DAMAGE TO VESSEL & OIL SPILL. AUTHORITIES NOTIFIED & VESSEL PROCEEDED TO ANCHOR.

45. Witness (Name, Address, Telephone No.) SUN MAO CAI
46. Witness (Name, Address, Telephone No.) WANQI HONG ZHI

SECTION V. PERSON MAKING THIS REPORT

47. Name (PRINT) (Last, First, Middle) SUN MAO CAI	47b. Address (City, State, Zip Code) DALIAN LIAONING CHINA	47c. Title CAPTAIN
47a. Signature 		47d. Telephone No.
		47e. Date 12. NOV. 2007

FOR COAST GUARD USE ONLY

REPORTING OFFICE:

MISLE Incident Investigation Activity Data Entry:		MISLE Incident Investigation Activity Number (if applicable)			
<input type="checkbox"/> NONE	<input type="checkbox"/> PRELIMINARY	<input type="checkbox"/> DATA COLLECTION	<input type="checkbox"/> INFORMAL	<input type="checkbox"/> FORMAL	
Serious Marine Incident <input type="checkbox"/> Yes <input type="checkbox"/> No	INVESTIGATOR (Name)	DATE	APPROVED BY (Name)	DATE	
Major Marine Casualty <input type="checkbox"/> Yes <input type="checkbox"/> No					

SECTION III. PERSONNEL ACCIDENT INFORMATION

27. Person Involved <input type="checkbox"/> MALE or <input type="checkbox"/> FEMALE <input type="checkbox"/> DEAD <input type="checkbox"/> INJURED <input type="checkbox"/> MISSING		27a. Name (Last, First, Middle Name) N/A		27c. Status <input type="checkbox"/> Crew <input type="checkbox"/> Passenger <input type="checkbox"/> Other	
28. Birth Date		29. Telephone No.		30. Job Position	
27b. Address (City, State, Zip Code)					
31. (Check here if off duty) <input type="checkbox"/>					
32. Employer - (if different from Block 18, fill in Name, Address, Telephone No.)					
33. Person's Time			34. Industry of Employer (Towing, Fishing, Shipping, Crew Supply, Drilling, etc.)		
A. IN THIS INDUSTRY -			YEAR(S) _____ MONTH(S) _____		
B. WITH THIS COMPANY -			_____		
C. IN PRESENT JOB OR POSITION -			_____		
D. ON PRESENT VESSEL/FACILITY -			_____		
E. HOURS ON DUTY WHEN ACCIDENT OCCURRED -			_____		
35. Was the Injured Person Incapacitated 72 Hours or More?					
36. Date of Death					
37. Activity of Person at Time of Accident					
38. Specific Location of Accident on Vessel/Facility					
39. Type of Accident (Fall, Caught between, etc.)			40. Resulting Injury (Cut, Bruise, Fracture, Burn, etc.)		
41. Part of Body Injured			42. Equipment Involved in Accident		
43. Specific Object, Part of the Equipment in block 42., or Substance (Chemical, Solvent, etc.) that directly produced the Injury.					

SECTION IV. DESCRIPTION OF CASUALTY

44. Describe how accident occurred, damage, information on alcohol/drug involvement and recommendations for corrective safety measures. (See instructions and attach additional sheets if necessary).

0645- Pilot "R" on COSCO BUSAN asked tug REVOLUTION to put up a single headline on the port quarter of the ship. 0755- Pilot asks us to back easy, working up to half, assisting ship off the dock. Approximately 0800 - Pilot orders us to cast off and shift to center lead aft, slack line. Pilot then informed us that he would keep us until he passed the Bar Channel. We proceeded out the center of the channel at slow speed. At buoys #1 and #2, the ship increased its speed to approximately 12 kts and turned hard to port. We continued following at ¾ throttle at the stern of the vessel, starboard of the ship's propeller wash, with slack line. When the bow of the ship was approximately abeam of "D" Tower, the ship turned hard to starboard and increased speed without warning. The increased speed and propeller wash required me to release our winch brake to maintain a slack line to the ship. Approximately one minute later, the ship turned hard to port, steadied up, and slowed down as we passed "D" tower. I observed floating fender pile debris and oil in the water. We proceeded, slack line, to Anchorage No. 7. The Pilot then told us "REVOLUTION, you're released, I guess I forgot about you in all of the excitement." We returned to the dock and went to be drug tested. We haven't yet received the results of the test.

45. Witness (Name, Address, Telephone No.)

Angel Jimenez 201 Burma Road, Oakland, CA 94607

46. Witness (Name, Address, Telephone No.)

SECTION V. PERSON MAKING THIS REPORT

47. Name (PRINT) (Last, First, Middle) Alfers, Doug Wood		47b. Address (City, State, Zip Code) [REDACTED]		47c. Title Master	
47a. Signature [REDACTED]		[REDACTED]		47d. Telephone No. [REDACTED]	
47e. Date 11/8/2007					

FOR COAST GUARD USE ONLY

REPORTING OFFICE:

MISLE Incident Investigation Activity Data Entry:

MISLE Incident Investigation Activity Number (if applicable)

 NONE PRELIMINARY DATA COLLECTION INFORMAL FORMAL
Serious Marine Incident Yes No

INVESTIGATOR (Name)

DATE

APPROVED BY (Name)

DATE

Major Marine Casualty Yes No

EXHIBIT 3

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

PILOT'S REPORT

WHILE INCLUDED IN THE REPORT,
THESE DOCUMENTS HAVE BEEN
REMOVED FROM THIS VOLUME AS
THEY ARE NOT PART OF THE PUBLIC
RECORD. (7 C.C.R. § 210(c)(11))

EXHIBIT 4

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

0824
0830

MAKE RUDDER TO STB.
VESSEL CLOSE THE SAN FRANCISCO - OAKLAND BAY BRIDGE
PORTSIDE TOUCH THE BRIDGE. CENTER BILLOADS.
37°48.0'N 122°25.0'W.

0832

VESSEL MAKE HARD TO STB. CREW REPORT LEAKAGE LOCATE
NEAR PORT SIDE OF THE VESSEL HULL. PILOT REPORT TO U.S.C.G.

0847

VSL GOING TO ANCHORAGE AREA ACCORDING TO PILOT ORDER
FOR INSPECTION.

0855

PROP STB ANCHOR 5 SHACKLE IN WATER
37°49.618'N 122°23.599'W

0858

LET GO AFT TUG

0900

ANOTHER PILOT COME ON BOARD. REPORT C/E TRY TO

0905

THE THIRD PILOT. TRANSFER OIL FROM PORT TANK
~~COST GUARD~~ COME ON BOARD TO STB TANK

0915

TRANSFERRING OIL TO STB'S TANK

0925

VSL POSITION. 37°49.66'N 122°23.26'W

0930

C/E TELL DECK CREW SOUNDING BALLAST TANK NO. 4

0935

USCG BOAT COME AND MAKE PHOTO FOR THE HULL

0945

TWO PILOTS DISEMBARK. ONE REMAIN ON BOARD

0955

COST GUARD COME ON BOARD & START INSPECTION

1002

START HEAVING UP ANCHOR S.B. BOTH \uparrow

1006

ANCHOR AWAY. START USE DOWN THRUSTER & ENGINES

1030

VSL CLOSE SAN-FRANCISCO - OAKLAND BAY BRIDGE
POSIV: 37°48.3'N 122°23.5'W

1038

PASSING SAN-OAK BAY BRIDGE 37°47.5'N

1040

VSL GOING TO ANOTHER ANCHORAGE. 122°22.9'W

1045

OIL LEAKING COMING DOWN.

1100

TWO COST GUARD COME TO BRIDGE

1104

TWO C.G. LEAVE FROM BRIDGE

Encl: (4B)

1200

THREE C.G. OFFICER STAY ON BRIDGE FOR INSPECTION

1105 DROP PORT ANCHOR 6 SHACKLE IN WATER.

POS N: $37^{\circ}46.2'N$ $122^{\circ}21.5'W$.

1110 CAPT TELL CREW CHECK F&A DRIFT. SOUNDING
TANK AGAIN.

1112 ANCHOR HOLD. 3 CONST GUARD. COME TO BRIDGE

1124 F.W.E.

Manoeuvring Order Book

Arrival
 Departure **OAKLAND** Date: **7-Nov-07** Voyage No: **0130V**

Its
 Tides (Longitude) at Steering purposes: Clocks at Its

Stand by
 ELP **0630** Its CCW: EWE Its

Time	Movements and Events
0605	On H. W. to E/R.
0610	B/C LAPPED OUT. TUGS OK.
0620	P. O. B. TEST ENGINE FRONT SWS.
0630	S. H. E.
0648	AFT. TUG FAST. + RE-VALUATION
0714	AFT SINGLE UP
0725	FWD SINGLE UP
0748	A. E. CAST OFF. S. B. WITH COURSE
0800	CHIFFINER TO AFT CENTRE
0830	USE TUGS. BRIDGE 1-3-2-9. ¹⁷⁵⁰ ₀₈₃₀
0847	VAL WING TO THE WIRAGE AREA
	37° 49' 12" 23.5 W
0855	FRONT TUG ANCHOR 5 SWATH
	IN WATER
	37° 49' 12" 23.599 W
0958	GET ON AFT TUG
0900	ANCHOR PICOT COME ON BOARD
0905	COAST GUARD COME ON BOARD
	TO NEXT
Master/Chief Engineer:	Officer on watch:

Encl: (4c)

210 260 220 270 16:26 45 230 PT 0 STB 240 45
 250 300 260 310 16:28 45 270 PT 0 STB 280 45
 300 350 310 0 16:29 45 320 PT 0 STB 330 45

DATE 07.11.07 LAT 37:48.83N LON 122:23.05W ST.M:M DIFF.AL:05 N.VAR:00.0E SPD:26
 G1:340.0 G2:339.0 MAG:----- SRC:G1 COR:DOO.0 TIME 16:40
 PLATH

RUDDER ANGLE [°] HEADING [°]

300 350 310 0 16:40 45 320 PT 0 STB 330 45
 330 20 340 30 16:52 45 350 PT 0 STB 0 45
 300 350 310 0 16:57 45 320 PT 0 STB 330 45

320 280 330 17:20 45 290 PT 0 STB 300 45

Encl: 4F

PILOT CARD

for the port of

OAKLAND

DATE: 7-Nov-07



Draught Aft: 12,23 m =40 ft 01 inch Draught Fwd: 12,12 m =39 ft 09 inch

Ship's name **MV "COSCO BUSAN"** Displacement(max): 92,149.9 t

Call sign **VRDI 6** Deadweight (S & W) 68086.5 tonnes (max) Year built 2001

SHIP'S PARTICULARS

Length overall: 274,67 m Anchor chain: Port 13,5 shackles (1 shackle = 27,5 m)
 Breadth : 40,00 m Starboard 13 shackles (1 shackle = 15 fms)
 Bulbous bow Yes Stern - shackles



STEERING PARTICULARS

Type of rudder: SEMI BALANCED Maximum angle 35 ° P&S Hard-over to hard-over 28 s
 Rudder angle for neutral effect ___ ° port/starboard
 Thruster : BOW 2000 kW (2700 Hp) Stern ___ kW (___ Hp)

Type of engine: B & W 10K98 Maximum power 57000 kW (77600Hp)
 Type of propeller FIXED BLADES; RIGHT HANDED

Manoeuvring engine order	Rpm/pitch	Speed (knots)	
		Loaded	Ballast
Full ahead	65	17	18
Half ahead	50	13	14
Slow ahead	35	9	10
Dead slow ahead	24	6	7
Dead slow astern	24	Time limit astern <u>10.2 min</u>	
Slow astern	35	Full ahead to full astern <u>16.25 min</u>	
Half astern	50	Max. no of consecutive starts <u>9</u>	
Full astern	65	Minimum RPM = <u>24 / 6</u> knots	
		Astern power = ___ ahead	

CHECKED IF ABOARD AND READY

- Anchors.....2.....
- Wistle.....2.....
- Radar 3cm 10cm
- ARPA.....
- Speed log..
- Water speed.....
- Ground speed...
- Dual-axis.....
- Engine telegraphs.....
- Steering gear.....
- Number of power units operating .4...
- Indicators: Rudder.....
- Ppm/pitch...
- Rate of turn.
- Compass system.....
- Constant gyro error+/- 0 °
- VHF
- Electronic position fixing system
- Type: DGPS

OTHER INFORMATION: CRT: 65131 NRT: 34078

PILOT SIGNATURE rec'd only

T. 124 - P. EVOLUTION

Encl: (4I)

EXHIBIT 5

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

RPM
 (WIND)

NAV: Full	104	27.3
FULL	65	16.9
Half	50	13.0
Slow	35	9.1
DEAD slow	24	6.2

07 NOV 07 08.06:13
 EVENT LOG :

 END OF PERIODIC LOG

 0 RPM
 Dead band check :
 STB. BR. WING CONTR.
 Control location :
 Reply.: STAND BY
 Order.: STAND BY
 Sub telegraph pos :
 Reply.: STOP
 Order.: STOP
 Telegraph pos :

 07 NOV 07 08.00:00
 PERIODIC LOG :

>STB. BR. WING CONTR.
 Control Loc.: 07.46:14
 >D:STOP 9 RPM
 BRIDGE CONTRL 06.49:10
 >D:D.SLOW AHEAD 0 RPM
 BRIDGE CONTRL 06.49:00
 >D:STOP 12 RPM
 BRIDGE CONTRL 06.47:42
 >D:D.SLOW AHEAD 0 RPM
 BRIDGE CONTRL 06.47:34
 >BRIDGE CONTROL
 Control Loc.: 06.46:24
 >D:STOP 0 RPM
 CTRL.R CONTRL 06.44:32
 >R:STOP 0 RPM
 CTRL.R CONTRL 06.44:30
 >D:D.SLOW AHEAD 0 RPM
 CTRL.R CONTRL 06.42:46
 >R:D.SLOW AHEAD 0 RPM
 CTRL.R CONTRL 06.42:42
 >CONTROL ROOM CONTROL
 Control Loc.: 06.42:36
 >BRIDGE CONTROL
 Control Loc.: 06.42:32
 >CONTROL ROOM CONTROL
 Control Loc.: 06.42:02
 >BRIDGE CONTROL
 Control Loc.: 06.41:58
 >D:STAND BY 0 RPM
 CTRL.R CONTRL 06.28:59
 >R:STAND BY 0 RPM
 CTRL.R CONTRL 06.28:37
 >N SLOW DOWN 06.12:38
 >N SHUT DOWN 06.12:38

 07 NOV 07 06.12:39
 EVENT LOG :

 END OF PERIODIC LOG

 SLOW DOWN

BRIDGE CONTRL 10.16:06
 0 RPM
 BRIDGE CONTRL 08.54:03
 >D:STOP 10 RPM
 BRIDGE CONTRL 08.53:54
 23 RPM
 BRIDGE CONTRL 08.52:42
 31 RPM
 BRIDGE CONTRL 08.52:33
 >D:D.SLOW AHEAD 0 RPM
 BRIDGE CONTRL 08.52:00
 >BRIDGE CONTRL 08.51:24
 24 RPM
 BRIDGE CONTRL 08.51:17
 >D:D.SLOW ASTERN- 60 RPM
 BRIDGE CONTRL 08.50:48
 58 RPM
 BRIDGE CONTRL 08.49:28
 >D:FULL ASTERN- 51 RPM
 BRIDGE CONTRL 08.49:16
 49 RPM
 BRIDGE CONTRL 08.48:15
 >D:HALF ASTERN- 36 RPM
 BRIDGE CONTRL 08.48:04
 33 RPM
 BRIDGE CONTRL 08.47:51
 >D:SLOW ASTERN- 26 RPM
 BRIDGE CONTRL 08.47:38
 >D:D.SLOW ASTERN 0 RPM
 BRIDGE CONTRL 08.47:20
 0 RPM
 BRIDGE CONTRL 08.46:12
 10 RPM
 BRIDGE CONTRL 08.45:46
 >D:STOP 18 RPM
 BRIDGE CONTRL 08.45:38
 25 RPM
 BRIDGE CONTRL 08.45:21
 >D:D.SLOW AHEAD 35 RPM
 BRIDGE CONTRL 08.45:08
 37 RPM
 BRIDGE CONTRL 08.36:40
 39 RPM
 BRIDGE CONTRL 08.36:29
 >D:SLOW AHEAD 21 RPM
 BRIDGE CONTRL 08.36:18
 >D:D.SLOW AHEAD 0 RPM
 BRIDGE CONTRL 08.36:14
 0 RPM
 BRIDGE CONTRL 08.34:36
 10 RPM
 BRIDGE CONTRL 08.34:19
 >D:STOP 18 RPM
 BRIDGE CONTRL 08.34:08
 26 RPM
 BRIDGE CONTRL 08.30:51
 >D:D.SLOW AHEAD 64 RPM
 BRIDGE CONTRL 08.30:24
 66 RPM
 BRIDGE CONTRL 08.27:56
 59 RPM
 BRIDGE CONTRL 08.27:16
 >D:FULL AHEAD 51 RPM
 BRIDGE CONTRL 08.27:06
 >A SLD CANCELED 08.20:56
 49 RPM
 BRIDGE CONTRL 08.20:25
 >D:HALF AHEAD 35 RPM
 BRIDGE CONTRL 08.20:12
 33 RPM
 BRIDGE CONTRL 08.09:02
 >D:SLOW AHEAD 29 RPM
 BRIDGE CONTRL 08.08:56
 22 RPM
 BRIDGE CONTRL 08.08:25

Encl: (5C)

04-11-07	12:26:01.920	MS045	ELEVATOR ABNORMAL	XA			ALARM	ALARM
04-11-07	12:26:05.479	MS045	ELEVATOR ABNORMAL	XA			ALARM	RETURN
04-11-07	12:52:03.049	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
04-11-07	13:27:22.125	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
11-07	13:50:00.919	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07	13:52:09.986	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07	14:08:58.970	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
04-11-07	14:10:41.321	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
04-11-07	14:28:41.451	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
04-11-07	14:30:02.029	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
04-11-07	14:55:24.137	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
04-11-07	15:21:01.308	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
04-11-07	15:37:01.095	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
04-11-07	15:41:28.002	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
04-11-07	21:19:49.513	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
04-11-07	21:21:14.336	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
04-11-07	22:12:56.8183	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
05-11-07	00:59:47.542	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
05-11-07	03:41:31.270	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	ALARM
05-11-07	03:42:41.067	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	RETURN
05-11-07	09:17:31.461	MC014	M/E NO.2 OIL MIST DETECTOR FAIL	XA			ALARM	ALARM
05-11-07	09:20:26.716	MC012	M/E NO.1 OIL MIST DETECTOR FAIL	XA			ALARM	ALARM
05-11-07	09:29:50.939	MA027	M/E NO.9 CYL EXH. GAS OUT TEMP	TIAHH	99.8	DEG.C	OFFSC	ALARM
05-11-07	10:21:04.706	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
05-11-07	11:16:03.976	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
05-11-07	17:04:44.324	MS045	ELEVATOR ABNORMAL	XA			ALARM	ALARM

LIET for HANJIN CAIRO

KONGSBERG NDCCONTROL AS

DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
05-11-07	17:04:46.034	MS045	ELEVATOR ABNORMAL	XA			ALARM	RETURN
05-11-07	21:06:49.171	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
05-11-07	21:09:04.846	GD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
05-11-07	22:55:01.370	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	ALARM
05-11-07	22:55:03.059	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	RETURN
05-11-07	22:55:11.476	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	ALARM
05-11-07	23:37:01.704	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	RETURN
06-11-07	02:40:32.269	GD043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
06-11-07	02:57:19.624	GD043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
06-11-07	04:30:42.656	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	ALARM
06-11-07	04:32:31.382	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	RETURN
06-11-07	06:21:10.387	ML055	M/E NO.1 L.O FILTER DIFF PRESS	DPIAH	0.83	KG/CM2	HIGH	ALARM
06-11-07	06:21:12.000	SD003	M/E MAIN L.O PRESS LOW	SHD			SHD-AL	RETURN
06-11-07	06:21:11.766	ML056	M/E NO.2 L.O FILTER DIFF PRESS	DPIAH	0.86	KG/CM2	HIGH	ALARM
06-11-07	06:21:12.925	ML055	M/E NO.1 L.O FILTER DIFF PRESS	DPIAH	0.80	KG/CM2	HIGH	RETURN
06-11-07	06:21:13.025	ML056	M/E NO.2 L.O FILTER DIFF PRESS	DPIAH	0.80	KG/CM2	HIGH	RETURN
06-11-07	06:21:17.961	ML003	M/E PISTON C.L.D IN PRESS	PIAL	1.60	KG/CM2	LOW	RETURN
06-11-07	06:21:21.000	SD005	M/E T/C L.O PRESS LOW	SHD			SHD-AL	RETURN
06-11-07	06:21:21.000	SL008	M/E T/C L.O INLET PRESS LOW	SLD			SLD-AL	RETURN
06-11-07	06:21:22.000	SL001	M/E SLOW DOWN	SLD			ALARM	RETURN
06-11-07	06:21:23.000	SD004	M/E CAMSHAFT L.O PRESS LOW	SHD			SHD-AL	RETURN
06-11-07	06:21:23.000	SD001	M/E SHUT DOWN	SHD			ALARM	RETURN
06-11-07	06:21:23.057	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
06-11-07	06:21:28.676	ML081	M/E NO.1 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
06-11-07	06:21:42.604	ML083	M/E NO.3 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
06-11-07	06:21:44.053	ML082	M/E NO.2 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
06-11-07	06:21:55.357	ML083	M/E NO.3 T/C L.O INLET PRESS	PIAL	1.17	KG/CM2	LOW	ALARM
06-11-07	06:22:02.522	ML082	M/E NO.2 T/C L.O INLET PRESS	PIAL	1.18	KG/CM2	LOW	ALARM

Evidence: 3095030
052-JD-A

Encl: (50)

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
06-11-07	19:28:54.000	MC037	M/E NOT READY	XA			ALARM	RETURN
06-11-07	19:28:47.654	MC019	M/E SAFETY AIR P.L	PAL			ALARM	ALARM
06-11-07	19:28:47.654	MC017	M/E CONTROL AIR PRESS	PIAL	-0.03	KG/CM2	LOW	ALARM
06-11-07	19:28:50.003	MC019	M/E SAFETY AIR P.L	PAL			ALARM	RETURN
06-11-07	19:27:02.871	MC018	M/E EXH. V/V SPRING AIR PRESS	PIAL	4.80	KG/CM2	LOW	ALARM
06-11-07	19:27:06.000	MC036	M/E CONTROL POSITION MISSING	XA			ALARM	RETURN
06-11-07	19:27:06.000	MC004	M/E REMOTE CONTROL SYS ABNORMAL	XA			ALARM	RETURN
06-11-07	19:27:30.563	MC018	M/E EXH. V/V SPRING AIR PRESS	PIAL	5.50	KG/CM2	LOW	RETURN
06-11-07	19:27:37.268	MC017	M/E CONTROL AIR PRESS	PIAL	5.50	KG/CM2	LOW	RETURN
06-11-07	19:37:30.537	MC017	M/E CONTROL AIR PRESS	PIAL	5.33	KG/CM2	LOW	ALARM
06-11-07	19:37:41.722	MC017	M/E CONTROL AIR PRESS	PIAL	5.50	KG/CM2	LOW	RETURN
06-11-07	19:40:46.038	MC012	M/E NO.1 OIL MIST DETECTOR FAIL	XA			ALARM	RETURN
06-11-07	19:40:59.513	MC014	M/E NO.2 OIL MIST DETECTOR FAIL	XA			ALARM	RETURN
06-11-07	19:47:56.677	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
06-11-07	20:11:37.723	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
06-11-07	20:26:11.000	MC033	M/E SLOW DOWN CANCELLED	XA			ALARM	ALARM
06-11-07	20:26:10.715	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
06-11-07	20:56:39.740	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
06-11-07	20:59:36.196	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
06-11-07	21:03:26.027	MS045	ELEVATOR ABNORMAL	XA			ALARM	ALARM
06-11-07	21:03:29.426	MS045	ELEVATOR ABNORMAL	XA			ALARM	RETURN
06-11-07	21:29:32.156	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
06-11-07	21:32:08.839	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-56.5	DEG.C	LOW	ALARM
06-11-07	21:32:08.839	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	67.5	DEG.C	HIGH	ALARM
06-11-07	21:32:24.864	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.3	DEG.C	HIGH	ALARM
06-11-07	21:33:09.311	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN

LIST for HANJIN CAIRO KONGSBERG NORCONTROL AS DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
06-11-07	21:33:29.583	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
06-11-07	21:34:05.423	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
06-11-07	21:36:34.614	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
06-11-07	21:09:27.626	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
06-11-07	22:07:28.525	BC043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
06-11-07	22:14:59.490	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	ALARM
06-11-07	22:51:43.843	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	ALARM
06-11-07	22:51:47.322	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	RETURN
06-11-07	22:52:40.897	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	ALARM
06-11-07	22:52:45.824	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	RETURN
06-11-07	23:12:47.996	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	ALARM
06-11-07	23:12:52.284	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	RETURN
06-11-07	23:17:20.888	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	ALARM
06-11-07	23:14:53.694	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	RETURN
06-11-07	23:51:03.129	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	ALARM
06-11-07	23:32:12.956	NF042	NO.3 HFD PURIFIER ABNORMAL	XA			ALARM	RETURN
07-11-07	00:29:00.054	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.6	DEG.C	HIGH	ALARM
07-11-07	00:29:23.150	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.8	DEG.C	LOW	ALARM
07-11-07	00:29:51.320	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.5	DEG.C	LOW	ALARM
07-11-07	00:30:22.159	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.2	DEG.C	LOW	ALARM
07-11-07	00:31:17.984	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
07-11-07	00:31:30.790	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
07-11-07	00:32:05.297	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
07-11-07	00:32:41.646	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
07-11-07	01:54:54.795	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	RETURN
07-11-07	02:07:11.247	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	ALARM
07-11-07	02:07:19.072	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	RETURN
07-11-07	02:22:02.092	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	ALARM

Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
11-07 12:26:01.920	MS045	ELEVATOR ABNORMAL	XA			ALARM	ALARM
11-07 12:26:05.979	MS045	ELEVATOR ABNORMAL	XA			ALARM	RETURN
11-07 12:52:03.049	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
11-07 13:27:22.125	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
11-07 13:50:00.919	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07 13:52:09.988	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07 14:09:58.840	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07 14:10:41.321	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07 14:28:41.451	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07 14:30:02.029	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07 14:55:24.137	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
11-07 15:21:01.408	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
11-07 15:37:01.895	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
11-07 15:41:28.002	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
11-07 21:19:48.583	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07 21:21:14.338	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07 22:12:58.883	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
11-07 00:59:47.542	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
11-07 03:41:31.970	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	ALARM
11-07 03:42:41.067	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	RETURN
11-07 09:17:31.461	MC014	M/E NO.2 OIL MIST DETECTOR FAIL	XA			ALARM	ALARM
11-07 09:20:36.718	MC012	M/E NO.1 OIL MIST DETECTOR FAIL	XA			ALARM	ALARM
11-07 09:29:50.939	NA027	M/E NO.9 CYL EXH. GAS OUT TEMP	TIAHH	99.8	DEG.C	OFFSC	ALARM
11-07 10:21:04.706	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
11-07 11:16:03.976	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
11-07 17:04:44.324	MS045	ELEVATOR ABNORMAL	XA			ALARM	ALARM

for HANJIN CAIRO KONGSBERG NORCONTROL AS DC C20

Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
11-07 17:04:46.054	MS045	ELEVATOR ABNORMAL	XA			ALARM	RETURN
11-07 21:06:49.171	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07 21:09:04.846	SD043	NO.4 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07 22:55:01.390	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	ALARM
11-07 22:55:03.059	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	RETURN
11-07 22:55:11.436	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	ALARM
11-07 23:37:01.704	ML500	ALPHA LUBR., COMMON ALARM	XA			ALARM	RETURN
11-07 02:40:32.269	SD043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	ALARM
11-07 02:57:19.624	SD043	NO.3 G/E L.O SUMP TK L.L	LAL			ALARM	RETURN
11-07 04:30:42.086	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	ALARM
11-07 04:32:31.382	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA			ALARM	RETURN
11-07 06:21:10.387	ML055	M/E NO.1 L.O FILTER DIFF PRESS	DPIAH	0.83	KG/CM2	HIGH	ALARM
11-07 06:21:12.000	SD003	M/E MAIN L.O PRESS LOW	SHD			SHD-AL	RETURN
11-07 06:21:11.736	ML056	M/E NO.2 L.O FILTER DIFF PRESS	DPIAH	0.86	KG/CM2	HIGH	ALARM
11-07 06:21:12.915	ML055	M/E NO.1 L.O FILTER DIFF PRESS	DPIAH	0.80	KG/CM2	HIGH	RETURN
11-07 06:21:13.025	ML056	M/E NO.2 L.O FILTER DIFF PRESS	DPIAH	0.80	KG/CM2	HIGH	RETURN
11-07 06:21:17.961	ML003	M/E PISTON C.L.O IN PRESS	PIAL	1.60	KG/CM2	LOW	RETURN
11-07 06:21:21.000	SD005	M/E T/C L.O PRESS LOW	SHD			SHD-AL	RETURN
11-07 06:21:21.006	SL008	M/E T/C L.O INLET PRESS LOW	SLD			SLD-AL	RETURN
11-07 06:21:22.000	SL001	M/E SLOW DOWN	SLD			ALARM	RETURN
11-07 06:21:23.000	SD004	M/E CAMSHAFT L.O PRESS LOW	SHD			SHD-AL	RETURN
11-07 06:21:23.000	SD001	M/E SHUT DOWN	SHD			ALARM	RETURN
11-07 06:21:23.057	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
11-07 06:21:28.676	ML081	M/E NO.1 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
11-07 06:21:42.804	ML083	M/E NO.3 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
11-07 06:21:44.033	ML082	M/E NO.2 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
11-07 06:21:55.357	ML083	M/E NO.3 T/C L.O INLET PRESS	PIAL	1.17	KG/CM2	LOW	ALARM
11-07 06:22:02.522	ML082	M/E NO.2 T/C L.O INLET PRESS	PIAL	1.18	KG/CM2	LOW	ALARM

Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
7-11-07 05:01:46.830	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.61	M	OFFSC	RETURN
7-11-07 05:01:48.847	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.91	M	HIGH	ALARM
7-11-07 05:07:13.592	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	YA			ALARM	ALARM
7-11-07 05:21:14.823	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	YA			ALARM	RETURN
7-11-07 05:41:17.358	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 05:41:18.538	GD043	NO.3 G/E L.O SWMP TK L.L	LAL			ALARM	ALARM
7-11-07 05:41:23.925	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.66	M	HIGH	ALARM
7-11-07 05:41:55.383	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 05:41:57.557	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	ALARM
7-11-07 05:41:57.901	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
7-11-07 05:42:15.033	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 05:42:19.960	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.66	M	HIGH	ALARM
7-11-07 05:42:25.716	GD043	NO.4 G/E L.O SWMP TK L.L	LAL			ALARM	ALARM
7-11-07 05:42:39.510	GD043	NO.4 G/E L.O SWMP TK L.L	LAL			ALARM	RETURN
7-11-07 05:43:26.999	GD043	NO.3 G/E L.O SWMP TK L.L	LAL			ALARM	RETURN
7-11-07 05:47:07.302	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	RETURN
7-11-07 07:04:34.609	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:04:36.837	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
7-11-07 07:06:11.446	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:06:14.684	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
7-11-07 07:07:51.660	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:07:55.420	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
7-11-07 07:07:29.413	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:09:31.502	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
7-11-07 07:09:37.909	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:09:40.387	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM

RT for HANJIN CAIRO KONGSBERG NORCONTROL AS DC C20

Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
7-11-07 07:10:25.645	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:10:28.104	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
7-11-07 07:10:57.094	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:11:00.881	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
7-11-07 07:11:05.198	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:11:07.597	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
7-11-07 07:11:30.726	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:11:33.654	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
7-11-07 07:11:59.273	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:12:01.812	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM
7-11-07 07:12:17.665	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:12:22.192	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.66	M	HIGH	ALARM
7-11-07 07:12:34.636	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:12:39.013	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
7-11-07 07:12:53.670	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:12:57.897	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
7-11-07 07:13:54.384	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:13:59.411	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.66	M	HIGH	ALARM
7-11-07 07:14:11.334	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:14:16.141	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
7-11-07 07:14:29.064	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:14:34.281	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.66	M	HIGH	ALARM
7-11-07 07:14:38.139	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:14:40.727	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
7-11-07 07:15:26.646	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:15:31.544	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.61	M	HIGH	ALARM
7-11-07 07:15:42.149	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
7-11-07 07:15:44.571	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
7-11-07 07:16:00.987	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN

07-11-07	07:17:26.960	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:17:31.528	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
07-11-07	07:17:36.425	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:17:38.704	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.61	M	HIGH	ALARM
07-11-07	07:17:42.922	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:17:49.093	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
07-11-07	07:18:44.447	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:18:48.395	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:19:53.223	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:19:57.140	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
07-11-07	07:19:00.199	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:19:04.916	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:19:08.504	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:19:12.492	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM
07-11-07	07:19:20.976	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:19:27.632	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM
07-11-07	07:19:42.145	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:19:46.625	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
07-11-07	07:20:13.221	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:20:17.418	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.61	M	HIGH	ALARM
07-11-07	07:20:17.548	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:20:22.165	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:20:27.053	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:20:36.518	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:20:46.218	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:20:51.715	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM

IST for HANJIN CAIRO

KONIGSBERG NORCONTROL AS

DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
07-11-07	07:21:03.378	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:21:09.514	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:21:18.830	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:21:24.936	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:21:38.090	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:21:43.799	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:21:53.095	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:21:56.073	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:22:08.036	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:22:13.122	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:22:15.451	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:22:18.179	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
07-11-07	07:22:22.327	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:22:27.804	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
07-11-07	07:22:36.658	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:22:40.737	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:22:45.108	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:22:47.436	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:22:52.324	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:22:57.900	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.61	M	HIGH	ALARM
07-11-07	07:23:07.046	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:23:15.261	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM
07-11-07	07:23:23.126	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:23:33.810	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM
07-11-07	07:23:39.837	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:23:44.240	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:23:48.158	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
07-11-07	07:23:50.956	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
07-11-07	07:23:50.810	MF007	HFD OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN

17-11-07	07:24:55.294	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:24:59.721	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.61	M	HIGH	ALARM
17-11-07	07:25:00.041	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:25:06.177	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.67	M	HIGH	ALARM
17-11-07	07:25:09.735	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:25:20.379	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
17-11-07	07:25:26.456	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:25:36.760	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
17-11-07	07:25:41.538	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:25:46.409	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM
17-11-07	07:25:47.858	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:25:54.274	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.65	M	HIGH	ALARM
17-11-07	07:26:00.001	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:26:08.467	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
17-11-07	07:26:11.125	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:26:13.774	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
17-11-07	07:26:18.591	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:26:26.446	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
17-11-07	07:26:35.182	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:26:45.251	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
17-11-07	07:26:52.817	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:27:04.550	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.64	M	HIGH	ALARM
17-11-07	07:27:13.046	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:27:21.412	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
17-11-07	07:27:31.927	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:27:39.892	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.62	M	HIGH	ALARM

LIST for HANJIN CAIRO KONGSBERG NORCONTROL AS DE C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
17-11-07	07:27:45.041	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:27:49.639	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
17-11-07	07:27:52.467	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.60	M	HIGH	RETURN
17-11-07	07:27:58.093	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.63	M	HIGH	ALARM
17-11-07	07:28:03.091	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.62	M	OFFSC	ALARM
17-11-07	08:43:17.704	MF007	HFO OVERFLOW TK LEVEL	LIAH	1.61	M	OFFSC	RETURN
17-11-07	08:56:47.730	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	ALARM
17-11-07	09:01:29.168	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	RETURN
17-11-07	09:31:11.306	MA024	N/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-11.5	DEG.C	LO-LO	ALARM
17-11-07	09:31:14.000	SL015	N/E CYL EXH GAS OUTLET TEMP HIGH	SLD			SLD-AL	ALARM
17-11-07	09:32:02.075	MA024	N/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	1.1	DEG.C	LO-LO	RETURN
17-11-07	09:32:03.000	SL015	N/E CYL EXH GAS OUTLET TEMP HIGH	SLD	-14.7	DEG.C	SLD-AL	RETURN
17-11-07	09:32:08.000	SL015	N/E CYL EXH GAS OUTLET TEMP HIGH	SLD	4.00		OFFSC	ALARM
17-11-07	09:32:19.741	MA024	N/E NO.6 CYL EXH					

17-11-07	09:32:44.620	MA024	N/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-15.9	DEG.C	OFFSC	ALARM
17-11-07	10:49:53.445	MC006	N/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
17-11-07	10:50:00.303	MC006	N/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM

7-11-07	10:56:47.076	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	10:56:51.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	2.00		BROKEN	ALARM
7-11-07	10:56:51.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	4.00		BROKEN	RETURN
7-11-07	10:57:01.333	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	10:57:03.000	MC032	M/E SHUT DOWN CANCELLED	XA			ALARM	ALARM
7-11-07	10:57:08.074	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	10:57:36.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	2.00		BROKEN	ALARM
7-11-07	10:57:38.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	4.00		BROKEN	RETURN
7-11-07	10:58:33.151	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	10:59:00.159	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	10:59:31.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	2.00		BROKEN	ALARM
7-11-07	10:59:33.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	4.00		BROKEN	RETURN
7-11-07	11:00:40.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	2.00		BROKEN	ALARM
7-11-07	11:00:42.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	4.00		BROKEN	RETURN
7-11-07	11:01:23.000	SD006	M/E J.C.F.W INLET PRESS LOW	SHD	4.00		OFFSC	ALARM
7-11-07	11:01:50.280	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	11:01:57.138	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	11:02:00.497	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	11:02:07.459	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	11:04:36.103	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	11:04:43.021	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	11:11:21.255	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	ALARM
7-11-07	11:13:21.739	AB010	BOILER FEED FILTER TK L.H	LAH			ALARM	RETURN
7-11-07	11:42:07.733	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	11:42:14.552	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	11:54:58.938	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-16.5	DEG.C	OFFSC	RETURN
7-11-07	11:55:13.853	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-11.4	DEG.C	LD-LO	ALARM
7-11-07	11:55:17.391	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	50.1	DEG.C	HIGH	ALARM
7-11-07	11:55:19.390	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
7-11-07	11:55:36.344	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-11.4	DEG.C	OFFSC	ALARM
7-11-07	11:56:26.029	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	11:56:32.887	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	11:59:34.836	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	11:59:41.503	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	12:00:24.334	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	12:00:31.221	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	12:03:51.272	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	12:03:58.160	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM

ARM LIST for HANJIN CAIRO

KONGSBERG NORCONTROL AS

DC C20

ate	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
7-11-07	12:11:45.208	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	12:11:52.076	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	12:14:05.746	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
7-11-07	12:14:12.594	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
7-11-07	13:28:34.750	GC043	NO.3 S/E L.D SUMP TK L.L	LAL			ALARM	ALARM
7-11-07	13:28:05.252	GC043	NO.3 S/E L.D SUMP TK L.L	LAL			ALARM	RETURN
7-11-07	14:26:54.918	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	50.7	DEG.C	HIGH	ALARM
7-11-07	14:27:17.958	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	55.0	DEG.C	HIGH	RETURN
7-11-07	14:36:30.560	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-11.3	DEG.C	OFFSC	RETURN
7-11-07	14:37:40.965	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-10.4	DEG.C	LD-LO	ALARM
7-11-07	14:39:49.588	SB002	NO.2 S/G MOTOR NO-VOLTAGE	XA			ALARM	ALARM
7-11-07	14:39:57.755	SB002	NO.2 S/G MOTOR NO-VOLTAGE	XA			ALARM	RETURN
7-11-07	14:40:09.240	SB001	NO.1 S/G MOTOR NO-VOLTAGE	XA			ALARM	ALARM
7-11-07	14:40:10.830	SB007	NO.1 S/G CONTROL POWER FAIL	XA			ALARM	ALARM
7-11-07	14:40:17.218	SB001	NO.1 S/G MOTOR NO-VOLTAGE	XA			ALARM	RETURN
7-11-07	14:43:15.097	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	88.2	DEG.C	HIGH	ALARM
7-11-07	14:43:16.097	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	59.2	DEG.C	HIGH	ALARM

07-11-07	14:47:04.742	NA030	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
07-11-07	14:49:32.067	NA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
07-11-07	14:49:42.133	NA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	50.8	DEG.C	HIGH	ALARM
07-11-07	14:50:40.380	SG002	NO.2 S/G MOTOR NO-VOLTAGE	XA			ALARM	ALARM
07-11-07	14:50:45.747	SG007	NO.1 S/G CONTROL POWER FAIL	XA			ALARM	RETURN
07-11-07	14:50:48.209	NA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
07-11-07	14:51:03.293	NA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.2	DEG.C	HIGH	ALARM
07-11-07	14:51:58.129	NA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
07-11-07	14:52:13.444	NA034	M/E NO.6 CYL EXH. GAS DEV. TEMP	TDIAHL	-217.2	DEG.C	LOW	RETURN
07-11-07	14:55:09.479	SG008	NO.2 S/G CONTROL POWER FAIL	XA			ALARM	ALARM
07-11-07	14:55:28.388	SG008	NO.2 S/G CONTROL POWER FAIL	XA			ALARM	RETURN
07-11-07	14:56:06.092	NA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	1.0	DEG.C	LO-LO	RETURN
07-11-07	14:56:09.873	SG002	NO.2 S/G MOTOR NO-VOLTAGE	XA			ALARM	RETURN
07-11-07	14:56:22.098	NA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	23.2	DEG.C	OFFSC	ALARM
07-11-07	14:58:46.140	NA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	22.6	DEG.C	OFFSC	RETURN
07-11-07	15:05:35.328	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
07-11-07	15:06:04.458	GA019	NO.1 G/E H.T WATER INLET PRESS	PIAL	0.00	BAR	LOW	ALARM
07-11-07	15:06:04.468	GA021	NO.1 G/E L.T WATER INLET PRESS	PIAL	0.86	BAR	LOW	ALARM
07-11-07	15:06:09.566	GA022	NO.1 G/E L.T WATER INLET TEMP	TIAH	63.9	DEG.C	HIGH	ALARM
07-11-07	15:06:09.855	GA019	NO.1 G/E H.T WATER INLET PRESS	PIAL	2.18	BAR	LOW	RETURN
07-11-07	15:06:10.765	GA021	NO.1 G/E L.T WATER INLET PRESS	PIAL	3.47	BAR	LOW	RETURN
07-11-07	15:06:23.676	NA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-4.0	DEG.C	LO-LO	ALARM
07-11-07	15:06:25.757	GA022	NO.1 G/E L.T WATER INLET TEMP	TIAH	43.5	DEG.C	HIGH	RETURN
07-11-07	15:08:15.679	NA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-17.6	DEG.C	OFFSC	ALARM
07-11-07	15:09:04.987	AB001	BOILER TRIP	XA			ALARM	ALARM
07-11-07	15:10:16.166	AB001	BOILER TRIP	XA			ALARM	RETURN
07-11-07	15:10:21.228	AB002	BOILER DRUM STEAM PRESS	PIAHL	4.98	KG/CM2	LOW	ALARM
07-11-07	15:10:26.158	AB002	BOILER DRUM STEAM PRESS	PIAHL	5.00	KG/CM2	LOW	RETURN
07-11-07	15:10:38.893	AB002	BOILER DRUM STEAM PRESS	PIAHL	4.97	KG/CM2	LOW	ALARM
07-11-07	15:10:49.868	AB002	BOILER DRUM STEAM PRESS	PIAHL	5.00	KG/CM2	LOW	RETURN
07-11-07	15:10:54.197	AB002	BOILER DRUM STEAM PRESS	PIAHL	4.97	KG/CM2	LOW	ALARM
07-11-07	15:12:15.752	NA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	-17.5	DEG.C	OFFSC	RETURN
07-11-07	15:14:21.207	AB002	BOILER DRUM STEAM PRESS	PIAHL	5.00	KG/CM2	LOW	RETURN
07-11-07	15:17:43.000	MC033	M/E SLOW DOWN CANCELLED	XA			ALARM	RETURN
07-11-07	15:19:51.000	MC032	M/E SHUT DOWN CANCELLED	XA			ALARM	RETURN
07-11-07	15:19:50.702	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	RETURN
07-11-07	15:21:50.321	AB011	BOILER FEED FILTER TK L.L	LAL			ALARM	ALARM
07-11-07	15:22:20.715	AB005	BOILER ABNORMAL	XA			ALARM	RETURN

LARM LIST for HANJIN CAIRD

KONGSBERG NORCONTROL AS

DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Opnd.	State
07-11-07	15:23:43.514	AB001	BOILER TRIP	XA			ALARM	ALARM
07-11-07	15:24:07.227	AB001	BOILER TRIP	XA			ALARM	RETURN
07-11-07	15:24:11.708	AB011	BOILER FEED FILTER TK L.L	LAL			ALARM	RETURN
07-11-07	15:24:20.733	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
07-11-07	15:24:53.843	NA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	56.9	DEG.C	HIGH	ALARM
07-11-07	15:26:20.569	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	RETURN
07-11-07	15:26:50.905	NA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	51.9	DEG.C	HIGH	RETURN
07-11-07	15:27:30.258	MS025	TOPPING-UP AIR COMP. ABNORMAL	XA			ALARM	ALARM
07-11-07	15:29:51.134	NA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	68.2	DEG.C	HIGH	ALARM
07-11-07	15:29:59.040	NA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	52.6	DEG.C	HIGH	ALARM
07-11-07	15:29:59.760	NA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-54.0	DEG.C	LOW	ALARM
07-11-07	15:30:05.289	NA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-53.5	DEG.C	LOW	ALARM
07-11-07	15:30:08.028	NA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-52.1	DEG.C	LOW	ALARM
07-11-07	15:30:14.555	NA030	M/E NO.2 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.1	DEG.C	LOW	ALARM
07-11-07	15:30:47.281	NA030	M/E NO.2 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
07-11-07	15:31:30.573	NA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
07-11-07	15:31:34.495	NA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
07-11-07	19:51:23.180	ML003	N/E PISTON C.L.O IN PRESS	PIAL	0.44	KG/CM2	LOW	ALARM
07-11-07	19:51:24.000	SD004	N/E CAMSHAFT L.O PRESS LOW	SHD			SHD-AL	ALARM
07-11-07	19:51:24.869	ML081	N/E NO.1 T/C L.O INLET PRESS	PIAL	0.86	KG/CM2	LOW	ALARM
07-11-07	19:51:25.000	SL008	N/E T/C L.O INLET PRESS LOW	SLD			SLD-AL	ALARM
07-11-07	19:51:26.000	SD005	N/E T/C L.O PRESS LOW	SHD			SHD-AL	ALARM
07-11-07	19:51:27.846	ML083	N/E NO.3 T/C L.O INLET PRESS	PIAL	1.01	KG/CM2	LOW	ALARM
07-11-07	19:51:30.195	ML082	N/E NO.2 T/C L.O INLET PRESS	PIAL	1.06	KG/CM2	LOW	ALARM
07-11-07	19:51:30.000	SD001	N/E SHUT DOWN	SHD				ALARM ALARM
07-11-07	19:51:31.000	SL001	N/E SLOW DOWN	SLD				ALARM ALARM
07-11-07	19:51:36.005	MC006	N/E SAFETY SYS ABNORMAL	XA				ALARM ALARM
07-11-07	19:53:59.227	MC006	N/E SAFETY SYS ABNORMAL	XA				ALARM RETURN
07-11-07	19:54:00.000	SD003	N/E MAIN L.O PRESS LOW	SHD			SHD-AL	ALARM
07-11-07	19:54:06.105	MC006	N/E SAFETY SYS ABNORMAL	XA				ALARM ALARM
07-11-07	19:54:28.227	GC002	NO.3 G/E L.O LOW PRESS	SHD				ALARM ALARM
07-11-07	19:56:54.686	GC002	NO.3 G/E L.O LOW PRESS	SHD				ALARM RETURN
07-11-07	23:20:13.156	GD043	NO.4 G/E L.O SUMP TK L.L	LAL				ALARM ALARM
07-11-07	23:23:07.613	GD043	NO.3 G/E L.O SUMP TK L.L	LAL				ALARM ALARM
07-11-07	23:27:24.145	GD043	NO.4 G/E L.O SUMP TK L.L	LAL				ALARM RETURN
07-11-07	23:29:24.115	GD043	NO.3 G/E L.O SUMP TK L.L	LAL				ALARM RETURN
08-11-07	00:22:31.149	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:22:31.678	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:22:50.151	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:22:53.760	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:23:10.623	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:23:10.913	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:23:15.845	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:23:19.884	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:23:26.632	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:23:29.691	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:23:32.030	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.2	DEG.C	HIGH	ALARM
08-11-07	00:23:36.137	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:23:40.005	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:23:40.455	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:23:50.541	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:23:59.756	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:24:02.347	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.2	DEG.C	HIGH	ALARM
08-11-07	00:24:06.215	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN

ALARM LIST for HANJIN CAIRO

KONGSBERG NORCONTROL AS

DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
08-11-07	00:24:09.514	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.1	DEG.C	HIGH	ALARM
08-11-07	00:24:16.763	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.0	DEG.C	HIGH	RETURN
08-11-07	00:24:22.352	MF021	NO.3 HFD BUNKER TK(P) TEMP	TIAH	60.2	DEG.C	HIGH	ALARM
08-11-07	04:07:01.818	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.1	DEG.C	HIGH	ALARM
08-11-07	04:07:02.747	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN
08-11-07	04:07:08.275	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.1	DEG.C	HIGH	ALARM
08-11-07	04:07:23.129	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN
08-11-07	04:07:28.577	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.1	DEG.C	HIGH	ALARM
08-11-07	04:07:35.837	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN
08-11-07	04:07:41.375	MF023	NO.3 HFD BUNKER TK(S) TEMP	TIAH	62.2	DEG.C	HIGH	ALARM
08-11-07	06:09:04.734	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA				ALARM ALARM
08-11-07	06:11:35.443	ML075	NO.2 MAIN L.O PURIFIER ABNORMAL	XA				ALARM RETURN
08-11-07	07:10:42.895	ML500	ALPHA LUBR., COMMON ALARM	XA				ALARM ALARM
08-11-07	07:10:44.378	ML500	ALPHA LUBR., COMMON ALARM	XA				ALARM RETURN
08-11-07	07:10:52.935	ML500	ALPHA LUBR., COMMON ALARM	XA				ALARM ALARM
08-11-07	07:11:01.725	ML055	N/E NO.1 L.O FILTER DIFF PRESS	DPIAH	0.93	KG/CM2	HIGH	ALARM
08-11-07	07:11:05.000	SD003	N/E MAIN L.O PRESS LOW	SHD			SHD-AL	RETURN

08-11-07	07:11:12.000	SL001	M/E SLOW DOWN	SLD			ALARM	RETURN
08-11-07	07:11:17.093	ML091	M/E NO.1 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
08-11-07	07:11:32.248	ML083	M/E NO.3 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
08-11-07	07:11:38.121	ML082	M/E NO.2 T/C L.O INLET PRESS	PIAL	1.20	KG/CM2	LOW	RETURN
08-11-07	07:21:03.777	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.61	M	LOW	ALARM
08-11-07	07:21:47.133	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:22:08.342	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.62	M	LOW	ALARM
08-11-07	07:25:06.263	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:25:44.266	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.62	M	LOW	ALARM
08-11-07	07:26:31.722	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:27:03.582	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.61	M	LOW	ALARM
08-11-07	07:27:24.090	MC036	M/E CONTROL POSITION MISSING	XA			ALARM	RETURN
08-11-07	07:27:36.187	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:27:47.920	MC017	M/E CONTROL AIR PRESS	PIAL	5.12	KG/CM2	LOW	ALARM
08-11-07	07:27:42.023	MW013	M/E J.C.F.W COMMON OUT TEMP	TIAHL	53.2	DEG.C	LOW	ALARM
08-11-07	07:27:42.028	MW002	M/E JACKET C.F.W IN TEMP	TIAL	54.1	DEG.C	LOW	ALARM
08-11-07	07:27:47.316	MC017	M/E CONTROL AIR PRESS	PIAL	5.50	KG/CM2	LOW	RETURN
08-11-07	07:28:01.532	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.62	M	LOW	ALARM
08-11-07	07:28:02.890	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:29:57.747	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.62	M	LOW	ALARM
08-11-07	07:30:00.593	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:30:27.000	MC037	M/E NOT READY	XA			ALARM	RETURN
08-11-07	07:30:28.000	MC002	M/E START BLOCKED	XA			ALARM	RETURN
08-11-07	07:30:28.000	MC004	M/E REMOTE CONTROL SYS ABNORMAL	XA			ALARM	RETURN
08-11-07	07:31:16.263	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.62	M	LOW	ALARM
08-11-07	07:31:26.689	ML058	MAIN L.O SUMP TK LEVEL	LIAHL	0.63	M	LOW	RETURN
08-11-07	07:39:10.031	BA022	NO.1 G/E L.T WATER INLET TEMP	TIAH	45.1	DEG.C	HIGH	ALARM
08-11-07	07:39:11.231	BA022	NO.1 G/E L.T WATER INLET TEMP	TIAH	43.1	DEG.C	HIGH	RETURN
08-11-07	07:41:11.000	MC030	M/E SOLENOID VALVE LOOP FAIL	XA			ALARM	ALARM
08-11-07	07:41:12.000	MC030	M/E SOLENOID VALVE LOOP FAIL	XA			ALARM	RETURN
08-11-07	07:47:41.361	MW002	M/E JACKET C.F.W IN TEMP	TIAL	60.0	DEG.C	LOW	RETURN
08-11-07	07:47:43.469	MW002	M/E JACKET C.F.W IN TEMP	TIAL	59.9	DEG.C	LOW	ALARM
08-11-07	07:47:44.478	MW002	M/E JACKET C.F.W IN TEMP	TIAL	60.0	DEG.C	LOW	RETURN
08-11-07	07:50:36.936	MW013	M/E J.C.F.W COMMON OUT TEMP	TIAHL	60.0	DEG.C	LOW	RETURN
08-11-07	08:05:39.724	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN
08-11-07	08:05:45.661	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.1	DEG.C	HIGH	ALARM
08-11-07	08:06:17.457	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN

ALARM LIST for HANJIN CAIRO

KONGSBERG NORCONTROL AS

DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
08-11-07	08:06:32.731	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.2	DEG.C	HIGH	ALARM
08-11-07	08:06:33.001	MF021	NO.3 HFO BUNKER TK(P) TEMP	TIAH	71.6	DEG.C	OFFSC	ALARM
08-11-07	08:06:48.415	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN
08-11-07	08:07:24.620	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.1	DEG.C	HIGH	ALARM
08-11-07	08:07:35.909	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	62.0	DEG.C	HIGH	RETURN
08-11-07	08:08:31.661	MF023	NO.3 HFO BUNKER TK(S) TEMP	TIAH	61.9	DEG.C	OFFSC	ALARM
08-11-07	09:19:20.852	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-54.4	DEG.C	LOW	ALARM
08-11-07	09:19:20.852	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	83.1	DEG.C	HIGH	ALARM
08-11-07	09:19:20.852	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	61.5	DEG.C	HIGH	ALARM
08-11-07	09:19:30.488	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.3	DEG.C	LOW	ALARM
08-11-07	09:19:32.000	MC033	M/E SLOW DOWN CANCELLED	XA			ALARM	ALARM
08-11-07	09:19:31.786	MC006	M/E SAFETY SYS ABNORMAL	XA			ALARM	ALARM
08-11-07	09:19:37.456	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.7	DEG.C	LOW	ALARM
08-11-07	09:21:55.900	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:22:04.167	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-30.0	DEG.C	LOW	RETURN
08-11-07	09:23:32.352	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	09:24:01.960	MA072	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN

08-11-07	09:26:30.923	MA027	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	-32.1	DEG.C	LOW	ALARM
08-11-07	09:27:31.974	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:27:49.137	MA036	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	09:27:50.017	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:28:02.162	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	433.6	DEG.C	HIGH	ALARM
08-11-07	09:28:09.955	GC043	NO.3 6/E L.O SUMP TK L.L	LAL			ALARM	ALARM
08-11-07	09:28:59.944	GC043	NO.3 6/E L.O SUMP TK L.L	LAL			ALARM	RETURN
08-11-07	09:29:06.269	MA027	M/E NO.9 CYL EXH. GAS OUT TEMP	TIAHH	430.0	DEG.C	HIGH	RETURN
08-11-07	09:29:08.491	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	430.0	DEG.C	HIGH	RETURN
08-11-07	09:29:09.331	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	09:29:12.829	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:29:35.680	MA035	M/E NO.7 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.8	DEG.C	LOW	ALARM
08-11-07	09:32:06.791	MA035	M/E NO.7 CYL EXH. GAS DEV. TEMP	TDIAHL	-60.9	DEG.C	LOW	RETURN
08-11-07	09:35:19.361	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	ALARM
08-11-07	09:35:20.571	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	RETURN
08-11-07	09:36:18.271	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	ALARM
08-11-07	09:36:41.472	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	RETURN
08-11-07	09:37:11.155	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	ALARM
08-11-07	09:37:26.979	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	RETURN
08-11-07	09:37:56.167	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	ALARM
08-11-07	09:38:38.274	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	RETURN
08-11-07	09:45:59.211	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	663.6	DEG.C	IFH	ALARM
08-11-07	09:47:22.138	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-60.4	DEG.C	LOW	ALARM
08-11-07	09:47:22.138	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	83.5	DEG.C	HIGH	ALARM
08-11-07	09:47:22.138	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	52.5	DEG.C	HIGH	ALARM
08-11-07	09:47:26.255	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.2	DEG.C	LOW	ALARM
08-11-07	09:47:27.655	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.8	DEG.C	LOW	ALARM
08-11-07	09:47:59.263	MA024	M/E NO.6 CYL EXH. GAS OUT TEMP	TIAHH	582.5	DEG.C	IFH	RETURN
08-11-07	09:47:59.263	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	30.9	DEG.C	HIGH	RETURN
08-11-07	09:48:01.832	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	60.8	DEG.C	HIGH	ALARM
08-11-07	09:49:35.632	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	09:49:42.639	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:49:43.439	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:49:47.888	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	09:50:12.513	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	09:50:33.974	MA035	M/E NO.7 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.5	DEG.C	LOW	ALARM
08-11-07	09:51:00.775	MA033	M/E NO.5 CYL EXH. GAS DEV. TEMP	TDIAHL	-53.3	DEG.C	LOW	ALARM

ALARM LIST for HANJIN CAIRO

KONGSBERG NORCONTROL AS

DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
08-11-07	09:51:02.374	MA035	M/E NO.7 CYL EXH. GAS DEV. TEMP	TDIAHL	-49.4	DEG.C	LOW	RETURN
08-11-07	09:51:21.661	MA033	M/E NO.5 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	10:01:43.884	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	ALARM
08-11-07	10:01:54.039	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	RETURN
08-11-07	10:02:49.662	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	ALARM
08-11-07	10:03:37.347	MF041	NO.2 HFO PURIFIER ABNORMAL	XA			ALARM	RETURN
08-11-07	10:28:46.616	MF015	HFO LOW SUL. SETTLING TK LEVEL	LIAHL	0.08	M	LOW	ALARM
08-11-07	10:31:08.888	MF015	HFO LOW SUL. SETTLING TK LEVEL	LIAHL	0.10	M	LOW	RETURN
08-11-07	10:31:53.885	MF009	HFO TRANS P/P DISCH. PRESS	PIAL	-0.01	KG/CM2	LOW	ALARM
08-11-07	10:39:17.255	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.1	DEG.C	HIGH	ALARM
08-11-07	10:39:19.484	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.0	DEG.C	HIGH	RETURN
08-11-07	10:39:24.750	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.1	DEG.C	HIGH	ALARM
08-11-07	10:39:40.292	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.0	DEG.C	HIGH	RETURN
08-11-07	10:39:42.376	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.1	DEG.C	HIGH	ALARM
08-11-07	10:39:49.706	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.0	DEG.C	HIGH	RETURN
08-11-07	10:40:05.927	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.1	DEG.C	HIGH	ALARM
08-11-07	10:40:08.475	MF037	D.B HFO BUNKER TK TEMP	TIAH	68.0	DEG.C	HIGH	RETURN

08-11-07	11:17:32.630	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	64.4	DEG.C	HIGH	ALARM
08-11-07	11:17:32.630	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	55.4	DEG.C	HIGH	ALARM
08-11-07	11:18:54.681	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	11:19:37.790	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	11:21:28.885	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-52.2	DEG.C	LOW	ALARM
08-11-07	11:21:31.934	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	51.5	DEG.C	HIGH	ALARM
08-11-07	11:21:47.349	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-52.6	DEG.C	LOW	ALARM
08-11-07	11:21:50.608	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.4	DEG.C	LOW	ALARM
08-11-07	11:22:47.589	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	11:23:24.718	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	11:23:34.505	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	11:23:05.165	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	11:23:07.694	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	11:36:02.170	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
08-11-07	11:36:57.557	AB005	BOILER ABNORMAL	XA			ALARM	RETURN
08-11-07	11:36:56.296	AB001	BOILER TRIP	XA			ALARM	ALARM
08-11-07	11:36:59.246	AB001	BOILER TRIP	XA			ALARM	RETURN
08-11-07	11:37:01.305	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
08-11-07	11:37:02.095	AB005	BOILER ABNORMAL	XA			ALARM	RETURN
08-11-07	11:37:04.174	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
08-11-07	11:37:07.643	AB005	BOILER ABNORMAL	XA			ALARM	RETURN
08-11-07	11:37:11.362	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
08-11-07	11:38:11.324	AB002	BOILER DRUM STEAM PRESS	PIAHL	4.98	KG/CM2	LOW	ALARM
08-11-07	11:38:18.937	AB005	BOILER ABNORMAL	XA			ALARM	RETURN
08-11-07	11:38:22.785	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
08-11-07	11:38:37.840	AB005	BOILER ABNORMAL	XA			ALARM	RETURN
08-11-07	11:38:39.910	AB005	BOILER ABNORMAL	XA			ALARM	ALARM
08-11-07	11:42:04.081	AB001	BOILER TRIP	XA			ALARM	ALARM
08-11-07	11:42:09.449	AB001	BOILER TRIP	XA			ALARM	RETURN
08-11-07	11:49:16.136	AB002	BOILER DRUM STEAM PRESS	PIAHL	5.00	KG/CM2	LOW	RETURN
08-11-07	11:52:19.362	AB011	BOILER FEED FILTER TK L.L	LAL			ALARM	ALARM
08-11-07	11:53:41.502	AB011	BOILER FEED FILTER TK L.L	LAL			ALARM	RETURN
08-11-07	12:02:26.193	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-64.6	DEG.C	LOW	ALARM
08-11-07	12:02:26.193	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-57.6	DEG.C	LOW	ALARM
08-11-07	12:02:26.193	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-67.2	DEG.C	LOW	ALARM
08-11-07	12:02:26.193	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	90.8	DEG.C	HIGH	ALARM
08-11-07	12:02:26.193	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	64.4	DEG.C	HIGH	ALARM
08-11-07	12:02:26.165	MA030	M/E NO.2 CYL EXH. GAS DEV. TEMP	TDIAHL	-51.2	DEG.C	LOW	ALARM

ALARM LIST for HANJIN CAIRO

KONGSBERG NORCONTROL AS


DC C20

Date	Time	Tagname	Tag description	Func	Value	Eng.	Cond.	State
08-11-07	12:02:50.353	MA030	M/E NO.2 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	12:03:17.234	MA031	M/E NO.3 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	12:03:25.964	MA029	M/E NO.1 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	12:04:04.071	MA032	M/E NO.4 CYL EXH. GAS DEV. TEMP	TDIAHL	-50.0	DEG.C	LOW	RETURN
08-11-07	12:04:19.968	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	12:04:45.119	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.7	DEG.C	HIGH	ALARM
08-11-07	12:04:58.063	MA038	M/E NO.10 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	12:05:16.237	MA037	M/E NO.9 CYL EXH. GAS DEV. TEMP	TDIAHL	50.0	DEG.C	HIGH	RETURN
08-11-07	12:14:26.281	AB005	BOILER ABNORMAL	XA			ALARM	RETURN
08-11-07	12:18:16.318	MF009	HFO TRANS P/P DISCH. PRESS	PIAL	-0.05	KG/CM2	LOW	RETURN
08-11-07	12:22:30.978	MC021	M/E NO.2 AUX. BLOWER FAIL	XA			ALARM	ALARM
08-11-07	12:22:30.978	MC022	M/E NO.3 AUX. BLOWER FAIL	XA			ALARM	ALARM
08-11-07	12:22:33.408	MC022	M/E NO.3 AUX. BLOWER FAIL	XA			ALARM	RETURN
08-11-07	12:22:33.438	MC021	M/E NO.2 AUX. BLOWER FAIL	XA			ALARM	RETURN
08-11-07	12:24:44.000	MC036	M/E CONTROL POSITION MISSING	XA			ALARM	ALARM
08-11-07	12:24:44.000	MC004	M/E REMOTE CONTROL SYS ABNORMAL	XA			ALARM	ALARM
08-11-07	12:22:36.000	MC002	M/E START BLOCKED	XA			ALARM	ALARM

EXHIBIT 6

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007


326 37° 49.3' N 122.7' W Treasure Island, 0.2 mile west of Flood 172° Ebb 343°
 Wednesday November 7, 2007



Encl: (6)

431 37° 45.0' N 20.0' W Potrero Point, 2 miles east of Flood 159° Ebb 328°


Wednesday November 7, 2007



Current in Anchorage 9 on 7 Nov

271 37° 49.7' N 27.7° W GOLDEN GATE BRIDGE Flood 55° Ebb 237°

Wednesday November 7, 2007



<Large current eddies which cause ships to sheer off course are reported near the foundation piers of Golden Gate Bridge and San Francisco-Oakland Bay Bridge.>

Sunrise 6:41 AM
Moonset 3:44 PM

Moonrise 4:40 AM
Sunset 5:05 PM

7


6.2 ft.
9:57 AM

4.8 ft.
11:10 PM

1.8 ft.
3:37 AM

0.2 ft.
4:35 PM

7 8 9 10 11 12 1 2 3 4 5

Legend:  Zero Line;
November 7, 2007 5.6 ft. 8:25 AM






EXHIBIT 7

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

VESSEL TRAFFIC SERVICES AREA
(see note C)

REGULATED NAVIGATION AREA
165.1185 (see note A)



Encl: (7)




EXHIBIT 8

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

INVESTIGATOR'S REPORT

WHILE INCLUDED IN THE REPORT,
THESE DOCUMENTS HAVE BEEN
REMOVED FROM THIS VOLUME AS
THEY ARE NOT PART OF THE PUBLIC
RECORD. (7 C.C.R. § 210(c)(11))

EXHIBIT 9

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

Photos -

1. Jane's Merchant Ships () general view
2. View of damage - taken from Pilot Boat 16 Nov 07
3. " "
4. " "
5. Port side bridge consol - from left: radar,
elect. chart display, vessel control data monitor,
radar, helm consol.
6. Stbd side bridge consol - from centerline:
helm consol, engine order telegraph - lever w/
black knob is bow thruster, vessel control gauges,
monitor for engine functions - at bridge windows -
Capt Sun, Capt Miller
7. Radar screen, next to helm consol
8. Electronic Chart Monitor, next to outboard radar
9. Elect. Chart Monitor - vessel approaching Pier 70
complex. Note stern appears to be in allision
with pier. Note "Chart Warnings" box at lower
left of screen
10. Elect. Chart Monitor - Vessel docking at shipyard.
Note: stern appears to be in allision with pier:
Note: "Chart Warnings" "Chart is not ECDIS
Compliant Data"

156 M²FK H1

LAURA MAERSK DIS/De (Odense) 2001; Con; 50,721 gt/63,200 dwt; 265.84 x 37.38 x 14.00 m (872.18 x 122.64 x 45.93 ft); M (B & W); 24 kt; 3,700 TEU.

Sisters: LARS MAERSK (DIS); LAUST MAERSK (DIS); LEDA MAERSK (DIS); LEXA MAERSK (DIS); LICA MAERSK (DIS); LUNA MAERSK (DIS)



Hanjin Helsinki

The Shipping Information Service (D Hazell) / 0558862



Ming Cosmos

The Shipping Information Service (D Hazell) / 0567660

157 M²FK H1


MING PLUM Pa/Ko (Hyundai) 2000; Con; 64,254 gt/68,413 dwt; 274.69 x 40.00 (mb) x 12.00 m (901.21 x 131.23 x 39.37 ft); M (Sulzer); 26 kt; 5,512 TEU (including 400 reefer).

Sister: MING ORCHID (Pa)

Probable sisters: MERCURY BRIDGE (Li) ex-Ming Cypress; MING GREEN (Tw)

Similar: CSCL SEATTLE (Li) ex-Hansa Columbia; HANJIN CAIRO (MI); HANJIN GOTHENBURG (MI); HANJIN HELSINKI (MI); HANJIN TAIPEI (Ge)

Similar (builder — China SB): JUPITER BRIDGE (Li) ex-Ming Bamboo; MING COSMOS (Pa); VENUS BRIDGE (Li) ex-Ming Pine; YM WEALTH (Li)



Katsuragi

(builder — IHI) / 0019497



MOL Elbe


The Shipping Information Service (David Hazell) / 0533440

158 M²FK H1

MOL ELBE Ja/Ja (IHI) 1990; Con; 50,352 gt/58,112 dwt; 292.15 x 32.20 (mb) x 13.03 m (958.50 x 105.64 x 42.75 ft); M (Sulzer); 23.9 kt; ex-Elbe; 3,796 TEU (including 305 reefer)

Sister: MOL INGENUITY (Pa) ex-Danube


Similar: KATSURAGI (Pa)



MSC Samantha (as Pacific Sky) The Shipping Information Service (Chris Gee) / 0572572

159 M²FK H1

MSC SAMANTHA Pa/Ja (IHI) 1982; Con; 30,955 gt/34,098 dwt; 210.01 x 32.21 (mb) x 12.02 m (689.01 x 105.68 x 39.44 ft); M (Sulzer); 18.8 kt; ex-S A Vaal; 1,855 TEU (including 510 reefer). See entry number 12/357 — original sisters. Some of the latter also have this appearance now ('N' masts removed from superstructure).



P&O Nedlloyd Kilindini (as Global Horizon)

92WG DETA RAAF 1998 / 0106969




WEC Rotterdam

The Shipping Information Service (Jane Ellen Hazell) / 0568594


160 M²FK H1


P&O NEDLLOYD KILINDINI Ma/Sp (AES) 1982; Con; 19,872 gt/19,185 dwt; 184.00 x 27.06 x 9.52 m (603.67 x 88.78 x 31.23 ft); M (B & W); 19 kt; ex-Almudena; 1,552 TEU (including 134 reefer)


Sister: WEC ROTTERDAM (Cy) ex-Pilar














6





ALARMS OFF
 Radar On
 TIME 20:00
 Radar On
 ORDERED HARDWARE DSE 2
 CONTROL OFF
 PPL CH / Speed On / SYSE
 V Plan OAK-FUS-VP
 HDG 200
 COG 140 T
 SOG 07 kn
 STW 00 kn
 POS ST. 100000
 Set & Drift ↓ Chart On ↓
 CID
 EBL 1 EBL 2 VRM EBL
 Radar On / Anchor / EBL
 Chart On / Vector 15 min
 Chart
 Chart / Other / MAN /
 Z In / Z Out / Window /
 Scale 17.500 OVER
 EBL 1 EBL 2 VRM EBL
 Radar On / Anchor / EBL
 Chart On / Vector 15 min
 Chart
 Chart / Other / MAN /
 Z In / Z Out / Window /
 Scale 17.500 OVER




CHART/WARNINGS

TRUE WIND



314 073

ENGINE RPM



AUTOPILOT MODE

MANUAL TRACK



WATER SPEED GROUND SPEED



DEPTH 8.3m

RUDDER



RELATIVE WIND



316 073

VOYAGE PLAN

NEXT WPT

WPT TRK BRG DIST RAD ETA





FINAL WPT

DIST ETA

10243346140000


CHART SCOUT TRACK


11





FILE
ORG
COM
FIG
VPI
HD
CO
SO
ST
PC
Set
CID
EBI
Pat
CPI
CPI















EXHIBIT 10

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

156 M²FK H1

LAURA MAERSK DIS/De (Odense) 2001; Con; 50,721 gt/63,200 dwt; 265.84 x 37.38 x 14.00 m (872.18 x 122.64 x 45.93 ft); M (B & W); 24 kt; 3,700 TEU.

Sisters: LARS MAERSK (DIS); LAUST MAERSK (DIS); LEDA MAERSK (DIS); LEXA MAERSK (DIS); LICA MAERSK (DIS); LUNA MAERSK (DIS)



Hanjin Helsinki

The Shipping Information Service (D Hazell) / 0558862



Ming Cosmos

The Shipping Information Service (D Hazell) / 0567660

157 M²FK H1


MING PLUM Pa/Ko (Hyundai) 2000; Con; 64,254 gt/68,413 dwt; 274.69 x 40.00 (mb) x 12.00 m (901.21 x 131.23 x 39.37 ft); M (Sulzer); 26 kt; 5,512 TEU (including 400 reefer).

Sister: MING ORCHID (Pa)

Probable sisters: MERCURY BRIDGE (Li) ex-Ming Cypress; MING GREEN (Tww)

Similar: CSCL SEATTLE (Li) ex-Hansa Columbia; HANJIN CAIRO (MI); HANJIN GOTHENBURG (MI); HANJIN HELSINKI (MI); HANJIN TAIPEI (Ge)

Similar (builder — China SB): JUPITER BRIDGE (Li) ex-Ming Bamboo; MING COSMOS (Pa); VENUS BRIDGE (Li) ex-Ming Pine; YM WEALTH (Li)



Katsuragi

(builder — IHI) / 0019497

MOL Elbe


The Shipping Information Service (David Hazell) / 0533440

158 M²FK H1

MOL ELBE Ja/Ja (IHI) 1990; Con; 50,352 gt/58,112 dwt; 292.15 x 32.20 (mb) x 13.03 m (958.50 x 105.64 x 42.75 ft); M (Sulzer); 23.9 kt; ex-Elbe; 3,796 TEU (including 305 reefer)

Sister: MOL INGENUITY (Pa) ex-Danube


Similar: KATSURAGI (Pa)



MSC Samantha (as Pacific Sky) The Shipping Information Service (Chris Gee) / 0572572


159 M²FK H1

MSC SAMANTHA Pa/Ja (IHI) 1982; Con; 30,955 gt/34,098 dwt; 210.01 x 32.21 (mb) x 12.02 m (689.01 x 105.68 x 39.44 ft); M (Sulzer); 18.8 kt; ex-S A Vaal; 1,855 TEU (including 510 reefer). See entry number 12/357 — original sisters. Some of the latter also have this appearance now ('N' masts removed from superstructure).



P&O Nedlloyd Kilindini (as Global Horizon)

92WG DETA RAAF 1998 / 0106969



WEC Rotterdam

The Shipping Information Service (Jane Ellen Hazell) / 0568594

160 M²FK H1

P&O NEDLLOYD KILINDINI Ma/Sp (AESA) 1982; Con; 19,872 gt/19,185 dwt; 184.00 x 27.06 x 9.52 m (603.67 x 88.78 x 31.23 ft); M (B & W); 19 kt; ex-Almudena; 1,552 TEU (including 134 reefer)


Sister: WEC ROTTERDAM (Cy) ex-Pilar

Line No.	Ship Name	Class	Yd No.	Yr	Builder	Capacity	Engines	Speed	Remarks
110315	HANJIN BOMBAY	Class: KR	16,252	1995-02	Hanjin Heavy Industries Co., Ltd. - Ulsan Yd No: 622	26,24	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 5,480KW(7,450hp) B&W
SDUS	Korea French Banking Corp (SOGEKO)		9,669						
2R-952084	Hanjin Shipping Co Ltd		27,209						
128142	HANJIN BRISBANE	Class: KR	16,270	1997-03	Hanjin Heavy Industries Co., Ltd. - Ulsan Yd No: 632	26,20	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 6,657KW(9,050hp) B&W
3SEP4	Korea French Banking Corp (SOGEKO)		9,620						
2R-972764	Hanjin Shipping Co Ltd		27,382						
1200691	HANJIN BRUSSELS	Class: GL	66,278	2000-05	Hanjin Heavy Industries Co., Ltd. - Pusan Yd No: 069	14,000	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 4,900KW(7,638hp) Sulzer
3JW	KG ms 'Grosser Verwaltungsgesellschaft mbH & Co		36,993						
			68,790						
7811367	HANJIN BUSAN	Class: KR (AB)	17,933	1975-08	Hyundai Heavy Industries Co., Ltd. - Ulsan Yd No: 1895	23,88	1 oil engine driving 1 FP propeller	17.0	1 oil engine driving 1 FP propeller Total Power: 13,422KW(18,248hp) Sulzer
P3V87	Busan Maritime Co Ltd		6,062						
			18,700						
9231743	HANJIN CAIRO	Class: GL	65,131	2001-12	Hyundai Heavy Industries Co., Ltd. - Ulsan Yd No: 1381	14,000	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 57,100KW(77,633hp) MAN-B&W
DPSQ	Conti Cairo (MI) Shipping Ltd		34,078						
			68,086						
9128104	HANJIN CALCUTTA	Class: KR	16,270	1997-02	Hanjin Heavy Industries Co., Ltd. - Pusan Yd No: 037	26,20	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 6,657KW(9,050hp) B&W
DSE05	Korea French Banking Corp (SOGEKO)		9,669						
ICR-972612	Hanjin Shipping Co Ltd		27,365						
9054274	HANJIN CAPETOWN	Class: KR (AB)	76,954	1993-02	Daewoo Shipbuilding & Heavy Machinery, Ltd. - Okpo Yd No: 1060	45,00	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 10,158KW(13,810hp) B&W
DSWX5	Mitsui Maritime SA		48,886						
SGR-	Hanjin Shipping Co Ltd		151,525						
048964	Sogwipo								
9248162	HANJIN CHICAGO	Class: GL	65,918	2003-07	Hanjin Heavy Industries Co., Ltd. - Pusan Yd No: 106	40,30	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 54,896KW(74,638hp) Sulzer
A8C/2	Bereederungs- und Schiffahrtsgesellschaft mbH & Co ms 'Chicago' KG		36,896						
11927	NSB Niederelbe Schiffahrtsgesellschaft mbH & Co KG		68,037						
9082960	HANJIN COLOMBO	Class: AB (GL) (KR)	51,754	1994-12	Hanjin Heavy Industries Co., Ltd. - Pusan Yd No: 017	32,30	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 40,500KW(55,061hp) Sulzer
A6F55	Agia Maritime Inc		29,349						
			62,742						
9200689	HANJIN COPENHAGEN	Class: GL	66,278	1999-12	Hanjin Heavy Industries Co., Ltd. - Pusan Yd No: 068	14,020	1 oil engine driving 1 FP propeller	18.0	1 oil engine driving 1 FP propeller Total Power: 54,900KW(74,638hp) Sulzer
DHDM	Conti Caila Schiffahrtsgesellschaft mbH & Co KG ms 'Conti Canberra'		36,993						
			68,996						
91144	HANJIN LISBON	Class: KR (AB)	17,933	1975-08	Hyundai Heavy Industries Co., Ltd. - Ulsan Yd No: 1895	23,88	1 oil engine driving 1 FP propeller	17.0	1 oil engine driving 1 FP propeller Total Power: 13,422KW(18,248hp) Sulzer
A6F55	Bereederungs- und Schiffahrtsgesellschaft mbH & Co KG		6,062						
			18,700						

Encl: (10)



Name: COSCO Busan
Type: Container ship
SKN-nr: 000058
Length: 274,67 m
Beam: 40,00 m
Draught: 14,00 m
GT: 65.131 t
Capacity: 5.750 TEU
Owner/Manager: NSB Niederelbe
Built: 2001
Shipyard: Hyundai Heavy Ir
Flag: Germany
Port of registry: Hamburg
IMO-number: 9231743
Callsign: DPSQ
Date: 09.11.2006
Location: Predöhlkai 1 - Eu



8

USCG Spill Reporting 399-3547



Hanjin Helsinki

The Shipping Information Service (D Hazell) / 055886



Ming Cosmos

The Shipping Information Service (D Hazell) / 056766

157 M²FK H1

UG

MING PLUM Pa/Ko (Hyundai) 2000; Con; 64,254 gt/68,413 dwt; 274.69 x 40.00 (mb) x 12.00 m (901.21 x 131.23 x 39.37 ft); M (Sulzer); 26 kt; 5,512 TEU (including 400 reefer).

Sister: **MING ORCHID** (Pa)

Probable sisters: **MERCURY BRIDGE** (Li) ex-Ming Cypress; **MING GREEN** (Tw)

Similar: **CSCL SEATTLE** (Li) ex-Hansa Columbia; **HANJIN CAIRO** (MI); **HANJIN GOTHENBURG** (MI); **HANJIN HELSINKI** (MI); **HANJIN TAIPEI** (Ge)

Similar (builder — China SB): **JUPITER BRIDGE** (Li) ex-Ming Bamboo; **MING COSMOS** (Pa); **VENUS BRIDGE** (Li) ex-Ming Pine; **YM WEALTH** (Li)

EXHIBIT 11

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

TUG DATA SHEET

Name of vessel: COSCO BUSAN

Name: REVOLUTION

Operator: Douglas Alters


Owner: AM NAV

Length: ' Beam: ' Draft: '

tonnage: grt

Propulsion configuration: twin Z drive,

Bollard pull: 135,000#



Dolphin Class

Principle Characteristics

Length.....	78'0"
Breadth	34'0"
Draft.....	14'0"
Design Speed	12.0 Knots
Certified Bollard Pull	65 Tons Ahead 60 Tons Astern
Diesel Oil Capacity.....	10,000 Gallons
Fresh Water Capacity	500 Gallons
Registry.....	U. S. Flag
Regulatory Tonnage	Under 200 Gross Tons

144 gwt

Major Equipment

Main Engines	CAT 3512 B HD Series II 2,540 HP each at 1,800 RPM
ASDs	US 205 FP Rolls Royce
Forward Hawser Winch.....	Markey Model DEPGF-42
Stern Hawser Winch	Markey DEPC-32

EXHIBIT 12

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

**PILOT INCIDENT FACTORS CHECK LIST
M/V COSCO BUSAN**

Human Factors:

- _____ Fatigue (pilot/crew)*
- _____ Complacency
- _____ Confusion
- _____ Over confidence
- _____ Reflex Action
- _____ Distraction (personal life events)
- _____ Distraction (on/off ship events)
- _____ Sickness/injury
- _____ Forgetfulness
- _____ Lack of confidence
- _____ Habit
- _____ Substance use/abuse

Communications:*

- _____ Communication not understood
- _____ Communication did not occur
- _____ Communication not verified
- _____ Communication format inadequate
- _____ External communication failure
- _____ Use of standard communications with tug(s)

Performance Pressure:

- _____ Task overload
- _____ Time constraint
- _____ Failure to ask for help
- _____ Performance anxiety
- _____ Fear of consequences
- _____ Fear of failure

Personal Choice:

- _____ Disregard of instruction
- _____ Risk considered acceptable
- _____ Convenience
- _____ Personal comfort

External:

- _____ Speed*
- _____ Visibility
- _____ Traffic*
- _____ Weather*
- _____ Tugs
- _____ Mechanical*

EXHIBIT 13

BOARD OF PILOT COMMISSIONERS
INCIDENT REVIEW COMMITTEE REPORT:
M/V COSCO BUSAN - CAPT. JOHN COTA
NOVEMBER 7, 2007

INCIDENT INVESTIGATION CHECKLIST

Name of ship: COSCO BUSAN

1. Preliminary Investigation Report from SFBP
2. A. USCG Documents
B. NTSB Documents
C. Press releases
3. A. Pilot's Report of the Incident
B. Correspondence w/ Pilot/Att'y
4. A. Master's Report of the incident
B. Copy of Bridge Log
C. Copy of Bell Book
D. Copy of Radio Log or Tape
E. Copy of Chart
F. Copy of Course Recorder
G. Fathometer Record
H. Copy of Official Log
I. Vessel's Particulars
J. Statements from other Deck Dept Witnesses
K. GPS/AIS Printout
L. Crew List (Customs form)
M. Vessel's turning/maneuvering characteristics.
N. Port damage report documents.
O. Vessel cargo plan
P. Correspondence with vessel's agent
5. A. Chief Engineer's Report of Incident
B. Copy of Engine Log
C. Engine Recorder Copy
D. Statements from other Engine Dept Witnesses
6. Tidal Conditions
7. Overview of Port Area
8. A. Investigator's Report
B. Investigator's Worksheet
C. Exec. Director's Documents
9. A. Photo or Drawing of Ship
B. Photos of Damage

Encl: (14)

- 10. Lloyds Register or Jane's Merchant Ships Info.
- 11. Tug Data Sheets
- 12. Pilot Incidents
- 13. Factors Checklist.
- 14. Investigation Checklist.