MP 608 – Marshall, Michigan Incident NTSB/PHMSA Information Request No. 24

24.5	Reference:	Field request
	Preamble:	
	Request:	Please provide all Cathodic protection records on the pipe and the area of the leak.
	Response:	0135_001.pdf
		Also see IR 21.3

ENBRIDGE

Jerry DeWitt Senior Cathodic Protection Specialist Enbridge Pipelines ((US) INC. Chicago Region 1500 W. Main Street Griffith, IN 46319 Tel 219 922 7023 Fax 219 922 3122

TO: Jay Johnson

ĺ

SUBJECT: Marshal Area Close Interval Survey

At the request of the National Transportation Safety Board I was asked to collect close interval survey data in the vicinity of the defect area on mainline 6-B.

A close interval survey consists of recording structure to soil voltage potentials over the top of the pipeline, at 10 foot intervals, and with the rectifiers providing cathodic protection current cycling on and off so the IR drops in the circuit can be eliminated.

Structure to soil voltage is collected by placing a copper/copper sulfate reference electrode in the ground directly over the top of the pipeline, connecting the reference electrode to a high impedance volt meter that is connected to the structure. The measured voltage represents the average structure potential that equates to (4xD = L) D is depth to the top of structure and L is the length of the structure. By taking potential readings at intervals not exceeding 20 feet, it is possible to determine if the structure receiving adequate cathodic protection current and meets or exceeds the minimum levels of cathodic protection mandated in CFR 49 Part 195 which refers to NACE SPO196- latest revision.

Cathodic protection is achieved if one the following criteria are achieved:


- -850 millivolts with current applied
- -850 millivolts instant off
- 100 millivolt shift

At all locations tested on mainline 6-B acceptable levels of cathodic were found.

Jerry DeWiTT

NACE CERTIFICATION:

CP SPECIALIST 3593 COATING INSPECTOT LEVEL 3, 3885 INTERNAL CORROSION TECHKNOLOGIST 3593



July 31, 2010

Mr. Jerry DeWitt Enbridge Energy

RE: Cathodic Protection Results - Marshall Leak Site

Dear Mr. DeWitt,

National Pipeline Services, LLC (NPS) obtained cathodic protection structure-to-soil potentials at the Marshall, MI leak site on July 31, 2010 between 6:30 and 7:00 pm. These readings were obtained by Keith Boswell and Cliff Metcalf with National Pipeline Services. These reading were obtained prior to the pipeline being exposed for inspection.

The following Enbridge Energy rectifiers were interrupted with synchronized GPS interrupters on an 8 second cycle ON and 3 second cycle OFF. Readings were obtained on approximately 10 foot intervals, starting at the temporary valve at Station 7553+24. Survey direction was down stream towards the leak site and beyond approximately 100 feet. Attached is a graph of the potentials obtained during this test.


ID	Location	Volts	Amperes
585	Fulton	10.6	4.9
599	Leroy Station	29.2	5.8
607	Marshall Station	21.7	8.4
620	Albion Station	31.4	6.1

Cathodic protection levels appear adequate with minimal deviation along the length of pipeline surveyed.

If you have any questions or comments, please call me at 989-928-9188.

Sincerely, National Pipeline Services, LLC

Keith B. Boswell Operations Manager – NACE CP Specialist #5407



ENBRIDGE

Jerry DeWitt Senior Cathodic Protection Specialist Enbridge Pipelines ((US) INC. Chicago Region 1500 W. Main Street Griffith, IN 46319 Tel 219 922 7023 Fax 219 922 3122

11

SUBJECT: Line 6-B Foreign pipeline interference DATE: August 11, 2010

Today I contacted corrosion personnel from Wolverine Pipeline, Buckeye, and Panhandle Eastern and requested information on cathodic protection rectifier and bond locations.

Buckeye operates several cathodic protection systems at their terminal on 17 mile Road North of Division with anodes placed directly around the tank bottoms, with no direct connection to Enbridge there is little chance that any voltage gradient from their facility would affect out pipeline.

Panhandle Eastern temporally deactivated their cathodic protection system at 11 mile road, this resulted in a 24 millivolt drop measured at the test station near 17 Mile Road, this voltage drop is negligible and has minimal effect on line 6-B. Panhandle Eastern has returned their rectifier to service.

Wolverine remotely cycled their rectifiers located at 11 mile Road, 14 mile Road, Homer Road, and old Division Street. Enbridge has a bond with Wolverine at homer road. The voltage drop measured 532 millivolts at 17 mile road.

When we conduct testing to ensure the effectiveness of our cathodic protection systems we will interrupt the Wolverine rectifiers in sequence with our rectifiers. This will eliminate the error in measuring our pipe to soil potentials and provide a more accurate voltage measurement.

Jerry DeWitt

NACE CERTIFICATION:

CP SPECIALIST 3593 COATING INSPECTOT LEVEL 3, 3885 INTERNAL CORROSION TECHKNOLOGIST 3593



Jerry DeWitt Senior Cathodic Protection Specialist Enbridge Pipelines ((US) INC. Chicago Region 1500 W. Main Street Griffith, IN 46319 Tel 219 922 7023 Fax 219 922 3122

SUBJECT: Line 6-B exposed coating inspection DATE: August 10, 2010

As mandated by the Federal Code of Regulations (CFR 49 part 195) Coating inspections are required whenever a regulated pipeline is excavated. Operators are required to visually inspect the pipeline coating and identify any anomalous conditions.

Prior to the start of excavation activities National Pipeline Services (NPS) conducted a close interval cathodic protection survey in the defect area. This survey recorded pipe to soil on/off voltage potentials on approximately 500 feet of pipeline. The level of cathodic protection substantially exceeded the minimum criteria.

The pipeline was visually inspected only on the upper portion of the pipeline that was exposed from August 5th thru August 9th.

The pipeline coating appears to be a vinyl half lapped tape system, which is referenced in the pipeline alignment sheet as Polyken 960.

The coating in contact with oil was observed to be in generally poor condition exhibiting looseness, softening, and wrinkles. Coated surfaces not in contact with the oil residue were in fair to good condition with only slight evidence of wrinkling.

There were a few areas where the coating was damaged and the pipeline was exposed to the soil, calcareous deposits were observed and are believed to be a direct result of minerals transported to the structure surface with the passage of cathodic protection current. This is an additional indication that the cathodic protection system is functional.

There were no signs of corrosion observed during this inspection.

Jerry DeWiTT

NACE CERTIFICATION:

CP SPECIALIST 3593 COATING INSPECTOT LEVEL 3, 3885 INTERNAL CORROSION TECHKNOLOGIST 3593



FORM CF-106

INTERNAL / EXTERNAL PIPE INSPECTION FORM

COMPANY NAME	Enbridge Inc.				DATE	8/12/1010			
PIPELINE SEGMENT NAME	Line 6-B from station 7552+46 to 7554+99								
Is person conducting task qualified in accordance with the Enbridge Operator Qualification Program? If no, do not proceed with inspection.						YES X	NO		
Does the pipeline have cathodic protection?						YES X	NO		
If so, what is	s the p	ipe/soil rea	ading?	-1.045	millivolts				
Is pipe bare	or coa	ated?		coated					
Type of coa	ting?	Poleyken	tape	Conditi	on of Coat	ing?	Fair	to poor	
with visible slight damage and wrinkles from station 7552+46 to 7553+95 from this point to 7994+55 the coating was removed and abrasive blasted or is coated with fusion bond epoxy, from 7554+55 to 7554+99 the Polyken tape coating is oil damaged and should be replaced. The PLM crew is planning to remove all exposed tape coat and replacing it with SPC epoxy. See attached photos below									
If pipe was cut for any reason an internal inspection must be done.									
Describe internal condition.									

PRINT NAME	JERRY DEWITT	NAME OF			
SIGNATURE		COMPANY (IF Contractor)	•		

ï







L.





1



Mr. Jerry DeWitt Enbridge Energy

RE: Cathodic Protection Results - Marshall Defect Site Replacement

Dear Mr. DeWitt,

National Pipeline Services, LLC (NPS) obtained follow-up cathodic protection structure-to-soil potentials at the Marshall, MI defect site on August 31, 2010. These readings were obtained by Cliff Metcalf and Jason Dropp with National Pipeline Services. These reading were obtained after the pipeline was replaced.

Initially, a survey was performed when the pipeline was exposed at the defect site on July 31 and August 1, 2010. This initial survey was performed with just the Enbridge rectifiers interrupted. Wolverine Pipeline corrosion technicians could not be reached during that initial survey due to the weekend.

This follow-up survey was performed with both Enbridge and Wolverine rectifiers simultaneously interrupted with remotely operated GPS interrupters. Rectifier outputs for the rectifiers interrupted are attached.

Attached is the graph of the potentials obtained after the pipeline segment was replaced. Cathodic protection levels show adequate potentials with Instant OFF potentials of -1.150 volts. Also included is a copy of the initial survey that was performed on July 31 and August 1, 2010.

An ACVG survey was also performed to identify any coating defects along the pipeline replacement. This survey identified zero coating defects. Operation of the ACVG equipment was verified by introducing a simulated coating defect at a test station.

If you have any questions or comments, please call me at 989-928-9188.


Sincerely, National Pipeline Services, LLC


Keith B. Boswell Operations Manager – NACE CP Specialist #5407

Enbridge - Marshall Leak Site Investigation Rectifier Log

	Date	Company Type	Manufacturer	Location	ON	OFF	Volts	Amps
Set	8/31/2010						24.30	32.5
Pulled	8/31/2010	WOVERINE PIPELINE CO.	RMU OPERATED	11 MILE ROAD	8 SEC	3 SEC	24.30	32.5
Set	8/31/2010						38.60	21.6
Pulled	8/31/2010	WOVERINE PIPELINE CO.	RMU OPERATED	14 MILE ROAD	8 SEC	3 SEC	38.60	21.6
Set	8/31/2010						41.90	17.1
Pulled	8/31/2010	WOVERINE PIPELINE CO.	RMU OPERATED	HOMER ROAD	8 SEC	3 SEC	41.90	17.1
Set	8/31/2010			OLD DIVISION			41.10	13.9
Pulled	8/31/2010	WOVERINE PIPELINE CO.	RMU OPERATED	ROAD	8 SEC	3 SEC	41.10	13.9
Set	8/31/2010						10.60	4.0
Pulled	8/31/2010	ENBRIDGE	RMU OPERATED	FULTON STATION	8 SEC	3 SEC	10.60	4.0
Set	8/31/2010						29.40	5.9
Pulled	8/31/2010	ENBRIDGE	RMU OPERATED	LEROY STATION	8 SEC	3 SEC	29.40	5.9
Set	8/31/2010			MARSHALL			21.10	9.0
Pulled	8/31/2010	ENBRIDGE	RMU OPERATED	STATION	8 SEC	3 SEC	21.10	9.0
Set	8/31/2010						30.10	6.5
Pulled	8/31/2010	ENBRIDGE	RMU OPERATED	ALBION STATION	8 SEC	3 SEC	30.10	6.5

Marshall – 8/31/10 Survey (Pipeline Segment Replaced)





Marshall – 7/31/10 Survey (Defect Exposed)

	CI Survey - Volts								
	0.0	-1.0	- <u>1</u> .5	-2.0	-2.5				
50 7550+94 7551+04 7551+14 7551+24 7551+34 7551+34 7551+54 7551+64 7551+74	PLM at portable toilets Read on top of tempor Edge of temporary roa 3 ft. after stake - 41" co remote left 10 ft due to 5 ft. after planking at co 5 ft. before stake - 40" 5 FT. after stake - 40" At stake - 49" cover	ary road d over planking ommand post cover			ON P/S (volts)				
7551+94 7552+14 7552+24 7552+54	5 ft. before stake - 42" At stake - 42" cover 2 ft. before stake - 47" At stake - 49" cover				Enbrid ROW: MARSHALL DEFECT & 				
7552+84 7553+04 7553+14 7553+24 7553+34	In between cracks in p Edge of planking Top of bank to tempor 2" vent piping Top of bank to tempor	ary valve			'idge Energy DT SITE; Marshall Defect Site -				
CP Data Manager 08/01/10 Page 1 7554+54 7554+54 7554+54 7554+64 7554+74 7554+94	Edge of planking In between cracks in p Remote left 10 ft. due Start readings in oil Begin defect area Remote left 10 ft. due Center of defect area Remote left 10 ft. due sheet piling. End defect area	to planking to leak site hole	gin		Site - Pipe: 6b				

50 Feet/Inch

CP Data Manager 08/01/10 Page 1

