

Engine Data

| Model | Serial Number | Total Time |
|------------|---------------|------------------------------|
| IO-360-L2A | L-30896-51A | 1889.1 Hours Since Field O/H |

Above engine information taken from: Engine dataplate and maintenance logbooks.

Case Match # K2878 Engine S/N on Case: L-30896-51A

Crankshaft S/N: unknown

Last Annual Inspection by: A/P2747693I/A Date Jan 15, 2013

Last Overhaul by: Teledyne Mattituck CRS T10R507Y Date April 29, 2008

Maintenance Records Attached? Yes No

On-Scene Exam? Yes No

Was Engine Disturbed Prior to Your Arrival? Yes No

Does Crankshaft Rotate? Yes No

Propeller Attached? Yes No

Does Engine Appear to be run able? Yes No

Evidence of Fire? Yes No

Comments:

There was no Lycoming Engines travel to the mishap site. Investigators from the National Transportation Safety Board (NTSB), Cessna Aircraft Company and the Federal Aviation Administration, Flight Standards District Office (FAA-FSDO) responded and documented the mishap site.

The aircraft was subsequently removed from the site and transported to the facilities of Plain Parts, Pleasant Grove, California, where a subsequent examination was conducted February 11, 2013. Reference the report narrative for additional information.

Engine Data

Propeller

| Manufacturer | Part Number | Serial Number |
|--------------|-------------|---------------|
| McCauley | 1A170E-7660 | TF023 |

Propeller Type Metal Wood Composite Unknown

Propeller Blade Serial

Numbers:

| | |
|------------------------|------------------------|
| Blade 1 <u> n/a </u> | Blade 2 <u> n/a </u> |
| Blade 3 <u> n/a </u> | Blade 4 <u> n/a </u> |

Propeller Governor

| Manufacturer | Part Number | Serial Number |
|--------------|-------------|---------------|
| n/a | n/a | n/a |

Gasket Screen Condition: n/a

Governor Oil Line: Properly Secured? Yes No Unknown N/A

Correct Line Nuts? Yes No Unknown N/A

Correct Fittings? Yes No Unknown N/A

Propeller Comments:

The two bladed fixed pitch propeller, along with the attached crankshaft flange were displaced from the engine. The crankshaft fracture surface exhibited signatures consistent with *torsional* overload due to the absorption of rotational energy.

The propeller blades were marked "A" & "B" for narrative purposes.

The propeller blade marked as "A" displayed moderate leading edge gouging, torsional twisting, chordwise striations across the cambered surface and trailing edge "S" Bending.

The propeller blade marked as "B" was separated from the hub area near the root of the blade due to the absorption of impact energy. The propeller displayed leading edge gouging, torsional twisting, chordwise striations across the cambered surface and trailing edge "S" Bending.

The propeller damage signatures were consistent with the absorption of rotational forces applied at the crankshaft at the time of impact.

Engine Data

Ignition System:

Magnetos:

Left or Dual Magneto

Manufacturer: Slick Model 4371 P/N S/N 08122601

Impulse Coupling? Yes No
Timing Checked? Yes No
Functioning? Yes No Unknown
Results: _____

Damage: Substantial

Right Magneto

Manufacturer: Slick Model 4371 P/N S/N 06111728

Impulse Coupling? Yes No
Timing Checked? Yes No
Functioning? Yes No Unknown
Results: _____

Damage: Destroyed

Magneto Comments:

Reference the "Engine Observations" narrative for more information.

Spark Plugs

Manufacturer: Champion Type: REM-38E SI 1042 Approved? Yes No

| | | | |
|-------|--|----------|--------------------|
| 1 Top | <u>Undamaged electrode, oil soaked</u> | 1 Bottom | <u>Not removed</u> |
| 2 Top | <u>Undamaged electrode, normal color</u> | 2 Bottom | <u>Not removed</u> |
| 3 Top | <u>Undamaged electrode, oil soaked</u> | 3 Bottom | <u>Not removed</u> |
| 4 Top | <u>Undamaged electrode, normal color</u> | 4 Bottom | <u>Not removed</u> |
| 5 Top | _____ | 5 Bottom | _____ |
| 6 Top | _____ | 6 Bottom | _____ |
| 7 Top | _____ | 7 Bottom | _____ |
| 8 Top | _____ | 8 Bottom | _____ |

Spark Plug Comments:

The spark plugs were secure at each position with their respective spark plug lead attached. The spark plugs (as noted) were removed, examined and photographed. The spark plug electrodes remained mechanically undamaged, and according to the Champion Spark Plugs "Check-A-Plug" chart AV-27, the spark plug electrodes displayed coloration consistent with normal operation. The static oil soaking of the spark plugs (as noted) was attributed to the engine positioning at the mishap site and post recovery.

Ignition Harness

Tested: Yes No Condition: Destroyed

Comments:

The ignition harness had sustained varying degrees of damage by impact energy and was not tested. The ignition harness was attached at each magneto and respective spark plug.

Engine Data

Starter:

Manufacturer: unknown

Part No.: unknown

Serial No.: unknown

Comments: The starter was displaced from the engine and destroyed. The subject starter was not examined.

Alternator:

Manufacturer: unknown

Part No.: unknown

Serial No.: unknown

Comments: The alternator was detached from the engine and destroyed. The subject alternator was not examined.

Generator:

Manufacturer: n/a

Part No.: n/a

Serial No.: n/a

Comments:

Vacuum Pump:

Manufacturer: Airborne

Part No.: 215CC

Serial No.: 62613

Comments:

Stand-by Pump or Aux. Pump:

Manufacturer: Tempest

Part No.: AA32116CW

Serial No.: unknown

Lubrication System:

Oil Suction Screen: Clean Contaminated Unknown

Oil Pressure Screen: Clean Contaminated Unknown N/A

Oil Filter: Clean Contaminated Unknown N/A

Oil Cooler Integrity: Secure Leaking Unknown N/A

Oil Cooler Hoses: Tight Leaking Unknown N/A

Oil System Comments:

The oil suction screen was found secure and uncontaminated by any pre-mishap debris. The oil filter was detached and crushed. There was no evidence of any pre-mishap lubrication system contamination.

Engine Data

Turbo System:

Single or Left

Page Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Rotate? Yes No

Functioning? Yes No Unknown

Damage: _____

Right

Manufacturer: _____

Part No.: _____

Serial No.: _____

Rotate? Yes No

Functioning? Yes No Unknown

Damage: _____

Density Controller

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Differential Control

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Variable Absolute Controller

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Slope Controller

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Manifold Pressure Relief Valve

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Exhaust Bypass Valve

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Comments:

Engine Observations

The subject engine was examined February 11, 2013, at the facilities of Plain Parts, Pleasant Grove, California, under the auspices of the National Transportation Safety Board, Investigator in charge (NTSB-IIC).

The powerplant is a four cylinder, air cooled, direct drive, horizontally opposed, normally aspirated (fuel-injected), internal combustion engine rated at 180hp @ 2700rpm.

The engine had been removed from the airframe at the engine mount to facilitate examination. The engine had sustained significant impact energy damage at the left forward area encompassing the number two cylinder assembly. The exhaust system was crushed aft. The starter and alternator had been displaced from the engine. Visual examination of the engine revealed no evidence of pre-impact catastrophic mechanical malfunction or fire.

The top spark plugs were removed, examined and photographed. The top vacuum pump had been displaced exposing the drive, and the crankshaft was rotated by hand through the drive utilizing a drive tool. The crankshaft was free and easy to rotate in both directions. "Thumb" compression was observed in proper order on all four cylinders. The valve train which had not been damaged by impact forces was observed to operate in proper order, and appeared to be free of any pre-mishap mechanical malfunction. Normal "lift action" was observed at each rocker assembly. Clean, uncontaminated oil was observed at all four rockerbox areas. Mechanical continuity was established throughout the rotating group, valve train and accessory section during hand rotation of the crankshaft. The bottom spark plugs were not removed. The combustion chamber of each cylinder was examined through the spark plug holes utilizing a lighted borescope. The combustion chambers remained mechanically undamaged, and there was no evidence of foreign object ingestion or detonation. The valves were intact and undamaged. There was no evidence of valve to piston face contact observed. The gas path and combustion signatures observed at the spark plugs, combustion chambers and exhaust system components displayed coloration consistent with normal operation. There was no oil residue observed in the exhaust system gas path. There was significant ductile bending of the exhaust system components.

The left magneto had sustained impact energy damage, and was displaced from the mounting pad. The fracture surface signatures at the magneto-mounting flange were consistent with overload forces. The pieces of magneto flange that remained at the mounting pad were securely clamped. Magneto to engine timing could not be ascertained. The impulse coupler drive was found intact and secure. The drive functioned normally during hand rotation of the drive. The magneto produced spark at the four leads during hand rotation the drive.

The right magneto had sustained impact energy damage, and was partially displaced from the mounting pad. The fracture surface signatures at the magneto-mounting flange were consistent with overload forces. The pieces of magneto flange that remained at the mounting pad were securely clamped. Magneto to engine timing could not be ascertained. The impulse coupler drive was found intact and secure. The magneto sustained varying degrees of damage that rendered the unit inoperative and therefore, could not be functionally tested.

There was no evidence of pre-impact mechanical malfunctions observed during the examination of the engine.