



**LYCOMING**  
A Textron Company

## Air Safety Investigation →

### Single Engine Final Report

<b>Mishap Date:</b> May 16, 2002	<b>Mishap Time (24 hr.):</b> 2154 MST
<b>Aircraft Registration:</b> N328CG	<b>Air Safety Investigator:</b> Mark W. Platt
<b>Aircraft Manufacturer:</b> Socata 2000	<b>Aircraft Model:</b> TB-21
<b>Location:</b> New River, AZ	<b>Aircraft S/N:</b> 2025
<b>On Scene</b> Yes	<b>Aircraft Damage:</b> Destroyed
<b>Examination:</b>	
<b>Federal IIC:</b> Wayne Pollack	<b>NTSB Report#:</b> LAX02FA166

Engine:	Engine
<b>Model</b>	TIO-540-AB1AD
<b>Serial Number</b>	L-10523-61A
<b>Total Time</b>	~125 Hours Since New
<b>Crankshaft S/N</b>	Unknown
<b>Case Match #</b>	K0136

Propeller:	Manufacturer	Part Number	Serial Number
	Hartzell		

Injuries:	Number	Fatal	Serious	Minor	None
<b>Crew</b>	1	1	0	0	0
<b>Passengers</b>	1	1	0	0	0
<b>Ground</b>		0	0	0	

**Registered Owner:** Avex Inc  
205 Durley Ave Suite A  
Camarillo, CA 93010

**Operator:** Same as owner

**Pilot:** Arlen Barry Braunstein

**Medical, Date Issued:** 03/02

**Pilot Rating:** CASEL

### Summary:

On May 16, 2002, about 2154 mountain standard time (MST), a Socata TB-21, registered as N328CG, descended into mountainous terrain in the Tonto National Forest, about 7 nm northeast of New River, Arizona. The airplane was destroyed. The pilot, who was demonstrating the airplane to the prospective purchaser, possessed a commercial pilot certificate and was fatally injured. The prospective purchaser possessed a student pilot certificate and was also fatally injured. The sales demonstration flight was performed under the provisions of Title 14 CFR Part 91. No flight plan was filed. Visual meteorological conditions during the hours of darkness prevailed in the vicinity of the Phoenix Deer Valley Airport, 17 nm south of the accident site.

## Cockpit Instruments and Switches

Legend: D – Destroyed  
B – Broken  
N – No Damage

F – Fire Damage  
I – Impact Damage  
S – Separated

OSL – Off Scale Left  
OSR – Off Scale Right  
E Electronic/ Digital

Unk – Unknown  
N/A – Not Applicable  
N/O – Not Obtainable  
N/L – Not Located

Communication and Navigational Aids					Electrical Switches			
<input type="checkbox"/> All Destroyed by Fire					<input type="checkbox"/> All Destroyed by Fire			
	On	Off	Destroyed	Freq		On	Off	Destroyed
COM 1	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	D, N/O	Master Switch	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
COM 2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Alternator Switch	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
DME	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Avionics Switch	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
ADF	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Pitot Heat	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
NAV 1	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	D, N/O	Navigation Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
NAV 2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Rotating Beacon	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
RNAV	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Landing Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Loran	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Taxi Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
GPS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Strobe Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Auto Pilot	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Instrument Lights	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
					Stall Heat	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transponder	<input type="checkbox"/> Off	<input type="checkbox"/> Sby	<input type="checkbox"/> On	D, N/O	Fuel Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Alt							

Flight Instruments & Controls			Magnetos			
<input type="checkbox"/> All Destroyed by Fire			<input type="checkbox"/> Destroyed by Fire			
	Left	Right	<input type="checkbox"/> Off <input type="checkbox"/> L <input type="checkbox"/> R <input type="checkbox"/> Both			
Airspeed Indicator	123 kts					
Altimeter						
Altimeter Setting						
Directional Gyro						
Heading Bug						
Vertical Speed Indicator						
Attitude Indicator (pitch)						
Attitude Indicator (roll)						
Turn Coordinator (Indicator)						
Turn Coordinator (Ball)						
Magnetic Compass						
NAV1 OBS						
NAV2 OBS						
RNAV Bearing						
RNAV Distance						
Clock						
			Environmental Controls			
			On	Off	Destroyed	
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
			Pressurization Controls			
			Cabin VSI	n/a		
			Cabin Altitude	n/a		
			Differential Pressure	n/a		
			Press. Safety Valve	n/a		
			Pressurization Overflow Valve	n/a		

**Comments:**

The subject aircraft sustained extensive damage resulting from the absorption of impact energy. The instrument panel was extensively fragmented. Reliable and useful information could not be extracted due to the destruction of the instrument panel.

## Engine Instruments and Controls

Legend: D – Destroyed  
B – Broken  
N – No Damage

F – Fire Damage  
I – Impact Damage  
S – Separated

OSL – Off Scale Left  
OSR – Off Scale Right  
E Electronic/ Digital

Unk – Unknown  
N/A – Not Applicable  
N/O – Not Obtainable  
N/L – Not Located

Engine Instruments		Engine Controls (Cockpit)	
Hourmeter	n/a	Throttle	D, N/O
Tachometer - RPM	0	Mixture Control	D, N/O
Tachometer - Hours	E, UNK	Propeller Control	D, N/O
Manifold Pressure	D, N/O	Cowl Flaps	
Cylinder Head Temp	D, N/O	Carburetor Heat	n/a
Oil Pressure	photo 25	Alternate Air	D, N/O
Oil Temperature	photo 25	Ram Air	n/a
Fuel Pressure	D, N/O	<b>Fuel Management</b>	
Exhaust Gas Temperature	D, N/O	Selector Handle	Left
Turbine Inlet Temperature	n/a	Selector Valve	Left
Ammeter		L Main Tank Quantity	D, N/O
Voltmeter	photo 25	L Aux Tank Quantity	
Vacuum Pressure	D, N/O	R Main Tank Quantity	D, N/O
Fuel Flow	D, N/O	R Aux Tank Quantity	
Primer Locked?	n/a	Fuel Management	
<b>Engine Control Positions (Engine Compartment)</b>		Comments:	
Throttle	D, N/O		
Mixture Control	D, N/O		
Propeller Control	D, N/O		
Cowl Flaps			
Carburetor Heat	n/a		
Alternate Air	D, N/O		
Ram Air	n/a		

**Comments:**

The subject aircraft sustained extensive damage resulting from the absorption of impact energy. The instrument panel was extensively fragmented. Reliable and useful information could not be extracted due to the destruction of the instrument panel.

# Engine Data

Model	Serial Number	Total Time
TIO-540-AB1AD	L-10523-61A	~125 Hours Since New

Above engine Information taken from: Aircraft Maintenance logbook.

Case Match # K0136 Engine S/N on Case: L-10523-61A

Crankshaft S/N: Not recorded

Last Annual Inspection by: \_\_\_\_\_ Date \_\_\_\_\_

Last Overhaul by: TEXTRON Lycoming Date \_\_\_\_\_

- |   |   |  |   |
|---|---|--|---|
| Maintenance Records Attached?               | <input type="checkbox"/> Yes            | <input checked="" type="checkbox"/> No |   |
| On-Scene Exam?                              | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No            | Propeller Attached?   |
| Was Engine Disturbed Prior to Your Arrival? | <input type="checkbox"/> Yes            | <input checked="" type="checkbox"/> No | Does Engine Appear to be Runnable?                                  |
| Does Crankshaft Rotate?                     | <input type="checkbox"/> Yes            | <input checked="" type="checkbox"/> No | Evidence of Fire?   |
|   |   |  | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

**Comments:**

Investigators from the National Transportation Safety Board (NTSB), the Federal Aviation Administration, Flight Standards District Office (FAA-FSDO), and Lycoming Engines responded to and documented the mishap site. Reference the report narrative for additional information.

The aircraft was subsequently removed from the site and transported to the facilities of Air Transport Inc; Phoenix, Arizona.

## Engine Data

### Propeller

Manufacturer	Part Number	Serial Number
Hartzell	Unknown	Unknown

Propeller Type  Metal  Wood  Composite  Unknown

Propeller Blade Serial Numbers: \_\_\_\_\_

Blade 1 Unknown

Blade 2 Unknown

Blade 3 Unknown

Blade 4 \_\_\_\_\_

### Propeller Governor

Manufacturer	Part Number	Serial Number
Woodward	F210761	12316990

Gasket Screen Condition: Not removed

Governor Oil Line: Properly Secured?  Yes  No  Unknown  N/A  
 Correct Line Nuts?  Yes  No  Unknown  N/A  
 Correct Fittings?  Yes  No  Unknown  N/A

### Propeller Comments:

The three bladed constant speed propeller was displaced from the crankshaft flange at the mechanical attachment area of the hub. The fracture surfaces exhibited signatures consistent with overload due to the absorption of rotational energy. The spinner and dome were displaced from the propeller hub. The propeller blades remained attached to the propeller hub. In addition to significant material loss at each propeller blade tip area, the propeller blades displayed leading edge gouging, torsional twisting, chordwise striations across the cambered surface and trailing edge "S" Bending. The signatures were consistent with the absorption of rotational forces applied at the crankshaft at the time of impact. Reference photographs 74-83 for views of the subject propeller.

The propeller governor (photo 47) was securely attached at the mounting pad with the pitch control rod securely attached at the control wheel.



General view of propeller and blade damage.



View of the mechanical attachment area of propeller hub.



## Engine Data

### Ignition System:

#### Magnetos:

Left or  Dual Magneto

Manufacturer: TCM Model: D6LN-3000 P/N \_\_\_\_\_ S/N C070018G  
Impulse Coupling?  Yes  No Functioning?  Yes  No  Unknown  
Timing Checked?  Yes  No Results: \_\_\_\_\_  
Damage: Substantial

#### Right Magneto

Manufacturer: \_\_\_\_\_ Model: \_\_\_\_\_ P/N \_\_\_\_\_ S/N \_\_\_\_\_  
Impulse Coupling?  Yes  No Functioning?  Yes  No  Unknown  
Timing Checked?  Yes  No Results: \_\_\_\_\_  
Damage: \_\_\_\_\_

**Magneto Comments:** Reference the "Engine Observations" narrative for information.

#### Spark Plugs

Manufacturer: Champion Type: RHB-36S SI 1042 Approved?  Yes  No

1 Top	<u>Undamaged electrode, normal color</u>	1 Bottom	<u>Not removed</u>
2 Top	<u>Undamaged electrode, normal color</u>	2 Bottom	<u>Not removed</u>
3 Top	<u>Undamaged electrode, normal color</u>	3 Bottom	<u>Not removed</u>
4 Top	<u>Undamaged electrode, normal color</u>	4 Bottom	<u>Not removed</u>
5 Top	<u>Undamaged electrode, normal color</u>	5 Bottom	<u>Not removed</u>
6 Top	<u>Undamaged electrode, normal color</u>	6 Bottom	<u>Not removed</u>
7 Top	_____	7 Bottom	_____
8 Top	_____	8 Bottom	_____

#### Spark Plug Comments:

The spark plugs were secure at each position with their respective spark plug lead "B-nut" attached. The top spark plugs were removed, examined and photographed. The spark plug electrodes remained mechanically undamaged, and according to the Champion Spark Plugs Check-A-Plug chart AV-27, the spark plug electrodes displayed coloration consistent with normal operation. Reference photographs 48-50 for views of the spark plugs, as removed.

#### Ignition Harness

Tested:  Yes  No Condition: Destroyed

**Comments:** The ignition harness had sustained varying degrees of damage by impact energy and was not tested. The ignition harness was attached at the respective magneto and spark plugs.



## Engine Data

### Starter:

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

**Comments:** The starter was displaced from the engine and destroyed. The subject starter was not examined.

### Alternator:

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

**Comments:** The alternator was detached from the engine and destroyed. The subject alternator was not examined.

### Generator:

Manufacturer: \_\_\_\_\_

Part No.: \_\_\_\_\_

Serial No.: \_\_\_\_\_

**Comments:**

### Vacuum Pump:

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

**Comments:** The vacuum pump was destroyed and not available for examination.

### Stand-by Pump or Aux. Pump:

Manufacturer: \_\_\_\_\_

Part No.: \_\_\_\_\_

Serial No.: \_\_\_\_\_

### Lubrication System:

Oil Suction Screen:  Clean  Contaminated  Unknown

Oil Pressure Screen:  Clean  Contaminated  Unknown  N/A

Oil Filter:  Clean  Contaminated  Unknown  N/A

Oil Cooler Integrity:  Secure  Leaking  Unknown  N/A

Oil Cooler Hoses:  Tight  Leaking  Unknown  N/A

**Oil System Comments:** The oil cooler, oil suction screen and oil filter (photos 35-36) were destroyed by impact.

## Engine Data

### Turbo System:

Page Not Applicable on this engine model.

Single or  Left

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

Rotate?  Yes  No

Functioning?  Yes  No  Unknown

Damage: Destroyed. No data plate found.

Right

Manufacturer: \_\_\_\_\_

Part No.: \_\_\_\_\_

Serial No.: \_\_\_\_\_

Rotate?  Yes  No

Functioning?  Yes  No  Unknown

Damage: \_\_\_\_\_

### Density Controller

Not Applicable on this engine model.

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

### Differential Control

Not Applicable on this engine model.

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

### Variable Absolute Controller

Not Applicable on this engine model.

Manufacturer: \_\_\_\_\_

Part No.: \_\_\_\_\_

Serial No.: \_\_\_\_\_

### Slope Controller

Not Applicable on this engine model.

Manufacturer: \_\_\_\_\_

Part No.: \_\_\_\_\_

Serial No.: \_\_\_\_\_

### Manifold Pressure Relief Valve

Not Applicable on this engine model.

Manufacturer: \_\_\_\_\_

Part No.: \_\_\_\_\_

Serial No.: \_\_\_\_\_

### Exhaust Bypass Valve

Not Applicable on this engine model.

Manufacturer: Unknown

Part No.: Unknown

Serial No.: Unknown

**Comments:** Reference the "Engine Observations" narrative for details.

## Engine Observations

The subject wreckage and engine were examined on-scene on May 18, 2002, under the auspices of the National Transportation Safety Board, Investigator in charge (NTSB-IIC).

The powerplant is a six cylinder, air cooled, direct drive, horizontally opposed, turbo-charged fuel injected, internal combustion engine rated at 250hp @ 2575rpm.

The engine was displaced from the engine mount. The engine had sustained significant impact energy damage. The oil sump and induction system including the fuel injection servo and induction pipes were completely displaced from the engine. All of the accessories mounted at the rear of the engine were displaced from their respective mountings. The cylinder head of the number six cylinder was displaced. The crankcase at the cylinder number one position was fractured and the cylinder was skewed from its normal position. Visual examination of the engine revealed no evidence of pre-impact catastrophic mechanical malfunction or fire. The propeller was displaced from the crankshaft flange.

The top spark plugs were removed, examined and photographed. Rotation of the crankshaft was precluded due to impact damage to the case and cylinders. The gears at the rear of the engine could be visualized and appeared intact. Internal components of the engine were examined utilizing a lighted bore scope. The crankshaft and attached connecting rods remained intact and exhibited no evidence of heat distress or malfunction. The cylinder(s) combustion chamber was examined through the spark plug holes utilizing a lighted bore scope. The combustion chambers remained mechanically undamaged, and there was no evidence of foreign object ingestion. The valves were intact and undamaged. There was no evidence of valve to piston face contact observed. The gas path and combustion signatures observed at the spark plugs, combustion chambers and exhaust system components displayed coloration consistent with normal operation. There was no oil residue observed in the exhaust system gas path. There was significant ductile bending of the exhaust system components.

The single drive dual magneto had sustained minor impact energy damage, and was displaced from the mounting pad. The surface signatures at the magneto-mounting flange were consistent with overload forces applied. Magneto to engine timing could not be ascertained. The impulse coupler drive was found intact and secure. The drive functioned normally during hand rotation of the drive. The magneto produced spark at the twelve leads during hand rotation the drive. Reference photographs 52-54 for views of the magneto.

The turbo-charger system had sustained varying degrees of impact energy damage. The turbo-charger was displaced from the mountings and had sustained major damage. The turbine impeller remained secure and had sustained rotational damage. The impeller blades exhibited no damage consistent with the ingestion of foreign objects. The exhaust gas path coloration at the turbo and respective exhaust system components exhibited coloration consistent with normal operation and remained free of oil residue. The compressor impeller was destroyed and not found. The compressor impeller shroud was recovered and exhibited circumferential scoring where it had contacted the compressor turbine during the absorption of impact energy. The exhaust by-pass valve (aka: wastegate) was displaced from the engine. The butterfly valve within the pipe remained intact and undamaged. The density and differential controllers were destroyed with fragments of the components identified along the debris path. Reference photographs 27-33 for views of the various components, as described.