

Air Safety Investigation +

Final Engine Test Report

Mishap Date: February 28, 2002

N33584

Aircraft Registration: Aircraft Manufacturer:

Piper 1975

Location:

Hamilton, GA

On Scene Examination:

Yes

Federal IIC: C.A. Smith

Mishap Time (24 hr.):

0950 UTC

Air Safety Investigator: Aircraft Model:

Aaron L. Spotts PA-32-300

Aircraft S/N:

32-7540107

Aircraft Damage: Substantial

NTSB Report#: ATL02FA057

Engine:		Engine	
	Model	IO-540-K1A5	
	Serial Number	L-12899-48	
	Total Time	24.3 Hours Since Field O/H	
	Crankshaft S/N	71804	
	Case Match #	2522	

Propeller:	Manufacturer	Part Number	Serial Number
	Hartzell	HC-C2YR-1BF	CH34755B

Injuries:	Number	Fatal	Serious	Minor	None
Crew	1	1	0	0	0
Passengers	1	0	1	0	0
Ground		n	0	0	

Registered Owner:

E&F Flying Club, LLC

995 La Salle St.

Waterford, MI 48328

Operator:

John A. Frazer

Phone Investigation Supplement:

☐ Yes ⊠No

Phone Investigation Performed by:

Field Investigation Supplement:

⊠ Yes □No

Field Investigation Performed by:

Edward Rogalski-Lycoming

Engine Test Requested by:

C.A. Smith-NTSB

Engine Test Conducted by:

Paul Cox-NTSB/ Aaron Spotts-Lycoming

Engine Test Date:

June 11, 2002

Test Location:

Lycoming/ 652 Oliver St. Williamsport, PA 17701

Engine As Received or First Viewed

- Right magneto harness leads displayed heavy sealant at the attachment point to the magneto harness cap all leads.
- Right magneto observed to have sealant at magneto flange and magneto adapter attachment point.
- Right magneto flange broken at upper magneto clamp attachment point.
- Alternator damaged.
- Light damage to starter (accessory attachment boss broken.)
- Starter support assembly not returned with the engine.
- Bottoms of exhaust pipes observed to be cut separated.
- Light damage to #2 cylinder front cooling fins.
- Oil cooler displayed light damage.
- Both lower engine mounts broken and the top right engine mount was broken.
- Oil filter adapter broken and separate from engine as received.

Engine Data

Model	Serial Number	Total Time
IO-540-K1A5	L-12899-48	24.3 Hours Since Field O/H

Above engine Info	rmation ta	ken from:	Data Plate				
Case Match #	2522			Engine S/N on Case:	L-128	399-48	
Crankshaft S/N:	71804						
Last Annual Inspe	ction by:	(See Field f	Report)		Date	(See Field Report)	
Last Overhaul by:	•	(See Field f	Report)		Date	(See Field Report)	_
Maintenance Reco	ords Attacl	ned?	☐ Yes [☑ No			

Comments:

	Engine Data	
Propeller		
Manufacturer	Part Number	Serial Number
Hartzell	HC-C2YR-1BF	CH34755B
Propeller Type Metal Wood Propeller Blade Serial Numbers: U Blade 1 Unk Blade 3 Unk		Blade 2 Unk Blade 4 Unk
blade 5 <u>Olk</u>	· · · · · · · · · · · · · · · · · · ·	bidde 4 Offk
Propeller Governor Manufacturer	Part Number	Serial Number
Unk	Unk	Unk
Gasket Screen Condition: Unk Governor Oil Line: Properly Sc Correct Lin Correct Fitte	ecured?	vn ⊠ N/A vn ⊠ N/A
Propeller Comments: (See Field Report)		

	En	gine Dat	a		
Fuel System ☑ Inject Manufacturer: Precision	ction	Model: R	SA-10ED1	Setting:	2524273-12
Serial. No.: 43042	Floats:	☐ Metal	☐ Composite		
	Carburetor/Injector Inlet: craft Main Fuel Strainer:	☐ Clean ☐ Clean	Contaminated Contaminated		
Flow Divider Manufacturer: Bendix		Part No.:	78924	Serial No.:	C412
Evidence of Fuel Found?	☐ Yes ☐ No	Jnknown			
Injector Nozzles: Type: Condition:	☑ One Piece ☐ Tw]Unknown]Unknown		
Fuel Pump:	☐ Diaphragm Ge	ared [Unknown 🗌 No	ne	
Manufacturer: Romec	Part	No.: <u>RG17</u>	<u>'980D/M</u> S	erial No.: _	B-7838
Fuel System Comments: \	Jpon removal of the serv	o fuel inlet s	creen, water was o	bserved. W	/ater was also

Fuel System Comments: Upon removal of the servo fuel inlet screen, water was observed. Water was also observed upon removal of the fuel line at the pump outlet to the servo inlet. Approximately one ounce of water was captured. Water paste was used, (see digital photo's).

Engin	e Data
Ignition System: Magnetos: ☑ Left or ☐ Dual Magneto	
Manufacturer: Bendix Model: S6LN-1227	P/N 10-349370-4 S/N C179811GN
Impulse Coupling? Yes No Coupl	P/N 10-349370-4 S/N C179811GN ng Functioning? ☑ Yes ☐ No ☐ Unknown s received 19 degrees B.T.D.C
Right Magneto	
Manufacturer: TCM Model: S6LN-1209 Impulse Coupling? ☐ Yes ☒ No Coupling	P/N 10-349310-1 S/N A289842GN ng Functioning? Yes No Unknown s received, unable to record a reading area.
Magneto Comments: Right magneto was slaved for the 349310-1.	test run. Model: S6LN-1209, S/N: 8225202, P/N: 10-
Spark Plugs Manufacturer: Champion Type: REM-38E	SI 1042 Approved? 🛛 Yes 🔲 No
1 Top Normal operation	1 Bottom Not removed
2 Top Normal operation	2 Bottom Not removed
3 Top Normal operation	3 Bottom Not removed
4 Top Normal operation	4 Bottom Not removed
5 Top Normal operation	5 Bottom Not removed
6 Top Normal operation	6 Bottom Not removed
7 Top	7 Bottom
8 Top	8 Bottom
Spark Plug Comments: See Champion Aviation's Checological See Champion Aviation See Champion Aviation's Checological See Champion See Cham	
Compression Test: Engine Cold Comments:	☐Thumb Method ⊠ N/A

Valve Action: Rotate Engine if possible to verify continuity through engine. **Comments:** See engine run

		Engir	e Data	
Starter: Manufacturer: Prest Part No.: MZ-4 Comments:	olite 222R		Serial No.: <u>L000072</u>	
Alternator: Manufacturer: Part No.: 41118 Comments:			Serial No.: 9902	
Generator: Manufacturer: Part No.: N/A Comments:			Serial No.: N/A	
Vacuum Pump: Manufacturer: Airbo Part No.: RA21 Comments:			Serial No.: <u>A4028</u>	
Stand-by Pump Manufacturer: Unk Part No.: Unk	or 🗌 A	ux. Pump:	Serial No.: Unk	
Lubrication Syste Oil Suction Screen:	m: ⊠ Clean	☐ Contaminated	Unknown	
Oil Pressure Screen:	☐ Clean	Contaminated	☐ Unknown N/A	
Oil Filter:	⊠ Clean	Contaminated	☐ Unknown ☐ N/A	
Oil Cooler Integrity:	⊠ Secure	Leaking	☐ Unknown ☐ N/A	
Oil Cooler Hoses:	⊠ Tight	Leaking	☐ Unknown ☐ N/A	
Oil System Comment	e. There is ty	vo all coalers with th	s installation	

	Engine Data
Turbo System: ☐ Single or ☐ Left	Page Not Applicable on this engine model. No Turbo Supplied.
Manufacturer: Part No.:	Serial No.:
Rotate? Yes	☐ No Functioning? ☐ Yes ☐ No ☐ Unknown
Damage:	
Right	
Manufacturer: Part No.:	Serial No.:
Rotate? Tyes	
Damage:	
Part No.: Differential Control Manufacturer:	Not Applicable on this engine model. Serial No.: Not Applicable on this engine model.
Part No.:	Serial No.:
Manufacturer:	Serial No.:
Slope Controller	Not Applicable on this engine model.
Manifold Pressure Relief	Valve ☑ Not Applicable on this engine model.
Exhaust Bypass Valve	Serial No.: Not Applicable on this engine model.
Manufacturer: Part No.:	Serial No.:

Comments:

Engine Observations

Engine serial number L-12899-48 was removed from the secured shipping container and installed on a ring and skid.

The following was accomplished in order to prepare the engine for test:

- Removed all airframe baffling.
- Removed both oil coolers.
- Vacuum pump was removed and a cover plate was added at the mounting pad.
- Removed right magneto due to the broken flange.
- Installed front crankshaft plug.
- Installed slave starter ring gear support.
- Installed slave right magneto and timed at 20 degrees B.T.D.C.
- Installed prop governor cover plate.
- Installed slave oil filter adapter.
- Capped manifold pressure fitting at #5 cylinder.

The oil suction screen had been removed from the engine, as received, with no debris observed.

The oil filter element had been removed from the oil can, as received, with no debris observed.

The fuel inlet screen was removed and water was observed.

The fuel line from the engine driven pump to the fuel servo and water was observed.

The engine was transported to the test cell area and installed on test cell 2-3. All required test equipment was installed.

The engine was started without any problems. The engine was run at various test points for approximately 25 minutes. It was determined that the oil pressure was low for the given rpm value so a white oil relief spring was installed (see Lycoming's "Service Table of Limits"). The use of the lower pressure oil relief valve spring is most likely due to the dual oil cooler installation. The test run continued with acceptable results. The engines maximum-recorded speed was 2714 rpm. The engine test run was concluded.

Narrative

Engine serial number L-12899-48 was built as an IO-540-K1A5 and shipped to Piper Aircraft Corporation, Vero Beach, Florida on January 4, 1975. The engine was not returned to Lycoming until after the mishap on February 28, 2002.

The engine test run results show that the engine was capable of producing power. The engine as tested, was within new engine fuel flow limits. There were not any discrepancies or anomalies that would indicate the engine was not capable of running and producing power prior to the mishap.

The engine serial number L-12899-48 was released by the NTSB-IIC on June 12, 2002 and was shipped same date, to Atlanta Air Salvage, Griffin, Georgia.

Witnesses			
Name & Address	Phone	Statement Included [Y/N]	Remarks:
Unk	Unk	Unk	Unk

	Wreckage Disposition
Insurance:	Salvage:
Unk	Atlanta Air Salvage

Investigative Participants								
Name & Address	Phone	Organization						
Paul Cox		NTSB						
Aaron L. Spotts		Lycoming						
Lee Netterblade		Lycoming						
								

Investigator Name:	Aaron L. Spotts	1	7		-#	Date:	June 6, 200)2	
Signature:		OU	WICK (X	000				
			`	7	-				