



Air Safety Investigation →

Single Engine Final Report

Mishap Date: July 11, 2012	Mishap Time (24 hr.): 1240 MST
Aircraft Registration: N718JT	Air Safety Investigator: Mark W. Platt
Aircraft Manufacturer: Bunch Matthew 2005	Aircraft Model: Cozy-Canard III
Location: Winslow, AZ	Aircraft S/N: Bunch 1
On Scene: No	Aircraft Damage: Destroyed
Examination:	
Federal IIC: Patrick Jones	NTSB Report#: WPR12LA302

Engine:	Engine
Model	O-320-E2D
Serial Number	L-25183-27A
Total Time	Hours Since Field O/H
Crankshaft S/N	unknown
Case Match #	1708

Propeller:	Manufacturer	Part Number	Serial Number
	unknown	unknown	unknown

Injuries:	Number	Fatal	Serious	Minor	None
Crew	1	0	1	0	0
Passengers	1	1	0	0	0
Ground		0	0	0	

Registered Owner: Tischler Joseph F
 [Redacted]
 Thousand Oaks, CA 91360

Operator: Pilot/owner

Pilot: Joseph Tischler

Medical, Date Issued:
Pilot Rating:

Summary:

On July 11, 2012, about 1240 Mountain Standard Time (MST), an experimental Bunch-Cozy Canard III, registered as N718JT, impacted terrain during takeoff at Winslow, Arizona. The private pilot sustained serious injuries, and the passenger was fatally injured. The owner/pilot was operating the airplane under the provisions of 14 Code of Federal Regulations (CFR) Part 91. The airplane was destroyed impact forces and there was no fire. The cross-country personal flight was departing Winslow-Lindbergh Regional Airport (INW) about 1240, with an unconfirmed destination. Visual meteorological conditions prevailed, and no flight plan had been filed.

Engine Data

Model	Serial Number	Total Time
O-320-E2D	L-25183-27A	Hours Since Field O/H

Above engine information taken from: Dataplate

Case Match # 1708 Engine S/N on Case: L-25183-27A
Crankshaft S/N: unknown

Last Annual Inspection by: _____ Date _____
Last Overhaul by: _____ Date _____

Maintenance Records Attached? Yes No
On-Scene Exam? Yes No Propeller Attached? Yes No
Was Engine Disturbed Prior to Your Arrival? Yes No Does Engine Appear to be run able? Yes No
Does Crankshaft Rotate? Yes No Evidence of Fire? Yes No

Comments:

There was no National Transportation Safety Board or Lycoming Engines travel to the mishap site. Inspectors from the Federal Aviation Administration (FAA) responded to the accident site. The aircraft was subsequently removed from the site and transported to the facilities of Air Transport, Phoenix, Arizona, where a subsequent examination was conducted July 24, 2012.

Engine Data

Propeller

Manufacturer	Part Number	Serial Number
unknown	unknown	unknown

Propeller Type Metal Wood Composite Unknown

Propeller Blade Serial

Numbers:

Blade 1 n/a Blade 2 n/a
Blade 3 n/a Blade 4 n/a

Propeller Governor

Manufacturer	Part Number	Serial Number
n/a	n/a	n/a

Gasket Screen Condition: _____

Governor Oil Line: Properly Secured? Yes No Unknown N/A
Correct Line Nuts? Yes No Unknown N/A
Correct Fittings? Yes No Unknown N/A

Propeller Comments:

The two bladed wooden propeller remained attached at the crankshaft flange. The wooden/composite covered propeller blades had been splintered and separated with about 9 inches of blade material remaining near the hub.

Engine Data

Fuel System Injection Carburetor

Manufacturer: Airflow Performance Model: FM-100 Setting: 5010005

Serial. No.: 20611448 Floats: Metal Composite Plastic

Fuel Screens Carburetor/Injector Inlet: Clean Contaminated Unknown
Aircraft Main Fuel Strainer: Clean Contaminated Unknown

Flow Divider N/A

Manufacturer: _____ Part No.: _____ Serial No.: _____

Evidence of Fuel Found? Yes No Unknown

Injector Nozzles: N/A

Type: One Piece Two Piece Unknown

Condition: Open Plugged Unknown

Fuel Pump: Diaphragm Geared Unknown None

Manufacturer: unknown Part No.: unknown Serial # / Date unknown
Code: _____

Fuel System Comments:

The subject engine was originally delivered from Lycoming as a normally aspirated (carbureted) engine and had been field modified with a fuel injection system. The installed fuel system is manufactured by Airflow Performance.

The Ney fuel injection nozzles were installed by way of STC SE 8628 SW.

The fuel injection servo had been displaced from the engine due to the forces of impact. The fracture surfaces exhibited signatures consistent with overload.

The throttle and mixture controls remained secure at their respective control arms of the servo.

The fuel lines at the fuel nozzles and divider manifold remained secure at each fitting.

The fuel injection nozzles remained secure at each cylinder with the fuel line attached. The nozzles remained free of obstruction to flow.

The fuel pump was not removed.

Engine Data

Ignition System:

Magnetos:

Left or Dual Magneto

Manufacturer: Slick Model 4371 P/N S/N 04091936

Impulse Coupling? Yes No Functioning? Yes No Unknown
Timing Checked? Yes No Results: 25° BTDC #1

Damage: None

Right Magneto

Manufacturer: unknown Model unknown P/N unknown S/N unknown

Impulse Coupling? Yes No Functioning? Yes No Unknown
Timing Checked? Yes No Results:

Damage: None

Magneto Comments:

Reference the "Engine Observations" narrative for more information.

Spark Plugs

Manufacturer: Champion Type: REM-37BY SI 1042 Approved? Yes No

1 Top	<u>undamaged electrode, oil soaked</u>	1 Bottom	<u>Undamaged electrode, normal color</u>
2 Top	<u>undamaged electrode, oil soaked</u>	2 Bottom	<u>Undamaged electrode, normal color</u>
3 Top	<u>undamaged electrode, oil soaked</u>	3 Bottom	<u>Undamaged electrode, normal color</u>
4 Top	<u>Undamaged electrode, normal color</u>	4 Bottom	<u>Undamaged electrode, normal color</u>
5 Top	<u></u>	5 Bottom	<u></u>
6 Top	<u></u>	6 Bottom	<u></u>
7 Top	<u></u>	7 Bottom	<u></u>
8 Top	<u></u>	8 Bottom	<u></u>

Spark Plug Comments:

The spark plugs were secure at each position with their respective spark plug lead attached. The spark plugs were removed, examined and photographed. The spark plug electrodes remained mechanically undamaged, and according to the Champion Spark Plugs "Check-A-Plug" chart AV-27, the spark plug electrodes displayed coloration consistent with normal operation. The static oil soaking of the spark plugs (as noted) was attributed to the engine positioning at the mishap site and post recovery.

Ignition Harness

Tested: Yes No Condition: Good

Comments:

The ignition harness was attached at the respective magneto electronic ignition and each spark plug.

Engine Data

Starter:

Manufacturer: not recorded

Part No.: not recorded

Serial No.: not recorded

Comments: The starter was securely attached at the mounting pad, with the electrical connection secure at the post.

Alternator:

Manufacturer: not recorded

Part No.: not recorded

Serial No.: not recorded

Comments: The alternator was securely attached at the mounting pad, with the electrical connections secure at each post.

Generator:

Manufacturer: n/a

Part No.: n/a

Serial No.: n/a

Comments:

Vacuum Pump:

Manufacturer: not recorded

Part No.: not recorded

Serial No.: not recorded

Comments: The rear-mounted vacuum pump was secure at the mounting pad. The vacuum pump was not removed for examination.

Stand-by Pump or Aux. Pump:

Manufacturer: _____

Part No.: _____

Serial No.: _____

Lubrication System:

Oil Suction Screen: Clean Contaminated Unknown

Oil Pressure Screen: Clean Contaminated Unknown N/A

Oil Filter: Clean Contaminated Unknown N/A

Oil Cooler Integrity: Secure Leaking Unknown N/A

Oil Cooler Hoses: Tight Leaking Unknown N/A

Oil System Comments:

The oil filter was secure at the mounting pad and was not removed for examination. The oil suction screen was secure at the mounting and was not removed for examination. There was no evidence of pre-mishap metal contamination observed at the rocker box areas when opened for examination.

Engine Data

Turbo System:

Single or Left

Page Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Rotate? Yes No

Functioning? Yes No Unknown

Damage: _____

Right

Manufacturer: _____

Part No.: _____

Serial No.: _____

Rotate? Yes No

Functioning? Yes No Unknown

Damage: _____

Density Controller

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Differential Control

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Variable Absolute Controller

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Slope Controller

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Manifold Pressure Relief Valve

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Exhaust Bypass Valve

Not Applicable on this engine model.

Manufacturer: _____

Part No.: _____

Serial No.: _____

Comments:

Engine Observations

The subject wreckage and engine were examined July 24, 2012, at the facilities of Air Transport, Phoenix, Arizona, under the auspices of the National Transportation Safety Board, Investigator in charge (NTSB-IIC).

The powerplant is a four cylinder, air cooled, direct drive, horizontally opposed, normally aspirated (fuel injected), internal combustion engine rated at 150hp @ 2700rpm. The subject engine was originally shipped from Lycoming Engines as a carbureted engine and had been field modified to fuel injected.

The subject aircraft is configured in the "pusher" style; therefore, the engine is situated with the crankshaft flange facing aft. For the purposes of clarification, all references to right and left positions will be made as if viewing the rear of the engine.

The bottom spark plugs were removed, examined and photographed. The crankshaft was rotated by hand utilizing the propeller. The crankshaft was free and easy to rotate in both directions. "Thumb" compression was observed in proper order on all four cylinders; however, the number one cylinder produced a notably weaker thumb compression when compared to the others. Air could be heard leaking into the exhaust system pipe. The complete valve train was observed to operate in proper order, and appeared to be free of any pre-mishap mechanical malfunction. Normal "lift action" was observed at each rocker assembly. Clean, uncontaminated oil was observed at all four rockerbox areas. Mechanical continuity was established throughout the rotating group, valve train and accessory section during hand rotation of the crankshaft. The top spark plugs were removed, examined and photographed. The combustion chamber of each cylinder was examined through the spark plug holes utilizing a lighted borescope. The combustion chambers remained mechanically undamaged, and there was no evidence of foreign object ingestion. The tops of each piston was devoid of significant carbon build-up. The valves were intact and undamaged. There was no evidence of valve to piston face contact observed. The blue painted cylinder fin area denoting nitrite cylinder barrels was white in color.

The gas path and combustion signatures observed at the spark plugs, combustion chambers and exhaust system components displayed coloration consistent with normal operation. There was no oil residue observed in the exhaust system gas path.

The left magneto remained secure at the mounting pad with the distributor cap secure. The left magneto impulse coupler could be heard clicking during hand rotation of the crankshaft. The magneto timing was observed at 25 degrees BTDC cylinder #1, which was within specification. The magneto powered all of the top spark plugs. The magneto was not removed.

The right electronic ignition system could not be identified and remained secure at the magneto mounting pad. The spark plug leads remained secure and were connected to the bottom spark plugs. The ignition module was not removed.