

**DOCKET NO.: SA-515**

**NATIONAL TRANSPORTATION SAFETY BOARD  
WASHINGTON, D.C.**

**MAINTENANCE GROUP CHAIRMAN'S FACTURAL REPORT**

**ATTACHMENT 8**

**PRATT & WHITNEY JT8D ENGINE MANUAL  
FRONT COMPRESSOR HUB INSPECTION  
SECTION 72-33-31**

**(12 PAGES)**

Rev. date 5-20-

Task 72-33-00-2  
Pr: (1)

R  
R  
R  
R  
R

Eq:  
Pr:  
See: (1)

INSPECTION-01

Inspection

Task 72-33-00-2

all seal and 1st stage  
fluorescent penetrant  
see Task 72-33-31-30  
Repair-05 and

Figure 801.  
the following areas

- (2) Inspect for fretting
- general physical condition of hub.
- Hub diameter (hub see instructions in
- Inspection-01.

EXCEPTS OF CONTRARY INSTRUCTIONS, THE  
BEST CHEMICAL CLEANING METHOD ALLOWED FOR  
ENGINE OVERHAUL CLEANING OF TITANIUM AND  
TITANIUM ALLOY PARTS IS SPOP 18. ALSO,  
THIS CLEANING METHOD SHOULD ONLY BE APPLIED  
WHEN SPECIFICALLY CALLED FOR.

TITANIUM WELDMENTS AND ASSEMBLIES SHOULD NOT  
BE PROCESSED THROUGH TRICHOETHYLENE  
DEGREASERS OR ANY CLEANER CONTAINING  
CHLORIDES. IN ORDER TO AVOID POSSIBILITY  
OF STRESS CORROSION ASSOCIATED WITH ENTRAP-  
MENT OF CHLORINE CONTAINING MATERIALS IN  
TIGHT FITTING AREAS. THIS RESTRICTION ALSO  
APPLIES TO PARTS SUCH AS TITANIUM DISKS OF  
HUBS CONTAINING PLUGS, SLEEVES, OR PINS.  
TITANIUM DISKS MUST BE DEBLADED PRIOR TO  
CLEANING AND FLUORESCENT PENETRANT INSPECTION.

DO NOT WIRE BRUSH TITANIUM DISKS AND HUBS FOR  
ANY REASON SUSPECTED DEPOSITS OF CADMIUM

**72-33-31**

INSP-01  
Page 801  
MAY 1/94  
200

EFF: -ALL


①

α


FRON

ION-0

HOLES



ALLET R



L-87656

RIM SLOT BOTTOM

Critical Inspection Areas  
 Figure 801  
 (Task 72-33-31-22-008)

R  
R

REF: ALL

72-33-31

INSP-01  
 Page 802  
 MAY 1/94  
 200

2

FR

TIOM






FIG. 802 STAGE



VIEW A



L-71817  
0491

Surface Damage Limits  
Figure 802  
(Task 72-33-31-32-000)

**72-33-31**

INSP-01  
Page 803  
SRP 1/91  
-300

EPF: -ALL

3

PRO

CTION-

atter .125 image aximu ating ithou atter ccept 0.254 mage spair ear H 0.127 or Su Unre iamet r Tas adius 3.175 atter s Acc nch atter .001 vider 2-33- 0.005 repair blende requir ) Unre to Man

Deep Width Without Repair 0.005 Inch (0.127 mm) No Damage is Allowed For Individual Blends on Basis of Basis. Damage To Be Allowed In Snap Fitments. (Repair-02) No Damage is Allowed In Snap Diameter Within 0.125 Inch Surface Damage To 0.005 Inch (0.127 mm) Deep In Slot No Repair. Local Blend Repairing To 0.005 Inch (0.127 mm) Depth Is Permitted. Damage And Round Bottom Depressions Up To 0.005 Inch Deep Are Acceptable Without Repair. Damage Shall Be Removed By Shotpeening Per Task 2-33-02. Scattered Surface Damage Up To 0.005 Inch Shall Be Shotpeened Per Referenced Task. Scattered Surface Damage After Shotpeening May Be Locally Blended To 0.005 Inch (0.127 mm) Deep And Reshotpeened To 0.005 Inch (0.127 mm) Depth. Local Blend Repairing To 0.005 Inch (0.127 mm) Depth Is Permitted.

See To Figure 910

R  
H

EFP: ALL

72-33-31-

INSP-01  
Page 804  
SEP 1/91  
200



SECTION

MOVED

Subtask (3)

ent (w... surface... corrosion... removed areas... may... samples...

clean... recommended... commercially available... SPOF...

- b) ... take into consideration... repair... blend...
c) Acceptability and reparability of specific areas of disk shall be made with reference to Figure 802...

CAUTION UNDER NO CIRCUMSTANCES SHALL THE SNAP DIAMETER OF DISK BE CHANGED, AS EVALUATION OF DISK GROWTH WOULD BE IMPAIRED.

- d) A ripple observed in web or in a surface between bore and snap does not cause a material reduction in thickness and is acceptable.

Subtask 72-33-31-22-062

(4) Service time marking See Figure 803.

- (a) Inspect disk for markings. Markings in areas other than disk OD tang are unacceptable. Such areas must be blended out and disk remarked in acceptable area.
(b) Use metal stamp (roll) drag impression, or non-etching ink for marking
(c) See Time Limits, for disk life.


R R

EFF: -ALL

72-33-31

INSP-01 Page 805 MAY 1/9- 200

5



9 (0393)

1. Service and Time Marking Area
2. 0.060 Inch (1.524 mm) Minimum Gap Allowed

R  
R

Hub Service Time Marking  
Figure 803  
Task 72-33-31-22-000

**72-33-31**  
INSP-01  
Page 806  
MAY 1/96  
200

EFF: -ALL

Task

TIOW- 1  
LY CE C 2  
VI/ER 1 1

4 of 0 A

Task (5)

efere c 3  
-03.  
lamet 1  
snaps a 3  
growt l  
rthar 9 2

reparl  
sk.

ANNON E  
OLT E L

repla e

ot es 2 1  
lred 2 1  
Y. E 2  
ers 8 0 Lc  
od hc 9  
r grc t 1  
l whet a  
eptind v'asi  
tion l' 21

Task (6)

Rejex at

Task (7)

ls a capt  
exce dnd.

NOT ALL

72-3-31

INSP-01  
E: 99 807  
SEP 1/93  
200



FR

CTION

FACE



L-71613

F  
F

Dimensional Requirements  
August 80  
Case 72-33-31 (2-000)

EFF - ALL

**72-33-31**

INSP-01  
Page 803  
SEP 1, 93  
200

**Prait & Whitman**  
**1000 ENGINE MANUAL**  
**INSPECTION -**  
**ESSOR FRONT HUB**

12.6	Inches (321.539)	This Diameter
Mus	With Face A Within	(.013 mm) FIR
13.3	5 Inches (338.46)	
2.99	Inches (76.124)	
12.5	Inches (318.99)	This Diameter
Mus	ric With Index	.001 Inch
(0.		
4.72	Inches (120.137)	This Diameter
Mus	ric With Index	.001 Inch
(0.		
3.80	Inches (96.520)	
6.22	Inches (158.192)	Diameter
Mus	ric With Index	.002 Inch
(0.		
8.83	Inches (224.282)	This Diameter Must
Be	Face B Within	(.02 mm) FIR
4.91	Inches (124.84)	

**Key To Figure**

circumferential scoring in bearing seating area maximum depth of .010 inch (0.254 mm) and to maximum width of 0.150 inch (3.81 mm). These limits may be individual or cumulative total. Scoring of entire length of journal to maximum 0.010 inch (0.254 mm) depth and maximum width 0.250 inch (6.35 mm). These limits may be individual or cumulative total. Scoring and/or galling of journals in areas other than bearing seating area acceptable to depth 0.015 inch (0.381 mm) and as not more than 15 percent of area is affected. Sharp ridges and metal pickup must be removed to insure smooth surface comparable to remainder of journal. Damaged journals must be hardness tested in three places around circumference to Rockwell C32 - 41, equivalent. Blain out hardness test marks. Repair damaged journal per Task 72-33-31-30-016, Repair-16).

Subta  
(

-22-056  
 slots inspection  
 special attention shall be given to surface of front compressor rotor from hub broached slots. Inspect broached slots for machining demarcations, steps, irregularities and/or discontinuities.

**72-33-31**  
 INSP-01  
 Page 809  
 SEP 1/93  
 200

-ALL



# Pratt & Whitney

JT8D ENGINE MANUAL (PN 773128)

## FRONT COMPRESSOR FRONT HUB (STAGE ONE) - INSPECTION-01

- (b) Hubs showing evidence of surface tears, sharp depressions, or folded material indicative of displaced metal, attributed to shotpeening of a rough broached surface, should be scrapped.
- (c) Strip blade slots of antigalling compound, shot-peen, and reapply compound per Task 72-33-31-30-002, (Repair-02).

### Subtask 72-33-31-22-057



- (9) Tiered and/or counterweight hole inspection.
  - (a) Clean hub per Task 72-33-00-10-001, (Cleaning-01).
  - (b) Clean each hole with acetone and cotton swab.
  - (c) Mount hub on tilted, rotating holding fixture and illuminate opposite end of hole from viewing end.

NOTE: EACH HOLE MUST BE INSPECTED FROM BOTH SIDES.

- (d) Smooth, continuous finish for entire surface of hole is acceptable.
- (e) Superficial tool marks such as those caused by normal cutting tool removal following machining or by tiered installation and removal are acceptable. Deep tool marks or steps that interrupt normal, smooth machined surface of hole are cause for rejection.
- (f) Shallow circumferential tool marks in a thread pattern are acceptable. Circumferential tool marks showing tearing or smearing of metal are cause for rejection.
- (g) Evidence that finish machining did not remove all traces of semi-finished machined surface is cause for rejection. Repair tiered holes per Task 72-33-31-30-015, (Repair-15).

NOTE: Hubs with holes displaying metal tearing or smearing, deep circular scoring, or machining discoloration shall be scrapped.

### Subtask 72-33-31-22-058

- (10) Inspect labyrinth seals as follows.
  - (a) No cracks are permitted on seals except those cracks in knife-edge seal area which can be blended within limits.
  - (b) If seals are dropped or subjected to accidental shock, inspect knife-edges and end faces for damage.

R  
R

EFF: -ALL

72-33-31

INSP-01  
Page 810  
SEP 1/93  
200

10

U

72-33-31

REF - ALT

R  
R

Seals damaged in Area Y may be blended by pro-  
filling, provided depth of blend does not extend  
into Area B. See Figure  
Removal of material from knife-edge seal must  
not exceed 0.500 linear inch (12.7 mm) total  
(measured circumferentially around seal).  
Bent seals may be straightened provided such  
straightening does not result in seal cracking.  
Radial cracks in Area Y are repairable provided  
they do not extend into Area B, or can be removed  
per step (a). Cracks beyond this point are  
unacceptable.

CAUTION: IF AN AIRSEAL IS REMOVED, IT MUST BE  
REPLACED WITH A NEW AIRSEAL.

See Figure 805

(11) Inspect disk at rotor interface  
ubtask 72-33-31-055

Removal of seal material in excess of one linear  
inch (25.4 mm) at any one location is  
unacceptable. However, blended areas may be adjacent or  
overlapping. See Figure 801, (Repair-01).  
The cracks are permitted in any location along  
the diameter of seal, provided matching ID dia-  
meters of seal rings are maintained. Seal  
assemblies shall be inspected in accordance with  
those given in Section 33-00-00, Inspection-02,  
Reference 210).  
One knife-edge per seal may be 0.003 inch  
(0.076 mm) over present replace limits provided  
all other knife-edges of same seal are within  
replace limits.

Seal edges must be maintained to within 0.015 inch  
(0.381 mm) of nominal diameter to maintain  
proper function. Seal edges must be blended without  
provided there are no cracks. Knife-edge seal  
over the entire length of the seal. (Repair-01)  
straightening in permitted. Seals may be  
seal sections damaged. Seals may be  
blended provided depth of blend does not extend  
into Area B. See Figure 801, (Repair-01).

FROM: ENGINEER REPORT FOR (LWAVE) - INSPECTION-11

THE ENGINEER REPORT IS THE PROPERTY OF  
PART 8 WHIRLY

Pratt & Whitney

ENGINEERING MANUAL (P/N 773129)

PROVIDE SUBMITTER WITH (STAMPED) - INSPECTION

Minimum Depth: 0.0010  
Break Sharp Edge  
Reference Area:  
Reference Area:

Hot Gutter-Edge Seal  
Figure 40

Submittal No. 24-35

R  
R

EPP -ALL

72-33-31

INSP-01  
Page 812  
SEP 1/93  
200