

DOCKET NO. SA-516

EXHIBIT NO. 11M

**NATIONAL TRANSPORTATION SAFETY BOARD**  
WASHINGTON, D.C.

**TWA MODIFICATION ORDER 72F57**

(PAGES M-1 THRU M-11)

COPIES:

DEPT	M.O.	INSTL DWG	FAB DWG
PRD CTL			
TOOLING			
PROCESSING			
REED			

AD - FAR

**TWA**

**MODIFICATION ORDER**

MMD/

AMG/

M.O. NUMBER 72F57

DATE 4/1/96

ATA 28-20

PAGE 1 OF 11 PAGES

CHARGE TO APPROVED MASTER MODIFICATION ORDER NO.

THIS PAGE REPLACES PAGE DATED

TITLE **FUEL BOOST & OVERRIDE/JETTISON PUMP INSULATION RESISTANCE CHECK**

AIRCRAFT AFFECTED ENGINES AFFECTED	747 All - See Pg 2	ENGINEER J. C. Gietz	DATE 4/1/96
---------------------------------------	--------------------	-------------------------	----------------

TOTAL QUANTITY	AIRCRAFT	ENGINES	UNITS	1	2	3	4	5	6	7	8	MANAGER/ENGINEERING	DATE
MODIFIED	11											M. G. Raub	4/8/96
INSPECTED													

<input checked="" type="checkbox"/> SCHEDULE REPAIR	<input checked="" type="checkbox"/> BASE OVERHAUL	CLASSIFICATION	<input type="checkbox"/> MAJOR	<input checked="" type="checkbox"/> MINOR	DIR./PROJ. COORD. ENGINEERING	DATE
<input checked="" type="checkbox"/> SHOP OVERHAUL	<input type="checkbox"/> UNSCHEDULED REPAIR	F.A.A. APRVL REQ'D	<input type="checkbox"/> YES	<input type="checkbox"/> NO	D. G. Kirkpatrick	4-9-96
<input type="checkbox"/> PRE-SERVICE	<input checked="" type="checkbox"/> OTHER	F.A.A. LIAISON (TWA)	F.A.A. REPRESENTATIVE		Sr. V.P. - ENGINEERING	DATE

<input checked="" type="checkbox"/> CHECK "C"	<input type="checkbox"/> LAYOVER	RA Raub				N/12
---	----------------------------------	---------	--	--	--	------

TOTAL DIRECT COSTS	TOTAL RELATED COSTS	TOTAL COST	CONTROLLER	DATE
\$11,188.	\$0.00	\$11,188.		

FINANCIAL USE ONLY		TOTAL OBSOLESCENCE	Sr. V.P. - MAINT. & ENGINEERING	DATE
--------------------	--	--------------------	---------------------------------	------

OVERHEAD	TOTAL COSTS	COST PER UNIT
	11,188.00	1,017.00

<input checked="" type="checkbox"/> EXPENSE	<input type="checkbox"/> CAPITAL	<input type="checkbox"/> BILLABLE	CODE	REVIEWED BY/DATE	COST CTR	ACCOUNT
			12	4-11-96 V. Loganbill	711	1426-2

WATER	NONE	WEIGHT & BALANCE DATA	NONE	S.T.C. REQ'D	NONE	FLT OPS INFO	NONE
-------	------	-----------------------	------	--------------	------	--------------	------

**A. REFERENCE:**

- Boeing Alert Service Bulletin 747-28A2194, dated August 3, 1995.
- Boeing Telex M-7240-95-1171, dated August 4, 1995.
- Boeing Telex M-7240-95-1881, dated December 12, 1995.
- Boeing Telex M-7240-96-0576, dated March 21, 1996.
- ATA Wire 3/18/96C

**B. DESCRIPTION:**

This modification order directs the initial inspection of 747 fuel pumps for leaks at the fuel pump/wire bundle interface and test the insulation resistance of the pump wiring.

**C. JUSTIFICATION: (Priority 1) Pending Airworthiness Directive**

Boeing Alert S.B. 747-28A2194 informs operators of the possibility of corrosion developing in the pump wire terminal assembly. This can lead to arcing within the terminal assembly which might lead to failure of the pump and a fuel leak.

**RELATED INFORMATION:**

None.

M-1

MMD to CF 4-3-96

SUBJECT: FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION	M.O. NO. 72F57
---	----------------

ENGINEER J. C. Giertz

MANAGER M. G. Raub

**AFFECTED AIRCRAFT:**

NOTE: THIS FORM WILL ONLY BE INFREQUENTLY REVISED, SO REFER TO AS&P 7-10-07 WHICH IS THE OFFICIAL LISTING OF AIRCRAFT TO BE COVERED BY MO'S AND INCLUDES AIRCRAFT LEASED TO OTHERS AS WELL AS PARKED AIRCRAFT.

727	747	767	L-1011	DC9	DC9	MD80			
-231	-231A	-131	-231	-1	-10(-15)	-32	-41	-82	-83
4308	4338	17104	16001	11003	8169	8220	8433	9001	9301
4309	4339	17107	16002	11004	8170	8221	8434	9002	9302
4310	4340	17108	16003	11005	8171	8222	8435	9003	9303
4311	4341	17109	16005	11006	8173	8223		9004	9304
4312	4342	17110	16006	11008	8175	8224	-51	9005	9305
4313	4343	17116	16007	11013	8190	8225	8905	9006	9306
4314	4344	17119	16008	11014	8191	8226	8906	9007	9307
4315	4345		16009	11016		8229	8908	9008	
4319	4346	-156A	16010	11017	-31	8231	8909	9009	-83
4320	4347	17133			8376	8232	8910	9011	9401
4322	4348	17134	-205	-50	8377	8295	8911	9012	9402
4325	4349		16050	21019	8378	8296	8912	9013	9403
4326	4350	-257B/284B	16051	21023	8379	8297	8914	9014	9404
4327	4351	17303		21027	8380	8298	8915	9015	9405
4329	4352	17305	-3Y0		8381		8916	9016	9406
4330	4353		16101	-100	8382	-33CF	8917	9017	9407
4331	4354		16102	31029	8383	8537	8918	9018	9408
4332	4355			31031	8384			9019	9409
4333	4357		-330	31036	8385	-34		9020	9410
4334			16103		8386	8627		9050	9411
4335					8387	8628		9051	9412
4336					8388	8636		9052	9413
4337					8389			9053	9414
					8390			9054	
					8391			9055	
					8392			9056	
					8393			9057	
								9058	
								9059	

HADED A/C NUMBERS ARE NOT APPLICABLE FOR THIS MODIFICATION ORDER

M-2

TITLE  
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION

M.O. NO.  
72F57

ENGINEER J. C. Giertz                      MANAGER M. G. Raub

MODIFICATION INSTRUCTIONS:

Part One: Inspect Spare Fuel Pumps

1. On each pump, do a visual inspection of the pump wire terminal assembly. Look for these conditions:
  - a. Signs that fuel has leaked from the wire terminal assembly.
  - b. Signs that the terminal assembly or wire insulation is discolored because of too much heat. Clean the cap as specified in the SWPM 20-60-01.
  - c. Signs of damage to the wire terminal assembly like bulges, bent flanges, broken screws, corrosion, etc.
  - d. If any of the above conditions can be seen, replace/repair as necessary, then go to step 2. If pump checks ok, go to step 2.
2. Do these steps on each pump using a megohmmeter, TWA S/N R&R 90014, TWA Spec. No. EQ 249:
  - a. Set megohmmeter to 10 VDC.  
NOTE: This step is conducted at 10 VDC to prevent arcing or overheating in a flammable leakage zone when high voltage is applied to a pump with low insulation resistance.
  - b. Measure the resistance between pin 4 and any of pins 1, 2 or 3 of the pump mounted electrical connector (see Figure 1). Record the resistance on the data sheet, Table 1.  
NOTE: Make sure the resistance is equal to or greater than 1 megohm; if the resistance is greater than 1 megohm, go to step 2c; if the resistance is less than 1 megohm, replace/repair as necessary, then repeat step 2. If pump checks ok, proceed to following instructions.

FOR REVISED PAGES ONLY:  
AIRCRAFT FLEET 747  
NO. OF COPIES PRODUCTION CONTROL:  
M.O. \_\_\_ FAB.DWG. \_\_\_ INSTL.DWG. \_\_\_

TYPED ig DATE 4/1/96 PAGE 4  
THIS PAGE REPLACES PAGE DATED \_\_\_\_\_

---

FILE  
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION

---

M.O. NO.  
72F57

---

ENGINEER J. C. Giertz                      MANAGER M. G. Raub

---

E. MODIFICATION INSTRUCTIONS: continued

Part One: Inspect Spare Fuel Pumps

2. continued

c. Set the megohmmeter to 500 VDC

d. Measure the resistance between pin 4 and any of pins 1, 2 or 3 of the pump mounted electrical connector (see Figure 1). Record the resistance on the data sheet, Table 1.

NOTE: Make sure the resistance is equal to or greater than 5 megohms; if the resistance is greater than 5 megohms, return unit to stock; if the resistance is less than 5 megohms, replace/repair as necessary, then repeat step 2. If pump checks ok, return unit to spare stock.

M-4

OR REVISED PAGES ONLY:

AIRCRAFT FLEET 747

NO. OF COPIES PRODUCTION CONTROL:

M.O. \_\_\_ FAB.DWG. \_\_\_ INSTL.DWG. \_\_\_

TYPED ig DATE 4/1/96 PAGE 5  
THIS PAGE REPLACES PAGE DATED \_\_\_\_\_

---

TITLE  
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION

M.O. NO.  
72F57

---

ENGINEER J. C. Giertz                      MANAGER M. G. Raub

---

3. MODIFICATION INSTRUCTIONS: continued

Part Two: Inspect Fuel Pumps on Aircraft

1. Ensure that the airplane is in an area which permits air to circulate freely.
2. Ensure that fire fighting equipment is available near the test location.
3. Ensure that the airplane is grounded correctly. Refer to the 747 MM 20-41-01, Static Ground Procedure.
4. Ensure that all work stands are grounded correctly. Refer to the 747 MM 20-41-01, Static Ground Procedure.
5. Get access to the airplane fuel pumps. For boost pumps (8 each) reference 747 MM 28-22-03, and for jettison/override pumps (6 each) reference 28-31-01. In the applicable MM subjects, do the steps necessary to get access to the fuel pump electric motor.
6. Open the circuit breaker for one fuel pump and attach a DO-NOT-CLOSE tag. See step 5 for MM references to get circuit breaker data.
7. On each pump, do a visual inspection of the pump wire terminal assembly. Look for these conditions:
  - a. Signs that fuel has leaked from the wire terminal assembly.
  - b. Signs that the terminal assembly or wire insulation is discolored because of too much heat. Clean the cap as specified in the SWPM 20-60-01.
  - c. Signs of damage to the wire terminal assembly like bulges, bent flanges, broken screws, corrosion, etc.
  - d. If any of the above conditions can be seen, replace the pump, then go to step 6. Refer to step 5 for MM references to remove/install the fuel pump. If pump checks ok, go to step 8.

M-5

FOR REVISED PAGES ONLY:

AIRCRAFT FLEET 747

NO. OF COPIES PRODUCTION CONTROL:

M.O. \_\_\_ FAB.DWG. \_\_\_ INSTL.DWG. \_\_\_

TYPED ig DATE 4/1/96 PAGE 6  
THIS PAGE REPLACES PAGE DATED \_\_\_\_\_

TITLE

FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION

M.O. NO.

72F57

ENGINEER J. C. Giertz

MANAGER M. G. Raub

E. MODIFICATION INSTRUCTIONS: continued

Part Two: Inspect Fuel Pumps on Aircraft

8. Do these steps on each pump using a megohmmeter, TWA S/N R&R 90014, TWA Spec. No. EQ 249:

a. Disconnect pump's electrical connector.

b. Set megohmmeter to 10 VDC.

NOTE: This step is conducted at 10 VDC to prevent arcing or overheating in a flammable leakage zone when high voltage is applied to a pump with low insulation resistance.

c. Measure the resistance between pin 4 and any of pins 1, 2 or 3 of the pump mounted electrical connector (see Figure 1). Record the resistance on the data sheet, Table 1.

NOTE: Make sure the resistance is equal to or greater than 1 megohm; if the resistance is greater than 1 megohm, go to step 8d; if the resistance is less than 1 megohm, replace pump and return to step 6.

d. Set the megohmmeter to 500 VDC

e. Measure the resistance between pin 4 and any of pins 1, 2 or 3 of the pump mounted electrical connector (see Figure 1). Record the resistance on the data sheet, Table 1.

NOTE: Make sure the resistance is equal to or greater than 5 megohms; if the resistance is greater than 5 megohms, go to step 8f; if the resistance is less than 5 megohms, replace pump and return to step 6.

M-6

FOR REVISED PAGES ONLY:

AIRCRAFT FLEET 747

NO. OF COPIES PRODUCTION CONTROL:

M.O. \_\_\_ FAB.DWG. \_\_\_ INSTL.DWG. \_\_\_

TYPED jpg DATE 4/1/90 PAGE 7  
THIS PAGE REPLACES PAGE DATED \_\_\_\_\_

FILE  
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION

M.O. NO.  
72F57

ENGINEER J. C. Giertz                      MANAGER M. G. Raub

MODIFICATION INSTRUCTIONS: continued

Part Two: Inspect Fuel Pumps on Aircraft

9. After pump passes all previous steps, go to step 6 for next fuel pump.
  - a. #1 main fwd boost pump
  - b. #1 main aft boost pump
  - c. #2 main fwd boost pump
  - d. #2 main aft boost pump
  - e. #2 main outboard ovr/jettison pump
  - f. #2 main inboard ovr/jettison pump
  - g. center wing tank left ovr/jettison pump
  - h. center wing tank right ovr/jettison pump
  - ~~9.7h~~ i. center wing tank scavenge pump
  - j. #3 main fwd boost pump
  - k. #3 main aft boost pump
  - l. #3 main outboard ovr/jettison pump
  - m. #3 main inboard ovr/jettison pump
  - j. #4 main fwd boost pump
  - k. #4 main aft boost pump
10. Close the circuit breakers opened in step 6 and remove the DO-NOT-CLOSE tags.
11. Return aircraft to serviceable condition per all applicable 747 MM references.
12. Return removed units to MCL, Building 2 Accessory Shop, C/C 644, Col 909.

m-7



FOR REVISED PAGES ONLY:

AIRCRAFT FLEET 747

NO. OF COPIES PRODUCTION CONTROL:

M.O.     FAB.DWG.     INSTL.DWG.    

TYPED ig DATE 4/1/96 PAGE 8  
THIS PAGE REPLACES PAGE DATED    

TITLE  
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION

M.O. NO.  
72F57

ENGINEER J. C. Giertz

MANAGER M. G. Raub

747 FUEL PUMP INSPECTION DATA SHEET

AIRPLANE TAIL NBR: \_\_\_\_\_ HRS/CYCLES: \_\_\_\_\_ DATE: \_\_\_\_\_

PUMP LOCATION	INSTALLED PUMP			RESISTENCE IN MEGOHMS		NEW PUMP (IF NECESSARY)	
	PART NBR.	SERIAL NBR.	TSO/TSN OVHL/NEW	10 VDC	500 VDC	PART NBR.	SERIAL NBR.
NBR 1 MAIN FWD BOOST PUMP							
NBR 1 MAIN AFT BOOST PUMP							
NBR 2 MAIN FWD BOOST PUMP							
NBR 2 MAIN AFT BOOST PUMP							
NBR 2 MAIN OUTBOARD OVRD/JETTISON PUMP							
NBR 2 MAIN INBOARD OVRD/JETTISON PUMP							
CTR WING TANK LEFT OVRD/JETTISON PUMP							
CTR WING TANK RIGHT OVRD/JETTISON PUMP							
CTR TANK SCAVENGE PUMP							
NBR 3 MAIN FWD BOOST PUMP							
NBR 3 MAIN AFT BOOST PUMP							
NBR 3 MAIN OUTBOARD OVRD/JETTISON PUMP							
NBR 3 MAIN INBOARD OVRD/JETTISON PUMP							
NBR 4 MAIN FWD BOOST PUMP							
NBR 4 MAIN AFT BOOST PUMP							

TABLE 1 - PUMP INSPECTION SUMMARY


M-8

**FILE**  
**FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION**

**M.O. NO.**  
**72F57**


**ENGINEER** J. C. Giertz

**MANAGER** M. G. Raub



TYPICAL

(A)



(B)

FIGURE 1

M-9

OR REVISED PAGES ONLY:

JRCRAFT FLEET 747

NO. OF COPIES PRODUCTION CONTROL:

NO.      FAB.DWG.      INSTL.DWG.     

TYPED   jg   DATE 4/1/96 PAGE 10  
THIS PAGE REPLACES PAGE DATED     

TITLE	M.O. NO.
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION	72F57

ENGINEER J. C. Giertz	MANAGER M. G. Raub
-----------------------	--------------------

MODIFICATION KIT LIST:

Item	Mfr. Code	Mfr. P/N	TWA S/N	SPS No.	Nomenclature	Qty/Plane
1.	04237	2101A	90014		Megohmmeter - Test Set	1*

One test set must be available at each scheduled station to perform inspection.

DRAWINGS REQUIRED:

Drawing No.	Sheet	Change	Type	Source	Title
None					

PARTS REMOVED:

Mfr. Old P/N	Nomenclature	Qty/Pln	Replaced Mfr. New P/N	Obsolete	Disposition of Part
None					

SPECIAL OR ADDITIONAL TOOLS AND EQUIPMENT:

SPECIAL INSTRUCTIONS TO GROUND OPERATIONS FUNCTIONS:

SPECIAL INFORMATION FOR OTHER DEPARTMENTS:

MANUAL, JOB METHOD AND OVERHAUL SPECIFICATION INFORMATION:

1. An MSL is not required.
2. Airplane Maintenance Manual revision is not required.
3. Airplane Wiring Diagram change is not required.
4. Component Maintenance Manual revision is not required.
5. Technical Information Support should not request new component maintenance manual or revision to existing manual from vendor.
6. Technical Information Support is not required to forward M.O. for customized Airframe IPC incorporation, or otherwise make IPC revision.
7. An Aircraft Electrical Load change is not being made.
8. Operational Specifications are not affected.
9. Fault Isolation Reporting Method/Fault Reporting Method/Malfunction Reporting System (FIRM/FRM/MRS) is not affected.

M-10

FILE	M.O. NO.
FUEL BOOST AND OVERRIDE/JETTISON PUMP INSPECTION	72F57
ENGINEER J. C. Giertz	Supervisor
MANAGER M. G. Raub	Production Estimator T. McKinney

LABOR SPECIALTY	BLDG 1 SHOP (TOTAL MAN HRS.)	BLDG 2 SHOP (TOTAL MAN HRS.)	MCI HANGAR (MAN HRS. PER AIRCRAFT/UNIT)	FIELD
Avionics	_____	_____	_____	16
Aircraft	_____	_____	_____	8
	_____	_____	_____	
	_____	_____	_____	
	_____	_____	_____	
	_____	_____	_____	
	_____	_____	_____	
	_____	_____	_____	
TOTAL MAN HRS:	_____	_____	TOTAL:	24
		No. of ACFT/Units:		11
		No. of Eng. (if app):		
		TOTAL MAN HRS:		264
TOTAL SHOP MAN HOURS:		TOTAL HANGAR & FIELD MAN HRS:		
HOURLY LABOR RATE: \$		HOURLY LABOR RATE: \$		42.38
TOTAL SHOP LABOR COST: \$		TOTAL HANGAR/FIELD LABOR COST: \$		11,188.32

OVERHEAD	\$ 0	MANHOURS PER A/C /UNIT	24
TOTAL MOD. LABOR COST: \$	11,188.32	MATERIAL COST PER A/C	\$ 0.

2. COST ANALYSIS	
A. DIRECT COSTS	
(1) LABOR (INCLUDING OVERHEAD) \$	11,188.32
(2) MATERIAL/TOOLS/EQPT. CONSUMED	
(a) MATERIAL INSTALLED:	
CAPITAL	\$ _____
EXPENSE	\$ _____
SUB-TOTAL	\$ _____
(b) TOOLS/EQPT. CONSUMED	\$ _____
SUB-TOTAL	\$ _____
MAT'L/TOOLS/EQPT	\$ _____
(3) SERVICES PURCHASED	\$ _____
(VENDOR)	
GROSS LBR/MAT'L/SVC PUR \$	
(4) LESS KNOWN CRS (SEE E <sub>(2)</sub> ) \$	
TOTAL DIRECT COSTS	\$ _____
B. RELATED SUPPORT COSTS	
(1) SPARE PARTS/MATERIAL	
CAPITAL (FLT EQPT. R & R)	\$ _____
EXPENDABLE INV. STOCK	\$ _____
SUB-TOTAL	\$ _____
(2) MAINT/O'HAUL SUPPORT TOOLING/EQPT	
CAPITAL	\$ _____
EXPENSE	\$ _____
SUB-TOTAL	\$ _____
TOTAL RELATED SUPPORT COST	\$ _____
TOTAL COST	\$ 11,188.32

C. SPECIAL PROJECT STOCK KIT COST:	
(DO NOT USE IF TOTAL MATERIAL COST IS > \$1,000)	
MATERIAL INSTALLED	\$ _____
NUMBER OF AIRCRAFT UNITS MODIFIED	
MATERIAL COST PER KIT	\$ _____
D. TOTAL ENGRG MAN HOURS	
E. OTHER COST FACTORS (EXPLAIN)	
(1) OBSOLESCENCE	\$ _____
(a) SHELF	\$ _____
(2) CREDITS	\$ _____

M-11