

# NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering  
Materials Laboratory Division  
Washington, D.C. 20594



June 2, 2015

MATERIALS LABORATORY FACTUAL REPORT

Report No. 15-061

## A. ACCIDENT INFORMATION

Place : Philadelphia, Pennsylvania  
Date : May 12, 2015  
Vehicle : Train 188, Passenger Coach 81528  
Operator : Amtrak  
NTSB No. : DCA15MR010  
Investigator : Dana Sanzo, RPH-40

## B. COMPONENTS EXAMINED


Seat pedestal with fractured studs.

## C. DETAILS OF THE EXAMINATION


A seat pedestal was submitted to the NTSB Materials Laboratory for examination. The pedestal, as it was received, is shown in figure 1. The pedestal had two studs along its bottom face with the purpose of anchoring the seat to the floor of the rail car. For convenience, the two studs were labelled as "Stud 1" and "Stud 2", as indicated in figure 1. Both studs were fractured. Longitudinal and side view images of Stud 1 are shown in figures 2a and 2b, respectively. Similarly, longitudinal and side view images of Stud 2 are shown in figures 3a and 3b, respectively.

Each stud's flange was fractured on one side adjacent to the shank of the stud. There was an additional crack in the flange of Stud 2 approximately 180° from the fracture, also adjacent to the shank. The fracture surfaces were examined and each fracture surface exhibited parallel smear lines consistent with a shear overstress fracture of each flange.


Donald Kramer, Ph.D.  
Sr. Materials Engineer



**Figure 1:** Image of the seat pedestal with fractured studs at the bottom of the image. For convenience, the studs were labelled “Stud 1” and “Stud 2”.



**Figure 2:** Images of Stud 1: a) Longitudinal view of the stud and b) side view showing the fracture surface.



**Figure 3:** Images of Stud 2: a) Longitudinal view of the stud head and b) side view showing the fracture surface.