

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering
Materials Laboratory Division
Washington, D.C. 20594



February 24, 2016

MATERIALS LABORATORY FACTUAL REPORT

Report No. 16-012

A. ACCIDENT INFORMATION

Place : Scottsdale, Arizona
Date : August 27, 2015
Vehicle : Cirrus SR22, N915TD
NTSB No. : WPR15IA252
Investigator : Thomas M. Little, AS-WPR

B. COMPONENTS EXAMINED

Nose Landing Gear Strut Weldment, p/n 18633-003

C. DETAILS OF THE EXAMINATION

The as-received nose landing gear (NLG) strut assembly was fractured through the strut tube adjacent to the forward edge of the gusset tube attachment welds. The fractured assembly is displayed from the left side in figure 1 and from the top in figure 2. The label affixed to the strut tube indicated the part number as 18631-405, from lot 702635 with serial number 1083 and a QA date of 5/22/14. A representative of Cirrus Aircraft indicated that this lot had contained 11 total strut assemblies.

The FAA registry database indicates that N915TD received its airworthiness certificate on July 31, 2014 with serial number 4098. The strut had a reported total of 391 service hours with an unknown number of landings at the time the strut fractured.

The NLG strut weldment was an inseparable fusion welded¹ assembly consisting of the strut tube with a spindle welded to the forward end and an upper fitting welded to the aft end. Two gusset tubes are welded between the upper fitting and the strut tube along with tabs to connect the oleo strut and lower fairing welded to the strut tube. The material of all components was specified as AISI² 4130³ alloy steel in the normalized condition. The strut was quench and temper heat treated⁴ after welding to a specified hardness of HRC 40 to 44.

¹ Per CDC Specification 90497, class A.

² American Iron and Steel Association.

³ Per various Military specifications.

⁴ Per MIL-H-6875, Military Specification HEAT TREATMENT OF STEEL, PROCESS FOR (version H, 1 MAR 1989) [S/S BY SAE-AMS-H-6875]

As shown in figure 2, the fracture through the strut tube was located at the forward edges (toes) of the gusset tube welds to the strut tube. Visual examinations of the fracture faces found multiple fracture regions on multiple fracture planes with various features within each region as exhibited by the aft fracture face displayed in figure 3. All of the fracture regions were oriented on slanted planes through the wall thickness of the strut tube.

Most prominent, were opposed reflective (shiny) regions at the right and left sides of the fracture, as denoted in figure 3. Both shiny regions were approximately centered at the weld intersection of the respective gusset tube with the strut tube. Magnified stereoscopic examinations revealed wide spread and extensive mechanical surface damage within these regions consistent with repeated mutual crack face recontact from crack closure prior to total strut separation indicative of preexistent cracks.

The reflective region on the left side (image right) of the strut measured approximately 1.9 inches around the circumference of the strut tube. Crack arrest markings as shown in the right side image of figure 4, indicated initial through the wall propagation from the forward toe of the left side gusset tube weld bead. The through the wall penetration area measure about 0.9 inch circumferentially and was on an approximate 45 degree plane through the strut tube wall. At the margins of the though the wall area fracture marking indicated circumferential progression in both the upward and downward directions as denoted by arrows in figure 3 and the right view of figure 4.

The right side reflective region (image left) was much smaller measuring only 0.7 inch circumferentially. Similar to the right side, fracture markings indicated through the wall thickness crack penetration from the forward toe of the respective gusset tube weld bead. However, unlike the left side region, no circumferential progression was noted on the on the right side.

The fracture regions between the two reflective regions were matte in coloration with surface textures and deformation patterns and marking indicative of overstress separations. The overstress regions were also on multiple slant planes through the strut tube wall. The overstress region at the top of the tube had features indicative of a tension separation while the features and deformation at the bottom were typical of combinations of bending and twisting separations.

Scanning electron microscope examinations of the aft fracture face found the recontact mechanical damage to be extensive, obliterating almost all of the fine fracture features within the left and right reflective regions. One band of intact features was located in the through the wall area of the left reflective region that were highly suggestive of high stress fatigue propagation. These are shown in the upper view of figure 5. Identifiable ductile dimples were found starting about midway in the circumferential progression areas and continuing to the termini. Indicating that this portion of the fracture was overstress in nature. These are shown in the lower image of

figure 5. Ductile dimples were also found in the overstress regions between the reflective fracture regions.

With the paint mostly removed, the weld beads and surrounding surfaces were visually inspected at low magnification with a stereo microscope. The surfaces had a fine mottled textures consistent with grit blasting prior to painting. No obvious weld discontinuities were apparent at these optical magnifications. The weld puddle solidification ripple pattern indicated that both gusset tube-to-strut tube-welds were made in a clockwise direction when the individual welds are viewed looking at the strut tube. The start / stop points of the welds were not clearly apparent.

The aft fracture face along with the gusset tubes welds were transversely saw cut from the strut and then sectioned along the horizontal plane through the approximate center lines of the gusset tube as shown in figure 6. The upper pieces containing cross sections of the gusset welds, at the forward and aft side of the individual tubes and the fracture were then mounted and metallographically prepared. Figures 7 and 8 display the welds at the forward (top) and aft (bottom) sides of the right and left gusset tubes, respectively.

Sectioning revealed a dark brown organic coating on all of the interior surfaces of the strut and gusset tubes, see figure 6. A representative of Cirrus described the coating as LPS Hardcoat. The coating was bubbled adjacent to the weld regions but still covered the surfaces. No internal corrosion was noted.

The fracture was at the forward toes of the forward gusset tube welds as shown in the upper views of figures 7 and 8. Also note the slanted nature of the fracture through the strut tube wall thickness.

The welds were specified as full circumferential fillet weld in accordance with Cirrus Design Corporation (CDC) specification 90497 class A⁵ by GTAW (gas tungsten arc weld).

As shown in the upper images of figures 7 and 8, the weld beads at the forward edges of both gusset tubes completely melted the ends of the tubes and incorporated them into the fusion zones. This satisfied the welding specification requirements for complete root penetration plus 10%. The weld sizes were towards the maximum but within the process specifications range for leg lengths "L" and throat depths "K".

The welds on the aft side of the gusset tubes displayed incomplete penetration to the root of the joint and a large pore on the left side weld, lower images in figure 7 and 8. Figure 4.5.3-4 of the weld specification allows for incomplete root penetration for angled tube joints where the acute angle between the tube is 45 degrees or less. The measured angle between the strut and gusset tubes was measured between 55 and 60 degrees.

⁵ CDC Process Specification Welding –Ferrous- Alloys current revision F dated 4/12/02. Class A indicates critical applications "where a failure of any portion would cause loss of system...".

When etched with 2% Nital⁶, the welds and surrounding tube structures showed tempered martensitic structures consistent with the post welding specified quench and tempered heat treatment, see figure 9. The strut tube microstructure showed an elongated structure consistent with the drawing direction of the original tube. Partial decarburization was also noted on the inner diameter of the strut tube as shown in figure 10. The decarburization was visually measured to be between 0.007 and 0.010 inch in depth. The outer diameter of the strut tube, the welds and gusset tube surfaces did not display any decarburization. Heat treating is required to be in accordance with MIL-H-6875H which limits decarburization for this hardness level to 0.005 inch or less as determined by a micro hardness survey.

Microhardness traverses across the fusion zone base metal interfaces of the forward welds showed a uniform hardness and no significant gradients.

As the aft fracture was sectioned from the strut, a ring section was also removed from the strut tube about 1.5 inches aft of the fracture. The ring section was ground to ensure parallel surfaces and measurements were made using an optical comparator⁷. The inner diameter measured 1.690 inches and the outer diameter was 1.934 inches. Cirrus reports the nominal diameters at this location as 1.938 inch outer diameter with a 0.010 inch profile tolerance and 1.687 inch inner diameter. The wall thickness measured at 8 approximately equal spaced circumferential locations ranged from 0.12345 inch to 0.11930 inch for a maximum variation of 0.00415 inch.

Direct HRC⁸ hardness measurements were made on the ring cross section averaging 39.6 HRC for 9 measurements. Slightly lower than the 40 HRC specified but within testing tolerance of + or – 1.0 HRC.

The strut and both gusset tubes were confirmed to be AISI 4130 alloy steel using a hand held x-ray fluorescence spectrograph⁹.

Joe Epperson
Senior Metallurgist

⁶ 2% concentrated nitric acid in ethanol.

⁷ Opticom Qualifier 14B by OGP (Optical Gaging Products)

⁸ Hardness Rockwell "C" scale.

⁹ Thermo Scientific Niton XL3t-980 x-ray fluorescence (XRF) alloy analyzer




Figure 1. Left side views of the fractured strut assembly overall at top and closer view of the fracture area below. Aircraft forward at left.




Figure 2. Upper surface views of the fracture area showing the fracture location at the forward edge of the gusset tube welds identified by brackets at right. Aircraft forward at left.




Figure 3. Looking aft at the fracture face. Double headed red arrows denote the reflective regions and orange arrow the overstress areas. Red brackets denote initiation locations of through the wall crack portions at the toes of the gusset tube welds. Circumferential extensions (two directions) of the left crack are between the red and yellow arcs. Arrows indicate local crack propagation directions.




Figure 4. Closer views of the left and right crack initiations and through the wall penetration showing the crack arrest markings. Arrows indicate local crack propagation directions.





Figure 5. At top an SEM image showing a band of striations indicative of high stress fatigue propagation in the through the wall region of the left reflective band. The lower view displays typical ductile dimples uncovered about midway in the circumferential propagations of the left reflective region.




Figure 6. An overall view of the sectioned intersections of the left and right gusset tubes with the strut tube showing the welds in cross section as further shown below. Aircraft forward is at top on section views. Interior tube surfaces coated with a dark brown material.





Figure 7. Metallographic views of the forward and aft portions of the fillet weld on the right gusset tube weld. Forward portion at top shows more than 100% root penetration. Yellow and red lines denote the approximate original gusset and strut tube surfaces. Note the slant profile of the fracture plane at top. Lower view shows the aft portion of the weld with the red bracket denoting the area of incomplete root penetration.




Figure 8. Metallographic views of the forward and aft portions of the fillet weld on the left gusset tube weld. Forward portion at top shows more than 100% root penetration. Yellow and red lines denote the approximate original gusset and strut tube surfaces. Note the slant profile of the fracture plane at top. Lower view shows the aft portion of the weld with the red bracket denoting the area of incomplete root penetration.





Figure 10. The etched microstructures of the forward welds of the left (top) and right gusset tubes showing a fully martensitic microstructure except at inner diameter of strut tube. See Figure 11. Images mirrored from figures above.






Figure 11. Closer view showing decarburized layer at inner diameter surface of strut tube. Visually measured about 0.007 inch at this location.