



National Transportation Safety Board

Office of Railroad, Pipeline and Hazardous Materials Investigations

Washington, D.C. 20594

Derailment & Hazardous Materials Release with Fire of Train UEGKOT-09

Union Pacific Railroad Company (UP) Unit Train

Graettinger, Iowa

March 10, 2017

Mechanical Group Factual Report

## **Accident**

NTSB Accident Number: DCA17MR007  
Date of Accident: March 10, 2017  
Time of Accident: 12:50 a.m. (CDT)  
Type of Trains: UEGKOT-09 (Unit Train)  
Railroad Owner: UP  
Train Operator: UP  
Fatalities: 0  
Injuries: 0  
Location of Accident: Graettinger, Iowa

## **Mechanical Group Members**

National Transportation Safety Board (NTSB)  
James Southworth  
490 L Enfant Plaza SW  
Washington, D.C. 20594

Federal Railroad Administration (FRA)  
Joseph C. Berry  
Railroad Safety Inspector  
Motive Power & Equipment

Federal Railroad Administration (FRA)  
Patrick Holderby  
Railroad Safety Inspector  
Motive Power & Equipment

Union Pacific Railroad Company (UP)  
Rex Beck  
General Manager Freight Car

## **Accident Summary**

For a summary of the accident, refer to the *Accident Summary* report, within this docket, NTSB Docket DCA17MR007.

## **Train Consist**

Train UEGKOT-09 consisted of two locomotives units at the front of the train, 98 loaded tank cars, 2 buffer cars full of sand (one at the front and one at the rear) and a locomotive at the rear of the train configured as a distributed power unit (DPU). The train weighed 12,699 trailing tons and was 6,215 feet in length. The train was hauling ethanol.

## **Pre- Accident Inspection**

The train crew for Train UEGKOT-09 performed a Federal Railroad Administration (FRA) Class I brake test - initial terminal inspection at Great Plains LLC in Superior, Iowa, on March 9, 2017 at 10:22 pm CST. Superior is just less than 20 miles from the accident location. The train destination was Texas City, Texas, scheduled to arrive on March 13, 2017. A required Class IA – 1000-mile brake test was scheduled en route at Parsons, Kansas. Records showed there were no exceptions were recorded in the collected records.

## **Records Review**

During the on-scene phase of this investigation, investigators collected the daily and periodic inspection records from all locomotives involved in the accident. The daily inspection requirements are outlined in 49 CFR 229.21. This Federal regulation requires that each locomotive in use shall be inspected at least once during each calendar day. A written report of the inspection shall be made. This report shall contain the name of the carrier; the initials and number of the locomotive; the place, date and time of the inspection; a description of the non-complying conditions disclosed by the inspection; and the signature of the employee making the inspection.

Investigators reviewed the daily inspection records for all locomotives in the train consist. The records were in compliance with Federal regulations. The last documented inspections were performed March 10, 2017, at 12:01 a.m., in Superior (DR069) where the train originated. A required inspection at an interval not to exceed 33 days was performed by a qualified mechanical inspector (QMI) on March 8, 2017.

Periodic inspection requirements for locomotives are outlined in 49 CFR 229.23. Each periodic inspection is to be recorded on FRA form F6180-49A. The interval between any two periodic inspections cannot exceed 92-days unless the locomotive is equipped with advanced micro-

processor based on-board electronic condition monitoring controls. The interval for such locomotives types is 184-days.

Investigators reviewed the periodic maintenance records for all locomotives in the train consist. The records were in compliance with the Federal regulations. The required inspections were performed on March 3, 2017, at South Morrill, Nebraska (lead locomotive), on January 10, 2017, at Houston, Texas (trailing locomotive), and on January 13, 2017, at North Little Rock, Arkansas (DPU).

## **Wreckage Description**

A review of the leading locomotive's event recorder showed Train UEGKOT-09 was approaching the timber bridge over Jack Creek located at MP 57 traveling at about 28 MPH. About 12:50 a.m., an unintended emergency brake was initiated. The train separated between the 20<sup>th</sup> and 21<sup>st</sup> cars. During the emergency response, the train crew moved the locomotives and the non-derailed cars away from the point-of-derailment (POD) and the fire that resulted from the train accident.

As a result of the accident the 21<sup>st</sup> through the 40<sup>th</sup> cars in the train were derailed (see summary below):

1. DBUX 301674 (sequence 21) – burned, lying on left side
2. TAEX 2893 (sequence 22) – burned, breached, nearly inverted, lying in Jack Creek
3. TILX 199147 (sequence 23) – burned, lying on side in Jack Creek
4. TCBX 198194 (sequence 24) – burned, nearly inverted, lying in Jack Creek
5. CTCX 732108 (sequence 25) – burned, overturned about 90 degrees, partially underneath sequence 28
6. TILX 197694 (sequence 26) – burned, overturned about 90 degrees
7. DBUX 302834 (sequence 27) – breached, nearly inverted
8. DBUX 302746 (sequence 28) – overriding, listing about 45 degrees, lying in Jack Creek
9. TAEX 2909 (sequence 29) – burned, AEI read issue with GATX 203812
10. WCHX 30078 (sequence 30) – active fire, breached, severely buckled, listing about 10 degrees
11. WCHX 30098 (sequence 31) – active fire, overriding
12. TILX 199819 (sequence 32) – burned, breached
13. TILX 195202 (sequence 33) – burned, breached, listing about 22 degrees
14. CTCX 731383 (sequence 34) – burned, upright
15. TILX 195386 (sequence 35) – A-end, end crushed (no apparent penetration)
16. CTCX 731997 (sequence 36) – burned, breached, listing about 22 degrees
17. TILX 197615 (sequence 37) – A-end, B-end, derailed upright
18. TILX 199168 (sequence 38) – A-end, B-end, derailed, listing about 22 degrees
19. TILX 191239 (sequence 39) – A-end, B-end, derailed, upright
20. DBUX 301606 (sequence 40) – B-end (lead truck), derailed, upright



Figure 1-Aerial Photograph of accident location





Figure 2-Aerial photograph of the derailed tank cars

## Equipment Post Accident Inspections

On March 10, 2017, investigators inspected the lead locomotive consist at the point where they were repositioned east of the derailment site. The inspections of the locomotives revealed that one of two headlights were inoperative (burned out) on the lead locomotive. The rear continuous barrier chain was improperly secured on the trailing locomotive.

Investigators also inspected the distributive power unit (DPU) locomotive that was the end of the train and moved west of the derailment site. Investigators found that the air compressor governor was defective on the DPU causing the unit to continuously run and vent excess pressure. This condition did not affect the charging or maintaining of brake pipe pressure.

None of these conditions were causal to the train accident

On March 11, 2017, investigators inspected the non-derailed cars (1<sup>st</sup> through the 20<sup>th</sup>). The locomotives and the cars were oriented just as they were after passing over the timber bridge. The train was travelling in an easterly direction—right-side wheels of the lead locomotive (and trailing locomotives) and tank cars were running on the south rail. Several wheels on the south side of the train exhibited fresh horizontal damage on the wheel tread (e.g. impressions perpendicular to the wheel tread). Investigators did not observe any horizontal damage to the tread on the wheels that traveled over the north rail. The wheel damage observed was more pronounced on south side

wheels of tank cars further from the locomotive consist. (see Figure 7 at the end of this report for recorded notes from Mechanical Group inspections)

The series of photographs below (figures 3 through 6) document the location and position of remarkable horizontal damage on a southside wheel tread (on TCBX 198115) that traveled over the point-of-derailment (POD). In the photographs, note that there are two marks on the tread.



Figure 3-TCBX 198115 (Photo FRA)



Figure 4-TCBX 198115 wheel damage. (Photo FRA)



Figure 5- TCBX 198115 wheel damage (Photo FRA)



Figure 6- TCBX 198115 wheel damage (Photo FRA)

On March 11, 2017, investigators completed a mechanical walking inspection and an FRA Class 1 brake test on all cars that did not derail. Post-accident inspections and tests of the non-derailed cars in the train revealed very few exceptions (defects). All cars inspected and tested revealed good integrity of the train air brake system. All brakes applied and released as designed. None of the conditions observed on the cars were causal regarding the train accident.

Investigators examined the derailed tank cars, truck assemblies and 80-wheel sets after the post recovery. All wheels were found to be intact except for two broken wheels found to be fractured (derailment damage). Several wheels showed indications of thermal exposure consistent with the

tank car fire. None of the wheels from cars behind the 20<sup>th</sup> car from the lead locomotives exhibited any horizontal wheel marks on the wheel tread.

### **Damage Estimates**

UP has estimated the damage to the equipment about \$1.4 million.

### **In-Service Tank Car Net Braking Ratio Testing**

On June 19, 2017, two NTSB investigators traveled to the Trinity Rail tank car maintenance facility in Saginaw, TX to witness in-service tank car net braking ratio (NBR) tests on three (3) exemplar undamaged tank cars from accident train UEGKOT-09. The brake system tests were conducted in response to an NTSB request to quantify tank car NBR values for representative in-service cars. The results of the testing are presented in the official docket for this investigation.



Figure 7 – Mechanical Group inspection notes for Train UEGKOT-09

Deliver to: OSUE531

Site Monitor's AEI Consist Information  
(Head to Rear)

Train ID: UEGKOT 09                      Date/Time: 03/10/17 00:26  
Site: 509 Estherville East              Circ7: DR058

Locomotives

SEQ NBR	CAR NBR	TYPE	EQ,OR	AXLES	FUEL	SPEED	TAG	ST
001	UP 005666	D	A	6	N/A	23	G	
002	UP 008376	D	A	6	N/A	23	G	
103	UP 008037	D	B	6	N/A	30	G	

Rail Equipment

SEQ NBR	CAR NBR	TYPE	EQ,OR	AXLES	PLTFM	SPEED	TAG	ST	CVR/DYN/RAW
001	GACX 056766	R	A	4	1	24	G		
002	CITX 220168	R	B	4	1	24	G		
003	TCBX 192256	R	A	4	1	24	G		
004	TCBX 193731	R	B	4	1	24	G		
005	TCBX 192230	R	A	4	1	24	G		
006	TILX 320113	R	B	4	1	24	G		
007	TILX 197715	R	B	4	1	24	G		
008	TILX 198343	R	B	4	1	24	G		
009	SHPX 209530	R	B	4	1	24	G		
010	TAEX 001077	R	A	4	1	24	G		
011	TAEX 001184	R	A	4	1	24	G		
012	DBUX 302558	R	A	4	1	25	G		
013	TILX 199805	R	A	4	1	25	G		
014	TILX 318593	R	B	4	1	25	G		
015	DBUX 301604	R	B	4	1	25	G		
016	TILX 199046	R	B	4	1	25	G		
017	TCBX 198068	R	B	4	1	25	G		
018	TILX 198094	R	B	4	1	25	G		
019	DBUX 302412	R	B	4	1	25	G		
020	TCBX 198115	R	A	4	1	25	G		
021	DBUX 301674	R	A	4	1	25	G		
022	TAEX 002893	R	A	4	1	26	G		
023	TILX 199147	R	A	4	1	26	G		
024	TCBX 198194	R	A	4	1	26	G		
025	CTCX 732108	R	B	4	1	26	G		
026	TILX 197694	R	A	4	1	26	G		
027	DBUX 302834	R	B	4	1	26	G		
028	DBUX 302746	R	B	4	1	26	G		
029	TAEX 002909	R	B	4	1	26	G		

Sequence numbers (non-derailed front portion of Train Symbol UEGKOT-09) in yellow highlight exhibited horizontal marks on the wheel tread (south rail) as follows:  
004 - L2, L3  
007 - L2  
008 - L2  
010 - R4, R3  
011 - R4, R3, R2, R1  
012 - R4, R2  
013 - R4, R2, R1  
014 - L1, L2, L3  
015 - L1, L4  
016 - L1, L2, L4  
017 - L1, L2, L3, L4  
019 - L1, L3, L4  
020 - R4, R3, R2, R1; B-end, knuckle broke

Sequence numbers 21 through 29 were derailed as follows:  
21 - burned, lying on left side  
22 - burned, breached, nearly inverted, in water  
23 - burned, lying on its side, in water  
24 - burned, nearly inverted, in water  
25 - burned, overturned about 90 degrees, partially underneath 28  
26 - burned, overturned about 90 degrees  
27 - breached, nearly inverted  
28 - overriding, listing about 45 degrees, in water  
29 - burned, AEI read issue with GATX 203812

030	WCHX 030078 R	A	4	1	26	
031	WCHX 030098 R	A	4	1	26	
032	TILX 199819 R	A	4	1	26	G
033	TILX 195202 R	A	4	1	26	G
034	CTCX 731383 R	B	4	1	27	G
035	TILX 195386 R	A	4	1	27	G
036	CTCX 731997 R	A	4	1	27	G
037	TILX 197615 R	A	4	1	27	G
038	TILX 199168 R	B	4	1	27	G
039	TILX 191239 R	B	4	1	27	G
040	DBUX 301606 R	B	4	1	27	G
041	TILX 199067 R	A	4	1	27	G
042	DBUX 302766 R	B	4	1	27	G
043	TCBX 198257 R	A	4	1	27	G
044	TILX 199462 R	B	4	1	27	G
045	WCHX 030062 R	B	4	1	27	G
046	UTLX 210649 R	A	4	1	27	G
047	TCBX 198147 R	A	4	1	27	G
048	CTCX 731722 R	B	4	1	27	G
049	TILX 198350 R	B	4	1	28	G
050	TILX 194940 R	A	4	1	28	G
051	TILX 197761 R	B	4	1	28	G
052	CTCX 731432 R	A	4	1	28	G
053	TILX 198216 R	A	4	1	28	G
054	TILX 198282 R	A	4	1	28	G
055	TILX 194948 R	A	4	1	28	G
056	TILX 198035 R	A	4	1	28	G
057	TILX 192027 R	A	4	1	28	G
058	DBUX 302744 R	B	4	1	28	G
059	DBUX 302714 R	A	4	1	28	G
060	TILX 198364 R	B	4	1	28	G
061	TILX 195238 R	A	4	1	28	G
062	CTCX 732482 R	A	4	1	28	G
063	DBUX 300569 R	B	4	1	28	G
064	TILX 199980 R	A	4	1	28	G
065	WCHX 030063 R	A	4	1	28	G
066	TCBX 197606 R	B	4	1	29	G
067	TEIX 030133 R	B	4	1	29	G
068	TILX 198681 R	B	4	1	29	G
069	TILX 194336 R	A	4	1	29	G
070	DBUX 302767 R	A	4	1	29	G
071	TILX 199160 R	A	4	1	29	G
072	CTCX 731749 R	B	4	1	29	G
073	TCBX 198126 R	A	4	1	29	G

Sequence numbers 30 through 40 were derailed as follows:  
30 - active fire, breached, severely buckled, listing about 10 degrees  
31 - active fire, overriding  
32 - burned, breached  
33 - burned, breached, listing about 22 degrees  
34 - burned, upright  
35 - A-end, end crushed (no apparent penetration)  
36 - burned, breached, listing about 22 degrees  
37 - A-end, B-end, derailed, upright  
38 - A-end, B-end, derailed, listing about 22 degrees  
39 - A-end, B-end, derailed, upright  
40 - B-end (lead truck), derailed, upright

Sequence numbers 41 through 100 were not derailed.

074	TCBX 197631 R B	4	1	29	G
075	TILX 320122 R B	4	1	29	G
076	DBUX 300858 R A	4	1	29	G
077	TILX 198558 R B	4	1	29	G
078	SHPX 208992 R A	4	1	29	G
079	TILX 195016 R A	4	1	29	G
080	TILX 198660 R B	4	1	29	G
081	CITX 220196 R A	4	1	29	G
082	SHPX 208987 R B	4	1	29	G
083	TILX 198279 R B	4	1	30	G
084	TILX 197582 R B	4	1	30	G
085	TILX 195097 R A	4	1	30	G
086	CTCX 731430 R B	4	1	30	G
087	TILX 198160 R A	4	1	30	G
088	TCBX 198183 R A	4	1	30	G
089	TILX 199577 R A	4	1	30	G
090	TILX 199545 R B	4	1	30	G
091	TCBX 199295 R A	4	1	30	G
092	TAEX 001134 R B	4	1	30	G
093	TAEX 001187 R A	4	1	30	R
094	TCBX 198191 R B	4	1	30	G
095	DBUX 208809 R A	4	1	30	G
096	TILX 199808 R B	4	1	30	G
097	TILX 199176 R B	4	1	30	G
098	TILX 193912 R B	4	1	30	G
099	DBUX 302126 R B	4	1	30	G
100	MP 718012 R A	4	1	30	G

-  
End Of Train Equipment  
NONE.  
-

END OF REPORT