

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering
Materials Laboratory Division
Washington, D.C. 20594



May 22, 1996

METALLURGIST'S FACTUAL REPORT

Report No. 96-57

A. ACCIDENT

Place : Aliquippa, Pennsylvania
Date : September 8, 1994
Vehicle : Boeing 737-3B7, N513AU
NTSB No. : DCA94-M-A076
Investigator : Thomas A. Haueter

B. COMPONENTS EXAMINED

Three bundles of wires identified as follows:

1. Box 453, E1-2, WB891/W007, D5923;
2. Removed from Box 000422, Crate #35;
3. Removed from Box 533.

C. DETAILS OF THE EXAMINATION

The following party representatives and NTSB specialists participated in an examination of the components on January 1, 1996, at the Safety Board Materials Laboratory in Washington, D.C.:

D. Bruce Skoropinski	Boeing
David M. Haselman	Boeing
Joseph Packingham	USAir
Jeffrey M. Rich	FAA
James F. Wildey II	NTSB, National Resource Specialist - Metallurgy
Merritt M. Birky	NTSB, Toxicology, Chemistry & Fire Science
Vincent M. Giuliana	NTSB, Electrical Engineer
Jean Bernstein	NTSB, Metallurgist

DEPOSIT ANALYSIS

An overall view of the wire bundle listed as No. 1 in the component examined list is shown in figure 1. The plug denoted by arrow "1a" in this figure was heavily damaged and the internal pins were partially exposed. Close up views of this plug are shown in figures 2 and 3. No evidence of blue and/or green color deposits were found on this bundle with the exceptions noted below.

I. **Turquoise colored chunky substance in the plug interior** (see arrow "c" in figure 2). A small portion of this substance was analyzed using a scanning electron microscope (SEM) equipped with an X-ray energy dispersive spectrometer (EDS) system. The EDS analysis produced spectra containing the characteristic peaks of carbon (C), oxygen (O), silicon (Si)¹, magnesium (Mg), aluminum (Al), chlorine (Cl), potassium (K), calcium (Ca), fluorine (F) and iron (Fe). The spectrum is shown as SAMPLE 1 in Appendix.

II. **Turquoise colored fibers adjacent to a plug mounting screw** (see arrow "d" in figure 3). The EDS analysis of a sample of these fibers produced spectra containing the characteristic peaks of silicon (Si), oxygen (O), phosphorus (P), calcium (Ca), carbon (C), magnesium (Mg), aluminum (Al), sulphur (S), potassium (K), barium (Ba), and zinc (Zn) and possibly sodium (Na)². The spectrum is shown as SAMPLE 2 in Appendix.

The plug denoted by arrow "1b" in figure 1 was relatively intact. A close up view of this plug is shown in figure 4. Numerous areas of the external surface of the plug were covered with loose brown deposits of what appeared to be a dried and compacted soil. At some locations, green fibrous material, similar in appearance to the fibers found adjacent to the connecting screw in plug "1a" was embedded into the soil (see arrow "e" in figure 4). EDS analysis of a sample of these fibers produced spectra containing the characteristic peaks of C, O, Mg, Al, Si, S, K, Ca, Fe, Zn, Ba, and possibly Na (see spectrum for SAMPLE 3 in Appendix). Similar fibrous deposits were found in the threads on one side of the connector (see arrow "f" in figure 4). The EDS analysis of these deposits produced spectra containing the characteristic peaks of C, O, Na, Mg, Al, Si, P, S, K, Ca, Zn, Cd, Ba (see spectrum for SAMPLE 4 in Appendix).

A piece of distorted aluminum bracket was attached to plug "1b" (see arrow "i" in figure 4). Blue colored areas were noted on the white painted surface of the piece. The opposite surface of the piece was unpainted and also contained some areas of bluish discoloration. Small chips of the paint containing blue stain were removed for EDS analysis. The EDS analysis of white (not stained) areas of the paint on the chips produced spectra containing the characteristic peaks of C, O, Na, Al, Si, P, S, Cl, Ca, and Ti (see spectrum for SAMPLE 5W in Appendix). The EDS analysis of blue regions of paint produced spectra containing the characteristic peaks of C, O, Na, Al, Si, P, S, Cl, Ca, and Ti (see spectrum for SAMPLE 5B in Appendix).

Examination of the wire sheathing material revealed that the outside layer of the fibers was colored green, whereas the interior fibers were colored white. A small sample of the sheathing material was obtained from the location denoted by arrow "g" in figure 4. The EDS analysis of this sample produced spectra containing the characteristic peaks of C, O, F, Na, Mg, Al, Si, P, S, Cl, K, Ca, Ti, and Cd (see spectrum for SAMPLE 6 in Appendix).

¹When listing elemental composition, elements with major peaks will be underlined.

²Sodium K-peak coincides with an L-peak for zinc.

An exemplar plug containing the "Blue Water" deposits was submitted by Boeing for comparative analysis. The EDS analysis of a sample of these deposits produced a spectrum containing the characteristic peaks of C, O, Na, Mg, Al, P, Si, S, Cl, K, and Ca (see spectrum for SAMPLE 7 in Appendix).

Three additional samples for EDS analysis were obtained from the aluminum bracket piece attached to plug "1b".

Blue-green color deposit from the edge of white paint

The analysis of this deposit produced the characteristic peaks of C, O, Mg, Al, Si, P, S, CL, Ca, Cd, Ti, and Cr (see spectrum for SAMPLE8-1 in Appendix.)

Light green color deposit from the area of the bracket that had not been painted

The analysis of this deposit produced the characteristic peaks of C, O, Ca, Mg, Al, Si, P, S, Cd, Ca, Ti, and Cr (see spectrum for SAMPLE 8-2 in Appendix).

Two samples of a light blue color deposit from the painted surface

The analysis of the first sample produced a spectrum containing the characteristic peaks of C, O, Ca, Na, Mg, Al, Si, P, S, Cl, Cr, and Fe (see spectrum for SAMPLE8-3A in Appendix).

The analysis of the second sample produced a spectrum containing the characteristic peaks of C, Ti, Al, Si, P, S, and Cl (see the spectrum for SAMPLE8-3B in Appendix).

CONNECTOR "1b" IDENTIFICATION AND DAMAGE

The wires on one side of connector "1b" contained a tape that identified the component as a "D05923J" connector. The "J" at the end of the identification reportedly indicates the side of a connector that is attached to a rack. The "J" side of the connector contained the part number TRW MS24265R16. The opposite side of the connector was expected to be "D05923P", with the "P" indicating the instrument side.

The bracket piece with the blue-green stain was removed from the D05923J/P connector indicated by "1b" in figure 1. One corner of the square mounting plate on the "J" side of the connector was broken off. In general, the connector was in relatively good condition. However, it was noted that the "J" connector clamp end and threaded portion was crushed over a distance of about 0.5 inch.

ELECTRICAL TESTING OF THE D05923J/P CONNECTOR

The wires on the "P" side of the connector were cut about 8 inches from the connector. The wires on both sides of the connector were then spread apart to electrically separate the wires. The connector was determined to be a 24-pin connector, and examination of the back sides of both connector halves showed that each wire entry point cavity was filled with either a wire or a nylon filler rod. On the "P" side of the connector, wires entered positions "1", "2", "3", "6", "7", "10", "11", and "18" through "23". On the "J" side of the connector, wires entered

positions "1" through "14" and "18" through "23".

~~The resistance between each wire on one side of the connector and each wire on the~~ opposite side was measured by applying 500 volts DC across wire pairs. These measurements showed zero resistance across wire pairs of the same number and a resistance of at least 10^{11} ohms between all pairs with different numbers. The testing revealed an intermittent short (zero ohms) between wires "21", "22", and "23" and the case of the connector. It was noted that the side of the connector with these three wires contained the greatest amount of mechanical damage.

A 1500 volt dielectric test (using 60 hz AC) of 10 second duration was conducted between wire pairs that were adjacent to each other in the connector. The testing instrument indicated a "MAX CURRENT 23V" failure between wires "1" and "2", and a "0 CURRENT" failure between wires "2" and "3". All other wire pairs passed the dielectric test.

A handwritten signature in black ink, appearing to read 'Jean Bernstein', is written over a solid black rectangular redaction box.

Jean Bernstein
Metallurgist




Figure 1. Overall view of one of the wire bundles. Arrows "1a" and "1b" denote the plugs.




Figure 2. Close-up view of the plug denoted by arrow "1a" in figure 1 showing the turquoise color chunky substance in the plug interior by arrow "c".




Figure 3. Another view of the plug denoted by arrow "1a" in figure 1, showing the turquoise color fibers adjacent to the mounting screw by arrow "d".





Figure 4. Close-up view of the plug denoted by arrow "1b" in figure 1, showing the locations of samples for the EDS analysis by arrows "e", "f", "g", and "i".

APPENDIX

Spectrum: SAMPLE1

Range: 20 keV


Total Counts=650399. Linear US=1000



Spectrum: SAMPLE2

Range: 20 keV


Total Counts=71885. Linear US=100



Spectrum: SAMPLE3

Range:20 keV


Total Counts=133742. Linear US=2000



Spectrum: SAMPLE4

Range:20 keV


Total Counts=159713. Linear US=200




Spectrum: SAMPLE5W

Range: 20 keV

Total Counts=106869. Linear US=100%




Total Counts=112282. Linear US=100



Spectrum: SAMPLE6

Range: 20 keV


Total Counts=66493. Linear US=100



Spectrum: SAMPLE7

Range: 20 keV


Total Counts=170592. Linear US=200



Spectrum: SAMPLE8-1

Range: 20 keV


Total Counts=788555. Linear US=10000



Spectrum: SAMPLE8-2

Range: 20 keV


Total Counts=433532. Linear US=500



Spectrum: SAMPLE8-3A

Range: 20 keV

Total Counts=675112. Linear US=1000



Spectrum: SAMPLE8-3B

Range: 20 keV

Total Counts=158147. Linear US=20

