## Malinowski Edward

From: Sent: To: Subject: Attachments: Dan Schiffer Monday, October 29, 2012 9:48 AM Malinowski Edward N217RK Sept. 17 2011 accident image.jpeg; ATT100039.txt; 59D5A476-6761-43DF-8705-73673025B489.pdf

## Mr. Malinowski,

I may have previously sent this to you, if so I apologize for the duplication.

The fuel receipts show I filled the tanks twice on the day of the accident, last fill up was just prior to my accident flt. and that flt lasted only 57 minutes verified by the GPS that was installed in the plane's dash during the flt. Also I was flying in formation four other T6's. I flew up from Mason (KTEW) and joined the flt over Alma bound for Hatfield's event. My T6 left KTEW Mason Jewett Field with 110 gallons on board. (55 in left & 55 in rt). 57 minutes of flt at 1/2 gallon per minute would have left 78.5 gallons of which I saw on fuel flow gage at startup, less 2 for start & taxi just prior to takeoff, less 2 for takeoff at full power and minimum fuel on board at engine failure would have been 19.5 left tank and 55 right tank. Anything less than that would have occurred after the engine failure and resulting crash. The engine driven fuel pump puts out 200 gallons per hour and the fuel pressure relief valve keeps the fuel pressure between 3.5 & 4.2 psi. To properly test the pressure relief valve after the accident the fuel lines would need to be intact to create their normal system and a pump putting out 200 gallons per minute cycling fuel thru the lines would be required. Simply energizing the pump to see if it pumps fuel only tests the pump not the pressure relief valve. I have always believed the cause of the engine failure to be the pressure relief valve and that remains my belief today. In the 10 months prior to the accident I had a failure while on the ground of the pressure relief valve and we actually went thru several overhauled units before getting one that worked properly. I hadn't had any issue with the pressure relief valve in the most recent months leading to the accident but the low pressure light came on seconds before the engine quit, exactly like it would had the low pressure relief valve failed. I know I had plenty of fuel on board and in the tank selected for flight.

Please see the Garmin 396 readout of my route indicating 57 minutes of flight time from fuel tank filling to destination. Also please see attached PDF file copy of both my fuel fill up receipts that day. Thank you

Dan Schiffer

Ful bought on day Raccident 2 tanks Rt = 1ft 55 galo EAch = 110 total I Never consider more than 106 useAble MASON JEWETT MASON JEWETT MULTI SERVICE TERMINAL I would have Merchant 12876 MULTI SERVICE TERMINAL Merchant 12876 had & least Batch 101575-002 Invoice 102911 Batch 101573-001 23.5 gal Remaining Invoice 102906 AUTH CODE AUTH CODE I left tank after 09/17/11 - 14:28:15 09/17/11 - 09:09:30 57 Min FH : CARD: American Express ACCT#: \*\*\*\*\*\*\*\* CARD: American Express less gal for taki ACCT#: \*\*\*\*\*\*\*\*\* TAIL#: 217 23.5 Remaining TAIL#: 217 The To over the PUMP: 1 (2) wusable PRODUCT: 4 [ 4 ] PUMP: PRODUCT: 4 [ 4 ] LAST 18 YEARS has burned 21,5 USEAble AVGAS 100LL AVGAS 100LL An Average of 30 gallows Remaining QUANTITY: 22. 470 GI PRICE/UNIT: \$ QUANTITY: 60.380 GL Pes hour or Egallon PRICE/UNIT: \$ TOTAL COST: \$ TOTAL COST: \$ PER Minute. THANK YOU FOR YOUR BUSINESS THANK YOU FOR YO HAVE A SAFE FLIGHT 2wd Fit I FIEW 57 Minutes HAVE A SAFE This was also a FROM KTEW - 397 Which fill up and again I Reset the metas to 110 sal. This was A Fill up and I set Fuel meter is the identifies Airport within A couple miles of HAT Field. 57 x.5= 28,5+3 For The. 55 gal - 31.5 = 23,5 REALING IN AT TANK

GPSmap 396

## GARMI

GPS	Date	Route Of Flight	Hours
Weather	17-SEP	KTEW-39Z	1.0
XM	17-SEP	2H4-KTEW	0.5
Flights	17-SEP	KTEW-2H4	0.6
Route	11-SEP	65G-KTEW	0.2
Points	11-SEP	KTEW-65G	0.7
Track	28-AUG	KPTK-KTEW	0.5
Aircraft	28-AUG	KPTK (Local)	0.3
E6B	And a state of the second s	KTEW-KPTK	0.8
Alarms			1
Calendar	Last Flight	00:57:50	