



# National Transportation Safety Board

Sinking of Cargo Vessel *El Faro*  
Atlantic Ocean, Northeast of Acklins and  
Crooked Island, Bahamas  
October 1, 2015




# National Transportation Safety Board


## Recovery of *El Faro's* Voyage Data Recorder

Brian Curtis


Director, Office of Marine Safety



Proposed Search Areas for El Faro VDR/Mast (NTSB Draft, 3-18-2016)



# El Faro Wreckage Map



# Organizations Assisting in VDR Recovery

- Department of the Navy
  - Supervisor of Salvage and Diving
  - Military Sealift Command
- United States Coast Guard
- American Bureau of Shipping
- National Oceanic and Atmospheric Administration
- National Science Foundation
- Woods Hole Oceanographic Institution
- TOTE Services, Inc.
- University of Rhode Island
  - Inner Space Center



# National Transportation Safety Board

Sinking of Cargo Vessel *El Faro*  
Atlantic Ocean, Northeast of Acklins and  
Crooked Island, Bahamas  
October 1, 2015

Brian Young  
Investigator-in-Charge



# National Transportation Safety Board

## Accident Overview Sinking of Cargo Vessel *El Faro*

Brian Young  
Investigator-in-Charge



# Investigation

CV El Faro  
Dive 02  
CURV 21  
USN SUPSALV





# National Transportation Safety Board

## Accident Narrative: Sinking of Cargo Vessel *El Faro*

# On Scene Team

- Board Member Dinh-Zarr
- Office of Marine Safety
- Office of Research and Engineering
- Office of Highway Safety
- Office of General Counsel
- Office of Chief Information Officer
- Office of Safety Recommendations and Communications
  - Transportation Disaster Assistance Division
  - Government Affairs
  - Media Relations



# Investigation Team

- Brian Young – Investigator-in-charge/Engineering
- Eric Stolzenberg – Naval architecture
- Michael Kucharski – Nautical operations
- Carrie Bell – Human factors
- Mike Richards – Meteorology
- Jon Furukawa – Survival factors
- Doug Mansell – Voyage data recorders
- Sean Payne – Voyage data recorders
- Charlotte Cox – Writer/editor

# Staff that Supported Team

- Monica Mitchell – Writer/editor
- Andrew Ehlers – Writer/editor
- William Tuccio – Voyage data recorders
- Chris Babcock – Voyage data recorders
- Dennis Crider – Vessel stability
- Xiaohu Liu – Cargo lashing analysis
- Loren Groff – Research and engineering
- Greg Smith – Research and engineering

# Staff that Supported Team

- Katherine Chisom – Family assistance
- Stephanie Matonek – Family assistance
- Alice Park – Animation
- Carl Schultheisz – Animation
- Christy Spangler – Vessel graphics
- Ed Kendall – General counsel
- Peter Knudsen – Media relations

# Parties to the Investigation

- United States Coast Guard
- TOTE Services
- American Bureau of Shipping
- National Weather Service
- Herbert Engineering
- Palfinger Marine

# Investigation

- Interviews
- Document collection / review
- Marine Board of Investigation hearings
- Independent analytical reports





# Investigation – *El Yunque*



# Safety Issues

- Loss of propulsion
- Flooding in cargo holds
- Downflooding through ventilation closures
- Need for damage control plan
- Lack of suitable survival craft
- Late decision to muster the crew

# Safety Issues

- Inadequate company oversight
- Company's safety management system
- Ineffective bridge resource management
- Use of noncurrent weather information
- Captain's actions

# Other Issues

- Alternate Compliance Program
- Voyage data recorders
- Expanded use of automatic identification system

# Presentations - Morning

Engineering factors

Brian Young

Flooding of cargo holds

Eric Stolzenberg

Damage control and stability information

Michael Kucharski

Survival factors

Jon Furukawa

# Presentations - Afternoon

Electronic data

Sean Payne

Onboard weather information and  
weather reporting from vessels

Mike Richards

Human performance factors

Carrie Bell

Captain's decision-making and actions

Michael Kucharski



# National Transportation Safety Board

## Engineering Factors

Brian Young  
Investigator-in-Charge

# Overview – Engineering Factors

- Vessel history
- Major conversion
- Inspections
- Exclusions
- Loss of propulsion





# National Transportation Safety Board

## Vessel History

Brian Young  
Engineering Group Chairman

# El Faro



© Allen Baker  
MarineTraffic.com

# Major Conversion Determination

- Major vessel conversions:
  - Substantially alter stability characteristics, dimensions, or carrying capacity of vessel
  - Change the type of vessel
  - Substantially prolong the vessel's service life
- Major conversions require the vessel to be updated to current safety standards

# Major Conversion Determination

- *El Faro's* lengthening in 1993 was a major conversion
  - Added 90-foot mid-body section
- *El Faro's* conversion from Ro/Ro to Ro/Con in 2005-2006
  - Added capacity for 1,414 containers
  - Increased draft/lowered freeboard over 2 feet
- After request for reconsideration from company, Ro/Con modification not designated as a major conversion



# National Transportation Safety Board

## Alternate Compliance Program

Brian Young  
Engineering Group Chairman

# Alternate Compliance Program



- *El Faro* enrolled in ACP since 2006
- ACP avoids redundancies in Coast Guard and authorized classification society (ACS) inspections and surveys
- Coast Guard issues Certificate of Inspection (COI) after ACS verifies compliance with applicable standards
- “US supplement” bridges gap between Coast Guard and ACS standards
- Annual Coast Guard oversight examinations of ACP vessels to confirm ACSs are enforcing compliance

# Alternate Compliance Program

- No qualification level required and no formal training program for the Coast Guard ACP examiners
- Communications between Coast Guard and ACSs lacking
- Lack of resources to complete “US supplement” reviews
- Review of targeted ACP vessels that had successfully completed ACS surveys found safety deficiencies; lacked deficiency records



# National Transportation Safety Board

## Exclusions

Brian Young  
Engineering Group Chairman



# Exclusions

- Not factors in accident:
  - Boilers, steering, and electrical systems
  - Riding gang
  - Medical conditions and medication use
  - Structural failure
  - Rogue wave

# Exclusions

- Not factors in initial list of vessel:
  - Lashing failure
  - Cargo shift
- Insufficient evidence to determine:
  - Fatigue
  - Drug or alcohol use



# National Transportation Safety Board

## Loss of Propulsion

Brian Young  
Engineering Group Chairman

# Loss of Propulsion

0440/0513 – Chief Engineer reported oil levels affected by list

0554 – Captain turned *El Faro* to port


After 0600 – Vessel began losing speed

0616 – Bridge notified of loss of propulsion


# Lube Oil System



# Lube Oil System



# Lube Oil System




# Design Standards



Extreme list to port




# Design Standards



18° list to port – looking forward

# Oil Level in Sump





25" = 1,255 gallons

26" = 1,346 gallons

27" = 1,436 gallons

# 18° List to Port



# Summary – Engineering Factors

- Findings
- Recommendations



# National Transportation Safety Board

## Flooding of Cargo Holds

Eric Stolzenberg

Naval Architecture Group Chairman


# Overview

- Increasing seas and waves, resultant windheel
- Flooding sources
- Car lashings
- Bilge pumping
- Bilge high-level alarms in cargo holds
- Watertight hatch open/closed indicators
- Cargo hold ventilation closures
- Hull wreckage examination

# Increasing Seas


- Seas increase rapidly after 0130
- Over 7 meters (23 feet) by 0300
- Build to 9 meters (30 feet)
- Wave period of 11 seconds

**Analysis of Post-Storm (Hindcast Data) Sea/Weather Models Along *El Faro's* Track**




# Sustained Windheel

- Increasing winds after 0200 on vessel's port beam
- Wind near 70 knots by 0400
- Effect: increasing and sustained heel (windheel) to starboard
- Hydrostatic analysis shows heel from 5° to 8° for winds 60 to 80 knots on beam






# Watertight Deck



- Boarding seas (green water) was known to enter onto 2<sup>nd</sup> deck in past
- Partially enclosed 2<sup>nd</sup> deck was watertight

# Dynamic Analysis



# Downflooding from Watertight Scuttle (Deck Hatch)

- Hold 3 was flooding at 0543 per VDR
- Small watertight deck hatch (scuttle) to cargo hold 3 on second deck was open
- Open scuttle allowed downflooding through ship's watertight envelope




# Unsecured Scuttle to Hold 3

- Crew did not know when or how scuttle to hold 3 opened
- If bridge had open/close indicator, crew would have known scuttle was open



*El Faro Scuttle*

# El Faro Cargo Hold 3



# Cargo Hold 3 Tanktop (4<sup>th</sup> Deck)

Supply Ventilation  
Trunks (Upper)


Hold  
2A

Lower Supply  
Ventilation Trunk

*El Yunque Hold 3*

# Automobile Lashings in Hold 3

- Automobile lashings did not conform to cargo-securing manual
- Cars were more likely to shift during heavy weather



*El Yunque Hold 3 Car Lashings*


# Flooding Effect on Car Lashings

- Adverse effects:
  - Small amount of water decreases friction
  - Rising water begins to float cars
  - Mass of sloshing water acts on cars
- Crew said cars were loose
- Water plus vessel's motion loosened cars



# Seawater Inlet Piping to Emergency Fire Pump

- Cars loose in hold 3 at 0544
- Bilge pumps already running
- Scuttle secured about 0600, but hold 3 still flooding
- Piping to fire pump possible source of flooding
- Loose cars could have struck piping to fire pump



# Hold 3 Flooding Effect

- Damaged piping potentially flooded hold 10% to 20% by 0716
- MSC hydrostatic analysis
  - Beam-to 80-knot wind after loss of propulsion
  - Hold 3 flooded 10% to 30%
  - Rolling about sustained windheel
  - Vessel susceptible to capsizing
- Damage to seawater piping in hold 3 most likely led to flooding in the hold, which significantly compromised vessel's stability

# Bilge Pumping

- Two bilge wells per cargo hold (port and starboard)
- Bilge system operated continuously from at least 0544
- Flooding in hold 3 exceeded design capacity of bilge pumps
- Water level continued to rise despite pumping



*El Yunque Bilge Well, Hold 3*


# Bilge Alarm System

- Visible and audible alarms in engine room only
- Hold 3 alarms typically investigated by engineering watch
- No evidence of how flooding in hold 3 detected
- Discussion on VDR of hold 2A alarm
- Crew most likely alerted to water in hold 3 by bilge alarm system



# Bilge Alarm Requirements

- Alarms quickly identify flooding
- Alarms not required on cargo vessels
- Cargo vessels should be equipped with bilge alarms

# Cargo Hold Ventilation System



# Cargo Hold Ventilation System




# Cargo Hold Ventilation Closures



- Ventilation closures most likely remained open throughout sinking
- COI required ventilation of holds at sea
- Intact and damage stability standards consider ventilation openings to be closed
- Vessels should not have conflicting requirements



# Cargo Hold Ventilation Downflooding




# Examination of Wreckage





NTSB



NTSB

# Summary – Flooding of Cargo Holds

- Findings
- Recommendations



# National Transportation Safety Board

## Damage Control and Stability Information

Michael J. Kucharski  
Nautical Group Chairman

# Overview

- Damage control plan and booklet
- Stability book
- Computer program damage stability module

# Damage Control Information

- Clear information on ship's watertight subdivision
- Equipment related to maintaining boundaries and effectiveness of subdivision
- Proper precautions to take to prevent progressive flooding through openings
- Effective action that can be taken to quickly mitigate and, where possible, recover ship's loss of stability



# Damage Control Plan and Booklet

- Ship's watertight boundaries
- Means to correct list



# Damage Control Plan and Booklet Information

- Watertight and weathertight closures
- Pump capacities and piping diagrams
- Advice to master to obtain shore assistance
- Visual guidance to master

# Damage Control Plan and Booklet

- Assist in planning for and addressing flooding
- All cargo vessels should have
- Classification societies should review and approve
- Available from computer software

# Damage Control Module to CargoMax

CargoMax 1.21.0203 (01 Jun 2010) - Transference used

File View Entry Results Help

Emergency Response Calc Define Run Calc Print Quit DamStab

Profile/Plan

111.824A-looking fwd

Draft/Displacement Summary Free-Floating Damaged

		Free-Floating Draft / Displacement Data		
		Intact Direct	After Outflow	Damaged
Draft at FP	m	3.467		3.467
Draft at AP	m	8.142		8.142
Trim	m	4.675A		4.675A
Draft at Fwd Marks	m	3.492		3.492
Draft at Aft Marks	m	7.970		7.970
Static Heel Angle	deg	0.0		0.0
Total Weight	MT	20,657	20,657	20,657
VCG	m	8.290	8.290	8.290
LCG	m-FP	125.222A	125.222A	125.222A
TCG	m-CL	0.000	0.000	0.000
Buoyancy	MT	20,657		20,657
KB	m	3.474		3.474
LCB	m-FP	125.326A		125.326A

Righting Arm

Heel Angle(deg)

Calc Points GZ Curve Equil+20 DF Angle

No Criteria	Units	Available
Static Heel Angle	deg	0.0
Freeboard to Margin Line	m	---
Freeboard to Downflooding	m	---
Angle at Maximum GZ	deg	37.7
Maximum GZ	m	3.264
Range of Positive GZ	deg	>60.0
Initial GM	m	6.328

Strength Summary

Values Shear & Moment % of Allowables

Interpolate Allowables

Shear and Moment

Shear (MT)/10<sup>3</sup> Moment (m-MT)/10<sup>5</sup>

Shear Allowable (MT)/10<sup>3</sup> Moment Allowable (m-MT) / 10<sup>5</sup>

start CargoMax for SS B.F... CargoMax 1.21.0203... 8:46 AM

# Stability Book

- Must contain sufficient information to master
- Unintentional flooding and operation during emergency situations to be “considered”

INSTRUCTIONS FOR ROLL-ON/ROLL-OFF  
VESSEL TRIM AND STABILITY

Page 6

**Objective:** This booklet has been prepared to enable operating personnel to determine the vessel's operating metacentric height (corrected GM) and drafts for any condition of loading or operation. The instructions contained herein are intended to aid personnel in using this booklet and to provide the necessary operating information of maintaining satisfactory stability.

**General:**

1. The Cargo conditions shown in this booklet represent any cargo loading having tonnages and vertical centers of gravity similar to those shown.
2. "The Minimum GM values given on Page 16 shall be adhered to at all times." ✓
3. It is further recommended that heavier trailers be loaded close to Amidships to reduce stresses in the hull girder.

**Instructions for Computation of Vessel's Stability & Trim:**

1. In calculating the vessel's trim and stability for each condition of loading, the detail weights in each category such as cargo, fuel oil, ballast and fresh water are entered in separate detailed loading tables (Pages 36-47) together with the vertical and longitudinal centers for each item. Appropriate free surface and VCG values for the settlers and for storage tanks containing consumable liquids which are not pressed up shall be entered from Appendix A, Variable Tank Data Tables for the major tanks included in the Appendix. The table on page 17 contains for all-consumable tanks the capacity and full condition values plus the maximum free surface value and the 98% full free surface value for fuel tanks. Information not contained in Appendix A can be found in the tank table on page 17. Settler tanks shall always have a "slack" free surface value. For tanks which are consumed during the voyage a free surface value shall be entered that results in a sum not less than the tank value, **which is largest, for each type of consumable liquid onboard.** This requirement will allow use of the vessel's tankage in any order desired without undetected low stability due to free surface occurring at any time during the voyage. (See Routine Operating Instruction No. 1). All other 98% full fuel oil tanks shall have 98% - 5 degree heel free surface entered for them. In the separate detail loading tables, each category is summed with respect to tonnage, vertical moment, longitudinal moment and free surface. (Moment is the product of tonnage by center of gravity distance for each item).

1252-700-602

NOTED AS PART  
Rev E  
EQUIPMENT  
016  
MAY 31 2007  
**ABS**  
HOUSTON

# Stability Book

- VDR crew statements relating to:
  - The vessel “hanging” to one side
  - The sail area of the vessel
  - The angle at which downflooding would occur on the vessel

# Stability Book

- The stability book did not identify:
  - Downflooding points
  - The angle of downflooding
  - Windheel criteria information and unintentional flooding due to list
- These items would have been useful for decision-making

# Summary – Damage Control and Stability Information

- Findings
- Recommendations





# National Transportation Safety Board

## Survival Factors

R. Jon Furukawa  
Survival Factors Group Chairman

# Overview

- Search and rescue (SAR)
- Position formatting (latitude/longitude)
- Emergency position indicating radio-beacons (EPIRBs)
- Personal locator beacons
- Survival craft requirements

# Search and Rescue (SAR) – Coast Guard

- Critical to get assets on scene
- Joaquin prevented search and rescue efforts for two days
- During first two days, Coast Guard positioned assets





## Assets Utilized During Search Efforts



# SAR Position Formatting Error

<u>Source</u>	<u>Format</u>	<u>Position</u>
Inmarsat-C	DD.MM	23.28N, 73.48W
Traditional	DD°MM'	23°28'N, 073°48'W
but SAROPS interpreted	DD.dd	23.28N, 73.48W
and converted to	DD-MM.mmm	23-16.800N, 073-28.800W <u>23 NM error</u>

# SAR Latitude/Longitude Formatting

<u>Source &amp; Format</u>		<u>Source Format</u>
Navigation	DD°MM.m'	23°28.0'N, 073°48.0'W
Inmarsat-C	DD.MM	23.28N, 73.48W
SSAS	DD:MM.mm	23:25.39N, 073:52.51W
USCG	DD-MM.mmm	23-28.000N, 73-48.000W

# Emergency Position Indicating Radio-Beacon (EPIRB)

- Automatic alert
- Indicates location
- Float-free
- Automatic activation
- Detectable anywhere
- 406 MHz frequency
- Non-GPS or with GPS




# Emergency Position Indicating Radio-Beacon (EPIRB)

- *El Faro's* EPIRB
  - Detected at 0736
  - Location not determined
- GPS-enabled EPIRB – sends an accurate position with the first transmission
- *Lady Mary* accident in 2009
  - 6 of 7 crew perished
  - Delayed sending SAR assets




# Personal Locator Beacons (PLBs)

- Portable
  - Small manual EPIRB
- GPS input capable
- *Trinity II* accident in 2011
  - Crew evacuated
  - 3 days to rescue
  - Drifted 150 miles
  - 4 of 10 crew lost



# Personal Locator Beacons (PLBs)



# Survival Craft – Open Lifeboats

- 1980s: recognized as inadequate
- Does not protect crew from elements
- Not allowed on new vessels since 1986
- Allowed to remain if maintained



# Open Lifeboats



# Enclosed Lifeboats



Side-launched



Stern-launched Freefall

# Inflatable Liferafts



Stowed Liferafts



Inflated Liferaft

# Inflatable Liferrafts

- Survivors swim to liferaft through
  - Floating containers
  - Mountainous seas
  - Sea-foam from winds
- Then board liferaft

# Review of Regulatory Standards

- Major modification/conversion
  - Opportunities to update
- No modifications – no review
- Advances in lifesaving benefits crew



# Review of Regulatory Standards

- Average vessel lifespan is 20 to 30 years
  - El Faro was 40 years old
  - Open lifeboats superseded by enclosed 30 years ago
- To review and upgrade – 5 years or an important regulatory or class event
- Maximum 20 years to upgrade to new standards

# Summary – Survival Factors

- Findings
- Recommendations





# National Transportation Safety Board

## Electronic Data and Audio

Sean Payne

Electronic Data and Audio Group Chairman

# Overview

- Voyage data recorder (VDR) transcription issues
- Inadequate performance testing for VDRs
- Global maritime distress and safety system (GMDSS) user entered position errors
- Automatic identification system (AIS) emerging standards

# Voyage Data Recorder Audio Quality

- Poor audio quality prevented a complete transcription
  - Use of monoaural audio channels to record multiple microphones
  - Noise pollution
  - Microphone placement

# VDR Annual Performance Testing

- Inadequate annual performance testing
  - IMO definition of “normal operations” inadequate
  - Ability of VDR audio system to perform while the ship is underway at sea, using main source of propulsion

# Recording of Internal and External Ship's Communications


- Internal communications not recorded
  - Calls to/from engine room
  - Calls to/from the captain's stateroom
  - Calls to/from other portions of the ship
- External (VHF) communications not recorded
  - *El Faro* VHF radio recorded through ambient noise



# VDR Annual Performance Testing

- Expired locator beacon battery
- VDR capsule recovery hampered






# GMDSS Formatting Issues

- GMDSS – Global maritime distress and safety system
  - Inmarsat-C distress alert interface
  - User modifiable distress position
  - System does not update distress position at time of sending



# Expanding AIS – Benefits and Limitations

- Automatic identification system (AIS) can be overloaded with application specific messages (ASM)



# Expanding AIS – Frequency Allocation

- Effort to separate AIS and ASM messages under VHF data exchange system (VDES)
- VDES frequencies not allocated by United States
- Frequencies currently licensed by private corporation
- License will expire in 2018

# Summary – Electronic Data and Audio

- Findings
- Recommendations



# National Transportation Safety Board

## Onboard Weather Information Weather Reporting from Vessels

Mike Richards  
Meteorology Group Chairman

# Onboard Weather Information

- Primary sources of weather guidance:
  - SAT-C
  - BVS
- Different delivery methods
- Different formats
- Conflicting information on storm location



# SAT-C

IBC Message --- MET Navarea Warning or MET Forecast ---  
Message Sequence No. : 12704  
LES : Vizada (NDR)  
Priority : Urgent  
Size : 2191 characters  
Receive Date & Time : 16-10-16 20:46 (UTC)

Eik LES 16-OCT-2016 20:44:15 069791

NTNT25 KNHC 162043  
TCMAT5 ADW 2043

HURRICANE NICOLE FORECAST/ADVISORY NUMBER 51  
NWS NATIONAL HURRICANE CENTER MIAMI FL AL152016  
2100 UTC SUN OCT 16 2016

THERE ARE NO COASTAL WATCHES OR WARNINGS IN EFFECT.

HURRICANE CENTER LOCATED NEAR 39.7N 45.6W AT 16/2100Z  
POSITION ACCURATE WITHIN 30 NM

PRESENT MOVEMENT TOWARD THE NORTHEAST OR 45 DEGREES AT 8 KT

ESTIMATED MINIMUM CENTRAL PRESSURE 960 MB  
EYE DIAMETER 70 NM  
MAX SUSTAINED WINDS 70 KT WITH GUSTS TO 85 KT.  
64 KT..... 60NE 80SE 80SW 70NW.  
50 KT.....130NE 150SE 180SW 130NW.  
34 KT.....380NE 330SE 330SW 380NW.  
12 FT SEAS..480NE 660SE 960SW 720NW.  
WINDS AND SEAS VARY GREATLY IN EACH QUADRANT. RADII IN NAUTICAL  
MILES ARE THE LARGEST RADII EXPECTED ANYWHERE IN THAT QUADRANT.

REPEAT...CENTER LOCATED NEAR 39.7N 45.6W AT 16/2100Z  
AT 16/1800Z CENTER WAS LOCATED NEAR 39.4N 45.9W

FORECAST VALID 17/0600Z 40.5N 44.5W  
MAX WIND 65 KT...GUSTS 80 KT.  
64 KT... 60NE 80SE 80SW 70NW.  
50 KT...130NE 150SE 180SW 130NW.  
34 KT...400NE 360SE 360SW 420NW.


FORECAST VALID 17/1800Z 42.6N 42.5W  
MAX WIND 65 KT...GUSTS 80 KT.  
64 KT... 50NE 70SE 70SW 60NW.  
50 KT...130NE 150SE 160SW 110NW.  
34 KT...420NE 400SE 380SW 480NW.

FORECAST VALID 18/0600Z 46.3N 39.6W...POST-TROP/EXTRATROP  
MAX WIND 65 KT...GUSTS 80 KT.  
64 KT... 50NE 70SE 70SW 60NW.  
50 KT...130NE 140SE 120SW 90NW.  
34 KT...450NE 450SE 400SW 550NW.

FORECAST VALID 18/1800Z 51.3N 37.3W...POST-TROP/EXTRATROP  
MAX WIND 65 KT...GUSTS 80 KT.  
50 KT...130NE 130SE 80SW 60NW.  
34 KT...480NE 510SE 430SW 650NW.

FORECAST VALID 19/1800Z 59.6N 32.7W...POST-TROP/EXTRATROP  
MAX WIND 55 KT...GUSTS 65 KT.  
50 KT...120NE 240SE 05W 00NW.  
34 KT...360NE 400SE 420SW 600NW.


# BVS



# Onboard Weather Information

- BVS provided a storm position and forecast track 6 hours behind SAT-C
- Old storm information was due to processing limitations at the vendor
- Mitigation options were published by the vendor but not acted upon

# Onboard Weather Information Delay



# Weather Reporting from Vessels

- In June 2017, NTSB issued 10 recommendations to NOAA, National Weather Service, and the Coast Guard
  - Addressed tropical cyclone forecasting and weather products for mariners
  - Staff is currently reviewing addressee responses
- Additional findings regarding weather reporting from vessels at sea to improve mariner safety

# Summary – Weather Reporting from Vessels

- Findings
- Recommendations



# National Transportation Safety Board

## Human Performance Factors

Carrie Bell

Human Factors Group Chairman

# Overview

- Bridge resource management
- Company oversight
  - Safety management system
  - Training
  - Safety culture
- Coast Guard training
  - Bridge resource management
  - Meteorology



# Captain's Experience

- All officers were qualified and credentialed mariners
- Captain
  - 24 years of experience
  - 6 years with TOTE
  - In May 2014, named captain of *El Faro*
- Captain's responsibilities
  - Safe operation and navigation
  - Company's representative on board


# Officers' Experience

- Deck Officers
  - Captain, chief mate, second mate, third mate
- Experience
  - Deck: Employed at TOTE for over 10 years
  - Sailed primarily on same route
  - Chief mate was newest member of team
- Engineering Officers
  - Chief, 1st, 2nd, three 3rd engineers
  - Senior engineers 6–12 years experience with TOTE steam ships

# Opportunities to Change Course



# Passages Available along *El Faro's* Route



# Captain's Reluctance to Change Course

- Why did the captain not take action against the impending danger?
  - Experience
  - Normalization of risk
    - Experience can cloud judgement
  - Confirmation bias
    - Ignore information that conflicts with beliefs

# Crew's Reluctance to Challenge Captain

- Why did the crew not challenge the captain?
  - Confidence in his abilities
    - Reluctant to question
  - Hierarchical structure
    - Power distance
  - Poor implementation of BRM
    - Starts at leadership level

# Bridge Resource Management

- Effective BRM
  - Cohesive team
  - Manages risk and maintains shared mental model
  - Cooperatively monitors vessel progress
  - Acquires and exchanges information
  - Anticipates dangerous situations
  - Open environment to challenge



# Bridge Resource Management

- Power Distance
  - Unequally distributed power between officers
  - Can be created by hierarchy
  - Subordinates do not feel empowered to challenge
  - Often characterized by mitigated speech



# Bridge Resource Management Effectiveness

- Assertiveness
  - Challenging in a hierarchical environment
  - Fear of reprimand
  - Uncertain outcome of the situation
  - Reluctance to speak up

# Bridge Resource Management Summary

- Loss of situation awareness
  - Inability to have shared mental model
- Limited information passed between watch officers
- High power distance

# Company Oversight

- Preparing crew for heavy weather
- Monitoring ships at sea
- Shoreside communications with *El Faro*
- Training
- Assessment of officer performance

# Safety Management System

- Did not address securement of cargo
  - Lashings, watertight doors, and hatches
- Lack of heavy weather checklists
- Minimal guidance for preparing crew for heavy weather

# Safety Management System

- Communication with vessel during accident voyage was minimal
  - Two routine voyage messages
  - E-mail requesting change to northbound voyage
- Risk to vessel on this voyage was not addressed

# Safety Management System

- Bridge Resource Management
  - Quarterly BRM training required onboard
  - BRM section marked “deleted” in SMS
  - Company did not follow through to ensure training was completed

# Company Oversight

- No training department
  - Various training logged in separate departments
- Scenarios not specific to heavy weather
  - Shoreside drills did not include flooding
- Minimal accountability of work/rest records


# Company Oversight

- Evaluating officer performance
  - Measurement of competency
  - Incomplete performance evaluations
- Personnel files not comprehensive
  - No documentation of known issues
  - Statements from management not reflected
  - No background on resignation with previous employer



# Bon Voyage System (BVS) Training

- No requirement for formal training in weather information provided on bridge



# Safety Culture

- Oversight not adequate
- Ineffective training
- No support for storm avoidance and heavy-weather preparations
- No risk assessment

# Training

- Bridge resource management
  - Recurrent training
    - Updated concepts
    - Allow for lessons learned
  - Enhance course to include scenario-based training
- Advanced meteorology and shiphandling
- Captain was exempted

# Summary – Human Performance Factors

- Findings
- Recommendations



# National Transportation Safety Board

## Captain's Decision-making and Actions

Michael J. Kucharski  
Nautical Group Chairman

# Overview

- Decisions and actions
  - Leaving port
  - Original route
  - Sufficiency of weather information
  - Reliance on outdated information
  - Storm avoidance
  - Late mustering and abandoning ship

# Overview


- Tools to assist in decision-making
  - Stability instrument training
  - Rapid Response Damage Assessment training
  - Anemometer
  - Company support for storm avoidance and preparation

# Captain's Decisions and Actions


- Leaving port was reasonable
  - Low risk
  - Options available
- Original passage plan brought vessel into storm's path
- Vessel received sufficient weather information
- The captain did not use up-to-date weather information



# Routes from Jacksonville to San Juan



# Actual Track of *El Faro*



# Captain's Decisions and Actions

- Storm Avoidance
  - Brought vessel close to hurricane eye
  - Put crew in peril
- Late decision to muster and abandon ship
  - Events should have prompted mustering
  - Late mustering and abandoning reduced possible mitigation attempts and survival

# Tools to Assist in Decision-making

- Training for onboard tools – stability instrument and Rapid Response Damage Assessment (RRDA)
- Properly working anemometer
- Weather routing service

# Tools to Assist in Decision-making

- Training in the use of onboard tools
  - Stability instrument training
  - Rapid Response Damage Assessment Service (RRDA) training


# El Faro Anemometer Wind Sensors



# Tools to Assist in Decision-making

- Anemometer
  - Wind direction and shift are best guides to a storm's position and movement
  - Crew statements about “white out” conditions
  - *El Faro* did not have a properly functioning anemometer

# Locating the Low





# Tools to Assist in Decision-making

- Storm avoidance and heavy-weather support
  - Monitoring and contacting vessel
  - Providing contracted weather routing service
  - Heavy-weather support through dialogue and policy

# Summary – Captain's Decision-making and Actions

- Findings
- Recommendations

