



**NATIONAL TRANSPORTATION SAFETY BOARD**

**Office of Aviation Safety**

**Western Pacific Region**

**August 23, 2018**

**PROPELLER EXAMINATION**

**WPR17FA066**

**(2 Pages)**

**WPR17FA066**  
**Riverside, California**  
**February 27, 2017**  
**1641 PST**  
**Cessna T310Q – N1270P**

**EXAMINATION PARTICIPANTS**

**Stephen Stein**  
**Air Safety Investigator (IIC)**  
**National Transportation Safety Board**  
**Federal Way, WA**

**Mike Council**  
**Air Safety Investigator**  
**Continental Motors Group**  
**Mobile, Alabama**

**Christy Eckerman**  
**FAA Aviation Safety Inspector**  
**Federal Aviation Administration**  
**Wichita, Kansas**

**Danny Ball**  
**Air Safety Investigator**  
**Textron Aviation**  
**Wichita, Kansas**

**Jeff Janusz**  
**FAA Aviation Safety Inspector**  
**Federal Aviation Administration**  
**Wichita, Kansas**

**Ricardo Ascensio**  
**Air Safety Investigator**  
**Textron Aviation**  
**Wichita, Kansas**

**PROPELLER MODEL AND SERIAL NUMBERS**

Left Engine

Propeller Model No.: 3AF32C87-N1R/S-82NC-5.5

Propeller Serial No.: 804717

Blade 1 Serial No.: F15282YS

Blade 2 Serial No.: F43916YS

Blade 3 Serial No.: F64573YS

Right Engine

Propeller Model No.: 3AF332C87-NR/S-82NB-6

Propeller Serial No.: 757839

Blade 1 Serial No.: F11513YS

Blade 2 Serial No.: F11530YS

Blade 3 Serial No.: F11534YS

## **PROPELLER BLADES**

Both the LH and RH propeller hub socket plates displayed witness marks from contact with blade counterweight hardware during the accident sequence. The position of all these marks indicates an approximate propeller blade angle of low pitch position at impact.

The RH propeller was found with a sheared latch screw arrowhead, consistent with a piston near the low pitch stop at impact. The LH propeller showed a dent in the cylinder proximal to the feather end and the piston assembly was found outside the dented region near the low pitch stop position.

Both the LH and RH propeller blades exhibited bending, twisting pain scuffing, leading edge impact marks consistent with a mid-level rotational energy absorption.