

# CT scan data from Appareo package #2

# Experimental Details

- Two CT scans of Appareo package #2 were performed.
  - First CT scan with field of view (FOV) that covered the entire memory package (provided voxel size resolution of 37  $\mu\text{m}$ ).
  - Second CT scan zoomed in on  $\sim$  half the die with full row of wire bonds in FOV (provided voxel size resolution of 17 $\mu\text{m}$ ).
- CT scans were performed at 110 – 120 kV tube voltage, 110  $\mu\text{A}$  current, spot mode 0.
- Cu filter along with a collimator, was used during x-ray exposure.
- Total exposure time for two CT scans was  $\sim$  2.75 hrs.
- Defects within the package were identified and snap shots of such defects were taken along 3 axes (orthogonal planes)


# Summary and Conclusions

- Appareo package #2 contains 4 stacked dies, 2 on each side of the Cu paddle.
- Molding compound of this package, was found to be severely damaged probably from high-temp/fire. Such extreme heat/fire can also damage the chip circuitry.
- Widespread cracks, voids, separation areas, were detected in the entire mold compound.
- Most cracks seem to go through the mold thickness, and reach die top with circuitry. These exposed die areas could possibly have damaged the chip circuitry.
- Large areas of separation between mold and die top, were detected on both sides of the package. Some of these areas are close enough to wire bonds to cause their delamination /dislodging. Such wire defects could not be detected in the CT scan data due to resolution limitation and image artefacts created by high x-ray absorption Au wires.

# Low-mag CT data from side 1: 3D slice views

Frontal (x,z)

Frontal View



Cracks in the mold

Molding compound crack on surface appears to go down to the die top with circuitry

Wire bonds


Saggital View



This separation between mold/die top, is close to wire bonds to possibly dislodge/delaminate them.

Dense materials appear bright  
Light materials, voids/separation appear darker in CT snap shots.  
Notice red-cross hair on a defect in each slice image. These 3 slice views correspond to image of that defect in three axes.

Several cracks and separation areas are detected in the molding compound on both sides of the package



Axial View

ADL

Analytical and Diagnostics Laboratory

SIP


The Small Scale Systems Integration and Packaging Center

A New York State Center of Excellence



# Low-mag CT data from side 2: 3D slice views

Frontal (x,z) Slice 0.450628

Sagittal (y,z) Slice -0.202



Molding compound crack on surface goes all the way down to the die top with circuitry




Several cracks, and separation areas are detected in the molding compound on both sides of the package

# Low-mag CT data from side 1: 3D slice views


;) Slice -0.369

Fronta View



Sagittal (y,z) Slice 1.821

Saggital View



Mold compound separation too close to wire bonds, may dislodge the wire bonds and cause discontinuity



Wire bonds

Image artefacts



Axial View

Analytical and Diagnostics Laboratory




A New York State Center of Excellence


# Low-mag CT data from side 2: 3D slice views

Frontal (x,z) Slice 0.414

Sagittal (y,z) Slice -2.04162





Cross-hair indicating separation between molding compound and die top with circuitry



Other areas of such separation shown by arrows

# Higher-mag CT data, side 2: 3D slice views

Frontal (x,z) Slice 2.271



L

L




Axial (x,y) Slice 0.506

Cross-hair indicating separation/crack between molding compound and die top

Other areas of such separation/cracks shown by arrows

Higher-mag scan area




The and  
A Ne




# Higher-mag CT data, side 1: 3D slice views

Frontal (x,z) Slice 2.946




Original (y,z) Slice 0.000



L

L

Cross-hair indicating separation between molding compound and die top






Axial (x,y) Slice -0.381

Other areas of such separation/cracks shown by arrows

# Higher-mag CT data, side 1: 3D slice views

Frontal (x,z) Slice 4.20643

Sagittal (y,z) Slice 1.703




Axial (x,y) Slice -0.307569

Cross-hair indicating separation between molding compound and die top

Other areas of such separation/cracks shown by arrows

# Higher-mag CT data, side 2: 3D slice views

Frontal (x,z) Slice 2.185



Sagittal (y,z) Slice -3.205





Image artefacts because of high x-ray attenuation gold wires

Red cross-hair indicating separation between molding compound and die top

Other areas of such separation/cracks shown by arrows

Axial (x,y) Slice 0.492



# Summary and Conclusions

- Appareo package #2 contains 4 stacked dies, 2 on each side of the Cu paddle.
- Molding compound of this package, was found to be severely damaged probably from high-temp/fire. Such extreme heat/fire can also damage the chip circuitry.
- Widespread cracks, voids, separation areas, were detected in the entire mold compound.
- Most cracks seem to go through the mold thickness, and reach die top with circuitry. These exposed die areas could possibly have damaged the chip circuitry.
- Large areas of separation between mold and die top, were detected on both sides of the package. Some of these areas are close enough to wire bonds to cause their delamination /dislodging. Such wire defects could not be detected in the CT scan data due to resolution limitation and image artefacts created by high x-ray absorption Au wires.