Attachment 23

Operational Factors Group Chairman's Factual Report

DCA00MA030

PULL-UP Warning Escape Procedure

11.2.54 FAA Approved

Southwest Airlines
Flight Operations Manual

Non-normal Operations QRH 737-300/-500

ADDITIONAL INFORMATION/CONSIDERATIONS

PULL-UP WARNING

This procedure is accomplished anytime the "Whoop Whoop Pull-Up" aural warning sounds or the red GPWS Warning Light illuminates with no associated aural signal.

Speedbrakes must be retracted during the GPWS escape maneuver to maximize climb performance. Maximum thrust and a best angle climb should be used to achieve maximum altitude gain in minimum distance to ensure obstacle clearance. Best climb angle can be achieved by initially rotating the aircraft to approximately 15 degrees nose up and maintaining approximately 220 knots (in a clean configuration). Do not delay climb to achieve this airspeed, climb at present speed. If above this airspeed, excess airspeed may be traded for additional climb performance, however, do not allow airspeed to drop below best climb speed.

If a warning occurs when flying in Day and VMC conditions, and positive visual verification is made that no ground contact hazard exists, the alert may be regarded as cautionary and the approach/cruise may be continued.

D-2

Rev 1-98

Mar 13-98



Non-normal Operations QRH 737-300 -500 Southwest Airlines Flight Operations Manual 11.2.55 FAA Approved

PULL UP WARNING

PROCEDURE:

Im	mediately And Simultaneously:
1.	Thrust Levers
	"Pull Up Warning Checklist Complete

PULL UP WARNING

D-3

Rev 1-98

Mar 13-98



2 of 4

11.2.62 FAA Approved Southwest Airlines
Flight Operations Manual

Non-normal Operations QRH 737-300/-500

ADDITIONAL INFORMATION/CONSIDERATIONS

OVERSPEED

This condition is recognized by the Mach. Airspeed Warning clacker. The clacker sounds until airspeed is reduced below $V_{\rm mo}/M_{\rm mo}$. Thrust should be reduced and pitch attitude increased as required to reduce airspeed below $V_{\rm mo}/M_{\rm mo}$.

STALL

This procedure is accomplished at the earliest recognizable stall warning, initial airframe buffet and/or stick shaker

Without delay apply maximum thrust, and smoothly adjust pitch attitude to avoid ground contact or obstacles. At higher altitudes, it may be necessary to decrease pitch attitude to achieve acceleration

CONFIGURATION WARNING

This procedure is accomplished when an intermittent warning horn sounds while advancing thrust levers during takeoff, or a steady warning horn sounds in-flight. Check and correct the position of the items which cause the warnings.

- Stabilizer trim
- Flaps
- Leading edge devices
- Speedbrakes
- · Landing ger
- · Parking brake ras installed-

GROUND PROXIMITY ALERT

If an alert occurs when flying under Day and VMC conditions, and positive visual verification is made that no hazard exists, the alert may be regarded as cautionary and the approach may be continued. If the verification cannot be made, immediately check correct the aircraft flightpath, or go-around if necessary.

D-10

Rev 1-98

Mar 13-98



3 of 4

	outhwest Airlines at Operations Manual	11.2.63 FAA Approved
The state of the s	OVERSPEED	
	• • • • • • • • • • • • • • • • • • • •	
	peed Checklist Complete"	Adjust
	STALL	
•		
without d	elay:	
	!! Checklist Complete	Adjust
Config	URATION WARNING	
	n Warning Checklist Complete	•
GROUND	PROXIMITY ALERT	
• • • • • • • • •	unity Alert Checklist Complete	Verify Correct

OVERSPEED // STALL // CONFIGURATION WARNING // GROUND PROXIMITY ALERT

D-11

Rev 1-98

Mar 13-98

