Customer:	Evaluation Date:
FAA	15 July, 2014
Sales Order:	Repair Order#:
981753	K166776
Part Number:	Model Number:
2751550	
Serial Number:	
0056	Complaint Verified: Yes No

Reason for Return: Investigation

On July 5, 2013, about 1845 Pacific daylight time, a Rockwell International Corporation NA-265-65, Mexican registered XB-RSC, sustained substantial damage following a reported loss of control while taxiing at the McCarran International Airport (LAS) Las Vegas, Nevada. The airplane was registered to and operated by Eseasa Contrucciones, S. A. de C. V., under the provisions of Title 14 Code of Federal Regulations Part 91. The captain, first officer and four passengers were not injured. Visual meteorological conditions prevailed and instrument flight rules (IFR) flight plan was filed for the personal flight which originated from Brownsville, Texas at about 1755, central daylight time.

The pilots reported that prior to landing, the main hydraulic system lost pressure. The pilots selected the auxiliary hydraulic system and continued the approach. During the landing roll, about two thirds down the runway, the pilots turned onto a taxiway. Once on the taxiway, the captain reported he was unable to stop or steer the airplane as it proceeded across a parallel runway and then into a grass field and subsequently struck a metal beam located within a drainage area.

History:

Hyd Pump Repaired Nov 10, 2006: H107899

- Returned for Overhaul and had been previously repaired prior to 11/10/2006.
- Pump run-in test was out of specification: 2000rpm and 3000rpm shaft seal leakage leaks greater than 1drop/min.
- Spring, Coupling, Gasket & Cartridge Assy were replaced.

Time/Cycles: Unknown

Received Condition:

Unit received is very dirty and paint is peeling on the electric motor. No caps or plugs were on the pump as-received. Final test date stamp on the pump is not legible. Plastic debris can be seen in the pump discharge port (captured). There is dirt/ dust in the pump inlet port. On the side of the electric motor is a two-pin connector (that was connected) but the wires leading from the connector have been cut. There is gray tape (resembles duct tape) on one of the power leads to the electric motor. All power leads to the electric motor have been cut.

Investigation:

- Residual oil sample obtained from pump inlet and captured. (Will be retained for 1 year).
- Inlet and discharge ports were flushed with Stoddard Solvent, then captured.
- Unit was clamped to the bench for operational testing.
- Red Oil MIL-PRF-5606 used on the test bench.
- Pressure and temperature transducers installed to the pump inlet and discharge lines.
- The motor and pump turn when energized with 25V.
- The pump performed per ATP when tested at the following settings:
 - o 103°F fluid temperature



Parker Customer Support Kalamazoo Service Center

Parker Aerospace Parker Hannifin Corporation FAA UCER345K Cage 93835

- o 2.17 gpm
- o 25V
- o 3052 psi
- o 196.9 amps
- See Appendix 1 for Test Results
- The unit was run for 1 minute in an attempt to see if the thermal switch opens
 - Thermal switch did not open during this run.
 - o The maximum temperature of the motor case after testing was approximately 150°F.
 - The temperature of the motor case during the test was 115°F.
- At the direction of NTSB (Albert Nixon), the unit was energized per ATP and operated while monitoring the thermal switch continuity.
 - 8 cycles of 1 minute on; 3 minutes off while monitoring the thermal switch continuity and external motor temperature.
 - 2 cycles of 3 minutes on; 3 minutes off while monitoring the thermal switch continuity and external motor temperature.
 - Results are in Table 1 and Table 2.
 - Thermal switch opened when outside motor temperature reached 220°F.
 - o Thermal Switch closed when outside motor temperature reached 226°F.
 - The maximum outside motor temperature achieved was 251°F.
- Note: Radio Noise Filter box was dented during testing due to the clamp.

Summary

This pump motor package operated normally and satisfied acceptance testing per H61A1250 flow and current requirements.

Further testing was performed to determine the functionality of the thermal switch. Functionality of the thermal switch was confirmed by monitoring the continuity of the switch wires during thermal cycling.



Parker Customer Support Kalamazoo Service Center

Parker Aerospace Parker Hannifin Corporation FAA UCER345K Cage 93835

Cycle	Motor Temp (°F)	Thermal Switch Ohms
1	95.5	0.3
3	112.6	0.3
1	106	0.3
3	133.8	0.3
1	116.8	0.3
3	150.1	0.3
1	124.8	0.3
3	169.1	0.4
1	134.6	0.3
3	181.1	0.5
1	140.6	0.3
3	187.9	0.5
1	144.4	0.3
3	193.3	0.6
1	147.5	0.3
3	197.3	0.6
3	148.8	0.3
3	219.3	0.6
3	158.5	0.4
2	220	Open
3	240	Open
3	251	Open
Fan		
Cool	226	0.6

Table 1



Parker Customer Support Kalamazoo Service Center Parker Aerospace Parker Hannifin Corporation FAA UCER345K Cage 93835




Table 2





Figure 2



Figure 3



Figure 4



Figure 5



Parker Customer Support Kalamazoo Service Center Parker Aerospace Parker Hamilin Corporation FAA UCER345K Cage 93835



Figure 6



Figure 7



Figure 8



Figure 9




Figure 10



Parker Customer Support Kalamazoo Service Center Parker Aerospace Parker Hanniin Corporation FAA UCER345K Cage 93835





Figure 11



Parker Customer Support Kalamazoo Service Center Parker Aerospace Parker Hanniin Corporation FAA UCER345K Cage 93835

Appendix 1
Test Results

Parker Customer Support Kalamazoo Service Center Parker Aerospace Parker Hannifin Corporation FAA UCER345K Cage 93835



Parker Aerospace Parker Hannifin Corporation FAA UCER345K Cage 93835