NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public use aircraft accidents and incidents

BASIC INFORMATION												
Accident/Incident Loca						D	Date/Time					
Nearest City/Place: Albuc	Nearest City/Place: Albuquerque State: NM				D	ate: 04/20/2	2013	Loca	al Time: 13	3:04		
ZIP: 87106 Country: United States of America						mm/dd/yy	уу					
Latitude: 35°08'02"N (dd:mm:ss N/S) Lo	ngitude: 100	6º47'40"W	<u>/</u> (ddd:	:mm:ss E/W)				Tim	e Zone: IVIL	DT	
Phase of Operation						C	Collision with C	ther Airc	eraft	Altitude o	f In-Flight	
	(incl. initial climb)			_	Iover	_	Midair			Occurren	ce	
✓ Taxi ☐ Climb ☐ Descent ☐ Landing	•	☐ Mane			Other Jnknown		On-ground None				5,834	4 MCI
AIRCRAFT INFO		Аррг	oacii		JIKHOWH		<u>I</u> TYONC				0,001	II WISL
							M C N	7 • 1 4		0.050 #		
Manufacturer: Cessna Model: 175 Skylark / /							Max Gross W				2.0	10 11
Serial Number: 175-56							Weight at Tir Location of C					19 lbs
			A	. •14.			Location of C		-		or 🔽 datur	
Registration Number:	NOSSSE		Amateur-i	ount:	☐ Yes ☑ N	10	-or-				namic Cord (
Category of Aircraft	Type of Airwo		Certificate		Number of	Se	eats:	4	Landir	ıg Gear	Retrac	table
Airplane	(Check all that a										nal landing ge	ar
☐ Balloon ☐ Blimp/Dirigible	Standard	Spec	cial estricted		If Large Airc	raft	, how many seats	tor:	_	uration that	applies:	
Glider	✓ Normal ☐ Utility	☐ Li			Flight C	rew	r:		Tri	cycle	☐ Ta	ilwheel
Gyrocraft Helicopter	☐ Acrobatic		ovisional		Cabin C	rew	r:			phibian		gh Skid
Powered lift	Transport		operimental pecial Flight		Passenge	ers:			☐ Em	ergency Flo	at ☐ Sk	
☐ Ultralight ☐ Unknown			ght Sport						☐ Hu	11		i/Wheel
			ı							known		
Type of Maintenance F	rogram		Last Ins	-				Date La	st Inspec		<mark>03/20/2103</mark> m/dd/yyyy	
✓ Annual ☐ Conditional (Amateur-b	uilt only)		☐ 100 He	our	☐ Continue		Airworthiness Inspection			m	m/aa/yyyy	
Manufacturer's Inspecti		D)	✓ Annual Unknow				e Total T	tal Time: 3,158 hrs				
Other Approved Inspect		P)						hour	s measured	at (check	one)	_
Other, specify:								✓ L	ast Inspect	ion 🔲 T	ime of Accid	ent/Incident
IFR Equipped			Stall Wa	rning System Installed			Type of	Fire Ext	inguishing	System		
☐ Yes ☑ No ☐ Unl	known		✓ Yes	Yes No Unknown			None✓ Specify manual extinguisher					
								Specii	ly <u>marraar</u>	- CALLINGUIOTI		
ELT Installed F	ELT Activated				. Г		may Dagger C	\				
	Yes No						ency Beacon C	orporatio	on			
ELT Aided in Locating		ent			EBC 102A		triovo until Mo					
☐ Yes ☑ No	, ricerdenty inclu	CIIC			: MERL BP1		trieve until Ma	y 1, 2013			stor lung 2	015
Engine Type	Re	eciprocatin			opeller	104	.0		Datte	ту Ехр. Da	ite: June 2	010
_ " '' _	ırbo Jet Sy	stem Type		11	opener							
	1100 1 an	Carburetor Fuel Injecte	.d		Fixed Pitch		Manufac	turer: Mc	Cauley			
☐ Turbo Prop ☐ Ui	nknown L	Fuel Injecte			Controllable 1	Pitc	h Model: _	IB175/MI	FC - S/N	70840		
								Engine R Power M				
							Date	as (check		Total	Time Since	Time Since
	Engi				ufacturer's		of Mfg.		epower or	Time	Inspection	Overhaul
Engine Engine Manufac	turer Mod	el/Series		Seria 12233-9	l Number		<i>mm/dd/yyyy</i> 1959	∐ lbs of	f Thrust 175	(hours) 3,158	(hours)	(hours)
Eng. 2	30-30			12200-8	,,,		1909	-	.73	3,138	3	
Eng. 3										1		
Eng. 4								1		1		
•	<u> </u>						•	-		-	-	

OWNER/OPERATOR INFORMATION							
Registered Aircraft Owner	Owner Address						
Name: Chris Grotbeck			City:	, Albuquerque			
Fractional Ownership Aircraft: Yes	State: NM Country: USA	ZIP: <u>87199</u>					
Operator of Aircraft Same A	Operator Address	Same As Registered Owner					
Name:			City:				
			City:State:	ZIP:			
Air Carrier/Operator Designator (4 Char	racter Code):		Country:				
Regulation Flight Conducted Under			Revenue Sightseeing				
☑ FAR 91 ☐ FAR 129 ☐ FAR	R 91 Special Flight	Public Use (select type)	☐ Yes ✓ No				
	-US, Commercial-US, Non-commerci	☐ Federal ☐ State ☐ Local al ☐ Unknown	Air Medical Flight				
	ed Forces	ai	Ye	es 🔽 No			
Purpose of Flight for FAR 91, 103, 133, 137 (Select one)		nue Operation AR 121, 125, 129, 135 (Select one)	Type of Commercial (Check all that apply)	Operating Certificate Held			
✓ Personal		heduled or Commuter	None None				
Business		on-Scheduled or Air Taxi	Flag Carrier Operatin	ng Certificate (121)			
Executive/Corporate			☐ Supplemental ☐ Air Cargo				
☐ Other Work Use ☐ Instructional	Dome	stic or International	Foreign Air Carriers	(129)			
Ferry	☑ Do	omestic International	Commuter Air Carrie	er (135)			
Positioning			☐ On-Demand Air Taxi☐ Large Helicopter (12)				
☐ Aerial Application ☐ Aerial Observation	Cargo	Operation					
☐ Air Drop	П Pa	ssenger/Cargo	Rotorcraft External Load (133) - or - Agricultural Aircraft (137)				
Air Race / Show	Pa	How many?					
☐ Flight Test ☐ Public Use		rgolbs	☐ Other Operator of Large Aircraft				
Unknown							
OTHER AIRCRAFT – COLLIS	SION (If air or	average collision accounted commists t					
	OIOIT (II all OI	ground collision occurred, complete t	nis section for other ai	rcrait)			
				Damage to Other Aircraft			
Aircraft Registration Number Manu	ufacturer:			Damage to Other Aircraft ☐ Destroyed ☐ Minor			
Aircraft Registration Number Manu Mode	ufacturer:			Damage to Other Aircraft			
Aircraft Registration Number Manu Mode Registered Owner of Other Aircraft	ufacturer:el:			Damage to Other Aircraft ☐ Destroyed ☐ Minor			
Aircraft Registration Number Manu Mode Registered Owner of Other Aircraft First Name:	ufacturer:el:			Damage to Other Aircraft ☐ Destroyed ☐ Minor ☐ Substantial ☐ None			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name: Middle Initial:	ufacturer:el:	City: State:	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Manu Mode Registered Owner of Other Aircraft First Name:	ufacturer:el:	City: State:		Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ufacturer:	City: State: Country:	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Manu Mode Registered Owner of Other Aircraft First Name:	ufacturer:	City: State: Country:	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ufacturer:	City: State: Country:	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ufacturer:	City: State: Country: City: State: Country:	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ufacturer:el:	City: State: Country: City: State: Country: City: State: Country: (If more space is needed, continue of	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Manu Mode Registered Owner of Other Aircraft First Name: Middle Initial: Last Name: Pilot of Other Aircraft First Name: Middle Initial: Last Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None Total Time/Cycles On Part			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None Total Time/Cycles On Part Hours			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None Total Time/Cycles On Part			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Damage to Other Aircraft Destroyed Minor Substantial None Total Time/Cycles On Part Hours Cycles			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name:	ON/FAILURE	City: State: Country: City: State: Country: (If more space is needed, continue of the contin	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part Inspected/Overhauled			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name: Middle Initial: Last Name: MECHANICAL MALFUNCTIC Was there Mechanical Malfunction/Facilifyes, list the name of the part, manufacturer	ON/FAILURE Failure?	City: State: Country: City: State: Country: (If more space is needed, continue of the failure.)	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part Inspected/Overhauled			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name: Middle Initial: Last Name: MECHANICAL MALFUNCTIC Was there Mechanical Malfunction/Fa (If yes, list the name of the part, manufacturer) DAMAGE TO AIRCRAFT AN	on/FAILURE Failure?	City: State: Country: City: State: Country: (If more space is needed, continue of the failure.)	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part Inspected/Overhauled			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name: Middle Initial: Last Name: MECHANICAL MALFUNCTIC Was there Mechanical Malfunction/Facilifyes, list the name of the part, manufacturer DAMAGE TO AIRCRAFT AN Aircraft Damage	ON/FAILURE Failure? Yes Part no., serial no	City:	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part Inspected/Overhauled Hours			
Aircraft Registration Number Mode Registered Owner of Other Aircraft First Name: Middle Initial: Last Name: Pilot of Other Aircraft First Name: Middle Initial: Last Name: MECHANICAL MALFUNCTION Was there Mechanical Malfunction/Fa (If yes, list the name of the part, manufacturer Aircraft Damage None Substantial Minor Destroyed	on/FAILURE Failure?	City: State: Country: City: State: Country: (If more space is needed, continue of the failure.)	ZIP:	Total Time/Cycles On Part Hours Cycles Time Since This Part Inspected/Overhauled			

Description of Damage to Aircraft and C	Other Property (use addi	itional sheet if	necessary)			
Dust devil lifted left wing during taxi. Prop str	ruck taxiway, prop tips def	formed. Righ	t wing struck taxiv	way and right wir	ngtip outboar	d of aileron deformed.
AIRPORT INFORMATION (If the	e accident/incident occu	irred on app	roach. takeoff or	within 3 miles	of an airport	t. complete this section)
Airport Identifier: KAEG				n Airport Cent		•
Airport Name: Double Eagle II, Albuqu	eraue			m Airport:		90_ degrees MAG
Proximity to Airport Off Airport/Airst		On Airstrip		_		5,834 ft. MSL
	np 💋 On Airport 🔲 C	On Airstrip	Airport Eleva			II. MSL
Approach Segment (Select one)						
☐ On Instrument Approach ☐ Landin☐ Crosswind ☐ Down		e leg Approach	☐ F	final Aborted Landing (a	ofter touchdow	Go Around
IFR Approach (Check all that apply)	Willia Dow	прричен		h (Check all tha		
✓ None □ PAR	☐ MLS ☐	Practice	□ None	ii (eneen an ma		op and Go
ADF/NDB Sidestep		GPS	Traffic Patter	n	☐ To	ouch and Go
		Loran	Straight-In	- P. H 1		mulated Forced Landing
□ VOR/TVOR □ Localizer Only □ VOR/DME □ LOC-back course	☐ Visual ☐ Contact	Unknown	☐ Valley/Terrai☐ Go Around	n Following		orced Landing ecautionary Landing
☐ TACAN ☐ RNAV	Circling		✓ Full Stop			ıknown
Runway Information				-	-	(Check all that apply)
Runway ID: <u>22</u> (L/R/C) Length:	7,398 ft Width:	ft	✓ Dry Holes		Compacted Crusted	Water-Calm
Runway/Landing Surface (Check all that	annly)		Ice Covered	☐ Snow-		☐ Water-Choppy ☐ Water-Glassy
✓ Asphalt ☐ Grass/Turf ☐ Mac			Rough	☐ Snow-		□ Wet
	al/Wood 🔲 Unknown		Rubber Depo			Unknown
☐ Dirt ☐ Ice ☐ Snow			☐ Slush Covere	d Vegeta	ation	
FLIGHT ITINERARY INFORMA						
Last Departure Point	Time of Departure	Destination	n			t Plan Filed
Airport ID: 1N1	Time: 12:45	Airport ID:	KAEG		None	☐ VFR/IFR
City: Edgewood	Time. <u>12.10</u>	City: Albuq	luerque		☐ Company ☐ Military V	
State: New Mexico	Time Zone: MDT	State: New	Mexico		VFR	
Country: USA		Country: US	SA		Activated?	☐ Yes ☐ No
Type of ATC Clearance/Service (Check a	ıll that apply)			ı.		
☐ None ☐ Special VFR	☐ Specia	al IFR	□ VI	FR Flight Followi	ng	Cruise
✓ VFR ☐ IFR	□ VFR (On Top	☐ Tr	raffic Advisory		Unknown / NA
Airspace where the accident/incident occ						
☐ Class A ☐ Class E ☐ Class B ☐ Class G	=	nibited Area tricted Area		☐ Jet Training☐ TRSA	Area	☐ Special ☐ Air Traffic Control Area
Class C Demo Area	_		s Area (MOA)	☐ FAR 93		Unknown
☐ Class D ☐ Warning Area		ort Advisory A		_		
Aircraft Load Description (Check all that	apply)					
		chutists		Livestock		
▼ None ☐ Towing Glide						
Passengers Towing Bann	er Wat		/G 1	Unknown		
Passengers Towing Bann Cargo Other Externa	er Wat	er mical/Fertilizer	r/Seeds	Unknown		
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMAT	er Wat		r/Seeds	∐ Unknown		
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMAT Fuel on Board at Last Takeoff	er Wat I Che TION Fuel Type	mical/Fertilizer		_		
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMA Fuel on Board at Last Takeoff (convert from pounds, as necessary)	er Wat		r/Seeds JP3 JP4	_	er, specify	
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMAT Fuel on Board at Last Takeoff	Wat	mical/Fertilizer	☐ JP3 ☐ JP4	_	er, specify	
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMA Fuel on Board at Last Takeoff (convert from pounds, as necessary)	Wat Wat Che	mical/Fertilizer	☐ JP3 ☐ JP4	_	er, specify	
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMAT Fuel on Board at Last Takeoff (convert from pounds, as necessary) 52 Gallons	Wat Wat Che	mical/Fertilizer	☐ JP3 ☐ JP4	_	er, specify	
Passengers Towing Bann Cargo Other Externa FUEL & SERVICES INFORMAT Fuel on Board at Last Takeoff (convert from pounds, as necessary) 52 Gallons Other Services, if Any, Prior to Departu	Wat Wat Che	mical/Fertilizer	☐ JP3 ☐ JP4	_	er, specify	

EVACUATION OF AIRCRAFT								
Was an emergency evacuation	Was an emergency evacuation of the aircraft performed? ✓ Yes No							
Method of Exit – Describe how the occupants exited and how many occupants evacuated each location								
After pilot shut down engine, fuel, and electrical systems, pilot exited aircraft through passenger (RH) door.								
WEATHER INFORMA	TION AT THE	ACCID	ENT	/INCIDENT S	SITE			
Weather Observation Facilit	y			ce of Weather In	formation			Method of Briefing
Facility ID: KAEG Observation Time: OOA 12:45 Time Zone: MDT Distance from Accident Site:	<u>0</u> N	— —	(Check all that apply) ☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☑ Automated Report ☐ Commercial Weather Service (DUAT		ΓS)	☐ Company ☐ Military ☐ Internet ☐ Unknown	(Check all that apply) ☐ In Person ☐ Teletype ☑ Telephone/Computer ☑ Aircraft Radio ☐ TV/Radio	
Direction from Accident Site:	270 degre							Unknown
Briefing Type/Completeness	☐ Abbreviate	d	Light Da Da Da				Dark Night Bright Night	Visibility 10 miles
✓ Partial / Limited By Pilot☐ Partial / Limited By Briefer	☐ Not Pertine		V Da	ny 🔲 Nig	gnt		Not Reported	nincs
Few	Thin Broken Thin Overcast Unknown	Ceiling None (compared Broken) Overcase		☐ Inde	cured efinite enown		None Blowing Dust Blowing Sand Blowing Snow	(Check all that apply) Fog Ground Fog Haze I ce Fog
Lowest Cloud Condition Hei	ght	Ceiling H	leight	;			Blowing Spray	Smoke
	ft AGL			12,000 f	t AGL		Dust	Unknown
Wind Direction	Wind Speed			Wind Gusts		Ty	pe of Turbulence (C)	heck all that apply)
✓ Indicated:	Velocity:	15 KTS		Velocity: 2	<u>85</u> KTS		None In Clear Air Vicin	ouds ity of Thunderstorm
☐ Variable	☐ Calm ☐ Light and Varia	able	✓ Gusting ☐ Not Gusting			Severity of Turbulence ☐ Extreme ☐ Moderate ☐ Light ☐ Severe ☐ Moderate Chop		
NOTAMs (D, L and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident								
or(F) Altimeter Setting:29.96 in. HG		Amount None Trace Light ing Actual Amount	Moderate		Type Rime Clear Mixed		Mone ☐ Rain ☐ Snow ☐ Hail ☐ Rain Showers ☐ Freezing Rain	on (Check all that apply) Drizzle Ice Pellets Snow Pellets Snow Grains Ice Crystals Ice Pellets Shower Freezing Drizzle
Dew Point: 11 (C) or(F)		None Trace Light	_	Moderate Severe	Rime Clear Mixed	-	Intensity of Precipi	


PILOT "A" INFORM <i>A</i>	ATION									
Pilot "A" Responsibilities a ✓ Pilot □ Co-Pilot	t the Time of A	ccident/Incid		Check Pilot	☐ Flight	Engineer	Other	Flight Crew		
Pilot "A" Identification										
First Name: Christopher Middle Initial: L Last Name: Grotbeck City: Albuquerque State: NM ZIP: 87199 Country: USA										
Age at time of Accident/Incid	dent:47	Date of Bi	rth: <i>mm/dd/yy</i>		tificate N	umber:				<u>+</u>
Degree of Injury	Seat Occup	ied		Seat	Belt			Shoulder H	larness	
Minor ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Left Right Center	☐ Front ☐ Rear ☐ Single	Unknov	vn Used Avail	_		□ No □ No	Used Available	☐ Yes ☐ Yes	☑ No ☑ No
Pilot Certificate(s) (Check a	ll that apply)									
□ None □ Stud ☑ Private □ Flig	lent ht Instructor	☐ Recre	eational	Commercia			Flight Engir U.S. Militar		Foreign	
Principal Occupation	Medical Certific	cate				ificate Va	-	Date of L	ast Medica	l
✓ Other	Class 1	Class 3 Driver's Lice Unknown	ense (Sport Pilot	only)		tations/wai ons/waiver		01/10/ mm/dd/		
Medical Certificate Limitat	ions			•				•		
Medical Certificate Waiver	S									
Date of Last Flight Review		Flioh	t Review Airc	raft						
or Equivalent, Including	10/10/0011		Cessna	, and						
FAR 121/135 Checks: _	10/16/2011		ı: 175							
11 1 D (1 ()	mm/dd/yyyy			(D) (1) (1)	1	T	D (1) (1)			
Airplane Rating(s) (Check all that apply)	Other Aircra			ent Rating(s) l that apply)		Instructo (Check all	r Rating(s)			
None	☐ None	*PP*97	None	11 .,		None	11 //		Instrument .	Airnlane
Single-Engine Land	Airship		Airpla				e Single-Eng		Instrument	
Single-Engine Sea	Free Balloon	1	Helico			Airplan	e Multi-Engi	ne 🗌	Helicopter	•
☐ Multiengine Land ☐ Multiengine Sea	☐ Glider ☐ Gyroplane		☐ Power	ed Lift		Gyropla			Glider	
ividitiengine Sea	Helicopter					Powere	a Litt		Sport	
	Powered Lif	t								
Type Ratings								nts (Include o	lates)	
SEL						0/19/2008 I	nitial Solo ΓΟ/L 0E0 w/8	v wind		
						1/26/2009 9		x-wiriu		
							Add'l airports			
							oractice TO/L solo flights C-			
							and 04/19/200		anto.	
Flight Time (enter appropriate	2 All	This Make	Airplane Single	Airplane		Inst	rument			Lighter
number of hours in each box)	Aircraft	& Model	Engine	Multiengine	Night	Actual	Simulated	Rotorcraft	Glider	Than Air
Total Time	295	283	295	0	91	0	33	0	0	0
Pilot in Command (PIC)	254	242	254	0	91	0	33	0	0	0
Time as Instructor	0	0	0	0	0	0	0	0	0	0
This Make/Model	40			0	91	0	31			
Last 90 Days	12	12	12	_	1	0	0	0	0	0
Last 30 Days Last 24 Hours	2	1	1	0	0				0	0
						•			_	

PILOT "B" INFORMATION										
Pilot "B" Responsibilities ☐ Pilot ☐ Co-Pilot		nt/Incident] Flight Instr		Check Pilot	☐ Flig	ght Engineer	Other	Flight Crew		
Pilot "B" Identification										
First Name: Middle Initial: Last Name:				City Stat Cou	y: te: ıntry:	Z	IP:			
Age at time of Accident/Inc	eident: Da	ite of Birth:	mm/dd/yy		rtificate	Number:		· · · · · · · · · · · · · · · · · · ·		
Degree of Injury	Seat Occupied		,		t Belt			Shoulder H	arness	
None Fatal Unknown Serious	Left 1	Front [Rear Single	Unknown	Used] No] No	Used Available	☐ Yes	□ No □ No
Pilot Certificate(s) (Check										
		☐ Recreatio ☐ Sport	onal	Commerci			Flight Engir U.S. Militar	У	Foreign	
Principal Occupation	Medical Certificate			Med	lical Ce	rtificate Val	idity	Date of La	ast Medica	l
☐ Pilot ☐ Other ☐ Unknown	□ None □ Clas □ Class 1 □ Driv □ Class 2 □ Unk	er's License	(Sport Pilot	only)		mitations/waivers		mm/dd/y	yyy	
Medical Certificate Limit	ations							- W		
Medical Certificate Waive	ers									
Date of Last Flight Review	v	Flight Re	eview Airc	raft						
or Equivalent, Including										
FAR 121/135 Checks:	mm/dd/yyyy	Model:								
Airplane Rating(s)	Other Aircraft Ra	ting(s)	Instrum	ent Rating(s)		Instructor	Rating(s)			
(Check all that apply)	(Check all that apply)			that apply)	<i>'</i>	(Check all th				
None	None		☐ None			None			Instrument A	
☐ Single-Engine Land☐ Single-Engine Sea	☐ Airship ☐ Free Balloon		Airpla			Airplane			Instrument H	elicopter
☐ Multiengine Land	Glider		☐ Helico☐ Power	pter ed Lift		☐ Airplane ☐ Gyroplan			Helicopter Glider	
☐ Multiengine Sea	Gyroplane			cu Ent		Powered			Sport	
	☐ Helicopter ☐ Powered Lift									
Type Ratings	☐ Powered Lift					Student En	dorsemen	ı ts (Include da	ntes)	
Type Katings						Student En	iuoi seilleli	its (include ad	ues)	
Flight Time (enter appropri	ate All Thi		Airplane	A 2 1		Insti	ument			T :=1 /
number of hours in each box)		s Make Model	Single Engine	Airplane Multiengine	Night	Actual	Simulated	Rotorcraft	Glider	Lighter Than Air
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days								1		
Last 30 Days								1		
Last 24 Hours										

ADDITIONAL FLIGHT CREW MEMBE	RS (Exclusive of cabin attendants, complete the	e following informat	ion)
Pilot Name and Address First Name: Middle Initial: Last Name:	State: ZIP:		Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Student ☐ Recreation ☐ Private ☐ Flight Instructor ☐ Sport Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ N	al Commercial Flight Engineer Airline Transport U.S. Military Total Flight Time at the Time	☐ Foreign	Seat Occupied Left Front Right Rear Center Single Unknown
			T =
First Name: Middle Initial: Last Name:	State: ZIP:		Degree of Injury
Pilot Certificate(s) (Check all that apply) None Student Recreation Private Flight Instructor Sport Type Rating/Endorsement for Accident/Incident Aircraft? Yes	al Commercial Flight Engineer Airline Transport U.S. Military Total Flight Time at the Time	☐ Foreign	Seat Occupied Left Front Right Rear Center Single Unknown
Pilot Name and Address			Degree of Injury
First Name: Middle Initial: Last Name:	State: ZIP:		None Fatal Minor Unknown Serious
Pilot Certificate(s) (Check all that apply) None Student Recreation Private Flight Instructor Sport Type Rating/Endorsement for Accident/Incident Aircraft?	Airline Transport U.S. Military Total Flight Time at the Time	☐ Foreignhrs	Seat Occupied Left Front Rear Center Single Unknown
PASSENGER(S) / OTHER DERSONNE	EL (Include flight attendants; continue on separ	ata shoot if nacessa	ary)
TASSENGER(S) / OTHER TERSONNE	LE (include hight attendants, continue on separ		
Name and Address		Seat Crew	Non- Revenue Revenue Non- Occupant FAA Fatal Serious Injury Minor Injury No Injury
First Name: Middle Initial: Last Name:	City: ZIP: Country:		
First Name: Middle Initial: Last Name:			
First Name: Middle Initial: Last Name:	City: ZIP: Country:		
First Name: Middle Initial: Last Name:	City: ZIP:		
First Name: Middle Initial: Last Name:	City: ZIP: Country:		00000000
First Name: Middle Initial: Last Name:	City: ZIP: Country:		
First Name:Middle Initial:Last Name:	City: ZIP: Country:		00000000
First Name: Middle Initial: Last Name:	City: ZIP: Country:		00000000

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)
Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State time and point of departure, intended destination, and services obtained.
Departed Sandia Airpark (1N1) 12:40 MDT (18:40Z) for Albuquerque Double Eagle II (KAEG). Established with Albuquerque Approach approximately 1845Z and traversed Albuquerque class C from east to west, obtaining KAEG ATIS information Zulu while en route. Changed frequency to KAEG tower with airport in sight (approximately 1855Z) and was cleared to land runway 22. KAEG tower pointed out a dust devil to the northeast of the airport that was moving east. It was no factor. Pilot observed another dust devil to the southwest of the tower that also appeared to be diminishing and no factor. Runway 22 wind increased from L&V at time of information Zulu, to 250/15 while on base, to 250/25 while on final. Pilot landed long and gracefully, with some extra airspeed, exited runway 22 at A4, and was instructed to taxi A4-A-Bode ramp and remain on tower frequency. When almost to the intersection of A4 and A, a dust devil materialized approximately 100m to the west of the aircraft, and it appeared to be traveling southeast, but suddenly changed direction and engulfed the airplane, lifting it approximately 1m off the ground and yawing it approximately 30deg left. Pilot maintained level flight and the airplane settled back gently to the ground. Almost immediately upon returning to the taxiway, the wind direction changed and the left wing was rapidly lifted, driving the right wingtip and propeller both to contact the taxiway and sustain damage and dragging the airplane perhaps half a meter on the right wingtip, and nosegear. Later inspection revealed that some of the screws at the the right main gear attachment point were loose, possibly indicating stress to the right main gear.
RECOMMENDATION (How could this accident/incident have been prevented?)
RECOMMENDATION (How could this accident/incident have been prevented?) Operator/Owner Safety Recommendation
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the
Operator/Owner Safety Recommendation By the time the offending dust devil appeared, no evasive action could be taken. Short of not landing at all, or staying home in bed and not flying in the first place, there is little that could have been done to avoid or prevent the dust devil from attacking the airplane. A prop strike might have been prevented by quickly shutting down the engine when the dust devil was first observed, but it would depend on the angle of the prop when it stopped, and having the prop turning might have actually increased stability when the turbulence first began. Although no injuries occurred, installing shoulder harnesses might reduce the

ADDITIONAL INFORMATION (Please type or print in ink) Use this space if additional space is needed for any answers.						
Use this space if addi	tional space	is needed for any answers.				
I HEREBY CERTIF	Y THAT TH	IE ABOVE INFORMATION IS COMPLI	ETE AND ACCURATE TO THE BEST OF I	MY KNOWLEDGE		
Date of this Report	Signature	and Name of Pilot/Operator				
04/27/2013	Signature:_					
mm/dd/yyyy		nt Name: Christopher Grotbeck				
_		Filing Report if Other than Pilot/Operato				
11tte:		EOD NTSD	IISE ONI V			
NTSB Accident/Incident	dent No	FOR NTSB Reviewed by NTSB Regional Office	Name of Investigator	Date Report Received		
CEN13CA234	uent 110.	NTSB - Central Region	Thomas J. Latson, Jr.	April 28, 2013		



N6955E encounter with dust devil 4/20/2013 AEG Airport. (19:042)



Subject: NTSB additional questions - NTSB Form 6120.1 N6955E

Date: Wed, 1 May 2013 08:57:29 -0400

To: Tom Latson NTSB From: Christopher Grotbeck

(Answers to additional questions)

Where were you when you when you first became aware of the dust devil?

on taxiway A4, bearing NW, just after having left runway 22.

Where were you when you when the dust devil first came in contact?

At the intersection of A4 and A, but had not yet begun to turn NE along A.


In what direction were you moving, and how fast were you taxiing?

NW at an estimated 5 mph,

slowing to 1-2 mph just as the dust devil engulfed the airplane.

Relative to your airplane, from what direction did the dust devil come?

from 10 o'clock.



ALBUQUERQUE, NEW MEXICO