

## NTSB National Transportation Safety Board

Office of Aviation Safety

Empire Fight 8284
ATR-42 Landing Accident
January 27, 2009
Lubbock, Texas
Leah D. Yeager - IIC

- January 27, 2009
- 0437 AM CST
- Empire 8284
- ATR-42-320
- Landed 300 feet short of runway
- FedEx Feeder Flight
- Night instrument meteorological conditions





- Cessna 208 Caravans unable to operate due to weather conditions
- FAA restrictions
- Arrived at Fort Worth Alliance Airport at 1218 AM on January 27



- Weather information
- Advised of light freezing drizzle
- Empire GOM approval of operations
- No de-icing prior to departure



- Departed at 0313
- Level 3 ice protection used during flight (moderate to severe per Captain)
- Icing ceased at 14,000 feet
- Advised of light freezing drizzle
- ILS 17R approach



- Captain briefed approach
- First Officer limitations
- Crew ascertained that First Officer could fly approach



- Airplane cleared to land
- Airplane configuration
- Flap asymmetry
- Crew verification of flap problem



- First of 5 stick shaker warnings
- Autopilot disconnected
- First Officer suggested to go-around and Captain said no
- Captain took control of airplane
- Airplane impacted ground 300 feet short of runway












#### Weather

- Wind from 020 degrees at 11 knots, gusting to 18 knots
- 2 miles visibility
- Light freezing drizzle and mist
- Overcast at 500 feet
- Temperature -08 degrees C
- Dew Point -09 degrees C






NEXRAD LEVEL-II KLBB - LUBBOCK, TX 01/27/2009 10:34:35 GMT

LAT: 33/39/15 N LON: 101/48/50 W ELEV: 3258 FT

VCP: 31

REFLECTIVITY ELEV ANGLE: 0.57

Legend: dBZ (Category)



TWR: Empire eighty two eighty four Lubbock Tower runway one seven right clear to land. winds zero one zero at eight.



# Response

- NTSB response
- Weather delays
- Examination of wreckage
- Conducting interviews
- Collecting records



# **Performance Data**

- DFDR and performance analysis
- Ice accretion
- Flap asymmetry
- No stall, loss of lateral control, or sudden change in aileron hinge movement



### **Performance Data**

- Stick shaker
- Ice accretion did not exceed control authority
- Right flap did not extend
- Left flap extended approximately 8-10 degrees
- Flap asymmetry detection system functioned as designed
- Initiating flap asymmetry event part of ongoing investigation



# **On-Scene Documentation**

Engine and flight control documentation



# **Areas of Inquiry**

- Crew resource management (CRM)
- Training
- FAA guidance for operations in icing conditions
- Design and performance of ATR-42 with a flap anomaly in icing conditions
- Avionics systems and aircraft design modifications to mitigate icing effects



#### **NTSB Staff**

Christopher Babcock

Dan Baker

Michael Bauer

Dr. Dan Bower

Timothy Burtch

Darrin Broadwater

Scott Dunham

Kristi Dunks

Don Eick

Dr. Matt Fox

**Todd Gunther** 

Frank Hilldrup

Nancy McAtee

Jeff Marcus

Alice Park

Jennifer Rodi

Christy Spangler

Dr. Katherine Wilson



# Parties to the Investigation

Federal Aviation Administration
Empire Airlines
Federal Express



# **Accredited Representatives**

Bureau of d'Enquetes et d'Analyses (BEA) ATR

Transportation Safety Board of Canada Pratt and Whitney





NTSB