

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Western Pacific Region

August 20, 2010

AIRFRAME AND ENGINE EXAMINATION

WPR110LA297

A. ACCIDENT

Location: Truckee, California Date: June 17, 2012

Aircraft: Experimental Bernard Vans RV8 Number: N901X, Serial #: 81051

NTSB IIC: Tealeye Cornejo

B. EXAMINATION PARTICIPANTS:

Tealeye Cornejo Air Safety Investigator National Transportation Safety Board 1515 W. 190th Street, Suite 555 Gardena, CA 90248

C. SUMMARY

Examination of the recovered airframe and engine was conducted on August 20, 2010, at the facilities of Plain Parts, Pleasant Grove, CA. No evidence of pre impact mechanical malfunction was noted during the examination of the recovered airframe and engine.

D. DETAILS OF THE INVESTIGATION

The visual inspection performed by the National Transportation Safety Board (NTSB) investigator, revealed that the fuselage remained intact, but exhibited crush damage from the propeller section rearward to the empennage. The cockpit area floor and sides exhibited compression crush damage. The right main landing gear remained attached to the fuselage. The propeller assembly remained attached to the engine; however, damage was sustained to all three of the wooden propeller blades. All of the blades had separated; however, about one-third of each blade from the hub outboard remained attached. The left wing had separated from the airplane. No discrepancies were noted with the flight control, and all cables and hardware were present. The throttle mixture and propeller controls were in the forward position. A visual inspection of the engine revealed no obvious holes. The engine controls, cables, and hardware remained attached at their respective positions.

The upper spark plugs were and valve train continuity w the Champion Aviation Chec	ere established. The	e spark plugs show	ngine crankshaft. red normal wear a	Mechanical ccording to
Submitted by: Investigator				