No. SB-AG-39

P. O. BOX 3090 ONE ROCKWELL AVENUE ALBANY, GA 31706-3090 PHONE 912-883-1440 FAX 912-439-9790

Service Bulletin

Service Bulletin No. SB-AG-39 17 September 1996

# WING SPAR INSPECTION AND FATIGUE LIFE EXTENSION

**MODELS AFFECTED:** 

corporation

**4V** 

All S2R models and serial numbers manufactured and listed here, including any others converted, which have:

- a) Wing assemblies with aluminum spar webs with 4500 hours or more time in service.
- b) A gas turbine engine of any type.
- c) A piston engine rated at more than 600 horespower.

S2R-R1340-011, -012, -019, -020, -024, -025, -027 S2R-R1820-001 thru -035 S2R-5000R thru -5099R S2R-T11-001 thru T11-005 S2R-T15 - T15/27-001 thru T15/27-029 thru -033 S2R-T34-6000R thru 6049R S2R-T34-6000R thru 6049R S2R-T34-001 thru -143, -145, -147 thru -167, -171 S2R-T34-180, -181 S2R-G1 - G1-101 thru -108

All T34 models whose serial numbers have the prefix T36, T41 or T42 applies if the number is listed.

All models with or without the DC suffix apply, if listed.

MODELS EXEMPTED:

- a) All 600 horsepower radial engine models, regardless of wing spar web material or total flight time.
- b) All S2R models, manufactured or converted which have all steel wing spar assemblies.
- c) All S2R models whose wing assemblies have less than 4500 hours time in service.

Specific models and serial numbers as manufactured are:

S2R-1380R, 1416R and subs S2R-R1340-001 thru -010, -013 thru -018, -021 thru -023, -026 S2R-R1340-028 and subs S2R-R3S-001 thru -011

Service Bulletin No. SB-AG-39 17 September 1996 Page 3 of 11

#### **Inspection only:**

- 1. Inspect the spar cap for cracks within the next 100 hours of flight or the next 100 hour/annual inspection, whichever comes first.
- 2. If a crack is found, replace the spar cap or wing prior to the next flight. Consult Ayres Corporation if a ferry flight to a suitable repair station is required.
- 3. If no cracks are found, return the aircraft to service and repeat the inspection at 500 hour or annual intervals, whichever occurs first.

#### **Rework:**

1. Rework by cold expansion of the 1/4 and 5/16 inch bolt holes per this bulletin will end the requirement for the crack inspection.

## BY WHOM WORK MAY BE ACCOMPLISHED:

#### Inspection:

An FAA approved repair station with NDT certification employing a technician certified to conduct non-destructive testing per MIL-STD-410E, ISO 9712, or SNT-TC-1A.

#### **Rework:**

A&P mechanic or equivalent approved by Ayres Corporation. Owner/operators are to contact Ayres Corporation for a list of approved facilities.

**APPROVAL:** 

The FAA and Ayres Corporation.

ESTIMATED MAN HOURS FOR COMPLIANCE:	• Inspection:	8 hours.
	Rework:	3 hours.
PARTS DATA:	Inspection:	Full complement of lower splice fitting bolts, nuts and washers. 2 upper spar tube-nuts. Paint.

Service Bulletin No. SB-AG-39 17 September 1996 Page 4 of 11 And the later of the

Rework: Full complement of lower splice fitting bolts, nuts and washers.
2 upper spar tube nuts.
2 each "x" oversize 1/4 inch bolts.
2 each "x" oversize 5/16 inch bolts.
Paint.

Inspection: NDT inspection equipment. Calibrated torque wrench.

> ESK 556-1 fixture. FTI Document No. 52373 Cold expansion equipment. 0.2490, 0.2646, 0.2651, 0.3110, 0.3268 and 0.3276 reamers. Calibrated torque wrench. Micrometer. Ball gauges.

#### \*NOTE\*

If there is any doubt concerning spar material, remove an inspection plate outboard of the fuel tank and use an ordinary magnet on the spar web face. The magnet will not stick to aluminum.

## ACCOMPLISHMENT INSTRUCTIONS:

**SPECIAL TOOLS:** 

#### Inspection:

-

**Rework:** 

- 1. Gain access to the wing main spar splice fittings. Remove spray pump and spray pump mounting brackets.
- 2. Remove the lower spar splice fitting bolts and splice fittings per attached removal procedure.
- 3. Thoroughly clean the area in and around the 1/4 and 5/16 bolt holes and remove the paint from an area extending one inch from the center of each of these holes.
- 4. If rust or corrosion are found anywhere on the spar cap or spar web, perform SB-AG-29 in conjunction with this bulletin.
- 5. Remove all corrosion from all of the bolt holes by mechanical and/or chemical means.

Service Bulletin No. SB-AG-39 17 September 1996 Page 5 of 11

- 6. Inspect the walls of the 1/4 and 5/16 inch bolt holes in the lower spar cap for cracks or flaws using magnetic particle or equivalent flaw detection equipment.
- 7. If no cracks or flaws are found, prime and repaint all areas where the paint was removed.
- 8. Reassemble the splice fittings per the attached installation procedure using **new** nuts, bolts and washers.
- 9. Return the aircraft to its airworthy configuration, make appropriate log book entries and return the aircraft to service

#### \*WARNING\*

If cracks or flaws are found, either replace the spar cap or wing prior to the next flight or reassemble the splice fittings and proceed with the rework if there is a possibility that oversizing the holes will remove the crack or flaw. Contact Ayres Corporation if a ferry flight to a suitable repair station is required.

#### **Rework:**

- 1. Gain access to the main spar splice fittings. Remove the spray pump and spray pump mounting brackets.
- 2. Remove the 1/4, 5/16 and 1/2 inch bolts (first, second and fourth from the ends of the splice fittings).
- 3. Thoroughly clean in and around the splice fittings and bolt holes.
- 4. Remove the paint from the spot faces of the 1/2 inch holes in the splice fitting.
- 5. With 250 grit or finer sand paper, clean the 1/2 inch bolt holes so that they easily accept the 1/2 bolts of the ESK 556-1 fixture assembly.
- 6. Install the ESK 556-1 fixture.

#### \*WARNING\*

Under no circumstances attempt to ream a hole without the use of the ESK 556-1 fixture and bushings.

- Lubricate the 0.2490 reamer and with the reamer bushing 
  installed in the fixture, ream the 1/4 inch holes.
- 8. Lubricate the 0.3110 reamer and with the reamer bushing installed in the fixture, ream the 5/16 inch holes.
- 9. Remove the ESK 556-1 fixture.

•

Service Bulletin No. SB-AG-39 17 September 1996 Page 6 of 11

- Using the attached Fatigue Technology, Inc. procedure described in F.T.I. Document No. 52373, cold expand the 1/4 and 5/16 inch holes.
- 11. Install the ESK 556-1 fixture.
- 12. Lubricate the 0.2646 reamer (smaller of the two 1/4 inch final reamers) and with the reamer bushing installed in the fixture, ream the 1/4 inch holes.
- 13. Lubricate the 0.3268 reamer (smaller of the two 5/16 inch final reamers) and with the reamer bushing installed in the fixture, ream the 5/16 inch holes.

#### \*NOTE\*

The oversize repair bolts are manufactured to a tolerance of 0.2641 - 0.2651 for the "x" oversize 1/4 inch bolt and 0.3266 - 0.3276 for the "x" oversize 5/16 inch bolt. The diameter of a reamed hole depends on reamer quality, operator technique, lubricant, RPM and other factors. Because of these variations in bolt diameter and hole size, bolt-in-hole fit will vary. Use caution when installing the bolts so as not to remove the bolt cadmium plating on installation.

14. Insert an "x" oversize 1/4 inch bolt into one of the 1/4 inch holes. If resistance is encountered, encourage the installation with moderate taps of a 6 ounce plastic mallet. If further
resistance is encountered or it appears that installation will remove the cadmium plate from the bolt, remove the bolt and ream the hole with the 0.2651 final reamer (larger of the two final reamers).

#### \*NOTE\*

If the bolt is still excessively tight after using the larger final

- reamer, use a micrometer to check the mandrel for wear, the reamer for wear, and the bolt diameter, it may be required to select a bolt with a small diameter.
- 15. In a similar manner, prepare the other 1/4 inch hole.

-

- Using similar technique and precautions, prepare the 5/16 inch holes for "x" oversize 5/16 inch bolts using the 0.3110 and 0.3276 inch reamers.
- 17. Mark these 1/4 and 5/16 inch "x" oversize bolts and be sure to install them in their respective holes during reassembly.

# Service Bulletin No. SB-AG-39 17 September 1996 Page 7 of 11

- 18. Remove the remaining spar splice bolts and the spar splice fittings per the attached removal procedure.
- 19. Remove all corrosion from all of the bolt holes by mechanical and/or chemical means.
- 20. Thoroughly clean the area in and around the 1/4 and 5/16 bolt holes and remove the paint from an area extending one inch from the center of each of these holes.
- 21. If rust or corrosion is found anywhere on the spar cap or spar web, perform SB-AG-29 in conjunction with this bulletin.
- 22. Inspect the walls of the 1/4 and 5/16 inch bolt holes in the lower spar cap for cracks or flaws using magnetic particle or equivalent flaw detection equipment.
- 23. If no cracks or flaws are found, prime and repaint areas where the paint was removed.

#### \*WARNING\*

If cracks or flaws are found, replace the spar cap or wing prior to the next flight. Contact Ayres Corporation if a ferry flight to a suitable repair station is required.

- 24. Drill or ream the MS20002C4 washers to 0.2720. Drill or ream the MS20002C5 to 0.332.
- 25. Reassemble the splice fittings per the attached installation procedure. Use all **new** nuts, bolts and washers.
- 26. Install the pump mount and brackets.
- 27 Return the aircraft to its airworthy configuration, make appropriate log book entries and return the aircraft to service.

WEIGHT AND BALANCE:

No change.

#### PUBLICATIONS AFFECTED:

None.

**RECORD OF COMPLIANCE:** 

Make appropriate airframe logbook entry. Complete the SB-AG-39 compliance card and mail to Ayres Corporation.

18 AN

Service Bulletin No. SB-AG-39 17 September 1996 Page 8 of 11 a dequient,

# LOWER SPLICE FITTING REMOVAL (Reference Figure 1)

- 1. Park the aircraft in a closed door hangar and secure the aircraft for maintenance.
- 2. Disconnect the battery and external power sources.

----

- 3. Gain access to the wing splice area by removing the wing root fairings and the necessary aircraft side and belly panels.
- 4. Support the wings at the jack points located approximately 6 feet from the wing tips and under various wing ribs to prevent wing movement when the attach bolts are removed.
- 5. Back the locknuts off of the NAS bolts in the splice fittings far enough to conceal the end of the bolt threads. Spray the bolt shanks with WD-40 or an equivalent lubricant.
- 6. Remove the AN5 bolts securing the tubes to the tube nuts and loosen the lower splice fitting tube nuts. As the nuts are loosened, the bolts will back out of the holes. Once the tube nuts are off of the lower bolts, loosen the upper tube nuts to back them out of the holes. If one of the bolts does not move, rethread the tube nut onto this bolt and place a spacer between the opposite end of the tube and the spar cap (or NAS bolt). Proceed, once again, to loosen the tube nut and back the bolt out of the hole. Remove the tubes and tube nuts once sufficient clearance has been obtained.

#### \*CAUTION \*

Extreme care must be taken to avoid damaging the spar cap and the surface finish of the holes through the spar cap.

#### \*NOTE\*

Adjusting the angle of the wings with the wing jacks may assist in wing bolt removal.

- 7. Place an aluminum block on the smallest nut and with a 4X rivet gun, drive the nut flush to the splice fitting. Proceed in a similar manner with the remainder of the bolts working from the smallest to the largest.
- 8. Remove all of the nuts and tube nuts from the NAS bolts. Place the aluminum block on the threaded end of the smallest bolt and with the 4X rivet gun, drive it flush with the splice fitting. Proceed in a similar manner with the remainder of the bolts working from the smallest to the largest.
- 9. Pry the lower splice fitting (top half) off of the NAS bolts by tapping aluminum wedges between the lower splice fitting (top half) and the lower spar cap. Remove the top half of the lower splice fitting.
- 10. Place the aluminum block on the threaded end of the smallest bolt in the lower splice fitting and with a 2X rivet gun, drive it flush with the spar cap. Proceed in a similar manner with the remainder of the bolts working from the smallest to the largest.

Service Bulletin No. SB-AG-39 17 September 1996 Page 9 of 11

#### \*WARNING\*

Under no circumstances should the bolts be turned while the threads are in the spar cap. This could damage the hole surface finish which could result in a stress concentration.

- 11. Pry the lower splice fitting (bottom half) off of the lower spar cap by tapping aluminum wedges between the two. Remove the bottom half of the lower splice fitting along with the NAS bolts.
- 12. Discard all used nuts, bolts and washers.
- 13. Clean and remove corrosion from the splice fittings.

## LOWER SPLICE FITTING INSTALLATION (Reference Figure 1)

- 1. Install the upper tube nuts and torque to specification in accordance with the Figure 2 torque chart.
- 2. Grease the the 12 NAS wing splice attach bolts and the holes in the lower splice fittings (top and bottom halves) with Moly-Disulfide grease. Insert the two large NAS bolts with MS20002C countersunk washers installed into the lower splice fitting (bottom half). Be sure to mate the countersunk portion of the washer with the head of the bolt. Insert the remaining 10 NAS bolts with their respective, properly orientated, MS20002C washers into their respective holes and position all 12 bolts flush with the top face of the lower fitting (bottom half).


#### \* CAUTION \*

Use extreme care to avoid damaging the spar cap or the surface finish of the holes through the spar cap.

- 3. Apply Moly-Disulfide grease to the matching holes in the lower spar cap and place the top splice fitting into position. Press the bolts through the holes in the lower spar cap.
- 4. Place the lower splice fitting (top-half) into position and press the fitting downward over the bolts. Install MS20002 (no countersink) washers (12 places). Slip the 20240-1 tubes over the upper splice tube futs and install the lower splice tube nuts. Bring the 20239-4 tube nuts (2 places) and the AN365 nuts (10 places) up snug.
- 5. Torque the tube nuts and the AN365 locknuts on the NAS bolts through the lower splice fittings per Figure 2, 4 places and 20 places, respectively.
- 6. Position the tubes equidistant between the upper and lower tube nuts. Drill 5/16 inch diameter holes (+0.003, -0.001), 2 places per tube, parallel to the spar web through the pilot holes in the tubes and through the tube nut shanks, 4 places total. Install AN5 bolts through these holes and secure with AN960 washers and AN365 locknuts. Torque locknuts per Figure 2.

-

7. Remove the wing jacks.



# Figure 1 - SPLICE FITTING

Service Bulletin No., SB-AG-39 17 September 1996

•

Service Bulletin No. SB-AG-39 17 September 1996 Page 11 of 11

l

21. 1.13

	BQLTS Blosi Tension				DOLTS Sleel Tension				BOLTS Aluminum			
	Bicei Tension           AN 3 thru AN 20           AN 42 thru AN 40           AN 73 thru AN 81           AN 173 thru AN 81           AN 173 thru AN 81           MS 20033 thru MS 2           MS 20074           AN 509 NK9           MS 24004           AN 525 NK525           MS 27030           NUT8           Steel Tension           AN 310           AN 315           AN 363           AN 365		20 7 49 7 81 N 186 N18 2004	20 34 1022 7826	Steel Ter           MB 20004 thru           NAS 144 thru           NAS 333 thru           NAS 583 thru           NAS 624 thru           NAS 624 thru           NAS 624 thru           NAS 624 thru           NAS 1303 thr           NAS 1304 thr           NAS 517           NUT           Steel Termion           AN 310           AN 315           AN 363           AN 365           MS 17825           MS 20365		MS 20024 NAS 158 NAS 340 NAS 590 NAS 544 NAS 132 Steel sheet	0 r bolt 44 wear 10 14 1022 1928	Aluminum Aluminum AN 3DD thru AN 20DD AN 173DD thru AN 186DD AN 509DD AN 525D M8 27039D M8 24694DD 		Bhoar D D	
	M8 2 M8 2 M8 2 NA8	0365 0500			M8 2 NA5 NA8	1045 1021						
				F	INE TH	READ S	ERIE8					
lut-bolt size			Limite ibe.	Terque Limits Terque Lin inibs. inibs.		Limite be.	Torque Limits inibs,		Torque Limits in,-ibs.			
	Min.	Max.	Min.	Max,	Min.	Max.	Min.	Mas.	Mis.	Max.	Min.	Max.
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		15 25 70 140 190 500 690 1,000 1,000 1,000 3,000 4,500 7,000 11,000	7 12 30 60 95 270 290 480 660 1, 300 1, 500 2, 200 3, 000 5, 400	9 18 40 85 110 300 410 600 780 1, 500 1, 500 1, 800 3, 300 4, 200 6, 600	25 80 120 520 770 1, 100 1, 250 2, 650 3, 550 4, 500 6, 000 11, 000	30 100 145 250 630 950 1, 300 1, 300 1, 550 3, 200 4, 350 5, 500 7, 300 13, 400	15 50 70 120 300 450 650 750 1,600 2,100 2,100 2,700 3,600 6,600	20 60 90 150 400 550 800 950 1,900 2,600 3,300 4,400 8,000	30           40           75           180           280           380           550           950           1,250           1,600           2,100		270 560 750 950 1, 250	6 10 30 40 70 170 260 360 420 880 1, 200 1, 500 2, 000 3, 650
				· cc	ARSE 1	BREAD	BERIES	l 				
8 -32 10 -24 % -20 % -18 % -16 % -14 % -13	20 40 80 160 235 400		12 25 48 95 140 240	9 15 30 55 110 165 290		-						
Xe-12 X -11 X -10 X - 9 1 - 8	700 1, 150 2, 200	900 1,600 3,000 5,000	420 700 1, 300 2, 200	3,000					· · · · · · · · · · · · · · · · · · ·			
114 - 8												

121

.

Recommended torque values for nut-bolt combinations (without lubrication) Figure 2

# Ayres service bulletin No. SB-AG-39 REV 1 corporation

P.O. Box 3090 One Ayres Way Albany, Georgia 31706-3090 Phone:912/883-1440 Fax:912/439-9790

Service Bulletin N0. SB-AG-39 Rev. 1 December 12, 1997

# SB-AG-39 Revised Compliance Options and Inspection Intervals

# **Models Affected:**

<b>Group 1 Airplanes</b> Model S-2R	Serial Numbers 5000 through 5099R
S2R-R1340	R1340-011,R1340-012,R1340-019,R1340-020, R1340-024, R1340- 025, and R1340-027
S2R-R1820	R1820-001 through 1820-035
S2R-T34	6000R through 6049R, T34-001 through T34-143, T34-145, T34- 147 through T34-167, T34-171, T34-180, and T34-181*
82R-T15	T15-001 through T15-033**
S2R-T11	T11-001 through T11-005
S2R-G1	G1-101 through G1-108

• The serial numbers of the Model S2R-T34 airplanes could incorporate T34-xxx, T36-xxx, or T41-xxx or T42-xxx. This Service Bulletin applies to all of these serial number designations, as they are Model S2R-T34 airplanes.

\*\* The serial numbers of the Model S2R-T15 airplanes could incorporate T15-xx and T27-xx. This Service Bulletin applies to both of these serial number designations as they both Model S2R-T15 airplanes.

Perform Initial Inspection at 2000 hours time in service (TIS).

Group 2 Airplanes Model S2R-R1340	<mark>Serial Numbers</mark> R1340-0028 through R1340-035
S2R-R1820	R1820-036
S2 <b>R-T65</b>	T65-001 through T65-017
S2RHG-T65	T65-002 through T65-017
S2R-T34	<b>T34-144, T34-146, T34-168, T34-169,T34-172</b> through T34- 179, and <b>T34-189</b> through T <b>34-232,</b> T34-234, & T34-238*
S2R-T45	T45-001 through T45-014
52R-G6	G6-101 through G6-147
S2R-G10	G10-101 through G10-141
S2R-G5	G5-101 through G5-106

\*The serial numbers of the Model S2R-T34 airplanes could incorporate T35-xxx, T36-xxx, T41-xxx, or T42-xxx. This Service Bulletin applies to all of these serial number designations as they are all Model S2R-T34 airplanes.

Perform initial inspection at 2200 hours time in service (TIS).

Group 3 Airplanes* Model 600 S2D	<b>Serial Numbers</b> All serial numbers beginning with 600-1311D
S2R	1380 and 1416R through 4999R
S2R-R1340	R1340-001 through 1340-010, R1340-013 through R1340- 018, R1340-021 through R1340-023, and R1340-026
S2R-R3S	R38-001 through R3S-011

\*Any Group # airplane that has been modified with a hopper over 400 gallons, a piston engine greater than 600 horsepower, or any gas turbine engine makes the airplane a Group 1 airplane for the purpose of this Service Bulletin. The owner/ operator must inspect the airplane at the group 1 compliance time specified in the Compliance section of this Service Bulletin.

Perform initial inspection at 6400 hours time in service (TIS).

Reason for publication:	Ayres Service Bulletin No.SB-AG-39 was published to detect before failure, cracks in the wing spar assemblies of Ayres Thrush Agricultural Airplanes.				
	The revision to the Service Bulletin defines the re-inspection interval for certain models after rework and redefines model effectivity and grouping.				
Compliance:	Options				

1) Perform SB-AG-39 as originally written.

2) Perform Ayres CK-AG-29 Part 1if necessary.

3) Add the "big butterfly" P/N 20211-09 and --11 in accordance with CK-AG-29 Part 2.

# By whom work may be performed:

Approval:

7000

d: A & P Mechanic or Equivalent

The FAA and Ayres Corporation

# **Revised inspection requirements:**

Based on findings from accomplishment of SB-AG-39 and damage tolerance analysis, the following Inspections are acceptable for all Groups of airplanes:

Work performed/Technique	Mag. Particie	Ultrasonic	<b>EddyCurrent</b>		
Inspect only	<b>500 hours</b>	400 hours	450 hours		
Inspect, no cracks, cold work	1500 hours	1200 hours	1300 hours		
Inspect, no cracks, cold work, install big butterfly	2500 hours	1950 hours	2150 hours		
Inspect, small crack, cold work To remove crack, re-inspect	950 hours	750 hours	825 hours		
Inspect, small crack, cold work, to remove crack, re-inspect, install big butterfly	1550 hours	1200 hours	1350 hours		
Weight and Balance:	N/A				
Publications affected:	8B-AG-39				
Record of Compliance:	Make appropriate airframe logbook entry.				
Aircraft records:					

SB-AG-39A, dated December 12, 1997 Entitled SB-AG-39 INSPECTION INTERVALS, Accomplished\_\_\_\_\_(date).