




Rolls-Royce

Engine Investigation

**Allison
Model 250-C30P
Engine CAE 890569**

**Bell 206 L-4
Registration: N57AW**



Model 250-C30P

**Cochise County Sheriff's Dept.
Benson, Arizona**

**David W. Riser
Air Safety Investigator**

**Accident date: December 31, 2014
Investigation date: January 1-3, 2015
Report date: January 9, 2015**

Report Enclosures:

Report Narrative

Appendix A, Photographs On-Site

Appendix B, Photographs at Recovery Location

Appendix C, Photographs at Disassembly

Appendix D, Engine Records

Background Information:

On December 31, 2014 at approximately 1710 Mountain Standard Time a Bell 206 L-4 helicopter, N57AW was involved in an accident 7 miles west of Benson, Arizona. The commercial pilot and pilot rated mechanic were fatally injured when the helicopter collided with terrain and the helicopter was destroyed. The flight had been a positioning flight. The helicopter was registered to N57AW LLC, and operated by Airwest Helicopters under lease to Cochise County AZ. Sheriff's Department. Visual meteorological conditions prevailed for the flight, which operated on a company visual flight rules flight plan. The flight originated from Glendale, Arizona, at 1550, and was destined for Sierra Vista, Arizona.

The operator reported that the helicopter had not arrived at its destination and that the Sky Connect Tracking System indicated that the helicopter was at a stationary location between Tucson and Benson. The Cochise County Sheriff's Department located the helicopter wreckage about 2030 at the location the Sky Connect system was reporting. The helicopter was fragmented into multiple pieces along a 174-foot-long debris path. Witnesses living in the local area reported hearing a low flying helicopter around the time of the accident, and that the visibility at ground level was very limited, with low clouds and fog.

Airframe Observations on Site:

The airframe was completely fragmented over an approximate 180 foot debris path, and no cockpit crew occupiable space remained. Both main rotor blades had separated outboard of the doublers. One separated blade section was measured as 12 feet in length and the other blade section measured 8 feet in length. The main rotor blades exhibited leading edge bending and chordwise scratches. The tail rotor and gearbox separated from the tail boom. One blade on the tail rotor was absent half the blade with the other displaying both spanwise and chordwise bending. The tail rotor drive shaft remained with the tail boom. Both the forward end of the drive shaft and the tail rotor end of the drive shaft exhibited torsional overload separations. The main transmission remained attached to fuselage with transmission mount assembly. (Fig 1)

Engine Observations on Site:

The engine was located along with an aft section of airframe at the downstream end of the debris field resting against a tree. With the exception of several oil lines and some wiring the engine was separate from the airframe. All mounting arms had been fractured. The engine was resting on the ground in a generally upright position. The left side of the airframe exhaust stack as well as the left side of the exhaust collector support stack was crushed in a downward direction. The left side scroll and the left side compressor air discharge tube displayed denting and impact damage. Bending of four compressor impeller blades opposite direction of rotation was noted. The power turbine governor displayed a fracture of the after body at the split line. Other than some bending of engine lines from impact, externally the balance of the engine was in visually good condition. (Fig 2)

Engine Observations at Recovery:

The wreckage was recovered to Air Transport in Phoenix AZ for further examination. Other than damage noted on site, the compressor impeller was found to exhibit the blade tips and leading edges of at least four blades to have bending and deformation opposite the direction of rotation. Manual rotation of both the N1 and N2 drive trains at their respective tachometer generator drive pads revealed free rotation and continuity. N1 exhibited smooth rotation with N2 exhibiting a light drag. The engine was then prepared for movement to AeroMaritime for disassembly and further investigation. The freewheeling unit and other airframe components were removed prior to transport as were all engine fuel, oil and pneumatic lines. During removal all “B” nuts were found at least finger tight with no evidence of leakage. (Fig 3)

Engine Information:

An Allison M250-C30P gas turbine engine, S/N CAE 890569, powered the helicopter. Engine log records reflect the engine was installed on the air frame November 4, 2014 at 13453.6 ETT following 2000 hour compressor inspection, installation of an overhauled turbine and accessory gearbox.

Manufacturer	Allison
Engine Model	250-C30P
Rating:	650 Shaft Horsepower
Serial Number	CAE890569
Engine Total Hours	13547.2
Last 100-Hour Inspection	13547.2
Last 300-Hour inspection	13547.2

Component	Serial Number	Part Number	TSO	Total Time
Engine	CAE 890569	23004545		13547.2
Gearbox	CAG 90685	23053349	93.6	8749.8
Compressor	CAC 91925	23051643	4106.1	4106.1
Turbine	CAT 98196	23035128	93.6	3868.5
Fuel Control	87421462	23070613	2223.5	
Governor	BR40630	23070106	1356.7	
Fuel Pump	T-200838	6896822	1130.3	
Fuel Nozzle	1WN05923	23077067	57.0	57.0
Bleed Valve	FF36854	23073353	102.0	102.0

* All times are from last recorded flight and do not include the accident flight.

Engine Investigation:

Engine investigation and disassembly was conducted on January 3, 2015 at AeroMaritime in Mesa Arizona under the auspices of an NTSB investigator. The following represents the facts and findings of that investigation. (Fig 4)

Compressor Section:

Externally the compressor displayed minor impact damage to the outside left shoulder area of the scroll but was otherwise visually normal. Visual examination of the impeller revealed bending of four blades tips and outboard ends of the leading edges in the direction opposite of impeller rotation. Removal of the compressor from the engine revealed smooth and continuous rotation of the compressor during manual rotation by the spur adapter gear shaft. No further disassembly of the compressor was conducted. (Fig 5)

Accessory Gearbox Section:

The accessory gear box was not opened. No damage to the gear box was noted. Manual rotation of both N1 and N2 drive trains at the tachometer generator pads resulted in smooth and continuous gear rotation of both N1 and N2 drive trains through the gear box. (Fig 6)

Combustion Section:

The outer combustion case exhibited impact damage across the bottom surface. A small puncture hole was noted just forward of the combustor drain emanating from the outside inward. The combustor liner was in position and visually undamaged. Removal and examination of the combustor liner revealed it to be normal in appearance with no evidence of unusual streaking or thermal damage. Both left and right side compressor air discharge tubes were in position and properly seated. The left air tube exhibited impact denting along its length with the right side being visually normal. A light dirt coating was noted throughout both air discharge tubes and internally on both the outer combustion case and combustor liner. (Fig 7)

Turbine Section:

Both the gas producer and power turbine supports were visually normal and undamaged. The gas producer rotor was freely rotatable and undamaged. The power turbine rotor was easily rotatable but did exhibit a slight drag due to the impact damage sustained to the exhaust collector support causing an out of round condition in the blade track of the stage three and stage four wheels. (Fig 8) The turbine was separated from the exhaust collector support allowing visual access to the pressure side of the stage three wheel and the suction side of the stage three nozzle. Removal of the stage three nozzle allowed for visual examination of the suction side of the stage two wheel. Thermocouple harness probe tips revealed no evidence of over temperatures. Dirt adhesion was noted throughout the gas path across vane and blade surfaces with heavier amounts observed on the inside of the outer rim area of the stage three wheel. The stage three wheel was otherwise

visually normal and undamaged. The stage four nozzle was in position and undamaged. The stage three nozzle was undamaged but exhibited light spatter across vane surfaces. Coked oil was noted on the suction side near bore and outer rim areas. The stage one wheel and nozzle and the stage two wheel and nozzle were visually normal and exhibited no damage. (Fig 9)

Engine Shafting:

Examination of N1 shafting consisting of the turbine to compressor coupling and spur adapter gear shaft revealed both to have been properly seated, oil coated and visually normal in appearance. The power turbine to pinion gear coupling was in normal position, undamaged and oil coated. The power turbine rotor was not separated however both the power turbine inner shaft and power turbine outer shaft were in normal position and undamaged. (Fig 10)

Oil System and Engine Bearings:

Manual rotation of the N1 gear box drive train resulted in smooth rotation of the oil pump. The internal portion of the accessory was coated with clean oil. The piccolo tube was in position and undamaged. The #4 bearing oil nozzle was in proper position and visually undamaged. The # 1 and #8 bearings were not removed but rotated freely during manual rotation. Engine bearings #2, 2 ½, 3, 4, 5 and 6, were all visually and tactilely examined. Each was found in proper position, oil coated with all balls and or rollers in position and undamaged. (Fig 11) Both the upper and lower chip detectors were void of metal. (Fig 12)

Fuel System:

Fuel system examination consisted of visual examination of the engine fuel pump and all associated engine fuel lines and visual examination of the fuel nozzle. The engine fuel pump was in position with no visible damage. At fuel pump removal the pump drive shaft was normal in appearance and undamaged. Removal of fuel lines at the fuel pump revealed fuel present in the lines. Removal of the fuel line between the check valve and fuel nozzle revealed fuel present in the line. The fuel nozzle was visually normal with no excessive carbon on the outer air shroud. (Fig 13)

Engine Accessories:

The fuel control unit was normal in appearance with no visible damage. Manual operation of the fuel control unit throttle arm resulted in full and smooth travel from stop to stop. The power turbine governor was fractured from impact at the at the split line forward of the after body and could not be actuated due to damage but was otherwise visually normal. (Fig 14)

Summary of Findings:

- During engine disassembly and examination, no pre accident damage or anomalies were discovered which would have precluded normal engine operation.
- Bending of compressor impeller blade leading edges and tips opposite direction of impeller rotation is consistent with engine operation during the accident.
- Dirt noted throughout the gas path and adhesion of dirt on and around turbine blade and vane surfaces is consistent with engine operation during the accident sequence.
- Torsional fracture of the tail rotor drive shaft is consistent with engine operation resulting from rotational tail rotor impact while being driven.

Appendix A, Photographs On Site

Fig 1



Fig 1 Cont





Forward Fuselage / Main Rotor / Main Transmission



Engine to Main transmission Drive Shaft



Tail Boom



Tail Rotor Drive Shafting



Tail Rotor Gearbox and Tail Rotor Blades

Fig 2



Engine on Site




[\(Return\)](#)

Appendix B, Photographs at Recovery Location

Fig 3



Engine at Recovery



(Return)

Appendix C, Disassembly Photographs

Fig 4



Engine as Received for Disassembly



(Return)

Fig 5



Compressor



Compressor Inlet / Impeller



Compressor Aft Side

(Return)

Fig 6




Accessory Gearbox




(Return)

Fig 7



Outer Combustion Case



Combustor Liner

[\(Return\)](#)

Fig 8



Exhaust Collector Support Damage



Power Turbine Rotor in Position inside exhaust Collector Support

[\(Return\)](#)


Fig 9



Stage Three Nozzle



Stage Three Wheel



Stage One Nozzle




Stage Two Wheel



Thermocouple Probe

[\(Return\)](#)

Fig 10



Spur Adapter Gear Shaft on Position



Turbine to Compressor Coupling



Power Turbine to Pinion Gear Coupling



Aft End of Power Turbine Inner Shaft in Position

Fig 11



Piccolo Tube and #2 1/2 Bearing in Position



4 Bearing and #4 Bearing Oil Nozzle



2 Bearing in Position




#6 Bearing in Position

[\(Return\)](#)

Fig 12



Upper Chip Detector



Lower Chip Detector

[\(Return\)](#)

Fig 13




Fuel Pump




Fuel Nozzle

(Return)

Fig 14



Fuel Control with Fuel Pump



Power Turbine Governor

[\(Return\)](#)

Appendix D, Selected Engine records

AIRCRAFT STATUS REPORT

N57AW

1/2/2015

1/2/2015

AIRWEST HELICOPTERS

MODEL: 206L-4

SERIAL NO.

52004

1992

HOURS	CYCLES	RINS-T	RINS-M	ENGINE HRS:	13547.2	HOBBS=	285.7
NEW TOTAL TIME/CYCLES	8116.7	12220	30170	30170	ENG-ACFT=	5430.5	A/C-Hobbs 7831.0
OLD TOTAL TIME/CYCLES	7631.8						
FLIGHT HOURS/CYCLES	484.9				Remote Hook	162.1	Cargo Hook 438.6

DESCRIPTION	SERIAL NUMBER	PART NUMBER	TIME LIFE	COMPONENT TOTAL TIME	COMPONENT TSO/TSI	TIME TO OH/IN/RT	DUE AT A/C TT/CY/RIN	INSTALLED A/C TT/CY	COMP T.T. AT INSTL.	TSI/TSO AT INSTL.
SERVO, LH	RH-4178A	206-076-062-101FM	3600 OH	8081.6	936.7	2663.3	10780.0	7180.0	7144.9	0.0
SERVO, RH	RH-2785A	206-076-062-101FM	3600 OH	936.7	936.7	2663.3	10780.0	7180.0	0.0	0.0
CYCLIC EXT. TUBE, RH	A-8454	206-001-193-001	4800 RT	3378.4	3378.4	1421.6	9538.3	4738.3	0.0	0.0
CYCLIC EXT. TUBE, LH	A-8449	206-001-193-001	4800 RT	3378.4	3378.4	1421.6	9538.3	4738.3	0.0	0.0
START-GENERATOR	Y30060	23081-018	1000 OH	1665.5	751.6	248.4	8365.1	7725.7	1274.5	360.6
HYDR. PUMP	142627	206-076-030-117FM	OC					03/08/02	3465.1	0.0

Engine

ENGINE	CAE-890569S		OC	13547.2			O/C	8023.1	13453.6	1944.7
GEARBOX	CAG-90685	23053349	OC	8749.8	93.6		O/C	8023.1	8656.2	0.0
COMPRESSOR	CAC-91925	23051643	OC	4106.1	4106.1		O/C	8023.1	4012.5	4012.5
IMPELLER HOURS	DU94748	23076543	15000 RT	4106.1	4106.1	10893.9	19010.6	8023.1	4012.5	4012.5
IMPELLER FPI			12500 IN	4106.1	4106.1	8023.9	16510.6	8023.1	4012.5	4012.5
IMPELLER CYCLES			25000 RT	5506		19494	31714	12138	5424	5424
COMP ADPT. INSP.		CSL-A-3066	2000 IN	4106.1	93.6	1906.4	10023.1	8023.1	4012.5	0.0
COMB CASE AND LINER			2000 IN	2038.3	93.6	1906.4	10023.1	8023.1	1944.7	0.0
DISCHARGE TUBES			2000 IN	2038.3	93.6	1906.4	10023.1	8023.1	1944.7	0.0
TURBINE-OVERHAUL	CAT-98196	23035128	2000 OH	3868.5	93.6	1906.4	10023.1	8023.1	3774.9	0.0
1st ST. WHL. HRS	X618515	M250-10227	2025 RT	93.6	93.6	1931.4	10048.1	8023.1	0.0	0.0
1st ST. WHL. CYL			3000 RT	82		2918	15138	12138	0	0
2nd ST. WHL. HRS	X633116	M250-10658	2025 RT	93.6	93.6	1931.4	10048.1	8023.1	0.0	0.0
2nd ST. WHL. CYL			3000 RT	82		2918	15138	12138	0	0
3rd ST. WHL. HRS	X619988	6898663	4550 RT	93.6	93.6	4456.4	12573.1	8023.1	0.0	0.0
3rd ST. WHL. CYL			6000 RT	82		5918	18138	12138	0	0
4th ST. WHL. HRS	X632803	23066744	4550 RT	93.6	93.6	4456.4	12573.1	8023.1	0.0	0.0
4th ST. WHL. CYL			6000 RT	82		5918	18138	12138	0	0
BLEED VALVE	FF-36854	23073353	1500 OH	102.0	102.0	1398.0	9514.7	8023.1	8.4	8.4
FUEL PUMP	T 200838	6896822	3000 OH	1130.3	1130.3	1869.7	9986.4	8023.1	1036.7	1036.7
FUEL CONTROL	87421462	23070613	2500 OH	2223.5	2223.5	276.5	8393.2	8023.1	2129.9	2129.9
FILTER INSPECTION		73-20-02 PAR. 5.A.	2000 IN	318.2	318.2	1681.8	9798.5	8023.1	224.6	224.6
FUEL NOZZLE	1WN05923	23077067	2000 OH	57.0	57.0	1943.0	10059.7	8059.7	0.0	0.0
GOVERNOR	BR 40630	23070106	2000 OH	1356.7	1356.7	643.3	8760.0	8023.1	1263.1	1263.1

Inspections

AD 2013-25-10	1/31/2014	Tailboom Fitting	100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
FUEL NOZZLE			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI BAG FLOOR PROTECTOR			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI BAG WALL PROTECTOR			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI CABIN FLOOR PROTECT.			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI CYC-COLL COVERS			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI DOOR OPENERS			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI FOLDING STEPS			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI HAT RACK NET			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI LOCKING FUEL CAP			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI SKID TUBES			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI SPACEMAKER			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI STEP HANDLES			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
AAI WINDOWS			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
BRISTOL WIRE STRIKE			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
CARGO MIRROR			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0
DART HEATER-DEFROST			100 IN	0.0	0.0	100.0	8216.7	8116.7	0.0	0.0

AIRWORK **MODIFICATION RECORD** PART III
Allison **ENGINE ASSEMBLY** Page No. 5

Engine Serial Number CAE 890569s Engine Model 250 - c30p p


Compliance Date	Bulletin or Directive No.	Rev.	Title	Signature	Organization
10/25/10	CSL A 3117		CONTROL SYSTEM PLUMBING INSPECTION.	[Redacted]	YRR4491L
10/25/10			FOUND THE FOLLOWING BULLETINS PREVIOUSLY COMPLIED WITH CEB72-3200, CEB72-3234, CEB72-3158, CEB73-3071, CEB73-3075 CEB73-3106, CEB73-3111, CEB72-3227, CEB73-3047 CEB75-3011 AND 75-3024	[Redacted]	YRR4491L
11/4/14	CEB A 723295		Spur adapter retaining ring. No Defects Found	[Redacted]	AWH

Allison **AIRWORK** PART IV
INSPECTION - MAINTENANCE - OVERHAUL RECORD Page No. 42
ENGINE ASSEMBLY


Engine Serial Number CAE 890569s Engine Model 250 - c30P

DATE	ENGINE TOTAL TIME TOTAL CYCLES	REMARKS	SIGNATURE	ORGANIZATION
4-29-92	1664.4 2532	Engine Converted From Model 250-C30S to 250-C30P. Job No: M12936	[Redacted]	Airwork
Counter:	0111			
		For: Airwork Corporation CRS QT2R121L Municipal Airport Millville, New Jersey 08332		

Inspection - Maintenance - Overhaul Record Engine Assembly




Part IV Page No. 21
 Engine Serial Number CAE-890569¹ Engine Model 250-C30P

Date	Engine Time		Remarks	Signature and Certificate No.	Organization
	Since OH	Total			
6/21/12	12,416.9		Removed Fuel pump P/N 23070460 S/N 5604 AKW 0193 TSO 3074.4. Removed for maintenance convenience. Installed overhauled fuel pump P/N 6896822 S/N 200838 TSO unk TSO 0.0. All O/S and leak checks good		
		ACTY 6897			
04/01/14 N57AW Engine Log A/C TT: 7702.6 Hobbs: 1819.2 Removed turbine P/N: 23035128 S/N: CAT-98621 TSN: 3890.8 TSO: 1790.9 for temporary maintenance convenience install onto N85AW. Reinstalled serviceable turbine P/N: 23035128 S/N: CAT-98621 TSN: 3896.1 TSO: 1796.2. Installed overhauled liner p/n: 23066675 s/n: 0904-210. Bled fuel system. Pre-oiled #6, 7 and 8 bearings. Complied with ground run and leak check and found okay.					
				 Chad Myers	

GT-2784AT (1/05)

Inspection - Maintenance - Overhaul Record Engine Assembly




Part IV Page No. _____
 Engine Serial Number CAE- Engine Model 250-

Date	Engine Time		Remarks	Signature and Certificate No.	Organization
	Since OH	Total			
	New	0.0	Fuel system preserved with MIL-0-6081 oil.		Rolls-Royce
7/15/14	13445.2		Removed bleed valve P/N 23073353 S/N: FF-40477 TSN: unk TSO: 1487.4. Installed overhauled bleed valve P/N: 23073353 S/N: FF-36854 TSN: unk TSO: 0.0.		
		A/C TT: 7846.0			
7/18/14	13453.6		Removed Turbine P/N: 23035128 S/N: CAT-98621 TSN: 4049.9 TSO: 1950.0 for install onto engine Assy S/N: CAE-895835.		
		A/C TT: 7856.4			
7/18/14	13453.6		Removed Engine Assy S/N: CAE-8905695 from N57AW/ for maintenance convenience.		
		A/C TT: 7856.4			


GT-2784AT (1/05)

Inspection - Maintenance - Overhaul Record Engine Assembly



Part IV
Page No. _____

Engine Serial Number CAE- Engine Model 250-

Date	Engine Time		Remarks	Signature and Certificate No.	Organization
	Since OH	Total			
7/18/14	13453.6		Removed gearbox P/N: 23053349 S/N: CAG-90120 TSN: 8401.8 TSO: new for leaking mating surface at turbine. Installed overhauled gearbox P/N: 23053349 S/N: CAG-90685 TSN: 8656.2 TSO: 0.0 Removed compressor P/N: 23051643 S/N: CAC-91925 TSN: 4012.5 TSO: 1944.7 and sent to Aero Maritime for 2000 hour inspection. Reinstalled compressor P/N: 23051643 S/N: CAC-91925 TSN: 4012.5 TSO: new.		
		N/C T: 7856.4			
<div style="border: 1px solid black; padding: 5px;"> <p>11/04/14 Cycles: 12138 N57AW Engine Log A/C TT: 8023.1 Hobbs: 192.1</p> <p>Removed engine assembly S/N: CAE-895431 TSN: 6886.6 TSO: 312.2 CSN: 15186 CSO: 216. Installed serviceable engine assembly s/n: CAE-890569S TSN: 13453.6 TSO: 1944.7 with overhauled gear box p/n: 23053349 s/n: CAG-90685 TSN: 8656.2 TSO: 0.0, repaired compressor p/n: 23051643 s/n: CAC-91925 TSN: 4012.5 TSO: 4012.5 and overhauled turbine p/n: 23035128 s/n: CAT-98196 TSN: 3774.9 TSO: 0.0. Bled fuel system. Pre-oiled #6,7 and 8 bearings. Adjusted idle and governor beep range. Ground run and leak check good.</p> </div>					
				 Tyler Evans	

GT-2784AT (1/05)

Inspection - Maintenance - Overhaul Record Engine Assembly



Part IV
Page No. _____

Engine Serial Number CAE- Engine Model 250-

Date	Engine Time		Remarks	Signature and Certificate No.	Organization
	Since OH	Total			
	New	0.0	Fuel system preserved with MIL-0-6081 oil.		Rolls-Royce
11/24/14			Removed fuel nozzle P/N: 23077067 S/N: AG42399 TSN: UNK TSO: 1981.3		
	13490.2		Installed overhauled fuel nozzle P/N: 23077067 S/N: 14W05923		
		N/C T: 8059.7	TSN: UNK TSO: 0.0. Bled fuel system. OPS & leak check good.		

GT-2784AT (1/05)

DallasAirmotive

COMPONENT INSTALLATION / REMOVAL RECORD

Part V
Page No. _____

Engine Serial Number CAE-890569 Model 1584.2.2.2. 1261.8 250 C30P

Component	Part Number Serial Number	Installed Date	Engine		Component TSN	Removed Date	Engine		Component TSN	Reason
			TSN	CSN			TSN	CSN		
Bleed Valve	23073353 FF-50174	1/03/10	11508.7 10291	UNK	UNK	7/28/11	11957.4 10624	UNK	1510.3	overhaul
Fuel control	23070613 87421402	1/6/10	11508.7 10281	UNK	185.2					
Bleed Valve	23073353 FF-40477	8/28/11	4.9524 10624	UNK	0-0	7/15/14	13445.2 11995	UNK	1487.4	overhaul
Governor	23070106 RR-40630	02/15/12	12190.5 10972	UNK	0-0					
Fuel pump	23070960 J6047RW018	04/27/12	12333.3 10947	UNK	NEW	06/21/12	12416.9 11077	UNK	3074.4	maintenance convenience
Fuel pump	23073353 FF-32854	06/01/12	12416.9 11077	UNK	0-0					
Bleed Valve	23073353 FF-32854	7/15/14	13445.2 11995	UNK	0-0					
Turbine	23035128 CAT-98621	4/1/14	13299.8 11811	UNK	3896.1 1796.2	7/18/14	13453.6 11972	UNK	4049.9 1950.0	maintenance convenience
Gearbox	23053349 CAC-90685	7/18/14	13453.6 11963	UNK	8656.2 0-0					
Compressor	23051643 CAC-91925	8/20/14	13453.6 11963	UNK	4012.5 NEW					
Turbine	23035128 CAT-98196	10/28/14	13453.6 11963	UNK	3774.9 0-0					
Fuel Nozzle	23070667 1WNJ05923	11/24/14	13490.2 12159	UNK	0-0					

DTP / RE: 100-004 R2

Service Accessory Record

Rolls-Royce


Nomenclature P.T. GOVERNOR Part I
Page No. 1

Component Serial Number BR 40630 Engine Model 250-C30

Installed					Removed				Reason
Date	Engine S/N	Engine TT	Accessory Time		Date	Engine TT	Accessory Time		
			Since OH	Total			Since OH	Total	
02/15/12	CAE 890569	12,190.5	0.0	UNK					

GT-11778(F) 7/03

Service Accessory Record



Rolls-Royce

Nomenclature Bleed Valve 23055366 Part I
 Page No. 1
 Component serial number KF26854 Engine Model 250-CAE

Installed					Removed			
Date	Engine S/N	A/C S/N Reg. #	Accy. Time		Date	Accy. Time		Reason
			Since OH	Total		Since OH	Total	
9-22-05	844031	#49014 N30090	New	0.0	16-Jan-204	1170.8	UNK	POWER LOST
7/15/14	CAE 890569	52004 N57AW	0.0	UNK				

GT-11778(F) 5/00

Service Accessory Record


Rolls-Royce

Nomenclature FCU Part I
 Page No. _____
 Component Serial Number 87421462 Engine Model 250-

Installed					Removed			
Date	Engine S/N	A/C S/N Reg. No.	Accessory Time		Date	Accessory Time		Reason
			Since OH	Total		Since OH	Total	
8-19-09	CAE-895790	52115 N73AW	New	0.0	03/22/10	NEW	105.2	Install on CAE-890569
3/23/10	CAE-890569	45261 N85AW	NEW	105.2	5/17/10	150.175.7 2276 175.7	UNK	DAI CONVENIENCE
08/17/10	CAE-895790	52115 N73AW	175.7	UNK	11/04/10	185.2	UNK	convenience
11/04/10	CAE-890569	45261 N85AW	185.2	UNK				

GT-11778T (F) 5/00

Part I
Page No. _____

SERVICE RECORD TURBINE ASSEMBLY

GT 2782D-1 (9-83)

Turbine Serial Number CAT- 98196 Engine Model 250- C30P

INSTALLED					REMOVED			
Date	Owner	A/C or Eng. S/N	Turbine Time		Date	Turbine Time		Reason
			Since OH	Total		Since OH	Total	
10-30-94		895790	NEW	0.0	8-4-08	NEW	1992.7	overhaul
10-24-08	AWH	895790	0.0	1992.7	4-16-13	1430.0	3422.7	wheel Rub
10-05-13	AMS	895695	1430.0	3422.7	7-16-14	1782.2	3774.9	Cycles
11/4/14	AWH	890569	3774.9	0.0				

Part IV
Page No. _____

INSPECTION — MAINTENANCE — OVERHAUL RECORD TURBINE ASSEMBLY

GT 2784D-1 (9-83)

Turbine Serial Number CAT- 98196 Engine Model 250- C30P

Date	Turbine Time		Remarks	Signature	Organization
	Since OH	Total			
7/29/2013	W/O#	W319405	<p>4927 East Falcon Drive Mesa, Arizona USA 85215 480-830-7780 www.aeromarus.com</p>  <p>Engine Model: RR M250-C30P Item Serial #: CAT-98196 TSO : 1430.0 TT : 3422.7 CSO : 2088 TC : 4435</p> <p>Turbine repaired for N1 Rub and low power. Functionally tested. All work performed in accordance with Rolls-Royce 14W2 and 14W3 Specs. This certifies that the work requested by the customer and described on the work order listed below was accomplished and inspected with reference to instructions for continued airworthiness, other data acceptable to the FAA and current FAA regulations, and with respect to the work performed, is approved for return to service. Pertinent details of this repair are on file at this FAA Certified Repair Station. AeroMaritime America Incorporated CRS# XZNR915L</p> <p>Signed:  Charles Garrett Hagen</p>		
10/6/2014	W/O#	19528	<p>4927 East Falcon Drive Mesa, Arizona USA 85215 480-830-7780 www.aeromarus.com</p>  <p>Engine Model: RR M250-C30P Item Serial #: CAT-98196 TSO : 0.0 TT : 3774.9 CSO : 0 TC : 5330</p> <p>Complied with overhaul. Tie Bolt PN: 23008030 SN: NC83384 Free Length: 7.371 Stretch Length: 7.387 Total Stretch: 0.016. Functionally tested and accepted. All work performed in accordance with Rolls-Royce 14W3 Specs. This certifies that the work requested by the customer and described on the work order listed below was accomplished and inspected with reference to instructions for continued airworthiness, other data acceptable to the FAA and current FAA regulations, and with respect to the work performed, is approved for return to service. Pertinent details of this repair are on file at this FAA Certified Repair Station. AeroMaritime America Incorporated CRS# XZNR915L</p> <p>Signed:  Kevin Driscoll</p>		

