SPANWISE BEAM #1 - WING CENTER TANK

CW-907	CW-908
Z-2679	GREEN
GREEN	Z-2662

This section is from the left SOB rib to LBL 107 and is 40" tall. It starts 10" above the lower chord and extends to the mating fracture with CW-904. The stiffener common to SOB rib remains intact.

Three fasteners common to SOB rib web and the outboard stiffener on the forward side remain. These 3 fasteners exhibit no bending and failed in tension. The aft lower six fasteners common to the stiffener and LSOB rib are sheared forward and down and remain in outboard stiffener. Eight of the nine forward fastener holes are elongated forward and down. The lower eight inches of stiffener flange is bent aft approximatley ten degrees and twisted counterclockwise when viewed looking down. The upper fastener holes in the outboard stiffener are elongated upward. The remainder of the fastener holes do not exhibit obvious elongation. The stiffener at LBL 112 suffered severe impact damage and most of the stiffener web and free flange is separated. CW-908 is designated as this stiffener free flange with portion of stiffener stabilization strap. All the horizontal stiffeners (qty of 5) at the aft side except for the lowest stiffener are intact. The lowest stiffener has part of the inbd end bent down. The lower section of the web is bent fwd slightly.

Some sooting is exhibited on the forward and aft sides. See fire and explosion group notes for documentation.

Affliptis 12-6-AL TWA

SO GREEN 12-7-96 ALPIA

Acile 12-8-96 IAM Stophini F Kilapach JATT 2-08-96 FMA Oli Reimer 12/12/96 BOEING

