

FATIGUE

Front Spar lower horizontal chord - existing fatigue cracking


Fatigue cracks were found in the Front Spar lower horizontal chord in the fillet radius just outboard of the Drag Splice fittings at RBL/LBL 80. The existing cracks were approximately 1.2 inch and 1.45 inch on the RHS and LHS, respectively. The cracks originated at the inside fillet radius and were part through cracks, progressing approximately one third through the chord thickness (approximately 0.10 inch deep and 0.125 inch deep on the RHS and LHS, respectively).

The lower horizontal chord in the vicinity of the fatigue cracking is subjected to inspection under the Supplemental Structural Inspection Document (SSID) program. A previous instance of cracking at this location was found on a different 747-100. Those cracks were longer than those on TWA800 but also did not extend through the thickness of the chord. This region is affected by SB 747-53-2064 for adjacent ring chord cracking. The modification per SB 747-53-2064 had been installed in 1982, installing two bathtub fittings on the Wing Center Section lower skin panel and a double bathtub fitting on the fuselage skin. These fittings are immediately adjacent to the drag splice fitting and serve to provide an alternate load path for the drag splice forward/aft loads. It is apparent from the bathtub fitting arrangement that the post-modification configuration is very stiff and the deflection that would have initiated the fatigue cracking has been significantly limited. Without continued deflection, the fatigue growth cannot continue, indicating that the fatigue cracking existed prior to the installation of the bathtub fittings.

Visual examination of the ductile rupture surfaces adjacent to the relatively short, shallow cracks did not reveal any indication of wear. This is indicative of the gross fracture precipitating from something other than the fatigue cracking. The NTSB Materials Laboratory has examined the larger of the two fatigue cracks and will issue a separate report.

See the Metallurgical Field Notes for a complete cracking description.

ATM 12/21/97
JFW 1/27/97




Front Spar vertical stiffener shear ties - existing fatigue cracking

Small existing fatigue cracks were found in the vertical stiffener shear ties at RBL 83.24 (lower), RBL 75.92 (upper and lower), LBL 75.92 (upper and lower), and LBL 83.24 (lower).

The cracks were all in the shear tie radius near the base of the leg that attaches to the vertical stiffener at the aft edge. This cracking is the subject of SB 747-57-2249. The Service Bulletin was issued in 1989 after reports of in-service cracking. The maximum crack length on the subject airplane was 0.20 inch long. In service, operators have reported cracks ranging from 0.50 inch to 1.5 inch long without complete part fracture, demonstrating the capability of these shear ties to withstand cracking in excess of the 0.20 inch detected cracking under normal operating conditions.

See the Metallurgical Field Notes for a complete cracking description.



QFWII
1/24/97


QFWII
1/24/97

Longitudinal Floorbeam at Front Spar - existing fatigue cracking

Small cracks were found in the shear tie of the LBL 75.92 and the LBL 33.99 longitudinal floorbeams at the intersection with the Front Spar upper chord at STA 1000. The LBL 75.92 shear tie has a 0.15 inch fatigue crack emanating from the aft side of the hole and a possible 0.125 inch fatigue crack emanating from the forward side of the hole as shown. The LBL 33.99 shear tie has a 0.25 inch fatigue crack emanating from the forward side of the hole.

The component is a secondary attachment for floor structure and does not contribute to carrying primary operating loads.

See the Metallurgical Field Notes for a complete cracking description.



JEWI
1/24/97

JEWI - DENIS
1/24/97

Front Spar areas with apparent fatigue cracks

* LH. ON 12/12/96
LEWIS
HARRISON - TWA
L.H.


- A** RH Upper Wing Terminal Fitting approx. 2 inch below upper wing skin. Crack initiated from INBD Side. Crack dimension ≈ 0.6 " long $\times \approx 0.1$ " deep. Mechanical damage. JE 12/4/96 L.H.
- B** Upper Chord to Stiffener Shear Tie at RBL 75.92. Crack initiated at AFT/OUTBD Corner. Crack dimensions ≈ 0.1 " \times 0.2 ". JE 12 LH.
- C** Upper Chord to Stiffener Shear Tie at LBL 75.92. Crack initiated at AFT/OUTBD Corner. Crack dimensions ≈ 0.15 " $\times \approx 0.20$ ". JE 12 LH.
- D** Floor beam to Upper Wing Skin Shear Tie at LBL 75.92. Crack initiated at fastener hole common to floor beam web. JE 12/4 LH.
- E** Lower Chord to Stiffener Shear Tie at RBL 83.24. Crack initiated at AFT/INBD Corner. Crack dimensions ≈ 0.1 " $\times \approx 0.2$ ". JE LH.
- F** Lower Chord at \approx RBL 80.5. Crack initiated at upper surface from multiple origins in the extruded radius. Crack dimension ≈ 1.2 " long $\times \approx 0.1$ " deep. JE LH.
- G** Lower chord at \approx LBL 80.5. Crack initiated at upper surface from multiple origins in the extruded radius. Crack dimensions ≈ 1.45 " long $\times \approx 0.125$ " deep. JE LH.
- H** Lower Chord to Stiffener Shear Tie at LBL 83.24. Crack initiated at AFT/INBD Corner. Crack dimensions ≈ 0.08 " $\times \approx 0.2$ ". JE LH.
- I** Lower chord to Stiffener Shear Tie at LBL 91.14. Crack initiated at AFT/INBD Corner. Crack dimensions ≈ 0.1 " $\times \approx 0.2$ ". JE LH.

J SIMILAR TO **D** EXCEPT AT LBL 33.99, .25 IN. LONG APPROX., AND FROM FWD SIDE OF HOLE. J. TRZIL 1-23-97

Discovered by G. Fleis, J. Trzil, J. Straus


Confirmed by J.R. Straus 1/16/96

JE 12/1/97



- RBL 91.14
- RBL 83.24
- RBL 75.92
- BL 0
- LBL 75.92
- LBL 83.24
- LBL 91.14

Front Spar
View Looking
AFT



ADDED
JTR 2/11
1/23/97


11/16/96
JTR Strauss

Underwing
Longmen
Ftg.

LOCATION **A**

RW-7
GREEN C2151


Forward Fracture of RH Terminal Ftg at Upper Skin Att




FOR G. FLEIS/
CONFIRMED J. STRAUSS
J. TRILL
10/18/96

Apparent Fatigue Crack Location

- AFT End of Shear Tie Fracture at front Spar Stiffener to Upper Chord at RBL 75.92. Similar crack located at LBL 75.92 (see CW114).



RBL
75.92



A-A

J.R. Strawn 11/16/91

VERIFIED 12/4/96

(initials)

JE 11/4/96

JWK 12/4/96

LH 12/2/96

JRW II 1/23/97


LOCATION **C**

CW-114
10/19/96
J. TRZIL

APPARENT FATIGUE CRACK LOCATION


F.S. WPR CHORD SHEAR TIE

[C913
GREEN
TAG]




APR L/H CORNER #23028
~ 3mm x 3mm (~ 1/8" x 1/8")
~ 1/8" THICK

CRACK ~ .1" ABOVE SURFACE



LBL 75.92



Stephen F. Klepac II Jr
FAN 11-09-96 NO Photo
JE 12/4/96


JWK LH 12/12/96

Similar Apparent Fatigue
Crack noted on CW 101 at
RBL 75.92. J.R. Straws 11/16/96

JFW II
1/23/97

LOCATION D

CW-114



VIEW LOOKING UP

FLOOR BEAM TO FRONT SPAR SHEAR TIE
AT LBL 75.92


[Signature]
G. FLEIS
11/7/96

J.E. 12/4/96
[Signature]
LH 12/12/96

Confirmed
J.R. Straus 11/13/96

LOCATION E

Apparent Fatigue Crack Location - AFT/INBD Corner of
Shear Tie fracture at front Spar Stiffener RBL 83.24.



RBL
83.24

J.R. Strain 11/16/96

J.E. 12/4/96



Jwk
LH 12/12/90

QFCW II
1/23/97

LOCATION F


CW216

Apparent Fatigue Crack Location -
Front Spar Lower Chord at \approx RBL 80.5



JE 12/4/96
JWK
LH 12/2/96

Fatigue Detail




J.R. Shaw 11/16/96

LOCATION G

CW22

Apparent Fatigue Crack Location -

Front Spar Lower Chord at \approx LBL 80.5.




LOCATION

H


CW 221

Apparent Fatigue Crack Location - AFT/INBD Corner of Shear Tie fracture at Front Spar Stiffener LBL 83.24.

CRACKS ~ .15" ABOVE FLANGE



LBL 83.24



possible multiple initiations on surface


AE 12/4/96

Ⓜ JWR need to be verified 11/12/96

11/16/96

J.R. Strain





LOCATION



CW221

Apparent Fatigue Crack Location - AFT/INBD Corner of Shear Tie fracture at front Spar Stiffener LBL 91.14.

CRACK ~ .23 INCH ABOVE FLANGE



JE / 12/4/96
Jwk
14 12/12/96

RFW II
1/23/97


J.R. Strauss 11/16/96

LOCATION J

CW-502

J. TREIL

1-23-97



FLOOR BEAM TO FRONT SPAR
SHEAR TIE AT LBL 33.99

J. TREIL
1/24/97

5

FRACTURE POSSIBLY
15/17/96
Smearred & Mech Damaged
Overstress
12/12/96
12/4/96
Fwd

G. FLEIS
10/29/96

REAR SPAR
TERMINAL FITTING

OUT BOARD

CHORD
EXTENDS
TO
RBL100

DIRECTION
OF
FRACTURE

CW-223

REAR SPAR
LOWER CHORD

VISIBLE FEATURES :

1. FLAT PROFILE FOR 1.0 - 1.25 INCHES
2. GENTLE TRANSITION TO SLANTED PROFILE
3. HAMMERED SURFACE (SHINEY) IN THE FLAT PROFILE REGION.

NOTE ! THERE'S A SECOND CRACK ABOUT 3/8" BELOW THIS FRACTURE, CAN'T CHARACTERIZE IT WITHOUT REMOVING SEALANT FROM THE AREA.

